

```
2024-04-26T14:04:24.882263Z INFO periodic_scheduler[1519]: cleanup_logs: job completed
2024-04-26T14:04:27.395929Z WARNING kernel: [ 338.553451] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:04:27.396166Z WARNING kernel: [ 338.556533] audit: audit_lost=6
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:04:27.400682Z ERR kernel: [ 338.564085] audit: backlog limit exceeded
2024-04-26T14:04:48.132316Z WARNING kernel: [ 359.286862] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:04:48.132391Z WARNING kernel: [ 359.289063] audit: audit_lost=7
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:04:48.138033Z ERR kernel: [ 359.295770] audit: backlog limit exceeded
2024-04-26T14:04:54.172162Z INFO periodic_scheduler[3552]: cros-machine-id-regen: running
/usr/sbin/cros-machine-id-regen -r periodic -t 21600
2024-04-26T14:04:54.364232Z NOTICE cros-machine-id-regen[8460]: Not regenerating since we
did so 351 seconds ago.
2024-04-26T14:04:54.394666Z INFO periodic_scheduler[3552]: cros-machine-id-regen: job
completed
2024-04-26T14:04:58.540631Z WARNING kernel: [ 369.689990] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:04:58.540749Z WARNING kernel: [ 369.694547] audit: audit_lost=8
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:04:58.546005Z ERR kernel: [ 369.701103] audit: backlog limit exceeded
2024-04-26T14:05:06.625615Z INFO kernel: [ 377.770770] binder_alloc: 6377:
binder_alloc_buf size 1056768 failed, no address space
2024-04-26T14:05:06.625700Z INFO kernel: [ 377.777652] binder_alloc: allocated: 8184
(num: 15 largest: 3920), free: 1032200 (num: 6 largest: 1030112)
2024-04-26T14:05:06.630831Z INFO kernel: [ 377.785946] binder: 6265:8465 transaction
failed 29201/-28, size 1056768-0 line 3061
2024-04-26T14:05:09.866527Z INFO kernel: [ 380.990945] binder_alloc: 8649:
binder_alloc_buf, no vma
2024-04-26T14:05:09.866608Z INFO kernel: [ 381.016837] binder: 4763:5389 transaction
failed 29189/-3, size 76-0 line 3061
2024-04-26T14:05:16.365315Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:05:16.396226Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:05:16.396325Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T14:05:16.396400Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T14:05:16.396800Z INFO dlcservice[1384]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:05:16.398383Z WARNING cras_server[1432]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:05:16.398458Z ERR cras_server[1432]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:05:16.398524Z ERR cras_server[1432]: download_supported_dlc: retry 7 times
2024-04-26T14:05:21.728238Z WARNING kernel: [ 392.872856] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:05:21.728330Z WARNING kernel: [ 392.877747] audit: audit_lost=9
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:05:21.731589Z ERR kernel: [ 392.883534] audit: backlog limit exceeded
2024-04-26T14:05:23.272872Z WARNING kernel: [ 394.417457] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:05:23.272992Z WARNING kernel: [ 394.423194] audit: audit_lost=10
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:05:23.277448Z ERR kernel: [ 394.429208] audit: backlog limit exceeded
2024-04-26T14:05:37.402209Z WARNING kernel: [ 408.549073] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:05:37.402292Z WARNING kernel: [ 408.552080] audit: audit_lost=11
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:05:37.424213Z ERR kernel: [ 408.574375] audit: backlog limit exceeded
2024-04-26T14:05:47.178913Z WARNING kernel: [ 418.318174] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:05:47.178987Z WARNING kernel: [ 418.325178] audit: audit_lost=12
audit_rate_limit=0 audit_backlog_limit=64
```

```
2024-04-26T14:05:47.184596Z ERR kernel: [ 418.334730] audit: backlog limit exceeded
2024-04-26T14:05:48.701474Z INFO cryptohomed[856]: AuthSession: timed out.
2024-04-26T14:06:16.462893Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:06:16.470149Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:06:16.470269Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T14:06:16.470331Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T14:06:16.470815Z INFO dlcservice[1384]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:06:16.472923Z WARNING cras_server[1432]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:06:16.473207Z ERR cras_server[1432]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:06:16.473279Z ERR cras_server[1432]: download_supported_dlc: retry 8 times
2024-04-26T14:06:37.510362Z ERR arc-kmsg-logger[4032]: init: Could not find service
hosting interface android.hardware.vibrator@1.0::IVibrator/default
2024-04-26T14:06:44.066269Z ERR kernel: [ 475.208140] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:06:47.449640Z WARNING kernel: [ 478.588639] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:06:47.449723Z WARNING kernel: [ 478.592519] audit: audit_lost=13
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:06:47.460749Z ERR kernel: [ 478.604790] audit: backlog limit exceeded
2024-04-26T14:06:53.028841Z WARNING kernel: [ 484.161956] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:06:53.028926Z WARNING kernel: [ 484.171308] audit: audit_lost=14
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:06:53.033925Z ERR kernel: [ 484.178243] audit: backlog limit exceeded
2024-04-26T14:07:07.981194Z ERR kernel: [ 499.121951] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:08.662203Z ERR kernel: [ 499.799011] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:09.688621Z INFO kernel: [ 500.824340] binder: 4928:5904 transaction
failed 29189/-22, size 60-0 line 2893
2024-04-26T14:07:15.549264Z INFO kernel: [ 506.687299] binder: 4763:4763 transaction
failed 29189/-22, size 84-0 line 2893
2024-04-26T14:07:16.486908Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:07:16.500993Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:07:16.501210Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T14:07:16.501284Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T14:07:16.501607Z INFO dlcservice[1384]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:07:16.503863Z WARNING cras_server[1432]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:07:16.504882Z ERR cras_server[1432]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:07:16.504947Z ERR cras_server[1432]: download_supported_dlc: retry 9 times
2024-04-26T14:07:16.664099Z WARNING cras_server[1432]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1050720 > 1048576
2024-04-26T14:07:17.847812Z WARNING kernel: [ 508.977311] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:07:17.847967Z WARNING kernel: [ 508.987086] audit: audit_lost=15
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:07:17.847999Z ERR kernel: [ 508.991333] audit: backlog limit exceeded
2024-04-26T14:07:24.131267Z ERR kernel: [ 515.263794] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:25.305751Z ERR kernel: [ 516.418751] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
```

```
2024-04-26T14:07:37.565158Z ERR kernel: [ 528.706515] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:37.693246Z ERR kernel: [ 528.832480] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:38.488193Z ERR kernel: [ 529.613120] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:38.900204Z ERR kernel: [ 530.039090] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:44.651688Z ERR kernel: [ 535.790902] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:44.716192Z ERR kernel: [ 535.830027] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:44.744592Z ERR kernel: [ 535.878264] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:45.850194Z ERR kernel: [ 536.987109] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:47.228245Z ERR kernel: [ 538.366169] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:47.284194Z ERR kernel: [ 538.424781] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:48.177319Z ERR kernel: [ 539.317284] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:49.853965Z ERR kernel: [ 540.992233] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:49.889340Z ERR kernel: [ 541.026347] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:49.911193Z ERR kernel: [ 541.052547] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:49.947221Z ERR kernel: [ 541.088971] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:50.011193Z ERR kernel: [ 541.152164] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:50.021192Z ERR kernel: [ 541.161366] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:50.327314Z ERR kernel: [ 541.467937] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:50.339198Z ERR kernel: [ 541.479002] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:50.367193Z ERR kernel: [ 541.506628] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:51.173223Z ERR kernel: [ 542.314406] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:51.409364Z ERR kernel: [ 542.542065] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:52.480243Z ERR kernel: [ 543.621001] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:52.645230Z ERR kernel: [ 543.779162] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:54.148859Z WARNING cras_server[1432]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1053120 > 1048576
2024-04-26T14:07:54.682227Z ERR kernel: [ 545.814652] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:54.750222Z ERR kernel: [ 545.888099] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:55.170213Z ERR kernel: [ 546.304800] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:56.177252Z ERR kernel: [ 547.312087] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:56.406224Z ERR kernel: [ 547.541828] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:57.948209Z ERR kernel: [ 549.086874] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:58.287312Z ERR kernel: [ 549.426927] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:58.869199Z ERR kernel: [ 550.007024] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:59.490453Z ERR kernel: [ 550.626568] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:07:59.769202Z ERR kernel: [ 550.909414] [drm:vmw_kms_fb_create] *ERROR*
```

```
failed to create vmw_framebuffer: -22
2024-04-26T14:08:02.627336Z ERR kernel: [ 553.752581] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:03.029415Z ERR kernel: [ 554.161551] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:05.298291Z ERR kernel: [ 556.431567] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:05.321232Z ERR kernel: [ 556.458155] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:09.910482Z ERR kernel: [ 561.041140] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:10.106250Z ERR kernel: [ 561.243957] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:10.119270Z ERR kernel: [ 561.258953] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:10.747214Z ERR kernel: [ 561.887449] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:12.460301Z ERR kernel: [ 563.596274] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:12.892353Z ERR kernel: [ 564.026131] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:14.382194Z ERR kernel: [ 565.515807] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:16.513544Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:08:16.520823Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:08:16.520973Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T14:08:16.521156Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T14:08:16.521511Z INFO dlcservice[1384]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:08:16.523985Z WARNING cras_server[1432]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:08:16.524203Z ERR cras_server[1432]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:08:16.524265Z ERR cras_server[1432]: download_supported_dlc: retry 10 times
2024-04-26T14:08:17.418158Z WARNING kernel: [ 568.553492] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:08:17.418235Z WARNING kernel: [ 568.556450] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:08:17.418265Z WARNING kernel: [ 568.559824] audit: audit_lost=16
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:08:17.422894Z ERR kernel: [ 568.566420] audit: backlog limit exceeded
2024-04-26T14:08:17.440357Z WARNING kernel: [ 568.574605] audit: audit_lost=17
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:08:17.440443Z ERR kernel: [ 568.583168] audit: backlog limit exceeded
2024-04-26T14:08:17.573234Z ERR kernel: [ 568.712024] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:18.040202Z ERR kernel: [ 569.177215] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:18.083226Z ERR kernel: [ 569.221548] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:21.004315Z ERR kernel: [ 572.124279] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:21.047234Z ERR kernel: [ 572.186996] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:24.166299Z INFO kernel: [ 575.306926] binder: undelivered transaction
194095, process died.
2024-04-26T14:08:24.599396Z INFO crash_reporter[11271]: developer build - not testing -
always dumping
2024-04-26T14:08:24.624425Z WARNING crash_reporter[11271]: [ARC_java] Received
system_app_crash notification for com.android.vending (handling)
2024-04-26T14:08:24.715612Z INFO crash_reporter[11271]: Accessing crash dir '/run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65' via symlinked handle
'/proc/self/fd/10'
```

```
2024-04-26T14:08:24.726389Z INFO crash_reporter[11271]: Finishing crash. Meta file:
/proc/self/fd/10/com_android_vending.20240426.140824.21676.66188.meta
2024-04-26T14:08:25.601485Z ERR kernel: [ 576.736452] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:25.699229Z ERR kernel: [ 576.836083] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:25.718294Z ERR kernel: [ 576.858800] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:25.813325Z ERR kernel: [ 576.947295] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:25.854231Z ERR kernel: [ 576.982524] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:25.894343Z ERR kernel: [ 577.024515] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:26.039226Z ERR kernel: [ 577.175797] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:26.131201Z ERR kernel: [ 577.271457] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:26.203256Z ERR kernel: [ 577.334784] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:26.239242Z ERR kernel: [ 577.369057] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:26.258229Z ERR kernel: [ 577.388365] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:33.435036Z INFO kernel: [ 584.570260] binder_alloc: 11276:
binder_alloc_buf, no vma
2024-04-26T14:08:33.435228Z INFO kernel: [ 584.576585] binder: 4763:5389 transaction
failed 29189/-3, size 76-0 line 3061
2024-04-26T14:08:59.392231Z ERR kernel: [ 610.526424] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:08:59.412614Z ERR kernel: [ 610.552256] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:09:00.000220Z ERR kernel: [ 611.136945] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:09:16.676285Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:09:16.690841Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:09:16.690986Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T14:09:16.691213Z ERR dlcservice[1384]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T14:09:16.691571Z INFO dlcservice[1384]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:09:16.693998Z WARNING cras_server[1432]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:09:16.694232Z ERR cras_server[1432]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:09:16.694272Z ERR cras_server[1432]: download_supported_dlc: failed to
install the DLC. Please check the network connection. Restart CRAS to retry.
2024-04-26T14:09:20.976319Z ERR kernel: [ 632.115967] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:09:21.000260Z ERR kernel: [ 632.142050] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:09:22.963277Z ERR kernel: [ 634.101812] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:09:23.075346Z ERR kernel: [ 634.216216] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:09:27.552969Z WARNING kernel: [ 638.691370] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:09:27.553205Z WARNING kernel: [ 638.695236] audit: audit_lost=18
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:09:27.568208Z ERR kernel: [ 638.707823] audit: backlog limit exceeded
2024-04-26T14:09:27.585343Z NOTICE auditd[457]: Audit daemon rotating log files
2024-04-26T14:12:05.122241Z ERR kernel: [ 796.259314] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:05.146260Z ERR kernel: [ 796.286284] [drm:vmw_kms_fb_create] *ERROR*
```

```
failed to create vmw_framebuffer: -22
2024-04-26T14:12:05.153189Z ERR kernel: [ 796.294852] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:05.574306Z ERR kernel: [ 796.715259] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:05.595184Z ERR kernel: [ 796.736009] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:06.037888Z ERR kernel: [ 797.168279] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:06.373230Z ERR kernel: [ 797.513989] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:06.392213Z ERR kernel: [ 797.528506] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:06.543199Z ERR kernel: [ 797.683777] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:35.739203Z ERR kernel: [ 826.880989] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:35.867153Z ERR kernel: [ 827.008458] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:35.877190Z ERR kernel: [ 827.017384] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:35.906181Z ERR kernel: [ 827.047186] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:38.120198Z ERR kernel: [ 829.261022] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:38.392528Z ERR kernel: [ 829.531589] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:38.437194Z ERR kernel: [ 829.577124] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:38.448779Z ERR kernel: [ 829.587759] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:38.648376Z ERR kernel: [ 829.789150] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:38.976221Z ERR kernel: [ 830.117587] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:47.139183Z ERR kernel: [ 838.255795] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:48.037534Z ERR kernel: [ 839.176769] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:48.087190Z ERR kernel: [ 839.218012] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:48.113199Z ERR kernel: [ 839.252850] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:49.680521Z ERR kernel: [ 840.815151] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:50.081269Z ERR kernel: [ 841.221165] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:50.104230Z ERR kernel: [ 841.244397] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:12:50.159195Z ERR kernel: [ 841.297138] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:13:23.443181Z ERR kernel: [ 874.583422] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:14:09.643569Z ERR shill[785]: ERROR shill: [rtnl_message.cc(1103)] RTNL
address message does not have a valid IFA_ADDRESS
2024-04-26T14:14:23.302501Z INFO rsyslogd[485]: [origin software="rsyslogd"
swVersion="8.2112.0" x-pid="485" x-info="https://www.rsyslog.com"] rsyslogd was HUPed
2024-04-26T14:15:50.222346Z INFO dbus-daemon[524]: [system] Activating service
name='org.chromium.MachineLearning' requested by ':1.41' (uid=1000 pid=1056
comm="/opt/google/chrome/chrome --enable-webgl-image-chr" label="u:r:cros_browser:s0")
(using servicehelper)
2024-04-26T14:15:50.304736Z NOTICE ml-service[14434]: Pre-start ml-service
task=mojo_service
2024-04-26T14:15:50.388651Z INFO minijail0[14439]: libminijail[14439]: applying policy
for default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:15:50.392308Z WARNING minijail0[14440]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:15:50.392424Z WARNING minijail0[14440]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
```

```
2024-04-26T14:15:50.393177Z INFO minijail0[14440]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFER: false
2024-04-26T14:15:50.393461Z WARNING minijail0[14439]: libminijail[14439]: failed to
create a ruleset: Function not implemented
2024-04-26T14:15:50.393488Z WARNING minijail0[14439]: libminijail[14439]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:15:50.630496Z INFO dbus-daemon[524]: [system] Successfully activated
service 'org.chromium.MachineLearning'
2024-04-26T14:17:25.284329Z INFO trunksd[743]: Finished saving contexts.
2024-04-26T14:17:30.281439Z NOTICE powerd_suspend[15184]: Going to suspend-to-RAM state:
args=-nosuspend_to_idle --wakeup_count=13705
2024-04-26T14:17:30.593101Z NOTICE powerd_suspend[15184]: Available order 3 pages: 47120
2024-04-26T14:17:30.602857Z NOTICE powerd_suspend[15184]: Finalizing suspend
2024-04-26T14:17:30.611206Z INFO kernel: [ 1121.755614] PM: suspend entry (s2idle)
2024-04-26T14:17:30.630363Z INFO kernel: [ 1121.774108] Filesystems sync: 0.017 seconds
2024-04-26T14:17:30.630437Z DEBUG kernel: [ 1121.775113] PM: Preparing system for sleep
(s2idle)
2024-04-26T14:25:34.972413Z INFO kernel: [ 1121.862330] Freezing user space processes ...
(elapsed 0.029 seconds) done.
2024-04-26T14:25:34.972576Z INFO kernel: [ 1121.893466] OOM killer disabled.
2024-04-26T14:25:34.973337Z INFO kernel: [ 1121.894121] Freezing remaining freezable
tasks ... (elapsed 0.007 seconds) done.
2024-04-26T14:25:34.973921Z DEBUG kernel: [ 1121.903202] PM: Suspending system (s2idle)
2024-04-26T14:25:35.075972Z INFO kernel: [ 1121.929429] rfkill rfkill0: PM: calling
rfkill_suspend+0x0/0x21 @ 15271, parent: hci0
2024-04-26T14:25:35.076031Z INFO kernel: [ 1121.932367] rfkill rfkill0: PM:
rfkill_suspend+0x0/0x21 returned 0 after 7 usecs
2024-04-26T14:25:35.076186Z INFO kernel: [ 1121.933674] input input10: PM: calling
input_dev_suspend+0x0/0x47 @ 15271, parent: card0
2024-04-26T14:25:35.076210Z INFO kernel: [ 1121.937755] input input10: PM:
input_dev_suspend+0x0/0x47 returned 0 after 708 usecs
2024-04-26T14:25:35.076234Z INFO kernel: [ 1121.939847] input input9: PM: calling
input_dev_suspend+0x0/0x47 @ 15271, parent: card0
2024-04-26T14:25:35.076254Z INFO kernel: [ 1121.941215] input input9: PM:
input_dev_suspend+0x0/0x47 returned 0 after 6 usecs
2024-04-26T14:25:35.076277Z INFO kernel: [ 1121.942484] input input8: PM: calling
input_dev_suspend+0x0/0x47 @ 15271, parent: card0
2024-04-26T14:25:35.076920Z INFO kernel: [ 1121.943886] input input8: PM:
input_dev_suspend+0x0/0x47 returned 0 after 6 usecs
2024-04-26T14:25:35.088435Z INFO kernel: [ 1121.945194] input input7: PM: calling
input_dev_suspend+0x0/0x47 @ 15271, parent: card0
2024-04-26T14:25:35.091932Z INFO kernel: [ 1121.946559] input input7: PM:
input_dev_suspend+0x0/0x47 returned 0 after 6 usecs
2024-04-26T14:25:35.091973Z INFO kernel: [ 1121.948876] input input6: PM: calling
input_dev_suspend+0x0/0x47 @ 15271, parent: card0
2024-04-26T14:25:35.091999Z INFO kernel: [ 1121.950511] input input6: PM:
input_dev_suspend+0x0/0x47 returned 0 after 6 usecs
2024-04-26T14:25:35.092144Z INFO kernel: [ 1121.952285] sound pcmC0D0c: PM: calling
do_pcm_suspend+0x0/0x23 @ 15271, parent: card0
2024-04-26T14:25:35.092172Z INFO kernel: [ 1121.955523] sound pcmC0D0c: PM:
do_pcm_suspend+0x0/0x23 returned 0 after 8 usecs
2024-04-26T14:25:35.092200Z INFO kernel: [ 1121.956750] sound pcmC0D0p: PM: calling
do_pcm_suspend+0x0/0x23 @ 15271, parent: card0
2024-04-26T14:25:35.092231Z INFO kernel: [ 1121.958072] sound pcmC0D0p: PM:
do_pcm_suspend+0x0/0x23 returned 0 after 6 usecs
2024-04-26T14:25:35.092327Z INFO kernel: [ 1121.962147] platform regulatory.0: PM:
calling platform_pm_suspend+0x0/0x4a @ 15271, parent: platform
2024-04-26T14:25:35.092354Z INFO kernel: [ 1121.960313] snd_hda_codec_generic
hdaudioC0D0: PM: calling hda_codec_pm_suspend+0x0/0x19 [snd_hda_codec] @ 774, parent:
0000:02:02.0
2024-04-26T14:25:35.092376Z INFO kernel: [ 1121.965072] platform regulatory.0: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 66 usecs
2024-04-26T14:25:35.092395Z INFO kernel: [ 1121.971134] usb 2-2.1: PM: calling
usb_dev_suspend+0x0/0x14 @ 15149, parent: 2-2
2024-04-26T14:25:35.092416Z INFO kernel: [ 1121.975076] input input5: PM: calling
input_dev_suspend+0x0/0x47 @ 15271, parent: 0003:0E0F:0003.0001
2024-04-26T14:25:35.092438Z INFO kernel: [ 1121.977134] input input5: PM:
input_dev_suspend+0x0/0x47 returned 0 after 7 usecs
2024-04-26T14:25:35.092462Z INFO kernel: [ 1121.977382] usb 2-2.1: PM:
```

```
usb_dev_suspend+0x0/0x14 returned 0 after 4189 usecs
2024-04-26T14:25:35.092485Z INFO kernel: [ 1121.979398] input input3: PM: calling
input_dev_suspend+0x0/0x47 @ 15271, parent: serio1
2024-04-26T14:25:35.092510Z INFO kernel: [ 1121.981031] usb 2-1: PM: calling
usb_dev_suspend+0x0/0x14 @ 15148, parent: usb2
2024-04-26T14:25:35.092615Z INFO kernel: [ 1121.981288] usb 2-2: PM: calling
usb_dev_suspend+0x0/0x14 @ 11601, parent: usb2
2024-04-26T14:25:35.092639Z INFO kernel: [ 1121.982258] input input3: PM:
input_dev_suspend+0x0/0x47 returned 0 after 8 usecs
2024-04-26T14:25:35.092661Z INFO kernel: [ 1121.986835] input input4: PM: calling
input_dev_suspend+0x0/0x47 @ 15271, parent: serio1
2024-04-26T14:25:35.092682Z INFO kernel: [ 1121.988343] input input4: PM:
input_dev_suspend+0x0/0x47 returned 0 after 7 usecs
2024-04-26T14:25:35.105527Z INFO kernel: [ 1121.990220] leds input1::scrolllock: PM:
calling led_suspend+0x0/0x3f @ 15271, parent: input1
2024-04-26T14:25:35.105583Z INFO kernel: [ 1121.993012] leds input1::scrolllock: PM:
led_suspend+0x0/0x3f returned 0 after 661 usecs
2024-04-26T14:25:35.105614Z INFO kernel: [ 1121.994803] leds input1::capslock: PM:
calling led_suspend+0x0/0x3f @ 15271, parent: input1
2024-04-26T14:25:35.105638Z INFO kernel: [ 1121.996235] leds input1::capslock: PM:
led_suspend+0x0/0x3f returned 0 after 8 usecs
2024-04-26T14:25:35.105661Z INFO kernel: [ 1121.997544] leds input1::numlock: PM: calling
led_suspend+0x0/0x3f @ 15271, parent: input1
2024-04-26T14:25:35.105684Z INFO kernel: [ 1121.998927] leds input1::numlock: PM:
led_suspend+0x0/0x3f returned 0 after 6 usecs
2024-04-26T14:25:35.105919Z INFO kernel: [ 1122.000938] input input1: PM: calling
input_dev_suspend+0x0/0x47 @ 15271, parent: serio0
2024-04-26T14:25:35.105946Z INFO kernel: [ 1122.003317] input input1: PM:
input_dev_suspend+0x0/0x47 returned 0 after 8 usecs
2024-04-26T14:25:35.105967Z INFO kernel: [ 1122.004673] alarmtimer alarmtimer.0.auto: PM:
calling platform_pm_suspend+0x0/0x4a @ 15271, parent: rtc0
2024-04-26T14:25:35.106734Z INFO kernel: [ 1122.008036] alarmtimer alarmtimer.0.auto: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 1744 usecs
2024-04-26T14:25:35.118002Z INFO kernel: [ 1122.010302] psmouse serio1: PM: calling
serio_suspend+0x0/0x1d @ 15271, parent: i8042
2024-04-26T14:25:35.118167Z INFO kernel: [ 1122.016246] psmouse serio1: PM:
serio_suspend+0x0/0x1d returned 0 after 3204 usecs
2024-04-26T14:25:35.118195Z INFO kernel: [ 1122.017662] atkbd serio0: PM: calling
serio_suspend+0x0/0x1d @ 15271, parent: i8042
2024-04-26T14:25:35.118916Z INFO kernel: [ 1122.019665] atkbd serio0: PM:
serio_suspend+0x0/0x1d returned 0 after 180 usecs
2024-04-26T14:25:35.118953Z INFO kernel: [ 1122.020920] i8042 i8042: PM: calling
platform_pm_suspend+0x0/0x4a @ 15271, parent: platform
2024-04-26T14:25:35.118979Z INFO kernel: [ 1122.022899] i8042 i8042: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 628 usecs
2024-04-26T14:25:35.119161Z INFO kernel: [ 1122.025222] usb usb1: PM: calling
usb_dev_suspend+0x0/0x14 @ 15149, parent: 0000:02:03.0
2024-04-26T14:25:35.119193Z INFO kernel: [ 1122.025476] platform Fixed MDIO bus.0: PM:
calling platform_pm_suspend+0x0/0x4a @ 15271, parent: platform
2024-04-26T14:25:35.119222Z INFO kernel: [ 1122.029049] platform Fixed MDIO bus.0: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 9 usecs
2024-04-26T14:25:35.119250Z INFO kernel: [ 1122.031287] ata2: PM: calling
ata_port_pm_suspend+0x0/0x3e @ 15151, parent: 0000:00:07.1
2024-04-26T14:25:35.119284Z INFO kernel: [ 1122.032240] usb 2-2: PM:
usb_dev_suspend+0x0/0x14 returned 0 after 50918 usecs
2024-04-26T14:25:35.119309Z INFO kernel: [ 1122.032270] usb 2-1: PM:
usb_dev_suspend+0x0/0x14 returned 0 after 48534 usecs
2024-04-26T14:25:35.119329Z INFO kernel: [ 1122.032446] ata1: PM: calling
ata_port_pm_suspend+0x0/0x3e @ 15148, parent: 0000:00:07.1
2024-04-26T14:25:35.119349Z INFO kernel: [ 1122.037766] ata2: PM:
ata_port_pm_suspend+0x0/0x3e returned 0 after 4394 usecs
2024-04-26T14:25:35.119459Z INFO kernel: [ 1122.038488] serial8250 serial8250: PM:
calling platform_pm_suspend+0x0/0x4a @ 15271, parent: platform
2024-04-26T14:25:35.119484Z INFO kernel: [ 1122.039322] serial8250 serial8250: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 335 usecs
2024-04-26T14:25:35.119506Z INFO kernel: [ 1122.039349] input input0: PM: calling
input_dev_suspend+0x0/0x47 @ 15271, parent: LNXPPWRBN:00
2024-04-26T14:25:35.119528Z INFO kernel: [ 1122.039396] input input0: PM:
input_dev_suspend+0x0/0x47 returned 0 after 13 usecs
```



```
2024-04-26T14:25:35.119549Z INFO kernel: [ 1122.039719] usb usb1: PM:
usb_dev_suspend+0x0/0x14 returned 0 after 12784 usecs
2024-04-26T14:25:35.119572Z INFO kernel: [ 1122.041398] platform intel_rapl_msr.0: PM:
calling platform_pm_suspend+0x0/0x4a @ 15271, parent: platform
2024-04-26T14:25:35.119609Z INFO kernel: [ 1122.041468] platform intel_rapl_msr.0: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 11 usecs
2024-04-26T14:25:35.119638Z INFO kernel: [ 1122.041689] usb usb2: PM: calling
usb_dev_suspend+0x0/0x14 @ 9, parent: 0000:02:00.0
2024-04-26T14:25:35.119665Z INFO kernel: [ 1122.041557] system 00:05: PM: calling
pnp_bus_suspend+0x0/0x14 @ 15271, parent: pnp0
2024-04-26T14:25:35.119690Z INFO kernel: [ 1122.043014] system 00:05: PM:
pnp_bus_suspend+0x0/0x14 returned 0 after 725 usecs
2024-04-26T14:25:35.119715Z INFO kernel: [ 1122.043031] system 00:04: PM: calling
pnp_bus_suspend+0x0/0x14 @ 15271, parent: pnp0
2024-04-26T14:25:35.119742Z INFO kernel: [ 1122.043059] system 00:04: PM:
pnp_bus_suspend+0x0/0x14 returned 0 after 8 usecs
2024-04-26T14:25:35.119769Z INFO kernel: [ 1122.043071] i8042 aux 00:03: PM: calling
pnp_bus_suspend+0x0/0x14 @ 15271, parent: pnp0
2024-04-26T14:25:35.119795Z INFO kernel: [ 1122.043409] i8042 aux 00:03: PM:
pnp_bus_suspend+0x0/0x14 returned 0 after 11 usecs
2024-04-26T14:25:35.119823Z INFO kernel: [ 1122.043424] i8042 kbd 00:02: PM: calling
pnp_bus_suspend+0x0/0x14 @ 15271, parent: pnp0
2024-04-26T14:25:35.119849Z INFO kernel: [ 1122.043873] i8042 kbd 00:02: PM:
pnp_bus_suspend+0x0/0x14 returned 0 after 11 usecs
2024-04-26T14:25:35.120444Z INFO kernel: [ 1122.043901] rtc_cmos 00:01: PM: calling
pnp_bus_suspend+0x0/0x14 @ 15271, parent: pnp0
2024-04-26T14:25:35.120476Z INFO kernel: [ 1122.044174] rtc_cmos 00:01: PM:
pnp_bus_suspend+0x0/0x14 returned 0 after 246 usecs
2024-04-26T14:25:35.124588Z INFO kernel: [ 1122.046170] usb usb2: PM:
usb_dev_suspend+0x0/0x14 returned 0 after 139 usecs
2024-04-26T14:25:35.124637Z INFO kernel: [ 1122.047788] system 00:00: PM: calling
pnp_bus_suspend+0x0/0x14 @ 15271, parent: pnp0
2024-04-26T14:25:35.124662Z INFO kernel: [ 1122.047817] system 00:00: PM:
pnp_bus_suspend+0x0/0x14 returned 0 after 8 usecs
2024-04-26T14:25:35.124687Z INFO kernel: [ 1122.047832] platform chromeos_acpi: PM:
calling platform_pm_suspend+0x0/0x4a @ 15271, parent: platform
2024-04-26T14:25:35.124711Z INFO kernel: [ 1122.049461] ata1: PM:
ata_port_pm_suspend+0x0/0x3e returned 0 after 16990 usecs
2024-04-26T14:25:35.124735Z INFO kernel: [ 1122.050905] platform chromeos_acpi: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 7 usecs
2024-04-26T14:25:35.124758Z INFO kernel: [ 1122.077994] platform efivars.0: PM: calling
platform_pm_suspend+0x0/0x4a @ 15271, parent: platform
2024-04-26T14:25:35.124782Z INFO kernel: [ 1122.079505] platform efivars.0: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 6 usecs
2024-04-26T14:25:35.124805Z INFO kernel: [ 1122.081142] platform rtc-efi.0: PM: calling
platform_pm_suspend+0x0/0x4a @ 15271, parent: platform
2024-04-26T14:25:35.124831Z INFO kernel: [ 1122.083419] platform rtc-efi.0: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 11 usecs
2024-04-26T14:25:35.124853Z INFO kernel: [ 1122.083507] snd_hda_codec_generic
hdaudioC0D0: PM: hda_codec_pm_suspend+0x0/0x19 [snd_hda_codec] returned 0 after 116224
usecs
2024-04-26T14:25:35.125207Z INFO kernel: [ 1122.085745] button LNX_PWRB0:00: PM: calling
acpi_button_suspend+0x0/0x19 @ 15271, parent: LNXSYSTM:00
2024-04-26T14:25:35.125272Z INFO kernel: [ 1122.091988] button LNX_PWRB0:00: PM:
acpi_button_suspend+0x0/0x19 returned 0 after 771 usecs
2024-04-26T14:25:35.125763Z INFO kernel: [ 1122.097097] platform ACPI0003:00: PM: calling
platform_pm_suspend+0x0/0x4a @ 15271, parent: platform
2024-04-26T14:25:35.125791Z INFO kernel: [ 1122.099674] platform ACPI0003:00: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 10 usecs
2024-04-26T14:25:35.125820Z INFO kernel: [ 1122.101484] platform PNP0800:00: PM: calling
platform_pm_suspend+0x0/0x4a @ 15271, parent: 0000:00:07.0
2024-04-26T14:25:35.125845Z INFO kernel: [ 1122.104139] platform PNP0800:00: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 11 usecs
2024-04-26T14:25:35.125927Z INFO kernel: [ 1122.106136] platform PNP0001:00: PM: calling
platform_pm_suspend+0x0/0x4a @ 15271, parent: 0000:00:07.0
2024-04-26T14:25:35.125956Z INFO kernel: [ 1122.108159] platform PNP0001:00: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 8 usecs
2024-04-26T14:25:35.125981Z INFO kernel: [ 1122.110685] nvme 0000:03:00.0: PM: calling
pci_pm_suspend+0x0/0x1da @ 774, parent: 0000:00:15.0
```

```
2024-04-26T14:25:35.144899Z INFO kernel: [ 1122.110813] ehci-pci 0000:02:03.0: PM:
calling pci_pm_suspend+0x0/0x1da @ 15151, parent: 0000:00:11.0
2024-04-26T14:25:35.144954Z INFO kernel: [ 1122.116053] ehci-pci 0000:02:03.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 2306 usecs
2024-04-26T14:25:35.144991Z INFO kernel: [ 1122.118268] snd_hda_intel 0000:02:02.0: PM:
calling pci_pm_suspend+0x0/0x1da @ 15151, parent: 0000:00:11.0
2024-04-26T14:25:35.145030Z INFO kernel: [ 1122.121104] e1000 0000:02:01.0: PM: calling
pci_pm_suspend+0x0/0x1da @ 15148, parent: 0000:00:11.0
2024-04-26T14:25:35.145270Z INFO kernel: [ 1122.125110] pcieport 0000:00:18.7: PM:
calling pci_pm_suspend+0x0/0x1da @ 15150, parent: pci0000:00
2024-04-26T14:25:35.145302Z INFO kernel: [ 1122.125350] pcieport 0000:00:18.6: PM:
calling pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.145329Z INFO kernel: [ 1122.125903] pcieport 0000:00:18.5: PM:
calling pci_pm_suspend+0x0/0x1da @ 11601, parent: pci0000:00
2024-04-26T14:25:35.145356Z INFO kernel: [ 1122.128450] pcieport 0000:00:18.5: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 2452 usecs
2024-04-26T14:25:35.145447Z INFO kernel: [ 1122.129293] pcieport 0000:00:18.7: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 1540 usecs
2024-04-26T14:25:35.145475Z INFO kernel: [ 1122.129337] pcieport 0000:00:18.4: PM:
calling pci_pm_suspend+0x0/0x1da @ 15150, parent: pci0000:00
2024-04-26T14:25:35.145503Z INFO kernel: [ 1122.130121] pcieport 0000:00:18.4: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 755 usecs
2024-04-26T14:25:35.184984Z INFO kernel: [ 1122.130163] pcieport 0000:00:18.3: PM:
calling pci_pm_suspend+0x0/0x1da @ 15150, parent: pci0000:00
2024-04-26T14:25:35.185182Z INFO kernel: [ 1122.130422] pcieport 0000:00:18.3: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 226 usecs
2024-04-26T14:25:35.185212Z INFO kernel: [ 1122.130454] pcieport 0000:00:18.2: PM:
calling pci_pm_suspend+0x0/0x1da @ 15150, parent: pci0000:00
2024-04-26T14:25:35.185238Z INFO kernel: [ 1122.130798] pcieport 0000:00:18.2: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 312 usecs
2024-04-26T14:25:35.185261Z INFO kernel: [ 1122.132559] pcieport 0000:00:18.6: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 201 usecs
2024-04-26T14:25:35.185284Z INFO kernel: [ 1122.132656] pcieport 0000:00:18.1: PM:
calling pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.185412Z INFO kernel: [ 1122.132864] pcieport 0000:00:18.1: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 185 usecs
2024-04-26T14:25:35.185436Z INFO kernel: [ 1122.132891] pcieport 0000:00:18.0: PM:
calling pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.185461Z INFO kernel: [ 1122.133078] pcieport 0000:00:18.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 163 usecs
2024-04-26T14:25:35.185484Z INFO kernel: [ 1122.133102] pcieport 0000:00:17.7: PM:
calling pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.185505Z INFO kernel: [ 1122.133298] pcieport 0000:00:17.7: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 172 usecs
2024-04-26T14:25:35.185527Z INFO kernel: [ 1122.133329] pcieport 0000:00:17.6: PM:
calling pci_pm_suspend+0x0/0x1da @ 11601, parent: pci0000:00
2024-04-26T14:25:35.185552Z INFO kernel: [ 1122.133666] pcieport 0000:00:17.6: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 310 usecs
2024-04-26T14:25:35.185579Z INFO kernel: [ 1122.133694] pcieport 0000:00:17.5: PM:
calling pci_pm_suspend+0x0/0x1da @ 11601, parent: pci0000:00
2024-04-26T14:25:35.185606Z INFO kernel: [ 1122.134141] pcieport 0000:00:17.5: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 422 usecs
2024-04-26T14:25:35.185633Z INFO kernel: [ 1122.134177] pcieport 0000:00:17.4: PM:
calling pci_pm_suspend+0x0/0x1da @ 11601, parent: pci0000:00
2024-04-26T14:25:35.185658Z INFO kernel: [ 1122.134401] pcieport 0000:00:17.4: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 197 usecs
2024-04-26T14:25:35.185682Z INFO kernel: [ 1122.134431] pcieport 0000:00:17.3: PM:
calling pci_pm_suspend+0x0/0x1da @ 11601, parent: pci0000:00
2024-04-26T14:25:35.185708Z INFO kernel: [ 1122.134779] pcieport 0000:00:17.2: PM:
calling pci_pm_suspend+0x0/0x1da @ 80, parent: pci0000:00
2024-04-26T14:25:35.185733Z INFO kernel: [ 1122.135769] uhci_hcd 0000:02:00.0: PM:
calling pci_pm_suspend+0x0/0x1da @ 9, parent: 0000:00:11.0
2024-04-26T14:25:35.185758Z INFO kernel: [ 1122.136829] pcieport 0000:00:17.2: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 2023 usecs
2024-04-26T14:25:35.185784Z INFO kernel: [ 1122.136864] pcieport 0000:00:17.1: PM:
calling pci_pm_suspend+0x0/0x1da @ 80, parent: pci0000:00
2024-04-26T14:25:35.185811Z INFO kernel: [ 1122.137133] pcieport 0000:00:17.1: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 211 usecs
2024-04-26T14:25:35.185836Z INFO kernel: [ 1122.137163] pcieport 0000:00:17.0: PM:
```

```
calling pci_pm_suspend+0x0/0x1da @ 80, parent: pci0000:00
2024-04-26T14:25:35.185861Z INFO kernel: [ 1122.137363] pcieport 0000:00:17.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 176 usecs
2024-04-26T14:25:35.185884Z INFO kernel: [ 1122.137393] pcieport 0000:00:16.7: PM:
calling pci_pm_suspend+0x0/0x1da @ 80, parent: pci0000:00
2024-04-26T14:25:35.185904Z INFO kernel: [ 1122.137663] pcieport 0000:00:16.7: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 246 usecs
2024-04-26T14:25:35.185929Z INFO kernel: [ 1122.137691] pcieport 0000:00:16.6: PM:
calling pci_pm_suspend+0x0/0x1da @ 80, parent: pci0000:00
2024-04-26T14:25:35.185954Z INFO kernel: [ 1122.137890] pcieport 0000:00:16.6: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 175 usecs
2024-04-26T14:25:35.185978Z INFO kernel: [ 1122.137919] pcieport 0000:00:16.5: PM:
calling pci_pm_suspend+0x0/0x1da @ 80, parent: pci0000:00
2024-04-26T14:25:35.186002Z INFO kernel: [ 1122.138133] pcieport 0000:00:16.5: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 190 usecs
2024-04-26T14:25:35.186146Z INFO kernel: [ 1122.138368] pcieport 0000:00:16.4: PM:
calling pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.186174Z INFO kernel: [ 1122.138684] pcieport 0000:00:16.4: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 285 usecs
2024-04-26T14:25:35.186198Z INFO kernel: [ 1122.138719] pcieport 0000:00:16.3: PM:
calling pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.186280Z INFO kernel: [ 1122.138946] pcieport 0000:00:16.3: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 200 usecs
2024-04-26T14:25:35.186306Z INFO kernel: [ 1122.138979] pcieport 0000:00:16.2: PM:
calling pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.186331Z INFO kernel: [ 1122.139227] pcieport 0000:00:16.2: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 219 usecs
2024-04-26T14:25:35.186355Z INFO kernel: [ 1122.139262] pcieport 0000:00:16.1: PM:
calling pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.186377Z INFO kernel: [ 1122.139492] pcieport 0000:00:16.1: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 201 usecs
2024-04-26T14:25:35.186400Z INFO kernel: [ 1122.139525] pcieport 0000:00:16.0: PM:
calling pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.186498Z INFO kernel: [ 1122.139833] pcieport 0000:00:16.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 278 usecs
2024-04-26T14:25:35.186532Z INFO kernel: [ 1122.139866] pcieport 0000:00:15.7: PM:
calling pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.186558Z INFO kernel: [ 1122.140135] pcieport 0000:00:15.7: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 197 usecs
2024-04-26T14:25:35.186585Z INFO kernel: [ 1122.140168] pcieport 0000:00:15.6: PM:
calling pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.186612Z INFO kernel: [ 1122.140404] pcieport 0000:00:15.6: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 208 usecs
2024-04-26T14:25:35.186639Z INFO kernel: [ 1122.140438] pcieport 0000:00:15.5: PM:
calling pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.186723Z INFO kernel: [ 1122.140740] pcieport 0000:00:15.5: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 273 usecs
2024-04-26T14:25:35.186750Z INFO kernel: [ 1122.140773] pcieport 0000:00:15.4: PM:
calling pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.186774Z INFO kernel: [ 1122.140836] pcieport 0000:00:15.3: PM:
calling pci_pm_suspend+0x0/0x1da @ 15150, parent: pci0000:00
2024-04-26T14:25:35.186799Z INFO kernel: [ 1122.140981] pcieport 0000:00:15.4: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 181 usecs
2024-04-26T14:25:35.186822Z INFO kernel: [ 1122.141009] pcieport 0000:00:15.2: PM:
calling pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.186845Z INFO kernel: [ 1122.143121] pcieport 0000:00:15.1: PM:
calling pci_pm_suspend+0x0/0x1da @ 80, parent: pci0000:00
2024-04-26T14:25:35.186913Z INFO kernel: [ 1122.158024] pcieport 0000:00:15.3: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 595 usecs
2024-04-26T14:25:35.186939Z INFO kernel: [ 1122.161047] pcieport 0000:00:17.3: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 26590 usecs
2024-04-26T14:25:35.186962Z INFO kernel: [ 1122.161293] pcieport 0000:00:15.1: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 185 usecs
2024-04-26T14:25:35.186986Z INFO kernel: [ 1122.164859] uhci_hcd 0000:02:00.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 19366 usecs
2024-04-26T14:25:35.191886Z INFO kernel: [ 1122.168022] pci 0000:00:10.0: PM: calling
pci_pm_suspend+0x0/0x1da @ 80, parent: pci0000:00
2024-04-26T14:25:35.191939Z INFO kernel: [ 1122.168056] pcieport 0000:00:15.2: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 27021 usecs
```

```
2024-04-26T14:25:35.191964Z INFO kernel: [ 1122.168068] pci 0000:00:10.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 12 usecs
2024-04-26T14:25:35.192546Z INFO kernel: [ 1122.168090] vmwgfx 0000:00:0f.0: PM: calling
pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.192581Z INFO kernel: [ 1122.170221] vmwgfx 0000:00:0f.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 2044 usecs
2024-04-26T14:25:35.192605Z INFO kernel: [ 1122.170306] vmw_vmci 0000:00:07.7: PM:
calling pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.192630Z INFO kernel: [ 1122.171079] snd_hda_intel 0000:02:02.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 10315 usecs
2024-04-26T14:25:35.192656Z INFO kernel: [ 1122.171141] pci 0000:00:07.3: PM: calling
pci_pm_suspend+0x0/0x1da @ 15151, parent: pci0000:00
2024-04-26T14:25:35.192682Z INFO kernel: [ 1122.171176] pci 0000:00:07.3: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 10 usecs
2024-04-26T14:25:35.192719Z INFO kernel: [ 1122.171259] ata_piix 0000:00:07.1: PM:
calling pci_pm_suspend+0x0/0x1da @ 15151, parent: pci0000:00
2024-04-26T14:25:35.192798Z INFO kernel: [ 1122.173529] vmw_vmci 0000:00:07.7: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 3193 usecs
2024-04-26T14:25:35.192828Z INFO kernel: [ 1122.173777] pci 0000:00:07.0: PM: calling
pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.192851Z INFO kernel: [ 1122.173814] pci 0000:00:07.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 10 usecs
2024-04-26T14:25:35.192872Z INFO kernel: [ 1122.173841] pci 0000:00:01.0: PM: calling
pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.192925Z INFO kernel: [ 1122.173873] pci 0000:00:01.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 9 usecs
2024-04-26T14:25:35.193004Z INFO kernel: [ 1122.173897] pci 0000:00:00.0: PM: calling
pci_pm_suspend+0x0/0x1da @ 15149, parent: pci0000:00
2024-04-26T14:25:35.193160Z INFO kernel: [ 1122.173930] pci 0000:00:00.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 9 usecs
2024-04-26T14:25:35.193183Z INFO kernel: [ 1122.177357] ata_piix 0000:00:07.1: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 6067 usecs
2024-04-26T14:25:35.193223Z INFO kernel: [ 1122.190477] nvme 0000:03:00.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 74181 usecs
2024-04-26T14:25:35.193248Z INFO kernel: [ 1122.232769] e1000 0000:02:01.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 109184 usecs
2024-04-26T14:25:35.193272Z INFO kernel: [ 1122.233953] pcieport 0000:00:15.0: PM:
calling pci_pm_suspend+0x0/0x1da @ 11601, parent: pci0000:00
2024-04-26T14:25:35.193294Z INFO kernel: [ 1122.236021] pci 0000:00:11.0: PM: calling
pci_pm_suspend+0x0/0x1da @ 15150, parent: pci0000:00
2024-04-26T14:25:35.196408Z INFO kernel: [ 1122.242086] pcieport 0000:00:15.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 233 usecs
2024-04-26T14:25:35.196448Z INFO kernel: [ 1122.243882] pci 0000:00:11.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 8 usecs
2024-04-26T14:25:35.196472Z DEBUG kernel: [ 1122.386557] PM: suspend of devices complete
after 468.497 msecs
2024-04-26T14:25:35.196494Z DEBUG kernel: [ 1122.386587] PM: start suspend of devices
complete after 482.699 msecs
2024-04-26T14:25:35.196516Z INFO kernel: [ 1122.392100] nvme 0000:03:00.0: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 15149, parent: 0000:00:15.0
2024-04-26T14:25:35.196540Z INFO kernel: [ 1122.392104] snd_hda_intel 0000:02:02.0: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 80, parent: 0000:00:11.0
2024-04-26T14:25:35.196618Z INFO kernel: [ 1122.392104] e1000 0000:02:01.0: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 15273, parent: 0000:00:11.0
2024-04-26T14:25:35.196646Z INFO kernel: [ 1122.392209] nvme 0000:03:00.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 72 usecs
2024-04-26T14:25:35.202656Z INFO kernel: [ 1122.392379] snd_hda_intel 0000:02:02.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 241 usecs
2024-04-26T14:25:35.202707Z INFO kernel: [ 1122.392483] pcieport 0000:00:18.7: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.202734Z INFO kernel: [ 1122.392552] pcieport 0000:00:18.7: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 10 usecs
2024-04-26T14:25:35.202759Z INFO kernel: [ 1122.392647] pcieport 0000:00:18.6: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.202924Z INFO kernel: [ 1122.392678] pcieport 0000:00:18.6: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.202954Z INFO kernel: [ 1122.392712] pcieport 0000:00:18.5: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.202982Z INFO kernel: [ 1122.392743] pcieport 0000:00:18.5: PM:
```

```
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.220942Z INFO kernel: [ 1122.392775] pcieport 0000:00:18.4: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.220997Z INFO kernel: [ 1122.392806] pcieport 0000:00:18.4: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.221191Z INFO kernel: [ 1122.392840] pcieport 0000:00:18.3: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.221288Z INFO kernel: [ 1122.392870] pcieport 0000:00:18.3: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.221316Z INFO kernel: [ 1122.392903] pcieport 0000:00:18.2: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.221343Z INFO kernel: [ 1122.392934] pcieport 0000:00:18.2: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.221369Z INFO kernel: [ 1122.392977] pcieport 0000:00:18.1: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.221393Z INFO kernel: [ 1122.393008] pcieport 0000:00:18.1: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.221418Z INFO kernel: [ 1122.393041] pcieport 0000:00:18.0: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.221496Z INFO kernel: [ 1122.393071] pcieport 0000:00:18.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.221521Z INFO kernel: [ 1122.393104] pcieport 0000:00:17.7: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.221543Z INFO kernel: [ 1122.393135] pcieport 0000:00:17.7: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.221565Z INFO kernel: [ 1122.393167] pcieport 0000:00:17.6: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.221587Z INFO kernel: [ 1122.393198] pcieport 0000:00:17.6: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.221612Z INFO kernel: [ 1122.393230] pcieport 0000:00:17.5: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.221640Z INFO kernel: [ 1122.393287] pcieport 0000:00:17.5: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.221663Z INFO kernel: [ 1122.393342] pcieport 0000:00:17.4: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.221685Z INFO kernel: [ 1122.393373] pcieport 0000:00:17.4: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.221710Z INFO kernel: [ 1122.393406] pcieport 0000:00:17.3: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.221738Z INFO kernel: [ 1122.393436] pcieport 0000:00:17.3: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.221761Z INFO kernel: [ 1122.393469] pcieport 0000:00:17.2: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.221784Z INFO kernel: [ 1122.393500] pcieport 0000:00:17.2: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.221852Z INFO kernel: [ 1122.393532] pcieport 0000:00:17.1: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.221874Z INFO kernel: [ 1122.393563] pcieport 0000:00:17.1: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.221893Z INFO kernel: [ 1122.393664] pcieport 0000:00:17.0: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.221913Z INFO kernel: [ 1122.393695] pcieport 0000:00:17.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.221936Z INFO kernel: [ 1122.393728] pcieport 0000:00:16.7: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.221962Z INFO kernel: [ 1122.393759] pcieport 0000:00:16.7: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.222163Z INFO kernel: [ 1122.393792] pcieport 0000:00:16.6: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.222192Z INFO kernel: [ 1122.393822] pcieport 0000:00:16.6: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.222218Z INFO kernel: [ 1122.393855] pcieport 0000:00:16.5: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.222240Z INFO kernel: [ 1122.393886] pcieport 0000:00:16.5: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.222260Z INFO kernel: [ 1122.393919] pcieport 0000:00:16.4: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.222284Z INFO kernel: [ 1122.393949] pcieport 0000:00:16.4: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
```

2024-04-26T14:25:35.222354Z INFO kernel: [1122.393982] pcieport 0000:00:16.3: PM: calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00

2024-04-26T14:25:35.222377Z INFO kernel: [1122.394013] pcieport 0000:00:16.3: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs

2024-04-26T14:25:35.222396Z INFO kernel: [1122.394045] pcieport 0000:00:16.2: PM: calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00

2024-04-26T14:25:35.222416Z INFO kernel: [1122.394076] pcieport 0000:00:16.2: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs

2024-04-26T14:25:35.222436Z INFO kernel: [1122.394109] pcieport 0000:00:16.1: PM: calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00

2024-04-26T14:25:35.222507Z INFO kernel: [1122.394140] pcieport 0000:00:16.1: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs

2024-04-26T14:25:35.222531Z INFO kernel: [1122.394181] pcieport 0000:00:16.0: PM: calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00

2024-04-26T14:25:35.222828Z INFO kernel: [1122.394213] e1000 0000:02:01.0: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 8 usecs

2024-04-26T14:25:35.222854Z INFO kernel: [1122.394220] pcieport 0000:00:16.0: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 11 usecs

2024-04-26T14:25:35.225608Z INFO kernel: [1122.394292] pcieport 0000:00:15.7: PM: calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00

2024-04-26T14:25:35.225848Z INFO kernel: [1122.394332] pcieport 0000:00:15.7: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 12 usecs

2024-04-26T14:25:35.225885Z INFO kernel: [1122.394375] pcieport 0000:00:15.6: PM: calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00

2024-04-26T14:25:35.226174Z INFO kernel: [1122.394414] pcieport 0000:00:15.6: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 11 usecs

2024-04-26T14:25:35.226200Z INFO kernel: [1122.394456] pcieport 0000:00:15.5: PM: calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00

2024-04-26T14:25:35.226222Z INFO kernel: [1122.394493] pcieport 0000:00:15.5: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 11 usecs

2024-04-26T14:25:35.226245Z INFO kernel: [1122.394535] pcieport 0000:00:15.4: PM: calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00

2024-04-26T14:25:35.226270Z INFO kernel: [1122.394573] pcieport 0000:00:15.4: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 11 usecs

2024-04-26T14:25:35.226293Z INFO kernel: [1122.394709] pcieport 0000:00:15.3: PM: calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00

2024-04-26T14:25:35.226315Z INFO kernel: [1122.394748] pcieport 0000:00:15.3: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 11 usecs

2024-04-26T14:25:35.226339Z INFO kernel: [1122.394789] pcieport 0000:00:15.2: PM: calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00

2024-04-26T14:25:35.226430Z INFO kernel: [1122.394827] pcieport 0000:00:15.2: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 11 usecs

2024-04-26T14:25:35.226454Z INFO kernel: [1122.394868] pcieport 0000:00:15.1: PM: calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00

2024-04-26T14:25:35.226477Z INFO kernel: [1122.394941] pcieport 0000:00:15.1: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 12 usecs

2024-04-26T14:25:35.226499Z INFO kernel: [1122.395859] pci 0000:00:10.0: PM: calling pci_pm_suspend_late+0x0/0x3a @ 15275, parent: pci0000:00

2024-04-26T14:25:35.226522Z INFO kernel: [1122.395902] pci 0000:00:10.0: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 12 usecs

2024-04-26T14:25:35.226603Z INFO kernel: [1122.395957] vmwgfx 0000:00:0f.0: PM: calling pci_pm_suspend_late+0x0/0x3a @ 15275, parent: pci0000:00

2024-04-26T14:25:35.226642Z INFO kernel: [1122.395997] vmwgfx 0000:00:0f.0: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 12 usecs

2024-04-26T14:25:35.226674Z INFO kernel: [1122.396037] vmw_vmci 0000:00:07.7: PM: calling pci_pm_suspend_late+0x0/0x3a @ 15275, parent: pci0000:00

2024-04-26T14:25:35.226699Z INFO kernel: [1122.396076] vmw_vmci 0000:00:07.7: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 11 usecs

2024-04-26T14:25:35.226757Z INFO kernel: [1122.396116] pci 0000:00:07.3: PM: calling pci_pm_suspend_late+0x0/0x3a @ 15275, parent: pci0000:00

2024-04-26T14:25:35.226786Z INFO kernel: [1122.396155] pci 0000:00:07.3: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 11 usecs

2024-04-26T14:25:35.226884Z INFO kernel: [1122.396195] ata_piix 0000:00:07.1: PM: calling pci_pm_suspend_late+0x0/0x3a @ 15275, parent: pci0000:00

2024-04-26T14:25:35.226914Z INFO kernel: [1122.396235] ata_piix 0000:00:07.1: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 11 usecs

2024-04-26T14:25:35.226940Z INFO kernel: [1122.396276] pci 0000:00:07.0: PM: calling pci_pm_suspend_late+0x0/0x3a @ 15275, parent: pci0000:00

2024-04-26T14:25:35.226965Z INFO kernel: [1122.396316] pci 0000:00:07.0: PM:

```
pci_pm_suspend_late+0x0/0x3a returned 0 after 12 usecs
2024-04-26T14:25:35.226991Z INFO kernel: [ 1122.396359] pci 0000:00:01.0: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 15275, parent: pci0000:00
2024-04-26T14:25:35.227241Z INFO kernel: [ 1122.396399] pci 0000:00:01.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 12 usecs
2024-04-26T14:25:35.227325Z INFO kernel: [ 1122.396440] pci 0000:00:00.0: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 15275, parent: pci0000:00
2024-04-26T14:25:35.227355Z INFO kernel: [ 1122.396478] pci 0000:00:00.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 11 usecs
2024-04-26T14:25:35.227382Z INFO kernel: [ 1122.397202] pcieport 0000:00:15.0: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T14:25:35.227763Z INFO kernel: [ 1122.397464] uhci_hcd 0000:02:00.0: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 80, parent: 0000:00:11.0
2024-04-26T14:25:35.227796Z INFO kernel: [ 1122.397504] uhci_hcd 0000:02:00.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 10 usecs
2024-04-26T14:25:35.227821Z INFO kernel: [ 1122.405549] ehci-pci 0000:02:03.0: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 15272, parent: 0000:00:11.0
2024-04-26T14:25:35.227958Z INFO kernel: [ 1122.405656] ehci-pci 0000:02:03.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 71 usecs
2024-04-26T14:25:35.227995Z INFO kernel: [ 1122.409004] pcieport 0000:00:15.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.228223Z INFO kernel: [ 1122.410858] pci 0000:00:11.0: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 15274, parent: pci0000:00
2024-04-26T14:25:35.228249Z INFO kernel: [ 1122.601311] pci 0000:00:11.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 9 usecs
2024-04-26T14:25:35.228274Z DEBUG kernel: [ 1122.603129] PM: late suspend of devices
complete after 216.518 msecs
2024-04-26T14:25:35.228298Z INFO kernel: [ 1122.607146] nvme 0000:03:00.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 15148, parent: 0000:00:15.0
2024-04-26T14:25:35.228322Z INFO kernel: [ 1122.607157] ehci-pci 0000:02:03.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: 0000:00:11.0
2024-04-26T14:25:35.228346Z INFO kernel: [ 1122.607198] snd_hda_intel 0000:02:02.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15275, parent: 0000:00:11.0
2024-04-26T14:25:35.228370Z INFO kernel: [ 1122.608080] e1000 0000:02:01.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 15273, parent: 0000:00:11.0
2024-04-26T14:25:35.228454Z INFO kernel: [ 1122.609015] uhci_hcd 0000:02:00.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15274, parent: 0000:00:11.0
2024-04-26T14:25:35.228481Z INFO kernel: [ 1122.609799] uhci_hcd 0000:02:00.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 747 usecs
2024-04-26T14:25:35.228507Z INFO kernel: [ 1122.609871] pcieport 0000:00:18.6: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15274, parent: pci0000:00
2024-04-26T14:25:35.228534Z INFO kernel: [ 1122.611761] pcieport 0000:00:18.5: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15272, parent: pci0000:00
2024-04-26T14:25:35.228559Z INFO kernel: [ 1122.611831] pcieport 0000:00:18.7: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 9, parent: pci0000:00
2024-04-26T14:25:35.246727Z INFO kernel: [ 1122.611868] pcieport 0000:00:18.6: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1966 usecs
2024-04-26T14:25:35.250627Z INFO kernel: [ 1122.611907] pcieport 0000:00:18.4: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15274, parent: pci0000:00
2024-04-26T14:25:35.250665Z INFO kernel: [ 1122.612839] pcieport 0000:00:18.7: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 981 usecs
2024-04-26T14:25:35.250693Z INFO kernel: [ 1122.613240] pcieport 0000:00:18.4: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1303 usecs
2024-04-26T14:25:35.250716Z INFO kernel: [ 1122.613275] pcieport 0000:00:18.3: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15274, parent: pci0000:00
2024-04-26T14:25:35.250740Z INFO kernel: [ 1122.613433] ehci-pci 0000:02:03.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 676 usecs
2024-04-26T14:25:35.250765Z INFO kernel: [ 1122.613508] pcieport 0000:00:18.2: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.250791Z INFO kernel: [ 1122.614302] pcieport 0000:00:18.3: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 998 usecs
2024-04-26T14:25:35.250816Z INFO kernel: [ 1122.614335] pcieport 0000:00:18.1: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15274, parent: pci0000:00
2024-04-26T14:25:35.250841Z INFO kernel: [ 1122.614950] pcieport 0000:00:18.2: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1412 usecs
2024-04-26T14:25:35.250868Z INFO kernel: [ 1122.614984] pcieport 0000:00:18.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.250896Z INFO kernel: [ 1122.615298] pcieport 0000:00:18.1: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 934 usecs
```

```
2024-04-26T14:25:35.250930Z INFO kernel: [ 1122.615332] pcieport 0000:00:17.7: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15274, parent: pci0000:00
2024-04-26T14:25:35.250961Z INFO kernel: [ 1122.616519] pcieport 0000:00:18.5: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1173 usecs
2024-04-26T14:25:35.250990Z INFO kernel: [ 1122.616555] pcieport 0000:00:17.6: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15272, parent: pci0000:00
2024-04-26T14:25:35.251196Z INFO kernel: [ 1122.617308] pcieport 0000:00:17.4: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 80, parent: pci0000:00
2024-04-26T14:25:35.251228Z INFO kernel: [ 1122.618042] pcieport 0000:00:18.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 3029 usecs
2024-04-26T14:25:35.251256Z INFO kernel: [ 1122.618104] pcieport 0000:00:17.3: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.251933Z INFO kernel: [ 1122.618815] pcieport 0000:00:17.4: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1477 usecs
2024-04-26T14:25:35.251970Z INFO kernel: [ 1122.618851] pcieport 0000:00:17.2: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 80, parent: pci0000:00
2024-04-26T14:25:35.251998Z INFO kernel: [ 1122.619182] pcieport 0000:00:17.3: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1055 usecs
2024-04-26T14:25:35.252186Z INFO kernel: [ 1122.619221] pcieport 0000:00:17.1: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.252217Z INFO kernel: [ 1122.620040] pcieport 0000:00:17.2: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1157 usecs
2024-04-26T14:25:35.252244Z INFO kernel: [ 1122.620076] pcieport 0000:00:17.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 80, parent: pci0000:00
2024-04-26T14:25:35.252272Z INFO kernel: [ 1122.620207] snd_hda_intel 0000:02:02.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 12980 usecs
2024-04-26T14:25:35.252299Z INFO kernel: [ 1122.620241] pcieport 0000:00:16.7: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15275, parent: pci0000:00
2024-04-26T14:25:35.252325Z INFO kernel: [ 1122.620493] pcieport 0000:00:17.1: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1249 usecs
2024-04-26T14:25:35.252360Z INFO kernel: [ 1122.620519] pcieport 0000:00:16.6: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.252387Z INFO kernel: [ 1122.621369] pcieport 0000:00:16.7: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1098 usecs
2024-04-26T14:25:35.252414Z INFO kernel: [ 1122.621402] pcieport 0000:00:16.5: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15275, parent: pci0000:00
2024-04-26T14:25:35.252440Z INFO kernel: [ 1122.621817] pcieport 0000:00:16.6: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1275 usecs
2024-04-26T14:25:35.252463Z INFO kernel: [ 1122.621845] pcieport 0000:00:16.4: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.252689Z INFO kernel: [ 1122.622480] pcieport 0000:00:16.5: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1049 usecs
2024-04-26T14:25:35.252720Z INFO kernel: [ 1122.622515] pcieport 0000:00:16.3: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15275, parent: pci0000:00
2024-04-26T14:25:35.252745Z INFO kernel: [ 1122.622904] pcieport 0000:00:16.4: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1036 usecs
2024-04-26T14:25:35.252770Z INFO kernel: [ 1122.622929] pcieport 0000:00:16.2: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.252795Z INFO kernel: [ 1122.623038] pcieport 0000:00:16.1: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15150, parent: pci0000:00
2024-04-26T14:25:35.252817Z INFO kernel: [ 1122.623536] pcieport 0000:00:16.3: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 994 usecs
2024-04-26T14:25:35.252840Z INFO kernel: [ 1122.623562] pcieport 0000:00:16.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15275, parent: pci0000:00
2024-04-26T14:25:35.252862Z INFO kernel: [ 1122.623733] e1000 0000:02:01.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 15607 usecs
2024-04-26T14:25:35.252883Z INFO kernel: [ 1122.623758] pcieport 0000:00:15.7: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15273, parent: pci0000:00
2024-04-26T14:25:35.252907Z INFO kernel: [ 1122.624163] pcieport 0000:00:16.2: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1207 usecs
2024-04-26T14:25:35.252941Z INFO kernel: [ 1122.624196] pcieport 0000:00:15.6: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.252968Z INFO kernel: [ 1122.625715] pcieport 0000:00:15.6: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1465 usecs
2024-04-26T14:25:35.252999Z INFO kernel: [ 1122.626075] pcieport 0000:00:17.5: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15151, parent: pci0000:00
2024-04-26T14:25:35.253179Z INFO kernel: [ 1122.626517] pcieport 0000:00:15.5: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.253211Z INFO kernel: [ 1122.627172] pcieport 0000:00:15.5: PM:
```



```
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 627 usecs
2024-04-26T14:25:35.253238Z INFO kernel: [ 1122.627241] pcieport 0000:00:15.4: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.253264Z INFO kernel: [ 1122.627254] pcieport 0000:00:15.7: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 3470 usecs
2024-04-26T14:25:35.253287Z INFO kernel: [ 1122.627293] pcieport 0000:00:15.3: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15273, parent: pci0000:00
2024-04-26T14:25:35.253313Z INFO kernel: [ 1122.628326] pcieport 0000:00:15.4: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1061 usecs
2024-04-26T14:25:35.253339Z INFO kernel: [ 1122.628351] pcieport 0000:00:15.2: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.253365Z INFO kernel: [ 1122.628498] pcieport 0000:00:15.3: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1175 usecs
2024-04-26T14:25:35.253389Z INFO kernel: [ 1122.628532] pcieport 0000:00:15.1: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 15273, parent: pci0000:00
2024-04-26T14:25:35.253415Z INFO kernel: [ 1122.629761] pci 0000:00:11.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 15149, parent: pci0000:00
2024-04-26T14:25:35.253442Z INFO kernel: [ 1122.629936] pcieport 0000:00:15.2: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1560 usecs
2024-04-26T14:25:35.253468Z INFO kernel: [ 1122.629967] pci 0000:00:10.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.253492Z INFO kernel: [ 1122.631437] pcieport 0000:00:16.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 7850 usecs
2024-04-26T14:25:35.253514Z INFO kernel: [ 1122.631471] vmwgfx 0000:00:0f.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 15275, parent: pci0000:00
2024-04-26T14:25:35.253537Z INFO kernel: [ 1122.631496] pci 0000:00:10.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1501 usecs
2024-04-26T14:25:35.253617Z INFO kernel: [ 1122.631527] vmw_vmci 0000:00:07.7: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.253642Z INFO kernel: [ 1122.631782] nvme 0000:03:00.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 21633 usecs
2024-04-26T14:25:35.253661Z INFO kernel: [ 1122.631859] pci 0000:00:07.3: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 15148, parent: pci0000:00
2024-04-26T14:25:35.253682Z INFO kernel: [ 1122.632087] vmw_vmci 0000:00:07.7: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 532 usecs
2024-04-26T14:25:35.253703Z INFO kernel: [ 1122.632121] ata_piix 0000:00:07.1: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.253724Z INFO kernel: [ 1122.632161] ata_piix 0000:00:07.1: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 12 usecs
2024-04-26T14:25:35.253802Z INFO kernel: [ 1122.632193] pci 0000:00:07.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.253831Z INFO kernel: [ 1122.632747] pci 0000:00:07.3: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 858 usecs
2024-04-26T14:25:35.253858Z INFO kernel: [ 1122.632781] pci 0000:00:01.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 15148, parent: pci0000:00
2024-04-26T14:25:35.253885Z INFO kernel: [ 1122.633115] pci 0000:00:07.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 892 usecs
2024-04-26T14:25:35.253911Z INFO kernel: [ 1122.633147] pci 0000:00:00.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 774, parent: pci0000:00
2024-04-26T14:25:35.253934Z INFO kernel: [ 1122.633397] pci 0000:00:01.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 586 usecs
2024-04-26T14:25:35.253954Z INFO kernel: [ 1122.633843] pcieport 0000:00:15.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 11601, parent: pci0000:00
2024-04-26T14:25:35.258326Z INFO kernel: [ 1122.633922] pci 0000:00:00.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 748 usecs
2024-04-26T14:25:35.258375Z INFO kernel: [ 1122.635392] pcieport 0000:00:17.6: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 18808 usecs
2024-04-26T14:25:35.258402Z INFO kernel: [ 1122.635477] pcieport 0000:00:15.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1603 usecs
2024-04-26T14:25:35.258428Z INFO kernel: [ 1122.636087] pci 0000:00:11.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 386 usecs
2024-04-26T14:25:35.258454Z INFO kernel: [ 1122.636718] pcieport 0000:00:16.1: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 7906 usecs
2024-04-26T14:25:35.258480Z INFO kernel: [ 1122.637473] pcieport 0000:00:17.7: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 704 usecs
2024-04-26T14:25:35.258576Z INFO kernel: [ 1122.638043] pcieport 0000:00:15.1: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 9485 usecs
2024-04-26T14:25:35.258606Z INFO kernel: [ 1122.640441] pcieport 0000:00:17.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 453 usecs
```

2024-04-26T14:25:35.258634Z INFO kernel: [1122.641794] vmwgfx 0000:00:0f.0: PM: pci_pm_suspend_noirq+0x0/0x200 returned 0 after 8 usecs
2024-04-26T14:25:35.258658Z INFO kernel: [1122.644897] pcieport 0000:00:17.5: PM: pci_pm_suspend_noirq+0x0/0x200 returned 0 after 609 usecs
2024-04-26T14:25:35.258689Z DEBUG kernel: [1122.819037] PM: noirq suspend of devices complete after 213.503 msecs
2024-04-26T14:25:35.258721Z DEBUG kernel: [1122.819124] PM: suspend-to-idle
2024-04-26T14:25:35.258807Z ERR kernel: [1175.593489] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.258841Z WARNING kernel: [1175.595923] hwrng: no data available
2024-04-26T14:25:35.258868Z ERR kernel: [1187.881244] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.258895Z WARNING kernel: [1187.882984] hwrng: no data available
2024-04-26T14:25:35.258929Z ERR kernel: [1200.197006] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.258959Z WARNING kernel: [1200.199452] hwrng: no data available
2024-04-26T14:25:35.258987Z ERR kernel: [1212.457203] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.259226Z WARNING kernel: [1212.459215] hwrng: no data available
2024-04-26T14:25:35.259266Z ERR kernel: [1224.749048] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.259295Z WARNING kernel: [1224.751876] hwrng: no data available
2024-04-26T14:25:35.259396Z ERR kernel: [1237.123226] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.259424Z WARNING kernel: [1237.134696] hwrng: no data available
2024-04-26T14:25:35.259450Z ERR kernel: [1249.320911] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.259530Z WARNING kernel: [1249.322713] hwrng: no data available
2024-04-26T14:25:35.259557Z ERR kernel: [1261.627171] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.259583Z WARNING kernel: [1261.631937] hwrng: no data available
2024-04-26T14:25:35.259609Z ERR kernel: [1273.899932] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.259639Z WARNING kernel: [1273.902240] hwrng: no data available
2024-04-26T14:25:35.259672Z ERR kernel: [1286.185399] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.259696Z WARNING kernel: [1286.187403] hwrng: no data available
2024-04-26T14:25:35.259777Z ERR kernel: [1298.502935] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.259806Z WARNING kernel: [1298.504979] hwrng: no data available
2024-04-26T14:25:35.259833Z ERR kernel: [1310.761482] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.259859Z WARNING kernel: [1310.767610] hwrng: no data available
2024-04-26T14:25:35.259885Z ERR kernel: [1323.053230] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.259917Z WARNING kernel: [1323.055190] hwrng: no data available
2024-04-26T14:25:35.260001Z ERR kernel: [1335.337478] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.260180Z WARNING kernel: [1335.339317] hwrng: no data available
2024-04-26T14:25:35.260205Z ERR kernel: [1347.627121] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.260231Z WARNING kernel: [1347.629173] hwrng: no data available
2024-04-26T14:25:35.260257Z ERR kernel: [1359.913588] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.260282Z WARNING kernel: [1359.915393] hwrng: no data available
2024-04-26T14:25:35.260375Z ERR kernel: [1372.201019] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.260404Z WARNING kernel: [1372.202844] hwrng: no data available
2024-04-26T14:25:35.260430Z ERR kernel: [1384.488698] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.260456Z WARNING kernel: [1384.490591] hwrng: no data available
2024-04-26T14:25:35.260486Z ERR kernel: [1396.783705] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.260519Z WARNING kernel: [1396.785722] hwrng: no data available
2024-04-26T14:25:35.260542Z ERR kernel: [1409.072954] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.260565Z WARNING kernel: [1409.081407] hwrng: no data available
2024-04-26T14:25:35.260606Z ERR kernel: [1421.353207] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.260638Z WARNING kernel: [1421.355268] hwrng: no data available
2024-04-26T14:25:35.260665Z ERR kernel: [1433.641443] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.275490Z WARNING kernel: [1433.643174] hwrng: no data available
2024-04-26T14:25:35.275538Z ERR kernel: [1445.929623] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.275566Z WARNING kernel: [1445.931403] hwrng: no data available
2024-04-26T14:25:35.275596Z ERR kernel: [1458.217245] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.275682Z WARNING kernel: [1458.218987] hwrng: no data available
2024-04-26T14:25:35.275725Z ERR kernel: [1470.505355] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.275758Z WARNING kernel: [1470.507214] hwrng: no data available
2024-04-26T14:25:35.275781Z ERR kernel: [1482.792775] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.275971Z WARNING kernel: [1482.794728] hwrng: no data available
2024-04-26T14:25:35.276004Z ERR kernel: [1495.081070] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.276168Z WARNING kernel: [1495.083572] hwrng: no data available
2024-04-26T14:25:35.276255Z ERR kernel: [1507.425153] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.276285Z WARNING kernel: [1507.426993] hwrng: no data available
2024-04-26T14:25:35.276308Z ERR kernel: [1519.657303] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.276498Z WARNING kernel: [1519.659094] hwrng: no data available
2024-04-26T14:25:35.276526Z ERR kernel: [1531.946119] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.276551Z WARNING kernel: [1531.948340] hwrng: no data available
2024-04-26T14:25:35.276635Z ERR kernel: [1544.233276] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.276662Z WARNING kernel: [1544.235254] hwrng: no data available

```
2024-04-26T14:25:35.276688Z ERR kernel: [ 1556.520630] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.276714Z WARNING kernel: [ 1556.522607] hwrng: no data available
2024-04-26T14:25:35.276740Z ERR kernel: [ 1568.844424] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.276765Z WARNING kernel: [ 1568.861017] hwrng: no data available
2024-04-26T14:25:35.276791Z ERR kernel: [ 1581.100063] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.277350Z WARNING kernel: [ 1581.101929] hwrng: no data available
2024-04-26T14:25:35.277382Z ERR kernel: [ 1593.385560] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.277408Z WARNING kernel: [ 1593.387746] hwrng: no data available
2024-04-26T14:25:35.277432Z WARNING kernel: [ 1604.142747] PM: pm_system_irq_wakeup: 12
triggered i8042
2024-04-26T14:25:35.277459Z DEBUG kernel: [ 1604.147420] PM: Wakeup unrelated to ACPI SCI
2024-04-26T14:25:35.277484Z DEBUG kernel: [ 1604.147449] PM: resume from suspend-to-idle
2024-04-26T14:25:35.277567Z INFO kernel: [ 1604.152554] pci 0000:00:00.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 15148, parent: pci0000:00
2024-04-26T14:25:35.277595Z INFO kernel: [ 1604.160402] pci 0000:00:01.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 15151, parent: pci0000:00
2024-04-26T14:25:35.277621Z INFO kernel: [ 1604.165435] pci 0000:00:00.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 6305 usecs
2024-04-26T14:25:35.277647Z INFO kernel: [ 1604.167054] pci 0000:00:01.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 801 usecs
2024-04-26T14:25:35.277673Z INFO kernel: [ 1604.170162] pci 0000:00:07.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 15148, parent: pci0000:00
2024-04-26T14:25:35.277698Z INFO kernel: [ 1604.175185] ata_piix 0000:00:07.1: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15151, parent: pci0000:00
2024-04-26T14:25:35.277770Z INFO kernel: [ 1604.179729] pci 0000:00:07.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 637 usecs
2024-04-26T14:25:35.277798Z INFO kernel: [ 1604.186251] ata_piix 0000:00:07.1: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 1059 usecs
2024-04-26T14:25:35.277823Z INFO kernel: [ 1604.191073] pci 0000:00:07.3: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.277848Z INFO kernel: [ 1604.191735] pci 0000:00:07.3: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 607 usecs
2024-04-26T14:25:35.277875Z INFO kernel: [ 1604.191794] vmw_vmci 0000:00:07.7: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.277900Z INFO kernel: [ 1604.191954] vmwgfx 0000:00:0f.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.277970Z INFO kernel: [ 1604.192145] vmwgfx 0000:00:0f.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 69 usecs
2024-04-26T14:25:35.277996Z INFO kernel: [ 1604.192210] pci 0000:00:10.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.278180Z INFO kernel: [ 1604.194152] vmw_vmci 0000:00:07.7: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 2309 usecs
2024-04-26T14:25:35.278207Z INFO kernel: [ 1604.194221] pci 0000:00:11.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.278234Z INFO kernel: [ 1604.194289] pci 0000:00:11.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 20 usecs
2024-04-26T14:25:35.278258Z INFO kernel: [ 1604.194564] pci 0000:00:10.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 2308 usecs
2024-04-26T14:25:35.278337Z INFO kernel: [ 1604.195400] pcieport 0000:00:15.0: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.278365Z INFO kernel: [ 1604.195853] pcieport 0000:00:15.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 405 usecs
2024-04-26T14:25:35.278391Z INFO kernel: [ 1604.195914] pcieport 0000:00:15.1: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.278416Z INFO kernel: [ 1604.196043] pcieport 0000:00:15.1: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 89 usecs
2024-04-26T14:25:35.278441Z INFO kernel: [ 1604.196083] pcieport 0000:00:15.2: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.278467Z INFO kernel: [ 1604.196300] pcieport 0000:00:15.2: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 75 usecs
2024-04-26T14:25:35.278537Z INFO kernel: [ 1604.196512] pcieport 0000:00:15.3: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.278565Z INFO kernel: [ 1604.196998] pcieport 0000:00:15.3: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 231 usecs
2024-04-26T14:25:35.278591Z INFO kernel: [ 1604.198372] pcieport 0000:00:15.4: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.278616Z INFO kernel: [ 1604.198547] pcieport 0000:00:15.4: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 120 usecs
2024-04-26T14:25:35.278642Z INFO kernel: [ 1604.198713] pcieport 0000:00:15.5: PM:
```

```
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.278711Z INFO kernel: [ 1604.198856] pcieport 0000:00:15.5: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 94 usecs
2024-04-26T14:25:35.278739Z INFO kernel: [ 1604.198906] pcieport 0000:00:15.6: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.278765Z INFO kernel: [ 1604.199047] pcieport 0000:00:15.6: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 95 usecs
2024-04-26T14:25:35.278791Z INFO kernel: [ 1604.199091] pcieport 0000:00:15.7: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.278816Z INFO kernel: [ 1604.199232] pcieport 0000:00:15.7: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 95 usecs
2024-04-26T14:25:35.278843Z INFO kernel: [ 1604.199281] pcieport 0000:00:16.0: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.278915Z INFO kernel: [ 1604.199545] pcieport 0000:00:16.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 209 usecs
2024-04-26T14:25:35.278941Z INFO kernel: [ 1604.199717] pcieport 0000:00:16.1: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.279180Z INFO kernel: [ 1604.199855] pcieport 0000:00:16.1: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 93 usecs
2024-04-26T14:25:35.279208Z INFO kernel: [ 1604.199900] pcieport 0000:00:16.2: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.279235Z INFO kernel: [ 1604.200035] pcieport 0000:00:16.2: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 92 usecs
2024-04-26T14:25:35.279260Z INFO kernel: [ 1604.200083] pcieport 0000:00:16.3: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.279753Z INFO kernel: [ 1604.200381] pcieport 0000:00:16.3: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 120 usecs
2024-04-26T14:25:35.279788Z INFO kernel: [ 1604.200442] pcieport 0000:00:16.4: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.279815Z INFO kernel: [ 1604.200851] pcieport 0000:00:16.4: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 211 usecs
2024-04-26T14:25:35.279842Z INFO kernel: [ 1604.200902] pcieport 0000:00:16.5: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.279869Z INFO kernel: [ 1604.201043] pcieport 0000:00:16.5: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 94 usecs
2024-04-26T14:25:35.279896Z INFO kernel: [ 1604.201091] pcieport 0000:00:16.6: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.279978Z INFO kernel: [ 1604.201241] pcieport 0000:00:16.6: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 102 usecs
2024-04-26T14:25:35.280005Z INFO kernel: [ 1604.201289] pcieport 0000:00:16.7: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.280171Z INFO kernel: [ 1604.201934] pcieport 0000:00:16.7: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 263 usecs
2024-04-26T14:25:35.280198Z INFO kernel: [ 1604.201983] pcieport 0000:00:17.0: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.280224Z INFO kernel: [ 1604.202113] pcieport 0000:00:17.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 91 usecs
2024-04-26T14:25:35.280250Z INFO kernel: [ 1604.202156] pcieport 0000:00:17.1: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.280509Z INFO kernel: [ 1604.202275] pcieport 0000:00:17.1: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 80 usecs
2024-04-26T14:25:35.280536Z INFO kernel: [ 1604.202316] pcieport 0000:00:17.2: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.280562Z INFO kernel: [ 1604.202436] pcieport 0000:00:17.2: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 81 usecs
2024-04-26T14:25:35.280588Z INFO kernel: [ 1604.202477] pcieport 0000:00:17.3: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.280613Z INFO kernel: [ 1604.202754] pcieport 0000:00:17.3: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 237 usecs
2024-04-26T14:25:35.280638Z INFO kernel: [ 1604.202868] pcieport 0000:00:17.4: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.280719Z INFO kernel: [ 1604.202992] pcieport 0000:00:17.4: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 85 usecs
2024-04-26T14:25:35.280744Z INFO kernel: [ 1604.203032] pcieport 0000:00:17.5: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.280768Z INFO kernel: [ 1604.203154] pcieport 0000:00:17.5: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 81 usecs
2024-04-26T14:25:35.280792Z INFO kernel: [ 1604.203196] pcieport 0000:00:17.6: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
```

```
2024-04-26T14:25:35.280818Z INFO kernel: [ 1604.203313] pcieport 0000:00:17.6: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 80 usecs
2024-04-26T14:25:35.280899Z INFO kernel: [ 1604.203354] pcieport 0000:00:17.7: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.280930Z INFO kernel: [ 1604.203513] pcieport 0000:00:17.7: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 88 usecs
2024-04-26T14:25:35.280956Z INFO kernel: [ 1604.203522] pcieport 0000:00:18.0: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15148, parent: pci0000:00
2024-04-26T14:25:35.280977Z INFO kernel: [ 1604.203558] pcieport 0000:00:18.1: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.280999Z INFO kernel: [ 1604.203792] pcieport 0000:00:18.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 221 usecs
2024-04-26T14:25:35.281273Z INFO kernel: [ 1604.203840] pcieport 0000:00:18.2: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15148, parent: pci0000:00
2024-04-26T14:25:35.281592Z INFO kernel: [ 1604.203947] pcieport 0000:00:18.1: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 119 usecs
2024-04-26T14:25:35.281625Z INFO kernel: [ 1604.203998] pcieport 0000:00:18.3: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.281650Z INFO kernel: [ 1604.204009] pcieport 0000:00:18.2: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 126 usecs
2024-04-26T14:25:35.281673Z INFO kernel: [ 1604.204113] pcieport 0000:00:18.4: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15148, parent: pci0000:00
2024-04-26T14:25:35.281694Z INFO kernel: [ 1604.204245] pcieport 0000:00:18.4: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 88 usecs
2024-04-26T14:25:35.281714Z INFO kernel: [ 1604.204291] pcieport 0000:00:18.5: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15148, parent: pci0000:00
2024-04-26T14:25:35.281784Z INFO kernel: [ 1604.204462] pcieport 0000:00:18.5: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 128 usecs
2024-04-26T14:25:35.281806Z INFO kernel: [ 1604.204507] pcieport 0000:00:18.6: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15148, parent: pci0000:00
2024-04-26T14:25:35.281828Z INFO kernel: [ 1604.204753] pcieport 0000:00:18.6: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 203 usecs
2024-04-26T14:25:35.281865Z INFO kernel: [ 1604.204798] pcieport 0000:00:18.7: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15148, parent: pci0000:00
2024-04-26T14:25:35.281893Z INFO kernel: [ 1604.204926] pcieport 0000:00:18.7: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 86 usecs
2024-04-26T14:25:35.281919Z INFO kernel: [ 1604.204971] uhci_hcd 0000:02:00.0: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15148, parent: 0000:00:11.0
2024-04-26T14:25:35.282003Z INFO kernel: [ 1604.205031] uhci_hcd 0000:02:00.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 18 usecs
2024-04-26T14:25:35.300421Z INFO kernel: [ 1604.205075] e1000 0000:02:01.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 15148, parent: 0000:00:11.0
2024-04-26T14:25:35.300452Z INFO kernel: [ 1604.207860] i8042 i8042: PM: calling
i8042_pm_resume_noirq+0x0/0x21 @ 15271, parent: platform
2024-04-26T14:25:35.300484Z INFO kernel: [ 1604.208050] i8042 i8042: PM:
i8042_pm_resume_noirq+0x0/0x21 returned 0 after 137 usecs
2024-04-26T14:25:35.300516Z INFO kernel: [ 1604.208120] snd_hda_intel 0000:02:02.0: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15151, parent: 0000:00:11.0
2024-04-26T14:25:35.300558Z INFO kernel: [ 1604.208471] ehci-pci 0000:02:03.0: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 15279, parent: 0000:00:11.0
2024-04-26T14:25:35.301231Z INFO kernel: [ 1604.208537] ehci-pci 0000:02:03.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 19 usecs
2024-04-26T14:25:35.301262Z INFO kernel: [ 1604.208715] nvme 0000:03:00.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 15279, parent: 0000:00:15.0
2024-04-26T14:25:35.301289Z INFO kernel: [ 1604.257833] pcieport 0000:00:18.3: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 9661 usecs
2024-04-26T14:25:35.301314Z INFO kernel: [ 1604.278093] nvme 0000:03:00.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 69330 usecs
2024-04-26T14:25:35.301348Z INFO kernel: [ 1604.278219] e1000 0000:02:01.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 73103 usecs
2024-04-26T14:25:35.301374Z INFO kernel: [ 1604.284300] snd_hda_intel 0000:02:02.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 22878 usecs
2024-04-26T14:25:35.301450Z INFO kernel: [ 1604.722095] PM: noirq resume of devices
complete after 574.606 msecs
2024-04-26T14:25:35.301470Z INFO kernel: [ 1604.737735] pci 0000:00:00.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 15151, parent: pci0000:00
2024-04-26T14:25:35.301489Z INFO kernel: [ 1604.737949] pci 0000:00:01.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 15280, parent: pci0000:00
2024-04-26T14:25:35.301509Z INFO kernel: [ 1604.738167] pci 0000:00:07.0: PM: calling
```

```
pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.301534Z INFO kernel: [ 1604.738521] ata_piix 0000:00:07.1: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.301609Z INFO kernel: [ 1604.739126] pci 0000:00:07.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 915 usecs
2024-04-26T14:25:35.301637Z INFO kernel: [ 1604.739364] pci 0000:00:07.3: PM: calling
pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.301663Z INFO kernel: [ 1604.739427] pci 0000:00:07.3: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 18 usecs
2024-04-26T14:25:35.301689Z INFO kernel: [ 1604.739541] vmw_vmci 0000:00:07.7: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.301714Z INFO kernel: [ 1604.739606] vmw_vmci 0000:00:07.7: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 19 usecs
2024-04-26T14:25:35.301746Z INFO kernel: [ 1604.739675] vmwgfx 0000:00:0f.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.301841Z INFO kernel: [ 1604.739735] vmwgfx 0000:00:0f.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 18 usecs
2024-04-26T14:25:35.301875Z INFO kernel: [ 1604.739905] pci 0000:00:10.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.301914Z INFO kernel: [ 1604.740103] pci 0000:00:10.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 36 usecs
2024-04-26T14:25:35.301946Z INFO kernel: [ 1604.740242] pci 0000:00:11.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.301969Z INFO kernel: [ 1604.741002] ata_piix 0000:00:07.1: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 22 usecs
2024-04-26T14:25:35.301990Z INFO kernel: [ 1604.741083] pcieport 0000:00:15.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.302210Z INFO kernel: [ 1604.741084] pci 0000:00:11.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 20 usecs
2024-04-26T14:25:35.302235Z INFO kernel: [ 1604.741153] pcieport 0000:00:15.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 21 usecs
2024-04-26T14:25:35.302256Z INFO kernel: [ 1604.741153] pcieport 0000:00:15.1: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.302276Z INFO kernel: [ 1604.741220] pcieport 0000:00:15.1: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 20 usecs
2024-04-26T14:25:35.302297Z INFO kernel: [ 1604.741220] pcieport 0000:00:15.2: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.302324Z INFO kernel: [ 1604.741287] pcieport 0000:00:15.3: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.302396Z INFO kernel: [ 1604.741287] pcieport 0000:00:15.2: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 20 usecs
2024-04-26T14:25:35.302418Z INFO kernel: [ 1604.741355] pcieport 0000:00:15.3: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 20 usecs
2024-04-26T14:25:35.302439Z INFO kernel: [ 1604.741355] pcieport 0000:00:15.4: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.302464Z INFO kernel: [ 1604.741484] pcieport 0000:00:15.5: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.302489Z INFO kernel: [ 1604.741484] pcieport 0000:00:15.4: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 20 usecs
2024-04-26T14:25:35.302573Z INFO kernel: [ 1604.741552] pcieport 0000:00:15.5: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 20 usecs
2024-04-26T14:25:35.302605Z INFO kernel: [ 1604.741553] pcieport 0000:00:15.6: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.302633Z INFO kernel: [ 1604.741727] pcieport 0000:00:15.6: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 20 usecs
2024-04-26T14:25:35.302659Z INFO kernel: [ 1604.741727] pcieport 0000:00:15.7: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.302683Z INFO kernel: [ 1604.741795] pcieport 0000:00:16.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.302707Z INFO kernel: [ 1604.741794] pcieport 0000:00:15.7: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 20 usecs
2024-04-26T14:25:35.303322Z INFO kernel: [ 1604.741861] pcieport 0000:00:16.1: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.303357Z INFO kernel: [ 1604.741901] pcieport 0000:00:16.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 20 usecs
2024-04-26T14:25:35.303380Z INFO kernel: [ 1604.741928] pcieport 0000:00:16.1: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 19 usecs
2024-04-26T14:25:35.303401Z INFO kernel: [ 1604.741975] pcieport 0000:00:16.2: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15278, parent: pci0000:00
```

```
2024-04-26T14:25:35.303422Z INFO kernel: [ 1604.741996] pcieport 0000:00:16.3: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.303443Z INFO kernel: [ 1604.742041] pcieport 0000:00:16.2: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 20 usecs
2024-04-26T14:25:35.303517Z INFO kernel: [ 1604.742061] pcieport 0000:00:16.3: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 18 usecs
2024-04-26T14:25:35.303540Z INFO kernel: [ 1604.742109] pcieport 0000:00:16.4: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.303561Z INFO kernel: [ 1604.742130] pcieport 0000:00:16.5: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.303582Z INFO kernel: [ 1604.742175] pcieport 0000:00:16.4: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 20 usecs
2024-04-26T14:25:35.303603Z INFO kernel: [ 1604.742195] pcieport 0000:00:16.5: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 18 usecs
2024-04-26T14:25:35.303629Z INFO kernel: [ 1604.742243] pcieport 0000:00:16.6: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.303711Z INFO kernel: [ 1604.742265] pcieport 0000:00:16.7: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.303743Z INFO kernel: [ 1604.742309] pcieport 0000:00:16.6: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 20 usecs
2024-04-26T14:25:35.303771Z INFO kernel: [ 1604.742383] pcieport 0000:00:17.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.303797Z INFO kernel: [ 1604.742391] pcieport 0000:00:16.7: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 21 usecs
2024-04-26T14:25:35.303823Z INFO kernel: [ 1604.742454] pcieport 0000:00:17.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 21 usecs
2024-04-26T14:25:35.303883Z INFO kernel: [ 1604.742460] pcieport 0000:00:17.1: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.303989Z INFO kernel: [ 1604.742543] pcieport 0000:00:17.1: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 19 usecs
2024-04-26T14:25:35.321893Z INFO kernel: [ 1604.742543] pcieport 0000:00:17.2: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15278, parent: pci0000:00
2024-04-26T14:25:35.321947Z INFO kernel: [ 1604.742726] pcieport 0000:00:17.3: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.321977Z INFO kernel: [ 1604.742727] pcieport 0000:00:17.2: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 123 usecs
2024-04-26T14:25:35.322000Z INFO kernel: [ 1604.742786] pcieport 0000:00:17.3: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 16 usecs
2024-04-26T14:25:35.322168Z INFO kernel: [ 1604.742841] pcieport 0000:00:17.4: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.322266Z INFO kernel: [ 1604.742893] pcieport 0000:00:17.4: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 15 usecs
2024-04-26T14:25:35.322295Z INFO kernel: [ 1604.742947] pcieport 0000:00:17.5: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.322322Z INFO kernel: [ 1604.742984] pci 0000:00:00.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 20 usecs
2024-04-26T14:25:35.322349Z INFO kernel: [ 1604.743000] pcieport 0000:00:17.5: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 16 usecs
2024-04-26T14:25:35.322372Z INFO kernel: [ 1604.743054] pcieport 0000:00:17.6: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.322551Z INFO kernel: [ 1604.743066] pcieport 0000:00:17.7: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15151, parent: pci0000:00
2024-04-26T14:25:35.322583Z INFO kernel: [ 1604.743106] pcieport 0000:00:17.6: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 15 usecs
2024-04-26T14:25:35.322606Z INFO kernel: [ 1604.743135] pcieport 0000:00:17.7: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 19 usecs
2024-04-26T14:25:35.322630Z INFO kernel: [ 1604.743162] pcieport 0000:00:18.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.322654Z INFO kernel: [ 1604.743203] pcieport 0000:00:18.1: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15151, parent: pci0000:00
2024-04-26T14:25:35.322679Z INFO kernel: [ 1604.743214] pcieport 0000:00:18.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 15 usecs
2024-04-26T14:25:35.322758Z INFO kernel: [ 1604.743268] pcieport 0000:00:18.2: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.322786Z INFO kernel: [ 1604.743268] pcieport 0000:00:18.1: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 19 usecs
2024-04-26T14:25:35.322813Z INFO kernel: [ 1604.743320] pcieport 0000:00:18.2: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 15 usecs
2024-04-26T14:25:35.322836Z INFO kernel: [ 1604.743375] pcieport 0000:00:18.3: PM:
```

```
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.322857Z INFO kernel: [ 1604.743415] pcieport 0000:00:18.4: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15151, parent: pci0000:00
2024-04-26T14:25:35.322878Z INFO kernel: [ 1604.743427] pcieport 0000:00:18.3: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 16 usecs
2024-04-26T14:25:35.322956Z INFO kernel: [ 1604.743483] pcieport 0000:00:18.5: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.322978Z INFO kernel: [ 1604.743484] pcieport 0000:00:18.4: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 20 usecs
2024-04-26T14:25:35.322998Z INFO kernel: [ 1604.743535] pcieport 0000:00:18.5: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 15 usecs
2024-04-26T14:25:35.323187Z INFO kernel: [ 1604.743552] pcieport 0000:00:18.6: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15151, parent: pci0000:00
2024-04-26T14:25:35.323217Z INFO kernel: [ 1604.743681] pcieport 0000:00:18.7: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: pci0000:00
2024-04-26T14:25:35.323243Z INFO kernel: [ 1604.743724] pcieport 0000:00:18.6: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 19 usecs
2024-04-26T14:25:35.323777Z INFO kernel: [ 1604.743734] pcieport 0000:00:18.7: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 16 usecs
2024-04-26T14:25:35.323814Z INFO kernel: [ 1604.743790] e1000 0000:02:01.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 15279, parent: 0000:00:11.0
2024-04-26T14:25:35.323837Z INFO kernel: [ 1604.743790] uhci_hcd 0000:02:00.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15151, parent: 0000:00:11.0
2024-04-26T14:25:35.323859Z INFO kernel: [ 1604.743844] e1000 0000:02:01.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 16 usecs
2024-04-26T14:25:35.323881Z INFO kernel: [ 1604.743857] uhci_hcd 0000:02:00.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 19 usecs
2024-04-26T14:25:35.323902Z INFO kernel: [ 1604.743899] snd_hda_intel 0000:02:02.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15279, parent: 0000:00:11.0
2024-04-26T14:25:35.323975Z INFO kernel: [ 1604.743927] ehci-pci 0000:02:03.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 15151, parent: 0000:00:11.0
2024-04-26T14:25:35.323999Z INFO kernel: [ 1604.743953] snd_hda_intel 0000:02:02.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 16 usecs
2024-04-26T14:25:35.324170Z INFO kernel: [ 1604.744048] nvme 0000:03:00.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 15279, parent: 0000:00:15.0
2024-04-26T14:25:35.324196Z INFO kernel: [ 1604.744048] ehci-pci 0000:02:03.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 19 usecs
2024-04-26T14:25:35.329423Z INFO kernel: [ 1604.744102] nvme 0000:03:00.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 16 usecs
2024-04-26T14:25:35.329461Z INFO kernel: [ 1604.747636] pci 0000:00:01.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 20 usecs
2024-04-26T14:25:35.329486Z DEBUG kernel: [ 1605.273822] PM: early resume of devices
complete after 549.037 msecs
2024-04-26T14:25:35.329511Z INFO kernel: [ 1605.274374] ac ACPI0003:00: PM: calling
acpi_ac_resume+0x0/0x58 @ 15271, parent: LNXYBUS:00
2024-04-26T14:25:35.329534Z INFO kernel: [ 1605.274409] pci 0000:00:00.0: PM: calling
pci_pm_resume+0x0/0xed @ 15280, parent: pci0000:00
2024-04-26T14:25:35.329558Z INFO kernel: [ 1605.274591] pci 0000:00:01.0: PM: calling
pci_pm_resume+0x0/0xed @ 15278, parent: pci0000:00
2024-04-26T14:25:35.329582Z INFO kernel: [ 1605.275057] pci 0000:00:01.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 22 usecs
2024-04-26T14:25:35.329607Z INFO kernel: [ 1605.275115] pci 0000:00:07.0: PM: calling
pci_pm_resume+0x0/0xed @ 15278, parent: pci0000:00
2024-04-26T14:25:35.329635Z INFO kernel: [ 1605.275195] pci 0000:00:07.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 22 usecs
2024-04-26T14:25:35.329657Z INFO kernel: [ 1605.275244] ata_piix 0000:00:07.1: PM:
calling pci_pm_resume+0x0/0xed @ 15278, parent: pci0000:00
2024-04-26T14:25:35.329681Z INFO kernel: [ 1605.276456] ata_piix 0000:00:07.1: PM:
pci_pm_resume+0x0/0xed returned 0 after 1165 usecs
2024-04-26T14:25:35.329706Z INFO kernel: [ 1605.276512] pci 0000:00:07.3: PM: calling
pci_pm_resume+0x0/0xed @ 15278, parent: pci0000:00
2024-04-26T14:25:35.329731Z INFO kernel: [ 1605.276713] pci 0000:00:07.3: PM:
pci_pm_resume+0x0/0xed returned 0 after 155 usecs
2024-04-26T14:25:35.329754Z INFO kernel: [ 1605.276762] vmw_vmci 0000:00:07.7: PM:
calling pci_pm_resume+0x0/0xed @ 15278, parent: pci0000:00
2024-04-26T14:25:35.329784Z INFO kernel: [ 1605.277028] vmw_vmci 0000:00:07.7: PM:
pci_pm_resume+0x0/0xed returned 0 after 221 usecs
2024-04-26T14:25:35.329811Z INFO kernel: [ 1605.277079] vmwgfx 0000:00:0f.0: PM: calling
pci_pm_resume+0x0/0xed @ 15278, parent: pci0000:00
```



```
2024-04-26T14:25:35.329845Z INFO kernel: [ 1605.278076] vmwgfx 0000:00:0f.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 952 usecs
2024-04-26T14:25:35.329875Z INFO kernel: [ 1605.278124] pci 0000:00:10.0: PM: calling
pci_pm_resume+0x0/0xed @ 15278, parent: pci0000:00
2024-04-26T14:25:35.329900Z INFO kernel: [ 1605.278187] pci 0000:00:10.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 18 usecs
2024-04-26T14:25:35.329923Z INFO kernel: [ 1605.278232] pci 0000:00:11.0: PM: calling
pci_pm_resume+0x0/0xed @ 15278, parent: pci0000:00
2024-04-26T14:25:35.329945Z INFO kernel: [ 1605.279340] pci 0000:00:11.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 1062 usecs
2024-04-26T14:25:35.329969Z INFO kernel: [ 1605.279399] ac ACPI0003:00: PM:
acpi_ac_resume+0x0/0x58 returned 0 after 500 usecs
2024-04-26T14:25:35.329994Z INFO kernel: [ 1605.279851] platform PNP0001:00: PM: calling
platform_pm_resume+0x0/0x41 @ 15271, parent: 0000:00:07.0
2024-04-26T14:25:35.330227Z INFO kernel: [ 1605.279951] platform PNP0001:00: PM:
platform_pm_resume+0x0/0x41 returned 0 after 15 usecs
2024-04-26T14:25:35.330257Z INFO kernel: [ 1605.279974] platform PNP0800:00: PM: calling
platform_pm_resume+0x0/0x41 @ 15271, parent: 0000:00:07.0
2024-04-26T14:25:35.330282Z INFO kernel: [ 1605.280024] platform PNP0800:00: PM:
platform_pm_resume+0x0/0x41 returned 0 after 14 usecs
2024-04-26T14:25:35.330307Z INFO kernel: [ 1605.280046] platform ACPI0003:00: PM: calling
platform_pm_resume+0x0/0x41 @ 15271, parent: platform
2024-04-26T14:25:35.330333Z INFO kernel: [ 1605.280137] platform ACPI0003:00: PM:
platform_pm_resume+0x0/0x41 returned 0 after 15 usecs
2024-04-26T14:25:35.330358Z INFO kernel: [ 1605.280176] button LNXPRBN:00: PM: calling
acpi_button_resume+0x0/0xa9 @ 15271, parent: LNXSYSTEM:00
2024-04-26T14:25:35.330384Z INFO kernel: [ 1605.280230] button LNXPRBN:00: PM:
acpi_button_resume+0x0/0xa9 returned 0 after 16 usecs
2024-04-26T14:25:35.330409Z INFO kernel: [ 1605.280252] platform rtc-efi.0: PM: calling
platform_pm_resume+0x0/0x41 @ 15271, parent: platform
2024-04-26T14:25:35.330436Z INFO kernel: [ 1605.280302] platform rtc-efi.0: PM:
platform_pm_resume+0x0/0x41 returned 0 after 14 usecs
2024-04-26T14:25:35.330463Z INFO kernel: [ 1605.280323] platform efivars.0: PM: calling
platform_pm_resume+0x0/0x41 @ 15271, parent: platform
2024-04-26T14:25:35.330489Z INFO kernel: [ 1605.280444] platform efivars.0: PM:
platform_pm_resume+0x0/0x41 returned 0 after 14 usecs
2024-04-26T14:25:35.330513Z INFO kernel: [ 1605.280474] platform chromeos_acpi: PM:
calling platform_pm_resume+0x0/0x41 @ 15271, parent: platform
2024-04-26T14:25:35.330539Z INFO kernel: [ 1605.280579] platform chromeos_acpi: PM:
platform_pm_resume+0x0/0x41 returned 0 after 30 usecs
2024-04-26T14:25:35.330564Z INFO kernel: [ 1605.280720] system 00:00: PM: calling
pnp_bus_resume+0x0/0x9d @ 15271, parent: pnp0
2024-04-26T14:25:35.330592Z INFO kernel: [ 1605.280790] system 00:00: PM:
pnp_bus_resume+0x0/0x9d returned 0 after 20 usecs
2024-04-26T14:25:35.330619Z INFO kernel: [ 1605.280819] rtc_cmos 00:01: PM: calling
pnp_bus_resume+0x0/0x9d @ 15271, parent: pnp0
2024-04-26T14:25:35.330646Z INFO kernel: [ 1605.280888] rtc_cmos 00:01: PM:
pnp_bus_resume+0x0/0x9d returned 0 after 21 usecs
2024-04-26T14:25:35.330672Z INFO kernel: [ 1605.280915] i8042 kbd 00:02: PM: calling
pnp_bus_resume+0x0/0x9d @ 15271, parent: pnp0
2024-04-26T14:25:35.330698Z INFO kernel: [ 1605.280984] i8042 kbd 00:02: PM:
pnp_bus_resume+0x0/0x9d returned 0 after 19 usecs
2024-04-26T14:25:35.330872Z INFO kernel: [ 1605.281081] i8042 aux 00:03: PM: calling
pnp_bus_resume+0x0/0x9d @ 15271, parent: pnp0
2024-04-26T14:25:35.330900Z INFO kernel: [ 1605.281150] i8042 aux 00:03: PM:
pnp_bus_resume+0x0/0x9d returned 0 after 19 usecs
2024-04-26T14:25:35.330925Z INFO kernel: [ 1605.281178] system 00:04: PM: calling
pnp_bus_resume+0x0/0x9d @ 15271, parent: pnp0
2024-04-26T14:25:35.330949Z INFO kernel: [ 1605.281241] system 00:04: PM:
pnp_bus_resume+0x0/0x9d returned 0 after 18 usecs
2024-04-26T14:25:35.330974Z INFO kernel: [ 1605.281268] system 00:05: PM: calling
pnp_bus_resume+0x0/0x9d @ 15271, parent: pnp0
2024-04-26T14:25:35.331001Z INFO kernel: [ 1605.281333] system 00:05: PM:
pnp_bus_resume+0x0/0x9d returned 0 after 19 usecs
2024-04-26T14:25:35.331218Z INFO kernel: [ 1605.281365] platform intel_rapl_msr.0: PM:
calling platform_pm_resume+0x0/0x41 @ 15271, parent: platform
2024-04-26T14:25:35.331247Z INFO kernel: [ 1605.281432] platform intel_rapl_msr.0: PM:
platform_pm_resume+0x0/0x41 returned 0 after 18 usecs
2024-04-26T14:25:35.331271Z INFO kernel: [ 1605.281483] input input0: PM: calling
```

```
input_dev_resume+0x0/0x42 @ 15271, parent: LNX_PWRBN:00
2024-04-26T14:25:35.331297Z INFO kernel: [ 1605.281748] input input0: PM:
input_dev_resume+0x0/0x42 returned 0 after 20 usecs
2024-04-26T14:25:35.331324Z INFO kernel: [ 1605.281781] serial8250 serial8250: PM:
calling platform_pm_resume+0x0/0x41 @ 15271, parent: platform
2024-04-26T14:25:35.331350Z INFO kernel: [ 1605.282134] serial8250 serial8250: PM:
platform_pm_resume+0x0/0x41 returned 0 after 19 usecs
2024-04-26T14:25:35.331378Z INFO kernel: [ 1605.282180] platform Fixed MDIO bus.0: PM:
calling platform_pm_resume+0x0/0x41 @ 15271, parent: platform
2024-04-26T14:25:35.331404Z INFO kernel: [ 1605.282255] pcieport 0000:00:15.0: PM:
calling pci_pm_resume+0x0/0xed @ 15282, parent: pci0000:00
2024-04-26T14:25:35.331429Z INFO kernel: [ 1605.282324] pcieport 0000:00:15.1: PM:
calling pci_pm_resume+0x0/0xed @ 15279, parent: pci0000:00
2024-04-26T14:25:35.331455Z INFO kernel: [ 1605.282960] pci 0000:00:00.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 16 usecs
2024-04-26T14:25:35.331477Z INFO kernel: [ 1605.286790] pcieport 0000:00:15.2: PM:
calling pci_pm_resume+0x0/0xed @ 15278, parent: pci0000:00
2024-04-26T14:25:35.331500Z INFO kernel: [ 1605.287128] pcieport 0000:00:15.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 4822 usecs
2024-04-26T14:25:35.331526Z INFO kernel: [ 1605.287258] pcieport 0000:00:15.1: PM:
pci_pm_resume+0x0/0xed returned 0 after 4896 usecs
2024-04-26T14:25:35.331551Z INFO kernel: [ 1605.287301] pcieport 0000:00:15.3: PM:
calling pci_pm_resume+0x0/0xed @ 15279, parent: pci0000:00
2024-04-26T14:25:35.331575Z INFO kernel: [ 1605.290468] pcieport 0000:00:15.4: PM:
calling pci_pm_resume+0x0/0xed @ 15280, parent: pci0000:00
2024-04-26T14:25:35.331602Z INFO kernel: [ 1605.290808] platform Fixed MDIO bus.0: PM:
platform_pm_resume+0x0/0x41 returned 0 after 19 usecs
2024-04-26T14:25:35.331627Z INFO kernel: [ 1605.290851] i8042 i8042: PM: calling
platform_pm_resume+0x0/0x41 @ 15271, parent: platform
2024-04-26T14:25:35.331651Z INFO kernel: [ 1605.290921] i8042 i8042: PM:
platform_pm_resume+0x0/0x41 returned 0 after 21 usecs
2024-04-26T14:25:35.331675Z INFO kernel: [ 1605.290951] pcieport 0000:00:15.2: PM:
pci_pm_resume+0x0/0xed returned 0 after 4117 usecs
2024-04-26T14:25:35.331701Z INFO kernel: [ 1605.290950] atkbd serio0: PM: calling
serio_resume+0x0/0x94 @ 15271, parent: i8042
2024-04-26T14:25:35.331732Z INFO kernel: [ 1605.290993] pcieport 0000:00:15.5: PM:
calling pci_pm_resume+0x0/0xed @ 15278, parent: pci0000:00
2024-04-26T14:25:35.331757Z INFO kernel: [ 1605.292333] pcieport 0000:00:15.3: PM:
pci_pm_resume+0x0/0xed returned 0 after 4990 usecs
2024-04-26T14:25:35.331782Z INFO kernel: [ 1605.292387] pcieport 0000:00:15.6: PM:
calling pci_pm_resume+0x0/0xed @ 15279, parent: pci0000:00
2024-04-26T14:25:35.331806Z INFO kernel: [ 1605.294073] pcieport 0000:00:15.7: PM:
calling pci_pm_resume+0x0/0xed @ 15151, parent: pci0000:00
2024-04-26T14:25:35.331831Z INFO kernel: [ 1605.294252] pcieport 0000:00:16.0: PM:
calling pci_pm_resume+0x0/0xed @ 15148, parent: pci0000:00
2024-04-26T14:25:35.331855Z INFO kernel: [ 1605.294546] pcieport 0000:00:15.5: PM:
pci_pm_resume+0x0/0xed returned 0 after 3512 usecs
2024-04-26T14:25:35.331880Z INFO kernel: [ 1605.294723] pcieport 0000:00:16.1: PM:
calling pci_pm_resume+0x0/0xed @ 15278, parent: pci0000:00
2024-04-26T14:25:35.331903Z INFO kernel: [ 1605.301101] pcieport 0000:00:16.2: PM:
calling pci_pm_resume+0x0/0xed @ 15281, parent: pci0000:00
2024-04-26T14:25:35.331930Z INFO kernel: [ 1605.301511] pcieport 0000:00:16.1: PM:
pci_pm_resume+0x0/0xed returned 0 after 6741 usecs
2024-04-26T14:25:35.331957Z INFO kernel: [ 1605.301902] pcieport 0000:00:16.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 7545 usecs
2024-04-26T14:25:35.331983Z INFO kernel: [ 1605.301952] pcieport 0000:00:16.3: PM:
calling pci_pm_resume+0x0/0xed @ 15148, parent: pci0000:00
2024-04-26T14:25:35.332160Z INFO kernel: [ 1605.303749] pcieport 0000:00:16.4: PM:
calling pci_pm_resume+0x0/0xed @ 15282, parent: pci0000:00
2024-04-26T14:25:35.332189Z INFO kernel: [ 1605.305972] pcieport 0000:00:16.3: PM:
pci_pm_resume+0x0/0xed returned 0 after 3976 usecs
2024-04-26T14:25:35.332218Z INFO kernel: [ 1605.306027] pcieport 0000:00:16.5: PM:
calling pci_pm_resume+0x0/0xed @ 15148, parent: pci0000:00
2024-04-26T14:25:35.332244Z INFO kernel: [ 1605.306787] atkbd serio0: PM:
serio_resume+0x0/0x94 returned 0 after 15788 usecs
2024-04-26T14:25:35.332270Z INFO kernel: [ 1605.306819] psmouse serio1: PM: calling
serio_resume+0x0/0x94 @ 15271, parent: i8042
2024-04-26T14:25:35.332296Z INFO kernel: [ 1605.307247] pcieport 0000:00:16.4: PM:
pci_pm_resume+0x0/0xed returned 0 after 3454 usecs
```

```
2024-04-26T14:25:35.332321Z INFO kernel: [ 1605.310102] pcieport 0000:00:16.2: PM:
pci_pm_resume+0x0/0xed returned 0 after 2418 usecs
2024-04-26T14:25:35.332349Z INFO kernel: [ 1605.310148] pcieport 0000:00:16.6: PM:
calling pci_pm_resume+0x0/0xed @ 15281, parent: pci0000:00
2024-04-26T14:25:35.332373Z INFO kernel: [ 1605.311768] pcieport 0000:00:16.7: PM:
calling pci_pm_resume+0x0/0xed @ 15278, parent: pci0000:00
2024-04-26T14:25:35.332399Z INFO kernel: [ 1605.313780] pcieport 0000:00:15.4: PM:
pci_pm_resume+0x0/0xed returned 0 after 15874 usecs
2024-04-26T14:25:35.332426Z INFO kernel: [ 1605.313837] pcieport 0000:00:17.0: PM:
calling pci_pm_resume+0x0/0xed @ 15280, parent: pci0000:00
2024-04-26T14:25:35.332451Z INFO kernel: [ 1605.314457] psmouse serio1: PM:
serio_resume+0x0/0x94 returned 0 after 7589 usecs
2024-04-26T14:25:35.332475Z INFO kernel: [ 1605.314497] alarmtimer alarmtimer.0.auto: PM:
calling platform_pm_resume+0x0/0x41 @ 15271, parent: rtc0
2024-04-26T14:25:35.332500Z INFO kernel: [ 1605.316760] alarmtimer alarmtimer.0.auto: PM:
platform_pm_resume+0x0/0x41 returned 0 after 2211 usecs
2024-04-26T14:25:35.332524Z INFO kernel: [ 1605.317002] pcieport 0000:00:15.7: PM:
pci_pm_resume+0x0/0xed returned 0 after 15610 usecs
2024-04-26T14:25:35.332548Z INFO kernel: [ 1605.317121] pcieport 0000:00:17.1: PM:
calling pci_pm_resume+0x0/0xed @ 15151, parent: pci0000:00
2024-04-26T14:25:35.332572Z INFO kernel: [ 1605.323609] pcieport 0000:00:17.2: PM:
calling pci_pm_resume+0x0/0xed @ 15283, parent: pci0000:00
2024-04-26T14:25:35.332595Z INFO kernel: [ 1605.323932] pcieport 0000:00:16.6: PM:
pci_pm_resume+0x0/0xed returned 0 after 13680 usecs
2024-04-26T14:25:35.332620Z INFO kernel: [ 1605.323991] pcieport 0000:00:17.3: PM:
calling pci_pm_resume+0x0/0xed @ 15281, parent: pci0000:00
2024-04-26T14:25:35.332644Z INFO kernel: [ 1605.324754] pcieport 0000:00:17.4: PM:
calling pci_pm_resume+0x0/0xed @ 15282, parent: pci0000:00
2024-04-26T14:25:35.332666Z INFO kernel: [ 1605.328746] pcieport 0000:00:17.3: PM:
pci_pm_resume+0x0/0xed returned 0 after 4708 usecs
2024-04-26T14:25:35.332695Z INFO kernel: [ 1605.328825] pcieport 0000:00:15.6: PM:
pci_pm_resume+0x0/0xed returned 0 after 36396 usecs
2024-04-26T14:25:35.332720Z INFO kernel: [ 1605.328871] pcieport 0000:00:17.5: PM:
calling pci_pm_resume+0x0/0xed @ 15279, parent: pci0000:00
2024-04-26T14:25:35.332747Z INFO kernel: [ 1605.331928] pcieport 0000:00:17.4: PM:
pci_pm_resume+0x0/0xed returned 0 after 7124 usecs
2024-04-26T14:25:35.332772Z INFO kernel: [ 1605.332405] pcieport 0000:00:16.5: PM:
pci_pm_resume+0x0/0xed returned 0 after 26331 usecs
2024-04-26T14:25:35.332797Z INFO kernel: [ 1605.332457] pcieport 0000:00:17.6: PM:
calling pci_pm_resume+0x0/0xed @ 15148, parent: pci0000:00
2024-04-26T14:25:35.332820Z INFO kernel: [ 1605.335171] pcieport 0000:00:17.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 21288 usecs
2024-04-26T14:25:35.332847Z INFO kernel: [ 1605.337118] pcieport 0000:00:17.2: PM:
pci_pm_resume+0x0/0xed returned 0 after 3422 usecs
2024-04-26T14:25:35.332873Z INFO kernel: [ 1605.337313] pcieport 0000:00:17.7: PM:
calling pci_pm_resume+0x0/0xed @ 15283, parent: pci0000:00
2024-04-26T14:25:35.332899Z INFO kernel: [ 1605.337331] pcieport 0000:00:17.5: PM:
pci_pm_resume+0x0/0xed returned 0 after 8423 usecs
2024-04-26T14:25:35.332925Z INFO kernel: [ 1605.337374] pcieport 0000:00:18.0: PM:
calling pci_pm_resume+0x0/0xed @ 15279, parent: pci0000:00
2024-04-26T14:25:35.332952Z INFO kernel: [ 1605.341257] pcieport 0000:00:17.1: PM:
pci_pm_resume+0x0/0xed returned 0 after 24089 usecs
2024-04-26T14:25:35.332977Z INFO kernel: [ 1605.341874] pcieport 0000:00:17.6: PM:
pci_pm_resume+0x0/0xed returned 0 after 9372 usecs
2024-04-26T14:25:35.333003Z INFO kernel: [ 1605.341925] pcieport 0000:00:18.1: PM:
calling pci_pm_resume+0x0/0xed @ 15148, parent: pci0000:00
2024-04-26T14:25:35.333167Z INFO kernel: [ 1605.341925] pcieport 0000:00:18.2: PM:
calling pci_pm_resume+0x0/0xed @ 15280, parent: pci0000:00
2024-04-26T14:25:35.333193Z INFO kernel: [ 1605.342091] pcieport 0000:00:17.7: PM:
pci_pm_resume+0x0/0xed returned 0 after 4730 usecs
2024-04-26T14:25:35.333220Z INFO kernel: [ 1605.342145] pcieport 0000:00:18.3: PM:
calling pci_pm_resume+0x0/0xed @ 15283, parent: pci0000:00
2024-04-26T14:25:35.333245Z INFO kernel: [ 1605.344725] pcieport 0000:00:18.4: PM:
calling pci_pm_resume+0x0/0xed @ 15281, parent: pci0000:00
2024-04-26T14:25:35.333270Z INFO kernel: [ 1605.345997] pcieport 0000:00:18.5: PM:
calling pci_pm_resume+0x0/0xed @ 15151, parent: pci0000:00
2024-04-26T14:25:35.333294Z INFO kernel: [ 1605.346072] pcieport 0000:00:18.6: PM:
calling pci_pm_resume+0x0/0xed @ 15284, parent: pci0000:00
2024-04-26T14:25:35.333329Z INFO kernel: [ 1605.349204] pcieport 0000:00:18.4: PM:
```

```
pci_pm_resume+0x0/0xed returned 0 after 4434 usecs
2024-04-26T14:25:35.333363Z INFO kernel: [ 1605.349350] pcieport 0000:00:18.7: PM:
calling pci_pm_resume+0x0/0xed @ 15281, parent: pci0000:00
2024-04-26T14:25:35.333386Z INFO kernel: [ 1605.351788] input input1: PM: calling
input_dev_resume+0x0/0x42 @ 15271, parent: serio0
2024-04-26T14:25:35.333408Z INFO kernel: [ 1605.351836] pcieport 0000:00:18.6: PM:
pci_pm_resume+0x0/0xed returned 0 after 5722 usecs
2024-04-26T14:25:35.333572Z INFO kernel: [ 1605.351887] uhci_hcd 0000:02:00.0: PM:
calling pci_pm_resume+0x0/0xed @ 15284, parent: 0000:00:11.0
2024-04-26T14:25:35.333604Z INFO kernel: [ 1605.353313] pcieport 0000:00:18.7: PM:
pci_pm_resume+0x0/0xed returned 0 after 3921 usecs
2024-04-26T14:25:35.333671Z INFO kernel: [ 1605.353355] e1000 0000:02:01.0: PM: calling
pci_pm_resume+0x0/0xed @ 15281, parent: 0000:00:11.0
2024-04-26T14:25:35.333706Z INFO kernel: [ 1605.355233] snd_hda_intel 0000:02:02.0: PM:
calling pci_pm_resume+0x0/0xed @ 15282, parent: 0000:00:11.0
2024-04-26T14:25:35.333728Z INFO kernel: [ 1605.355441] pcieport 0000:00:18.2: PM:
pci_pm_resume+0x0/0xed returned 0 after 13466 usecs
2024-04-26T14:25:35.333751Z INFO kernel: [ 1605.355509] ehci-pci 0000:02:03.0: PM:
calling pci_pm_resume+0x0/0xed @ 15280, parent: 0000:00:11.0
2024-04-26T14:25:35.333772Z NOTICE kernel: [ 1605.355497] usb usb2: root hub lost power
or was reset
2024-04-26T14:25:35.333793Z INFO kernel: [ 1605.358371] pcieport 0000:00:18.3: PM:
pci_pm_resume+0x0/0xed returned 0 after 16182 usecs
2024-04-26T14:25:35.333815Z INFO kernel: [ 1605.358475] nvme 0000:03:00.0: PM: calling
pci_pm_resume+0x0/0xed @ 15283, parent: 0000:00:15.0
2024-04-26T14:25:35.333837Z INFO kernel: [ 1605.358532] nvme 0000:03:00.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 20 usecs
2024-04-26T14:25:35.333874Z INFO kernel: [ 1605.358951] ehci-pci 0000:02:03.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 3394 usecs
2024-04-26T14:25:35.333906Z INFO kernel: [ 1605.359359] ata2: PM: calling
ata_port_pm_resume+0x0/0x56 @ 15283, parent: 0000:00:07.1
2024-04-26T14:25:35.333931Z INFO kernel: [ 1605.359361] ata1: PM: calling
ata_port_pm_resume+0x0/0x56 @ 15280, parent: 0000:00:07.1
2024-04-26T14:25:35.333959Z INFO kernel: [ 1605.359533] ata2: PM:
ata_port_pm_resume+0x0/0x56 returned 0 after 134 usecs
2024-04-26T14:25:35.333984Z INFO kernel: [ 1605.359774] usb usb1: PM: calling
usb_dev_resume+0x0/0x14 @ 15283, parent: 0000:02:03.0
2024-04-26T14:25:35.345220Z INFO kernel: [ 1605.362007] pcieport 0000:00:16.7: PM:
pci_pm_resume+0x0/0xed returned 0 after 19246 usecs
2024-04-26T14:25:35.345276Z INFO kernel: [ 1605.362210] uhci_hcd 0000:02:00.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 10280 usecs
2024-04-26T14:25:35.345307Z INFO kernel: [ 1605.362808] usb usb1: PM:
usb_dev_resume+0x0/0x14 returned 0 after 2993 usecs
2024-04-26T14:25:35.345334Z INFO kernel: [ 1605.363030] usb usb2: PM: calling
usb_dev_resume+0x0/0x14 @ 15278, parent: 0000:02:00.0
2024-04-26T14:25:35.345362Z INFO kernel: [ 1605.365762] ata1: PM:
ata_port_pm_resume+0x0/0x56 returned 0 after 6352 usecs
2024-04-26T14:25:35.345388Z INFO kernel: [ 1605.366456] pcieport 0000:00:18.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 29043 usecs
2024-04-26T14:25:35.345415Z INFO kernel: [ 1605.374523] pcieport 0000:00:18.5: PM:
pci_pm_resume+0x0/0xed returned 0 after 2210 usecs
2024-04-26T14:25:35.345443Z INFO kernel: [ 1605.377752] input input1: PM:
input_dev_resume+0x0/0x42 returned 0 after 307 usecs
2024-04-26T14:25:35.345470Z INFO kernel: [ 1605.377796] leds input1::numlock: PM: calling
led_resume+0x0/0x20 @ 15271, parent: input1
2024-04-26T14:25:35.345508Z INFO kernel: [ 1605.377966] leds input1::numlock: PM:
led_resume+0x0/0x20 returned 0 after 21 usecs
2024-04-26T14:25:35.345535Z INFO kernel: [ 1605.377998] leds input1::capslock: PM:
calling led_resume+0x0/0x20 @ 15271, parent: input1
2024-04-26T14:25:35.345565Z INFO kernel: [ 1605.378058] leds input1::capslock: PM:
led_resume+0x0/0x20 returned 0 after 17 usecs
2024-04-26T14:25:35.345596Z INFO kernel: [ 1605.378086] leds input1::scrolllock: PM:
calling led_resume+0x0/0x20 @ 15271, parent: input1
2024-04-26T14:25:35.345627Z INFO kernel: [ 1605.378149] leds input1::scrolllock: PM:
led_resume+0x0/0x20 returned 0 after 17 usecs
2024-04-26T14:25:35.345651Z INFO kernel: [ 1605.378178] input input4: PM: calling
input_dev_resume+0x0/0x42 @ 15271, parent: serio1
2024-04-26T14:25:35.345673Z INFO kernel: [ 1605.378243] input input4: PM:
input_dev_resume+0x0/0x42 returned 0 after 17 usecs
```

```
2024-04-26T14:25:35.345694Z INFO kernel: [ 1605.378273] input input3: PM: calling
input_dev_resume+0x0/0x42 @ 15271, parent: serio1
2024-04-26T14:25:35.345718Z INFO kernel: [ 1605.378337] input input3: PM:
input_dev_resume+0x0/0x42 returned 0 after 19 usecs
2024-04-26T14:25:35.345740Z INFO kernel: [ 1605.379944] pcieport 0000:00:18.1: PM:
pci_pm_resume+0x0/0xed returned 0 after 13390 usecs
2024-04-26T14:25:35.345761Z INFO kernel: [ 1605.423318] e1000 0000:02:01.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 69921 usecs
2024-04-26T14:25:35.345786Z INFO kernel: [ 1605.433906] e1000: eth0 NIC Link is Up 1000
Mbps Full Duplex, Flow Control: None
2024-04-26T14:25:35.345821Z ERR kernel: [ 1605.457301] snd_hda_intel 0000:02:02.0: CORB
reset timeout#1, CORBRP = 0
2024-04-26T14:25:35.345855Z INFO kernel: [ 1605.489046] usb usb2: PM:
usb_dev_resume+0x0/0x14 returned 0 after 125967 usecs
2024-04-26T14:25:35.345894Z INFO kernel: [ 1605.491927] snd_hda_intel 0000:02:02.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 105802 usecs
2024-04-26T14:25:35.345923Z INFO kernel: [ 1605.496161] usb 2-1: PM: calling
usb_dev_resume+0x0/0x14 @ 15285, parent: usb2
2024-04-26T14:25:35.345956Z INFO kernel: [ 1605.497676] usb 2-2: PM: calling
usb_dev_resume+0x0/0x14 @ 15287, parent: usb2
2024-04-26T14:25:35.345988Z INFO kernel: [ 1605.500805] snd_hda_codec_generic
hdaudioC0D0: PM: calling hda_codec_pm_resume+0x0/0x19 [snd_hda_codec] @ 15296, parent:
0000:02:02.0
2024-04-26T14:25:35.346178Z INFO kernel: [ 1605.507223] usb 2-1: PM:
usb_dev_resume+0x0/0x14 returned 0 after 18 usecs
2024-04-26T14:25:35.346211Z INFO kernel: [ 1605.548006] nvme nvme0: 8/0/0
default/read/poll queues
2024-04-26T14:25:35.346240Z INFO kernel: [ 1605.591218] input input5: PM: calling
input_dev_resume+0x0/0x42 @ 15271, parent: 0003:0E0F:0003.0001
2024-04-26T14:25:35.346267Z INFO kernel: [ 1605.591295] input input5: PM:
input_dev_resume+0x0/0x42 returned 0 after 20 usecs
2024-04-26T14:25:35.346294Z INFO kernel: [ 1605.591340] platform regulatory.0: PM:
calling platform_pm_resume+0x0/0x41 @ 15271, parent: platform
2024-04-26T14:25:35.346328Z INFO kernel: [ 1605.591410] platform regulatory.0: PM:
platform_pm_resume+0x0/0x41 returned 0 after 20 usecs
2024-04-26T14:25:35.346366Z INFO kernel: [ 1605.619114] snd_hda_codec_generic
hdaudioC0D0: PM: hda_codec_pm_resume+0x0/0x19 [snd_hda_codec] returned 0 after 107898
usecs
2024-04-26T14:25:35.346392Z INFO kernel: [ 1605.666779] usb 2-2: reset full-speed USB
device number 3 using uhci_hcd
2024-04-26T14:25:35.346415Z INFO kernel: [ 1605.669108] input input6: PM: calling
input_dev_resume+0x0/0x42 @ 15271, parent: card0
2024-04-26T14:25:35.346437Z ERR kernel: [ 1605.701584] tpm tpm0: Operation Timed out
2024-04-26T14:25:35.346460Z INFO kernel: [ 1605.701984] input input6: PM:
input_dev_resume+0x0/0x42 returned 0 after 21 usecs
2024-04-26T14:25:35.346484Z WARNING kernel: [ 1605.705944] hwrng: no data available
2024-04-26T14:25:35.346519Z INFO kernel: [ 1605.709124] input input7: PM: calling
input_dev_resume+0x0/0x42 @ 15271, parent: card0
2024-04-26T14:25:35.346546Z INFO kernel: [ 1605.709202] input input7: PM:
input_dev_resume+0x0/0x42 returned 0 after 19 usecs
2024-04-26T14:25:35.346572Z INFO kernel: [ 1606.049087] usb 2-2: PM:
usb_dev_resume+0x0/0x14 returned 0 after 551291 usecs
2024-04-26T14:25:35.346609Z INFO kernel: [ 1606.051234] input input8: PM: calling
input_dev_resume+0x0/0x42 @ 15271, parent: card0
2024-04-26T14:25:35.346639Z INFO kernel: [ 1606.053304] usb 2-2.1: PM: calling
usb_dev_resume+0x0/0x14 @ 15148, parent: 2-2
2024-04-26T14:25:35.346665Z INFO kernel: [ 1606.057046] input input8: PM:
input_dev_resume+0x0/0x42 returned 0 after 19 usecs
2024-04-26T14:25:35.346691Z INFO kernel: [ 1606.060212] usb 2-2.1: PM:
usb_dev_resume+0x0/0x14 returned 0 after 18 usecs
2024-04-26T14:25:35.346713Z INFO kernel: [ 1606.063187] input input9: PM: calling
input_dev_resume+0x0/0x42 @ 15271, parent: card0
2024-04-26T14:25:35.346734Z INFO kernel: [ 1606.081009] input input9: PM:
input_dev_resume+0x0/0x42 returned 0 after 19 usecs
2024-04-26T14:25:35.346754Z INFO kernel: [ 1606.084722] input input10: PM: calling
input_dev_resume+0x0/0x42 @ 15271, parent: card0
2024-04-26T14:25:35.346780Z INFO kernel: [ 1606.088725] input input10: PM:
input_dev_resume+0x0/0x42 returned 0 after 18 usecs
2024-04-26T14:25:35.346806Z INFO kernel: [ 1606.092744] rfkill rfkill0: PM: calling
```

```
rfkill_resume+0x0/0x69 @ 15271, parent: hci0
2024-04-26T14:25:35.346831Z INFO kernel: [ 1606.098577] rfkill rfkill0: PM:
rfkill_resume+0x0/0x69 returned 0 after 1821 usecs
2024-04-26T14:25:35.346856Z DEBUG kernel: [ 1606.102472] PM: resume of devices complete
after 828.530 msecs
2024-04-26T14:25:35.346882Z DEBUG kernel: [ 1606.107016] PM: Finishing wakeup.
2024-04-26T14:25:35.346916Z INFO kernel: [ 1606.107044] OOM killer enabled.
2024-04-26T14:25:35.346949Z INFO kernel: [ 1606.108497] Restarting tasks ...
2024-04-26T14:25:35.346979Z INFO kernel: [ 1606.178687] usb 2-1: USB disconnect, device
number 2
2024-04-26T14:25:35.347003Z WARNING kernel: [ 1606.216512] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:25:35.347154Z WARNING kernel: [ 1606.219465] audit: audit_lost=19
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:25:35.347178Z ERR kernel: [ 1606.233827] audit: backlog limit exceeded
2024-04-26T14:25:35.347200Z WARNING kernel: [ 1606.242782] done.
2024-04-26T14:25:35.347223Z INFO kernel: [ 1606.243021] usb 2-2.1: USB disconnect, device
number 4
2024-04-26T14:25:35.347245Z INFO kernel: [ 1606.244454] Resume caused by IRQ 12, i8042
2024-04-26T14:25:35.347268Z INFO kernel: [ 1606.254321] PM: suspend exit
2024-04-26T14:25:35.347291Z INFO kernel: [ 1606.421821] usb 2-2.1: new full-speed USB
device number 5 using uhci_hcd
2024-04-26T14:25:35.407567Z INFO kernel: [ 1606.542398] usb 2-2.1: New USB device found,
idVendor=0e0f, idProduct=0008, bcdDevice= 1.00
2024-04-26T14:25:35.407604Z INFO kernel: [ 1606.547808] usb 2-2.1: New USB device
strings: Mfr=1, Product=2, SerialNumber=3
2024-04-26T14:25:35.417436Z INFO kernel: [ 1606.558125] usb 2-2.1: Product: Virtual
Bluetooth Adapter
2024-04-26T14:25:35.421560Z INFO kernel: [ 1606.564257] usb 2-2.1: Manufacturer: VMware
2024-04-26T14:25:35.428295Z INFO kernel: [ 1606.570864] usb 2-2.1: SerialNumber:
000650268328
2024-04-26T14:25:35.445718Z DEBUG kernel: [ 1606.590181] usb 2-2.1: GPIO lookup for
consumer reset
2024-04-26T14:25:35.445842Z DEBUG kernel: [ 1606.590216] usb 2-2.1: using lookup tables
for GPIO lookup
2024-04-26T14:25:35.445872Z DEBUG kernel: [ 1606.590350] usb 2-2.1: No GPIO consumer
reset found
2024-04-26T14:25:35.493685Z INFO kernel: [ 1606.630829] usb 2-1: new full-speed USB
device number 6 using uhci_hcd
2024-04-26T14:25:35.513300Z NOTICE powerd_suspend[15184]: Resume finished
2024-04-26T14:25:35.573356Z ERR kernel: [ 1606.710178] Bluetooth: hci0: unexpected cc
0x0c12 length: 2 < 3
2024-04-26T14:25:35.573450Z ERR kernel: [ 1606.714748] Bluetooth: hci0: Opcode 0x c12
failed: -38
2024-04-26T14:25:35.685749Z INFO kernel: [ 1606.821925] usb 2-1: New USB device found,
idVendor=0e0f, idProduct=0003, bcdDevice= 1.03
2024-04-26T14:25:35.685877Z INFO kernel: [ 1606.827529] usb 2-1: New USB device strings:
Mfr=1, Product=2, SerialNumber=0
2024-04-26T14:25:35.692250Z INFO kernel: [ 1606.834772] usb 2-1: Product: VMware Virtual
USB Mouse
2024-04-26T14:25:35.707476Z INFO kernel: [ 1606.850817] usb 2-1: Manufacturer: VMware
2024-04-26T14:25:35.796676Z INFO kernel: [ 1606.881844] input: VMware VMware Virtual USB
Mouse as /devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-1/2-
1:1.0/0003:0E0F:0003.0002/input/input11
2024-04-26T14:25:35.823608Z INFO kernel: [ 1606.947970] hid-generic 0003:0E0F:0003.0002:
input,hidraw0: USB HID v1.10 Mouse [VMware VMware Virtual USB Mouse] on usb-0000:02:00.0-
1/input0
2024-04-26T14:25:36.351013Z ERR shill[785]: ERROR shill: [rtnl_message.cc(1103)] RTNL
address message does not have a valid IFA_ADDRESS
2024-04-26T14:25:37.357621Z INFO usb_bouncer[15440]: Reporting metrics for
/devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-1
2024-04-26T14:25:37.372186Z INFO usb_bouncer[15441]: Reporting metrics for
/devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-2/2-2.1
2024-04-26T14:25:37.765588Z NOTICE send_metrics_on_resume[15496]: Unable to get
firmware_resume_time
2024-04-26T14:25:38.352260Z ERR kernel: [ 1609.463976] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:25:38.447241Z ERR kernel: [ 1609.587260] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
```

```
2024-04-26T14:25:39.729509Z INFO permission_broker[1301]:
ProcessPath(/dev/bus/usb/002/005)
2024-04-26T14:25:40.562430Z ERR kernel: [ 1611.703395] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:25:40.571211Z ERR kernel: [ 1611.708209] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:25:41.849321Z ERR kernel: [ 1612.991299] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:25:42.192525Z ERR kernel: [ 1613.303011] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:25:42.207200Z ERR kernel: [ 1613.347327] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:25:42.215189Z ERR kernel: [ 1613.357057] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:25:42.496873Z ERR kernel: [ 1613.636932] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:25:42.744933Z INFO permission_broker[1301]: AllowUsbDeviceRule: ALLOW
2024-04-26T14:25:42.745799Z INFO permission_broker[1301]: AllowTtyDeviceRule: IGNORE
2024-04-26T14:25:42.752553Z INFO permission_broker[1301]: Found claimed interface with
driver: btusb
2024-04-26T14:25:42.760651Z INFO permission_broker[1301]: Found claimed interface with
driver: btusb
2024-04-26T14:25:42.784367Z INFO permission_broker[1301]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T14:25:42.784674Z INFO permission_broker[1301]: Verdict for
/dev/bus/usb/002/005: DENY
2024-04-26T14:25:42.785319Z INFO permission_broker[1301]:
ProcessPath(/dev/bus/usb/002/005)
2024-04-26T14:25:43.117781Z INFO vm_cicerone[4469]: System timezone changed, updating
container timezones
2024-04-26T14:25:43.555427Z INFO permission_broker[1301]: AllowUsbDeviceRule: ALLOW
2024-04-26T14:25:43.555854Z INFO permission_broker[1301]: AllowTtyDeviceRule: IGNORE
2024-04-26T14:25:43.567975Z INFO permission_broker[1301]: Found claimed interface with
driver: btusb
2024-04-26T14:25:43.577537Z INFO permission_broker[1301]: Found claimed interface with
driver: btusb
2024-04-26T14:25:43.582918Z INFO permission_broker[1301]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T14:25:43.584132Z INFO permission_broker[1301]: Verdict for
/dev/bus/usb/002/005: DENY
2024-04-26T14:25:43.584759Z INFO permission_broker[1301]:
ProcessPath(/dev/bus/usb/002/005)
2024-04-26T14:25:44.476518Z ERR kernel: [ 1615.617268] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:25:44.632702Z INFO permission_broker[1301]: AllowUsbDeviceRule: ALLOW
2024-04-26T14:25:44.633417Z INFO permission_broker[1301]: AllowTtyDeviceRule: IGNORE
2024-04-26T14:25:44.639380Z INFO permission_broker[1301]: Found claimed interface with
driver: btusb
2024-04-26T14:25:44.642812Z INFO permission_broker[1301]: Found claimed interface with
driver: btusb
2024-04-26T14:25:44.645737Z INFO permission_broker[1301]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T14:25:44.646775Z INFO permission_broker[1301]: Verdict for
/dev/bus/usb/002/005: DENY
2024-04-26T14:25:44.651988Z INFO permission_broker[1301]:
ProcessPath(/dev/bus/usb/002/006)
2024-04-26T14:25:45.473994Z INFO permission_broker[1301]: AllowUsbDeviceRule: ALLOW
2024-04-26T14:25:45.474496Z INFO permission_broker[1301]: AllowTtyDeviceRule: IGNORE
2024-04-26T14:25:45.479966Z INFO permission_broker[1301]: Found claimed interface with
driver: usbhid
2024-04-26T14:25:45.487553Z INFO permission_broker[1301]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T14:25:45.487894Z INFO permission_broker[1301]: Verdict for
/dev/bus/usb/002/006: DENY
2024-04-26T14:25:45.488497Z INFO permission_broker[1301]:
ProcessPath(/dev/bus/usb/002/006)
2024-04-26T14:25:46.219857Z INFO permission_broker[1301]: AllowUsbDeviceRule: ALLOW
2024-04-26T14:25:46.224984Z INFO permission_broker[1301]: AllowTtyDeviceRule: IGNORE
2024-04-26T14:25:46.230954Z INFO permission_broker[1301]: Found claimed interface with
```

```
driver: usbhid
2024-04-26T14:25:46.244400Z INFO permission_broker[1301]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T14:25:46.244824Z INFO permission_broker[1301]: Verdict for
/dev/bus/usb/002/006: DENY
2024-04-26T14:25:46.245498Z INFO permission_broker[1301]:
ProcessPath(/dev/bus/usb/002/006)
2024-04-26T14:25:47.043669Z INFO permission_broker[1301]: AllowUsbDeviceRule: ALLOW
2024-04-26T14:25:47.044397Z INFO permission_broker[1301]: AllowTtyDeviceRule: IGNORE
2024-04-26T14:25:47.061783Z INFO permission_broker[1301]: Found claimed interface with
driver: usbhid
2024-04-26T14:25:47.080270Z INFO permission_broker[1301]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T14:25:47.081923Z INFO permission_broker[1301]: Verdict for
/dev/bus/usb/002/006: DENY
2024-04-26T14:25:48.353220Z ERR kernel: [ 1619.484705] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:25:48.381235Z ERR kernel: [ 1619.506935] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:26:00.317240Z ERR kernel: [ 1631.458122] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:26:00.329397Z ERR kernel: [ 1631.470361] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:26:08.390404Z INFO cups_launcher[1050]: Stopping after signal received
2024-04-26T14:26:08.455217Z INFO smbproviderd[4491]: smbproviderd stopping with exit code
0
2024-04-26T14:26:08.597295Z INFO kernel: [ 1639.739270] binder: release 4273:4273
transaction 381401 in, still active
2024-04-26T14:26:08.612149Z INFO kernel: [ 1639.755232] binder: send failed reply for
transaction 381401 to 4763:5507
2024-04-26T14:26:08.652864Z INFO minijail0[15956]: libminijail[15956]: applying policy
for default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:26:08.698612Z WARNING minijail0[15956]: libminijail[15956]: failed to
create a ruleset: Function not implemented
2024-04-26T14:26:08.709514Z WARNING minijail0[15956]: libminijail[15956]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:26:08.710686Z WARNING minijail0[15971]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:26:08.711325Z WARNING minijail0[15971]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:26:08.711817Z INFO minijail0[15971]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:26:08.754987Z INFO mojo_service_manager[707]: Disconnected from
u:r:cros_shill:s0
2024-04-26T14:26:08.806935Z INFO kernel: [ 1639.949150] binder: undelivered death
notification, 00007e3cc3e1c0a0
2024-04-26T14:26:08.819389Z INFO vm_cicerone[4469]: Shutting down due to SIGTERM
2024-04-26T14:26:08.833234Z ERR shill[785]: ERROR shill: [object_proxy.cc(590)] Failed to
call method: org.chromium.dhccpd.Release: object_path= /org/chromium/dhccpd:
org.freedesktop.DBus.Error.ServiceUnknown: The name :1.39 was not provided by any
.service files
2024-04-26T14:26:08.833333Z ERR shill[785]: ERROR shill: [dbus_method_invoker.h(115)]
CallMethodAndBlockWithTimeout(...): Domain=dbus,
Code=org.freedesktop.DBus.Error.ServiceUnknown, Message=Error calling D-Bus method:
org.chromium.dhccpd.Release: The name :1.39 was not provided by any .service files
2024-04-26T14:26:08.873421Z INFO seneschal[4423]: Shutting down due to SIGTERM
2024-04-26T14:26:08.885010Z INFO avahi-daemon[1362]: Withdrawing address record for
192.168.9.128 on eth0.
2024-04-26T14:26:08.887542Z INFO avahi-daemon[1362]: Leaving mDNS multicast group on
interface eth0.IPv4 with address 192.168.9.128.
2024-04-26T14:26:08.980853Z INFO avahi-daemon[1362]: Interface eth0.IPv4 no longer
relevant for mDNS.
2024-04-26T14:26:09.065886Z ERR dnsproxyd[2042]: ERROR dnsproxyd: [object_proxy.cc(590)]
Failed to call method: org.chromium.flimflam.Manager.ClearDNSProxyAddresses: object_path=
/: org.freedesktop.DBus.Error.UnknownMethod: Method "ClearDNSProxyAddresses" with
signature "" on interface "org.chromium.flimflam.Manager" doesn't exist#012
2024-04-26T14:26:09.065966Z ERR dnsproxyd[2042]: ERROR dnsproxyd:
[dbus_method_invoker.h(115)] CallMethodAndBlockWithTimeout(...): Domain=dbus,
Code=org.freedesktop.DBus.Error.UnknownMethod, Message=Error calling D-Bus method:
```



```
org.chromium.flimflam.Manager.ClearDNSProxyAddresses: Method "ClearDNSProxyAddresses"
with signature "" on interface "org.chromium.flimflam.Manager" doesn't exist#012
2024-04-26T14:26:09.067957Z ERR patchpaneld[1267]: ERROR patchpaneld:
[dbus_method_invoker.h(115)] CallMethodAndBlockWithTimeout(...): Domain=dbus,
Code=org.freedesktop.DBus.Error.UnknownObject, Message=Error calling D-Bus method:
org.chromium.flimflam.Device.GetProperties: Method "GetProperties" with signature "" on
interface "org.chromium.flimflam.Device" doesn't exist#012
2024-04-26T14:26:09.078546Z ERR dnsproxyd[4793]: ERROR dnsproxyd: [object_proxy.cc(590)]
Failed to call method: org.chromium.flimflam.Manager.GetProperties: object_path= /:
org.freedesktop.DBus.Error.ServiceUnknown: The name org.chromium.flimflam was not
provided by any .service files
2024-04-26T14:26:09.078620Z ERR dnsproxyd[4793]: ERROR dnsproxyd:
[dbus_method_invoker.h(115)] CallMethodAndBlockWithTimeout(...): Domain=dbus,
Code=org.freedesktop.DBus.Error.ServiceUnknown, Message=Error calling D-Bus method:
org.chromium.flimflam.Manager.GetProperties: The name org.chromium.flimflam was not
provided by any .service files
2024-04-26T14:26:09.080280Z ERR dnsproxyd[2046]: ERROR dnsproxyd: [object_proxy.cc(590)]
Failed to call method: org.chromium.flimflam.Manager.GetProperties: object_path= /:
org.freedesktop.DBus.Error.ServiceUnknown: The name org.chromium.flimflam was not
provided by any .service files
2024-04-26T14:26:09.080359Z ERR dnsproxyd[2046]: ERROR dnsproxyd:
[dbus_method_invoker.h(115)] CallMethodAndBlockWithTimeout(...): Domain=dbus,
Code=org.freedesktop.DBus.Error.ServiceUnknown, Message=Error calling D-Bus method:
org.chromium.flimflam.Manager.GetProperties: The name org.chromium.flimflam was not
provided by any .service files
2024-04-26T14:26:09.089531Z ERR dnsproxyd[2042]: ERROR dnsproxyd: [object_proxy.cc(590)]
Failed to call method: org.chromium.flimflam.Manager.GetProperties: object_path= /:
org.freedesktop.DBus.Error.ServiceUnknown: The name org.chromium.flimflam was not
provided by any .service files
2024-04-26T14:26:09.089911Z ERR dnsproxyd[2042]: ERROR dnsproxyd:
[dbus_method_invoker.h(115)] CallMethodAndBlockWithTimeout(...): Domain=dbus,
Code=org.freedesktop.DBus.Error.ServiceUnknown, Message=Error calling D-Bus method:
org.chromium.flimflam.Manager.GetProperties: The name org.chromium.flimflam was not
provided by any .service files
2024-04-26T14:26:09.287533Z INFO minijail0[15956]: libminijail[15956]: child process
15971 exited with status 2
2024-04-26T14:26:09.316793Z INFO session_manager[1034]: INFO session_manager:
[session_manager_impl.cc(504)] Emitting D-Bus signal SessionStateChanged: stopping
2024-04-26T14:26:09.322195Z INFO session_manager[1034]: INFO session_manager:
[browser_job.cc(267)] Terminating browser process 1056 with signal 15: exiting cleanly
2024-04-26T14:26:09.322481Z INFO session_manager[1034]: INFO session_manager:
[system_utils_impl.cc(131)] Sending signal 15 to PID 1056 as UID 1000
2024-04-26T14:26:09.323469Z INFO session_manager[1034]: INFO session_manager:
[android_oci_wrapper.cc(252)] Gracefully shutting down container
2024-04-26T14:26:09.393481Z INFO session_manager[1034]: INFO session_manager:
[session_manager_service.cc(658)] Waiting up to 3 seconds for browser process group to
exit
2024-04-26T14:26:09.586099Z INFO kernel: [ 1640.727317] binder: release 4987:4987
transaction 374321 in, still active
2024-04-26T14:26:09.586197Z INFO kernel: [ 1640.729410] binder: send failed reply for
transaction 374321 to 4763:5485
2024-04-26T14:26:11.691630Z INFO fusebox[4499]: Kernel FUSE : umount(8) /dev/fd/11
2024-04-26T14:26:11.807544Z INFO bluetoothd[748]: Applied debug levels: bluez(0),
kernel(0)
2024-04-26T14:26:12.396412Z WARNING session_manager[1034]: WARNING session_manager:
[session_manager_service.cc(668)] Browser process did not exit 3 seconds after SIGTERM.
2024-04-26T14:26:12.399179Z ERR session_manager[1034]: ERROR session_manager:
[safe_fd.cc(701)] unlinkat failed: No such file or directory (2)
2024-04-26T14:26:12.404249Z WARNING session_manager[1034]: WARNING session_manager:
[browser_job.cc(291)] Aborting browser process 1056
2024-04-26T14:26:12.405379Z INFO session_manager[1034]: INFO session_manager:
[browser_job.cc(267)] Terminating browser process 1056 with signal 6: Browser aborted
2024-04-26T14:26:12.405654Z INFO session_manager[1034]: INFO session_manager:
[system_utils_impl.cc(131)] Sending signal 6 to PID 1056 as UID 1000
2024-04-26T14:26:12.639961Z INFO crash_reporter[16026]: developer build - not testing -
always dumping
2024-04-26T14:26:12.645419Z WARNING crash_reporter[16026]: Received crash notification
for chrome[1056] user 1000 (called directly)
2024-04-26T14:26:12.651397Z INFO crash_reporter[16027]: developer build - not testing -
```

```
always dumping
2024-04-26T14:26:12.654370Z WARNING crash_reporter[16027]: [user] Received crash
notification for chrome[1056] sig 6, user 1000 group 1000 (ignoring call by kernel -
chrome crash; waiting for chrome to call us directly)
2024-04-26T14:26:12.751611Z NOTICE ml-service[16028]: Post-stop ml-service
task=mojo_service
2024-04-26T14:26:13.349780Z INFO cros_camera_service[3758]: OnServiceMojoChannelError():
Mojo connection to (Chrome) CameraHalDispatcher is disconnected. Chrome may have crashed.
2024-04-26T14:26:13.356148Z INFO cros_camera_service[3758]: OnServiceMojoChannelError():
Mojo connection to (Chrome) CameraHalDispatcher is disconnected. Chrome may have crashed.
2024-04-26T14:26:13.377418Z ERR cros_camera_service[3758]: ExitOnMainThread(): cros-
camera terminated with error: Connection reset by peer
2024-04-26T14:26:13.459785Z INFO mojo_service_manager[707]: Disconnected from
u:r:cros_browser:s0
2024-04-26T14:26:13.467972Z WARNING missed[3680]: Service became unavailable
2024-04-26T14:26:13.468088Z INFO iioservice[712]: INFO iioservice:
[sensor_service_impl.cc(417)] (2) OnSensorServiceDisconnect(): SensorDevice disconnected.
ReceiverId: 1
2024-04-26T14:26:13.487426Z ERR missed[3680]: Failed to call method:
org.chromium.ChromeReportingServiceInterface.UploadEncryptedRecord: object_path=
/org/chromium/ChromeReportingService: org.freedesktop.DBus.Error.NoReply: Message
recipient disconnected from message bus without replying
2024-04-26T14:26:13.487998Z ERR missed[3680]: message repeated 3 times: [ Failed to
call method: org.chromium.ChromeReportingServiceInterface.UploadEncryptedRecord:
object_path= /org/chromium/ChromeReportingService: org.freedesktop.DBus.Error.NoReply:
Message recipient disconnected from message bus without replying]
2024-04-26T14:26:13.568999Z INFO session_manager[1034]: INFO session_manager:
[browser_job.cc(301)] browser group 1056 gone after SIGABRT wait
2024-04-26T14:26:13.570419Z INFO session_manager[1034]: INFO session_manager:
[android_oci_wrapper.cc(89)] Killing container 4229
2024-04-26T14:26:13.570532Z INFO session_manager[1034]: INFO session_manager:
[system_utils_impl.cc(131)] Sending signal 9 to PID 4229 as UID 4294967295
2024-04-26T14:26:13.661354Z INFO session_manager[1034]: INFO session_manager:
[android_oci_wrapper.cc(275)] Cleaning up container 4229
2024-04-26T14:26:13.745987Z INFO session_manager[1034]: INFO session_manager:
[session_manager_impl.cc(2278)] Android container with PID 4229 stopped
2024-04-26T14:26:13.746889Z INFO session_manager[1034]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting stop-arc-instance Upstart signal
2024-04-26T14:26:14.611514Z INFO kernel: [ 1645.754894] arc_eth0: port 1(vetheth0)
entered disabled state
2024-04-26T14:26:14.619103Z INFO kernel: [ 1645.761871] device vetheth0 left promiscuous
mode
2024-04-26T14:26:14.619173Z INFO kernel: [ 1645.763044] arc_eth0: port 1(vetheth0)
entered disabled state
2024-04-26T14:26:14.776572Z INFO kernel: [ 1645.919493] arcbr0: port 1(vetharc0) entered
disabled state
2024-04-26T14:26:14.784251Z INFO kernel: [ 1645.926105] device vetharc0 left promiscuous
mode
2024-04-26T14:26:14.784361Z INFO kernel: [ 1645.927664] arcbr0: port 1(vetharc0) entered
disabled state
2024-04-26T14:26:14.976934Z WARNING session_manager[1034]: WARNING session_manager:
[bus.cc(644)] Bus::SendWithReplyAndBlock took 1227ms to process message:
type=method_call, path=/com/ubuntu/Upstart, interface=com.ubuntu.Upstart0_6,
member=EmitEvent
2024-04-26T14:26:14.977381Z INFO session_manager[1034]: INFO session_manager:
[session_manager_impl.cc(511)] Emitting D-Bus signal SessionStateChanged: stopped
2024-04-26T14:26:14.977506Z INFO session_manager[1034]: INFO session_manager:
[session_manager_service.cc(643)] SessionManagerService quitting run loop
2024-04-26T14:26:14.985373Z ERR session_manager[1034]: ERROR session_manager:
[session_manager_impl.cc(1696)] Error getting Android container pid.
2024-04-26T14:26:14.985518Z ERR session_manager[1034]: ERROR session_manager:
[dbus_util.cc(13)] CreateError(...): Domain=dbus,
Code=org.chromium.SessionManagerInterface.ContainerShutdownFail, Message=Error getting
Android container pid.
2024-04-26T14:26:14.993622Z INFO session_manager[1034]: INFO session_manager:
[session_manager_service.cc(269)] SessionManagerService exiting
2024-04-26T14:26:14.996193Z WARNING crash_reporter[16026]: Bus::SendWithReplyAndBlock
took 2342ms to process message: type=method_call, path=/org/chromium/SessionManager,
interface=org.chromium.SessionManagerInterface, member=RetrieveActiveSessions
```

```
2024-04-26T14:26:14.997528Z INFO crash_reporter[16026]: Accessing crash dir '/run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65' via symlinked handle
'/proc/self/fd/10'
2024-04-26T14:26:15.342961Z INFO chapsd[793]: Closing database for /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database
2024-04-26T14:26:15.357776Z ERR crash_reporter[16026]: AddDBusError(...): Domain=dbus,
Code=org.freedesktop.DBus.Error.ServiceUnknown, Message=The name org.chromium.debugd was
not provided by any .service files
2024-04-26T14:26:15.358169Z ERR crash_reporter[16026]: Error retrieving DriErrorState
from debugd: The name org.chromium.debugd was not provided by any .service files
2024-04-26T14:26:15.358514Z ERR crash_reporter[16026]: AddDBusError(...): Domain=dbus,
Code=org.freedesktop.DBus.Error.ServiceUnknown, Message=The name org.chromium.debugd was
not provided by any .service files
2024-04-26T14:26:15.358794Z ERR crash_reporter[16026]: Error retrieving dmesg from
debugd: The name org.chromium.debugd was not provided by any .service files
2024-04-26T14:26:15.358865Z INFO chapsd[793]: levelldb /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database dump:#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/LOCK (0 bytes, 2024-03-26
12:37:20.000 UTC)#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/CURRENT (16 bytes, 2024-04-
26 14:00:49.000 UTC)#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/000008.ldb (614 bytes,
2024-03-26 13:05:31.000 UTC)#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/LOG.old (184 bytes, 2024-
04-24 14:51:20.000 UTC)#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/MANIFEST-000034 (138 bytes,
2024-04-26 14:00:49.000 UTC)#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/000035.log (0 bytes, 2024-
04-26 14:00:49.000 UTC)#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/000005.ldb (393 bytes,
2024-03-26 12:58:13.000 UTC)#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/LOG (184 bytes, 2024-04-26
14:00:49.000 UTC)
2024-04-26T14:26:15.359951Z INFO chapsd[793]: Token at /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65 has been removed from slot 1
2024-04-26T14:26:15.360162Z INFO crash_reporter[16026]: Finishing crash. Meta file:
/proc/self/fd/10/chrome.20240426.142614.75942.1056.meta
2024-04-26T14:26:15.924900Z WARNING chapsd[793]: Unload Token event received for unknown
path: /run/daemon-store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65
2024-04-26T14:26:15.931919Z WARNING chapsd[793]: Unload Token event received for unknown
path: /run/daemon-store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65
2024-04-26T14:26:16.071244Z ERR cryptohomed[856]: Unable to send signal to 4375: No such
process (3)
2024-04-26T14:26:18.208907Z NOTICE pre-shutdown[16147]: Shutting down for halt: not-via-
powerd
2024-04-26T14:26:18.244140Z WARNING imageloader[16148]: Could not read key file
/usr/share/misc/oci-container-key-pub.der
2024-04-26T14:26:18.284975Z WARNING minijail0[722]: libminijail[722]: child process 734
received signal 15
2024-04-26T14:26:18.353737Z INFO chapsd[793]: Chaps exit triggered by signal 15.
2024-04-26T14:26:18.370729Z INFO auditd[457]: The audit daemon is exiting.
2024-04-26T14:26:18.461272Z NOTICE kernel: [ 1649.521692] audit: type=1400
audit(1714141578.372:30258): avc: denied { read } for pid=712 comm="iioservice"
scontext=u:r:cros_iioservice:s0 tcontext=u:r:cros_mojo_service_manager:s0
tclass=unix_stream_socket permissive=1
2024-04-26T14:26:18.461391Z NOTICE kernel: [ 1649.564703] audit: type=1300
audit(1714141578.372:30258): arch=c000003e syscall=47 success=yes exit=0 a0=12
a1=7ffd3ae42ac0 a2=40 a3=0 items=0 ppid=693 pid=712 auid=4294967295 uid=20158 gid=20158
euid=20158 suid=20158 fsuid=20158 egid=20158 sgid=20158 fsgid=20158 tty=(none)
ses=4294967295 comm="iioservice" exe="/usr/sbin/iioservice" subj=u:r:cros_iioservice:s0
key=(null)
2024-04-26T14:26:18.374968Z INFO mojo_service_manager[707]: Disconnected from
u:r:cros_powerd:s0
2024-04-26T14:26:18.375541Z INFO iioservice[712]: INFO iioservice:
[sensor_service_impl.cc(417)] (2) OnSensorServiceDisconnect(): SensorDevice disconnected.
ReceiverId: 0
2024-04-26T14:26:18.385703Z INFO bluetoothd[748]: Terminating
2024-04-26T14:26:18.391347Z INFO chapsd[793]: Closing database for
/var/lib/chaps/database
```

```
2024-04-26T14:26:18.399405Z INFO chapsd[793]: leveledb /var/lib/chaps/database dump:#012
/var/lib/chaps/database/LOG (184 bytes, 2024-04-26 13:59:02.000 UTC)#012
/var/lib/chaps/database/CURRENT (16 bytes, 2024-04-26 13:59:02.000 UTC)#012
/var/lib/chaps/database/LOG.old (184 bytes, 2024-04-24 14:50:25.000 UTC)#012
/var/lib/chaps/database/000005.ldb (393 bytes, 2024-03-26 12:57:11.000 UTC)#012
/var/lib/chaps/database/LOCK (0 bytes, 2024-03-26 12:25:52.000 UTC)#012
/var/lib/chaps/database/MANIFEST-000035 (92 bytes, 2024-04-26 13:59:02.000 UTC)#012
/var/lib/chaps/database/000036.log (0 bytes, 2024-04-26 13:59:02.000 UTC)
2024-04-26T14:26:18.433692Z INFO iioservice[712]: INFO iioservice: [main.cc(22)] (2)
main(): Daemon stopped
2024-04-26T14:26:18.437377Z ERR cros_healthd[1328]: Service IioSensordisconnectemessaged
with error kUnknown, message: iioservice is shutting down.
2024-04-26T14:26:18.445883Z INFO avahi-daemon[1362]: Got SIGTERM, quitting.
2024-04-26T14:26:18.458778Z INFO avahi-daemon[1362]: Leaving mDNS multicast group on
interface lo.IPv4 with address 127.0.0.1.
2024-04-26T14:26:18.545375Z WARNING kernel: [ 1649.676372] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:26:18.545461Z WARNING kernel: [ 1649.678501] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:26:18.545488Z WARNING kernel: [ 1649.682963] audit: audit_lost=20
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:26:18.545510Z ERR kernel: [ 1649.688744] audit: backlog limit exceeded
2024-04-26T14:26:18.552143Z WARNING kernel: [ 1649.691740] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:26:18.552278Z WARNING kernel: [ 1649.694483] audit: audit_lost=21
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:26:18.561675Z NOTICE kernel: [ 1649.703497] audit: type=1400
audit(1714141578.372:30259): avc: denied { getpgid } for pid=1 comm="init"
scontext=u:r:cros_init:s0 tcontext=u:r:cros_bluetoothd_minijail0:s0 tclass=process
permissive=1
2024-04-26T14:26:18.561737Z WARNING kernel: [ 1649.705093] audit: audit_lost=22
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:30:57.915248Z NOTICE kernel: [ 0.000000] Linux version 5.15.108-18907-
gba143be42d3a-dirty (builty@fydebeast) (Chromium OS 16.0_pre484197_p20230405-r7 clang
version 16.0.0 (/var/tmp/portage/sys-devel/llvm-16.0_pre484197_p20230405-r7/work/llvm-
16.0_pre484197_p20230405/clang 2916b99182752b1aece8cc4479d8d6a20b5e02da), LLD 16.0.0) #1
SMP PREEMPT Mon Jul 31 23:34:32 CST 2023
2024-04-26T14:30:57.916088Z INFO kernel: [ 0.000000] Command line:
BOOT_IMAGE=/syslinux/vmlinuz.A init=/sbin/init boot=local rootwait ro noresume noswap
loglevel=7 noinitrd earlyprintk=ttyS0,115200 console=ttyS0,115200 i915.modeset=1 cros_efi
cros_debug root=PARTUUID=5C728CA9-A521-2846-A29C-35E25A13FB4C
2024-04-26T14:30:57.916095Z INFO kernel: [ 0.000000] KERNEL supported cpus:
2024-04-26T14:30:57.916098Z INFO kernel: [ 0.000000] Intel GenuineIntel
2024-04-26T14:30:57.916100Z INFO kernel: [ 0.000000] Disabled fast string operations
2024-04-26T14:30:57.916103Z INFO kernel: [ 0.000000] x86/fpu: Supporting XSAVE feature
0x001: 'x87 floating point registers'
2024-04-26T14:30:57.916170Z INFO kernel: [ 0.000000] x86/fpu: Supporting XSAVE feature
0x002: 'SSE registers'
2024-04-26T14:30:57.916177Z INFO kernel: [ 0.000000] x86/fpu: Supporting XSAVE feature
0x004: 'AVX registers'
2024-04-26T14:30:57.916180Z INFO kernel: [ 0.000000] x86/fpu: xstate_offset[2]: 576,
xstate_sizes[2]: 256
2024-04-26T14:30:57.916183Z INFO kernel: [ 0.000000] x86/fpu: Enabled xstate features
0x7, context size is 832 bytes, using 'compact' format.
2024-04-26T14:30:57.916185Z INFO kernel: [ 0.000000] signal: max sigframe size: 1776
2024-04-26T14:30:57.916188Z INFO kernel: [ 0.000000] BIOS-provided physical RAM map:
2024-04-26T14:30:57.916269Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000000000-0x0000000000000fff] ACPI NVS
2024-04-26T14:30:57.916277Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000001000-0x0000000000001fff] reserved
2024-04-26T14:30:57.916280Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000002000-0x0000000000009ffff] usable
2024-04-26T14:30:57.916282Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x000000000000c000-0x000000000000ffff] reserved
2024-04-26T14:30:57.916285Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000010000-0x00000000000e56fff] usable
2024-04-26T14:30:57.916288Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x00000000000e57000-0x00000000000e603fff] ACPI data
2024-04-26T14:30:57.916291Z INFO kernel: [ 0.000000] BIOS-e820: [mem
```

```
0x000000000e604000-0x000000000ef99fff] usable
2024-04-26T14:30:57.916332Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x000000000ef9a000-0x000000000ef9dfff] type 20
2024-04-26T14:30:57.916338Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x000000000ef9e000-0x000000000efacfff] usable
2024-04-26T14:30:57.916341Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x000000000efad000-0x000000000efb1fff] type 20
2024-04-26T14:30:57.916344Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x000000000efb2000-0x000000000efb6fff] ACPI NVS
2024-04-26T14:30:57.916347Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x000000000efb7000-0x000000000fee4fff] usable
2024-04-26T14:30:57.916349Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x000000000fee5000-0x000000000ff04fff] type 20
2024-04-26T14:30:57.916393Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x000000000ff05000-0x000000000ff54fff] reserved
2024-04-26T14:30:57.916403Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x000000000ff55000-0x000000000ff73fff] usable
2024-04-26T14:30:57.916407Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x000000000ff74000-0x000000000ff74fff] ACPI NVS
2024-04-26T14:30:57.916410Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x000000000ff75000-0x00000000bfffffff] usable
2024-04-26T14:30:57.916412Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x000000000ffc00000-0x00000000ffc29fff] reserved
2024-04-26T14:30:57.916414Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x00000000100000000-0x000000001c9bffffff] usable
2024-04-26T14:30:57.916417Z INFO kernel: [ 0.000000] printk: bootconsole [earlyser0]
enabled
2024-04-26T14:30:57.916460Z INFO kernel: [ 0.000000] NX (Execute Disable) protection:
active
2024-04-26T14:30:57.916466Z INFO kernel: [ 0.000000] efi: EFI v2.40 by VMware, Inc.
2024-04-26T14:30:57.916469Z INFO kernel: [ 0.000000] efi: SMBIOS=0xefb2000 ACPI
2.0=0xe5e7000 MEMATTR=0xe623198
2024-04-26T14:30:57.916472Z INFO kernel: [ 0.000000] SMBIOS 2.7 present.
2024-04-26T14:30:57.916474Z INFO kernel: [ 0.000000] DMI: VMware, Inc. VMware7,1/440BX
Desktop Reference Platform, BIOS VMW71.00V.21805430.B64.2305221826 05/22/2023
2024-04-26T14:30:57.916477Z INFO kernel: [ 0.000000] vmware: hypercall mode: 0x00
2024-04-26T14:30:57.916533Z INFO kernel: [ 0.000000] Hypervisor detected: VMware
2024-04-26T14:30:57.916540Z INFO kernel: [ 0.000000] vmware: TSC freq read from
hypervisor : 1607.999 MHz
2024-04-26T14:30:57.916543Z INFO kernel: [ 0.000000] vmware: Host bus clock speed read
from hypervisor : 66000000 Hz
2024-04-26T14:30:57.916546Z INFO kernel: [ 0.000000] vmware: using clock offset of
8199105299 ns
2024-04-26T14:30:57.916548Z INFO kernel: [ 0.001087] tsc: Detected 1607.999 MHz
processor
2024-04-26T14:30:57.916551Z DEBUG kernel: [ 1.080813] e820: update [mem 0x00000000-
0x000000fff] usable ==> reserved
2024-04-26T14:30:57.916596Z DEBUG kernel: [ 1.080824] e820: remove [mem 0x000a0000-
0x000ffffff] usable
2024-04-26T14:30:57.916602Z INFO kernel: [ 1.080838] last_pfn = 0x1c9c00 max_arch_pfn
= 0x400000000
2024-04-26T14:30:57.916605Z INFO kernel: [ 1.082571] x86/PAT: Configuration [0-7]: WB
WC UC- UC WB WP UC- WT
2024-04-26T14:30:57.916608Z DEBUG kernel: [ 1.084642] e820: update [mem 0xc0000000-
0xffffffff] usable ==> reserved
2024-04-26T14:30:57.916611Z INFO kernel: [ 1.085551] last_pfn = 0xc0000 max_arch_pfn =
0x400000000
2024-04-26T14:30:57.916614Z INFO kernel: [ 1.128798] Using GB pages for direct mapping
2024-04-26T14:30:57.916616Z INFO kernel: [ 1.131230] Secure boot disabled
2024-04-26T14:30:57.916663Z INFO kernel: [ 1.132104] ACPI: Early table checksum
verification disabled
2024-04-26T14:30:57.916669Z INFO kernel: [ 1.133846] ACPI: RSDP 0x000000000E5E7000
000024 (v02 VMWARE)
2024-04-26T14:30:57.916672Z INFO kernel: [ 1.135723] ACPI: XSDT 0x000000000E5E7064
00005C (v01 INTEL 440BX 06040000 VMW 01324272)
2024-04-26T14:30:57.916675Z INFO kernel: [ 1.138417] ACPI: SRAT 0x000000000E5E70C0
00008D0 (v03 VMWARE EFISRAT 06040001 VMW 000007CE)
2024-04-26T14:30:57.916678Z INFO kernel: [ 1.140998] ACPI: FACP 0x000000000E602BF8
0000F4 (v04 INTEL 440BX 06040000 PTL 000F4240)
```

```

2024-04-26T14:30:57.916681Z INFO kernel: [ 1.143655] ACPI: DSDT 0x00000000E5E7990
01B268 (v01 PTLTD Custom 00000000 INTL 20130823)
2024-04-26T14:30:57.916723Z INFO kernel: [ 1.146200] ACPI: FACS 0x00000000FF74000
000040
2024-04-26T14:30:57.916730Z INFO kernel: [ 1.147613] ACPI: FACS 0x00000000FF74000
000040
2024-04-26T14:30:57.916733Z INFO kernel: [ 1.149710] ACPI: APIC 0x00000000E603000
000742 (v03 VMWARE EFIAPIC 06040001 VMW 000007CE)
2024-04-26T14:30:57.916735Z INFO kernel: [ 1.152364] ACPI: MCFG 0x00000000E603742
00003C (v01 VMWARE EFIMCFG 06040001 VMW 000007CE)
2024-04-26T14:30:57.916738Z INFO kernel: [ 1.154661] ACPI: HPET 0x00000000E60377E
000038 (v01 VMWARE VMW HPET 00000000 VMW 00000000)
2024-04-26T14:30:57.916741Z INFO kernel: [ 1.157037] ACPI: WAET 0x00000000E6037B6
000028 (v01 VMWARE VMW WAET 06040001 VMW 00000001)
2024-04-26T14:30:57.916813Z INFO kernel: [ 1.159438] ACPI: WSMT 0x00000000E6037DE
000028 (v01 VMWARE VMW WSMT 06040001 VMW 00000001)
2024-04-26T14:30:57.916821Z INFO kernel: [ 1.162244] ACPI: Reserving SRAT table memory
at [mem 0xe5e70c0-0xe5e798f]
2024-04-26T14:30:57.916824Z INFO kernel: [ 1.164319] ACPI: Reserving FACP table memory
at [mem 0xe602bf8-0xe602ceb]
2024-04-26T14:30:57.916826Z INFO kernel: [ 1.166190] ACPI: Reserving DSDT table memory
at [mem 0xe5e7990-0xe602bf7]
2024-04-26T14:30:57.916829Z INFO kernel: [ 1.168112] ACPI: Reserving FACS table memory
at [mem 0xff74000-0xff7403f]
2024-04-26T14:30:57.916832Z INFO kernel: [ 1.170220] ACPI: Reserving FACS table memory
at [mem 0xff74000-0xff7403f]
2024-04-26T14:30:57.916835Z INFO kernel: [ 1.172201] ACPI: Reserving APIC table memory
at [mem 0xe603000-0xe603741]
2024-04-26T14:30:57.916875Z INFO kernel: [ 1.174219] ACPI: Reserving MCFG table memory
at [mem 0xe603742-0xe60377d]
2024-04-26T14:30:57.916882Z INFO kernel: [ 1.176621] ACPI: Reserving HPET table memory
at [mem 0xe60377e-0xe6037b5]
2024-04-26T14:30:57.916885Z INFO kernel: [ 1.178646] ACPI: Reserving WAET table memory
at [mem 0xe6037b6-0xe6037dd]
2024-04-26T14:30:57.916888Z INFO kernel: [ 1.181109] ACPI: Reserving WSMT table memory
at [mem 0xe6037de-0xe603805]
2024-04-26T14:30:57.916890Z DEBUG kernel: [ 1.183837] system APIC only can use
physical flat
2024-04-26T14:30:57.916893Z INFO kernel: [ 1.183840] Setting APIC routing to physical
flat.
2024-04-26T14:30:57.916935Z INFO kernel: [ 1.185854] Zone ranges:
2024-04-26T14:30:57.916941Z INFO kernel: [ 1.186939] DMA [mem
0x0000000000002000-0x000000000ffff]
2024-04-26T14:30:57.916944Z INFO kernel: [ 1.188923] DMA32 [mem
0x0000000010000000-0x00000000ffff]
2024-04-26T14:30:57.916947Z INFO kernel: [ 1.190595] Normal [mem
0x0000000010000000-0x00000001c9bffff]
2024-04-26T14:30:57.916950Z INFO kernel: [ 1.192322] Movable zone start for each node
2024-04-26T14:30:57.916953Z INFO kernel: [ 1.193597] Early memory node ranges
2024-04-26T14:30:57.916955Z INFO kernel: [ 1.194705] node 0: [mem
0x0000000000002000-0x00000000009ffff]
2024-04-26T14:30:57.916994Z INFO kernel: [ 1.196553] node 0: [mem
0x0000000000100000-0x00000000e5e6fff]
2024-04-26T14:30:57.917001Z INFO kernel: [ 1.198192] node 0: [mem
0x000000000e604000-0x00000000ef99fff]
2024-04-26T14:30:57.917027Z INFO kernel: [ 1.200416] node 0: [mem
0x00000000ef9e000-0x00000000efacfff]
2024-04-26T14:30:57.917032Z INFO kernel: [ 1.202157] node 0: [mem
0x00000000efb7000-0x00000000fee4fff]
2024-04-26T14:30:57.917035Z INFO kernel: [ 1.203852] node 0: [mem
0x00000000ff55000-0x00000000ff73fff]
2024-04-26T14:30:57.917038Z INFO kernel: [ 1.205571] node 0: [mem
0x00000000ff75000-0x00000000bffff]
2024-04-26T14:30:57.917083Z INFO kernel: [ 1.207251] node 0: [mem
0x0000000010000000-0x00000001c9bffff]
2024-04-26T14:30:57.917090Z INFO kernel: [ 1.209169] Initmem setup node 0 [mem
0x0000000000002000-0x00000001c9bffff]
2024-04-26T14:30:57.917093Z INFO kernel: [ 1.211374] On node 0, zone DMA: 2 pages in
unavailable ranges

```

```
2024-04-26T14:30:57.917096Z INFO kernel: [ 1.212962] On node 0, zone DMA: 96 pages in
unavailable ranges
2024-04-26T14:30:57.917098Z INFO kernel: [ 1.236658] On node 0, zone DMA32: 29 pages
in unavailable ranges
2024-04-26T14:30:57.917101Z INFO kernel: [ 1.238337] On node 0, zone DMA32: 4 pages in
unavailable ranges
2024-04-26T14:30:57.917147Z INFO kernel: [ 1.242505] On node 0, zone DMA32: 10 pages
in unavailable ranges
2024-04-26T14:30:57.917154Z INFO kernel: [ 1.244213] On node 0, zone DMA32: 112 pages
in unavailable ranges
2024-04-26T14:30:57.917157Z INFO kernel: [ 1.528963] On node 0, zone DMA32: 1 pages in
unavailable ranges
2024-04-26T14:30:57.917160Z INFO kernel: [ 1.918854] On node 0, zone Normal: 25600
pages in unavailable ranges
2024-04-26T14:30:57.917162Z INFO kernel: [ 1.953625] ACPI: PM-Timer IO Port: 0x448
2024-04-26T14:30:57.917165Z DEBUG kernel: [ 1.957815] system APIC only can use
physical flat
2024-04-26T14:30:57.917168Z INFO kernel: [ 1.957838] ACPI: LAPIC_NMI (acpi_id[0x00]
high edge lint[0x1])
2024-04-26T14:30:57.917208Z INFO kernel: [ 1.959581] ACPI: LAPIC_NMI (acpi_id[0x01]
high edge lint[0x1])
2024-04-26T14:30:57.917215Z INFO kernel: [ 1.961170] ACPI: LAPIC_NMI (acpi_id[0x02]
high edge lint[0x1])
2024-04-26T14:30:57.943630Z INFO kernel: [ 1.962843] ACPI: LAPIC_NMI (acpi_id[0x03]
high edge lint[0x1])
2024-04-26T14:30:57.943643Z INFO kernel: [ 1.964948] ACPI: LAPIC_NMI (acpi_id[0x04]
high edge lint[0x1])
2024-04-26T14:30:57.943646Z INFO kernel: [ 1.966740] ACPI: LAPIC_NMI (acpi_id[0x05]
high edge lint[0x1])
2024-04-26T14:30:57.943647Z INFO kernel: [ 1.969497] ACPI: LAPIC_NMI (acpi_id[0x06]
high edge lint[0x1])
2024-04-26T14:30:57.943689Z INFO kernel: [ 1.971400] ACPI: LAPIC_NMI (acpi_id[0x07]
high edge lint[0x1])
2024-04-26T14:30:57.943695Z INFO kernel: [ 1.972979] ACPI: LAPIC_NMI (acpi_id[0x08]
high edge lint[0x1])
2024-04-26T14:30:57.943697Z INFO kernel: [ 1.974583] ACPI: LAPIC_NMI (acpi_id[0x09]
high edge lint[0x1])
2024-04-26T14:30:57.943699Z INFO kernel: [ 1.976148] ACPI: LAPIC_NMI (acpi_id[0x0a]
high edge lint[0x1])
2024-04-26T14:30:57.943701Z INFO kernel: [ 1.977775] ACPI: LAPIC_NMI (acpi_id[0x0b]
high edge lint[0x1])
2024-04-26T14:30:57.943703Z INFO kernel: [ 1.979367] ACPI: LAPIC_NMI (acpi_id[0x0c]
high edge lint[0x1])
2024-04-26T14:30:57.943704Z INFO kernel: [ 1.980940] ACPI: LAPIC_NMI (acpi_id[0x0d]
high edge lint[0x1])
2024-04-26T14:30:57.943709Z INFO kernel: [ 1.983399] ACPI: LAPIC_NMI (acpi_id[0x0e]
high edge lint[0x1])
2024-04-26T14:30:57.943711Z INFO kernel: [ 1.985440] ACPI: LAPIC_NMI (acpi_id[0x0f]
high edge lint[0x1])
2024-04-26T14:30:57.943712Z INFO kernel: [ 1.987038] ACPI: LAPIC_NMI (acpi_id[0x10]
high edge lint[0x1])
2024-04-26T14:30:57.943714Z INFO kernel: [ 1.988607] ACPI: LAPIC_NMI (acpi_id[0x11]
high edge lint[0x1])
2024-04-26T14:30:57.943716Z INFO kernel: [ 1.990239] ACPI: LAPIC_NMI (acpi_id[0x12]
high edge lint[0x1])
2024-04-26T14:30:57.943718Z INFO kernel: [ 1.991877] ACPI: LAPIC_NMI (acpi_id[0x13]
high edge lint[0x1])
2024-04-26T14:30:57.943722Z INFO kernel: [ 1.993490] ACPI: LAPIC_NMI (acpi_id[0x14]
high edge lint[0x1])
2024-04-26T14:30:57.943724Z INFO kernel: [ 1.995015] ACPI: LAPIC_NMI (acpi_id[0x15]
high edge lint[0x1])
2024-04-26T14:30:57.943725Z INFO kernel: [ 1.996597] ACPI: LAPIC_NMI (acpi_id[0x16]
high edge lint[0x1])
2024-04-26T14:30:57.943727Z INFO kernel: [ 2.001688] ACPI: LAPIC_NMI (acpi_id[0x17]
high edge lint[0x1])
2024-04-26T14:30:57.943729Z INFO kernel: [ 2.003884] ACPI: LAPIC_NMI (acpi_id[0x18]
high edge lint[0x1])
2024-04-26T14:30:57.943731Z INFO kernel: [ 2.005926] ACPI: LAPIC_NMI (acpi_id[0x19]
high edge lint[0x1])
```

```
2024-04-26T14:30:57.943735Z INFO kernel: [ 2.007920] ACPI: LAPIC_NMI (acpi_id[0x1a]
high edge lint[0x1])
2024-04-26T14:30:57.943740Z INFO kernel: [ 2.009880] ACPI: LAPIC_NMI (acpi_id[0x1b]
high edge lint[0x1])
2024-04-26T14:30:57.943742Z INFO kernel: [ 2.011772] ACPI: LAPIC_NMI (acpi_id[0x1c]
high edge lint[0x1])
2024-04-26T14:30:57.943744Z INFO kernel: [ 2.013793] ACPI: LAPIC_NMI (acpi_id[0x1d]
high edge lint[0x1])
2024-04-26T14:30:57.943746Z INFO kernel: [ 2.016783] ACPI: LAPIC_NMI (acpi_id[0x1e]
high edge lint[0x1])
2024-04-26T14:30:57.943747Z INFO kernel: [ 2.018437] ACPI: LAPIC_NMI (acpi_id[0x1f]
high edge lint[0x1])
2024-04-26T14:30:57.943749Z INFO kernel: [ 2.020069] ACPI: LAPIC_NMI (acpi_id[0x20]
high edge lint[0x1])
2024-04-26T14:30:57.943753Z INFO kernel: [ 2.021697] ACPI: LAPIC_NMI (acpi_id[0x21]
high edge lint[0x1])
2024-04-26T14:30:57.943755Z INFO kernel: [ 2.023319] ACPI: LAPIC_NMI (acpi_id[0x22]
high edge lint[0x1])
2024-04-26T14:30:57.943757Z INFO kernel: [ 2.024962] ACPI: LAPIC_NMI (acpi_id[0x23]
high edge lint[0x1])
2024-04-26T14:30:57.943759Z INFO kernel: [ 2.026567] ACPI: LAPIC_NMI (acpi_id[0x24]
high edge lint[0x1])
2024-04-26T14:30:57.943762Z INFO kernel: [ 2.028184] ACPI: LAPIC_NMI (acpi_id[0x25]
high edge lint[0x1])
2024-04-26T14:30:57.943764Z INFO kernel: [ 2.029895] ACPI: LAPIC_NMI (acpi_id[0x26]
high edge lint[0x1])
2024-04-26T14:30:57.943769Z INFO kernel: [ 2.031882] ACPI: LAPIC_NMI (acpi_id[0x27]
high edge lint[0x1])
2024-04-26T14:30:57.943771Z INFO kernel: [ 2.034674] ACPI: LAPIC_NMI (acpi_id[0x28]
high edge lint[0x1])
2024-04-26T14:30:57.943772Z INFO kernel: [ 2.036583] ACPI: LAPIC_NMI (acpi_id[0x29]
high edge lint[0x1])
2024-04-26T14:30:57.943774Z INFO kernel: [ 2.038173] ACPI: LAPIC_NMI (acpi_id[0x2a]
high edge lint[0x1])
2024-04-26T14:30:57.943776Z INFO kernel: [ 2.039805] ACPI: LAPIC_NMI (acpi_id[0x2b]
high edge lint[0x1])
2024-04-26T14:30:57.943778Z INFO kernel: [ 2.041451] ACPI: LAPIC_NMI (acpi_id[0x2c]
high edge lint[0x1])
2024-04-26T14:30:57.943779Z INFO kernel: [ 2.043077] ACPI: LAPIC_NMI (acpi_id[0x2d]
high edge lint[0x1])
2024-04-26T14:30:57.943783Z INFO kernel: [ 2.044787] ACPI: LAPIC_NMI (acpi_id[0x2e]
high edge lint[0x1])
2024-04-26T14:30:57.943785Z INFO kernel: [ 2.046395] ACPI: LAPIC_NMI (acpi_id[0x2f]
high edge lint[0x1])
2024-04-26T14:30:57.943787Z INFO kernel: [ 2.048166] ACPI: LAPIC_NMI (acpi_id[0x30]
high edge lint[0x1])
2024-04-26T14:30:57.943789Z INFO kernel: [ 2.049916] ACPI: LAPIC_NMI (acpi_id[0x31]
high edge lint[0x1])
2024-04-26T14:30:57.943791Z INFO kernel: [ 2.051766] ACPI: LAPIC_NMI (acpi_id[0x32]
high edge lint[0x1])
2024-04-26T14:30:57.943793Z INFO kernel: [ 2.053377] ACPI: LAPIC_NMI (acpi_id[0x33]
high edge lint[0x1])
2024-04-26T14:30:57.943797Z INFO kernel: [ 2.055012] ACPI: LAPIC_NMI (acpi_id[0x34]
high edge lint[0x1])
2024-04-26T14:30:57.943802Z INFO kernel: [ 2.056658] ACPI: LAPIC_NMI (acpi_id[0x35]
high edge lint[0x1])
2024-04-26T14:30:57.943804Z INFO kernel: [ 2.058309] ACPI: LAPIC_NMI (acpi_id[0x36]
high edge lint[0x1])
2024-04-26T14:30:57.943807Z INFO kernel: [ 2.059912] ACPI: LAPIC_NMI (acpi_id[0x37]
high edge lint[0x1])
2024-04-26T14:30:57.943809Z INFO kernel: [ 2.061648] ACPI: LAPIC_NMI (acpi_id[0x38]
high edge lint[0x1])
2024-04-26T14:30:57.943812Z INFO kernel: [ 2.063323] ACPI: LAPIC_NMI (acpi_id[0x39]
high edge lint[0x1])
2024-04-26T14:30:57.943817Z INFO kernel: [ 2.065415] ACPI: LAPIC_NMI (acpi_id[0x3a]
high edge lint[0x1])
2024-04-26T14:30:57.943820Z INFO kernel: [ 2.067773] ACPI: LAPIC_NMI (acpi_id[0x3b]
high edge lint[0x1])
2024-04-26T14:30:57.943822Z INFO kernel: [ 2.069617] ACPI: LAPIC_NMI (acpi_id[0x3c]
```



```
high edge lint[0x1])
2024-04-26T14:30:57.943825Z INFO kernel: [ 2.071282] ACPI: LAPIC_NMI (acpi_id[0x3d]
high edge lint[0x1])
2024-04-26T14:30:57.943827Z INFO kernel: [ 2.072892] ACPI: LAPIC_NMI (acpi_id[0x3e]
high edge lint[0x1])
2024-04-26T14:30:57.943829Z INFO kernel: [ 2.074551] ACPI: LAPIC_NMI (acpi_id[0x3f]
high edge lint[0x1])
2024-04-26T14:30:57.943831Z INFO kernel: [ 2.076252] ACPI: LAPIC_NMI (acpi_id[0x40]
high edge lint[0x1])
2024-04-26T14:30:57.943955Z INFO kernel: [ 2.077916] ACPI: LAPIC_NMI (acpi_id[0x41]
high edge lint[0x1])
2024-04-26T14:30:57.943959Z INFO kernel: [ 2.079524] ACPI: LAPIC_NMI (acpi_id[0x42]
high edge lint[0x1])
2024-04-26T14:30:57.943962Z INFO kernel: [ 2.081569] ACPI: LAPIC_NMI (acpi_id[0x43]
high edge lint[0x1])
2024-04-26T14:30:57.943964Z INFO kernel: [ 2.083664] ACPI: LAPIC_NMI (acpi_id[0x44]
high edge lint[0x1])
2024-04-26T14:30:57.943966Z INFO kernel: [ 2.085382] ACPI: LAPIC_NMI (acpi_id[0x45]
high edge lint[0x1])
2024-04-26T14:30:57.943969Z INFO kernel: [ 2.087113] ACPI: LAPIC_NMI (acpi_id[0x46]
high edge lint[0x1])
2024-04-26T14:30:57.943973Z INFO kernel: [ 2.088833] ACPI: LAPIC_NMI (acpi_id[0x47]
high edge lint[0x1])
2024-04-26T14:30:57.943976Z INFO kernel: [ 2.090521] ACPI: LAPIC_NMI (acpi_id[0x48]
high edge lint[0x1])
2024-04-26T14:30:57.943979Z INFO kernel: [ 2.092207] ACPI: LAPIC_NMI (acpi_id[0x49]
high edge lint[0x1])
2024-04-26T14:30:57.943981Z INFO kernel: [ 2.093902] ACPI: LAPIC_NMI (acpi_id[0x4a]
high edge lint[0x1])
2024-04-26T14:30:57.943984Z INFO kernel: [ 2.095623] ACPI: LAPIC_NMI (acpi_id[0x4b]
high edge lint[0x1])
2024-04-26T14:30:57.943986Z INFO kernel: [ 2.097318] ACPI: LAPIC_NMI (acpi_id[0x4c]
high edge lint[0x1])
2024-04-26T14:30:57.943989Z INFO kernel: [ 2.099667] ACPI: LAPIC_NMI (acpi_id[0x4d]
high edge lint[0x1])
2024-04-26T14:30:57.943994Z INFO kernel: [ 2.101515] ACPI: LAPIC_NMI (acpi_id[0x4e]
high edge lint[0x1])
2024-04-26T14:30:57.943997Z INFO kernel: [ 2.103335] ACPI: LAPIC_NMI (acpi_id[0x4f]
high edge lint[0x1])
2024-04-26T14:30:57.944000Z INFO kernel: [ 2.104877] ACPI: LAPIC_NMI (acpi_id[0x50]
high edge lint[0x1])
2024-04-26T14:30:57.944002Z INFO kernel: [ 2.106633] ACPI: LAPIC_NMI (acpi_id[0x51]
high edge lint[0x1])
2024-04-26T14:30:57.944032Z INFO kernel: [ 2.108192] ACPI: LAPIC_NMI (acpi_id[0x52]
high edge lint[0x1])
2024-04-26T14:30:57.944035Z INFO kernel: [ 2.109700] ACPI: LAPIC_NMI (acpi_id[0x53]
high edge lint[0x1])
2024-04-26T14:30:57.944042Z INFO kernel: [ 2.111306] ACPI: LAPIC_NMI (acpi_id[0x54]
high edge lint[0x1])
2024-04-26T14:30:57.944044Z INFO kernel: [ 2.112959] ACPI: LAPIC_NMI (acpi_id[0x55]
high edge lint[0x1])
2024-04-26T14:30:57.944047Z INFO kernel: [ 2.115812] ACPI: LAPIC_NMI (acpi_id[0x56]
high edge lint[0x1])
2024-04-26T14:30:57.944050Z INFO kernel: [ 2.118833] ACPI: LAPIC_NMI (acpi_id[0x57]
high edge lint[0x1])
2024-04-26T14:30:57.944052Z INFO kernel: [ 2.120732] ACPI: LAPIC_NMI (acpi_id[0x58]
high edge lint[0x1])
2024-04-26T14:30:57.944055Z INFO kernel: [ 2.122581] ACPI: LAPIC_NMI (acpi_id[0x59]
high edge lint[0x1])
2024-04-26T14:30:57.944060Z INFO kernel: [ 2.125357] ACPI: LAPIC_NMI (acpi_id[0x5a]
high edge lint[0x1])
2024-04-26T14:30:57.944063Z INFO kernel: [ 2.128418] ACPI: LAPIC_NMI (acpi_id[0x5b]
high edge lint[0x1])
2024-04-26T14:30:57.944066Z INFO kernel: [ 2.140081] ACPI: LAPIC_NMI (acpi_id[0x5c]
high edge lint[0x1])
2024-04-26T14:30:57.944069Z INFO kernel: [ 2.143063] ACPI: LAPIC_NMI (acpi_id[0x5d]
high edge lint[0x1])
2024-04-26T14:30:57.944071Z INFO kernel: [ 2.146773] ACPI: LAPIC_NMI (acpi_id[0x5e]
high edge lint[0x1])
```

```
2024-04-26T14:30:57.944085Z INFO kernel: [ 2.157148] ACPI: LAPIC_NMI (acpi_id[0x5f]
high edge lint[0x1])
2024-04-26T14:30:57.944087Z INFO kernel: [ 2.160884] ACPI: LAPIC_NMI (acpi_id[0x60]
high edge lint[0x1])
2024-04-26T14:30:57.944096Z INFO kernel: [ 2.163197] ACPI: LAPIC_NMI (acpi_id[0x61]
high edge lint[0x1])
2024-04-26T14:30:57.944098Z INFO kernel: [ 2.170128] ACPI: LAPIC_NMI (acpi_id[0x62]
high edge lint[0x1])
2024-04-26T14:30:57.944099Z INFO kernel: [ 2.173737] ACPI: LAPIC_NMI (acpi_id[0x63]
high edge lint[0x1])
2024-04-26T14:30:57.944101Z INFO kernel: [ 2.175614] ACPI: LAPIC_NMI (acpi_id[0x64]
high edge lint[0x1])
2024-04-26T14:30:57.944103Z INFO kernel: [ 2.177879] ACPI: LAPIC_NMI (acpi_id[0x65]
high edge lint[0x1])
2024-04-26T14:30:57.944105Z INFO kernel: [ 2.180229] ACPI: LAPIC_NMI (acpi_id[0x66]
high edge lint[0x1])
2024-04-26T14:30:57.944118Z INFO kernel: [ 2.183656] ACPI: LAPIC_NMI (acpi_id[0x67]
high edge lint[0x1])
2024-04-26T14:30:57.944121Z INFO kernel: [ 2.186509] ACPI: LAPIC_NMI (acpi_id[0x68]
high edge lint[0x1])
2024-04-26T14:30:57.944123Z INFO kernel: [ 2.188840] ACPI: LAPIC_NMI (acpi_id[0x69]
high edge lint[0x1])
2024-04-26T14:30:57.944126Z INFO kernel: [ 2.193388] ACPI: LAPIC_NMI (acpi_id[0x6a]
high edge lint[0x1])
2024-04-26T14:30:57.944128Z INFO kernel: [ 2.194991] ACPI: LAPIC_NMI (acpi_id[0x6b]
high edge lint[0x1])
2024-04-26T14:30:57.944131Z INFO kernel: [ 2.196907] ACPI: LAPIC_NMI (acpi_id[0x6c]
high edge lint[0x1])
2024-04-26T14:30:57.944133Z INFO kernel: [ 2.202861] ACPI: LAPIC_NMI (acpi_id[0x6d]
high edge lint[0x1])
2024-04-26T14:30:57.944142Z INFO kernel: [ 2.208662] ACPI: LAPIC_NMI (acpi_id[0x6e]
high edge lint[0x1])
2024-04-26T14:30:57.944145Z INFO kernel: [ 2.226666] ACPI: LAPIC_NMI (acpi_id[0x6f]
high edge lint[0x1])
2024-04-26T14:30:57.944147Z INFO kernel: [ 2.229154] ACPI: LAPIC_NMI (acpi_id[0x70]
high edge lint[0x1])
2024-04-26T14:30:57.944150Z INFO kernel: [ 2.235497] ACPI: LAPIC_NMI (acpi_id[0x71]
high edge lint[0x1])
2024-04-26T14:30:57.944153Z INFO kernel: [ 2.237712] ACPI: LAPIC_NMI (acpi_id[0x72]
high edge lint[0x1])
2024-04-26T14:30:57.944155Z INFO kernel: [ 2.239956] ACPI: LAPIC_NMI (acpi_id[0x73]
high edge lint[0x1])
2024-04-26T14:30:57.944164Z INFO kernel: [ 2.242449] ACPI: LAPIC_NMI (acpi_id[0x74]
high edge lint[0x1])
2024-04-26T14:30:57.944167Z INFO kernel: [ 2.244948] ACPI: LAPIC_NMI (acpi_id[0x75]
high edge lint[0x1])
2024-04-26T14:30:57.944450Z INFO kernel: [ 2.252985] ACPI: LAPIC_NMI (acpi_id[0x76]
high edge lint[0x1])
2024-04-26T14:30:57.944456Z INFO kernel: [ 2.255588] ACPI: LAPIC_NMI (acpi_id[0x77]
high edge lint[0x1])
2024-04-26T14:30:57.944458Z INFO kernel: [ 2.259187] ACPI: LAPIC_NMI (acpi_id[0x78]
high edge lint[0x1])
2024-04-26T14:30:57.944460Z INFO kernel: [ 2.280419] ACPI: LAPIC_NMI (acpi_id[0x79]
high edge lint[0x1])
2024-04-26T14:30:57.944471Z INFO kernel: [ 2.285840] ACPI: LAPIC_NMI (acpi_id[0x7a]
high edge lint[0x1])
2024-04-26T14:30:57.944473Z INFO kernel: [ 2.288534] ACPI: LAPIC_NMI (acpi_id[0x7b]
high edge lint[0x1])
2024-04-26T14:30:57.944475Z INFO kernel: [ 2.290611] ACPI: LAPIC_NMI (acpi_id[0x7c]
high edge lint[0x1])
2024-04-26T14:30:57.944476Z INFO kernel: [ 2.293520] ACPI: LAPIC_NMI (acpi_id[0x7d]
high edge lint[0x1])
2024-04-26T14:30:57.944478Z INFO kernel: [ 2.295353] ACPI: LAPIC_NMI (acpi_id[0x7e]
high edge lint[0x1])
2024-04-26T14:30:57.944481Z INFO kernel: [ 2.298641] ACPI: LAPIC_NMI (acpi_id[0x7f]
high edge lint[0x1])
2024-04-26T14:30:57.944483Z INFO kernel: [ 2.302249] IOAPIC[0]: apic_id 128, version
32, address 0xfec00000, GSI 0-23
2024-04-26T14:30:57.944491Z INFO kernel: [ 2.305407] ACPI: INT_SRC_OVR (bus 0 bus_irq
```

```

0 global_irq 2 high edge)
2024-04-26T14:30:57.944494Z INFO kernel: [ 2.309935] ACPI: Using ACPI (MADT) for SMP
configuration information
2024-04-26T14:30:57.944496Z INFO kernel: [ 2.312654] ACPI: HPET id: 0x8086af01 base:
0xfed00000
2024-04-26T14:30:57.944498Z WARNING kernel: [ 2.316311] smpboot: 128 Processors
exceeds NR_CPUS limit of 8
2024-04-26T14:30:57.944501Z INFO kernel: [ 2.319795] smpboot: Allowing 8 CPUs, 4
hotplug CPUs
2024-04-26T14:30:57.944503Z INFO kernel: [ 2.322771] [mem 0xc0000000-0xffbfffff]
available for PCI devices
2024-04-26T14:30:57.944510Z INFO kernel: [ 2.325149] Booting paravirtualized kernel on
VMware hypervisor
2024-04-26T14:30:57.944512Z INFO kernel: [ 2.328739] clocksource: refined-jiffies:
mask: 0xffffffff max_cycles: 0xffffffff, max_idle_ns: 1910969940391419 ns
2024-04-26T14:30:57.944515Z INFO kernel: [ 2.404440] setup_percpu: NR_CPUS:8
nr_cpumask_bits:8 nr_cpu_ids:8 nr_node_ids:1
2024-04-26T14:30:57.944518Z INFO kernel: [ 2.428737] percpu: Embedded 53 pages/cpu
s179864 r8192 d29032 u262144
2024-04-26T14:30:57.944519Z DEBUG kernel: [ 2.435935] pcpu-alloc: s179864 r8192 d29032
u262144 alloc=1*2097152
2024-04-26T14:30:57.944521Z DEBUG kernel: [ 2.435943] pcpu-alloc: [0] 0 1 2 3 4 5 6 7
2024-04-26T14:30:57.944528Z INFO kernel: [ 2.436039] Built 1 zonelists, mobility
grouping on. Total pages: 1587190
2024-04-26T14:30:57.944530Z NOTICE kernel: [ 2.438084] Kernel command line:
BOOT_IMAGE=/syslinux/vmlinuz.A init=/sbin/init boot=local rootwait ro noresume noswap
loglevel=7 noinitrd earlyprintk=ttyS0,115200 console=ttyS0,115200 i915.modeset=1 cros_efi
cros_debug root=PARTUUID=5C728CA9-A521-2846-A29C-35E25A13FB4C
2024-04-26T14:30:57.944534Z NOTICE kernel: [ 2.446773] Unknown kernel command line
parameters "noresume noswap cros_efi cros_debug BOOT_IMAGE=/syslinux/vmlinuz.A
boot=local", will be passed to user space.
2024-04-26T14:30:57.944535Z INFO kernel: [ 2.574106] Dentry cache hash table entries:
1048576 (order: 11, 8388608 bytes, linear)
2024-04-26T14:30:57.944537Z INFO kernel: [ 2.616351] Inode-cache hash table entries:
524288 (order: 10, 4194304 bytes, linear)
2024-04-26T14:30:57.944538Z INFO kernel: [ 2.618981] mem auto-init: stack:off, heap
alloc:off, heap free:off
2024-04-26T14:30:57.944546Z INFO kernel: [ 3.406629] Memory: 6216784K/6450184K
available (14348K kernel code, 2385K rwdata, 3664K rodata, 1784K init, 1424K bss, 233140K
reserved, 0K cma-reserved)
2024-04-26T14:30:57.944549Z INFO kernel: [ 3.412587] SLUB: HWalign=64, Order=0-3,
MinObjects=0, CPUs=8, Nodes=1
2024-04-26T14:30:57.944551Z INFO kernel: [ 3.430037] Kernel/User page tables
isolation: enabled
2024-04-26T14:30:57.944552Z INFO kernel: [ 3.437566] ftrace: allocating 46981 entries
in 184 pages
2024-04-26T14:30:57.944554Z INFO kernel: [ 3.556780] ftrace: allocated 184 pages with
4 groups
2024-04-26T14:30:57.944556Z INFO kernel: [ 3.562340] rcu: Preemptible hierarchical RCU
implementation.
2024-04-26T14:30:57.944564Z INFO kernel: [ 3.567509] Trampoline variant of
Tasks RCU enabled.
2024-04-26T14:30:57.944567Z INFO kernel: [ 3.569598] Rude variant of Tasks RCU
enabled.
2024-04-26T14:30:57.944568Z INFO kernel: [ 3.571012] Tracing variant of Tasks
RCU enabled.
2024-04-26T14:30:57.944570Z INFO kernel: [ 3.572444] rcu: RCU calculated value of
scheduler-enlistment delay is 100 jiffies.
2024-04-26T14:30:57.944571Z INFO kernel: [ 3.595529] NR_IRQS: 4352, nr_irqs: 488,
preallocated irq: 16
2024-04-26T14:30:57.944574Z INFO kernel: [ 3.626558] ACPI: Core revision 20210730
2024-04-26T14:30:57.944576Z INFO kernel: [ 3.640971] clocksource: hpet: mask:
0xffffffff max_cycles: 0xffffffff, max_idle_ns: 133484882848 ns
2024-04-26T14:30:57.944584Z INFO kernel: [ 3.646025] APIC: Switch to symmetric I/O
mode setup
2024-04-26T14:30:57.944586Z INFO kernel: [ 3.659632] ..TIMER: vector=0x30 apic1=0
pin1=2 apic2=-1 pin2=-1
2024-04-26T14:30:57.944588Z INFO kernel: [ 3.662715] clocksource: tsc-early: mask:
0xffffffffffffffff max_cycles: 0x172da94f0e2, max_idle_ns: 440795278248 ns

```

```

2024-04-26T14:30:57.944590Z INFO kernel: [ 3.669501] Calibrating delay loop (skipped)
preset value.. 3215.99 BogoMIPS (lpj=1607999)
2024-04-26T14:30:57.944592Z INFO kernel: [ 3.670506] pid_max: default: 32768 minimum:
301
2024-04-26T14:30:57.944595Z INFO kernel: [ 3.676578] LSM: Security Framework
initializing
2024-04-26T14:30:57.944603Z INFO kernel: [ 3.677520] Yama: becoming mindful.
2024-04-26T14:30:57.944606Z INFO kernel: [ 3.678563] LoadPin: ready to pin (currently
not enforcing)
2024-04-26T14:30:57.944608Z INFO kernel: [ 3.679500] Chromium OS LSM: enabled
2024-04-26T14:30:57.944611Z INFO kernel: [ 3.679500] overlaysfs: SELinux:
Initializing.
2024-04-26T14:30:57.944612Z INFO kernel: [ 3.684577] Mount-cache hash table entries:
16384 (order: 5, 131072 bytes, linear)
2024-04-26T14:30:57.944614Z INFO kernel: [ 3.689698] Mountpoint-cache hash table
entries: 16384 (order: 5, 131072 bytes, linear)
2024-04-26T14:30:57.944621Z INFO kernel: [ 3.701728] Disabled fast string operations
2024-04-26T14:30:57.944623Z INFO kernel: [ 3.703906] Last level iTLB entries: 4KB 64,
2MB 8, 4MB 8
2024-04-26T14:30:57.944626Z INFO kernel: [ 3.705552] Last level dTLB entries: 4KB 64,
2MB 0, 4MB 0, 1GB 4
2024-04-26T14:30:57.944628Z INFO kernel: [ 3.706518] Spectre V1 : Mitigation:
usercopy/swaps barriers and __user pointer sanitization
2024-04-26T14:30:57.944629Z INFO kernel: [ 3.708560] Spectre V2 : Mitigation: IBRS
2024-04-26T14:30:57.944631Z INFO kernel: [ 3.709548] Spectre V2 : Spectre v2 /
SpectreRSB mitigation: Filling RSB on context switch
2024-04-26T14:30:57.944638Z INFO kernel: [ 3.711545] Spectre V2 : Spectre v2 /
SpectreRSB : Filling RSB on VMEXIT
2024-04-26T14:30:57.944640Z INFO kernel: [ 3.713546] RETbleed: Mitigation: IBRS
2024-04-26T14:30:57.944643Z INFO kernel: [ 3.714550] Spectre V2 : mitigation: Enabling
conditional Indirect Branch Prediction Barrier
2024-04-26T14:30:57.944645Z INFO kernel: [ 3.716528] Speculative Store Bypass:
Mitigation: Speculative Store Bypass disabled via prctl and seccomp
2024-04-26T14:30:57.944646Z INFO kernel: [ 3.717524] MDS: Mitigation: Clear CPU
buffers
2024-04-26T14:30:57.944648Z INFO kernel: [ 3.718605] MMIO Stale Data: Mitigation:
Clear CPU buffers
2024-04-26T14:30:57.944651Z INFO kernel: [ 3.719563] SRBDS: Unknown: Dependent on
hypervisor status
2024-04-26T14:30:57.944659Z INFO kernel: [ 3.783572] Freeing SMP alternatives memory:
40K
2024-04-26T14:30:57.944661Z INFO kernel: [ 3.788813] smpboot: CPU0: Intel(R) Core(TM)
m3-8100Y CPU @ 1.10GHz (family: 0x6, model: 0x8e, stepping: 0x9)
2024-04-26T14:30:57.944663Z INFO kernel: [ 3.792713] Performance Events: Skylake
events, core PMU driver.
2024-04-26T14:30:57.944665Z WARNING kernel: [ 3.794508] core: CPUID marked event: 'cpu
cycles' unavailable
2024-04-26T14:30:57.944667Z WARNING kernel: [ 3.795509] core: CPUID marked event:
'instructions' unavailable
2024-04-26T14:30:57.944669Z WARNING kernel: [ 3.796517] core: CPUID marked event: 'bus
cycles' unavailable
2024-04-26T14:30:57.944679Z WARNING kernel: [ 3.797508] core: CPUID marked event:
'cache references' unavailable
2024-04-26T14:30:57.944682Z WARNING kernel: [ 3.798506] core: CPUID marked event:
'cache misses' unavailable
2024-04-26T14:30:57.944684Z WARNING kernel: [ 3.799507] core: CPUID marked event:
'branch instructions' unavailable
2024-04-26T14:30:57.944686Z WARNING kernel: [ 3.800506] core: CPUID marked event:
'branch misses' unavailable
2024-04-26T14:30:57.944689Z INFO kernel: [ 3.801508] ... version: 1
2024-04-26T14:30:57.944690Z INFO kernel: [ 3.802503] ... bit width: 48
2024-04-26T14:30:57.944697Z INFO kernel: [ 3.803507] ... generic registers: 4
2024-04-26T14:30:57.944700Z INFO kernel: [ 3.804507] ... value mask:
0000ffffffffffff
2024-04-26T14:30:57.944702Z INFO kernel: [ 3.805507] ... max period:
000000007fffffff
2024-04-26T14:30:57.944705Z INFO kernel: [ 3.806508] ... fixed-purpose events: 0
2024-04-26T14:30:57.944706Z INFO kernel: [ 3.807507] ... event mask:
000000000000000f

```

```
2024-04-26T14:30:57.944708Z INFO kernel: [ 3.809942] rcu: Hierarchical SRCU
implementation.
2024-04-26T14:30:57.944710Z INFO kernel: [ 3.812513] NMI watchdog: Perf NMI watchdog
permanently disabled
2024-04-26T14:30:57.944717Z INFO kernel: [ 3.821244] smp: Bringing up secondary CPUs
...
2024-04-26T14:30:57.944720Z INFO kernel: [ 3.822891] x86: Booting SMP configuration:
2024-04-26T14:30:57.944722Z INFO kernel: [ 3.823507] .... node #0, CPUs: #1
2024-04-26T14:30:57.944723Z INFO kernel: [ 0.039212] Disabled fast string operations
2024-04-26T14:30:57.944725Z INFO kernel: [ 0.039212] smpboot: CPU 1 Converting
physical 2 to logical package 1
2024-04-26T14:30:57.944728Z INFO kernel: [ 0.039212] smpboot: CPU 1 Converting
physical 0 to logical die 1
2024-04-26T14:30:57.944736Z WARNING kernel: [ 3.832507] #2
2024-04-26T14:30:57.944738Z INFO kernel: [ 0.039212] Disabled fast string operations
2024-04-26T14:30:57.944740Z INFO kernel: [ 0.039212] smpboot: CPU 2 Converting
physical 4 to logical package 2
2024-04-26T14:30:57.944742Z INFO kernel: [ 0.039212] smpboot: CPU 2 Converting
physical 0 to logical die 2
2024-04-26T14:30:57.944744Z WARNING kernel: [ 3.848162] #3
2024-04-26T14:30:57.944746Z INFO kernel: [ 0.039212] Disabled fast string operations
2024-04-26T14:30:57.944754Z INFO kernel: [ 0.039212] smpboot: CPU 3 Converting
physical 6 to logical package 3
2024-04-26T14:30:57.944756Z INFO kernel: [ 0.039212] smpboot: CPU 3 Converting
physical 0 to logical die 3
2024-04-26T14:30:57.944759Z INFO kernel: [ 3.858519] smp: Brought up 1 node, 4 CPUs
2024-04-26T14:30:57.944761Z INFO kernel: [ 3.862515] smpboot: Max logical packages:
128
2024-04-26T14:30:57.944763Z INFO kernel: [ 3.863505] smpboot: Total of 4 processors
activated (12863.99 BogoMIPS)
2024-04-26T14:30:57.944766Z INFO kernel: [ 3.870511] devtmpfs: initialized
2024-04-26T14:30:57.944767Z INFO kernel: [ 3.874738] ACPI: PM: Registering ACPI NVS
region [mem 0x00000000-0x00000fff] (4096 bytes)
2024-04-26T14:30:57.944774Z INFO kernel: [ 3.876508] ACPI: PM: Registering ACPI NVS
region [mem 0x0efb2000-0x0efb6fff] (20480 bytes)
2024-04-26T14:30:57.944777Z INFO kernel: [ 3.878506] ACPI: PM: Registering ACPI NVS
region [mem 0x0ff74000-0x0ff74fff] (4096 bytes)
2024-04-26T14:30:57.944780Z INFO kernel: [ 3.879906] clocksource: jiffies: mask:
0xffffffff max_cycles: 0xffffffff, max_idle_ns: 1911260446275000 ns
2024-04-26T14:30:57.944782Z INFO kernel: [ 3.880515] futex hash table entries: 2048
(order: 5, 131072 bytes, linear)
2024-04-26T14:30:57.944783Z INFO kernel: [ 3.883425] pinctrl core: initialized pinctrl
subsystem
2024-04-26T14:30:57.945093Z INFO kernel: [ 3.883934] PM: RTC time: 14:30:51, date:
2024-04-26
2024-04-26T14:30:57.945108Z INFO kernel: [ 3.886265] NET: Registered
PF_NETLINK/PF_ROUTE protocol family
2024-04-26T14:30:57.945111Z INFO kernel: [ 3.886942] audit: initializing netlink
subsys (disabled)
2024-04-26T14:30:57.945114Z NOTICE kernel: [ 3.888826] audit: type=2000
audit(1714141850.224:1): state=initialized audit_enabled=0 res=1
2024-04-26T14:30:57.945116Z INFO kernel: [ 3.889122] thermal_sys: Registered thermal
governor 'step_wise'
2024-04-26T14:30:57.945118Z INFO kernel: [ 3.889524] thermal_sys: Registered thermal
governor 'user_space'
2024-04-26T14:30:57.945120Z INFO kernel: [ 3.890541] cpuidle: using governor ladder
2024-04-26T14:30:57.945129Z INFO kernel: [ 3.892522] cpuidle: using governor menu
2024-04-26T14:30:57.945131Z INFO kernel: [ 3.894534] ACPI: bus type PCI registered
2024-04-26T14:30:57.945133Z INFO kernel: [ 3.895506] acpiphp: ACPI Hot Plug PCI
Controller Driver version: 0.5
2024-04-26T14:30:57.945135Z INFO kernel: [ 3.896968] PCI: MMCONFIG for domain 0000
[bus 00-7f] at [mem 0xe0000000-0xe7fffffff] (base 0xe0000000)
2024-04-26T14:30:57.945136Z INFO kernel: [ 3.897511] PCI: not using MMCONFIG
2024-04-26T14:30:57.945138Z INFO kernel: [ 3.898512] PCI: Using configuration type 1
for base access
2024-04-26T14:30:57.945140Z INFO kernel: [ 3.919561] cryptd: max_cpu_qlen set to 1000
2024-04-26T14:30:57.945147Z INFO kernel: [ 3.953549] ACPI: Added _OSI(Module Device)
2024-04-26T14:30:57.945150Z INFO kernel: [ 3.955505] ACPI: Added _OSI(Processor
Device)
```

```

2024-04-26T14:30:57.945152Z INFO kernel: [ 3.956512] ACPI: Added _OSI(3.0 _SCP
Extensions)
2024-04-26T14:30:57.945154Z INFO kernel: [ 3.957524] ACPI: Added _OSI(Processor
Aggregator Device)
2024-04-26T14:30:57.945156Z INFO kernel: [ 3.958512] ACPI: Added _OSI(Linux-Dell-
Video)
2024-04-26T14:30:57.945159Z INFO kernel: [ 3.959507] ACPI: Added _OSI(Linux-Lenovo-NV-
HDMI-Audio)
2024-04-26T14:30:57.945167Z INFO kernel: [ 3.960511] ACPI: Added _OSI(Linux-HPI-
Hybrid-Graphics)
2024-04-26T14:30:57.945169Z INFO kernel: [ 4.009856] ACPI: 1 ACPI AML tables
successfully acquired and loaded
2024-04-26T14:30:57.945171Z NOTICE kernel: [ 4.017847] ACPI: [Firmware Bug]: BIOS
_OSI(Linux) query ignored
2024-04-26T14:30:57.945173Z NOTICE kernel: [ 4.018538] ACPI: BIOS _OSI(Darwin) query
ignored
2024-04-26T14:30:57.945175Z INFO kernel: [ 4.097361] ACPI: Interpreter enabled
2024-04-26T14:30:57.945176Z INFO kernel: [ 4.097565] ACPI: PM: (supports S0 S1 S5)
2024-04-26T14:30:57.945184Z INFO kernel: [ 4.098506] ACPI: Using IOAPIC for interrupt
routing
2024-04-26T14:30:57.945187Z INFO kernel: [ 4.100510] PCI: MMCONFIG for domain 0000
[bus 00-7f] at [mem 0xe0000000-0xe7ffffff] (base 0xe0000000)
2024-04-26T14:30:57.945189Z INFO kernel: [ 4.108118] PCI: MMCONFIG at [mem 0xe0000000-
0xe7ffffff] reserved in ACPI motherboard resources
2024-04-26T14:30:57.945191Z WARNING kernel: [ 4.108524] pmd_set_huge: Cannot satisfy
[mem 0xe0000000-0xe0200000] with a huge-page mapping due to MTRR override.
2024-04-26T14:30:57.945193Z INFO kernel: [ 4.115970] PCI: Using host bridge windows
from ACPI; if necessary, use "pci=nocrs" and report a bug
2024-04-26T14:30:57.945195Z INFO kernel: [ 4.123937] ACPI: Enabled 4 GPEs in block 00
to 0F
2024-04-26T14:30:57.945202Z INFO kernel: [ 4.589414] ACPI: PCI Root Bridge [PCI0]
(domain 0000 [bus 00-7f])
2024-04-26T14:30:57.945203Z INFO kernel: [ 4.589525] acpi PNP0A03:00: _OSC: OS
supports [ExtendedConfig ASPM ClockPM Segments MSI HPX-Type3]
2024-04-26T14:30:57.945205Z INFO kernel: [ 4.591677] acpi PNP0A03:00: _OSC: platform
does not support [AER LTR]
2024-04-26T14:30:57.945206Z INFO kernel: [ 4.594919] acpi PNP0A03:00: _OSC: OS now
controls [PCIeHotplug PME PCIeCapability]
2024-04-26T14:30:57.945208Z INFO kernel: [ 4.597363] PCI host bridge to bus 0000:00
2024-04-26T14:30:57.945209Z INFO kernel: [ 4.598508] pci_bus 0000:00: root bus
resource [io 0x0d00-0xffff window]
2024-04-26T14:30:57.945216Z INFO kernel: [ 4.599512] pci_bus 0000:00: root bus
resource [io 0x0000-0x0cf7 window]
2024-04-26T14:30:57.945217Z INFO kernel: [ 4.600511] pci_bus 0000:00: root bus
resource [mem 0xfef00000-0xffdffffff window]
2024-04-26T14:30:57.945219Z INFO kernel: [ 4.601512] pci_bus 0000:00: root bus
resource [mem 0xfed45000-0xfedffffff window]
2024-04-26T14:30:57.945221Z INFO kernel: [ 4.602511] pci_bus 0000:00: root bus
resource [mem 0xfec10000-0xfed3ffff window]
2024-04-26T14:30:57.945222Z INFO kernel: [ 4.603510] pci_bus 0000:00: root bus
resource [mem 0xfa400000-0xfebffffff window]
2024-04-26T14:30:57.945224Z INFO kernel: [ 4.604508] pci_bus 0000:00: root bus
resource [mem 0xf0000000-0xfa3ffffff pref window]
2024-04-26T14:30:57.945226Z INFO kernel: [ 4.605512] pci_bus 0000:00: root bus
resource [mem 0xc0000000-0xefffffff window]
2024-04-26T14:30:57.945235Z INFO kernel: [ 4.606512] pci_bus 0000:00: root bus
resource [mem 0x000a0000-0x000bffff window]
2024-04-26T14:30:57.945236Z INFO kernel: [ 4.607511] pci_bus 0000:00: root bus
resource [mem 0x000c4000-0x000c7fff window]
2024-04-26T14:30:57.945238Z INFO kernel: [ 4.608511] pci_bus 0000:00: root bus
resource [mem 0x000c8000-0x000cbfff window]
2024-04-26T14:30:57.945241Z INFO kernel: [ 4.609511] pci_bus 0000:00: root bus
resource [mem 0x000d4000-0x000d7fff window]
2024-04-26T14:30:57.945243Z INFO kernel: [ 4.610846] pci_bus 0000:00: root bus
resource [mem 0x000d8000-0x000dbfff window]
2024-04-26T14:30:57.945246Z INFO kernel: [ 4.611507] pci_bus 0000:00: root bus
resource [mem 0x000e4000-0x000e7fff window]
2024-04-26T14:30:57.945252Z INFO kernel: [ 4.612512] pci_bus 0000:00: root bus
resource [mem 0x000e8000-0x000ebfff window]

```

```
2024-04-26T14:30:57.945254Z INFO kernel: [ 4.613508] pci_bus 0000:00: root bus
resource [mem 0x000ec000-0x000effff window]
2024-04-26T14:30:57.945255Z INFO kernel: [ 4.614510] pci_bus 0000:00: root bus
resource [bus 00-7f]
2024-04-26T14:30:57.945258Z INFO kernel: [ 4.616507] pci 0000:00:00.0: [8086:7190]
type 00 class 0x060000
2024-04-26T14:30:57.945260Z INFO kernel: [ 4.621510] pci 0000:00:01.0: [8086:7191]
type 01 class 0x060400
2024-04-26T14:30:57.945262Z INFO kernel: [ 4.625156] pci 0000:00:07.0: [8086:7110]
type 00 class 0x060100
2024-04-26T14:30:57.945264Z INFO kernel: [ 4.628505] pci 0000:00:07.1: [8086:7111]
type 00 class 0x01018a
2024-04-26T14:30:57.945273Z INFO kernel: [ 4.638506] pci 0000:00:07.1: reg 0x20: [io
0x2150-0x215f]
2024-04-26T14:30:57.945276Z INFO kernel: [ 4.642997] pci 0000:00:07.1: legacy IDE
quirk: reg 0x10: [io 0x01f0-0x01f7]
2024-04-26T14:30:57.945278Z INFO kernel: [ 4.643591] pci 0000:00:07.1: legacy IDE
quirk: reg 0x14: [io 0x03f6]
2024-04-26T14:30:57.945280Z INFO kernel: [ 4.644510] pci 0000:00:07.1: legacy IDE
quirk: reg 0x18: [io 0x0170-0x0177]
2024-04-26T14:30:57.945282Z INFO kernel: [ 4.645510] pci 0000:00:07.1: legacy IDE
quirk: reg 0x1c: [io 0x0376]
2024-04-26T14:30:57.945283Z INFO kernel: [ 4.652541] pci 0000:00:07.3: [8086:7113]
type 00 class 0x068000
2024-04-26T14:30:57.945290Z INFO kernel: [ 4.655369] pci 0000:00:07.3: quirk: [io
0x0440-0x047f] claimed by PIIX4 ACPI
2024-04-26T14:30:57.945292Z INFO kernel: [ 4.661230] pci 0000:00:07.7: [15ad:0740]
type 00 class 0x088000
2024-04-26T14:30:57.945293Z INFO kernel: [ 4.662732] pci 0000:00:07.7: reg 0x10: [io
0x2100-0x213f]
2024-04-26T14:30:57.945294Z INFO kernel: [ 4.664660] pci 0000:00:07.7: reg 0x14: [mem
0xffbe0000-0xffbe1fff 64bit]
2024-04-26T14:30:57.945296Z INFO kernel: [ 4.668694] pci 0000:00:0f.0: [15ad:0405]
type 00 class 0x030000
2024-04-26T14:30:57.945297Z INFO kernel: [ 4.671509] pci 0000:00:0f.0: reg 0x10: [io
0x2140-0x214f]
2024-04-26T14:30:57.945304Z INFO kernel: [ 4.674509] pci 0000:00:0f.0: reg 0x14: [mem
0xf0000000-0xf7ffffff pref]
2024-04-26T14:30:57.945305Z INFO kernel: [ 4.677508] pci 0000:00:0f.0: reg 0x18: [mem
0xfb800000-0xfbffffff]
2024-04-26T14:30:57.945308Z INFO kernel: [ 4.690509] pci 0000:00:0f.0: reg 0x30: [mem
0xffff8000-0xffffffff pref]
2024-04-26T14:30:57.945310Z INFO kernel: [ 4.692692] pci 0000:00:0f.0: Video device
with shadowed ROM at [mem 0x000c0000-0x000dffff]
2024-04-26T14:30:57.945312Z INFO kernel: [ 4.695505] pci 0000:00:10.0: [1000:0030]
type 00 class 0x010000
2024-04-26T14:30:57.945314Z INFO kernel: [ 4.699510] pci 0000:00:10.0: reg 0x10: [io
0x2000-0x20ff]
2024-04-26T14:30:57.945315Z INFO kernel: [ 4.702508] pci 0000:00:10.0: reg 0x14: [mem
0xffbc0000-0xffbdffff 64bit]
2024-04-26T14:30:57.945322Z INFO kernel: [ 4.704827] pci 0000:00:10.0: reg 0x1c: [mem
0xffba0000-0xffbbffff 64bit]
2024-04-26T14:30:57.945325Z INFO kernel: [ 4.707238] pci 0000:00:10.0: reg 0x30: [mem
0xffffc000-0xffffffff pref]
2024-04-26T14:30:57.945327Z INFO kernel: [ 4.709754] pci 0000:00:11.0: [15ad:0790]
type 01 class 0x060401
2024-04-26T14:30:57.945328Z INFO kernel: [ 4.714186] pci 0000:00:15.0: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.945330Z INFO kernel: [ 4.717108] pci 0000:00:15.0: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.945331Z INFO kernel: [ 4.719097] pci 0000:00:15.1: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.945338Z INFO kernel: [ 4.722067] pci 0000:00:15.1: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.945341Z INFO kernel: [ 4.724733] pci 0000:00:15.2: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.945342Z INFO kernel: [ 4.728291] pci 0000:00:15.2: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.945345Z INFO kernel: [ 4.730628] pci 0000:00:15.3: [15ad:07a0]
```

```
type 01 class 0x060400
2024-04-26T14:30:57.945346Z INFO kernel: [ 4.734024] pci 0000:00:15.3: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.945349Z INFO kernel: [ 4.737910] pci 0000:00:15.4: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.945351Z INFO kernel: [ 4.742931] pci 0000:00:15.4: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.945359Z INFO kernel: [ 4.745833] pci 0000:00:15.5: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.945362Z INFO kernel: [ 4.752091] pci 0000:00:15.5: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.945364Z INFO kernel: [ 4.755225] pci 0000:00:15.6: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.945366Z INFO kernel: [ 4.758616] pci 0000:00:15.6: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.945368Z INFO kernel: [ 4.761180] pci 0000:00:15.7: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.945370Z INFO kernel: [ 4.766785] pci 0000:00:15.7: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.945378Z INFO kernel: [ 4.769561] pci 0000:00:16.0: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.945380Z INFO kernel: [ 4.772911] pci 0000:00:16.0: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.945382Z INFO kernel: [ 4.775032] pci 0000:00:16.1: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.945385Z INFO kernel: [ 4.778093] pci 0000:00:16.1: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.945387Z INFO kernel: [ 4.780209] pci 0000:00:16.2: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.945389Z INFO kernel: [ 4.783227] pci 0000:00:16.2: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.945397Z INFO kernel: [ 4.785787] pci 0000:00:16.3: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.945398Z INFO kernel: [ 4.789714] pci 0000:00:16.3: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.945401Z INFO kernel: [ 4.793320] pci 0000:00:16.4: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.945403Z INFO kernel: [ 4.798560] pci 0000:00:16.4: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.945405Z INFO kernel: [ 4.801185] pci 0000:00:16.5: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.945407Z INFO kernel: [ 4.804788] pci 0000:00:16.5: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.945409Z INFO kernel: [ 4.807103] pci 0000:00:16.6: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.946471Z INFO kernel: [ 4.810928] pci 0000:00:16.6: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.946488Z INFO kernel: [ 4.814068] pci 0000:00:16.7: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.946491Z INFO kernel: [ 4.817091] pci 0000:00:16.7: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.946493Z INFO kernel: [ 4.819971] pci 0000:00:17.0: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.946495Z INFO kernel: [ 4.823604] pci 0000:00:17.0: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.946497Z INFO kernel: [ 4.826776] pci 0000:00:17.1: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.946549Z INFO kernel: [ 4.832516] pci 0000:00:17.1: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.946554Z INFO kernel: [ 4.837607] pci 0000:00:17.2: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.946556Z INFO kernel: [ 4.844649] pci 0000:00:17.2: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.946557Z INFO kernel: [ 4.849741] pci 0000:00:17.3: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.946559Z INFO kernel: [ 4.856513] pci 0000:00:17.3: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.946560Z INFO kernel: [ 4.859341] pci 0000:00:17.4: [15ad:07a0]
type 01 class 0x060400
```



```
2024-04-26T14:30:57.946562Z INFO kernel: [ 4.863228] pci 0000:00:17.4: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.946625Z INFO kernel: [ 4.865631] pci 0000:00:17.5: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.959082Z INFO kernel: [ 4.868943] pci 0000:00:17.5: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.959099Z INFO kernel: [ 4.871126] pci 0000:00:17.6: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.959101Z INFO kernel: [ 4.875847] pci 0000:00:17.6: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.959103Z INFO kernel: [ 4.878283] pci 0000:00:17.7: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.959105Z INFO kernel: [ 4.881186] pci 0000:00:17.7: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.959106Z INFO kernel: [ 4.883425] pci 0000:00:18.0: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.959108Z INFO kernel: [ 4.886226] pci 0000:00:18.0: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.959114Z INFO kernel: [ 4.887879] pci 0000:00:18.1: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.959116Z INFO kernel: [ 4.890459] pci 0000:00:18.1: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.959117Z INFO kernel: [ 4.894445] pci 0000:00:18.2: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.959119Z INFO kernel: [ 4.897401] pci 0000:00:18.2: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.959121Z INFO kernel: [ 4.901246] pci 0000:00:18.3: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.959122Z INFO kernel: [ 4.905133] pci 0000:00:18.3: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.959123Z INFO kernel: [ 4.907434] pci 0000:00:18.4: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.959125Z INFO kernel: [ 4.910032] pci 0000:00:18.4: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.959127Z INFO kernel: [ 4.912447] pci 0000:00:18.5: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.959128Z INFO kernel: [ 4.917468] pci 0000:00:18.5: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.959130Z INFO kernel: [ 4.921731] pci 0000:00:18.6: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.959131Z INFO kernel: [ 4.928848] pci 0000:00:18.6: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.959133Z INFO kernel: [ 4.933314] pci 0000:00:18.7: [15ad:07a0]
type 01 class 0x060400
2024-04-26T14:30:57.959134Z INFO kernel: [ 4.936701] pci 0000:00:18.7: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.959141Z INFO kernel: [ 4.940252] pci_bus 0000:01: extended config
space not accessible
2024-04-26T14:30:57.959142Z INFO kernel: [ 4.941537] pci 0000:00:01.0: PCI bridge to
[bus 01]
2024-04-26T14:30:57.959144Z INFO kernel: [ 4.943707] pci_bus 0000:02: extended config
space not accessible
2024-04-26T14:30:57.959146Z INFO kernel: [ 4.944592] acpiphp: Slot [32] registered
2024-04-26T14:30:57.959147Z INFO kernel: [ 4.946653] acpiphp: Slot [33] registered
2024-04-26T14:30:57.959149Z INFO kernel: [ 4.947598] acpiphp: Slot [34] registered
2024-04-26T14:30:57.959150Z INFO kernel: [ 4.948570] acpiphp: Slot [35] registered
2024-04-26T14:30:57.959152Z INFO kernel: [ 4.949692] acpiphp: Slot [36] registered
2024-04-26T14:30:57.959154Z INFO kernel: [ 4.950607] acpiphp: Slot [37] registered
2024-04-26T14:30:57.959155Z INFO kernel: [ 4.951868] acpiphp: Slot [38] registered
2024-04-26T14:30:57.959157Z INFO kernel: [ 4.952594] acpiphp: Slot [39] registered
2024-04-26T14:30:57.959159Z INFO kernel: [ 4.953639] acpiphp: Slot [40] registered
2024-04-26T14:30:57.959162Z INFO kernel: [ 4.954572] acpiphp: Slot [41] registered
2024-04-26T14:30:57.959166Z INFO kernel: [ 4.956600] acpiphp: Slot [42] registered
2024-04-26T14:30:57.959168Z INFO kernel: [ 4.957635] acpiphp: Slot [43] registered
2024-04-26T14:30:57.959169Z INFO kernel: [ 4.958584] acpiphp: Slot [44] registered
2024-04-26T14:30:57.959171Z INFO kernel: [ 4.959580] acpiphp: Slot [45] registered
2024-04-26T14:30:57.959173Z INFO kernel: [ 4.960572] acpiphp: Slot [46] registered
2024-04-26T14:30:57.959174Z INFO kernel: [ 4.961638] acpiphp: Slot [47] registered
2024-04-26T14:30:57.959176Z INFO kernel: [ 4.963600] acpiphp: Slot [48] registered
```

```
2024-04-26T14:30:57.959177Z INFO kernel: [ 4.964582] acpihp: Slot [49] registered
2024-04-26T14:30:57.959179Z INFO kernel: [ 4.966509] acpihp: Slot [50] registered
2024-04-26T14:30:57.959181Z INFO kernel: [ 4.967581] acpihp: Slot [51] registered
2024-04-26T14:30:57.959182Z INFO kernel: [ 4.968570] acpihp: Slot [52] registered
2024-04-26T14:30:57.959184Z INFO kernel: [ 4.969662] acpihp: Slot [53] registered
2024-04-26T14:30:57.959190Z INFO kernel: [ 4.970709] acpihp: Slot [54] registered
2024-04-26T14:30:57.959192Z INFO kernel: [ 4.971600] acpihp: Slot [55] registered
2024-04-26T14:30:57.959194Z INFO kernel: [ 4.973548] acpihp: Slot [56] registered
2024-04-26T14:30:57.959195Z INFO kernel: [ 4.974584] acpihp: Slot [57] registered
2024-04-26T14:30:57.959197Z INFO kernel: [ 4.975650] acpihp: Slot [58] registered
2024-04-26T14:30:57.959199Z INFO kernel: [ 4.976576] acpihp: Slot [59] registered
2024-04-26T14:30:57.959200Z INFO kernel: [ 4.977582] acpihp: Slot [60] registered
2024-04-26T14:30:57.959202Z INFO kernel: [ 4.978866] acpihp: Slot [61] registered
2024-04-26T14:30:57.959203Z INFO kernel: [ 4.979579] acpihp: Slot [62] registered
2024-04-26T14:30:57.959205Z INFO kernel: [ 4.980581] acpihp: Slot [63] registered
2024-04-26T14:30:57.959206Z INFO kernel: [ 4.982585] pci 0000:02:00.0: [15ad:0774]
type 00 class 0x0c0300
2024-04-26T14:30:57.959208Z INFO kernel: [ 4.989247] pci 0000:02:00.0: reg 0x20: [io
0x1040-0x105f]
2024-04-26T14:30:57.959210Z INFO kernel: [ 4.994571] pci 0000:02:01.0: [8086:100f]
type 00 class 0x020000
2024-04-26T14:30:57.959221Z INFO kernel: [ 4.997507] pci 0000:02:01.0: reg 0x10: [mem
0xfc000000-0xfc01ffff 64bit]
2024-04-26T14:30:57.959223Z INFO kernel: [ 5.000120] pci 0000:02:01.0: reg 0x18: [mem
0xfc020000-0xfc02ffff 64bit]
2024-04-26T14:30:57.959225Z INFO kernel: [ 5.002353] pci 0000:02:01.0: reg 0x20: [io
0x1000-0x103f]
2024-04-26T14:30:57.959226Z INFO kernel: [ 5.004234] pci 0000:02:01.0: reg 0x30: [mem
0xffff0000-0xffffffff pref]
2024-04-26T14:30:57.959228Z INFO kernel: [ 5.007117] pci 0000:02:01.0: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.959230Z INFO kernel: [ 5.009028] pci 0000:02:02.0: [15ad:1977]
type 00 class 0x040300
2024-04-26T14:30:57.959231Z INFO kernel: [ 5.011305] pci 0000:02:02.0: reg 0x10: [mem
0xfc040000-0xfc043fff 64bit]
2024-04-26T14:30:57.959233Z INFO kernel: [ 5.016133] pci 0000:02:02.0: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.959234Z INFO kernel: [ 5.018157] pci 0000:02:03.0: [15ad:0770]
type 00 class 0x0c0320
2024-04-26T14:30:57.959236Z INFO kernel: [ 5.019816] pci 0000:02:03.0: reg 0x10: [mem
0xfc044000-0xfc044fff]
2024-04-26T14:30:57.959237Z INFO kernel: [ 5.026927] pci 0000:00:11.0: PCI bridge to
[bus 02] (subtractive decode)
2024-04-26T14:30:57.959241Z INFO kernel: [ 5.027571] pci 0000:00:11.0: bridge window
[io 0x1000-0x1fff]
2024-04-26T14:30:57.959245Z INFO kernel: [ 5.028570] pci 0000:00:11.0: bridge window
[mem 0xfc000000-0xfc9fffff]
2024-04-26T14:30:57.959247Z INFO kernel: [ 5.029601] pci 0000:00:11.0: bridge window
[mem 0xf8000000-0xf84fffff 64bit pref]
2024-04-26T14:30:57.959249Z INFO kernel: [ 5.030507] pci 0000:00:11.0: bridge window
[io 0x0d00-0xffff window] (subtractive decode)
2024-04-26T14:30:57.959250Z INFO kernel: [ 5.032508] pci 0000:00:11.0: bridge window
[io 0x0000-0x0cf7 window] (subtractive decode)
2024-04-26T14:30:57.959254Z INFO kernel: [ 5.033513] pci 0000:00:11.0: bridge window
[mem 0xfef00000-0xffdfffff window] (subtractive decode)
2024-04-26T14:30:57.959256Z INFO kernel: [ 5.034510] pci 0000:00:11.0: bridge window
[mem 0xfed45000-0xfedfffff window] (subtractive decode)
2024-04-26T14:30:57.959258Z INFO kernel: [ 5.035509] pci 0000:00:11.0: bridge window
[mem 0xfec10000-0xfec3ffff window] (subtractive decode)
2024-04-26T14:30:57.959260Z INFO kernel: [ 5.036510] pci 0000:00:11.0: bridge window
[mem 0xfa400000-0xfefbffff window] (subtractive decode)
2024-04-26T14:30:57.959261Z INFO kernel: [ 5.038505] pci 0000:00:11.0: bridge window
[mem 0xf0000000-0xfa3fffff pref window] (subtractive decode)
2024-04-26T14:30:57.959263Z INFO kernel: [ 5.039511] pci 0000:00:11.0: bridge window
[mem 0xc0000000-0xefffffff window] (subtractive decode)
2024-04-26T14:30:57.959265Z INFO kernel: [ 5.040510] pci 0000:00:11.0: bridge window
[mem 0x000a0000-0x000bffff window] (subtractive decode)
2024-04-26T14:30:57.959266Z INFO kernel: [ 5.041511] pci 0000:00:11.0: bridge window
[mem 0x000c4000-0x000c7fff window] (subtractive decode)
```

```
2024-04-26T14:30:57.959273Z INFO kernel: [ 5.042508] pci 0000:00:11.0: bridge window
[mem 0x000c8000-0x000cbfff window] (subtractive decode)
2024-04-26T14:30:57.959274Z INFO kernel: [ 5.043507] pci 0000:00:11.0: bridge window
[mem 0x000d4000-0x000d7fff window] (subtractive decode)
2024-04-26T14:30:57.959276Z INFO kernel: [ 5.044510] pci 0000:00:11.0: bridge window
[mem 0x000d8000-0x000dbfff window] (subtractive decode)
2024-04-26T14:30:57.959278Z INFO kernel: [ 5.045510] pci 0000:00:11.0: bridge window
[mem 0x000e4000-0x000e7fff window] (subtractive decode)
2024-04-26T14:30:57.959279Z INFO kernel: [ 5.046511] pci 0000:00:11.0: bridge window
[mem 0x000e8000-0x000ebfff window] (subtractive decode)
2024-04-26T14:30:57.959281Z INFO kernel: [ 5.047509] pci 0000:00:11.0: bridge window
[mem 0x000ec000-0x000effff window] (subtractive decode)
2024-04-26T14:30:57.959283Z INFO kernel: [ 5.050219] pci 0000:03:00.0: [15ad:07f0]
type 00 class 0x010802
2024-04-26T14:30:57.959284Z INFO kernel: [ 5.052507] pci 0000:03:00.0: reg 0x10: [mem
0xfea00000-0xfea03fff 64bit]
2024-04-26T14:30:57.959286Z INFO kernel: [ 5.054508] pci 0000:03:00.0: reg 0x18: [io
0x3000-0x3007]
2024-04-26T14:30:57.959287Z INFO kernel: [ 5.058101] pci 0000:03:00.0: reg 0x30: [mem
0xfffffe000-0xffffffff pref]
2024-04-26T14:30:57.959289Z INFO kernel: [ 5.060387] pci 0000:03:00.0: PME# supported
from D0 D3hot D3cold
2024-04-26T14:30:57.959291Z INFO kernel: [ 5.062409] pci 0000:03:00.0: disabling ASPM
on pre-1.1 PCIe device. You can enable it with 'pcie_aspm=force'
2024-04-26T14:30:57.959298Z INFO kernel: [ 5.063506] pci 0000:00:15.0: PCI bridge to
[bus 03]
2024-04-26T14:30:57.959299Z INFO kernel: [ 5.064560] pci 0000:00:15.0: bridge window
[io 0x3000-0x3fff]
2024-04-26T14:30:57.959301Z INFO kernel: [ 5.065577] pci 0000:00:15.0: bridge window
[mem 0xfea00000-0xfeafffff]
2024-04-26T14:30:57.959303Z INFO kernel: [ 5.068427] pci 0000:00:15.1: PCI bridge to
[bus 04]
2024-04-26T14:30:57.959314Z INFO kernel: [ 5.068621] pci 0000:00:15.1: bridge window
[mem 0xfe900000-0xfe9fffff]
2024-04-26T14:30:57.959660Z INFO kernel: [ 5.069588] pci 0000:00:15.1: bridge window
[mem 0xfa300000-0xfa3fffff 64bit pref]
2024-04-26T14:30:57.959665Z INFO kernel: [ 5.071617] pci 0000:00:15.2: PCI bridge to
[bus 05]
2024-04-26T14:30:57.959667Z INFO kernel: [ 5.072634] pci 0000:00:15.2: bridge window
[mem 0xfe800000-0xfe8fffff]
2024-04-26T14:30:57.959669Z INFO kernel: [ 5.073620] pci 0000:00:15.2: bridge window
[mem 0xfa200000-0xfa2fffff 64bit pref]
2024-04-26T14:30:57.959670Z INFO kernel: [ 5.076619] pci 0000:00:15.3: PCI bridge to
[bus 06]
2024-04-26T14:30:57.959684Z INFO kernel: [ 5.078504] pci 0000:00:15.3: bridge window
[mem 0xfe700000-0xfe7fffff]
2024-04-26T14:30:57.959686Z INFO kernel: [ 5.079674] pci 0000:00:15.3: bridge window
[mem 0xfa100000-0xfa1fffff 64bit pref]
2024-04-26T14:30:57.959687Z INFO kernel: [ 5.082703] pci 0000:00:15.4: PCI bridge to
[bus 07]
2024-04-26T14:30:57.959689Z INFO kernel: [ 5.083631] pci 0000:00:15.4: bridge window
[mem 0xfe600000-0xfe6fffff]
2024-04-26T14:30:57.959691Z INFO kernel: [ 5.084610] pci 0000:00:15.4: bridge window
[mem 0xfa000000-0xfa0fffff 64bit pref]
2024-04-26T14:30:57.959692Z INFO kernel: [ 5.088138] pci 0000:00:15.5: PCI bridge to
[bus 08]
2024-04-26T14:30:57.959694Z INFO kernel: [ 5.088625] pci 0000:00:15.5: bridge window
[mem 0xfe500000-0xfe5fffff]
2024-04-26T14:30:57.959705Z INFO kernel: [ 5.089607] pci 0000:00:15.5: bridge window
[mem 0xf9f00000-0xf9fffff 64bit pref]
2024-04-26T14:30:57.959707Z INFO kernel: [ 5.092249] pci 0000:00:15.6: PCI bridge to
[bus 09]
2024-04-26T14:30:57.959709Z INFO kernel: [ 5.092623] pci 0000:00:15.6: bridge window
[mem 0xfe400000-0xfe4fffff]
2024-04-26T14:30:57.959711Z INFO kernel: [ 5.093599] pci 0000:00:15.6: bridge window
[mem 0xf9e00000-0xf9efffff 64bit pref]
2024-04-26T14:30:57.959712Z INFO kernel: [ 5.095819] pci 0000:00:15.7: PCI bridge to
[bus 0a]
2024-04-26T14:30:57.959714Z INFO kernel: [ 5.096624] pci 0000:00:15.7: bridge window
```

```
[mem 0xfe300000-0xfe3ffffff]
2024-04-26T14:30:57.959720Z INFO kernel: [ 5.098565] pci 0000:00:15.7: bridge window
[mem 0xf9d00000-0xf9dffffff 64bit pref]
2024-04-26T14:30:57.959722Z INFO kernel: [ 5.100933] pci 0000:00:16.0: PCI bridge to
[bus 0b]
2024-04-26T14:30:57.959724Z INFO kernel: [ 5.102559] pci 0000:00:16.0: bridge window
[mem 0xfe200000-0xfe2ffffff]
2024-04-26T14:30:57.959730Z INFO kernel: [ 5.103604] pci 0000:00:16.0: bridge window
[mem 0xf9c00000-0xf9cffffff 64bit pref]
2024-04-26T14:30:57.959731Z INFO kernel: [ 5.106235] pci 0000:00:16.1: PCI bridge to
[bus 0c]
2024-04-26T14:30:57.959733Z INFO kernel: [ 5.106618] pci 0000:00:16.1: bridge window
[mem 0xfe100000-0xfe1ffffff]
2024-04-26T14:30:57.959734Z INFO kernel: [ 5.107595] pci 0000:00:16.1: bridge window
[mem 0xf9b00000-0xf9bffffff 64bit pref]
2024-04-26T14:30:57.959741Z INFO kernel: [ 5.110125] pci 0000:00:16.2: PCI bridge to
[bus 0d]
2024-04-26T14:30:57.959743Z INFO kernel: [ 5.110634] pci 0000:00:16.2: bridge window
[mem 0xfe000000-0xfe0ffffff]
2024-04-26T14:30:57.959745Z INFO kernel: [ 5.112562] pci 0000:00:16.2: bridge window
[mem 0xf9a00000-0xf9affffff 64bit pref]
2024-04-26T14:30:57.959746Z INFO kernel: [ 5.115264] pci 0000:00:16.3: PCI bridge to
[bus 0e]
2024-04-26T14:30:57.959747Z INFO kernel: [ 5.115703] pci 0000:00:16.3: bridge window
[mem 0xfdf00000-0xfdfffffff]
2024-04-26T14:30:57.959748Z INFO kernel: [ 5.116611] pci 0000:00:16.3: bridge window
[mem 0xf9900000-0xf99ffffff 64bit pref]
2024-04-26T14:30:57.959755Z INFO kernel: [ 5.118575] pci 0000:00:16.4: PCI bridge to
[bus 0f]
2024-04-26T14:30:57.959756Z INFO kernel: [ 5.119624] pci 0000:00:16.4: bridge window
[mem 0xfde00000-0xfdeffffff]
2024-04-26T14:30:57.959757Z INFO kernel: [ 5.120613] pci 0000:00:16.4: bridge window
[mem 0xf9800000-0xf98ffffff 64bit pref]
2024-04-26T14:30:57.959759Z INFO kernel: [ 5.123026] pci 0000:00:16.5: PCI bridge to
[bus 10]
2024-04-26T14:30:57.959760Z INFO kernel: [ 5.123656] pci 0000:00:16.5: bridge window
[mem 0xfdd00000-0xfddffffff]
2024-04-26T14:30:57.959762Z INFO kernel: [ 5.124603] pci 0000:00:16.5: bridge window
[mem 0xf9700000-0xf97ffffff 64bit pref]
2024-04-26T14:30:57.959770Z INFO kernel: [ 5.126306] pci 0000:00:16.6: PCI bridge to
[bus 11]
2024-04-26T14:30:57.959772Z INFO kernel: [ 5.126620] pci 0000:00:16.6: bridge window
[mem 0xfdc00000-0xfdcffffff]
2024-04-26T14:30:57.959779Z INFO kernel: [ 5.127602] pci 0000:00:16.6: bridge window
[mem 0xf9600000-0xf96ffffff 64bit pref]
2024-04-26T14:30:57.959780Z INFO kernel: [ 5.129878] pci 0000:00:16.7: PCI bridge to
[bus 12]
2024-04-26T14:30:57.959782Z INFO kernel: [ 5.130777] pci 0000:00:16.7: bridge window
[mem 0xfdb00000-0xfdbffffff]
2024-04-26T14:30:57.959783Z INFO kernel: [ 5.131609] pci 0000:00:16.7: bridge window
[mem 0xf9500000-0xf95ffffff 64bit pref]
2024-04-26T14:30:57.959785Z INFO kernel: [ 5.134261] pci 0000:00:17.0: PCI bridge to
[bus 13]
2024-04-26T14:30:57.959792Z INFO kernel: [ 5.134628] pci 0000:00:17.0: bridge window
[mem 0xfda00000-0xfdaffffff]
2024-04-26T14:30:57.959793Z INFO kernel: [ 5.135620] pci 0000:00:17.0: bridge window
[mem 0xf9400000-0xf94ffffff 64bit pref]
2024-04-26T14:30:57.959795Z INFO kernel: [ 5.137796] pci 0000:00:17.1: PCI bridge to
[bus 14]
2024-04-26T14:30:57.959796Z INFO kernel: [ 5.138705] pci 0000:00:17.1: bridge window
[mem 0xfd900000-0xfd9ffffff]
2024-04-26T14:30:57.959798Z INFO kernel: [ 5.140535] pci 0000:00:17.1: bridge window
[mem 0xf9300000-0xf93ffffff 64bit pref]
2024-04-26T14:30:57.959804Z INFO kernel: [ 5.142796] pci 0000:00:17.2: PCI bridge to
[bus 15]
2024-04-26T14:30:57.959811Z INFO kernel: [ 5.143623] pci 0000:00:17.2: bridge window
[mem 0xfd800000-0xfd8ffffff]
2024-04-26T14:30:57.959813Z INFO kernel: [ 5.145561] pci 0000:00:17.2: bridge window
[mem 0xf9200000-0xf92ffffff 64bit pref]
```

```
2024-04-26T14:30:57.959814Z INFO kernel: [ 5.147944] pci 0000:00:17.3: PCI bridge to
[bus 16]
2024-04-26T14:30:57.959816Z INFO kernel: [ 5.148662] pci 0000:00:17.3: bridge window
[mem 0xfd700000-0xfd7ffffff]
2024-04-26T14:30:57.959817Z INFO kernel: [ 5.149620] pci 0000:00:17.3: bridge window
[mem 0xf9100000-0xf91ffffff 64bit pref]
2024-04-26T14:30:57.959819Z INFO kernel: [ 5.152673] pci 0000:00:17.4: PCI bridge to
[bus 17]
2024-04-26T14:30:57.959820Z INFO kernel: [ 5.153634] pci 0000:00:17.4: bridge window
[mem 0xfd600000-0xfd6ffffff]
2024-04-26T14:30:57.959831Z INFO kernel: [ 5.154606] pci 0000:00:17.4: bridge window
[mem 0xf9000000-0xf90ffffff 64bit pref]
2024-04-26T14:30:57.959833Z INFO kernel: [ 5.156926] pci 0000:00:17.5: PCI bridge to
[bus 18]
2024-04-26T14:30:57.959835Z INFO kernel: [ 5.158563] pci 0000:00:17.5: bridge window
[mem 0xfd500000-0xfd5ffffff]
2024-04-26T14:30:57.959836Z INFO kernel: [ 5.159611] pci 0000:00:17.5: bridge window
[mem 0xf8f00000-0xf8fffffff 64bit pref]
2024-04-26T14:30:57.959838Z INFO kernel: [ 5.162014] pci 0000:00:17.6: PCI bridge to
[bus 19]
2024-04-26T14:30:57.959839Z INFO kernel: [ 5.162649] pci 0000:00:17.6: bridge window
[mem 0xfd400000-0xfd4ffffff]
2024-04-26T14:30:57.959846Z INFO kernel: [ 5.163606] pci 0000:00:17.6: bridge window
[mem 0xf8e00000-0xf8effffff 64bit pref]
2024-04-26T14:30:57.959852Z INFO kernel: [ 5.166097] pci 0000:00:17.7: PCI bridge to
[bus 1a]
2024-04-26T14:30:57.959854Z INFO kernel: [ 5.166643] pci 0000:00:17.7: bridge window
[mem 0xfd300000-0xfd3ffffff]
2024-04-26T14:30:57.959856Z INFO kernel: [ 5.167591] pci 0000:00:17.7: bridge window
[mem 0xf8d00000-0xf8dffffff 64bit pref]
2024-04-26T14:30:57.959857Z INFO kernel: [ 5.169850] pci 0000:00:18.0: PCI bridge to
[bus 1b]
2024-04-26T14:30:57.959859Z INFO kernel: [ 5.170621] pci 0000:00:18.0: bridge window
[mem 0xfd200000-0xfd2ffffff]
2024-04-26T14:30:57.959865Z INFO kernel: [ 5.171603] pci 0000:00:18.0: bridge window
[mem 0xf8c00000-0xf8cffffff 64bit pref]
2024-04-26T14:30:57.959867Z INFO kernel: [ 5.173606] pci 0000:00:18.1: PCI bridge to
[bus 1c]
2024-04-26T14:30:57.959869Z INFO kernel: [ 5.174631] pci 0000:00:18.1: bridge window
[mem 0xfd100000-0xfd1ffffff]
2024-04-26T14:30:57.959870Z INFO kernel: [ 5.175608] pci 0000:00:18.1: bridge window
[mem 0xf8b00000-0xf8bffffff 64bit pref]
2024-04-26T14:30:57.959872Z INFO kernel: [ 5.177932] pci 0000:00:18.2: PCI bridge to
[bus 1d]
2024-04-26T14:30:57.959878Z INFO kernel: [ 5.178628] pci 0000:00:18.2: bridge window
[mem 0xfd000000-0xfd0ffffff]
2024-04-26T14:30:57.959880Z INFO kernel: [ 5.179608] pci 0000:00:18.2: bridge window
[mem 0xf8a00000-0xf8affffff 64bit pref]
2024-04-26T14:30:57.959886Z INFO kernel: [ 5.181700] pci 0000:00:18.3: PCI bridge to
[bus 1e]
2024-04-26T14:30:57.959888Z INFO kernel: [ 5.182618] pci 0000:00:18.3: bridge window
[mem 0xfcf00000-0xfcfffffff]
2024-04-26T14:30:57.959890Z INFO kernel: [ 5.184560] pci 0000:00:18.3: bridge window
[mem 0xf8900000-0xf89ffffff 64bit pref]
2024-04-26T14:30:57.959891Z INFO kernel: [ 5.186718] pci 0000:00:18.4: PCI bridge to
[bus 1f]
2024-04-26T14:30:57.959893Z INFO kernel: [ 5.187748] pci 0000:00:18.4: bridge window
[mem 0xfce00000-0xfceffffff]
2024-04-26T14:30:57.959894Z INFO kernel: [ 5.188621] pci 0000:00:18.4: bridge window
[mem 0xf8800000-0xf88ffffff 64bit pref]
2024-04-26T14:30:57.959907Z INFO kernel: [ 5.191020] pci 0000:00:18.5: PCI bridge to
[bus 20]
2024-04-26T14:30:57.959909Z INFO kernel: [ 5.192596] pci 0000:00:18.5: bridge window
[mem 0xfcd00000-0xfcdffffff]
2024-04-26T14:30:57.959911Z INFO kernel: [ 5.193591] pci 0000:00:18.5: bridge window
[mem 0xf8700000-0xf87ffffff 64bit pref]
2024-04-26T14:30:57.959912Z INFO kernel: [ 5.195816] pci 0000:00:18.6: PCI bridge to
[bus 21]
2024-04-26T14:30:57.959914Z INFO kernel: [ 5.196610] pci 0000:00:18.6: bridge window
```

```

[mem 0xfcc00000-0xfccfffff]
2024-04-26T14:30:57.959915Z INFO kernel: [ 5.197606] pci 0000:00:18.6: bridge window
[mem 0xf8600000-0xf86fffff 64bit pref]
2024-04-26T14:30:57.959917Z INFO kernel: [ 5.200195] pci 0000:00:18.7: PCI bridge to
[bus 22]
2024-04-26T14:30:57.959923Z INFO kernel: [ 5.200621] pci 0000:00:18.7: bridge window
[mem 0xfcb00000-0xfcbfffff]
2024-04-26T14:30:57.959930Z INFO kernel: [ 5.201599] pci 0000:00:18.7: bridge window
[mem 0xf8500000-0xf85fffff 64bit pref]
2024-04-26T14:30:57.959932Z DEBUG kernel: [ 5.207233] pci_bus 0000:00: on NUMA node 0
2024-04-26T14:30:57.959933Z INFO kernel: [ 5.207733] ACPI: PCI: Interrupt link LNKA
configured for IRQ 0
2024-04-26T14:30:57.959935Z INFO kernel: [ 5.208762] ACPI: PCI: Interrupt link LNKA
disabled
2024-04-26T14:30:57.959936Z INFO kernel: [ 5.210550] ACPI: PCI: Interrupt link LNKB
configured for IRQ 0
2024-04-26T14:30:57.959943Z INFO kernel: [ 5.211506] ACPI: PCI: Interrupt link LNKB
disabled
2024-04-26T14:30:57.959945Z INFO kernel: [ 5.213644] ACPI: PCI: Interrupt link LNKC
configured for IRQ 0
2024-04-26T14:30:57.959946Z INFO kernel: [ 5.214505] ACPI: PCI: Interrupt link LNKC
disabled
2024-04-26T14:30:57.959948Z INFO kernel: [ 5.215727] ACPI: PCI: Interrupt link LNKD
configured for IRQ 0
2024-04-26T14:30:57.959954Z INFO kernel: [ 5.216505] ACPI: PCI: Interrupt link LNKD
disabled
2024-04-26T14:30:57.959956Z NOTICE kernel: [ 5.282882] SCSI subsystem initialized
2024-04-26T14:30:57.959963Z DEBUG kernel: [ 5.284562] libata version 3.00 loaded.
2024-04-26T14:30:57.959965Z INFO kernel: [ 5.284755] ACPI: bus type USB registered
2024-04-26T14:30:57.959966Z INFO kernel: [ 5.285639] usbcore: registered new interface
driver usbfs
2024-04-26T14:30:57.959968Z INFO kernel: [ 5.286520] usbcore: registered new interface
driver hub
2024-04-26T14:30:57.959969Z INFO kernel: [ 5.287519] usbcore: registered new device
driver usb
2024-04-26T14:30:57.959971Z INFO kernel: [ 5.288616] mc: Linux media interface: v0.10
2024-04-26T14:30:57.959972Z INFO kernel: [ 5.289551] videodev: Linux video capture
interface: v2.00
2024-04-26T14:30:57.959984Z INFO kernel: [ 5.290681] Registered efivars operations
2024-04-26T14:30:57.959985Z INFO kernel: [ 5.291792] chromeos_acpi: installed
2024-04-26T14:30:57.960315Z INFO kernel: [ 5.292624] Advanced Linux Sound Architecture
Driver Initialized.
2024-04-26T14:30:57.960325Z INFO kernel: [ 5.294954] PCI: Using ACPI for IRQ routing
2024-04-26T14:30:57.960327Z DEBUG kernel: [ 5.391722] PCI: pci_cache_line_size set to
64 bytes
2024-04-26T14:30:57.960328Z DEBUG kernel: [ 5.395764] e820: reserve RAM buffer [mem
0x0e5e7000-0x0fffffff]
2024-04-26T14:30:57.960337Z DEBUG kernel: [ 5.395774] e820: reserve RAM buffer [mem
0x0ef9a000-0x0fffffff]
2024-04-26T14:30:57.960339Z DEBUG kernel: [ 5.395776] e820: reserve RAM buffer [mem
0x0efad000-0x0fffffff]
2024-04-26T14:30:57.960343Z DEBUG kernel: [ 5.395778] e820: reserve RAM buffer [mem
0x0fee5000-0x0fffffff]
2024-04-26T14:30:57.960347Z DEBUG kernel: [ 5.395780] e820: reserve RAM buffer [mem
0x0ff74000-0x0fffffff]
2024-04-26T14:30:57.960348Z DEBUG kernel: [ 5.395781] e820: reserve RAM buffer [mem
0x1c9c00000-0x1cbfffff]
2024-04-26T14:30:57.960350Z INFO kernel: [ 5.396774] hpet0: at MMIO 0xfed00000, IRQs
2, 8, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
2024-04-26T14:30:57.960352Z INFO kernel: [ 5.397506] hpet0: 16 comparators, 64-bit
14.318180 MHz counter
2024-04-26T14:30:57.960359Z INFO kernel: [ 5.405700] clocksource: Switched to
clocksource tsc-early
2024-04-26T14:30:57.960361Z NOTICE kernel: [ 5.488786] VFS: Disk quotas dquot_6.6.0
2024-04-26T14:30:57.960362Z INFO kernel: [ 5.490468] VFS: Dquot-cache hash table
entries: 512 (order 0, 4096 bytes)
2024-04-26T14:30:57.960364Z INFO kernel: [ 5.493077] pnp: PnP ACPI init
2024-04-26T14:30:57.960368Z INFO kernel: [ 5.495011] system 00:00: [io 0x0440-0x047f]
has been reserved

```

```
2024-04-26T14:30:57.960371Z INFO kernel: [ 5.497261] system 00:00: [io 0x5658-0x5659]
has been reserved
2024-04-26T14:30:57.960378Z INFO kernel: [ 5.499821] system 00:00: [io 0x5670] has
been reserved
2024-04-26T14:30:57.960380Z INFO kernel: [ 5.501509] system 00:00: [io 0x0cf0-0x0cf1]
has been reserved
2024-04-26T14:30:57.960382Z INFO kernel: [ 5.504929] system 00:04: [mem 0xfed00000-
0xfed003ff] has been reserved
2024-04-26T14:30:57.960383Z INFO kernel: [ 5.510308] system 00:05: [io 0x0400-0x041f]
has been reserved
2024-04-26T14:30:57.960385Z INFO kernel: [ 5.512050] system 00:05: [mem 0xe0000000-
0xe7ffffff] has been reserved
2024-04-26T14:30:57.960386Z INFO kernel: [ 5.513964] system 00:05: [mem 0xffc00000-
0xffdffffff] could not be reserved
2024-04-26T14:30:57.960493Z INFO kernel: [ 5.565787] pnp: PnP ACPI: found 6 devices
2024-04-26T14:30:57.960501Z INFO kernel: [ 5.574433] clocksource: acpi_pm: mask:
0xffffffff max_cycles: 0xffffffff, max_idle_ns: 2085701024 ns
2024-04-26T14:30:57.960503Z INFO kernel: [ 5.577215] NET: Registered PF_INET protocol
family
2024-04-26T14:30:57.960505Z INFO kernel: [ 5.591853] IP idents hash table entries:
131072 (order: 8, 1048576 bytes, linear)
2024-04-26T14:30:57.960506Z INFO kernel: [ 5.595894] tcp_listen_portaddr_hash hash
table entries: 4096 (order: 4, 65536 bytes, linear)
2024-04-26T14:30:57.960508Z INFO kernel: [ 5.600581] Table-perturb hash table entries:
65536 (order: 6, 262144 bytes, linear)
2024-04-26T14:30:57.960509Z INFO kernel: [ 5.602874] TCP established hash table
entries: 65536 (order: 7, 524288 bytes, linear)
2024-04-26T14:30:57.960565Z INFO kernel: [ 5.611985] TCP bind hash table entries:
65536 (order: 8, 1048576 bytes, linear)
2024-04-26T14:30:57.960575Z INFO kernel: [ 5.623056] TCP: Hash tables configured
(established 65536 bind 65536)
2024-04-26T14:30:57.960576Z INFO kernel: [ 5.626411] UDP hash table entries: 4096
(order: 5, 131072 bytes, linear)
2024-04-26T14:30:57.960578Z INFO kernel: [ 5.629242] UDP-Lite hash table entries: 4096
(order: 5, 131072 bytes, linear)
2024-04-26T14:30:57.960580Z INFO kernel: [ 5.632623] NET: Registered PF_UNIX/PF_LOCAL
protocol family
2024-04-26T14:30:57.960581Z INFO kernel: [ 5.634256] pci 0000:00:10.0: can't claim BAR
6 [mem 0xffffc000-0xffffffff pref]: no compatible bridge window
2024-04-26T14:30:57.960634Z INFO kernel: [ 5.637211] pci 0000:02:01.0: can't claim BAR
6 [mem 0xffff0000-0xffffffff pref]: no compatible bridge window
2024-04-26T14:30:57.960639Z INFO kernel: [ 5.639937] pci 0000:03:00.0: can't claim BAR
6 [mem 0xffffe000-0xffffffff pref]: no compatible bridge window
2024-04-26T14:30:57.960641Z INFO kernel: [ 5.642797] pci 0000:00:15.0: bridge window
[mem 0x00100000-0x000fffff 64bit pref] to [bus 03] add_size 200000 add_align 100000
2024-04-26T14:30:57.960642Z INFO kernel: [ 5.646197] pci 0000:00:15.1: bridge window
[io 0x1000-0x0fff] to [bus 04] add_size 1000
2024-04-26T14:30:57.960644Z INFO kernel: [ 5.649604] pci 0000:00:15.2: bridge window
[io 0x1000-0x0fff] to [bus 05] add_size 1000
2024-04-26T14:30:57.960645Z INFO kernel: [ 5.651814] pci 0000:00:15.3: bridge window
[io 0x1000-0x0fff] to [bus 06] add_size 1000
2024-04-26T14:30:57.960698Z INFO kernel: [ 5.654058] pci 0000:00:15.4: bridge window
[io 0x1000-0x0fff] to [bus 07] add_size 1000
2024-04-26T14:30:57.960707Z INFO kernel: [ 5.656436] pci 0000:00:15.5: bridge window
[io 0x1000-0x0fff] to [bus 08] add_size 1000
2024-04-26T14:30:57.960709Z INFO kernel: [ 5.658932] pci 0000:00:15.6: bridge window
[io 0x1000-0x0fff] to [bus 09] add_size 1000
2024-04-26T14:30:57.960711Z INFO kernel: [ 5.661595] pci 0000:00:15.7: bridge window
[io 0x1000-0x0fff] to [bus 0a] add_size 1000
2024-04-26T14:30:57.960712Z INFO kernel: [ 5.663927] pci 0000:00:16.0: bridge window
[io 0x1000-0x0fff] to [bus 0b] add_size 1000
2024-04-26T14:30:57.960714Z INFO kernel: [ 5.666331] pci 0000:00:16.1: bridge window
[io 0x1000-0x0fff] to [bus 0c] add_size 1000
2024-04-26T14:30:57.960768Z INFO kernel: [ 5.669253] pci 0000:00:16.2: bridge window
[io 0x1000-0x0fff] to [bus 0d] add_size 1000
2024-04-26T14:30:57.960773Z INFO kernel: [ 5.671438] pci 0000:00:16.3: bridge window
[io 0x1000-0x0fff] to [bus 0e] add_size 1000
2024-04-26T14:30:57.960774Z INFO kernel: [ 5.674094] pci 0000:00:16.4: bridge window
[io 0x1000-0x0fff] to [bus 0f] add_size 1000
```

```
2024-04-26T14:30:57.960776Z INFO kernel: [ 5.676448] pci 0000:00:16.5: bridge window
[io 0x1000-0x0fff] to [bus 10] add_size 1000
2024-04-26T14:30:57.960777Z INFO kernel: [ 5.683388] pci 0000:00:16.6: bridge window
[io 0x1000-0x0fff] to [bus 11] add_size 1000
2024-04-26T14:30:57.960779Z INFO kernel: [ 5.690075] pci 0000:00:16.7: bridge window
[io 0x1000-0x0fff] to [bus 12] add_size 1000
2024-04-26T14:30:57.960780Z INFO kernel: [ 5.695448] pci 0000:00:17.0: bridge window
[io 0x1000-0x0fff] to [bus 13] add_size 1000
2024-04-26T14:30:57.960832Z INFO kernel: [ 5.698000] pci 0000:00:17.1: bridge window
[io 0x1000-0x0fff] to [bus 14] add_size 1000
2024-04-26T14:30:57.960837Z INFO kernel: [ 5.700539] pci 0000:00:17.2: bridge window
[io 0x1000-0x0fff] to [bus 15] add_size 1000
2024-04-26T14:30:57.960838Z INFO kernel: [ 5.706262] pci 0000:00:17.3: bridge window
[io 0x1000-0x0fff] to [bus 16] add_size 1000
2024-04-26T14:30:57.960845Z INFO kernel: [ 5.710256] pci 0000:00:17.4: bridge window
[io 0x1000-0x0fff] to [bus 17] add_size 1000
2024-04-26T14:30:57.960846Z INFO kernel: [ 5.713127] pci 0000:00:17.5: bridge window
[io 0x1000-0x0fff] to [bus 18] add_size 1000
2024-04-26T14:30:57.960848Z INFO kernel: [ 5.716401] pci 0000:00:17.6: bridge window
[io 0x1000-0x0fff] to [bus 19] add_size 1000
2024-04-26T14:30:57.960895Z INFO kernel: [ 5.718832] pci 0000:00:17.7: bridge window
[io 0x1000-0x0fff] to [bus 1a] add_size 1000
2024-04-26T14:30:57.960904Z INFO kernel: [ 5.724922] pci 0000:00:18.0: bridge window
[io 0x1000-0x0fff] to [bus 1b] add_size 1000
2024-04-26T14:30:57.960906Z INFO kernel: [ 5.728372] pci 0000:00:18.1: bridge window
[io 0x1000-0x0fff] to [bus 1c] add_size 1000
2024-04-26T14:30:57.960907Z INFO kernel: [ 5.732421] pci 0000:00:18.2: bridge window
[io 0x1000-0x0fff] to [bus 1d] add_size 1000
2024-04-26T14:30:57.960909Z INFO kernel: [ 5.734846] pci 0000:00:18.3: bridge window
[io 0x1000-0x0fff] to [bus 1e] add_size 1000
2024-04-26T14:30:57.960910Z INFO kernel: [ 5.740910] pci 0000:00:18.4: bridge window
[io 0x1000-0x0fff] to [bus 1f] add_size 1000
2024-04-26T14:30:57.960970Z INFO kernel: [ 5.743867] pci 0000:00:18.5: bridge window
[io 0x1000-0x0fff] to [bus 20] add_size 1000
2024-04-26T14:30:57.960978Z INFO kernel: [ 5.746331] pci 0000:00:18.6: bridge window
[io 0x1000-0x0fff] to [bus 21] add_size 1000
2024-04-26T14:30:57.960984Z INFO kernel: [ 5.748494] pci 0000:00:18.7: bridge window
[io 0x1000-0x0fff] to [bus 22] add_size 1000
2024-04-26T14:30:57.960986Z INFO kernel: [ 5.750753] pci 0000:00:15.0: BAR 9: assigned
[mem 0xfef00000-0xff0fffff 64bit pref]
2024-04-26T14:30:57.960987Z INFO kernel: [ 5.752861] pci 0000:00:10.0: BAR 6: assigned
[mem 0xff100000-0xff103fff pref]
2024-04-26T14:30:57.960989Z INFO kernel: [ 5.758314] pci 0000:00:15.1: BAR 7: assigned
[io 0x4000-0x4fff]
2024-04-26T14:30:57.960990Z INFO kernel: [ 5.759938] pci 0000:00:15.2: BAR 7: assigned
[io 0x6000-0x6fff]
2024-04-26T14:30:57.961104Z INFO kernel: [ 5.761558] pci 0000:00:15.3: BAR 7: assigned
[io 0x7000-0x7fff]
2024-04-26T14:30:57.961109Z INFO kernel: [ 5.763168] pci 0000:00:15.4: BAR 7: assigned
[io 0x8000-0x8fff]
2024-04-26T14:30:57.961116Z INFO kernel: [ 5.765359] pci 0000:00:15.5: BAR 7: assigned
[io 0x9000-0x9fff]
2024-04-26T14:30:57.961117Z INFO kernel: [ 5.767286] pci 0000:00:15.6: BAR 7: assigned
[io 0xa000-0xafff]
2024-04-26T14:30:57.961119Z INFO kernel: [ 5.768973] pci 0000:00:15.7: BAR 7: assigned
[io 0xb000-0xbfff]
2024-04-26T14:30:57.961121Z INFO kernel: [ 5.771914] pci 0000:00:16.0: BAR 7: assigned
[io 0xc000-0xcfff]
2024-04-26T14:30:57.961177Z INFO kernel: [ 5.775582] pci 0000:00:16.1: BAR 7: assigned
[io 0xd000-0xdfff]
2024-04-26T14:30:57.961181Z INFO kernel: [ 5.777388] pci 0000:00:16.2: BAR 7: assigned
[io 0xe000-0xefff]
2024-04-26T14:30:57.961183Z INFO kernel: [ 5.779295] pci 0000:00:16.3: BAR 7: assigned
[io 0xf000-0xffff]
2024-04-26T14:30:57.961185Z INFO kernel: [ 5.781124] pci 0000:00:16.4: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.961186Z INFO kernel: [ 5.784105] pci 0000:00:16.4: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.961188Z INFO kernel: [ 5.786605] pci 0000:00:16.5: BAR 7: no space
```



```
for [io size 0x1000]
2024-04-26T14:30:57.961189Z INFO kernel: [ 5.789588] pci 0000:00:16.5: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.961244Z INFO kernel: [ 5.792533] pci 0000:00:16.6: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.961250Z INFO kernel: [ 5.794336] pci 0000:00:16.6: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.961251Z INFO kernel: [ 5.796293] pci 0000:00:16.7: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.961253Z INFO kernel: [ 5.798183] pci 0000:00:16.7: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.961254Z INFO kernel: [ 5.801085] pci 0000:00:17.0: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.961256Z INFO kernel: [ 5.803015] pci 0000:00:17.0: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.961309Z INFO kernel: [ 5.805673] pci 0000:00:17.1: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.961314Z INFO kernel: [ 5.807726] pci 0000:00:17.1: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.961315Z INFO kernel: [ 5.809915] pci 0000:00:17.2: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.961317Z INFO kernel: [ 5.811682] pci 0000:00:17.2: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.961586Z INFO kernel: [ 5.813605] pci 0000:00:17.3: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.961593Z INFO kernel: [ 5.815705] pci 0000:00:17.3: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.914543Z WARNING rsyslogd[462]: warning: ~ action is deprecated,
consider using the 'stop' statement instead [v8.2112.0 try https://www.rsyslog.com/e/2307
]
2024-04-26T14:30:57.914565Z WARNING rsyslogd[462]: warning: ~ action is deprecated,
consider using the 'stop' statement instead [v8.2112.0 try https://www.rsyslog.com/e/2307
]
2024-04-26T14:30:57.914573Z INFO rsyslogd[462]: rsyslogd's groupid changed to 202
2024-04-26T14:30:57.914583Z INFO rsyslogd[462]: rsyslogd's userid changed to 202
2024-04-26T14:30:57.914590Z INFO rsyslogd[462]: [origin software="rsyslogd"
swVersion="8.2112.0" x-pid="462" x-info="https://www.rsyslog.com"] start
2024-04-26T14:30:57.963365Z INFO kernel: [ 5.817673] pci 0000:00:17.4: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976028Z INFO kernel: [ 5.819766] pci 0000:00:17.4: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976043Z INFO kernel: [ 5.821833] pci 0000:00:17.5: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976865Z INFO kernel: [ 5.823492] pci 0000:00:17.5: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976871Z INFO kernel: [ 5.825302] pci 0000:00:17.6: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976874Z INFO kernel: [ 5.827186] pci 0000:00:17.6: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976875Z INFO kernel: [ 5.829362] pci 0000:00:17.7: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976877Z INFO kernel: [ 5.831089] pci 0000:00:17.7: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976879Z INFO kernel: [ 5.833162] pci 0000:00:18.0: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976881Z INFO kernel: [ 5.834995] pci 0000:00:18.0: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976882Z INFO kernel: [ 5.837286] pci 0000:00:18.1: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976884Z INFO kernel: [ 5.839096] pci 0000:00:18.1: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976886Z INFO kernel: [ 5.840968] pci 0000:00:18.2: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976888Z INFO kernel: [ 5.843250] pci 0000:00:18.2: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976889Z INFO kernel: [ 5.845495] pci 0000:00:18.3: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976891Z INFO kernel: [ 5.847303] pci 0000:00:18.3: BAR 7: failed
to assign [io size 0x1000]
```

```
2024-04-26T14:30:57.976893Z INFO kernel: [ 5.849172] pci 0000:00:18.4: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976895Z INFO kernel: [ 5.850895] pci 0000:00:18.4: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976896Z INFO kernel: [ 5.853079] pci 0000:00:18.5: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976898Z INFO kernel: [ 5.854813] pci 0000:00:18.5: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976900Z INFO kernel: [ 5.856601] pci 0000:00:18.6: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976902Z INFO kernel: [ 5.858330] pci 0000:00:18.6: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976903Z INFO kernel: [ 5.860216] pci 0000:00:18.7: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976905Z INFO kernel: [ 5.862072] pci 0000:00:18.7: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976911Z INFO kernel: [ 5.863952] pci 0000:00:18.7: BAR 7: assigned
[io 0x4000-0x4fff]
2024-04-26T14:30:57.976913Z INFO kernel: [ 5.865619] pci 0000:00:18.6: BAR 7: assigned
[io 0x6000-0x6fff]
2024-04-26T14:30:57.976915Z INFO kernel: [ 5.867275] pci 0000:00:18.5: BAR 7: assigned
[io 0x7000-0x7fff]
2024-04-26T14:30:57.976916Z INFO kernel: [ 5.869003] pci 0000:00:18.4: BAR 7: assigned
[io 0x8000-0x8fff]
2024-04-26T14:30:57.976918Z INFO kernel: [ 5.871151] pci 0000:00:18.3: BAR 7: assigned
[io 0x9000-0x9fff]
2024-04-26T14:30:57.976919Z INFO kernel: [ 5.873089] pci 0000:00:18.2: BAR 7: assigned
[io 0xa000-0xafff]
2024-04-26T14:30:57.976921Z INFO kernel: [ 5.874842] pci 0000:00:18.1: BAR 7: assigned
[io 0xb000-0xbfff]
2024-04-26T14:30:57.976923Z INFO kernel: [ 5.876526] pci 0000:00:18.0: BAR 7: assigned
[io 0xc000-0xcfff]
2024-04-26T14:30:57.976924Z INFO kernel: [ 5.878753] pci 0000:00:17.7: BAR 7: assigned
[io 0xd000-0xdfff]
2024-04-26T14:30:57.976926Z INFO kernel: [ 5.880882] pci 0000:00:17.6: BAR 7: assigned
[io 0xe000-0xefff]
2024-04-26T14:30:57.976931Z INFO kernel: [ 5.882615] pci 0000:00:17.5: BAR 7: assigned
[io 0xf000-0xffff]
2024-04-26T14:30:57.976932Z INFO kernel: [ 5.884351] pci 0000:00:17.4: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976934Z INFO kernel: [ 5.886075] pci 0000:00:17.4: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976936Z INFO kernel: [ 5.888591] pci 0000:00:17.3: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976937Z INFO kernel: [ 5.890385] pci 0000:00:17.3: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976939Z INFO kernel: [ 5.892298] pci 0000:00:17.2: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976941Z INFO kernel: [ 5.894034] pci 0000:00:17.2: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976942Z INFO kernel: [ 5.896094] pci 0000:00:17.1: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976944Z INFO kernel: [ 5.897876] pci 0000:00:17.1: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976948Z INFO kernel: [ 5.900091] pci 0000:00:17.0: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976950Z INFO kernel: [ 5.901749] pci 0000:00:17.0: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976952Z INFO kernel: [ 5.903923] pci 0000:00:16.7: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976953Z INFO kernel: [ 5.906567] pci 0000:00:16.7: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976955Z INFO kernel: [ 5.908438] pci 0000:00:16.6: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976957Z INFO kernel: [ 5.910199] pci 0000:00:16.6: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976958Z INFO kernel: [ 5.912074] pci 0000:00:16.5: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976960Z INFO kernel: [ 5.914406] pci 0000:00:16.5: BAR 7: failed
```

```
to assign [io size 0x1000]
2024-04-26T14:30:57.976961Z INFO kernel: [ 5.916348] pci 0000:00:16.4: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976963Z INFO kernel: [ 5.918132] pci 0000:00:16.4: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976965Z INFO kernel: [ 5.920123] pci 0000:00:16.3: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976966Z INFO kernel: [ 5.922137] pci 0000:00:16.3: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976968Z INFO kernel: [ 5.924189] pci 0000:00:16.2: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976969Z INFO kernel: [ 5.926169] pci 0000:00:16.2: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976971Z INFO kernel: [ 5.928053] pci 0000:00:16.1: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976973Z INFO kernel: [ 5.929950] pci 0000:00:16.1: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976974Z INFO kernel: [ 5.932092] pci 0000:00:16.0: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976976Z INFO kernel: [ 5.933824] pci 0000:00:16.0: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976978Z INFO kernel: [ 5.935753] pci 0000:00:15.7: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976979Z INFO kernel: [ 5.938045] pci 0000:00:15.7: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976981Z INFO kernel: [ 5.940186] pci 0000:00:15.6: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976983Z INFO kernel: [ 5.941929] pci 0000:00:15.6: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976984Z INFO kernel: [ 5.943718] pci 0000:00:15.5: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976986Z INFO kernel: [ 5.945439] pci 0000:00:15.5: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976987Z INFO kernel: [ 5.947247] pci 0000:00:15.4: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976989Z INFO kernel: [ 5.949132] pci 0000:00:15.4: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976991Z INFO kernel: [ 5.951618] pci 0000:00:15.3: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976992Z INFO kernel: [ 5.953998] pci 0000:00:15.3: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976994Z INFO kernel: [ 5.955796] pci 0000:00:15.2: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976995Z INFO kernel: [ 5.958264] pci 0000:00:15.2: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.976997Z INFO kernel: [ 5.960412] pci 0000:00:15.1: BAR 7: no space
for [io size 0x1000]
2024-04-26T14:30:57.976999Z INFO kernel: [ 5.962619] pci 0000:00:15.1: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T14:30:57.977000Z INFO kernel: [ 5.964443] pci 0000:00:01.0: PCI bridge to
[bus 01]
2024-04-26T14:30:57.977002Z INFO kernel: [ 5.966400] pci 0000:02:01.0: BAR 6: assigned
[mem 0xfc030000-0xfc03ffff pref]
2024-04-26T14:30:57.977038Z INFO kernel: [ 5.968769] pci 0000:00:11.0: PCI bridge to
[bus 02]
2024-04-26T14:30:57.977109Z INFO kernel: [ 5.970511] pci 0000:00:11.0: bridge window
[io 0x1000-0x1fff]
2024-04-26T14:30:57.977112Z INFO kernel: [ 5.972383] pci 0000:00:11.0: bridge window
[mem 0xfc000000-0xfc9fffff]
2024-04-26T14:30:57.977115Z INFO kernel: [ 5.974255] pci 0000:00:11.0: bridge window
[mem 0xf8000000-0xf84fffff 64bit pref]
2024-04-26T14:30:57.977117Z INFO kernel: [ 5.976660] pci 0000:03:00.0: BAR 6: assigned
[mem 0xfea04000-0xfea05fff pref]
2024-04-26T14:30:57.977118Z INFO kernel: [ 5.978873] pci 0000:00:15.0: PCI bridge to
[bus 03]
2024-04-26T14:30:57.977119Z INFO kernel: [ 5.980310] pci 0000:00:15.0: bridge window
[io 0x3000-0x3fff]
2024-04-26T14:30:57.977121Z INFO kernel: [ 5.982036] pci 0000:00:15.0: bridge window
[mem 0xfea00000-0xfeafffff]
```

```
2024-04-26T14:30:57.977123Z INFO kernel: [ 5.984095] pci 0000:00:15.0: bridge window
[mem 0xfef00000-0xff0ffffff 64bit pref]
2024-04-26T14:30:57.977124Z INFO kernel: [ 5.986367] pci 0000:00:15.1: PCI bridge to
[bus 04]
2024-04-26T14:30:57.977126Z INFO kernel: [ 5.987832] pci 0000:00:15.1: bridge window
[mem 0xfe900000-0xfe9ffffff]
2024-04-26T14:30:57.977127Z INFO kernel: [ 5.989724] pci 0000:00:15.1: bridge window
[mem 0xfa300000-0xfa3ffffff 64bit pref]
2024-04-26T14:30:57.977129Z INFO kernel: [ 5.992349] pci 0000:00:15.2: PCI bridge to
[bus 05]
2024-04-26T14:30:57.977130Z INFO kernel: [ 5.993950] pci 0000:00:15.2: bridge window
[mem 0xfe800000-0xfe8ffffff]
2024-04-26T14:30:57.977132Z INFO kernel: [ 5.996143] pci 0000:00:15.2: bridge window
[mem 0xfa200000-0xfa2ffffff 64bit pref]
2024-04-26T14:30:57.977133Z INFO kernel: [ 5.998449] pci 0000:00:15.3: PCI bridge to
[bus 06]
2024-04-26T14:30:57.977135Z INFO kernel: [ 6.000000] pci 0000:00:15.3: bridge window
[mem 0xfe700000-0xfe7ffffff]
2024-04-26T14:30:57.977137Z INFO kernel: [ 6.002077] pci 0000:00:15.3: bridge window
[mem 0xfa100000-0xfa1ffffff 64bit pref]
2024-04-26T14:30:57.977138Z INFO kernel: [ 6.004448] pci 0000:00:15.4: PCI bridge to
[bus 07]
2024-04-26T14:30:57.977140Z INFO kernel: [ 6.006293] pci 0000:00:15.4: bridge window
[mem 0xfe600000-0xfe6ffffff]
2024-04-26T14:30:57.977142Z INFO kernel: [ 6.008497] pci 0000:00:15.4: bridge window
[mem 0xfa000000-0xfa0ffffff 64bit pref]
2024-04-26T14:30:57.977143Z INFO kernel: [ 6.011130] pci 0000:00:15.5: PCI bridge to
[bus 08]
2024-04-26T14:30:57.977149Z INFO kernel: [ 6.012655] pci 0000:00:15.5: bridge window
[mem 0xfe500000-0xfe5ffffff]
2024-04-26T14:30:57.977151Z INFO kernel: [ 6.014571] pci 0000:00:15.5: bridge window
[mem 0xf9f00000-0xf9ffffff 64bit pref]
2024-04-26T14:30:57.977153Z INFO kernel: [ 6.016807] pci 0000:00:15.6: PCI bridge to
[bus 09]
2024-04-26T14:30:57.977155Z INFO kernel: [ 6.018564] pci 0000:00:15.6: bridge window
[mem 0xfe400000-0xfe4ffffff]
2024-04-26T14:30:57.977156Z INFO kernel: [ 6.020836] pci 0000:00:15.6: bridge window
[mem 0xf9e00000-0xf9effffff 64bit pref]
2024-04-26T14:30:57.977158Z INFO kernel: [ 6.023073] pci 0000:00:15.7: PCI bridge to
[bus 0a]
2024-04-26T14:30:57.977401Z INFO kernel: [ 6.024570] pci 0000:00:15.7: bridge window
[mem 0xfe300000-0xfe3ffffff]
2024-04-26T14:30:57.977406Z INFO kernel: [ 6.027014] pci 0000:00:15.7: bridge window
[mem 0xf9d00000-0xf9dffffff 64bit pref]
2024-04-26T14:30:57.977408Z INFO kernel: [ 6.029304] pci 0000:00:16.0: PCI bridge to
[bus 0b]
2024-04-26T14:30:57.977409Z INFO kernel: [ 6.030789] pci 0000:00:16.0: bridge window
[mem 0xfe200000-0xfe2ffffff]
2024-04-26T14:30:57.977411Z INFO kernel: [ 6.032736] pci 0000:00:16.0: bridge window
[mem 0xf9c00000-0xf9cffffff 64bit pref]
2024-04-26T14:30:57.977416Z INFO kernel: [ 6.035009] pci 0000:00:16.1: PCI bridge to
[bus 0c]
2024-04-26T14:30:57.977417Z INFO kernel: [ 6.036927] pci 0000:00:16.1: bridge window
[mem 0xfe100000-0xfe1ffffff]
2024-04-26T14:30:57.977419Z INFO kernel: [ 6.038915] pci 0000:00:16.1: bridge window
[mem 0xf9b00000-0xf9bffffff 64bit pref]
2024-04-26T14:30:57.977421Z INFO kernel: [ 6.041197] pci 0000:00:16.2: PCI bridge to
[bus 0d]
2024-04-26T14:30:57.977422Z INFO kernel: [ 6.042599] pci 0000:00:16.2: bridge window
[mem 0xfe000000-0xfe0ffffff]
2024-04-26T14:30:57.977424Z INFO kernel: [ 6.044609] pci 0000:00:16.2: bridge window
[mem 0xf9a00000-0xf9affffff 64bit pref]
2024-04-26T14:30:57.977426Z INFO kernel: [ 6.046990] pci 0000:00:16.3: PCI bridge to
[bus 0e]
2024-04-26T14:30:57.977428Z INFO kernel: [ 6.048508] pci 0000:00:16.3: bridge window
[mem 0xfdff0000-0xfdffffff]
2024-04-26T14:30:57.977430Z INFO kernel: [ 6.050471] pci 0000:00:16.3: bridge window
[mem 0xf9900000-0xf99ffffff 64bit pref]
2024-04-26T14:30:57.977431Z INFO kernel: [ 6.052836] pci 0000:00:16.4: PCI bridge to
```

```
[bus 0f]
2024-04-26T14:30:57.977433Z INFO kernel: [ 6.054835] pci 0000:00:16.4: bridge window
[mem 0xfde00000-0xfdeffffff]
2024-04-26T14:30:57.977435Z INFO kernel: [ 6.056804] pci 0000:00:16.4: bridge window
[mem 0xf9800000-0xf98ffffff 64bit pref]
2024-04-26T14:30:57.977436Z INFO kernel: [ 6.059250] pci 0000:00:16.5: PCI bridge to
[bus 10]
2024-04-26T14:30:57.977438Z INFO kernel: [ 6.060731] pci 0000:00:16.5: bridge window
[mem 0xfdd00000-0xfddffffff]
2024-04-26T14:30:57.977439Z INFO kernel: [ 6.063021] pci 0000:00:16.5: bridge window
[mem 0xf9700000-0xf97ffffff 64bit pref]
2024-04-26T14:30:57.977441Z INFO kernel: [ 6.065240] pci 0000:00:16.6: PCI bridge to
[bus 11]
2024-04-26T14:30:57.977443Z INFO kernel: [ 6.066672] pci 0000:00:16.6: bridge window
[mem 0xfdc00000-0xfdcffffff]
2024-04-26T14:30:57.977444Z INFO kernel: [ 6.068631] pci 0000:00:16.6: bridge window
[mem 0xf9600000-0xf96ffffff 64bit pref]
2024-04-26T14:30:57.977446Z INFO kernel: [ 6.071477] pci 0000:00:16.7: PCI bridge to
[bus 12]
2024-04-26T14:30:57.977448Z INFO kernel: [ 6.072941] pci 0000:00:16.7: bridge window
[mem 0xfdb00000-0xfdbffffff]
2024-04-26T14:30:57.977449Z INFO kernel: [ 6.074944] pci 0000:00:16.7: bridge window
[mem 0xf9500000-0xf95ffffff 64bit pref]
2024-04-26T14:30:57.977451Z INFO kernel: [ 6.077212] pci 0000:00:17.0: PCI bridge to
[bus 13]
2024-04-26T14:30:57.977453Z INFO kernel: [ 6.078720] pci 0000:00:17.0: bridge window
[mem 0xfda00000-0xfdaffffff]
2024-04-26T14:30:57.977454Z INFO kernel: [ 6.081048] pci 0000:00:17.0: bridge window
[mem 0xf9400000-0xf94ffffff 64bit pref]
2024-04-26T14:30:57.977456Z INFO kernel: [ 6.083621] pci 0000:00:17.1: PCI bridge to
[bus 14]
2024-04-26T14:30:57.977458Z INFO kernel: [ 6.085109] pci 0000:00:17.1: bridge window
[mem 0xfd900000-0xfd9ffffff]
2024-04-26T14:30:57.977459Z INFO kernel: [ 6.087217] pci 0000:00:17.1: bridge window
[mem 0xf9300000-0xf93ffffff 64bit pref]
2024-04-26T14:30:57.977461Z INFO kernel: [ 6.090058] pci 0000:00:17.2: PCI bridge to
[bus 15]
2024-04-26T14:30:57.977463Z INFO kernel: [ 6.091502] pci 0000:00:17.2: bridge window
[mem 0xfd800000-0xfd8ffffff]
2024-04-26T14:30:57.977464Z INFO kernel: [ 6.093666] pci 0000:00:17.2: bridge window
[mem 0xf9200000-0xf92ffffff 64bit pref]
2024-04-26T14:30:57.977466Z INFO kernel: [ 6.096125] pci 0000:00:17.3: PCI bridge to
[bus 16]
2024-04-26T14:30:57.977468Z INFO kernel: [ 6.097828] pci 0000:00:17.3: bridge window
[mem 0xfd700000-0xfd7ffffff]
2024-04-26T14:30:57.977469Z INFO kernel: [ 6.100061] pci 0000:00:17.3: bridge window
[mem 0xf9100000-0xf91ffffff 64bit pref]
2024-04-26T14:30:57.977471Z INFO kernel: [ 6.102326] pci 0000:00:17.4: PCI bridge to
[bus 17]
2024-04-26T14:30:57.977475Z INFO kernel: [ 6.103946] pci 0000:00:17.4: bridge window
[mem 0xfd600000-0xfd6ffffff]
2024-04-26T14:30:57.977477Z INFO kernel: [ 6.106195] pci 0000:00:17.4: bridge window
[mem 0xf9000000-0xf90ffffff 64bit pref]
2024-04-26T14:30:57.977479Z INFO kernel: [ 6.108819] pci 0000:00:17.5: PCI bridge to
[bus 18]
2024-04-26T14:30:57.977480Z INFO kernel: [ 6.110505] pci 0000:00:17.5: bridge window
[io 0xf000-0xffff]
2024-04-26T14:30:57.977482Z INFO kernel: [ 6.112556] pci 0000:00:17.5: bridge window
[mem 0xfd500000-0xfd5ffffff]
2024-04-26T14:30:57.977484Z INFO kernel: [ 6.114879] pci 0000:00:17.5: bridge window
[mem 0xf8f00000-0xf8fffffff 64bit pref]
2024-04-26T14:30:57.977485Z INFO kernel: [ 6.117844] pci 0000:00:17.6: PCI bridge to
[bus 19]
2024-04-26T14:30:57.977487Z INFO kernel: [ 6.119381] pci 0000:00:17.6: bridge window
[io 0xe000-0xefff]
2024-04-26T14:30:57.977488Z INFO kernel: [ 6.121326] pci 0000:00:17.6: bridge window
[mem 0xfd400000-0xfd4ffffff]
2024-04-26T14:30:57.977493Z INFO kernel: [ 6.123462] pci 0000:00:17.6: bridge window
[mem 0xf8e00000-0xf8effffff 64bit pref]
```

```
2024-04-26T14:30:57.977494Z INFO kernel: [ 6.125945] pci 0000:00:17.7: PCI bridge to
[bus 1a]
2024-04-26T14:30:57.977496Z INFO kernel: [ 6.127383] pci 0000:00:17.7: bridge window
[io 0xd000-0xdfff]
2024-04-26T14:30:57.977498Z INFO kernel: [ 6.129078] pci 0000:00:17.7: bridge window
[mem 0xfd300000-0xfd3fffffff]
2024-04-26T14:30:57.977500Z INFO kernel: [ 6.131032] pci 0000:00:17.7: bridge window
[mem 0xf8d00000-0xf8dfffffff 64bit pref]
2024-04-26T14:30:57.977501Z INFO kernel: [ 6.133746] pci 0000:00:18.0: PCI bridge to
[bus 1b]
2024-04-26T14:30:57.977503Z INFO kernel: [ 6.135170] pci 0000:00:18.0: bridge window
[io 0xc000-0xcfff]
2024-04-26T14:30:57.977505Z INFO kernel: [ 6.137364] pci 0000:00:18.0: bridge window
[mem 0xfd200000-0xfd2fffffff]
2024-04-26T14:30:57.977506Z INFO kernel: [ 6.139282] pci 0000:00:18.0: bridge window
[mem 0xf8c00000-0xf8cfffffff 64bit pref]
2024-04-26T14:30:57.977508Z INFO kernel: [ 6.141492] pci 0000:00:18.1: PCI bridge to
[bus 1c]
2024-04-26T14:30:57.977509Z INFO kernel: [ 6.142840] pci 0000:00:18.1: bridge window
[io 0xb000-0xbfff]
2024-04-26T14:30:57.977511Z INFO kernel: [ 6.144548] pci 0000:00:18.1: bridge window
[mem 0xfd100000-0xfd1fffffff]
2024-04-26T14:30:57.977513Z INFO kernel: [ 6.146395] pci 0000:00:18.1: bridge window
[mem 0xf8b00000-0xf8bfffffff 64bit pref]
2024-04-26T14:30:57.977514Z INFO kernel: [ 6.148716] pci 0000:00:18.2: PCI bridge to
[bus 1d]
2024-04-26T14:30:57.977516Z INFO kernel: [ 6.150657] pci 0000:00:18.2: bridge window
[io 0xa000-0xaaff]
2024-04-26T14:30:57.977518Z INFO kernel: [ 6.152691] pci 0000:00:18.2: bridge window
[mem 0xfd000000-0xfd0fffffff]
2024-04-26T14:30:57.977519Z INFO kernel: [ 6.154839] pci 0000:00:18.2: bridge window
[mem 0xf8a00000-0xf8afffff 64bit pref]
2024-04-26T14:30:57.977521Z INFO kernel: [ 6.157227] pci 0000:00:18.3: PCI bridge to
[bus 1e]
2024-04-26T14:30:57.977523Z INFO kernel: [ 6.158692] pci 0000:00:18.3: bridge window
[io 0x9000-0x9fff]
2024-04-26T14:30:57.977524Z INFO kernel: [ 6.160591] pci 0000:00:18.3: bridge window
[mem 0xfcf00000-0xfcffffffff]
2024-04-26T14:30:57.977526Z INFO kernel: [ 6.162614] pci 0000:00:18.3: bridge window
[mem 0xf8900000-0xf89fffffff 64bit pref]
2024-04-26T14:30:57.977527Z INFO kernel: [ 6.164933] pci 0000:00:18.4: PCI bridge to
[bus 1f]
2024-04-26T14:30:57.977529Z INFO kernel: [ 6.166390] pci 0000:00:18.4: bridge window
[io 0x8000-0x8fff]
2024-04-26T14:30:57.977531Z INFO kernel: [ 6.168954] pci 0000:00:18.4: bridge window
[mem 0xfce00000-0xfcefffffff]
2024-04-26T14:30:57.977532Z INFO kernel: [ 6.171143] pci 0000:00:18.4: bridge window
[mem 0xf8800000-0xf88fffffff 64bit pref]
2024-04-26T14:30:57.977534Z INFO kernel: [ 6.173579] pci 0000:00:18.5: PCI bridge to
[bus 20]
2024-04-26T14:30:57.977536Z INFO kernel: [ 6.175139] pci 0000:00:18.5: bridge window
[io 0x7000-0x7fff]
2024-04-26T14:30:57.977537Z INFO kernel: [ 6.177492] pci 0000:00:18.5: bridge window
[mem 0xfcd00000-0xfcdfffffff]
2024-04-26T14:30:57.977539Z INFO kernel: [ 6.179904] pci 0000:00:18.5: bridge window
[mem 0xf8700000-0xf87fffffff 64bit pref]
2024-04-26T14:30:57.977541Z INFO kernel: [ 6.182666] pci 0000:00:18.6: PCI bridge to
[bus 21]
2024-04-26T14:30:57.977542Z INFO kernel: [ 6.184673] pci 0000:00:18.6: bridge window
[io 0x6000-0x6fff]
2024-04-26T14:30:57.977544Z INFO kernel: [ 6.187094] pci 0000:00:18.6: bridge window
[mem 0xfcc00000-0xfccfffffff]
2024-04-26T14:30:57.977545Z INFO kernel: [ 6.189438] pci 0000:00:18.6: bridge window
[mem 0xf8600000-0xf86fffffff 64bit pref]
2024-04-26T14:30:57.977547Z INFO kernel: [ 6.191732] pci 0000:00:18.7: PCI bridge to
[bus 22]
2024-04-26T14:30:57.977551Z INFO kernel: [ 6.193493] pci 0000:00:18.7: bridge window
[io 0x4000-0x4fff]
2024-04-26T14:30:57.977553Z INFO kernel: [ 6.195405] pci 0000:00:18.7: bridge window
```

```
[mem 0xfcb00000-0xfcbfffff]
2024-04-26T14:30:57.977554Z INFO kernel: [ 6.197367] pci 0000:00:18.7: bridge window
[mem 0xf8500000-0xf85fffff 64bit pref]
2024-04-26T14:30:57.977556Z INFO kernel: [ 6.199700] pci_bus 0000:00: resource 4 [io
0x0d00-0xffff window]
2024-04-26T14:30:57.977558Z INFO kernel: [ 6.201391] pci_bus 0000:00: resource 5 [io
0x0000-0x0cf7 window]
2024-04-26T14:30:57.977560Z INFO kernel: [ 6.203241] pci_bus 0000:00: resource 6 [mem
0xfef00000-0xffdfffff window]
2024-04-26T14:30:57.977561Z INFO kernel: [ 6.205141] pci_bus 0000:00: resource 7 [mem
0xfed45000-0xfedfffff window]
2024-04-26T14:30:57.977563Z INFO kernel: [ 6.207030] pci_bus 0000:00: resource 8 [mem
0xfec10000-0xfed3ffff window]
2024-04-26T14:30:57.977565Z INFO kernel: [ 6.209015] pci_bus 0000:00: resource 9 [mem
0xfa400000-0xfebfffff window]
2024-04-26T14:30:57.977566Z INFO kernel: [ 6.210943] pci_bus 0000:00: resource 10 [mem
0xf0000000-0xfa3fffff pref window]
2024-04-26T14:30:57.977568Z INFO kernel: [ 6.213040] pci_bus 0000:00: resource 11 [mem
0xc0000000-0xefffffff window]
2024-04-26T14:30:57.977570Z INFO kernel: [ 6.215001] pci_bus 0000:00: resource 12 [mem
0x000a0000-0x000bffff window]
2024-04-26T14:30:57.977571Z INFO kernel: [ 6.216987] pci_bus 0000:00: resource 13 [mem
0x000c4000-0x000c7fff window]
2024-04-26T14:30:57.977573Z INFO kernel: [ 6.219026] pci_bus 0000:00: resource 14 [mem
0x000c8000-0x000cbfff window]
2024-04-26T14:30:57.977575Z INFO kernel: [ 6.221167] pci_bus 0000:00: resource 15 [mem
0x000d4000-0x000d7fff window]
2024-04-26T14:30:57.977576Z INFO kernel: [ 6.223148] pci_bus 0000:00: resource 16 [mem
0x000d8000-0x000dbfff window]
2024-04-26T14:30:57.977578Z INFO kernel: [ 6.225125] pci_bus 0000:00: resource 17 [mem
0x000e4000-0x000e7fff window]
2024-04-26T14:30:57.977580Z INFO kernel: [ 6.227095] pci_bus 0000:00: resource 18 [mem
0x000e8000-0x000ebfff window]
2024-04-26T14:30:57.977581Z INFO kernel: [ 6.229560] pci_bus 0000:00: resource 19 [mem
0x000ec000-0x000effff window]
2024-04-26T14:30:57.977583Z INFO kernel: [ 6.231744] pci_bus 0000:02: resource 0 [io
0x1000-0x1fff]
2024-04-26T14:30:57.977585Z INFO kernel: [ 6.233294] pci_bus 0000:02: resource 1 [mem
0xfc000000-0xfc9fffff]
2024-04-26T14:30:57.977586Z INFO kernel: [ 6.235007] pci_bus 0000:02: resource 2 [mem
0xf8000000-0xf84fffff 64bit pref]
2024-04-26T14:30:57.977588Z INFO kernel: [ 6.237323] pci_bus 0000:02: resource 4 [io
0x0d00-0xffff window]
2024-04-26T14:30:57.977731Z INFO kernel: [ 6.239158] pci_bus 0000:02: resource 5 [io
0x0000-0x0cf7 window]
2024-04-26T14:30:57.977735Z INFO kernel: [ 6.240862] pci_bus 0000:02: resource 6 [mem
0xfef00000-0xffdfffff window]
2024-04-26T14:30:57.977737Z INFO kernel: [ 6.242741] pci_bus 0000:02: resource 7 [mem
0xfed45000-0xfedfffff window]
2024-04-26T14:30:57.977738Z INFO kernel: [ 6.244639] pci_bus 0000:02: resource 8 [mem
0xfec10000-0xfed3ffff window]
2024-04-26T14:30:57.977740Z INFO kernel: [ 6.247478] pci_bus 0000:02: resource 9 [mem
0xfa400000-0xfebfffff window]
2024-04-26T14:30:57.977741Z INFO kernel: [ 6.249470] pci_bus 0000:02: resource 10 [mem
0xf0000000-0xfa3fffff pref window]
2024-04-26T14:30:57.977743Z INFO kernel: [ 6.251643] pci_bus 0000:02: resource 11 [mem
0xc0000000-0xefffffff window]
2024-04-26T14:30:57.977745Z INFO kernel: [ 6.253733] pci_bus 0000:02: resource 12 [mem
0x000a0000-0x000bffff window]
2024-04-26T14:30:57.977746Z INFO kernel: [ 6.256992] pci_bus 0000:02: resource 13 [mem
0x000c4000-0x000c7fff window]
2024-04-26T14:30:57.977748Z INFO kernel: [ 6.258868] pci_bus 0000:02: resource 14 [mem
0x000c8000-0x000cbfff window]
2024-04-26T14:30:57.977750Z INFO kernel: [ 6.261237] pci_bus 0000:02: resource 15 [mem
0x000d4000-0x000d7fff window]
2024-04-26T14:30:57.977751Z INFO kernel: [ 6.263418] pci_bus 0000:02: resource 16 [mem
0x000d8000-0x000dbfff window]
2024-04-26T14:30:57.977753Z INFO kernel: [ 6.265576] pci_bus 0000:02: resource 17 [mem
0x000e4000-0x000e7fff window]
```

```
2024-04-26T14:30:57.977755Z INFO kernel: [ 6.267585] pci_bus 0000:02: resource 18 [mem
0x000e8000-0x000ebfff window]
2024-04-26T14:30:57.977756Z INFO kernel: [ 6.269584] pci_bus 0000:02: resource 19 [mem
0x000ec000-0x000effff window]
2024-04-26T14:30:57.977758Z INFO kernel: [ 6.271861] pci_bus 0000:03: resource 0 [io
0x3000-0x3fff]
2024-04-26T14:30:57.977759Z INFO kernel: [ 6.273562] pci_bus 0000:03: resource 1 [mem
0xfea00000-0xfeafffff]
2024-04-26T14:30:57.977761Z INFO kernel: [ 6.275289] pci_bus 0000:03: resource 2 [mem
0xfef00000-0xff0fffff 64bit pref]
2024-04-26T14:30:57.977763Z INFO kernel: [ 6.277250] pci_bus 0000:04: resource 1 [mem
0xfe900000-0xfe9fffff]
2024-04-26T14:30:57.977764Z INFO kernel: [ 6.278945] pci_bus 0000:04: resource 2 [mem
0xfa300000-0xfa3fffff 64bit pref]
2024-04-26T14:30:57.977766Z INFO kernel: [ 6.281202] pci_bus 0000:05: resource 1 [mem
0xfe800000-0xfe8fffff]
2024-04-26T14:30:57.977768Z INFO kernel: [ 6.283381] pci_bus 0000:05: resource 2 [mem
0xfa200000-0xfa2fffff 64bit pref]
2024-04-26T14:30:57.977769Z INFO kernel: [ 6.285581] pci_bus 0000:06: resource 1 [mem
0xfe700000-0xfe7fffff]
2024-04-26T14:30:57.977771Z INFO kernel: [ 6.287352] pci_bus 0000:06: resource 2 [mem
0xfa100000-0xfa1fffff 64bit pref]
2024-04-26T14:30:57.977773Z INFO kernel: [ 6.289673] pci_bus 0000:07: resource 1 [mem
0xfe600000-0xfe6fffff]
2024-04-26T14:30:57.977774Z INFO kernel: [ 6.292029] pci_bus 0000:07: resource 2 [mem
0xfa000000-0xfa0fffff 64bit pref]
2024-04-26T14:30:57.977776Z INFO kernel: [ 6.294755] pci_bus 0000:08: resource 1 [mem
0xfe500000-0xfe5fffff]
2024-04-26T14:30:57.977778Z INFO kernel: [ 6.296527] pci_bus 0000:08: resource 2 [mem
0xf9f00000-0xf9fffff 64bit pref]
2024-04-26T14:30:57.977779Z INFO kernel: [ 6.298608] pci_bus 0000:09: resource 1 [mem
0xfe400000-0xfe4fffff]
2024-04-26T14:30:57.977781Z INFO kernel: [ 6.300483] pci_bus 0000:09: resource 2 [mem
0xf9e00000-0xf9efffff 64bit pref]
2024-04-26T14:30:57.977782Z INFO kernel: [ 6.302606] pci_bus 0000:0a: resource 1 [mem
0xfe300000-0xfe3fffff]
2024-04-26T14:30:57.977784Z INFO kernel: [ 6.304368] pci_bus 0000:0a: resource 2 [mem
0xf9d00000-0xf9dfffff 64bit pref]
2024-04-26T14:30:57.977786Z INFO kernel: [ 6.306327] pci_bus 0000:0b: resource 1 [mem
0xfe200000-0xfe2fffff]
2024-04-26T14:30:57.977789Z INFO kernel: [ 6.308593] pci_bus 0000:0b: resource 2 [mem
0xf9c00000-0xf9cfffff 64bit pref]
2024-04-26T14:30:57.977791Z INFO kernel: [ 6.310609] pci_bus 0000:0c: resource 1 [mem
0xfe100000-0xfe1fffff]
2024-04-26T14:30:57.977793Z INFO kernel: [ 6.312386] pci_bus 0000:0c: resource 2 [mem
0xf9b00000-0xf9bfffff 64bit pref]
2024-04-26T14:30:57.977794Z INFO kernel: [ 6.314399] pci_bus 0000:0d: resource 1 [mem
0xfe000000-0xfe0fffff]
2024-04-26T14:30:57.977796Z INFO kernel: [ 6.316219] pci_bus 0000:0d: resource 2 [mem
0xf9a00000-0xf9afffff 64bit pref]
2024-04-26T14:30:57.977798Z INFO kernel: [ 6.318253] pci_bus 0000:0e: resource 1 [mem
0xfd000000-0xfd0fffff]
2024-04-26T14:30:57.977799Z INFO kernel: [ 6.320032] pci_bus 0000:0e: resource 2 [mem
0xf9900000-0xf99fffff 64bit pref]
2024-04-26T14:30:57.977801Z INFO kernel: [ 6.321983] pci_bus 0000:0f: resource 1 [mem
0xfde00000-0xfdefffff]
2024-04-26T14:30:57.977803Z INFO kernel: [ 6.323736] pci_bus 0000:0f: resource 2 [mem
0xf9800000-0xf98fffff 64bit pref]
2024-04-26T14:30:57.977804Z INFO kernel: [ 6.325980] pci_bus 0000:10: resource 1 [mem
0xfdd00000-0xfddfffff]
2024-04-26T14:30:57.977806Z INFO kernel: [ 6.327750] pci_bus 0000:10: resource 2 [mem
0xf9700000-0xf97fffff 64bit pref]
2024-04-26T14:30:57.977807Z INFO kernel: [ 6.329806] pci_bus 0000:11: resource 1 [mem
0xfdc00000-0xfdcfffff]
2024-04-26T14:30:57.977809Z INFO kernel: [ 6.331753] pci_bus 0000:11: resource 2 [mem
0xf9600000-0xf96fffff 64bit pref]
2024-04-26T14:30:57.977811Z INFO kernel: [ 6.334028] pci_bus 0000:12: resource 1 [mem
0xfdb00000-0xfdbfffff]
2024-04-26T14:30:57.977817Z INFO kernel: [ 6.335783] pci_bus 0000:12: resource 2 [mem
```



```
0xf9500000-0xf95fffff 64bit pref]
2024-04-26T14:30:57.977819Z INFO kernel: [ 6.337877] pci_bus 0000:13: resource 1 [mem
0xfda00000-0xfdafffff]
2024-04-26T14:30:57.977820Z INFO kernel: [ 6.339658] pci_bus 0000:13: resource 2 [mem
0xf9400000-0xf94fffff 64bit pref]
2024-04-26T14:30:57.977822Z INFO kernel: [ 6.341903] pci_bus 0000:14: resource 1 [mem
0xfd900000-0xfd9fffff]
2024-04-26T14:30:57.977823Z INFO kernel: [ 6.343692] pci_bus 0000:14: resource 2 [mem
0xf9300000-0xf93fffff 64bit pref]
2024-04-26T14:30:57.977825Z INFO kernel: [ 6.345788] pci_bus 0000:15: resource 1 [mem
0xfd800000-0xfd8fffff]
2024-04-26T14:30:57.977827Z INFO kernel: [ 6.347601] pci_bus 0000:15: resource 2 [mem
0xf9200000-0xf92fffff 64bit pref]
2024-04-26T14:30:57.977828Z INFO kernel: [ 6.349752] pci_bus 0000:16: resource 1 [mem
0xfd700000-0xfd7fffff]
2024-04-26T14:30:57.977830Z INFO kernel: [ 6.351634] pci_bus 0000:16: resource 2 [mem
0xf9100000-0xf91fffff 64bit pref]
2024-04-26T14:30:57.977831Z INFO kernel: [ 6.353618] pci_bus 0000:17: resource 1 [mem
0xfd600000-0xfd6fffff]
2024-04-26T14:30:57.977833Z INFO kernel: [ 6.355543] pci_bus 0000:17: resource 2 [mem
0xf9000000-0xf90fffff 64bit pref]
2024-04-26T14:30:57.977835Z INFO kernel: [ 6.357778] pci_bus 0000:18: resource 0 [io
0xf000-0xffff]
2024-04-26T14:30:57.977836Z INFO kernel: [ 6.359566] pci_bus 0000:18: resource 1 [mem
0xfd500000-0xfd5fffff]
2024-04-26T14:30:57.977838Z INFO kernel: [ 6.361523] pci_bus 0000:18: resource 2 [mem
0xf8f00000-0xf8fffff 64bit pref]
2024-04-26T14:30:57.977840Z INFO kernel: [ 6.363587] pci_bus 0000:19: resource 0 [io
0xe000-0xefff]
2024-04-26T14:30:57.977841Z INFO kernel: [ 6.365162] pci_bus 0000:19: resource 1 [mem
0xfd400000-0xfd4fffff]
2024-04-26T14:30:57.977843Z INFO kernel: [ 6.366912] pci_bus 0000:19: resource 2 [mem
0xf8e00000-0xf8efffff 64bit pref]
2024-04-26T14:30:57.977844Z INFO kernel: [ 6.369103] pci_bus 0000:1a: resource 0 [io
0xd000-0xdfff]
2024-04-26T14:30:57.977846Z INFO kernel: [ 6.370710] pci_bus 0000:1a: resource 1 [mem
0xfd300000-0xfd3fffff]
2024-04-26T14:30:57.977848Z INFO kernel: [ 6.372480] pci_bus 0000:1a: resource 2 [mem
0xf8d00000-0xf8dfffff 64bit pref]
2024-04-26T14:30:57.977849Z INFO kernel: [ 6.374480] pci_bus 0000:1b: resource 0 [io
0xc000-0xcfff]
2024-04-26T14:30:57.977851Z INFO kernel: [ 6.376003] pci_bus 0000:1b: resource 1 [mem
0xfd200000-0xfd2fffff]
2024-04-26T14:30:57.977852Z INFO kernel: [ 6.377809] pci_bus 0000:1b: resource 2 [mem
0xf8c00000-0xf8cfffff 64bit pref]
2024-04-26T14:30:57.977854Z INFO kernel: [ 6.379854] pci_bus 0000:1c: resource 0 [io
0xb000-0xbfff]
2024-04-26T14:30:57.977856Z INFO kernel: [ 6.381340] pci_bus 0000:1c: resource 1 [mem
0xfd100000-0xfd1fffff]
2024-04-26T14:30:57.977857Z INFO kernel: [ 6.383326] pci_bus 0000:1c: resource 2 [mem
0xf8b00000-0xf8bfffff 64bit pref]
2024-04-26T14:30:57.977859Z INFO kernel: [ 6.385536] pci_bus 0000:1d: resource 0 [io
0xa000-0xafff]
2024-04-26T14:30:57.977861Z INFO kernel: [ 6.387201] pci_bus 0000:1d: resource 1 [mem
0xfd000000-0xfd0fffff]
2024-04-26T14:30:57.977862Z INFO kernel: [ 6.388940] pci_bus 0000:1d: resource 2 [mem
0xf8a00000-0xf8afffff 64bit pref]
2024-04-26T14:30:57.977864Z INFO kernel: [ 6.390952] pci_bus 0000:1e: resource 0 [io
0x9000-0x9fff]
2024-04-26T14:30:57.977865Z INFO kernel: [ 6.392491] pci_bus 0000:1e: resource 1 [mem
0xfc000000-0xfc0fffff]
2024-04-26T14:30:57.977867Z INFO kernel: [ 6.394211] pci_bus 0000:1e: resource 2 [mem
0xf8900000-0xf89fffff 64bit pref]
2024-04-26T14:30:57.977869Z INFO kernel: [ 6.396375] pci_bus 0000:1f: resource 0 [io
0x8000-0x8fff]
2024-04-26T14:30:57.977870Z INFO kernel: [ 6.397947] pci_bus 0000:1f: resource 1 [mem
0xfce00000-0xfcefffff]
2024-04-26T14:30:57.977872Z INFO kernel: [ 6.399686] pci_bus 0000:1f: resource 2 [mem
0xf8800000-0xf88fffff 64bit pref]
```

```

2024-04-26T14:30:57.977874Z INFO kernel: [ 6.401712] pci_bus 0000:20: resource 0 [io
0x7000-0x7fff]
2024-04-26T14:30:57.977875Z INFO kernel: [ 6.403437] pci_bus 0000:20: resource 1 [mem
0xfcd00000-0xfcdfffff]
2024-04-26T14:30:57.977877Z INFO kernel: [ 6.405216] pci_bus 0000:20: resource 2 [mem
0xf8700000-0xf87fffff 64bit pref]
2024-04-26T14:30:57.977879Z INFO kernel: [ 6.407205] pci_bus 0000:21: resource 0 [io
0x6000-0x6fff]
2024-04-26T14:30:57.977880Z INFO kernel: [ 6.408718] pci_bus 0000:21: resource 1 [mem
0xfcc00000-0xfccfffff]
2024-04-26T14:30:57.977882Z INFO kernel: [ 6.410429] pci_bus 0000:21: resource 2 [mem
0xf8600000-0xf86fffff 64bit pref]
2024-04-26T14:30:57.977883Z INFO kernel: [ 6.412354] pci_bus 0000:22: resource 0 [io
0x4000-0x4fff]
2024-04-26T14:30:57.977885Z INFO kernel: [ 6.413969] pci_bus 0000:22: resource 1 [mem
0xfcb00000-0xfcbfffff]
2024-04-26T14:30:57.977887Z INFO kernel: [ 6.415610] pci_bus 0000:22: resource 2 [mem
0xf8500000-0xf85fffff 64bit pref]
2024-04-26T14:30:57.977888Z INFO kernel: [ 6.417769] pci 0000:00:00.0: Limiting direct
PCI/PCI transfers
2024-04-26T14:30:57.977890Z INFO kernel: [ 6.424090] pci 0000:02:01.0: CLS mismatch
(32 != 64), using 64 bytes
2024-04-26T14:30:57.977892Z INFO kernel: [ 6.429051] PCI-DMA: Using software bounce
buffering for IO (SWIOTLB)
2024-04-26T14:30:57.977893Z INFO kernel: [ 6.431765] software IO TLB: mapped [mem
0x00000000bc000000-0x00000000c0000000] (64MB)
2024-04-26T14:30:57.977895Z INFO kernel: [ 6.435295] ACPI: bus type thunderbolt
registered
2024-04-26T14:30:57.977897Z INFO kernel: [ 6.442046] RAPL PMU: API unit is 2^-32
Joules, 0 fixed counters, 10737418240 ms ovfl timer
2024-04-26T14:30:57.977898Z ERR kernel: [ 6.446137] kvm: no hardware support
2024-04-26T14:30:57.977899Z INFO kernel: [ 6.447241] has_svm: not amd or hygon
2024-04-26T14:30:57.977901Z ERR kernel: [ 6.449140] kvm: no hardware support
2024-04-26T14:30:57.977902Z INFO kernel: [ 6.450381] clocksource: tsc: mask:
0xffffffffffffffff max_cycles: 0x172da94f0e2, max_idle_ns: 440795278248 ns
2024-04-26T14:30:57.977905Z INFO kernel: [ 6.460851] clocksource: Switched to
clocksource tsc
2024-04-26T14:30:57.977907Z INFO kernel: [ 6.471309] workingset: timestamp_bits=62
max_order=21 bucket_order=0
2024-04-26T14:30:57.977910Z INFO kernel: [ 6.479361] squashfs: version 4.0
(2009/01/31) Phillip Lougher
2024-04-26T14:30:57.977912Z INFO kernel: [ 6.481759] Registering esdfs 0.2
2024-04-26T14:30:57.978130Z INFO kernel: [ 6.483015] alt_syscall: table
'read_write_test' available.
2024-04-26T14:30:57.988265Z INFO kernel: [ 6.484717] alt_syscall: table 'android'
available.
2024-04-26T14:30:57.988278Z INFO kernel: [ 6.486613] alt_syscall: table
'android_permissive' available.
2024-04-26T14:30:57.988281Z INFO kernel: [ 6.488178] alt_syscall: table 'third_party'
available.
2024-04-26T14:30:57.988284Z INFO kernel: [ 6.489575] alt_syscall: table
'third_party_permissive' available.
2024-04-26T14:30:57.988286Z INFO kernel: [ 6.491183] alt_syscall: table 'complete'
available.
2024-04-26T14:30:57.988288Z INFO kernel: [ 6.493102] alt_syscall: table
'complete_permissive' available.
2024-04-26T14:30:57.988290Z INFO kernel: [ 6.505280] Block layer SCSI generic (bsg)
driver version 0.4 loaded (major 248)
2024-04-26T14:30:57.988293Z INFO kernel: [ 6.507361] io scheduler mq-deadline
registered
2024-04-26T14:30:57.988296Z INFO kernel: [ 6.508597] io scheduler kyber registered
2024-04-26T14:30:57.988298Z INFO kernel: [ 6.509831] io scheduler bfq registered
2024-04-26T14:30:57.988301Z INFO kernel: [ 6.512222] pci 0000:00:01.0: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988304Z INFO kernel: [ 6.514347] pci 0000:00:11.0: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988307Z INFO kernel: [ 6.516477] pci 0000:00:15.0: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988310Z INFO kernel: [ 6.520571] pcieport 0000:00:15.0: PME:

```

Signaling with IRQ 24

2024-04-26T14:30:57.988312Z INFO kernel: [6.522404] pcieport 0000:00:15.0: pciehp: Slot #160 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+

2024-04-26T14:30:57.988316Z INFO kernel: [6.528138] pci 0000:00:15.1: attach allowed to drvr pcieport [internal device]

2024-04-26T14:30:57.988318Z INFO kernel: [6.530751] pcieport 0000:00:15.1: PME:

Signaling with IRQ 25

2024-04-26T14:30:57.988321Z INFO kernel: [6.532962] pcieport 0000:00:15.1: pciehp: Slot #161 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+

2024-04-26T14:30:57.988324Z INFO kernel: [6.538165] pci 0000:00:15.2: attach allowed to drvr pcieport [internal device]

2024-04-26T14:30:57.988326Z INFO kernel: [6.540683] pcieport 0000:00:15.2: PME:

Signaling with IRQ 26

2024-04-26T14:30:57.988329Z INFO kernel: [6.542001] pcieport 0000:00:15.2: pciehp: Slot #162 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+

2024-04-26T14:30:57.988332Z INFO kernel: [6.546210] pci 0000:00:15.3: attach allowed to drvr pcieport [internal device]

2024-04-26T14:30:57.988335Z INFO kernel: [6.549724] pcieport 0000:00:15.3: PME:

Signaling with IRQ 27

2024-04-26T14:30:57.988338Z INFO kernel: [6.551705] pcieport 0000:00:15.3: pciehp: Slot #163 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+

2024-04-26T14:30:57.988341Z INFO kernel: [6.557522] pci 0000:00:15.4: attach allowed to drvr pcieport [internal device]

2024-04-26T14:30:57.988343Z INFO kernel: [6.560058] pcieport 0000:00:15.4: PME:

Signaling with IRQ 28

2024-04-26T14:30:57.988345Z INFO kernel: [6.562122] pcieport 0000:00:15.4: pciehp: Slot #164 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+

2024-04-26T14:30:57.988349Z INFO kernel: [6.567111] pci 0000:00:15.5: attach allowed to drvr pcieport [internal device]

2024-04-26T14:30:57.988351Z INFO kernel: [6.570262] pcieport 0000:00:15.5: PME:

Signaling with IRQ 29

2024-04-26T14:30:57.988354Z INFO kernel: [6.572287] pcieport 0000:00:15.5: pciehp: Slot #165 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+

2024-04-26T14:30:57.988356Z INFO kernel: [6.577415] pci 0000:00:15.6: attach allowed to drvr pcieport [internal device]

2024-04-26T14:30:57.988359Z INFO kernel: [6.581808] pcieport 0000:00:15.6: PME:

Signaling with IRQ 30

2024-04-26T14:30:57.988362Z INFO kernel: [6.583560] pcieport 0000:00:15.6: pciehp: Slot #166 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+

2024-04-26T14:30:57.988365Z INFO kernel: [6.589380] pci 0000:00:15.7: attach allowed to drvr pcieport [internal device]

2024-04-26T14:30:57.988367Z INFO kernel: [6.592790] pcieport 0000:00:15.7: PME:

Signaling with IRQ 31

2024-04-26T14:30:57.988370Z INFO kernel: [6.594599] pcieport 0000:00:15.7: pciehp: Slot #167 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+

2024-04-26T14:30:57.988373Z INFO kernel: [6.601125] pci 0000:00:16.0: attach allowed to drvr pcieport [internal device]

2024-04-26T14:30:57.988375Z INFO kernel: [6.604975] pcieport 0000:00:16.0: PME:

Signaling with IRQ 32

2024-04-26T14:30:57.988378Z INFO kernel: [6.608008] pcieport 0000:00:16.0: pciehp: Slot #192 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+

2024-04-26T14:30:57.988381Z INFO kernel: [6.613871] pci 0000:00:16.1: attach allowed to drvr pcieport [internal device]

2024-04-26T14:30:57.988384Z INFO kernel: [6.617246] pcieport 0000:00:16.1: PME:

Signaling with IRQ 33

2024-04-26T14:30:57.988386Z INFO kernel: [6.618996] pcieport 0000:00:16.1: pciehp: Slot #193 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+

2024-04-26T14:30:57.988389Z INFO kernel: [6.627600] pci 0000:00:16.2: attach allowed to drvr pcieport [internal device]

```
2024-04-26T14:30:57.988392Z INFO kernel: [ 6.630988] pcieport 0000:00:16.2: PME:
Signaling with IRQ 34
2024-04-26T14:30:57.988394Z INFO kernel: [ 6.632929] pcieport 0000:00:16.2: pciehp:
Slot #194 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988397Z INFO kernel: [ 6.643750] pci 0000:00:16.3: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988400Z INFO kernel: [ 6.647407] pcieport 0000:00:16.3: PME:
Signaling with IRQ 35
2024-04-26T14:30:57.988403Z INFO kernel: [ 6.650108] pcieport 0000:00:16.3: pciehp:
Slot #195 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988406Z INFO kernel: [ 6.657633] pci 0000:00:16.4: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988408Z INFO kernel: [ 6.661341] pcieport 0000:00:16.4: PME:
Signaling with IRQ 36
2024-04-26T14:30:57.988411Z INFO kernel: [ 6.663252] pcieport 0000:00:16.4: pciehp:
Slot #196 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988413Z INFO kernel: [ 6.669287] pci 0000:00:16.5: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988417Z INFO kernel: [ 6.672908] pcieport 0000:00:16.5: PME:
Signaling with IRQ 37
2024-04-26T14:30:57.988419Z INFO kernel: [ 6.675020] pcieport 0000:00:16.5: pciehp:
Slot #197 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988422Z INFO kernel: [ 6.680537] pci 0000:00:16.6: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988424Z INFO kernel: [ 6.683909] pcieport 0000:00:16.6: PME:
Signaling with IRQ 38
2024-04-26T14:30:57.988427Z INFO kernel: [ 6.686019] pcieport 0000:00:16.6: pciehp:
Slot #198 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988430Z INFO kernel: [ 6.692959] pci 0000:00:16.7: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988434Z INFO kernel: [ 6.696460] pcieport 0000:00:16.7: PME:
Signaling with IRQ 39
2024-04-26T14:30:57.988436Z INFO kernel: [ 6.697845] pcieport 0000:00:16.7: pciehp:
Slot #199 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988439Z INFO kernel: [ 6.704195] pci 0000:00:17.0: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988441Z INFO kernel: [ 6.708208] pcieport 0000:00:17.0: PME:
Signaling with IRQ 40
2024-04-26T14:30:57.988444Z INFO kernel: [ 6.710909] pcieport 0000:00:17.0: pciehp:
Slot #224 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988447Z INFO kernel: [ 6.715327] pci 0000:00:17.1: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988449Z INFO kernel: [ 6.718386] pcieport 0000:00:17.1: PME:
Signaling with IRQ 41
2024-04-26T14:30:57.988452Z INFO kernel: [ 6.720666] pcieport 0000:00:17.1: pciehp:
Slot #225 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988454Z INFO kernel: [ 6.724758] pci 0000:00:17.2: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988457Z INFO kernel: [ 6.727611] pcieport 0000:00:17.2: PME:
Signaling with IRQ 42
2024-04-26T14:30:57.988460Z INFO kernel: [ 6.728944] pcieport 0000:00:17.2: pciehp:
Slot #226 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988462Z INFO kernel: [ 6.733399] pci 0000:00:17.3: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988465Z INFO kernel: [ 6.736934] pcieport 0000:00:17.3: PME:
Signaling with IRQ 43
2024-04-26T14:30:57.988468Z INFO kernel: [ 6.738773] pcieport 0000:00:17.3: pciehp:
Slot #227 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988471Z INFO kernel: [ 6.744036] pci 0000:00:17.4: attach allowed
```

```
to drvr pcieport [internal device]
2024-04-26T14:30:57.988473Z INFO kernel: [ 6.747707] pcieport 0000:00:17.4: PME:
Signaling with IRQ 44
2024-04-26T14:30:57.988476Z INFO kernel: [ 6.749861] pcieport 0000:00:17.4: pciehp:
Slot #228 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988479Z INFO kernel: [ 6.761594] pci 0000:00:17.5: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988481Z INFO kernel: [ 6.765490] pcieport 0000:00:17.5: PME:
Signaling with IRQ 45
2024-04-26T14:30:57.988484Z INFO kernel: [ 6.767316] pcieport 0000:00:17.5: pciehp:
Slot #229 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988487Z INFO kernel: [ 6.772797] pci 0000:00:17.6: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988489Z INFO kernel: [ 6.776258] pcieport 0000:00:17.6: PME:
Signaling with IRQ 46
2024-04-26T14:30:57.988492Z INFO kernel: [ 6.778568] pcieport 0000:00:17.6: pciehp:
Slot #230 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988663Z INFO kernel: [ 6.787802] pci 0000:00:17.7: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988670Z INFO kernel: [ 6.791477] pcieport 0000:00:17.7: PME:
Signaling with IRQ 47
2024-04-26T14:30:57.988672Z INFO kernel: [ 6.793395] pcieport 0000:00:17.7: pciehp:
Slot #231 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988675Z INFO kernel: [ 6.799652] pci 0000:00:18.0: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988677Z INFO kernel: [ 6.803459] pcieport 0000:00:18.0: PME:
Signaling with IRQ 48
2024-04-26T14:30:57.988679Z INFO kernel: [ 6.805825] pcieport 0000:00:18.0: pciehp:
Slot #256 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988681Z INFO kernel: [ 6.811755] pci 0000:00:18.1: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988684Z INFO kernel: [ 6.815842] pcieport 0000:00:18.1: PME:
Signaling with IRQ 49
2024-04-26T14:30:57.988686Z INFO kernel: [ 6.818301] pcieport 0000:00:18.1: pciehp:
Slot #257 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988688Z INFO kernel: [ 6.824128] pci 0000:00:18.2: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988690Z INFO kernel: [ 6.827471] pcieport 0000:00:18.2: PME:
Signaling with IRQ 50
2024-04-26T14:30:57.988692Z INFO kernel: [ 6.829310] pcieport 0000:00:18.2: pciehp:
Slot #258 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988694Z INFO kernel: [ 6.835002] pci 0000:00:18.3: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988696Z INFO kernel: [ 6.838820] pcieport 0000:00:18.3: PME:
Signaling with IRQ 51
2024-04-26T14:30:57.988698Z INFO kernel: [ 6.841161] pcieport 0000:00:18.3: pciehp:
Slot #259 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988702Z INFO kernel: [ 6.846976] pci 0000:00:18.4: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988703Z INFO kernel: [ 6.850809] pcieport 0000:00:18.4: PME:
Signaling with IRQ 52
2024-04-26T14:30:57.988705Z INFO kernel: [ 6.852760] pcieport 0000:00:18.4: pciehp:
Slot #260 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988706Z INFO kernel: [ 6.858692] pci 0000:00:18.5: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988709Z INFO kernel: [ 6.862276] pcieport 0000:00:18.5: PME:
Signaling with IRQ 53
2024-04-26T14:30:57.988711Z INFO kernel: [ 6.864195] pcieport 0000:00:18.5: pciehp:
Slot #261 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
```

```
2024-04-26T14:30:57.988713Z INFO kernel: [ 6.870035] pci 0000:00:18.6: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988715Z INFO kernel: [ 6.873539] pcieport 0000:00:18.6: PME:
Signaling with IRQ 54
2024-04-26T14:30:57.988717Z INFO kernel: [ 6.875628] pcieport 0000:00:18.6: pciehp:
Slot #262 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988720Z INFO kernel: [ 6.881376] pci 0000:00:18.7: attach allowed
to drvr pcieport [internal device]
2024-04-26T14:30:57.988722Z INFO kernel: [ 6.885630] pcieport 0000:00:18.7: PME:
Signaling with IRQ 55
2024-04-26T14:30:57.988724Z INFO kernel: [ 6.887602] pcieport 0000:00:18.7: pciehp:
Slot #263 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T14:30:57.988727Z INFO kernel: [ 6.895453] ACPI: AC: AC Adapter [ACAD] (on-
line)
2024-04-26T14:30:57.988729Z INFO kernel: [ 6.897268] input: Power Button as
/devices/LNXSYSTM:00/LNXPWRBN:00/input/input0
2024-04-26T14:30:57.988731Z INFO kernel: [ 6.903716] ACPI: button: Power Button [PWRF]
2024-04-26T14:30:57.988733Z INFO kernel: [ 6.907581] Serial: 8250/16550 driver, 4
ports, IRQ sharing disabled
2024-04-26T14:30:57.988736Z INFO kernel: [ 6.911277] Non-volatile memory driver v1.3
2024-04-26T14:30:57.988738Z INFO kernel: [ 7.046081] ACPI: bus type drm_connector
registered
2024-04-26T14:30:57.988741Z INFO kernel: [ 7.047753] pci 0000:00:0f.0: attach allowed
to drvr vmwgfx [internal device]
2024-04-26T14:30:57.988743Z INFO kernel: [ 7.052301] vmwgfx 0000:00:0f.0: [drm] FIFO
at 0x00000000f0fb800000 size is 8192 kiB
2024-04-26T14:30:57.988746Z INFO kernel: [ 7.054793] vmwgfx 0000:00:0f.0: [drm] VRAM
at 0x00000000f0000000 size is 131072 kiB
2024-04-26T14:30:57.988748Z INFO kernel: [ 7.057043] vmwgfx 0000:00:0f.0: [drm]
Running on SVGA version 2.
2024-04-26T14:30:57.988751Z INFO kernel: [ 7.058841] vmwgfx 0000:00:0f.0: [drm]
Capabilities: rect copy, cursor, cursor bypass, cursor bypass 2, 8bit emulation, alpha
cursor, 3D, extended fifo, multimon, pitchlock, irq mask, display topology, gmr, traces,
gmr2, screen object 2, command buffers, command buffers 2, gobject, dx, hp cmd queue, no
bb restriction, cap2 register,
2024-04-26T14:30:57.988754Z INFO kernel: [ 7.067084] vmwgfx 0000:00:0f.0: [drm]
Capabilities2: grow otable, intra surface copy,
2024-04-26T14:30:57.988756Z INFO kernel: [ 7.069876] vmwgfx 0000:00:0f.0: [drm] DMA
map mode: Caching DMA mappings.
2024-04-26T14:30:57.988759Z INFO kernel: [ 7.072860] vmwgfx 0000:00:0f.0: [drm] Legacy
memory limits: VRAM = 4096 kB, FIFO = 256 kB, surface = 0 kB
2024-04-26T14:30:57.988762Z INFO kernel: [ 7.076757] vmwgfx 0000:00:0f.0: [drm] MOB
limits: max mob size = 131072 kB, max mob pages = 196608
2024-04-26T14:30:57.988765Z INFO kernel: [ 7.079746] vmwgfx 0000:00:0f.0: [drm] Max
GMR ids is 64
2024-04-26T14:30:57.988767Z INFO kernel: [ 7.081221] vmwgfx 0000:00:0f.0: [drm] Max
number of GMR pages is 65536
2024-04-26T14:30:57.988770Z INFO kernel: [ 7.083070] vmwgfx 0000:00:0f.0: [drm]
Maximum display memory size is 262144 kiB
2024-04-26T14:30:57.988773Z INFO kernel: [ 7.128874] vmwgfx 0000:00:0f.0: [drm] Screen
Target display unit initialized
2024-04-26T14:30:57.988775Z INFO kernel: [ 7.133725] vmwgfx 0000:00:0f.0: [drm] Fifo
max 0x00040000 min 0x00001000 cap 0x0000077f
2024-04-26T14:30:57.988778Z INFO kernel: [ 7.143898] vmwgfx 0000:00:0f.0: [drm] Using
command buffers with DMA pool.
2024-04-26T14:30:57.988780Z INFO kernel: [ 7.146266] vmwgfx 0000:00:0f.0: [drm]
Available shader model: SM4.
2024-04-26T14:30:57.988783Z INFO kernel: [ 7.151864] [drm] Initialized vmwgfx 2.20.0
20211206 for 0000:00:0f.0 on minor 0
2024-04-26T14:30:57.988785Z INFO kernel: [ 7.186243] loop: module loaded
2024-04-26T14:30:57.988787Z INFO kernel: [ 7.188486] lkdtm: No crash points
registered, enable through debugfs
2024-04-26T14:30:57.988789Z INFO kernel: [ 7.193150] pci 0000:00:07.7: attach allowed
to drvr vmw_vmci [internal device]
2024-04-26T14:30:57.988791Z INFO kernel: [ 7.196302] vmw_vmci 0000:00:07.7: enabling
device (0000 -> 0003)
2024-04-26T14:30:57.988795Z INFO kernel: [ 7.200236] vmw_vmci 0000:00:07.7: Found VMCI
```

```

PCI device at 0x12100, irq 16
2024-04-26T14:30:57.988797Z INFO kernel: [ 7.202791] vmw_vmci 0000:00:07.7: Using
capabilities 0xc
2024-04-26T14:30:57.988799Z INFO kernel: [ 7.206775] Guest personality initialized and
is active
2024-04-26T14:30:57.988801Z INFO kernel: [ 7.208996] VMCI host device registered
(name=vmci, major=10, minor=126)
2024-04-26T14:30:57.988803Z INFO kernel: [ 7.212327] Initialized host personality
2024-04-26T14:30:57.988805Z INFO kernel: [ 7.215733] VMware PVSCSI driver - version
1.0.7.0-k
2024-04-26T14:30:57.988807Z INFO kernel: [ 7.219699] pci 0000:03:00.0: attach allowed
to drvr nvme [internal device]
2024-04-26T14:30:57.988810Z INFO kernel: [ 7.224661] nvme nvme0: pci function
0000:03:00.0
2024-04-26T14:30:57.988812Z INFO kernel: [ 7.226562] pci 0000:00:07.1: attach allowed
to drvr ata_piix [internal device]
2024-04-26T14:30:57.988813Z DEBUG kernel: [ 7.228865] ata_piix 0000:00:07.1: version
2.13
2024-04-26T14:30:57.988815Z INFO kernel: [ 7.233866] scsi host0: ata_piix
2024-04-26T14:30:57.988817Z INFO kernel: [ 7.236837] scsi host1: ata_piix
2024-04-26T14:30:57.988819Z INFO kernel: [ 7.238302] ata1: PATA max UDMA/33 cmd 0x1f0
ctl 0x3f6 bmdma 0x2150 irq 14
2024-04-26T14:30:57.988822Z INFO kernel: [ 7.241624] nvme nvme0: 8/0/0
default/read/poll queues
2024-04-26T14:30:57.988824Z INFO kernel: [ 7.241740] ata2: PATA max UDMA/33 cmd 0x170
ctl 0x376 bmdma 0x2158 irq 15
2024-04-26T14:30:57.988826Z INFO kernel: [ 7.247812] ata_piix 0000:00:07.1: attach
allowed to drvr ata_generic [internal device]
2024-04-26T14:30:57.988828Z DEBUG kernel: [ 7.252314] mdio_bus fixed-0: GPIO lookup
for consumer reset
2024-04-26T14:30:57.988830Z DEBUG kernel: [ 7.252319] mdio_bus fixed-0: using lookup
tables for GPIO lookup
2024-04-26T14:30:57.988832Z DEBUG kernel: [ 7.252366] mdio_bus fixed-0: No GPIO
consumer reset found
2024-04-26T14:30:57.988833Z INFO kernel: [ 7.252418] PPP generic driver version 2.4.2
2024-04-26T14:30:57.988835Z INFO kernel: [ 7.254449] PPP MPPE Compression module
registered
2024-04-26T14:30:57.988837Z INFO kernel: [ 7.256395] VMware vmxnet3 virtual NIC driver
- version 1.6.0.0-k-NAPI
2024-04-26T14:30:57.988839Z INFO kernel: [ 7.258932] ehci_hcd: USB 2.0 'Enhanced' Host
Controller (EHCI) Driver
2024-04-26T14:30:57.988841Z INFO kernel: [ 7.259686] nvme0n1: p1 p2 p3 p4 p5 p6 p7 p8
p9 p10 p11 p12
2024-04-26T14:30:57.988843Z INFO kernel: [ 7.260851] ehci-pci: EHCI PCI platform
driver
2024-04-26T14:30:57.988845Z INFO kernel: [ 7.264001] pci 0000:02:03.0: attach allowed
to drvr ehci-pci [internal device]
2024-04-26T14:30:57.988847Z INFO kernel: [ 7.267721] ehci-pci 0000:02:03.0: EHCI Host
Controller
2024-04-26T14:30:57.988850Z INFO kernel: [ 7.269585] ehci-pci 0000:02:03.0: new USB
bus registered, assigned bus number 1
2024-04-26T14:30:57.988852Z INFO kernel: [ 7.272706] ehci-pci 0000:02:03.0: irq 17, io
mem 0xfc044000
2024-04-26T14:30:57.988853Z INFO kernel: [ 7.281704] ehci-pci 0000:02:03.0: USB 2.0
started, EHCI 1.00
2024-04-26T14:30:57.988855Z INFO kernel: [ 7.283642] usb usb1: New USB device found,
idVendor=1d6b, idProduct=0002, bcdDevice= 5.15
2024-04-26T14:30:57.988857Z INFO kernel: [ 7.286033] usb usb1: New USB device strings:
Mfr=3, Product=2, SerialNumber=1
2024-04-26T14:30:57.988859Z INFO kernel: [ 7.288613] usb usb1: Product: EHCI Host
Controller
2024-04-26T14:30:57.988861Z INFO kernel: [ 7.290235] usb usb1: Manufacturer: Linux
5.15.108-18907-gba143be42d3a-dirty ehci_hcd
2024-04-26T14:30:57.988863Z INFO kernel: [ 7.292735] usb usb1: SerialNumber:
0000:02:03.0
2024-04-26T14:30:57.988866Z INFO kernel: [ 7.294853] hub 1-0:1.0: USB hub found
2024-04-26T14:30:57.988868Z INFO kernel: [ 7.296044] hub 1-0:1.0: 6 ports detected
2024-04-26T14:30:57.988870Z INFO kernel: [ 7.298620] ohci_hcd: USB 1.1 'Open' Host
Controller (OHCI) Driver

```

```

2024-04-26T14:30:57.988871Z INFO kernel: [ 7.300676] ohci-pci: OHCI PCI platform
driver
2024-04-26T14:30:57.988873Z INFO kernel: [ 7.302167] uhci_hcd: USB Universal Host
Controller Interface driver
2024-04-26T14:30:57.988875Z INFO kernel: [ 7.304308] pci 0000:02:00.0: attach allowed
to drvr uhci_hcd [internal device]
2024-04-26T14:30:57.988878Z INFO kernel: [ 7.308328] uhci_hcd 0000:02:00.0: UHCI Host
Controller
2024-04-26T14:30:57.989054Z INFO kernel: [ 7.310148] uhci_hcd 0000:02:00.0: new USB
bus registered, assigned bus number 2
2024-04-26T14:30:57.989059Z INFO kernel: [ 7.313079] uhci_hcd 0000:02:00.0: irq 18, io
base 0x00001040
2024-04-26T14:30:57.989062Z INFO kernel: [ 7.315318] usb usb2: New USB device found,
idVendor=1d6b, idProduct=0001, bcdDevice= 5.15
2024-04-26T14:30:57.989065Z INFO kernel: [ 7.317867] usb usb2: New USB device strings:
Mfr=3, Product=2, SerialNumber=1
2024-04-26T14:30:57.989067Z INFO kernel: [ 7.321877] usb usb2: Product: UHCI Host
Controller
2024-04-26T14:30:57.989069Z INFO kernel: [ 7.323472] usb usb2: Manufacturer: Linux
5.15.108-18907-gba143be42d3a-dirty uhci_hcd
2024-04-26T14:30:57.989070Z INFO kernel: [ 7.325765] usb usb2: SerialNumber:
0000:02:00.0
2024-04-26T14:30:57.989072Z INFO kernel: [ 7.327656] hub 2-0:1.0: USB hub found
2024-04-26T14:30:57.989073Z INFO kernel: [ 7.328789] hub 2-0:1.0: 2 ports detected
2024-04-26T14:30:57.989075Z INFO kernel: [ 7.330861] usbcore: registered new interface
driver cdc_acm
2024-04-26T14:30:57.989077Z INFO kernel: [ 7.332922] cdc_acm: USB Abstract Control
Model driver for USB modems and ISDN adapters
2024-04-26T14:30:57.989079Z INFO kernel: [ 7.335871] usbcore: registered new interface
driver uas
2024-04-26T14:30:57.989081Z INFO kernel: [ 7.337781] usbcore: registered new interface
driver usb-storage
2024-04-26T14:30:57.989083Z INFO kernel: [ 7.339736] usbcore: registered new interface
driver ums-realtek
2024-04-26T14:30:57.989086Z INFO kernel: [ 7.341823] usbcore: registered new interface
driver usbserial_generic
2024-04-26T14:30:57.989088Z INFO kernel: [ 7.344500] usbserial: USB Serial support
registered for generic
2024-04-26T14:30:57.989090Z INFO kernel: [ 7.347075] i8042: PNP: PS/2 Controller
[PNP0303:KBC,PNP0f13:MOUS] at 0x60,0x64 irq 1,12
2024-04-26T14:30:57.989092Z INFO kernel: [ 7.352375] serio: i8042 KBD port at
0x60,0x64 irq 1
2024-04-26T14:30:57.989095Z INFO kernel: [ 7.354239] serio: i8042 AUX port at
0x60,0x64 irq 12
2024-04-26T14:30:57.989097Z INFO kernel: [ 7.360973] rtc_cmos 00:01: registered as
rtc0
2024-04-26T14:30:57.989099Z DEBUG kernel: [ 7.362662] rtc_cmos 00:01: GPIO lookup for
consumer wp
2024-04-26T14:30:57.989101Z DEBUG kernel: [ 7.362941] rtc_cmos 00:01: using ACPI for
GPIO lookup
2024-04-26T14:30:57.989104Z DEBUG kernel: [ 7.362946] acpi PNP0B00:00: GPIO: looking
up wp-gpios
2024-04-26T14:30:57.989107Z DEBUG kernel: [ 7.362982] acpi PNP0B00:00: GPIO: looking
up wp-gpio
2024-04-26T14:30:57.989109Z DEBUG kernel: [ 7.362984] rtc_cmos 00:01: using lookup
tables for GPIO lookup
2024-04-26T14:30:57.989112Z DEBUG kernel: [ 7.362987] rtc_cmos 00:01: No GPIO consumer
wp found
2024-04-26T14:30:57.989114Z INFO kernel: [ 7.363342] rtc_cmos 00:01: alarms up to one
month, y3k, 242 bytes nvram
2024-04-26T14:30:57.989116Z INFO kernel: [ 7.365485] i2c_dev: i2c /dev entries driver
2024-04-26T14:30:57.989119Z INFO kernel: [ 7.368064] IR NEC protocol handler
initialized
2024-04-26T14:30:57.989122Z INFO kernel: [ 7.370486] IR RC5(x/sz) protocol handler
initialized
2024-04-26T14:30:57.989125Z INFO kernel: [ 7.373169] IR RC6 protocol handler
initialized
2024-04-26T14:30:57.989127Z INFO kernel: [ 7.374549] IR JVC protocol handler
initialized

```



```

2024-04-26T14:30:57.989130Z INFO kernel: [ 7.375923] IR Sony protocol handler
initialized
2024-04-26T14:30:57.989133Z INFO kernel: [ 7.377295] IR SANYO protocol handler
initialized
2024-04-26T14:30:57.989135Z INFO kernel: [ 7.378667] IR Sharp protocol handler
initialized
2024-04-26T14:30:57.989138Z INFO kernel: [ 7.380174] IR MCE Keyboard/mouse protocol
handler initialized
2024-04-26T14:30:57.989141Z INFO kernel: [ 7.381904] IR XMP protocol handler
initialized
2024-04-26T14:30:57.989143Z INFO kernel: [ 7.383872] iTCO_vendor_support: vendor-
support=0
2024-04-26T14:30:57.989145Z INFO kernel: [ 7.385931] device-mapper: ioctl: 4.45.0-
ioctl (2021-03-22) initialised: dm-devel@redhat.com
2024-04-26T14:30:57.989147Z INFO kernel: [ 7.392349] device-mapper: verity-chromeos:
dm-verity-chromeos registered
2024-04-26T14:30:57.989149Z INFO kernel: [ 7.394442] intel_pstate: CPU model not
supported
2024-04-26T14:30:57.989152Z INFO kernel: [ 7.396151] sdhci: Secure Digital Host
Controller Interface driver
2024-04-26T14:30:57.989153Z INFO kernel: [ 7.398438] sdhci: Copyright(c) Pierre Ossman
2024-04-26T14:30:57.989155Z INFO kernel: [ 7.400093] EFI Variables Facility v0.08
2004-May-17
2024-04-26T14:30:57.989156Z INFO kernel: [ 7.456456] pstore: Registered efi as
persistent store backend
2024-04-26T14:30:57.989159Z INFO kernel: [ 7.458643] hid: raw HID events driver (C)
Jiri Kosina
2024-04-26T14:30:57.989161Z INFO kernel: [ 7.461027] usbcore: registered new interface
driver usbhid
2024-04-26T14:30:57.989163Z INFO kernel: [ 7.462650] usbhid: USB HID core driver
2024-04-26T14:30:57.989165Z INFO kernel: [ 7.464087] ashmem: initialized
2024-04-26T14:30:57.989168Z ERR kernel: [ 7.468473] cros_ec_lpcs: unsupported system.
2024-04-26T14:30:57.989170Z INFO kernel: [ 7.471639] GACT probability NOT on
2024-04-26T14:30:57.989172Z INFO kernel: [ 7.505001] xt_time: kernel timezone is -0000
2024-04-26T14:30:57.989174Z INFO kernel: [ 7.509369] Initializing XFRM netlink socket
2024-04-26T14:30:57.989177Z INFO kernel: [ 7.513219] NET: Registered PF_INET6 protocol
family
2024-04-26T14:30:57.989179Z INFO kernel: [ 7.518862] Segment Routing with IPv6
2024-04-26T14:30:57.989181Z INFO kernel: [ 7.521003] In-situ OAM (IOAM) with IPv6
2024-04-26T14:30:57.989183Z INFO kernel: [ 7.522543] NET: Registered PF_PACKET
protocol family
2024-04-26T14:30:57.989185Z INFO kernel: [ 7.523882] NET: Registered PF_KEY protocol
family
2024-04-26T14:30:57.989187Z INFO kernel: [ 7.527895] IPI shorthand broadcast: enabled
2024-04-26T14:30:57.989189Z INFO kernel: [ 7.529371] AVX2 version of gcm_enc/dec
engaged.
2024-04-26T14:30:57.989191Z INFO kernel: [ 7.531993] AES CTR mode by8 optimization
enabled
2024-04-26T14:30:57.989193Z INFO kernel: [ 7.547640] sched_clock: Marking stable
(7509333626, 38212295)->(9241270112, -1693724191)
2024-04-26T14:30:57.989196Z INFO kernel: [ 7.554103] usb 2-1: new full-speed USB
device number 2 using uhci_hcd
2024-04-26T14:30:57.989198Z INFO kernel: [ 7.559415] registered taskstats version 1
2024-04-26T14:30:57.989201Z NOTICE kernel: [ 7.563707] Key type .fscrypt registered
2024-04-26T14:30:57.989203Z NOTICE kernel: [ 7.565215] Key type fscrypt-provisioning
registered
2024-04-26T14:30:57.989206Z INFO kernel: [ 7.571393] pstore: Using crash dump
compression: deflate
2024-04-26T14:30:57.989208Z NOTICE kernel: [ 7.579180] Key type encrypted registered
2024-04-26T14:30:57.989210Z INFO kernel: [ 7.580460] input: AT Translated Set 2
keyboard as /devices/platform/i8042/serio0/input/input1
2024-04-26T14:30:57.989213Z INFO kernel: [ 7.581944] PM: Magic number: 4:903:536
2024-04-26T14:30:57.989216Z INFO kernel: [ 7.587413] acpi PNP0C80:eb: hash matches
2024-04-26T14:30:57.989219Z INFO kernel: [ 7.589137] input: VirtualPS/2 VMware VMMouse
as /devices/platform/i8042/serio1/input/input4
2024-04-26T14:30:57.989221Z INFO kernel: [ 7.590053] ALSA device list:
2024-04-26T14:30:57.989224Z INFO kernel: [ 7.594492] No soundcards found.
2024-04-26T14:30:57.989227Z INFO kernel: [ 7.594946] input: VirtualPS/2 VMware VMMouse
as /devices/platform/i8042/serio1/input/input3

```

```
2024-04-26T14:30:57.989229Z ERR kernel: [ 7.598962] Warning: unable to open an initial
console.
2024-04-26T14:30:57.989232Z INFO kernel: [ 7.603784] EXT4-fs (nvme0n1p3): mounting
ext2 file system using the ext4 subsystem
2024-04-26T14:30:57.989234Z INFO kernel: [ 7.612590] EXT4-fs (nvme0n1p3): mounted
filesystem without journal. Opts: (null). Quota mode: none.
2024-04-26T14:30:57.989237Z INFO kernel: [ 7.616442] VFS: Mounted root (ext2
filesystem) readonly on device 259:3.
2024-04-26T14:30:57.989239Z INFO kernel: [ 7.623109] devtmpfs: mounted
2024-04-26T14:30:57.989241Z INFO kernel: [ 7.642554] Freeing unused kernel image
(initmem) memory: 1784K
2024-04-26T14:30:57.989244Z INFO kernel: [ 7.653483] Write protecting the kernel read-
only data: 20480k
2024-04-26T14:30:57.989246Z INFO kernel: [ 7.681438] Freeing unused kernel image
(text/rodata gap) memory: 2032K
2024-04-26T14:30:57.989248Z INFO kernel: [ 7.686104] Freeing unused kernel image
(rodata/data gap) memory: 432K
2024-04-26T14:30:57.989249Z INFO kernel: [ 7.690745] Run /sbin/init as init process
2024-04-26T14:30:57.989251Z DEBUG kernel: [ 7.692411] with arguments:
2024-04-26T14:30:57.989253Z DEBUG kernel: [ 7.692415] /sbin/init
2024-04-26T14:30:57.989255Z DEBUG kernel: [ 7.692417] noresume
2024-04-26T14:30:57.989257Z DEBUG kernel: [ 7.692418] noswap
2024-04-26T14:30:57.989260Z DEBUG kernel: [ 7.692419] cros_efi
2024-04-26T14:30:57.989262Z DEBUG kernel: [ 7.692420] cros_debug
2024-04-26T14:30:57.989263Z DEBUG kernel: [ 7.692421] with environment:
2024-04-26T14:30:57.989265Z DEBUG kernel: [ 7.692422] HOME=/
2024-04-26T14:30:57.989267Z DEBUG kernel: [ 7.692423] TERM=linux
2024-04-26T14:30:57.989269Z DEBUG kernel: [ 7.692424]
BOOT_IMAGE=/syslinux/vmlinuz.A
2024-04-26T14:30:57.989271Z DEBUG kernel: [ 7.692426] boot=local
2024-04-26T14:30:57.989274Z INFO kernel: [ 7.705830] usb 2-1: New USB device found,
idVendor=0e0f, idProduct=0003, bcdDevice= 1.03
2024-04-26T14:30:57.989276Z INFO kernel: [ 7.709578] usb 2-1: New USB device strings:
Mfr=1, Product=2, SerialNumber=0
2024-04-26T14:30:57.989278Z INFO kernel: [ 7.711929] usb 2-1: Product: VMware Virtual
USB Mouse
2024-04-26T14:30:57.989279Z INFO kernel: [ 7.713696] usb 2-1: Manufacturer: VMware
2024-04-26T14:30:57.989281Z INFO kernel: [ 7.725983] input: VMware VMware Virtual USB
Mouse as /devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-1/2-
1:1.0/0003:0E0F:0003.0001/input/input5
2024-04-26T14:30:57.989283Z INFO kernel: [ 7.732067] hid-generic 0003:0E0F:0003.0001:
input,hidraw0: USB HID v1.10 Mouse [VMware VMware Virtual USB Mouse] on usb-0000:02:00.0-
1/input0
2024-04-26T14:30:57.989285Z INFO kernel: [ 7.853668] usb 2-2: new full-speed USB
device number 3 using uhci_hcd
2024-04-26T14:30:57.989288Z INFO kernel: [ 7.864972] SELinux: Permission
nlmsg_getneigh in class netlink_route_socket not defined in policy.
2024-04-26T14:30:57.989290Z INFO kernel: [ 7.867990] SELinux: Permission perfmon in
class capability2 not defined in policy.
2024-04-26T14:30:57.989292Z INFO kernel: [ 7.869976] SELinux: Permission bpf in class
capability2 not defined in policy.
2024-04-26T14:30:57.989295Z INFO kernel: [ 7.871872] SELinux: Permission
checkpoint_restore in class capability2 not defined in policy.
2024-04-26T14:30:57.989297Z INFO kernel: [ 7.874667] SELinux: Permission perfmon in
class cap2_userns not defined in policy.
2024-04-26T14:30:57.989298Z INFO kernel: [ 7.876938] SELinux: Permission bpf in class
cap2_userns not defined in policy.
2024-04-26T14:30:57.989299Z INFO kernel: [ 7.878952] SELinux: Permission
checkpoint_restore in class cap2_userns not defined in policy.
2024-04-26T14:30:57.989302Z INFO kernel: [ 7.881499] SELinux: Class mctp_socket not
defined in policy.
2024-04-26T14:30:57.989303Z INFO kernel: [ 7.883639] SELinux: Class anon_inode not
defined in policy.
2024-04-26T14:30:57.989305Z INFO kernel: [ 7.885263] SELinux: the above unknown
classes and permissions will be allowed
2024-04-26T14:30:57.989307Z INFO kernel: [ 7.909327] SELinux: policy capability
network_peer_controls=1
2024-04-26T14:30:57.989309Z INFO kernel: [ 7.911214] SELinux: policy capability
open_perms=1
```

```
2024-04-26T14:30:57.989311Z INFO kernel: [ 7.912491] SELinux: policy capability
extended_socket_class=1
2024-04-26T14:30:57.989314Z INFO kernel: [ 7.914624] SELinux: policy capability
always_check_network=0
2024-04-26T14:30:57.989317Z INFO kernel: [ 7.916705] SELinux: policy capability
cgroup_seclabel=0
2024-04-26T14:30:57.989318Z INFO kernel: [ 7.918646] SELinux: policy capability
nnp_nosuid_transition=1
2024-04-26T14:30:57.989320Z INFO kernel: [ 7.920847] SELinux: policy capability
genfs_seclabel_symlinks=0
2024-04-26T14:30:57.989321Z INFO kernel: [ 7.922524] SELinux: policy capability
ioctl_skip_cloexec=0
2024-04-26T14:30:57.989323Z INFO kernel: [ 7.997031] usb 2-2: New USB device found,
idVendor=0e0f, idProduct=0002, bcdDevice= 1.00
2024-04-26T14:30:57.989403Z INFO kernel: [ 7.999838] usb 2-2: New USB device strings:
Mfr=1, Product=2, SerialNumber=0
2024-04-26T14:30:57.989406Z INFO kernel: [ 8.002519] usb 2-2: Product: VMware Virtual
USB Hub
2024-04-26T14:30:57.989409Z INFO kernel: [ 8.004144] usb 2-2: Manufacturer: VMware,
Inc.
2024-04-26T14:30:57.989411Z INFO kernel: [ 8.011696] hub 2-2:1.0: USB hub found
2024-04-26T14:30:57.989413Z INFO kernel: [ 8.014967] hub 2-2:1.0: 7 ports detected
2024-04-26T14:30:57.989416Z NOTICE kernel: [ 8.035046] audit: type=1403
audit(1714141854.369:2): auid=4294967295 ses=4294967295 lsm=selinux res=1
2024-04-26T14:30:57.989418Z NOTICE kernel: [ 8.054568] audit: type=1400
audit(1714141854.388:3): avc: denied { read } for pid=1 comm="init" name="/"
dev="devpts" ino=1 scontext=u:r:kernel:s0 tcontext=u:object_r:devpts:s0 tclass=dir
permissive=1
2024-04-26T14:30:57.989419Z NOTICE kernel: [ 8.060687] audit: type=1400
audit(1714141854.389:4): avc: denied { open } for pid=1 comm="init" path="/dev/pts"
dev="devpts" ino=1 scontext=u:r:kernel:s0 tcontext=u:object_r:devpts:s0 tclass=dir
permissive=1
2024-04-26T14:30:57.989421Z NOTICE kernel: [ 8.066990] audit: type=1400
audit(1714141854.389:5): avc: denied { getattr } for pid=1 comm="init"
path="/dev/pts/ptmx" dev="devpts" ino=2 scontext=u:r:kernel:s0
tcontext=u:object_r:devpts:s0 tclass=chr_file permissive=1
2024-04-26T14:30:57.989424Z NOTICE kernel: [ 8.066998] audit: type=1400
audit(1714141854.394:6): avc: denied { relabelfrom } for pid=1 comm="init" name="/"
dev="tmpfs" ino=1 scontext=u:r:kernel:s0 tcontext=u:object_r:tmpfs:s0 tclass=dir
permissive=1
2024-04-26T14:30:57.989426Z NOTICE kernel: [ 8.067000] audit: type=1400
audit(1714141854.394:7): avc: denied { relabelto } for pid=1 comm="init" name="/"
dev="tmpfs" ino=1 scontext=u:r:kernel:s0 tcontext=u:object_r:cros_run:s0 tclass=dir
permissive=1
2024-04-26T14:30:57.989428Z NOTICE kernel: [ 8.067003] audit: type=1400
audit(1714141854.395:8): avc: denied { relabelto } for pid=1 comm="init" name="lock"
dev="tmpfs" ino=2 scontext=u:r:kernel:s0 tcontext=u:object_r:cros_run_lock:s0 tclass=dir
permissive=1
2024-04-26T14:30:57.989431Z NOTICE kernel: [ 8.090687] audit: type=1400
audit(1714141854.425:9): avc: denied { setattr } for pid=1 comm="init" name="lock"
dev="tmpfs" ino=2 scontext=u:r:cros_init:s0 tcontext=u:object_r:cros_run_lock:s0
tclass=dir permissive=1
2024-04-26T14:30:57.989433Z NOTICE kernel: [ 8.097582] audit: type=1400
audit(1714141854.425:10): avc: denied { search } for pid=1 comm="init" name="features"
dev="sysfs" ino=30728 scontext=u:r:cros_init:s0
tcontext=u:object_r:sysfs_fs_ext4_features:s0 tclass=dir permissive=1
2024-04-26T14:30:57.989435Z INFO kernel: [ 8.324887] usb 2-2.1: new full-speed USB
device number 4 using uhci_hcd
2024-04-26T14:30:57.989437Z NOTICE kernel: [ 8.376779] random: init: uninitialized
urandom read (12 bytes read)
2024-04-26T14:30:57.989439Z INFO kernel: [ 8.462248] usb 2-2.1: New USB device found,
idVendor=0e0f, idProduct=0008, bcdDevice= 1.00
2024-04-26T14:30:57.989441Z INFO kernel: [ 8.466001] usb 2-2.1: New USB device
strings: Mfr=1, Product=2, SerialNumber=3
2024-04-26T14:30:57.989443Z INFO kernel: [ 8.468585] usb 2-2.1: Product: Virtual
Bluetooth Adapter
2024-04-26T14:30:57.989446Z INFO kernel: [ 8.470354] usb 2-2.1: Manufacturer: VMware
2024-04-26T14:30:57.989448Z INFO kernel: [ 8.471673] usb 2-2.1: SerialNumber:
000650268328
```

```
2024-04-26T14:30:57.989449Z WARNING kernel: [ 8.888904] kauditd_printk_skb: 370
callbacks suppressed
2024-04-26T14:30:57.989451Z NOTICE kernel: [ 8.888932] audit: type=1400
audit(1714141855.222:381): avc: denied { ioctl } for pid=183 comm="cros_config_set"
path="/usr/sbin/cros_config_setup" dev="nvme0n1p3" ino=36719 ioctlcmd=0x5401
scontext=u:r:chromeos:s0 tcontext=u:object_r:cros_unconfined_exec:s0 tclass=file
permissive=1
2024-04-26T14:30:57.989453Z NOTICE kernel: [ 8.903878] audit: type=1400
audit(1714141855.226:382): avc: denied { mounton } for pid=186 comm="mount"
path="/sys/fs/pstore" dev="sysfs" ino=38483 scountext=u:r:cros_init_scripts:s0
tcontext=u:object_r:sysfs:s0 tclass=dir permissive=1
2024-04-26T14:30:57.989455Z NOTICE kernel: [ 8.912068] audit: type=1400
audit(1714141855.226:383): avc: denied { mount } for pid=186 comm="mount" name="/"
dev="pstore" ino=21515 scountext=u:r:cros_init_scripts:s0 tcontext=u:object_r:pstorefs:s0
tclass=filesystem permissive=1
2024-04-26T14:30:57.989458Z NOTICE kernel: [ 8.922842] audit: type=1400
audit(1714141855.233:384): avc: denied { execute_no_trans } for pid=187
comm="cros_config_set" path="/usr/bin/crosid" dev="nvme0n1p3" ino=32751
scountext=u:r:chromeos:s0 tcontext=u:object_r:cros_unconfined_exec:s0 tclass=file
permissive=1
2024-04-26T14:30:57.989461Z NOTICE kernel: [ 8.930346] audit: type=1400
audit(1714141855.244:385): avc: denied { setattr } for pid=188 comm="chmod" name="/"
dev="pstore" ino=21515 scountext=u:r:cros_init_scripts:s0 tcontext=u:object_r:pstorefs:s0
tclass=dir permissive=1
2024-04-26T14:30:57.989462Z NOTICE kernel: [ 8.953741] audit: type=1400
audit(1714141855.265:386): avc: denied { execute } for pid=183 comm="cros_config_set"
name="mkdir" dev="nvme0n1p3" ino=22059 scountext=u:r:chromeos:s0
tcontext=u:object_r:cros_coreutils_exec:s0 tclass=file permissive=1
2024-04-26T14:30:57.989464Z NOTICE kernel: [ 8.960805] audit: type=1400
audit(1714141855.267:387): avc: denied { read } for pid=189 comm="chgrp" name="group"
dev="nvme0n1p3" ino=28024 scountext=u:r:cros_init_scripts:s0
tcontext=u:object_r:cros_passwd_file:s0 tclass=file permissive=1
2024-04-26T14:30:57.989466Z NOTICE kernel: [ 8.968058] audit: type=1400
audit(1714141855.267:388): avc: denied { open } for pid=189 comm="chgrp"
path="/etc/group" dev="nvme0n1p3" ino=28024 scountext=u:r:cros_init_scripts:s0
tcontext=u:object_r:cros_passwd_file:s0 tclass=file permissive=1
2024-04-26T14:30:57.989469Z INFO kernel: [ 8.973384] loop0: detected capacity change
from 0 to 8
2024-04-26T14:30:57.989471Z NOTICE kernel: [ 8.976568] audit: type=1400
audit(1714141855.267:389): avc: denied { getattr } for pid=189 comm="chgrp"
path="/etc/group" dev="nvme0n1p3" ino=28024 scountext=u:r:cros_init_scripts:s0
tcontext=u:object_r:cros_passwd_file:s0 tclass=file permissive=1
2024-04-26T14:30:57.989474Z NOTICE kernel: [ 8.987378] audit: type=1400
audit(1714141855.267:390): avc: denied { chown } for pid=189 comm="chgrp" capability=0
scountext=u:r:cros_init_scripts:s0 tcontext=u:r:cros_init_scripts:s0 tclass=capability
permissive=1
2024-04-26T14:30:57.989476Z INFO kernel: [ 9.044530] udevd[195]: starting version 225
2024-04-26T14:30:57.989490Z NOTICE kernel: [ 9.073997] random: udevadm: uninitialized
urandom read (16 bytes read)
2024-04-26T14:30:57.989492Z NOTICE kernel: [ 9.077480] random: udevadm: uninitialized
urandom read (16 bytes read)
2024-04-26T14:30:57.989494Z NOTICE kernel: [ 9.384802] random: udevadm: uninitialized
urandom read (16 bytes read)
2024-04-26T14:30:57.989496Z NOTICE kernel: [ 9.388940] random: udevadm: uninitialized
urandom read (16 bytes read)
2024-04-26T14:30:57.989498Z NOTICE kernel: [ 9.400122] random: udevadm: uninitialized
urandom read (16 bytes read)
2024-04-26T14:30:57.989500Z INFO kernel: [ 9.428800] LoadPin: nvme0n1p3 (259:3):
writable
2024-04-26T14:30:57.989502Z INFO kernel: [ 9.431021] LoadPin: enforcement can be
disabled.
2024-04-26T14:30:57.989511Z NOTICE kernel: [ 9.433079] LoadPin: kernel-module pinned
obj="/lib/modules/5.15.108-18907-gba143be42d3a-dirty/kernel/drivers/input/joydev.ko"
pid=214 cmdline="udevd --daemon"
2024-04-26T14:30:57.989514Z INFO kernel: [ 9.583654] EXT4-fs (nvme0n1p1): recovery
complete
2024-04-26T14:30:57.989517Z WARNING kernel: [ 9.585567] EXT4-fs (nvme0n1p1): mounting
with "discard" option, but the device does not support discard
2024-04-26T14:30:57.989519Z INFO kernel: [ 9.588610] EXT4-fs (nvme0n1p1): mounted
```

```
filesystem with ordered data mode. Opts: commit=600,discard. Quota mode: journalled.
2024-04-26T14:30:57.989522Z INFO kernel: [ 9.622878] EXT4-fs (nvme0n1p8): orphan
cleanup on readonly fs
2024-04-26T14:30:57.989523Z INFO kernel: [ 9.625086] EXT4-fs (nvme0n1p8): mounted
filesystem with ordered data mode. Opts: . Quota mode: none.
2024-04-26T14:30:57.989531Z INFO kernel: [ 9.667734] EXT4-fs (nvme0n1p1): re-mounted.
Opts: . Quota mode: journalled.
2024-04-26T14:30:57.989534Z INFO kernel: [ 9.668240] frecon[336]: Frecon using drm
driver vmwgfx, version 2.20, date(20211206), desc(Linux drm driver for VMware graphics
devices)
2024-04-26T14:30:57.989536Z INFO kernel: [ 9.843653] loop1: detected capacity change
from 0 to 2048
2024-04-26T14:30:57.989538Z WARNING kernel: [ 9.868309] EXT4-fs (loop1): warning:
mounting unchecked fs, running e2fsck is recommended
2024-04-26T14:30:57.989541Z INFO kernel: [ 9.872704] EXT4-fs (loop1): mounted
filesystem without journal. Opts: (null). Quota mode: none.
2024-04-26T14:30:57.989543Z NOTICE kernel: [ 10.175011] random: crng init done
2024-04-26T14:30:57.989553Z NOTICE kernel: [ 10.176154] random: 776 urandom warning(s)
missed due to ratelimiting
2024-04-26T14:30:57.989555Z ERR kernel: [ 10.185585] tpm tpm0: A TPM error (256)
occurred attempting the self test
2024-04-26T14:30:57.989558Z INFO kernel: [ 10.188323] tpm tpm0: starting up the TPM
manually
2024-04-26T14:30:57.989560Z INFO kernel: [ 10.313202] loop2: detected capacity change
from 0 to 10587264
2024-04-26T14:30:57.989562Z INFO kernel: [ 10.789334] EXT4-fs (dm-0): mounted
filesystem with ordered data mode. Opts: discard,commit=600. Quota mode: none.
2024-04-26T14:30:57.989563Z INFO kernel: [ 11.299564] EXT4-fs (nvme0n1p1): re-mounted.
Opts: discard,resgid=20119,commit=600. Quota mode: journalled.
2024-04-26T14:30:57.989571Z INFO kernel: [ 11.469986] low_mem: threshold[0] 316 MB
2024-04-26T14:30:57.989573Z INFO kernel: [ 11.471383] low_mem: threshold[1] 2438 MB
2024-04-26T14:30:57.989576Z INFO kernel: [ 11.482792] loop3: detected capacity change
from 0 to 754088
2024-04-26T14:30:58.034390Z INFO kernel: [ 11.695574] zram: Added device: zram0
2024-04-26T14:30:58.040098Z INFO crash_reporter[510]: Enabling user crash handling
2024-04-26T14:30:58.079415Z NOTICE swap[549]: setting zram size to 12484728 Kb
2024-04-26T14:30:58.182139Z INFO kernel: [ 11.843255] overlayfs: "xino" feature enabled
using 32 upper inode bits.
2024-04-26T14:30:58.350568Z INFO kernel: [ 12.003658] loop4: detected capacity change
from 0 to 212568
2024-04-26T14:30:58.878101Z INFO kernel: [ 12.519954] overlayfs: "xino" feature enabled
using 32 upper inode bits.
2024-04-26T14:30:59.014338Z NOTICE fydeos-shell-daemon[636]: shell daemon starting...
2024-04-26T14:30:59.061267Z INFO kernel: [ 12.721002] loop5: detected capacity change
from 0 to 8
2024-04-26T14:30:59.086126Z INFO kernel: [ 12.748102] loop6: detected capacity change
from 0 to 8
2024-04-26T14:30:59.138425Z INFO kernel: [ 12.779320] zram0: detected capacity change
from 0 to 24384240
2024-04-26T14:30:59.265288Z INFO kernel: [ 12.924657] Adding 12192116k swap on
/dev/zram0. Priority:-2 extents:1 across:12192116k SS
2024-04-26T14:31:29.393504Z WARNING kernel: [ 43.055779] nvme nvme0: I/O 109 QID 3
timeout, completion polled
2024-04-26T14:31:29.422889Z NOTICE cr50-result[662]: cr50-result for non-GSC case
performs no-ops.
2024-04-26T14:31:29.485760Z NOTICE boot-update-firmware[703]: Update fwupd firmware.
2024-04-26T14:31:29.517866Z WARNING minijail0[681]: libminijail[681]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:29.517880Z WARNING minijail0[681]: libminijail[681]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:29.518365Z WARNING minijail0[719]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:29.518378Z WARNING minijail0[719]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:29.518388Z INFO minijail0[719]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:29.580611Z INFO mojo_service_manager[722]: DevMode is enabled, load
extra configs from /usr/local/etc/mojo/service_manager/policy
2024-04-26T14:31:29.581424Z INFO minijail0[726]: libminijail[726]: applying policy for
```

```
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:29.583154Z INFO mojo_service_manager[722]: mojo_service_manager started.
2024-04-26T14:31:29.587210Z INFO kernel: [ 43.245609] e1000: Intel(R) PRO/1000 Network
Driver
2024-04-26T14:31:29.587260Z INFO kernel: [ 43.247273] e1000: Copyright (c) 1999-2006
Intel Corporation.
2024-04-26T14:31:29.587976Z WARNING minijail0[726]: libminijail[726]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:29.589133Z WARNING minijail0[726]: libminijail[726]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:29.596697Z WARNING minijail0[739]: libminijail[739]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:29.596748Z WARNING minijail0[739]: libminijail[739]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:29.596760Z INFO minijail0[739]: libminijail[739]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:29.606058Z INFO kernel: [ 43.267112] pci 0000:02:01.0: attach allowed
to drvr e1000 [internal device]
2024-04-26T14:31:29.644672Z INFO trunksd[728]: Initialized last errno: 0
2024-04-26T14:31:29.644751Z INFO trunksd[728]: TPM: /dev/tpm0 opened successfully
2024-04-26T14:31:29.654581Z INFO iioservice[730]: INFO iioservice: [main.cc(19)] (2)
main(): Daemon started
2024-04-26T14:31:29.669663Z INFO trunksd[753]: Trunks service started.
2024-04-26T14:31:29.675951Z INFO mojo_service_manager[722]: Receive connection from:
u:r:cros_iioservice:s0
2024-04-26T14:31:29.703888Z INFO trunksd[753]: CheckState: TPM State verified.
2024-04-26T14:31:29.732849Z INFO minijail0[725]: libminijail[725]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:29.752928Z INFO local_data_migration[779]: local data migration is non-
applicable and performs no-ops.
2024-04-26T14:31:29.766146Z ERR spaced[696]: Failed to run command: No such file or
directory (2)
2024-04-26T14:31:29.766205Z ERR spaced[696]: Failed to get output from pvdisplay
2024-04-26T14:31:29.766570Z INFO check_tpm_preinit_condition[780]: Not Booting from
removable device. Quitting.
2024-04-26T14:31:29.778057Z NOTICE write-machine-info[785]: Fallback to WPSW_BOOT (-1),
which may be invalid
2024-04-26T14:31:29.799203Z WARNING minijail0[797]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:29.799326Z WARNING minijail0[797]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:29.799371Z INFO minijail0[797]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:29.803467Z INFO minijail0[798]: libminijail[798]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:29.809195Z WARNING minijail0[794]: libminijail[794]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:29.809235Z WARNING minijail0[794]: libminijail[794]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:29.847198Z ERR spaced[696]: Failed to run command: No such file or
directory (2)
2024-04-26T14:31:29.847274Z ERR spaced[696]: Failed to get output from pvdisplay
2024-04-26T14:31:29.877498Z INFO tpm_managerd[797]: Starting TPM Manager...
2024-04-26T14:31:29.902964Z WARNING tpm_managerd[797]: WARNING: Verified boot PCR 2 is
not initialized.
2024-04-26T14:31:29.909611Z WARNING tpm_managerd[797]: WARNING: Verified boot PCR 3 is
not initialized.
2024-04-26T14:31:29.932639Z INFO minijail0[830]: libminijail[830]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:29.944877Z WARNING minijail0[828]: libminijail[828]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:29.944962Z WARNING minijail0[828]: libminijail[828]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:29.946258Z WARNING minijail0[833]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:29.946287Z WARNING minijail0[833]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:29.946300Z INFO minijail0[833]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
```

```

2024-04-26T14:31:29.949946Z INFO minijail0[834]: libminijail[834]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:29.955565Z INFO tpm_managerd[797]: Ownership taken signal is sent.
2024-04-26T14:31:29.964080Z INFO minijail0[827]: libminijail[827]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:29.977421Z ERR tpm_managerd[797]: Unknown alerts family: 0
2024-04-26T14:31:29.977464Z INFO tpm_managerd[797]: The TPM chip does not support
GetAlertsData. Stop UploadAlertsData task.
2024-04-26T14:31:29.982539Z INFO tpm_managerd[797]:
PeriodicResetDictionaryAttackCounterTask: DA reset succeeded.
2024-04-26T14:31:29.984028Z WARNING minijail0[839]: libminijail[839]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:29.984177Z WARNING minijail0[839]: libminijail[839]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:29.985625Z WARNING minijail0[841]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:29.985741Z WARNING minijail0[841]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:29.985782Z INFO minijail0[841]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:30.020950Z INFO root[842]: fydeos-license-utils get disk /dev/nvme0n1
serial by lsblk
2024-04-26T14:31:30.033698Z INFO root[845]: fydeos-license-utils get fix id by disk
serial
2024-04-26T14:31:30.042483Z INFO chapsd[822]: Starting PKCS #11 services.
2024-04-26T14:31:30.045860Z INFO chapsd[822]: Starting D-Bus dispatcher.
2024-04-26T14:31:30.063544Z INFO chapsd[822]: Adding slot: 0
2024-04-26T14:31:30.063620Z INFO chapsd[822]: Adding slot: 1
2024-04-26T14:31:30.078200Z INFO chapsd[822]: Opening database in: /var/lib/chaps
2024-04-26T14:31:30.104426Z INFO chapsd[822]: leveldb /var/lib/chaps/database dump:#012
/var/lib/chaps/database/LOG (184 bytes, 2024-04-26 13:59:02.000 UTC)#012
/var/lib/chaps/database/CURRENT (16 bytes, 2024-04-26 13:59:02.000 UTC)#012
/var/lib/chaps/database/LOG.old (184 bytes, 2024-04-24 14:50:25.000 UTC)#012
/var/lib/chaps/database/000005.ldb (393 bytes, 2024-03-26 12:57:11.000 UTC)#012
/var/lib/chaps/database/LOCK (0 bytes, 2024-03-26 12:25:52.000 UTC)#012
/var/lib/chaps/database/MANIFEST-000035 (92 bytes, 2024-04-26 13:59:02.000 UTC)#012
/var/lib/chaps/database/000036.log (0 bytes, 2024-04-26 13:59:02.000 UTC)
2024-04-26T14:31:30.106694Z INFO rollback_cleanup[829]: Failed to get enterprise rollback
space state: This space is not preparable
2024-04-26T14:31:30.122843Z INFO bootlockboxd[833]: BootLockboxd started
2024-04-26T14:31:30.159474Z INFO chapsd[822]: leveldb.stats:#012
Compactions#012Level Files Size(MB) Time(sec) Read(MB) Write(MB)#012-----
-----#012 0 1 0 0 0 0#012
2024-04-26T14:31:30.160400Z INFO chapsd[822]: leveldb contains 5 keys.
2024-04-26T14:31:30.161043Z INFO chapsd[822]: Slot 0 ready for token at /var/lib/chaps
2024-04-26T14:31:30.163237Z INFO chapsd[822]: Created lock file:
/run/lock/power_override/chapsd_token_init_slot_0.lock
2024-04-26T14:31:30.191207Z INFO chapsd[822]: Root key is ready for token at
/var/lib/chaps
2024-04-26T14:31:30.191398Z INFO chapsd[822]: Deleted lock file:
/run/lock/power_override/chapsd_token_init_slot_0.lock
2024-04-26T14:31:30.191994Z INFO minijail0[887]: libminijail[887]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:30.258175Z WARNING attestationd[885]: Get: attested_device_id missing in
RO_VPD.
2024-04-26T14:31:30.258391Z INFO attestationd[885]: No ADID found.
2024-04-26T14:31:30.258462Z INFO attestationd[885]: Setting ADID to
fake_attested_device_id_ for simulator.
2024-04-26T14:31:30.259675Z INFO attestationd[885]: Attestation Daemon Started.
2024-04-26T14:31:30.265544Z INFO attestationd[885]: Attestation service started.
2024-04-26T14:31:30.280541Z INFO attestationd[885]: OnSignalConnected: Connected dbus
signal successfully.
2024-04-26T14:31:30.293073Z INFO attestationd[885]: Loading attestation database.
2024-04-26T14:31:30.301806Z WARNING minijail0[923]: libminijail[923]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:30.302088Z WARNING minijail0[923]: libminijail[923]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:30.302860Z WARNING minijail0[926]: libminijail[1]: failed to create a
ruleset: Function not implemented

```

```
2024-04-26T14:31:30.302960Z WARNING minijail0[926]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:30.303054Z INFO minijail0[926]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:30.304254Z INFO kernel: [ 43.964894] Bluetooth: Core ver 2.22
2024-04-26T14:31:30.304289Z INFO kernel: [ 43.967865] NET: Registered PF_BLUETOOTH
protocol family
2024-04-26T14:31:30.310303Z INFO kernel: [ 43.972529] Bluetooth: HCI device and
connection manager initialized
2024-04-26T14:31:30.310941Z NOTICE chaps-restore[884]: PKCS #11 restore TPM tokens call
failed: (dbus, org.freedesktop.DBus.Error.ServiceUnknown, Error calling D-Bus method:
org.chromium.CryptohomePkcs11Interface.Pkcs11RestoreTpmTokens: The name
org.chromium.UserDataAuth was not provided by any .service files).
2024-04-26T14:31:30.314154Z INFO kernel: [ 43.976129] Bluetooth: HCI socket layer
initialized
2024-04-26T14:31:30.314189Z INFO kernel: [ 43.978352] Bluetooth: L2CAP socket layer
initialized
2024-04-26T14:31:30.320358Z INFO kernel: [ 43.983075] Bluetooth: SCO socket layer
initialized
2024-04-26T14:31:30.326465Z INFO bluetoothd[778]: Bluetooth daemon 5.54
2024-04-26T14:31:30.326861Z WARNING bluetoothd[778]: Unknown key MaxControllers for group
General in /var/lib/bluetooth/main.conf
2024-04-26T14:31:30.327085Z INFO bluetoothd[778]: PageScanType=1(1)
2024-04-26T14:31:30.327112Z INFO bluetoothd[778]: PageScanInterval=1024(1024)
2024-04-26T14:31:30.327126Z INFO bluetoothd[778]: PageScanWindow=18(18)
2024-04-26T14:31:30.327149Z INFO bluetoothd[778]: EirMaxNameLength=180(180)
2024-04-26T14:31:30.327160Z INFO bluetoothd[778]: MinAdvertisementInterval=290(290)
2024-04-26T14:31:30.327171Z INFO bluetoothd[778]: MaxAdvertisementInterval=290(290)
2024-04-26T14:31:30.327184Z INFO bluetoothd[778]: ScanIntervalAutoConnect=588(588)
2024-04-26T14:31:30.327198Z INFO bluetoothd[778]: ScanWindowAutoConnect=60(60)
2024-04-26T14:31:30.327213Z INFO bluetoothd[778]: ScanIntervalDiscovery=36(36)
2024-04-26T14:31:30.327224Z INFO bluetoothd[778]: ScanWindowDiscovery=18(18)
2024-04-26T14:31:30.327234Z INFO bluetoothd[778]: ScanIntervalAdvMonitor=40(40)
2024-04-26T14:31:30.327245Z INFO bluetoothd[778]: ScanWindowAdvMonitor=20(20)
2024-04-26T14:31:30.327261Z INFO bluetoothd[778]: MinConnectionInterval=6(6)
2024-04-26T14:31:30.327274Z INFO bluetoothd[778]: MaxConnectionInterval=16(16)
2024-04-26T14:31:30.327287Z INFO bluetoothd[778]: ConnectionSupervisionTimeout=200(200)
2024-04-26T14:31:30.327298Z INFO bluetoothd[778]: Autoconnecttimeout=5000(5000)
2024-04-26T14:31:30.327312Z INFO bluetoothd[778]: EnableAdvMonInterleaveScan=1(1)
2024-04-26T14:31:30.329768Z INFO bluetoothd[778]: Starting SDP server
2024-04-26T14:31:30.331053Z INFO bluetoothd[778]: Applied debug levels: bluez(0),
kernel(0)
2024-04-26T14:31:30.335841Z INFO bluetoothd[778]: Bluetooth management interface 1.21
initialized
2024-04-26T14:31:30.352718Z INFO minijail0[938]: libminijail[938]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:30.354376Z WARNING attestationd[885]: Could not read hwid property.
2024-04-26T14:31:30.379579Z INFO mojo_service_manager[722]: Receive connection from:
u:r:cros_shill:s0
2024-04-26T14:31:30.404895Z ERR shill[837]: ERROR shill: [object_proxy.cc(590)] Failed to
call method: org.chromium.PatchPanel.GetTrafficCounters: object_path=
/org/chromium/PatchPanel: org.freedesktop.DBus.Error.ServiceUnknown: The name
org.chromium.PatchPanel was not provided by any .service files
2024-04-26T14:31:30.404935Z ERR shill[837]: ERROR shill: [client.cc(379)] Failed to send
TrafficCountersRequest message to patchpanel service
2024-04-26T14:31:30.416857Z INFO vtpmd[926]: OnSignalConnected: Connected dbus signal
successfully.
2024-04-26T14:31:30.516026Z ERR cryptohomed[936]: quotactl failed for user 0: No such
process (3)
2024-04-26T14:31:30.516532Z ERR cryptohomed[936]: Device is not mounted with quota
feature enabled.
2024-04-26T14:31:30.546808Z INFO kernel: [ 44.208551] loop7: detected capacity change
from 0 to 192888
2024-04-26T14:31:30.553707Z ERR session_manager[987]: ERROR session_manager:
[safe_fd.cc(701)] unlinkat failed: No such file or directory (2)
2024-04-26T14:31:30.555338Z ERR session_manager[987]: ERROR session_manager:
[safe_fd.cc(701)] unlinkat failed: No such file or directory (2)
2024-04-26T14:31:30.559588Z WARNING session_manager[987]: WARNING session_manager:
[chrome_setup.cc(240)] Could not find both paths: /usr/share/chromeos-
```



```
assets/wallpaper/oem_large.jpg and /usr/share/chromeos-assets/wallpaper/oem_small.jpg
2024-04-26T14:31:30.559632Z WARNING session_manager[987]: WARNING session_manager:
[chrome_setup.cc(249)] Could not find both paths: /usr/share/chromeos-
assets/wallpaper/oem_large.png and /usr/share/chromeos-assets/wallpaper/oem_small.png
2024-04-26T14:31:30.559656Z WARNING session_manager[987]: WARNING session_manager:
[chrome_setup.cc(240)] Could not find both paths: /usr/share/chromeos-
assets/wallpaper/default_large.jpg and /usr/share/chromeos-
assets/wallpaper/default_small.jpg
2024-04-26T14:31:30.570422Z NOTICE cros-machine-id-regen[1027]: Regenerated
/var/lib/dbus/machine-id (reason: network).
2024-04-26T14:31:30.589135Z ERR kernel: [ 44.251716] Filesystem uses "zstd"
compression. This is not supported
2024-04-26T14:31:30.601804Z INFO session_manager[987]: INFO session_manager:
[session_manager_main.cc(234)] Mount namespace created at /run/namespaces/mnt_chrome
2024-04-26T14:31:30.625958Z INFO cups_launcher[1038]: Waiting for events on
/run/cups/cups.sock
2024-04-26T14:31:30.637052Z INFO kernel: [ 44.297501] e1000 0000:02:01:0 eth0:
(PCI:66MHz:32-bit) 00:0c:29:17:b2:95
2024-04-26T14:31:30.637088Z INFO kernel: [ 44.299523] e1000 0000:02:01:0 eth0: Intel(R)
PRO/1000 Network Connection
2024-04-26T14:31:30.639542Z INFO session_manager[987]: INFO session_manager:
[session_manager_service.cc(183)] SessionManagerService starting
2024-04-26T14:31:30.645784Z INFO session_manager[987]: INFO session_manager:
[dev_mode_unblock_broker.cc(68)] DevModeUnblockBroker
awaiting_unblock_init_state_determination: 1 awaiting_unblock_enrollment: 1
awaiting_unblock_carrier_lock: 0
2024-04-26T14:31:30.648491Z WARNING powerd[1034]: libminijail[1034]: SECURE_NOROOT not
set, not dropping bounding set
2024-04-26T14:31:30.651123Z INFO session_manager[987]: INFO session_manager:
[browser_job.cc(224)] Running browser /opt/google/chrome/chrome --enable-webgl-image-
chromium --enable-
features=Pepper3DImageChromium,UmaStorageDimensions,ArcAdbSideload,Crostini,CrostiniGp
uSupport,SmartDim --gpu-sandbox-failures-fatal=no --enable-logging --log-level=1 --use-
cras --enable-wayland-server --user-data-dir=/home/chronos --system-developer-mode --
disable-mojo-broker --ash-use-cros-mojo-service-manager --cros-healthd-uses-service-
manager --login-profile=user --aura-legacy-power-button --guest-wallpaper-
large=/usr/share/chromeos-assets/wallpaper/guest_large.jpg --guest-wallpaper-
small=/usr/share/chromeos-assets/wallpaper/guest_small.jpg --child-wallpaper-
large=/usr/share/chromeos-assets/wallpaper/child_large.jpg --child-wallpaper-
small=/usr/share/chromeos-assets/wallpaper/child_small.jpg --default-wallpaper-
large=/usr/share/chromeos-assets/wallpaper/default_large.png --default-wallpaper-
small=/usr/share/chromeos-assets/wallpaper/default_small.png --fyde-dynamic-default-
wallpaper --enable-consumer-kiosk --device-help-content-id=fydeos --ozone-nnpalm-
properties={} --arc-availability=officially-supported --enable-houdini --enable-houdini64
--enterprise-enrollment-initial-modulus=15 --enterprise-enrollment-modulus-limit=19 --
enable-crashpad --ml-service=enabled --ondevice_handwriting=use_rootfs --
ondevice_document_scanner=use_rootfs --disable-features=FederatedService --remote-
debugging-port=9229 --drm-virtual-connector-is-external --enable-zero-copy --disable-arc-
opt-in-verification --enable-hardware-overlays=single-fullscreen --login-manager --
feature-flags=["scheduler-configuration@2"] --first-exec-after-boot --enable-
features=Pepper3DImageChromium,UmaStorageDimensions,ArcAdbSideload,Crostini,CrostiniGp
uSupport,SmartDim --disable-features=FederatedService
2024-04-26T14:31:30.652075Z INFO session_manager[987]: INFO session_manager:
[session_manager_service.cc(304)] Browser is 1044
2024-04-26T14:31:30.653089Z INFO kernel: [ 44.314324] e1000: eth0 NIC Link is Up 1000
Mbps Full Duplex, Flow Control: None
2024-04-26T14:31:30.664997Z ERR cryptohomed[936]: Failed to get FWMP state: No owner
password
2024-04-26T14:31:30.666069Z ERR session_manager[987]: ERROR session_manager:
[dev_mode_unblock_broker.cc(193)] Failed to get firmware management parameters:26
2024-04-26T14:31:30.666151Z INFO session_manager[987]: INFO session_manager:
[dev_mode_unblock_broker.cc(140)] block_devmode_fwmp 0
2024-04-26T14:31:30.666385Z ERR session_manager[987]: ERROR session_manager:
[dev_mode_unblock_broker.cc(155)] Failed to read block_devmode flag!
2024-04-26T14:31:30.668962Z ERR shill[837]: ERROR shill: [object_proxy.cc(590)] Failed to
call method: org.chromium.PatchPanel.GetTrafficCounters: object_path=
/org/chromium/PatchPanel: org.freedesktop.DBus.Error.ServiceUnknown: The name
org.chromium.PatchPanel was not provided by any .service files
2024-04-26T14:31:30.669000Z ERR shill[837]: ERROR shill: [client.cc(379)] Failed to send
```

```
TrafficCountersRequest message to patchpanel service
2024-04-26T14:31:30.669144Z INFO session_manager[987]: INFO session_manager:
[dev_mode_unblock_broker.cc(157)] block_devmode_system -1
2024-04-26T14:31:30.673841Z ERR shill[837]: ERROR shill: [object_proxy.cc(590)] Failed to
call method: org.chromium.PatchPanel.GetTrafficCounters: object_path=
/org/chromium/PatchPanel: org.freedesktop.DBus.Error.ServiceUnknown: The name
org.chromium.PatchPanel was not provided by any .service files
2024-04-26T14:31:30.674729Z ERR shill[837]: ERROR shill: [client.cc(379)] Failed to send
TrafficCountersRequest message to patchpanel service
2024-04-26T14:31:30.678902Z NOTICE auditd[458]: Audit daemon rotating log files
2024-04-26T14:31:30.687505Z INFO cryptohomed[936]: Valid secure install attributes cache
found.
2024-04-26T14:31:30.709276Z INFO kernel: [ 44.370333] 8021q: 802.1Q VLAN Support v1.8
2024-04-26T14:31:30.709340Z INFO kernel: [ 44.371815] 8021q: adding VLAN 0 to HW filter
on device eth0
2024-04-26T14:31:31.258215Z INFO mojo_service_manager[722]: Receive connection from:
u:r:cros_powerd:s0
2024-04-26T14:31:31.294919Z INFO iioservice[730]: INFO iioservice: [iio_sensor.cc(56)]
(2) Request(): Received SensorService from Mojo Service Manager
2024-04-26T14:31:31.467258Z INFO mojo_service_manager[722]: Receive connection from:
u:r:cros_browser:s0
2024-04-26T14:31:31.660196Z INFO dbus-daemon[583]: [system] Activating service
name='org.chromium.Rgbkbd' requested by ':1.41' (uid=1000 pid=1044
comm="/opt/google/chrome/chrome --enable-webgl-image-chr" label="u:r:cros_browser:s0")
(using servicehelper)
2024-04-26T14:31:31.698103Z INFO kernel: [ 45.360538] IPv6: ADDRCONF(NETDEV_CHANGE):
eth0: link becomes ready
2024-04-26T14:31:31.740501Z INFO minijail0[1110]: libminijail[1110]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:31.830178Z INFO rgbkbd[1116]: Starting Chrome OS RGB Keyboard Daemon
2024-04-26T14:31:31.838406Z INFO dbus-daemon[583]: [system] Successfully activated
service 'org.chromium.Rgbkbd'
2024-04-26T14:31:31.839829Z INFO rgbkbd[1116]: Checking RgbKeyboardCapabilities.
2024-04-26T14:31:31.840506Z INFO rgbkbd[1116]: Deducing Communication type
2024-04-26T14:31:31.840636Z ERR rgbkbd[1116]: Failed to open FD for EC with errno=2
2024-04-26T14:31:31.849991Z WARNING rgbkbd[1116]: Failed to initialize USB Endpoint after
retry #2
2024-04-26T14:31:31.850208Z INFO rgbkbd[1116]: Failed to initialize EC USB Endpoint.
2024-04-26T14:31:31.850686Z ERR rgbkbd[1116]: Failed to deduce communication type for
internal RGB Keyboard
2024-04-26T14:31:31.851251Z INFO rgbkbd[1116]: Device does not support an internal RGB
keyboard
2024-04-26T14:31:31.852966Z INFO rgbkbd[1116]: Chrome OS RGB Keyboard Daemon exited
successfully
2024-04-26T14:31:31.915204Z INFO session_manager[987]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting ash-initialized Upstart signal
2024-04-26T14:31:32.203957Z INFO iioservice[730]: INFO iioservice: [iio_sensor.cc(56)]
(2) Request(): Received SensorService from Mojo Service Manager
2024-04-26T14:31:32.208208Z INFO btmanagerd[739]: Set floss devcoredump to false
2024-04-26T14:31:32.231929Z INFO bluetoothd[778]: Bluetooth devcoredump state set to 0
2024-04-26T14:31:32.232325Z INFO bluetoothd[778]: LL Privacy status not changed: 0
2024-04-26T14:31:32.268367Z INFO minijail0[1169]: libminijail[1169]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:32.270592Z WARNING minijail0[1172]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:32.270635Z WARNING minijail0[1172]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:32.270909Z WARNING minijail0[1169]: libminijail[1169]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:32.270956Z WARNING minijail0[1169]: libminijail[1169]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:32.272276Z INFO minijail0[1172]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:32.568157Z INFO session_manager[987]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting login-prompt-visible Upstart signal
2024-04-26T14:31:32.636656Z ERR cryptohomed[936]: Failed to call method:
org.chromium.ChromeFeaturesServiceInterface.IsFeatureEnabled: object_path=
/org/chromium/ChromeFeaturesService: org.freedesktop.DBus.Error.InvalidArgs: Unexpected
feature name.
```

```
2024-04-26T14:31:32.637068Z WARNING cryptohomed[936]: No valid keysets on disk for
521ac76c473ca5ff9c03ccc71d8ad8646690ad65
2024-04-26T14:31:32.651738Z INFO kernel: [ 46.310793] EXT4-fs (nvme0n1p8): re-mounted.
Opts: . Quota mode: none.
2024-04-26T14:31:32.836646Z INFO kernel: [ 46.497565] EXT4-fs (nvme0n1p8): re-mounted.
Opts: . Quota mode: none.
2024-04-26T14:31:33.157349Z INFO minijail0[1218]: libminijail[1218]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:33.252599Z INFO minijail0[1258]: libminijail[1258]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:33.253546Z WARNING minijail0[1258]: libminijail[1258]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:33.253559Z WARNING minijail0[1258]: libminijail[1258]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:33.254181Z WARNING minijail0[1277]: libminijail[1277]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:33.254215Z WARNING minijail0[1277]: libminijail[1277]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:33.254226Z INFO minijail0[1277]: libminijail[1277]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:33.273930Z INFO minijail0[1220]: libminijail[1220]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:33.335651Z NOTICE cros-disks[1286]: Loading FUSE module
2024-04-26T14:31:33.495301Z WARNING minijail0[1232]: libminijail[1232]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:33.495323Z WARNING minijail0[1232]: libminijail[1232]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:33.497564Z WARNING minijail0[1299]: libminijail[1299]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:33.497703Z WARNING minijail0[1299]: libminijail[1299]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:33.497715Z INFO minijail0[1299]: libminijail[1299]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:33.668640Z WARNING minijail0[1309]: libminijail[1309]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:33.668674Z WARNING minijail0[1309]: libminijail[1309]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:33.669306Z WARNING minijail0[1321]: libminijail[1321]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:33.669340Z WARNING minijail0[1321]: libminijail[1321]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:33.669350Z INFO minijail0[1321]: libminijail[1321]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:33.686000Z INFO minijail0[1328]: libminijail[1328]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:33.715715Z WARNING minijail0[1328]: libminijail[1328]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:33.715858Z WARNING minijail0[1328]: libminijail[1328]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:33.721285Z WARNING minijail0[1332]: libminijail[1332]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:33.721445Z WARNING minijail0[1332]: libminijail[1332]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:33.721459Z INFO minijail0[1332]: libminijail[1332]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:33.773071Z INFO minijail0[1269]: libminijail[1269]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:33.932378Z WARNING kernel: [ 47.576177] -----[ cut here ]-----
-----
2024-04-26T14:31:33.932407Z WARNING kernel: [ 47.578324] refcount_t: addition on 0;
use-after-free.
2024-04-26T14:31:33.932411Z WARNING kernel: [ 47.580884] WARNING: CPU: 3 PID: 1097 at
lib/refcount.c:25 refcount_warn_saturate+0x9a/0x104
2024-04-26T14:31:33.932414Z WARNING kernel: [ 47.583705] Modules linked in: 8021q
bluetooth cfg80211 ecdh_generic ecc e1000 lzo_rle lzo_compress zram joydev
2024-04-26T14:31:33.932418Z WARNING kernel: [ 47.586925] CPU: 3 PID: 1097 Comm: chrome
Not tainted 5.15.108-18907-gba143be42d3a-dirty #1
2024-04-26T14:31:33.932420Z WARNING kernel: [ 47.591923] Hardware name: VMware, Inc.
VMware7,1/440BX Desktop Reference Platform, BIOS VMW71.00V.21805430.B64.2305221826
```

05/22/2023

```

2024-04-26T14:31:33.932424Z WARNING kernel: [ 47.595753] RIP:
0010:refcount_warn_saturate+0x9a/0x104
2024-04-26T14:31:33.965163Z WARNING kernel: [ 47.599637] Code: c7 44 63 f0 83 e8 bd 4f
ea ff 0f 0b eb 69 80 3d e6 f0 2f 01 00 75 60 c6 05 dd f0 2f 01 01 48 c7 c7 29 a1 e6 83 e8
9d 4f ea ff <0f> 0b eb 49 80 3d c7 f0 2f 01 00 75 40 c6 05 be f0 2f 01 01 48 c7
2024-04-26T14:31:33.969226Z WARNING kernel: [ 47.629558] RSP: 0018:ffff9244809afa60
EFLAGS: 00010246
2024-04-26T14:31:33.969298Z WARNING kernel: [ 47.633374] RAX: d094c433f16c1600 RBX:
0000000000000000 RCX: ffffffff8405daa8
2024-04-26T14:31:33.997191Z WARNING kernel: [ 47.635957] RDX: ffff9244809af838 RSI:
0000000000000000 RDI: 0000000000000001
2024-04-26T14:31:33.997304Z WARNING kernel: [ 47.641535] RBP: ffff9244809afa60 R08:
0000000000000000 R09: ffff9244809af830
2024-04-26T14:31:33.997420Z WARNING kernel: [ 47.644406] R10: 00000000ffffdfff R11:
ffffffffff8408dd50 R12: ffff88be09506c40
2024-04-26T14:31:33.997429Z WARNING kernel: [ 47.646542] R13: ffff88be31017a00 R14:
0000000000000000 R15: ffff9244809afac4
2024-04-26T14:31:33.997431Z WARNING kernel: [ 47.649024] FS: 00007ea287223040(0000)
GS: ffff88bec34c0000(0000) knlGS:0000000000000000
2024-04-26T14:31:33.997433Z WARNING kernel: [ 47.654386] CS: 0010 DS: 0000 ES: 0000
CR0: 0000000080050033
2024-04-26T14:31:33.997435Z WARNING kernel: [ 47.659088] CR2: 00002aa001cee800 CR3:
00000000120e2a001 CR4: 00000000003706e0
2024-04-26T14:31:33.997438Z WARNING kernel: [ 47.661162] Call Trace:
2024-04-26T14:31:33.997450Z WARNING kernel: [ 47.661917] <TASK>
2024-04-26T14:31:33.999954Z WARNING kernel: [ 47.663337] objects_lookup+0x92/0xc6
2024-04-26T14:31:34.016604Z WARNING kernel: [ 47.664495]
drm_gem_object_lookup+0x3c/0x5e
2024-04-26T14:31:34.016620Z WARNING kernel: [ 47.665633]
vmw_user_bo_noref_lookup+0x16/0xb4
2024-04-26T14:31:34.016623Z WARNING kernel: [ 47.667278]
vmw_translate_mob_ptr+0x34/0xfc
2024-04-26T14:31:34.016624Z WARNING kernel: [ 47.668565]
vmw_cmd_res_switch_backup+0x4e/0x96
2024-04-26T14:31:34.016627Z WARNING kernel: [ 47.669850]
vmw_cmd_dx_bind_shader+0x110/0x143
2024-04-26T14:31:34.016628Z WARNING kernel: [ 47.671136]
vmw_execbuf_process+0x55d/0xf8c
2024-04-26T14:31:34.016629Z WARNING kernel: [ 47.672723] ?
avc_has_extended_perms+0x297/0x4c8
2024-04-26T14:31:34.016631Z WARNING kernel: [ 47.674176] vmw_execbuf_ioctl+0x67/0x11d
2024-04-26T14:31:34.051350Z WARNING kernel: [ 47.713971] ?
vmw_execbuf_release_pinned_bo+0x3e/0x3e
2024-04-26T14:31:34.051382Z WARNING kernel: [ 47.715826] drm_ioctl_kernel+0xd9/0x14c
2024-04-26T14:31:34.084349Z WARNING kernel: [ 47.716908] drm_ioctl+0x23c/0x3a4
2024-04-26T14:31:34.084377Z WARNING kernel: [ 47.717790] ?
vmw_execbuf_release_pinned_bo+0x3e/0x3e
2024-04-26T14:31:34.084383Z WARNING kernel: [ 47.719061] __x64_sys_ioctl+0x7b/0xc8
2024-04-26T14:31:34.084386Z WARNING kernel: [ 47.720051] do_syscall_64+0x58/0xa5
2024-04-26T14:31:34.084388Z WARNING kernel: [ 47.721067]
entry_SYSCALL_64_after_hwframe+0x5c/0xc6
2024-04-26T14:31:34.084390Z WARNING kernel: [ 47.722536] RIP: 0033:0x7ea287a29649
2024-04-26T14:31:34.084392Z WARNING kernel: [ 47.723420] Code: 04 25 28 00 00 00 48 89
45 c8 31 c0 48 8d 45 10 c7 45 b0 10 00 00 00 48 89 45 b8 48 8d 45 d0 48 89 45 c0 b8 10 00
00 00 0f 05 <41> 89 c0 3d 00 f0 ff ff 77 1d 48 8b 45 c8 64 48 2b 04 25 28 00 00
2024-04-26T14:31:34.084394Z WARNING kernel: [ 47.727867] RSP: 002b:00007fff5531b9d0
EFLAGS: 00000246 ORIG_RAX: 0000000000000010
2024-04-26T14:31:34.084396Z WARNING kernel: [ 47.729645] RAX: ffffffffffffffffda RBX:
0000000000000000 RCX: 00007ea287a29649
2024-04-26T14:31:34.084398Z WARNING kernel: [ 47.731312] RDX: 00007fff5531ba88 RSI:
000000004028644c RDI: 000000000000000d
2024-04-26T14:31:34.084402Z WARNING kernel: [ 47.732984] RBP: 00007fff5531ba20 R08:
00000000000000d10 R09: 00007fff5531bb38
2024-04-26T14:31:34.084404Z WARNING kernel: [ 47.734686] R10: 0000000000000003 R11:
0000000000000246 R12: 000000000000000d
2024-04-26T14:31:34.084406Z WARNING kernel: [ 47.736381] R13: 00007fff5531bb88 R14:
000000004028644c R15: 00007fff5531ba88
2024-04-26T14:31:34.084407Z WARNING kernel: [ 47.738290] </TASK>

```

```
2024-04-26T14:31:34.084409Z WARNING kernel: [ 47.738832] ---[ end trace
cd219e6f9c779228 ]---
2024-04-26T14:31:34.099982Z INFO sshd[1337]: Server listening on 0.0.0.0 port 22.
2024-04-26T14:31:34.100094Z INFO sshd[1337]: Server listening on :: port 22.
2024-04-26T14:31:34.175054Z INFO kernel: [ 47.832385] fuse: init (API version 7.34)
2024-04-26T14:31:34.198307Z INFO mojo_service_manager[722]: Receive connection from:
u:r:cros_healthd:s0
2024-04-26T14:31:34.235434Z INFO cros_healthd[1319]: CrosHealthdDiagnosticsService is
ready.
2024-04-26T14:31:34.241726Z INFO iioservice[730]: INFO iioservice: [iio_sensor.cc(56)]
(2) Request(): Received SensorService from Mojo Service Manager
2024-04-26T14:31:34.262495Z INFO avahi-daemon[1277]: Found user 'avahi' (UID 238) and
group 'avahi' (GID 238).
2024-04-26T14:31:34.263486Z INFO avahi-daemon[1277]: Successfully dropped root
privileges.
2024-04-26T14:31:34.271425Z INFO minijail0[1387]: libminijail[1387]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:34.274692Z WARNING contrack-tools[1376]: scheduler configuration
failed: Operation not permitted. Likely a bug in contrackd, please report it. Continuing
with system default scheduler.
2024-04-26T14:31:34.274940Z NOTICE contrack-tools[1376]: configuring helper `mdns' with
queuenum=6 and queuelen=10240
2024-04-26T14:31:34.274964Z NOTICE contrack-tools[1376]: policy name=mdns
expect_timeout=30 expect_max=8
2024-04-26T14:31:34.275041Z NOTICE contrack-tools[1376]: helper `mdns' configured
successfully
2024-04-26T14:31:34.275065Z NOTICE contrack-tools[1376]: configuring helper `ssdp' with
queuenum=5 and queuelen=10240
2024-04-26T14:31:34.275085Z NOTICE contrack-tools[1376]: policy name=ssdp
expect_timeout=300 expect_max=8
2024-04-26T14:31:34.275265Z NOTICE contrack-tools[1376]: helper `ssdp' configured
successfully
2024-04-26T14:31:34.275284Z NOTICE contrack-tools[1376]: configuring helper `ssdp' with
queuenum=5 and queuelen=10240
2024-04-26T14:31:34.275299Z NOTICE contrack-tools[1376]: policy name=ssdp
expect_timeout=300 expect_max=8
2024-04-26T14:31:34.275335Z NOTICE contrack-tools[1376]: helper `ssdp' configured
successfully
2024-04-26T14:31:34.275351Z NOTICE contrack-tools[1376]: initialization completed
2024-04-26T14:31:34.275384Z NOTICE contrack-tools[1376]: -- starting in console mode --
2024-04-26T14:31:34.276055Z INFO avahi-daemon[1277]: avahi-daemon 0.8 starting up.
2024-04-26T14:31:34.278212Z ERR contrack-tools[1376]: failed to process message
2024-04-26T14:31:34.295707Z INFO avahi-daemon[1277]: Successfully called chroot().
2024-04-26T14:31:34.295817Z INFO avahi-daemon[1277]: Successfully dropped remaining
capabilities.
2024-04-26T14:31:34.301704Z ERR avahi-daemon[1398]: chroot.c: open() failed: No such file
or directory
2024-04-26T14:31:34.302044Z WARNING avahi-daemon[1277]: Failed to open /etc/resolv.conf:
Invalid argument
2024-04-26T14:31:34.302620Z INFO avahi-daemon[1277]: No service file found in
/etc/avahi/services.
2024-04-26T14:31:34.304143Z INFO avahi-daemon[1277]: Joining mDNS multicast group on
interface lo.IPv4 with address 127.0.0.1.
2024-04-26T14:31:34.304181Z INFO avahi-daemon[1277]: New relevant interface lo.IPv4 for
mDNS.
2024-04-26T14:31:34.304232Z INFO avahi-daemon[1277]: Network interface enumeration
completed.
2024-04-26T14:31:34.304297Z INFO avahi-daemon[1277]: Registering new address record for
127.0.0.1 on lo.IPv4.
2024-04-26T14:31:34.307804Z WARNING secanomalyd[1296]: Landlock is not supported by the
kernel.
2024-04-26T14:31:34.357676Z WARNING kernel: [ 48.015763] -----[ cut here ]-----
-----
2024-04-26T14:31:34.357699Z WARNING kernel: [ 48.017426] refcount_t: underflow; use-
after-free.
2024-04-26T14:31:34.357702Z WARNING kernel: [ 48.019718] WARNING: CPU: 1 PID: 1097 at
lib/refcount.c:28 refcount_warn_saturate+0xba/0x104
2024-04-26T14:31:34.361943Z WARNING kernel: [ 48.023007] Modules linked in:
ip6table_nat fuse 8021q bluetooth cfg80211 ecdh_generic ecc e1000 lzo_rle lzo_compress
```

zram joydev

2024-04-26T14:31:34.384041Z WARNING kernel: [48.036590] CPU: 1 PID: 1097 Comm: chrome Tainted: G W 5.15.108-18907-gba143be42d3a-dirty #1

2024-04-26T14:31:34.384067Z WARNING kernel: [48.041325] Hardware name: VMware, Inc. VMware7,1/440BX Desktop Reference Platform, BIOS VMW71.00V.21805430.B64.2305221826 05/22/2023

2024-04-26T14:31:34.384072Z WARNING kernel: [48.045332] RIP: 0010:refcount_warn_saturate+0xba/0x104

2024-04-26T14:31:34.384075Z WARNING kernel: [48.046978] Code: c7 29 a1 e6 83 e8 9d 4f ea ff 0f 0b eb 49 80 3d c7 f0 2f 01 00 75 40 c6 05 be f0 2f 01 01 48 c7 c7 6c 63 f0 83 e8 7d 4f ea ff <0f> 0b eb 29 80 3d a4 f0 2f 01 00 75 20 c6 05 9b f0 2f 01 01 48 c7

2024-04-26T14:31:34.399696Z WARNING kernel: [48.052830] RSP: 0018:ffff9244809afad8 EFLAGS: 00010246

2024-04-26T14:31:34.399892Z WARNING kernel: [48.055393] RAX: d094c433f16c1600 RBX: fffff88be31017a00 RCX: ffffffff8405daa8

2024-04-26T14:31:34.399899Z WARNING kernel: [48.058759] RDX: ffff9244809af8b8 RSI: 0000000000000000 RDI: 0000000000000001

2024-04-26T14:31:34.399902Z WARNING kernel: [48.060652] RBP: ffff9244809afad8 R08: 0000000000000000 R09: ffff9244809af8b0

2024-04-26T14:31:34.403676Z WARNING kernel: [48.066041] R10: 00000000ffffdfff R11: ffffffff8408dd50 R12: ffff88be03402a44

2024-04-26T14:31:34.437134Z WARNING kernel: [48.082913] R13: ffff88be0088a000 R14: ffff88be31017a00 R15: 0000000000000002

2024-04-26T14:31:34.437158Z WARNING kernel: [48.085234] FS: 00007ea287223040(0000) GS:ffff88bec3440000(0000) knlGS:0000000000000000

2024-04-26T14:31:34.437162Z WARNING kernel: [48.100499] CS: 0010 DS: 0000 ES: 0000 CR0: 0000000080050033

2024-04-26T14:31:34.446127Z WARNING kernel: [48.107456] CR2: 00007b4095aecb10 CR3: 0000000120e2a002 CR4: 00000000003706e0

2024-04-26T14:31:34.456112Z INFO root[1418]: fydeos-license-utils get disk /dev/nvme0n1 serial by lsblk

2024-04-26T14:31:34.482721Z INFO root[1420]: fydeos-license-utils get fix id by disk serial

2024-04-26T14:31:34.491701Z WARNING kernel: [48.147773] Call Trace:

2024-04-26T14:31:34.491718Z WARNING kernel: [48.148483] <TASK>

2024-04-26T14:31:34.491722Z WARNING kernel: [48.149240]

vmw_user_bo_noref_lookup+0x7b/0xb4

2024-04-26T14:31:34.491724Z WARNING kernel: [48.152022]

vmw_translate_mob_ptr+0x34/0xfc

2024-04-26T14:31:34.491726Z WARNING kernel: [48.153144]

vmw_cmd_res_switch_backup+0x4e/0x96

2024-04-26T14:31:34.491729Z WARNING kernel: [48.154292]

vmw_cmd_dx_bind_shader+0x110/0x143

2024-04-26T14:31:34.491732Z WARNING kernel: [48.155753]

vmw_execbuf_process+0x55d/0xf8c

2024-04-26T14:31:34.519068Z WARNING kernel: [48.181666] ?

avc_has_extended_perms+0x297/0x4c8

2024-04-26T14:31:34.531088Z WARNING kernel: [48.186096] vmw_execbuf_ioctl+0x67/0x11d

2024-04-26T14:31:34.548082Z WARNING kernel: [48.200309] ?

vmw_execbuf_release_pinned_bo+0x3e/0x3e

2024-04-26T14:31:34.548106Z WARNING kernel: [48.209346] drm_ioctl_kernel+0xd9/0x14c

2024-04-26T14:31:34.562697Z WARNING kernel: [48.223830] drm_ioctl+0x23c/0x3a4

2024-04-26T14:31:34.562726Z WARNING kernel: [48.225319] ?

vmw_execbuf_release_pinned_bo+0x3e/0x3e

2024-04-26T14:31:34.564435Z WARNING kernel: [48.227666] __x64_sys_ioctl+0x7b/0xc8

2024-04-26T14:31:34.564456Z WARNING kernel: [48.228911] do_syscall_64+0x58/0xa5

2024-04-26T14:31:34.567801Z WARNING kernel: [48.230611]

entry_SYSCALL_64_after_hwframe+0x5c/0xc6

2024-04-26T14:31:34.571312Z WARNING kernel: [48.234816] RIP: 0033:0x7ea287a29649

2024-04-26T14:31:34.571333Z WARNING kernel: [48.235786] Code: 04 25 28 00 00 00 48 89 45 c8 31 c0 48 8d 45 10 c7 45 b0 10 00 00 00 48 89 45 b8 48 8d 45 d0 48 89 45 c0 b8 10 00 00 00 0f 05 <41> 89 c0 3d 00 f0 ff ff 77 1d 48 8b 45 c8 64 48 2b 04 25 28 00 00

2024-04-26T14:31:34.583717Z WARNING kernel: [48.245416] RSP: 002b:00007fff5531b9d0

EFLAGS: 00000246 ORIG_RAX: 0000000000000010

2024-04-26T14:31:34.583757Z WARNING kernel: [48.248236] RAX: ffffffffda RBX:

0000000000000000 RCX: 00007ea287a29649

2024-04-26T14:31:34.613194Z WARNING kernel: [48.250406] RDX: 00007fff5531ba88 RSI:

000000004028644c RDI: 000000000000000d

2024-04-26T14:31:34.613221Z WARNING kernel: [48.271006] RBP: 00007fff5531ba20 R08:

```

00000000000000d10 R09: 00007fff5531bb38
2024-04-26T14:31:34.613224Z WARNING kernel: [ 48.276090] R10: 0000000000000003 R11:
00000000000000246 R12: 000000000000000d
2024-04-26T14:31:34.624144Z WARNING kernel: [ 48.285807] R13: 00007fff5531bb88 R14:
000000004028644c R15: 00007fff5531ba88
2024-04-26T14:31:34.628172Z WARNING kernel: [ 48.291901] </TASK>
2024-04-26T14:31:34.630062Z WARNING kernel: [ 48.292700] ---[ end trace
cd219e6f9c779229 ]---
2024-04-26T14:31:34.738624Z INFO cras_server[1368]: cras_feature_tier initialized with
board="FydeOS" cpu="Intel(R)_Core(TM)_m3-8100Y_CPU_@_1.10GHz"
2024-04-26T14:31:35.110781Z INFO dlcservice[1321]: INFO dlcservice: [dlc_service.cc(92)]
Update Engine service available=1
2024-04-26T14:31:35.113549Z INFO dlcservice[1321]: INFO dlcservice: [dlc_service.cc(388)]
Got update_engine status: IDLE
2024-04-26T14:31:35.185180Z INFO avahi-daemon[1277]: Server startup complete. Host name
is 57ba6badfd23b79c094dcc3b662bbac2.local. Local service cookie is 3366612485.
2024-04-26T14:31:35.905510Z WARNING kernel: [ 49.537408] -----[ cut here ]-----
-----
2024-04-26T14:31:35.905535Z WARNING kernel: [ 49.545690] refcount_t: saturated; leaking
memory.
2024-04-26T14:31:35.905540Z WARNING kernel: [ 49.565088] WARNING: CPU: 3 PID: 1097 at
lib/refcount.c:22 refcount_warn_saturate+0x7a/0x104
2024-04-26T14:31:35.963410Z WARNING kernel: [ 49.579894] Modules linked in:
ip6table_nat fuse 8021q bluetooth cfg80211 ecdh_generic ecc e1000 lzo_rle lzo_compress
zram joydev
2024-04-26T14:31:35.963481Z WARNING kernel: [ 49.586443] CPU: 3 PID: 1097 Comm: chrome
Tainted: G W 5.15.108-18907-gba143be42d3a-dirty #1
2024-04-26T14:31:35.963487Z WARNING kernel: [ 49.610035] Hardware name: VMware, Inc.
VMware7,1/440BX Desktop Reference Platform, BIOS VMW71.00V.21805430.B64.2305221826
05/22/2023
2024-04-26T14:31:35.963490Z WARNING kernel: [ 49.625980] RIP:
0010:refcount_warn_saturate+0x7a/0x104
2024-04-26T14:31:36.000617Z WARNING kernel: [ 49.647248] Code: 6d 83 fe 01 0f 85 84 00
00 00 80 3d 09 f1 2f 01 00 0f 85 80 00 00 00 c6 05 fc f0 2f 01 01 48 c7 c7 44 63 f0 83 e8
bd 4f ea ff <0f> 0b eb 69 80 3d e6 f0 2f 01 00 75 60 c6 05 dd f0 2f 01 01 48 c7
2024-04-26T14:31:36.000683Z WARNING kernel: [ 49.661205] RSP: 0018:ffff9244809afa60
EFLAGS: 00010246
2024-04-26T14:31:36.000689Z WARNING kernel: [ 49.663227] RAX: d094c433f16c1600 RBX:
0000000000000001 RCX: ffffffff8405daa8
2024-04-26T14:31:36.004134Z WARNING kernel: [ 49.665978] RDX: ffff9244809af838 RSI:
0000000000000000 RDI: 0000000000000001
2024-04-26T14:31:36.004160Z WARNING kernel: [ 49.668622] RBP: ffff9244809afa60 R08:
0000000000000000 R09: ffff9244809af830
2024-04-26T14:31:36.032432Z WARNING kernel: [ 49.682973] R10: 00000000ffffdfff R11:
ffffffffff8408dd50 R12: ffff88be09506c40
2024-04-26T14:31:36.032452Z WARNING kernel: [ 49.687057] R13: ffff88be31017a00 R14:
0000000000000000 R15: ffff9244809afac4
2024-04-26T14:31:36.032456Z WARNING kernel: [ 49.695816] FS: 00007ea287223040(0000)
GS:ffff88bec34c0000(0000) knlGS:0000000000000000
2024-04-26T14:31:36.108833Z WARNING kernel: [ 49.714138] CS: 0010 DS: 0000 ES: 0000
CR0: 0000000080050033
2024-04-26T14:31:36.108860Z WARNING kernel: [ 49.736382] CR2: 00002aa00232c000 CR3:
0000000120e2a003 CR4: 0000000003706e0
2024-04-26T14:31:36.108866Z WARNING kernel: [ 49.739579] Call Trace:
2024-04-26T14:31:36.108869Z WARNING kernel: [ 49.740467] <TASK>
2024-04-26T14:31:36.108871Z WARNING kernel: [ 49.741321] objects_lookup+0x92/0xc6
2024-04-26T14:31:36.108873Z WARNING kernel: [ 49.743198]
drm_gem_object_lookup+0x3c/0x5e
2024-04-26T14:31:36.108875Z WARNING kernel: [ 49.746089]
vmw_user_bo_noref_lookup+0x16/0xb4
2024-04-26T14:31:36.108877Z WARNING kernel: [ 49.751486]
vmw_translate_mob_ptr+0x34/0xfc
2024-04-26T14:31:36.108880Z WARNING kernel: [ 49.754241]
vmw_cmd_res_switch_backup+0x4e/0x96
2024-04-26T14:31:36.108883Z WARNING kernel: [ 49.757563]
vmw_cmd_dx_bind_shader+0x110/0x143
2024-04-26T14:31:36.108886Z WARNING kernel: [ 49.759242]
vmw_execbuf_process+0x55d/0xf8c
2024-04-26T14:31:36.108888Z WARNING kernel: [ 49.760935] ?

```

```
avc_has_extended_perms+0x297/0x4c8
2024-04-26T14:31:36.108891Z WARNING kernel: [ 49.762752] vmw_execbuf_ioctl+0x67/0x11d
2024-04-26T14:31:36.108893Z WARNING kernel: [ 49.764293] ?
vmw_execbuf_release_pinned_bo+0x3e/0x3e
2024-04-26T14:31:36.108896Z WARNING kernel: [ 49.766382] drm_ioctl_kernel+0xd9/0x14c
2024-04-26T14:31:36.108898Z WARNING kernel: [ 49.767881] drm_ioctl+0x23c/0x3a4
2024-04-26T14:31:36.108901Z WARNING kernel: [ 49.769288] ?
vmw_execbuf_release_pinned_bo+0x3e/0x3e
2024-04-26T14:31:36.108905Z WARNING kernel: [ 49.772168] __x64_sys_ioctl+0x7b/0xc8
2024-04-26T14:31:36.135751Z WARNING kernel: [ 49.773760] do_syscall_64+0x58/0xa5
2024-04-26T14:31:36.135946Z WARNING kernel: [ 49.800248]
entry_SYSCALL_64_after_hwframe+0x5c/0xc6
2024-04-26T14:31:36.145415Z WARNING kernel: [ 49.806948] RIP: 0033:0x7ea287a29649
2024-04-26T14:31:36.145456Z WARNING kernel: [ 49.809890] Code: 04 25 28 00 00 00 48 89
45 c8 31 c0 48 8d 45 10 c7 45 b0 10 00 00 00 48 89 45 b8 48 8d 45 d0 48 89 45 c0 b8 10 00
00 00 0f 05 <41> 89 c0 3d 00 f0 ff ff 77 1d 48 8b 45 c8 64 48 2b 04 25 28 00 00
2024-04-26T14:31:36.165404Z WARNING kernel: [ 49.826482] RSP: 002b:00007fff5531b9d0
EFLAGS: 00000246 ORIG_RAX: 0000000000000010
2024-04-26T14:31:36.165455Z WARNING kernel: [ 49.829662] RAX: ffffffffda RBX:
0000000000000000 RCX: 00007ea287a29649
2024-04-26T14:31:36.178374Z WARNING kernel: [ 49.835192] RDX: 00007fff5531ba88 RSI:
000000004028644c RDI: 000000000000000d
2024-04-26T14:31:36.178402Z WARNING kernel: [ 49.842638] RBP: 00007fff5531ba20 R08:
00000000000000928 R09: 00007fff5531bb38
2024-04-26T14:31:36.187864Z WARNING kernel: [ 49.845491] R10: 0000000000000003 R11:
0000000000000246 R12: 000000000000000d
2024-04-26T14:31:36.187999Z WARNING kernel: [ 49.852337] R13: 00007fff5531bb88 R14:
000000004028644c R15: 00007fff5531ba88
2024-04-26T14:31:36.198490Z WARNING kernel: [ 49.858561] </TASK>
2024-04-26T14:31:36.201813Z WARNING kernel: [ 49.863782] ---[ end trace
cd219e6f9c77922a ]---
2024-04-26T14:31:37.595444Z INFO dbus-daemon[583]: [system] Activating service
name='org.chromium.MachineLearning' requested by ':1.41' (uid=1000 pid=1044
comm="/opt/google/chrome/chrome --enable-webgl-image-chr" label="u:r:cros_browser:s0")
(using servicehelper)
2024-04-26T14:31:37.750598Z INFO kernel: [ 51.397787] loop7: detected capacity change
from 0 to 12728
2024-04-26T14:31:37.822326Z NOTICE ml-service[1836]: Pre-start ml-service
task=mojo_service
2024-04-26T14:31:38.001975Z NOTICE ml-service[1861]: ERROR: system services not running,
quit.
2024-04-26T14:31:38.121836Z NOTICE ml-service[1870]: Post-stop ml-service
task=mojo_service
2024-04-26T14:31:38.657213Z ERR patchpaneld[1230]: ERROR patchpaneld: [datapath.cc(416)]
Failed to create fwmark tagging rule for uid {source: UPDATE_ENGINE, uid: , classid:
65537, is_on_vpn: false} in apply_local_source_mark
2024-04-26T14:31:39.948827Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:31:39.951660Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:31:39.951689Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T14:31:39.951709Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T14:31:39.951992Z INFO dlcservice[1321]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:31:39.952626Z WARNING cras_server[1368]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:31:39.952843Z ERR cras_server[1368]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:31:39.952885Z ERR cras_server[1368]: download_supported_dlc: retry 1 times
2024-04-26T14:31:41.064359Z INFO kernel: [ 54.723559] IPv6: ADDRCONF(NETDEV_CHANGE):
arc_ns0: link becomes ready
2024-04-26T14:31:41.064386Z INFO kernel: [ 54.726327] IPv6: ADDRCONF(NETDEV_CHANGE):
veth0: link becomes ready
2024-04-26T14:31:42.497052Z INFO kernel: [ 56.152532] IPv6: ADDRCONF(NETDEV_CHANGE):
arc_ns1: link becomes ready
```



```
2024-04-26T14:31:42.497082Z INFO kernel: [ 56.157065] IPv6: ADDRCONF(NETDEV_CHANGE):
veth1: link becomes ready
2024-04-26T14:31:43.411893Z CRIT root[2518]: No new logout-started signal received after
10 seconds.
2024-04-26T14:31:45.098855Z INFO kernel: [ 58.727527] pci 0000:00:07.3: attach allowed
to drvr piix4_smbus [internal device]
2024-04-26T14:31:45.098883Z ERR kernel: [ 58.745977] piix4_smbus 0000:00:07.3: SMBus
base address uninitialized - upgrade BIOS or use force_addr=0xaddr
2024-04-26T14:31:45.498835Z INFO minijail0[834]: libminijail[834]: child process 835
exited with status 1
2024-04-26T14:31:45.994873Z ERR usb_bouncer[2810]: Owner uid is 0 instead of 20124
2024-04-26T14:31:46.417963Z ERR usb_bouncer[2896]: No active user session.
2024-04-26T14:31:46.546815Z ERR usb_bouncer[2914]: No active user session.
2024-04-26T14:31:47.316902Z ERR usb_bouncer[3014]: No active user session.
2024-04-26T14:31:47.372568Z ERR usb_bouncer[3021]: No active user session.
2024-04-26T14:31:47.453107Z INFO kernel: [ 61.114138] pci 0000:02:02.0: attach allowed
to drvr snd_hda_intel [internal device]
2024-04-26T14:31:47.499208Z WARNING kernel: [ 61.153132] udevd[1469]: Process
'/bin/chown resourced:resourced /sys/devices/system/cpu/cpu1/cpufreq/scaling_governor'
failed with exit code 1.
2024-04-26T14:31:47.499239Z ERR kernel: [ 61.159113] snd_hda_intel 0000:02:02.0: CORB
reset timeout#1, CORBRP = 0
2024-04-26T14:31:47.605064Z WARNING kernel: [ 61.244025] udevd[1493]: Process
'/bin/chown resourced:resourced /sys/devices/system/cpu/cpu3/cpufreq/scaling_governor'
failed with exit code 1.
2024-04-26T14:31:47.605094Z WARNING kernel: [ 61.263770] udevd[1476]: Process
'/bin/chown resourced:resourced /sys/devices/system/cpu/cpu0/cpufreq/scaling_governor'
failed with exit code 1.
2024-04-26T14:31:47.715064Z WARNING kernel: [ 61.372402] udevd[1468]: Process
'/bin/chown resourced:resourced /sys/devices/system/cpu/cpu2/cpufreq/scaling_governor'
failed with exit code 1.
2024-04-26T14:31:47.733776Z WARNING kernel: [ 61.381112] udevd[1457]: Process
'/bin/chown -R root:wilco_dtc /sys/firmware/dmi/tables' failed with exit code 1.
2024-04-26T14:31:47.775843Z INFO kernel: [ 61.417712] snd_hda_codec_generic
hdaudioC0D0: autoconfig for Generic: line_outs=4 (0x14/0x15/0x16/0x17/0x0) type:line
2024-04-26T14:31:47.775873Z INFO kernel: [ 61.434365] snd_hda_codec_generic
hdaudioC0D0: speaker_outs=0 (0x0/0x0/0x0/0x0/0x0)
2024-04-26T14:31:47.775878Z INFO kernel: [ 61.440106] snd_hda_codec_generic
hdaudioC0D0: hp_outs=0 (0x0/0x0/0x0/0x0/0x0)
2024-04-26T14:31:47.781268Z INFO kernel: [ 61.443398] snd_hda_codec_generic
hdaudioC0D0: mono: mono_out=0x0
2024-04-26T14:31:47.781306Z INFO kernel: [ 61.445752] snd_hda_codec_generic
hdaudioC0D0: inputs:
2024-04-26T14:31:47.790712Z INFO kernel: [ 61.447865] snd_hda_codec_generic
hdaudioC0D0: Mic=0x18
2024-04-26T14:31:47.848069Z INFO kernel: [ 61.508097] input: HD-Audio Generic Mic as
/devices/pci0000:00/0000:00:11.0/0000:02:02.0/sound/card0/input6
2024-04-26T14:31:47.858052Z INFO kernel: [ 61.512968] input: HD-Audio Generic Line Out
Front as /devices/pci0000:00/0000:00:11.0/0000:02:02.0/sound/card0/input7
2024-04-26T14:31:47.874097Z INFO kernel: [ 61.522788] input: HD-Audio Generic Line Out
Surround as /devices/pci0000:00/0000:00:11.0/0000:02:02.0/sound/card0/input8
2024-04-26T14:31:47.887461Z INFO kernel: [ 61.540282] input: HD-Audio Generic Line Out
CLFE as /devices/pci0000:00/0000:00:11.0/0000:02:02.0/sound/card0/input9
2024-04-26T14:31:47.887488Z INFO kernel: [ 61.546259] input: HD-Audio Generic Line Out
Side as /devices/pci0000:00/0000:00:11.0/0000:02:02.0/sound/card0/input10
2024-04-26T14:31:47.930803Z ERR usb_bouncer[3117]: No active user session.
2024-04-26T14:31:48.771058Z DEBUG kernel: [ 62.435366] usb 2-2.1: GPIO lookup for
consumer reset
2024-04-26T14:31:48.771085Z DEBUG kernel: [ 62.435375] usb 2-2.1: using lookup tables
for GPIO lookup
2024-04-26T14:31:48.771089Z DEBUG kernel: [ 62.435378] usb 2-2.1: No GPIO consumer
reset found
2024-04-26T14:31:48.806736Z INFO kernel: [ 62.435788] usbcore: registered new interface
driver btusb
2024-04-26T14:31:49.174891Z WARNING cras_server[1368]: [alsa-lib] uc_mgr_config_load() ->
could not open configuration file /usr/share/alsa/ucm2/HD-Audio Generic/HD-Audio
Generic.conf
2024-04-26T14:31:49.174942Z WARNING cras_server[1368]: [alsa-lib] load_master_config() ->
error: could not parse configuration for card HD-Audio Generic
```

```
2024-04-26T14:31:49.174972Z WARNING cras_server[1368]: [alsa-lib] snd_use_case_mgr_open()
-> error: failed to import HD-Audio Generic use case configuration -2
2024-04-26T14:31:49.174986Z WARNING cras_server[1368]: Can not open ucm for card HD-Audio
Generic, rc = -2
2024-04-26T14:31:49.174997Z WARNING cras_server[1368]: No ucm config on internal card HD-
Audio Generic
2024-04-26T14:31:49.245896Z INFO permission_broker[1266]:
ProcessPath(/dev/bus/usb/002/004)
2024-04-26T14:31:49.354957Z ERR kernel: [ 63.014184] Bluetooth: hci0: unexpected cc
0x0c12 length: 2 < 3
2024-04-26T14:31:49.355012Z ERR kernel: [ 63.016756] Bluetooth: hci0: Opcode 0x c12
failed: -38
2024-04-26T14:31:50.211066Z INFO kernel: [ 63.872946] NET: Registered PF_VSOCK protocol
family
2024-04-26T14:31:50.210719Z INFO minijail0[3246]: libminijail[3246]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:50.215081Z WARNING minijail0[3246]: libminijail[3246]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:50.215095Z WARNING minijail0[3246]: libminijail[3246]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:50.215181Z WARNING minijail0[3281]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:50.215193Z WARNING minijail0[3281]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:50.215203Z INFO minijail0[3281]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:50.219064Z WARNING minijail0[3282]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:50.219096Z WARNING minijail0[3282]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:50.219107Z INFO minijail0[3282]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:50.220428Z WARNING minijail0[3198]: libminijail[3198]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:50.220487Z WARNING minijail0[3198]: libminijail[3198]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:50.376562Z NOTICE temp_logger[3337]: Exiting temp_logger, system does
not have any temp sensor.
2024-04-26T14:31:50.396212Z NOTICE /usr/share/cros/init/crx-import.sh[3349]: CRX Cache
exists. No import performed.
2024-04-26T14:31:50.437747Z NOTICE send-boot-metrics[3368]: Missing timestamp in firmware
log
2024-04-26T14:31:50.438749Z INFO minijail0[3196]: libminijail[3196]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:50.441616Z WARNING minijail0[3196]: libminijail[3196]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:50.441627Z WARNING minijail0[3196]: libminijail[3196]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:50.441957Z WARNING minijail0[3369]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:50.441966Z WARNING minijail0[3369]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:50.441975Z INFO minijail0[3369]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:50.490826Z NOTICE chromeos-startup[3361]: 2024-04-26T14:30:55.964120Z
WARNING chromeos_startup: [chromeos_startup.cc(793)] Failed to get boot information from
crossystem
2024-04-26T14:31:50.490891Z NOTICE chromeos-startup[3361]: 2024-04-26T14:30:57.147740Z
ERROR chromeos_startup: [safe_fd.cc(701)] unlinkat failed: No such file or directory (2)
2024-04-26T14:31:50.490901Z NOTICE chromeos-startup[3361]: 2024-04-26T14:30:57.219115Z
WARNING chromeos_startup: [chromeos_startup.cc(703)] Unable to collect early logs and
crashes.: No such file or directory (2)
2024-04-26T14:31:50.572921Z WARNING minijail0[3384]: libminijail[3384]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:50.572939Z WARNING minijail0[3278]: libminijail[3278]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:50.572941Z WARNING minijail0[3384]: libminijail[3384]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:50.572951Z WARNING minijail0[3278]: libminijail[3278]: Landlock is not
```

```
supported by the current kernel: Function not implemented
2024-04-26T14:31:50.572952Z INFO minijail0[3384]: libminijail[3384]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:50.602974Z INFO minijail0[3283]: libminijail[3283]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:50.725812Z INFO permission_broker[1266]: AllowUsbDeviceRule: ALLOW
2024-04-26T14:31:50.726166Z INFO permission_broker[1266]: AllowTtyDeviceRule: IGNORE
2024-04-26T14:31:50.738901Z WARNING minijail0[3283]: libminijail[3283]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:50.738989Z WARNING minijail0[3283]: libminijail[3283]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:50.740916Z WARNING minijail0[3425]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:50.740979Z WARNING minijail0[3425]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:50.740991Z INFO minijail0[3425]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:50.743768Z INFO u2fd[3369]: INFO u2fd: [main.cc(34)] Daemon version
0.0.1-r1817-635ba60101
2024-04-26T14:31:50.758852Z INFO permission_broker[1266]: Found claimed interface with
driver: btusb
2024-04-26T14:31:50.765626Z INFO permission_broker[1266]: Found claimed interface with
driver: btusb
2024-04-26T14:31:50.784477Z INFO permission_broker[1266]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T14:31:50.787106Z INFO permission_broker[1266]: Verdict for
/dev/bus/usb/002/004: DENY
2024-04-26T14:31:50.836778Z INFO u2fd[3369]: INFO u2fd: [u2f_daemon.cc(367)] Requested
Mode: Policy[unset], force_u2f[0], force_g2f[0]
2024-04-26T14:31:50.837150Z INFO u2fd[3369]: INFO u2fd: [u2f_daemon.cc(381)] Mode:
Disabled (not supported)
2024-04-26T14:31:50.838916Z INFO minijail0[3475]: libminijail[3475]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:50.893219Z INFO permission_broker[1266]:
ProcessPath(/dev/bus/usb/002/004)
2024-04-26T14:31:50.904434Z WARNING minijail0[3364]: libminijail[3364]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:50.904456Z WARNING minijail0[3364]: libminijail[3364]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:50.905165Z WARNING minijail0[3484]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:50.905184Z WARNING minijail0[3484]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:50.905197Z INFO minijail0[3484]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:50.916758Z INFO missed[3476]: Starting Missive Service.
2024-04-26T14:31:50.943363Z INFO resourced[3426]: Starting resourced
2024-04-26T14:31:50.960811Z WARNING missed[3476]: Service became available
2024-04-26T14:31:50.962310Z WARNING missed[3476]: Parameters updated
2024-04-26T14:31:50.970445Z WARNING missed[3476]: Flag `controlled_degradation` is
initially disabled
2024-04-26T14:31:50.970961Z WARNING missed[3476]: Flag `compression` is initially
enabled
2024-04-26T14:31:50.971176Z WARNING missed[3476]: Flag `encryption` is initially
enabled
2024-04-26T14:31:50.971612Z WARNING missed[3476]: Flag `legacy_storage_enabled` is
initially enabled
2024-04-26T14:31:50.974143Z WARNING missed[3476]: Encryption is enabled, but the key is
not available yet, status=NOT_FOUND:No valid encryption key found
2024-04-26T14:31:51.050174Z NOTICE mount-vmware-share[3565]: mount vmware /run/vmware-
share
2024-04-26T14:31:51.081233Z INFO minijail0[3264]: libminijail[3264]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:51.255281Z INFO minijail0[3596]: libminijail[3596]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:51.292830Z INFO minijail0[3594]: libminijail[3594]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:53.793564Z INFO root[3636]: fydeos-license-utils get disk /dev/nvme0n1
serial by lsblk
```

```
2024-04-26T14:31:53.812801Z INFO root[3639]: fydeos-license-utils get fix id by disk
serial
2024-04-26T14:31:53.920548Z INFO minijail0[3657]: libminijail[3657]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:53.978289Z INFO session_manager[987]: INFO session_manager:
[device_identifiler_generator.cc(132)] Stable device secret missing!
2024-04-26T14:31:53.978562Z ERR session_manager[987]: ERROR session_manager:
[device_identifiler_generator.cc(263)] No stable device secret available.
2024-04-26T14:31:54.015578Z INFO minijail0[3669]: libminijail[3669]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:54.026143Z WARNING minijail0[3669]: libminijail[3669]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:54.026526Z WARNING minijail0[3669]: libminijail[3669]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:54.031635Z WARNING minijail0[3670]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:54.031881Z WARNING minijail0[3670]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:54.032287Z INFO minijail0[3670]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:54.093265Z INFO minijail0[3676]: libminijail[3676]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:54.186484Z INFO minijail0[3687]: libminijail[3687]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:54.212662Z INFO crash_reporter[3677]: Running boot collector
2024-04-26T14:31:54.212981Z INFO crash_reporter[3677]: developer build - not testing -
always dumping
2024-04-26T14:31:54.213180Z INFO crash_reporter[3677]: Unsupported GSC present on board.
Unable to query GSC crashes.
2024-04-26T14:31:54.213248Z INFO crash_reporter[3677]: Failed to get the GSC flog output.
2024-04-26T14:31:54.213415Z INFO crash_reporter[3677]: Enabling kernel crash handling
2024-04-26T14:31:54.213616Z INFO crash_reporter[3677]: Found 0 kernel crashes in efi-
pstore.
2024-04-26T14:31:54.213693Z INFO crash_reporter[3677]: /sys/firmware/log does not exist,
skipping BIOS crash check. (This is normal for older boards.)
2024-04-26T14:31:54.213778Z WARNING crash_reporter[3677]: No console-ramoops file found
after watchdog reset
2024-04-26T14:31:54.214239Z INFO crash_reporter[3677]: Examining
/run/crash_reporter/crash for crashes
2024-04-26T14:31:54.214339Z INFO crash_reporter[3677]: Examining
/mnt/stateful_partition/reboot_vault/crash for crashes
2024-04-26T14:31:54.258056Z INFO permission_broker[1266]: AllowUsbDeviceRule: ALLOW
2024-04-26T14:31:54.258226Z INFO permission_broker[1266]: AllowTtyDeviceRule: IGNORE
2024-04-26T14:31:54.268467Z INFO permission_broker[1266]: Found claimed interface with
driver: btusb
2024-04-26T14:31:54.290718Z INFO permission_broker[1266]: Found claimed interface with
driver: btusb
2024-04-26T14:31:54.291549Z NOTICE dbus-daemon[583]: [system] Rejected send message, 2
matched rules; type="method_call", sender=":1.111" (uid=20130 pid=3617
comm="/usr/libexec/fwupd/fwupd " label="u:r:cros_fwupd:s0")
interface="org.freedesktop.DBus.ObjectManager" member="GetManagedObjects" error name="
(unset)" requested_reply="0" destination=":1.26" (uid=218 pid=778
comm="/usr/libexec/bluetooth/bluetoothd --nodetach --co" label="u:r:cros_bluetoothd:s0")
2024-04-26T14:31:54.294219Z INFO permission_broker[1266]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T14:31:54.294306Z INFO permission_broker[1266]: Verdict for
/dev/bus/usb/002/004: DENY
2024-04-26T14:31:54.295094Z INFO permission_broker[1266]:
ProcessPath(/dev/bus/usb/002/002)
2024-04-26T14:31:54.375826Z INFO minijail0[3687]: libminijail[3687]: child process 3688
exited with status 1
2024-04-26T14:31:54.377499Z INFO minijail0[3706]: libminijail[3706]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:54.378576Z ERR debugd[3650]: RunHelper(...): Domain=dbus,
Code=org.chromium.debugd.SchedulerConfigurationPolicyError, Message=ERROR
scheduler_configuration_helper: [scheduler_configuration_utils.cc(276)] Failed to open:
/sys/devices/system/cpu/cpu1/online: Permission denied (13)#012ERROR
scheduler_configuration_helper: [scheduler_configuration_helper.cc(118)] Failed to open
CPU control files.#012
```

```
2024-04-26T14:31:54.378713Z ERR debugd[3650]: SetPolicy(...): Domain=dbus,
Code=org.chromium.debugd.SchedulerConfigurationPolicyError,
Message=scheduler_configuration_helper failed: stdout=
2024-04-26T14:31:54.391378Z INFO minijail0[3709]: libminijail[3709]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:31:54.393128Z WARNING minijail0[3706]: libminijail[3706]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:54.394636Z WARNING minijail0[3706]: libminijail[3706]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:54.395304Z WARNING minijail0[3708]: libminijail[3708]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:54.395468Z WARNING minijail0[3708]: libminijail[3708]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:54.395592Z INFO minijail0[3708]: libminijail[3708]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:54.435197Z INFO session_manager[987]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting start-arc-instance Upstart signal
2024-04-26T14:31:54.438928Z WARNING minijail0[3715]: libminijail[3715]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:54.438930Z WARNING minijail0[3717]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:54.438949Z WARNING minijail0[3715]: libminijail[3715]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:54.438950Z WARNING minijail0[3717]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:54.438962Z INFO minijail0[3717]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:54.448646Z INFO session_manager[987]: INFO session_manager:
[android_oci_wrapper.cc(125)] run_oci PID: 3720
2024-04-26T14:31:54.527949Z ERR debugd[3650]: AllowToolUse(...): Domain=dbus,
Code=org.chromium.debugd.error.AccessDenied, Message=Unavailable after device has an
owner or boot lockbox is finalized.
2024-04-26T14:31:54.646646Z WARNING minijail0[3734]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:31:54.646671Z WARNING minijail0[3734]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:54.646685Z INFO minijail0[3734]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:31:54.647693Z WARNING minijail0[3719]: libminijail[3719]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:54.647736Z WARNING minijail0[3719]: libminijail[3719]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:54.796002Z WARNING memd[3725]: memd started
2024-04-26T14:31:54.886391Z WARNING metrics_daemon[3708]: WARNING metrics_daemon:
[vmlog_writer.cc(464)] Failed to open scaling_cur_freq for logical core 0: No such file
or directory (2)
2024-04-26T14:31:54.886468Z WARNING metrics_daemon[3708]: WARNING metrics_daemon:
[vmlog_writer.cc(464)] Failed to open scaling_cur_freq for logical core 1: No such file
or directory (2)
2024-04-26T14:31:54.886506Z WARNING metrics_daemon[3708]: WARNING metrics_daemon:
[vmlog_writer.cc(464)] Failed to open scaling_cur_freq for logical core 2: No such file
or directory (2)
2024-04-26T14:31:54.886540Z WARNING metrics_daemon[3708]: WARNING metrics_daemon:
[vmlog_writer.cc(464)] Failed to open scaling_cur_freq for logical core 3: No such file
or directory (2)
2024-04-26T14:31:54.886643Z ERR metrics_daemon[3708]: ERROR metrics_daemon:
[vmlog_writer.cc(266)] RAPL info disabled (b/168594119).: No such file or directory (2)
2024-04-26T14:31:55.002840Z ERR cros_camera_service[3539]: InitializeOnGpuThread():
Failed to create EGL context
2024-04-26T14:31:55.024971Z INFO cros_camera_service[3539]: LoadCameraHal(): Try to load
camera hal /usr/lib64/camera_hal/usb.so
2024-04-26T14:31:55.032697Z INFO cros_camera_service[3539]: LoadCameraHal(): Running
camera HAL adapter on 2
2024-04-26T14:31:55.044959Z INFO cros_camera_service[3539]: Start(): Effects are not
enabled, DLC will not be installed.
2024-04-26T14:31:55.060139Z INFO cros_camera_service[3539]: StartOnThread(): Camera
module "V4L2 UVC Camera HAL v3" has 0 built-in camera(s)
2024-04-26T14:31:55.060400Z INFO cros_camera_service[3539]: StartOnThread(): SuperHAL
started with 1 modules, 0 built-in cameras and 0 unexposed physical cameras
```

```
2024-04-26T14:31:55.060550Z INFO cros_camera_service[3539]: main(): Started camera HAL v3
adapter
2024-04-26T14:31:55.061962Z INFO cros_camera_service[3539]:
CreateClientUnixDomainSocket(): Connect the camera socket successfully. Socket info:
creation_time: 2024-04-26 14:31:31.561 UTC last_accessed: 2024-04-26 14:31:55.060 UTC
last_modified: 2024-04-26 14:31:31.560 UTC
2024-04-26T14:31:55.077874Z ERR arc-setup-precreate[3754]: ERROR arc-setup:
[safe_fd.cc(701)] unlinkat failed: No such file or directory (2)
2024-04-26T14:31:55.111014Z INFO cros_camera_service[3539]: OnServerRegistered():
Successfully registered camera server.
2024-04-26T14:31:55.121461Z INFO cros_camera_service[3539]: BindOnThread(): Bridge ready
2024-04-26T14:31:55.242856Z INFO permission_broker[1266]: AllowUsbDeviceRule: ALLOW
2024-04-26T14:31:55.242951Z INFO permission_broker[1266]: AllowTtyDeviceRule: IGNORE
2024-04-26T14:31:55.246367Z INFO permission_broker[1266]: Found claimed interface with
driver: usbhid
2024-04-26T14:31:55.250718Z INFO permission_broker[1266]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T14:31:55.250767Z INFO permission_broker[1266]: Verdict for
/dev/bus/usb/002/002: DENY
2024-04-26T14:31:55.251110Z INFO permission_broker[1266]:
ProcessPath(/dev/bus/usb/002/002)
2024-04-26T14:31:55.349080Z ERR arc-setup-precreate[3754]: ERROR arc-setup:
[safe_fd.cc(138)] Owner uid is 0 instead of 603
2024-04-26T14:31:55.883159Z INFO permission_broker[1266]: AllowUsbDeviceRule: ALLOW
2024-04-26T14:31:55.883208Z INFO permission_broker[1266]: AllowTtyDeviceRule: IGNORE
2024-04-26T14:31:55.886109Z INFO permission_broker[1266]: Found claimed interface with
driver: usbhid
2024-04-26T14:31:55.895909Z INFO permission_broker[1266]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T14:31:55.895960Z INFO permission_broker[1266]: Verdict for
/dev/bus/usb/002/002: DENY
2024-04-26T14:31:56.312474Z INFO kernel: [ 67.705912] loop8: detected capacity change
from 0 to 754088
2024-04-26T14:31:56.371525Z INFO kernel: [ 67.766888] loop9: detected capacity change
from 0 to 212568
2024-04-26T14:31:56.413643Z INFO kernel: [ 67.807816] loop10: detected capacity change
from 0 to 8
2024-04-26T14:31:56.418813Z WARNING minijail0[3811]: libminijail[3811]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:56.418856Z WARNING minijail0[3811]: libminijail[3811]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:56.420119Z WARNING minijail0[3815]: libminijail[3815]: failed to create
a ruleset: Function not implemented
2024-04-26T14:31:56.420188Z WARNING minijail0[3815]: libminijail[3815]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:31:56.420201Z INFO minijail0[3815]: libminijail[3815]: Landlock support for
LANDLOCK_ACCESS_FS_REFER: false
2024-04-26T14:32:02.934364Z ERR shill[837]: ERROR shill: [dhcp_controller.cc(410)] Timed
out waiting for DHCP lease on eth0 (after 30 seconds).
2024-04-26T14:32:03.121232Z ERR dnsproxyd[2204]: ERROR dnsproxyd:
[dbus_method_invoker.h(115)] CallMethodAndBlockWithTimeout(...): Domain=dbus,
Code=org.freedesktop.DBus.Error.UnknownObject, Message=Error calling D-Bus method:
org.chromium.flimflam.IPConfig.GetProperties: Method "GetProperties" with signature "" on
interface "org.chromium.flimflam.IPConfig" doesn't exist#012
2024-04-26T14:32:03.121256Z ERR dnsproxyd[2206]: ERROR dnsproxyd:
[dbus_method_invoker.h(115)] CallMethodAndBlockWithTimeout(...): Domain=dbus,
Code=org.freedesktop.DBus.Error.UnknownObject, Message=Error calling D-Bus method:
org.chromium.flimflam.IPConfig.GetProperties: Method "GetProperties" with signature "" on
interface "org.chromium.flimflam.IPConfig" doesn't exist#012
2024-04-26T14:32:03.122042Z ERR dnsproxyd[1299]: ERROR dnsproxyd:
[dbus_method_invoker.h(115)] CallMethodAndBlockWithTimeout(...): Domain=dbus,
Code=org.freedesktop.DBus.Error.UnknownObject, Message=Error calling D-Bus method:
org.chromium.flimflam.IPConfig.GetProperties: Method "GetProperties" with signature "" on
interface "org.chromium.flimflam.IPConfig" doesn't exist#012
2024-04-26T14:32:03.122278Z ERR patchpaneld[1230]: ERROR patchpaneld:
[dbus_method_invoker.h(115)] CallMethodAndBlockWithTimeout(...): Domain=dbus,
Code=org.freedesktop.DBus.Error.UnknownObject, Message=Error calling D-Bus method:
org.chromium.flimflam.IPConfig.GetProperties: Method "GetProperties" with signature "" on
interface "org.chromium.flimflam.IPConfig" doesn't exist#012
```

```
2024-04-26T14:32:04.706644Z INFO avahi-daemon[1277]: Joining mDNS multicast group on
interface eth0.IPv4 with address 192.168.9.128.
2024-04-26T14:32:04.713283Z INFO avahi-daemon[1277]: New relevant interface eth0.IPv4 for
mDNS.
2024-04-26T14:32:04.713405Z INFO avahi-daemon[1277]: Registering new address record for
192.168.9.128 on eth0.IPv4.
2024-04-26T14:32:04.860176Z NOTICE dbus-daemon[583]: [system] Failed to activate service
'org.chromium.MachineLearning': timed out (service_start_timeout=25000ms)
2024-04-26T14:32:09.592389Z INFO session_manager[987]: INFO session_manager:
[android_oci_wrapper.cc(181)] Container PID: 3985
2024-04-26T14:32:09.592463Z INFO session_manager[987]: INFO session_manager:
[session_manager_impl.cc(2180)] Started Android container with PID 3985
2024-04-26T14:32:09.601245Z WARNING secanomalyd[1296]: Bus::SendWithReplyAndBlock took
2628ms to process message: type=method_call, path=/org/chromium/SessionManager,
interface=org.chromium.SessionManagerInterface, member=RetrieveActiveSessions
2024-04-26T14:32:09.726037Z ERR arc-kmsg-logger[3766]: selinux: SELinux: Could not stat
/dev/block: No such file or directory.
2024-04-26T14:32:09.726087Z ERR arc-kmsg-logger[3766]:
2024-04-26T14:32:09.734385Z ERR arc-kmsg-logger[3766]: init: waitid failed: No child
processes
2024-04-26T14:32:09.739756Z ERR arc-kmsg-logger[3766]: init: Unable to set property
'ro.boot.container' to '1' in property file '/default.prop': Read-only property was
already set
2024-04-26T14:32:09.817817Z ERR arc-kmsg-logger[3766]: init: Unable to read config file
'/vendor/etc/init/init.cpuset.rc': open() failed: No such file or directory
2024-04-26T14:32:09.817843Z ERR arc-kmsg-logger[3766]: init: /init.rc: 2: Could not
import file '/vendor/etc/init/init.cpuset.rc': No such file or directory
2024-04-26T14:32:09.823481Z ERR arc-kmsg-logger[3766]: init: Unable to read config file
'/vendor/etc/init/hw/init.cheets.rc': open() failed: No such file or directory
2024-04-26T14:32:09.823521Z ERR arc-kmsg-logger[3766]: init: /init.rc: 10: Could not
import file '/vendor/etc/init/hw/init.cheets.rc': No such file or directory
2024-04-26T14:32:09.847110Z ERR arc-kmsg-logger[3766]: init: Unable to read config file
'/product/etc/init': open() failed: No such file or directory
2024-04-26T14:32:09.847540Z ERR arc-kmsg-logger[3766]: init: Unable to read config file
'/odm/etc/init': open() failed: No such file or directory
2024-04-26T14:32:09.855970Z INFO kernel: [ 81.252771] SELinux: Context is not valid
(left unmapped).
2024-04-26T14:32:09.864510Z ERR kernel: [ 81.261450] cgroup: Unknown subsys name
'memory'
2024-04-26T14:32:09.882268Z ERR arc-kmsg-logger[3766]: init: Subcontext init could not
set 'ro.opengles.version' to '131072': Read-only property was already set
2024-04-26T14:32:09.883572Z ERR arc-kmsg-logger[3766]: init: Subcontext init could not
set 'ro.hardware.egl' to 'mesa': Read-only property was already set
2024-04-26T14:32:09.892571Z ERR arc-kmsg-logger[3766]: ueventd: Unable to read config
file '/vendor/ueventd.rc': open() failed: No such file or directory
2024-04-26T14:32:09.893722Z ERR arc-kmsg-logger[3766]: ueventd: Unable to read config
file '/odm/ueventd.rc': open() failed: No such file or directory
2024-04-26T14:32:09.899487Z ERR kernel: [ 81.296288] cgroup: Unknown subsys name
'schedtune'
2024-04-26T14:32:09.915615Z WARNING kernel: [ 81.310942] new mount options do not match
the existing superblock, will be ignored
2024-04-26T14:32:09.945188Z ERR arc-kmsg-logger[3766]: init: Init cannot set
'ro.opengles.version' to '196608': Read-only property was already set
2024-04-26T14:32:09.959774Z ERR arc-kmsg-logger[3766]: init: Unable to set property
'ro.product.board' to 'fydeos' in property file '/vendor/build.prop': Read-only property
was already set
2024-04-26T14:32:09.959844Z ERR arc-kmsg-logger[3766]: init: Unable to set property
'ro.oem.key1' to 'fydeos' in property file '/vendor/build.prop': Read-only property was
already set
2024-04-26T14:32:09.961330Z ERR arc-kmsg-logger[3766]: init: /recovery not specified in
fstab
2024-04-26T14:32:09.968265Z ERR arc-kmsg-logger[3766]: init: Failed to open file
'/proc/kmsg': Permission denied
2024-04-26T14:32:10.009687Z ERR arc-kmsg-logger[3766]: selinux: SELinux: Could not stat
/metadata: No such file or directory.
2024-04-26T14:32:10.009714Z ERR arc-kmsg-logger[3766]:
2024-04-26T14:32:10.045722Z ERR arc-kmsg-logger[3766]: init: Failed to bind socket
'pdx/system/vr/display/client': No such file or directory
2024-04-26T14:32:10.045779Z ERR arc-kmsg-logger[3766]: init: Failed to bind socket
```

```
'pdx/system/vr/display/manager': No such file or directory
2024-04-26T14:32:10.045944Z ERR arc-kmsg-logger[3766]: init: Failed to bind socket
'pdx/system/vr/display/vsync': No such file or directory
2024-04-26T14:32:10.875768Z INFO kernel: [ 82.267247] binder: 4023:4023 transaction
failed 29189/-22, size 0-0 line 2893
2024-04-26T14:32:11.818250Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.graphics.composer@2.1::IComposer/default
2024-04-26T14:32:11.885371Z ERR arc-kmsg-logger[3766]: vdc: Failed: Status(-8): '0: '
2024-04-26T14:32:11.887640Z ERR arc-kmsg-logger[3766]: init: Failure (reboot suppressed):
init_user0_failed
2024-04-26T14:32:11.982344Z ERR arc-kmsg-logger[3766]: init: Could not load single
persistent property file, trying legacy directory: Unable to read persistent property
file: open() failed: No such file or directory
2024-04-26T14:32:11.982352Z ERR arc-kmsg-logger[3766]: init: Unable to load legacy
persistent properties: Unable to open persistent property directory "/data/property": No
such file or directory
2024-04-26T14:32:12.047966Z ERR arc-kmsg-logger[3766]: init: couldn't write 43 to
/dev/cpuset/camera-daemon/tasks: No such file or directory
2024-04-26T14:32:12.048019Z ERR arc-kmsg-logger[3766]: init: failed to set pid 42
ioprio=1,4: Operation not permitted
2024-04-26T14:32:12.048025Z ERR arc-kmsg-logger[3766]: init: failed to set pid 43
ioprio=1,4: Operation not permitted
2024-04-26T14:32:12.058500Z ERR arc-kmsg-logger[3766]: init: failed to set pid 44
ioprio=1,4: Operation not permitted
2024-04-26T14:32:12.058766Z ERR arc-kmsg-logger[3766]: init: failed to set pid 45
ioprio=1,4: Operation not permitted
2024-04-26T14:32:12.058777Z ERR arc-kmsg-logger[3766]: init: Could not start service
'vendor.hwcomposer-2-1' as part of class 'hal': File
/vendor/bin/hw/android.hardware.graphics.composer@2.1-service-cheets(labeled
"u:object_r:vendor_file:s0") has incorrect label or no domain transition from u:r:init:s0
to another SELinux domain defined. Have you configured your service correctly?
https://source.android.com/security/selinux/device-
policy#label_new_services_and_address_denials
2024-04-26T14:32:12.075662Z ERR arc-kmsg-logger[3766]: init: failed to set pid 47
ioprio=1,4: Operation not permitted
2024-04-26T14:32:12.075667Z ERR arc-kmsg-logger[3766]: init: failed to set pid 46
ioprio=1,4: Operation not permitted
2024-04-26T14:32:12.103950Z ERR arc-kmsg-logger[3766]: init: failed to set pid 49
ioprio=1,4: Operation not permitted
2024-04-26T14:32:12.114391Z ERR arc-kmsg-logger[3766]: init: failed to set pid 51
ioprio=1,4: Operation not permitted
2024-04-26T14:32:12.333630Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.health@1.0::IHealth/default
2024-04-26T14:32:12.355807Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:12.370224Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:12.371493Z ERR arc-kmsg-logger[3766]: init: No such service 'bootanim'
for ctl.start
2024-04-26T14:32:12.430595Z ERR arc-kmsg-logger[3766]: android.hardware.health@2.0-impl:
wakealarm_init: timerfd_create failed
2024-04-26T14:32:12.538375Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.thermal@1.1::IThermal/default
2024-04-26T14:32:14.347076Z ERR cryptohomed[936]: Failed to call method:
org.chromium.ChromeFeaturesServiceInterface.IsFeatureEnabled: object_path=
/org/chromium/ChromeFeaturesService: org.freedesktop.DBus.Error.InvalidArgs: Unexpected
feature name.
2024-04-26T14:32:14.347365Z WARNING cryptohomed[936]: No valid keysets on disk for
521ac76c473ca5ff9c03ccc71d8ad8646690ad65
2024-04-26T14:32:14.350393Z INFO cryptohomed[936]: AuthSession: started with
is_ephemeral_user=0 intent=decrypt user_exists=1 factors=gaia(type 0 uss).
2024-04-26T14:32:14.357011Z INFO cryptohomed[936]: AuthSession: decrypt authentication
attempt via gaia
2024-04-26T14:32:15.023926Z INFO cryptohomed[936]: AuthSession: authorized for
decrypt,verify-only.
2024-04-26T14:32:15.117510Z INFO cryptohomed[936]: Preparing persistent vault
2024-04-26T14:32:15.213413Z INFO cryptohomed[936]: Started mounting for:
521ac76c473ca5ff9c03ccc71d8ad8646690ad65
2024-04-26T14:32:15.430077Z ERR cryptohome-namespace-mounter[4116]: Owner uid is 0
```



```

instead of 1000
2024-04-26T14:32:15.495787Z INFO kernel: [ 86.891873] fscrypt: AES-256-CTS-CBC using
implementation "cts-cbc-aes-aesni"
2024-04-26T14:32:15.431109Z ERR cryptohome-namespace-mounter[4116]: Owner uid is 0
instead of 1000
2024-04-26T14:32:15.547782Z INFO cryptohome-namespace-mounter[4116]: Not a first mount,
since found: /home/.shadow/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/mount/user/Shortcuts-
journal
2024-04-26T14:32:15.591721Z INFO cryptohomed[936]: OOP mount helper started successfully
2024-04-26T14:32:15.595413Z INFO cryptohomed[936]: Restoring SELinux contexts for:
/home/.shadow/521ac76c473ca5ff9c03ccc71d8ad8646690ad65, recursive=true
2024-04-26T14:32:15.677015Z INFO cryptohomed[936]: Mount succeeded.
2024-04-26T14:32:15.696645Z INFO chapsd[822]: Opening database in: /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65
2024-04-26T14:32:15.707852Z INFO chapsd[822]: leveldb /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/dump:#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/LOCK (0 bytes, 2024-03-26
12:37:20.000 UTC)#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/CURRENT (16 bytes, 2024-04-
26 14:00:49.000 UTC)#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/000008.ldb (614 bytes,
2024-03-26 13:05:31.000 UTC)#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/LOG.old (184 bytes, 2024-
04-24 14:51:20.000 UTC)#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/MANIFEST-000034 (138 bytes,
2024-04-26 14:00:49.000 UTC)#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/000035.log (0 bytes, 2024-
04-26 14:00:49.000 UTC)#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/000005.ldb (393 bytes,
2024-03-26 12:58:13.000 UTC)#012 /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/LOG (184 bytes, 2024-04-26
14:00:49.000 UTC)
2024-04-26T14:32:15.875730Z INFO kernel: [ 87.266873] fscrypt: AES-256-XTS using
implementation "xts-aes-aesni"
2024-04-26T14:32:15.934091Z INFO chapsd[822]: leveldb.stats:#012
Compactions#012Level Files Size(MB) Time(sec) Read(MB) Write(MB)#012-----
-----#012 0 2 0 0 0 0#012
2024-04-26T14:32:15.945148Z INFO chapsd[822]: leveldb contains 6 keys.
2024-04-26T14:32:15.946413Z INFO chapsd[822]: Slot 1 ready for token at /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65
2024-04-26T14:32:15.947244Z INFO chapsd[822]: Created lock file:
/run/lock/power_override/chapsd_token_init_slot_1.lock
2024-04-26T14:32:15.957716Z INFO cryptohomed[936]: PKCS#11 initialization succeeded.
2024-04-26T14:32:15.981610Z INFO chapsd[822]: Root key is ready for token at /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65
2024-04-26T14:32:15.981843Z INFO chapsd[822]: Deleted lock file:
/run/lock/power_override/chapsd_token_init_slot_1.lock
2024-04-26T14:32:16.066485Z INFO session_manager[987]: INFO session_manager:
[policy_key.cc(49)] No policy key on disk at /run/daemon-
store/session_manager/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/policy/key
2024-04-26T14:32:16.132108Z INFO session_manager[987]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting start-user-session Upstart signal
2024-04-26T14:32:16.141269Z INFO session_manager[987]: INFO session_manager:
[session_manager_impl.cc(772)] Starting user session
2024-04-26T14:32:16.141293Z INFO session_manager[987]: INFO session_manager:
[session_manager_impl.cc(780)] Emitting D-Bus signal SessionStateChanged: started
2024-04-26T14:32:16.150604Z INFO debugd[3650]: Deleting the ARC bug report backup
2024-04-26T14:32:16.579941Z INFO crosdns[4156]: Starting CroS DNS daemon
2024-04-26T14:32:16.790570Z INFO minijail0[4172]: libminijail[4172]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:16.828014Z INFO minijail0[4174]: libminijail[4174]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:16.862885Z INFO minijail0[4180]: libminijail[4180]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:16.979524Z INFO usb_bouncer[4181]: Reporting metrics for
/devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-2/2-2.1
2024-04-26T14:32:16.987334Z INFO usb_bouncer[4181]: Reporting metrics for
/devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2
2024-04-26T14:32:16.988148Z INFO usb_bouncer[4181]: Reporting metrics for

```

```
/devices/pci0000:00/0000:00:11.0/0000:02:03.0/usb1
2024-04-26T14:32:16.988922Z INFO usb_bouncer[4181]: Reporting metrics for
/devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-1
2024-04-26T14:32:16.991142Z INFO usb_bouncer[4181]: Reporting metrics for
/devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-2
2024-04-26T14:32:17.021961Z INFO bluetoothd[778]: Applied debug levels: bluez(0),
kernel(0)
2024-04-26T14:32:17.022688Z ERR bluetoothd[778]: No default adapter. Skip setting quality
debug.
2024-04-26T14:32:17.252293Z INFO vmlog_forwarder[4179]: Connecting to dbus signal
VmStartingUpSignal
2024-04-26T14:32:17.256216Z INFO vmlog_forwarder[4179]: Connecting to dbus signal
VmStoppedSignal
2024-04-26T14:32:17.257370Z INFO vmlog_forwarder[4179]: Started RotateLogs timer
2024-04-26T14:32:17.275686Z INFO dbus-daemon[583]: [system] Activating service
name='org.chromium.SmbProvider' requested by ':1.41' (uid=1000 pid=1044
comm="/opt/google/chrome/chrome --enable-webgl-image-chr" label="u:r:cros_browser:s0")
(using servicehelper)
2024-04-26T14:32:17.297171Z WARNING cros-disks[4194]: libminijail[1]: ioctl(SIOCSIFFLAGS)
failed: Operation not permitted
2024-04-26T14:32:17.311987Z INFO vmlog_forwarder[4179]: VM log forwarder listening on
port 9999
2024-04-26T14:32:17.424042Z INFO fusebox[4201]: fusebox /dev/fd/11 [2]
2024-04-26T14:32:17.426205Z INFO fusebox[4201]: fusebox fuse_daemonizing
2024-04-26T14:32:17.440739Z WARNING minijail0[4213]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:32:17.440763Z WARNING minijail0[4213]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:17.440776Z INFO minijail0[4213]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:32:17.443121Z WARNING minijail0[4209]: libminijail[4209]: failed to create
a ruleset: Function not implemented
2024-04-26T14:32:17.443146Z WARNING minijail0[4209]: libminijail[4209]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:17.447131Z INFO minijail0[4214]: libminijail[4214]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:17.599687Z INFO minijail0[4220]: libminijail[4220]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:17.630114Z WARNING minijail0[4217]: libminijail[4217]:
realpath(/dev/kvm) failed: No such file or directory
2024-04-26T14:32:17.632531Z INFO minijail0[4217]: libminijail[4217]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:17.653296Z WARNING minijail0[4221]: libminijail[4221]: stat(/dev/kvm)
failed: No such file or directory
2024-04-26T14:32:17.653358Z WARNING minijail0[4221]: libminijail[4221]: cannot create
mount target '/tmp/minijail.dev.SC0i84/kvm'
2024-04-26T14:32:17.653368Z WARNING minijail0[4221]: libminijail[4221]: mount_one failed
with /dev at '/tmp/minijail.dev.SC0i84'
2024-04-26T14:32:18.596862Z WARNING minijail0[4223]: libminijail[4223]: failed to create
a ruleset: Function not implemented
2024-04-26T14:32:18.596971Z WARNING minijail0[4223]: libminijail[4223]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:18.597922Z WARNING minijail0[4230]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:32:18.597967Z WARNING minijail0[4230]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:18.597978Z INFO minijail0[4230]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:32:18.790929Z INFO vm_cicerone[4228]: Server listening on
vsock:4294967295:8889, unix:///run/vm_cicerone/client/host.sock
2024-04-26T14:32:18.815773Z INFO vm_cicerone[4228]: Server listening on
vsock:4294967295:7778
2024-04-26T14:32:18.839198Z INFO vm_cicerone[4228]: Server listening on
vsock:4294967295:7779
2024-04-26T14:32:18.852937Z INFO vm_cicerone[4228]: Started tremplin grpc server
2024-04-26T14:32:19.382628Z WARNING kernel: [ 90.656680] hrtimer: interrupt took
12778527 ns
2024-04-26T14:32:20.100951Z INFO minijail0[4220]: libminijail[4220]: child process 4222
exited with status 1
```

```
2024-04-26T14:32:20.101928Z ERR debugd[3650]: Problem waiting for pid 4220: No child
processes (10)
2024-04-26T14:32:20.101973Z ERR debugd[3650]: Unable to send signal to 4220: No such
process (3)
2024-04-26T14:32:20.220899Z INFO smbproviderd[4213]: NTLM protocol is disabled
2024-04-26T14:32:20.223926Z INFO dbus-daemon[583]: [system] Successfully activated
service 'org.chromium.SmbProvider'
2024-04-26T14:32:20.241180Z WARNING featured[1219]: Bus::SendWithReplyAndBlock took
4093ms to process message: type=method_call, path=/org/chromium/ChromeFeaturesService,
interface=org.chromium.ChromeFeaturesServiceInterface, member=IsFeatureEnabled
2024-04-26T14:32:20.241277Z ERR featured[1219]: Failed to call method:
org.chromium.ChromeFeaturesServiceInterface.IsFeatureEnabled: object_path=
/org/chromium/ChromeFeaturesService: org.freedesktop.DBus.Error.InvalidArgs: Unexpected
feature name.
2024-04-26T14:32:20.278134Z INFO session_manager[987]: INFO session_manager:
[session_manager_impl.cc(872)] LoadShillProfile() method called.
2024-04-26T14:32:20.278199Z INFO session_manager[987]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting load-shill-profile Upstart signal
2024-04-26T14:32:20.580734Z INFO vm_cicerone[4228]: System timezone changed, updating
container timezones
2024-04-26T14:32:21.803705Z WARNING featured[1219]: Bus::SendWithReplyAndBlock took
1562ms to process message: type=method_call, path=/org/chromium/ChromeFeaturesService,
interface=org.chromium.ChromeFeaturesServiceInterface, member=IsFeatureEnabled
2024-04-26T14:32:21.803790Z ERR featured[1219]: Failed to call method:
org.chromium.ChromeFeaturesServiceInterface.IsFeatureEnabled: object_path=
/org/chromium/ChromeFeaturesService: org.freedesktop.DBus.Error.InvalidArgs: Unexpected
feature name.
2024-04-26T14:32:21.957239Z ERR tpm_managerd[797]:
ClearOwnerPasswordAndReplaceWithRandomPasswordIfPossible: missing owner password.
2024-04-26T14:32:21.957266Z INFO tpm_managerd[797]:
ClearStoredOwnerPasswordTaskReplaceOwnerPasswordResult: kFail
2024-04-26T14:32:23.105371Z WARNING featured[1219]: Bus::SendWithReplyAndBlock took
1301ms to process message: type=method_call, path=/org/chromium/ChromeFeaturesService,
interface=org.chromium.ChromeFeaturesServiceInterface, member=IsFeatureEnabled
2024-04-26T14:32:23.105492Z ERR featured[1219]: Failed to call method:
org.chromium.ChromeFeaturesServiceInterface.IsFeatureEnabled: object_path=
/org/chromium/ChromeFeaturesService: org.freedesktop.DBus.Error.InvalidArgs: Unexpected
feature name.
2024-04-26T14:32:23.696203Z NOTICE preload-network[4331]: WiFi interface not found after
30 seconds.
2024-04-26T14:32:23.759221Z INFO session_manager[987]: INFO session_manager:
[session_manager_impl.cc(1609)] Android container is running with PID 3985
2024-04-26T14:32:24.369623Z INFO session_manager[987]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting continue-arc-boot Upstart signal
2024-04-26T14:32:24.418768Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:24.761414Z ERR arc-boot-continue[4341]: ERROR arc-setup:
[safe_fd.cc(701)] unlinkat failed: No such file or directory (2)
2024-04-26T14:32:24.888517Z WARNING metrics_daemon[3708]: WARNING metrics_daemon:
[metrics_daemon.cc(709)] cannot read
/sys/devices/system/cpu/cpu0/cpufreq/cpuinfo_max_freq
2024-04-26T14:32:24.922269Z ERR bluetoothd[778]: No default adapter. Skip setting quality
debug.
2024-04-26T14:32:25.036246Z INFO kernel: [ 96.430686] EXT4-fs (nvme0n1p1): re-mounted.
Opts: . Quota mode: journalled.
2024-04-26T14:32:25.036272Z INFO kernel: [ 96.437395] EXT4-fs (nvme0n1p1): re-mounted.
Opts: . Quota mode: journalled.
2024-04-26T14:32:25.040593Z INFO kernel: [ 96.440490] EXT4-fs (nvme0n1p1): re-mounted.
Opts: . Quota mode: journalled.
2024-04-26T14:32:25.055124Z INFO root[4393]: fydeos-license-utils get disk /dev/nvme0n1
serial by lsblk
2024-04-26T14:32:25.064915Z INFO root[4394]: fydeos-license-utils get fix id by disk
serial
2024-04-26T14:32:25.225607Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.audio@4.0::IDevicesFactory/default
2024-04-26T14:32:25.276705Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.audio@2.0::IDevicesFactory/msd
2024-04-26T14:32:25.441580Z WARNING kernel: [ 96.839720] memfd_create() without
MFD_EXEC nor MFD_NOEXEC_SEAL, pid=1055 'chrome_crashpad'
```

```
2024-04-26T14:32:25.572171Z INFO crash_reporter[4423]: developer build - not testing -
always dumping
2024-04-26T14:32:25.603336Z WARNING crash_reporter[4423]: Received crash notification for
chrome[1044] user 1000 (called directly)
2024-04-26T14:32:25.655708Z INFO iioservice[730]: INFO iioservice: [iio_sensor.cc(56)]
(2) Request(): Received SensorService from Mojo Service Manager
2024-04-26T14:32:25.668551Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.audio.effect@4.0::IEffectsFactory/default
2024-04-26T14:32:25.738507Z NOTICE dbus-daemon[583]: [system] Rejected send message, 1
matched rules; type="method_call", sender=":1.41" (uid=1000 pid=1044
comm="/opt/google/chrome/chrome --enable-webgl-image-chr" label="u:r:cros_browser:s0")
interface="com.ubuntu.Upstart@_6.Job" member="Start" error name="(unset)"
requested_reply="0" destination="com.ubuntu.Upstart" (uid=0 pid=1 comm="/sbin/init "
label="u:r:cros_init:s0")
2024-04-26T14:32:25.959859Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.audio.effect@4.0::IEffectsFactory/default
2024-04-26T14:32:29.090345Z ERR bluetoothd[778]: No default adapter. Skip setting quality
debug.
2024-04-26T14:32:35.132885Z ERR bluetoothd[778]: message repeated 2 times: [ No default
adapter. Skip setting quality debug.]
2024-04-26T14:32:36.291946Z INFO iioservice[730]: INFO iioservice:
[sensor_service_impl.cc(417)] (2) OnSensorServiceDisconnect(): SensorDevice disconnected.
ReceiverId: 3
2024-04-26T14:32:38.173858Z ERR bluetoothd[778]: No default adapter. Skip setting quality
debug.
2024-04-26T14:32:41.327552Z ERR bluetoothd[778]: No default adapter. Skip setting quality
debug.
2024-04-26T14:32:42.241747Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:32:42.246254Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:32:42.246304Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T14:32:42.246323Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T14:32:42.246596Z INFO dlcservice[1321]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:32:42.248638Z WARNING cras_server[1368]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:32:42.248701Z ERR cras_server[1368]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:32:42.248718Z ERR cras_server[1368]: download_supported_dlc: retry 2 times
2024-04-26T14:32:42.794939Z INFO minijail0[4667]: libminijail[4667]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:42.801177Z WARNING minijail0[4667]: libminijail[4667]: failed to create
a ruleset: Function not implemented
2024-04-26T14:32:42.801208Z WARNING minijail0[4667]: libminijail[4667]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:42.801243Z WARNING minijail0[4668]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:32:42.801256Z WARNING minijail0[4668]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:42.801268Z INFO minijail0[4668]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:32:43.031815Z ERR hardware_verifier[4669]: Failed to read the verification
payload file.
2024-04-26T14:32:43.032080Z ERR hardware_verifier[4669]: Failed to read the verification
payload file.
2024-04-26T14:32:43.036807Z INFO minijail0[4667]: libminijail[4667]: child process 4668
exited with status 2
2024-04-26T14:32:43.066074Z NOTICE hardware_verifier[4672]: hardware_verifier exits with
status 2.
2024-04-26T14:32:43.858486Z INFO kernel: [ 115.268493] capability: warning: `main' uses
32-bit capabilities (legacy support in use)
2024-04-26T14:32:44.360924Z ERR bluetoothd[778]: No default adapter. Skip setting quality
debug.
2024-04-26T14:32:44.964831Z ERR arc-kmsg-logger[3766]: selinux: avc: denied { set } for
```

```
property=ro.wait_for_property_service pid=69 uid=0 gid=0 scontext=u:r:cros_arc_setup:s0
tcontext=u:object_r:default_prop:s0 tclass=property_service permissive=1
2024-04-26T14:32:44.964860Z ERR arc-kmsg-logger[3766]:
2024-04-26T14:32:44.964866Z ERR arc-kmsg-logger[3766]: selinux: avc: denied { set } for
property=ro.serialno pid=69 uid=0 gid=0 scontext=u:r:cros_arc_setup:s0
tcontext=u:object_r:serialno_prop:s0 tclass=property_service permissive=1
2024-04-26T14:32:44.964870Z ERR arc-kmsg-logger[3766]:
2024-04-26T14:32:44.967633Z ERR arc-kmsg-logger[3766]: selinux: avc: denied { set } for
property=ro.vendor.arc_boot_type pid=69 uid=0 gid=0 scontext=u:r:cros_arc_setup:s0
tcontext=u:object_r:vendor_default_prop:s0 tclass=property_service permissive=1
2024-04-26T14:32:44.967642Z ERR arc-kmsg-logger[3766]:
2024-04-26T14:32:45.174595Z INFO kernel: [ 116.586737] tun: Universal TUN/TAP device
driver, 1.6
2024-04-26T14:32:45.176983Z ERR arc-kmsg-logger[3766]: init: Init cannot set
'ro.persistent_properties.ready' to 'true': Read-only property was already set
2024-04-26T14:32:45.279558Z INFO kernel: [ 116.684925] IPv6: ADDRCONF(NETDEV_CHANGE):
vetharc0: link becomes ready
2024-04-26T14:32:45.279824Z INFO kernel: [ 116.690516] IPv6: ADDRCONF(NETDEV_CHANGE):
arc0: link becomes ready
2024-04-26T14:32:45.434053Z INFO kernel: [ 116.843369] arcbr0: port 1(vetharc0) entered
blocking state
2024-04-26T14:32:45.434134Z INFO kernel: [ 116.845880] arcbr0: port 1(vetharc0) entered
disabled state
2024-04-26T14:32:45.436637Z INFO kernel: [ 116.848921] device vetharc0 entered
promiscuous mode
2024-04-26T14:32:45.441583Z INFO kernel: [ 116.852227] arcbr0: port 1(vetharc0) entered
blocking state
2024-04-26T14:32:45.441647Z INFO kernel: [ 116.854084] arcbr0: port 1(vetharc0) entered
forwarding state
2024-04-26T14:32:45.664328Z INFO kernel: [ 117.071803] IPv6: ADDRCONF(NETDEV_CHANGE):
eth0: link becomes ready
2024-04-26T14:32:45.673116Z INFO kernel: [ 117.079398] arc_eth0: port 1(vetheth0)
entered blocking state
2024-04-26T14:32:45.673160Z INFO kernel: [ 117.083297] arc_eth0: port 1(vetheth0)
entered disabled state
2024-04-26T14:32:45.682295Z INFO kernel: [ 117.090441] device vetheth0 entered
promiscuous mode
2024-04-26T14:32:45.682528Z INFO kernel: [ 117.094334] arc_eth0: port 1(vetheth0)
entered blocking state
2024-04-26T14:32:45.682597Z INFO kernel: [ 117.096730] arc_eth0: port 1(vetheth0)
entered forwarding state
2024-04-26T14:32:45.825271Z ERR arc-kmsg-logger[3766]: init: Could not start service
'flash_recovery' as part of class 'main': Cannot find '/system/bin/install-recovery.sh':
No such file or directory
2024-04-26T14:32:45.899597Z INFO kernel: [ 117.311126] IPv6: ADDRCONF(NETDEV_CHANGE):
veth2: link becomes ready
2024-04-26T14:32:45.908500Z ERR arc-kmsg-logger[3766]: init: couldn't write 113 to
/dev/cpuset/camera-daemon/tasks: No such file or directory
2024-04-26T14:32:45.908528Z ERR arc-kmsg-logger[3766]: init: failed to set pid 113
ioprio=1,4: Operation not permitted
2024-04-26T14:32:45.935218Z INFO minijail0[4780]: libminijail[4780]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:45.941304Z WARNING minijail0[4780]: libminijail[4780]: failed to create
a ruleset: Function not implemented
2024-04-26T14:32:45.941399Z WARNING minijail0[4818]: libminijail[4818]: failed to create
a ruleset: Function not implemented
2024-04-26T14:32:45.941411Z WARNING minijail0[4818]: libminijail[4818]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:45.941447Z INFO minijail0[4818]: libminijail[4818]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:32:45.942075Z WARNING minijail0[4780]: libminijail[4780]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:45.986632Z INFO minijail0[4805]: libminijail[4805]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:45.987464Z WARNING minijail0[4805]: libminijail[4805]: failed to create
a ruleset: Function not implemented
2024-04-26T14:32:45.987580Z WARNING minijail0[4805]: libminijail[4805]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:45.987621Z WARNING minijail0[4823]: libminijail[4823]: failed to create
```

```
a ruleset: Function not implemented
2024-04-26T14:32:45.987704Z WARNING minijail0[4823]: libminijail[4823]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:45.987715Z INFO minijail0[4823]: libminijail[4823]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:32:46.033475Z INFO kernel: [ 117.419652] ESDFS-fs (esdfs): mounted on top
of /opt/google/containers/android/rootfs/android-data/data/media type ext4
2024-04-26T14:32:46.040683Z INFO kernel: [ 117.448623] ESDFS-fs (esdfs): mounted on top
of /opt/google/containers/android/rootfs/android-data/data/media type ext4
2024-04-26T14:32:46.043860Z INFO minijail0[4801]: libminijail[4801]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:46.052558Z INFO kernel: [ 117.459923] ESDFS-fs (esdfs): mounted on top
of /opt/google/containers/android/rootfs/android-data/data/media type ext4
2024-04-26T14:32:46.061525Z INFO minijail0[4806]: libminijail[4806]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:46.071402Z WARNING minijail0[4801]: libminijail[4801]: failed to create
a ruleset: Function not implemented
2024-04-26T14:32:46.071420Z WARNING minijail0[4801]: libminijail[4801]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:46.072189Z WARNING minijail0[4827]: libminijail[4827]: failed to create
a ruleset: Function not implemented
2024-04-26T14:32:46.072202Z WARNING minijail0[4827]: libminijail[4827]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:46.072215Z INFO minijail0[4827]: libminijail[4827]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:32:46.099296Z WARNING minijail0[4806]: libminijail[4806]: failed to create
a ruleset: Function not implemented
2024-04-26T14:32:46.099315Z WARNING minijail0[4806]: libminijail[4806]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:46.101746Z WARNING minijail0[4828]: libminijail[4828]: failed to create
a ruleset: Function not implemented
2024-04-26T14:32:46.101782Z WARNING minijail0[4828]: libminijail[4828]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:46.101795Z INFO minijail0[4828]: libminijail[4828]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:32:46.103190Z WARNING session_manager[987]: WARNING session_manager:
[bus.cc(644)] Bus::SendWithReplyAndBlock took 21733ms to process message:
type=method_call, path=/com/ubuntu/Upstart, interface=com.ubuntu.Upstart0_6,
member=EmitEvent
2024-04-26T14:32:46.108130Z INFO debugd[3650]: Deleting the ARC bug report backup
2024-04-26T14:32:46.116916Z WARNING crash_reporter[4423]: Bus::SendWithReplyAndBlock took
20496ms to process message: type=method_call, path=/org/chromium/SessionManager,
interface=org.chromium.SessionManagerInterface, member=RetrieveActiveSessions
2024-04-26T14:32:46.117636Z INFO crash_reporter[4423]: Accessing crash dir '/run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65' via symlinked handle
'/proc/self/fd/10'
2024-04-26T14:32:46.119326Z INFO minijail0[4822]: libminijail[4822]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:46.120149Z WARNING secanomalyd[1296]: Bus::SendWithReplyAndBlock took
6204ms to process message: type=method_call, path=/org/chromium/SessionManager,
interface=org.chromium.SessionManagerInterface, member=RetrieveActiveSessions
2024-04-26T14:32:46.121750Z WARNING minijail0[4822]: libminijail[4822]: failed to create
a ruleset: Function not implemented
2024-04-26T14:32:46.121808Z WARNING minijail0[4822]: libminijail[4822]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:46.130637Z WARNING minijail0[4842]: libminijail[4842]: failed to create
a ruleset: Function not implemented
2024-04-26T14:32:46.130669Z WARNING minijail0[4842]: libminijail[4842]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:46.130681Z INFO minijail0[4842]: libminijail[4842]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:32:46.144841Z INFO minijail0[4834]: libminijail[4834]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:46.151908Z WARNING minijail0[4834]: libminijail[4834]: failed to create
a ruleset: Function not implemented
2024-04-26T14:32:46.151943Z WARNING minijail0[4834]: libminijail[4834]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:32:46.151944Z WARNING minijail0[4846]: libminijail[1]: failed to create a
ruleset: Function not implemented
```

2024-04-26T14:32:46.151959Z WARNING minijail0[4846]: libminijail[1]: Landlock is not supported by the current kernel: Function not implemented
2024-04-26T14:32:46.151976Z INFO minijail0[4846]: libminijail[1]: Landlock support for LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:32:46.218386Z INFO minijail0[4855]: libminijail[4855]: applying policy for default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:46.297011Z WARNING minijail0[4824]: libminijail[4824]: failed to create a ruleset: Function not implemented
2024-04-26T14:32:46.297030Z WARNING minijail0[4824]: libminijail[4824]: Landlock is not supported by the current kernel: Function not implemented
2024-04-26T14:32:46.297121Z WARNING minijail0[4880]: libminijail[1]: failed to create a ruleset: Function not implemented
2024-04-26T14:32:46.297140Z WARNING minijail0[4880]: libminijail[1]: Landlock is not supported by the current kernel: Function not implemented
2024-04-26T14:32:46.297159Z INFO minijail0[4880]: libminijail[1]: Landlock support for LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:32:46.315589Z INFO minijail0[4825]: libminijail[4825]: applying policy for default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:46.375624Z INFO minijail0[4865]: libminijail[4865]: applying policy for default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:46.378750Z WARNING minijail0[4865]: libminijail[4865]: failed to create a ruleset: Function not implemented
2024-04-26T14:32:46.378783Z WARNING minijail0[4865]: libminijail[4865]: Landlock is not supported by the current kernel: Function not implemented
2024-04-26T14:32:46.378929Z WARNING minijail0[4903]: libminijail[4903]: failed to create a ruleset: Function not implemented
2024-04-26T14:32:46.378943Z WARNING minijail0[4903]: libminijail[4903]: Landlock is not supported by the current kernel: Function not implemented
2024-04-26T14:32:46.378957Z INFO minijail0[4903]: libminijail[4903]: Landlock support for LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:32:46.446240Z INFO session_manager[987]: INFO session_manager: [resilient_policy_store.cc(140)] Deleted old device policy file: /var/lib/devicesettings/policy.13
2024-04-26T14:32:46.461989Z INFO minijail0[4861]: libminijail[4861]: applying policy for default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:46.463870Z WARNING minijail0[4861]: libminijail[4861]: failed to create a ruleset: Function not implemented
2024-04-26T14:32:46.463909Z WARNING minijail0[4861]: libminijail[4861]: Landlock is not supported by the current kernel: Function not implemented
2024-04-26T14:32:46.465914Z WARNING minijail0[4910]: libminijail[4910]: failed to create a ruleset: Function not implemented
2024-04-26T14:32:46.465955Z WARNING minijail0[4910]: libminijail[4910]: Landlock is not supported by the current kernel: Function not implemented
2024-04-26T14:32:46.465970Z INFO minijail0[4910]: libminijail[4910]: Landlock support for LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:32:46.493113Z INFO session_manager[987]: INFO session_manager: [policy_store.cc(85)] Persisted policy to disk, path: /var/lib/devicesettings/policy.16
2024-04-26T14:32:46.494910Z INFO minijail0[4866]: libminijail[4866]: applying policy for default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:46.498378Z INFO u2fd[3369]: INFO u2fd: [u2f_daemon.cc(367)] Requested Mode: Policy[unset], force_u2f[0], force_g2f[0]
2024-04-26T14:32:46.498486Z INFO u2fd[3369]: INFO u2fd: [u2f_daemon.cc(381)] Mode: Disabled (not supported)
2024-04-26T14:32:46.504591Z WARNING minijail0[4917]: libminijail[4917]: failed to create a ruleset: Function not implemented
2024-04-26T14:32:46.504593Z WARNING minijail0[4866]: libminijail[4866]: failed to create a ruleset: Function not implemented
2024-04-26T14:32:46.504628Z WARNING minijail0[4917]: libminijail[4917]: Landlock is not supported by the current kernel: Function not implemented
2024-04-26T14:32:46.504641Z INFO minijail0[4917]: libminijail[4917]: Landlock support for LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T14:32:46.510547Z WARNING minijail0[4866]: libminijail[4866]: Landlock is not supported by the current kernel: Function not implemented
2024-04-26T14:32:46.702777Z ERR arc-kmsg-logger[3766]: init: failed to set pid 141 ioprio=1,4: Operation not permitted
2024-04-26T14:32:46.762717Z ERR arc-kmsg-logger[3766]: init: failed to set pid 143 ioprio=1,4: Operation not permitted
2024-04-26T14:32:46.799261Z ERR arc-kmsg-logger[3766]: init: failed to set pid 144 ioprio=1,4: Operation not permitted

```
2024-04-26T14:32:46.866714Z ERR arc-kmsg-logger[3766]: init: failed to set pid 151
ioprio=1,4: Operation not permitted
2024-04-26T14:32:47.078719Z ERR arc-kmsg-logger[3766]: init: Failed to open file
'/d/mmc0/mmc0:0001/ext_csd': No such file or directory
2024-04-26T14:32:47.137765Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.148308Z INFO minijail0[4996]: libminijail[4996]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:32:47.157811Z ERR arc-kmsg-logger[3766]: init: failed to set pid 164
ioprio=1,4: Operation not permitted
2024-04-26T14:32:47.157962Z ERR arc-kmsg-logger[3766]: init: failed to set pid 161
ioprio=1,4: Operation not permitted
2024-04-26T14:32:47.391873Z ERR bluetoothd[778]: No default adapter. Skip setting quality
debug.
2024-04-26T14:32:47.467785Z INFO crash_reporter[4423]: Finishing crash. Meta file:
/proc/self/fd/10/chrome.20240426.143246.26017.1044.meta
2024-04-26T14:32:47.559593Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.581278Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.581579Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.596931Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.656100Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.656339Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.656548Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.656904Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.657197Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.657652Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.670170Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.670486Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.camera.provider@2.4::ICameraProvider/legacy/0
2024-04-26T14:32:47.670783Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.camera.provider@2.4::ICameraProvider/legacy/0
2024-04-26T14:32:47.672054Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.675951Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.676281Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.678353Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.679898Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.680496Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.686397Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.686818Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.health@2.0::IHealth/default
2024-04-26T14:32:47.687046Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.687252Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.736148Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.777135Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.844804Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.gatekeeper@1.0::IGatekeeper/default
2024-04-26T14:32:47.846799Z ERR arc-kmsg-logger[3766]: init: Could not find service
```



```
hosting interface android.hardware.usb.gadget@1.0::IUsbGadget/default
2024-04-26T14:32:47.847192Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.882007Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.938216Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:47.982070Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:48.038319Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:48.058490Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.keymaster@4.0::IKeymasterDevice/default
2024-04-26T14:32:48.084522Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:48.152193Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:48.185066Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:48.255531Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:48.286044Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:48.357829Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:48.387114Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:48.476782Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:48.509651Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T14:32:49.922102Z INFO iioservice[730]: INFO iioservice: [iio_sensor.cc(56)]
(2) Request(): Received SensorService from Mojo Service Manager
2024-04-26T14:32:49.928967Z INFO iioservice[730]: INFO iioservice:
[sensor_service_impl.cc(417)] (2) OnSensorServiceDisconnect(): SensorDevice disconnected.
ReceiverId: 4
2024-04-26T14:32:50.183366Z INFO cros_camera_service[3539]: BindOnThread(): Bridge ready
2024-04-26T14:32:50.409917Z ERR bluetoothd[778]: No default adapter. Skip setting quality
debug.
2024-04-26T14:32:50.777110Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.camera.provider@2.4::ICameraProvider/external/0
2024-04-26T14:32:53.416842Z ERR bluetoothd[778]: No default adapter. Skip setting quality
debug.
2024-04-26T14:32:54.874917Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.power@1.0::IPower/default
2024-04-26T14:32:55.698531Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.light@2.0::ILight/default
2024-04-26T14:32:58.868884Z INFO root[5167]: fydeos-license-utils get disk /dev/nvme0n1
serial by lsblk
2024-04-26T14:32:58.886547Z INFO root[5168]: fydeos-license-utils get fix id by disk
serial
2024-04-26T14:33:00.766862Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.soundtrigger@2.0::ISoundTriggerHw/default
2024-04-26T14:33:00.779790Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.health@2.0::IHealth/default
2024-04-26T14:33:01.509470Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.vibrator@1.0::IVibrator/default
2024-04-26T14:33:01.524008Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.vibrator@1.0::IVibrator/default
2024-04-26T14:33:01.529008Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.vibrator@1.0::IVibrator/default
2024-04-26T14:33:01.543603Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.ir@1.0::IConsumerIr/default
2024-04-26T14:33:02.002208Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.vr@1.0::IVr/default
2024-04-26T14:33:02.842195Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.oemlock@1.0::IOemLock/default
2024-04-26T14:33:04.119279Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.thermal@1.0::IThermal/default
```

```
2024-04-26T14:33:04.448129Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.contexthub@1.0::IContexthub/default
2024-04-26T14:33:04.836350Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.weaver@1.0::IWeaver/default
2024-04-26T14:33:04.858160Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.authsecret@1.0::IAuthSecret/default
2024-04-26T14:33:07.297446Z INFO permission_broker[1266]:
ProcessPath(/dev/bus/usb/002/004)
2024-04-26T14:33:07.748047Z INFO permission_broker[1266]: AllowUsbDeviceRule: ALLOW
2024-04-26T14:33:07.748219Z INFO permission_broker[1266]: AllowTtyDeviceRule: IGNORE
2024-04-26T14:33:07.751151Z INFO permission_broker[1266]: Found claimed interface with
driver: btusb
2024-04-26T14:33:07.754115Z INFO permission_broker[1266]: Found claimed interface with
driver: btusb
2024-04-26T14:33:07.756552Z INFO permission_broker[1266]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T14:33:07.756682Z INFO permission_broker[1266]: Verdict for
/dev/bus/usb/002/004: DENY
2024-04-26T14:33:07.756868Z INFO permission_broker[1266]:
ProcessPath(/dev/bus/usb/002/002)
2024-04-26T14:33:08.172093Z INFO permission_broker[1266]: AllowUsbDeviceRule: ALLOW
2024-04-26T14:33:08.172320Z INFO permission_broker[1266]: AllowTtyDeviceRule: IGNORE
2024-04-26T14:33:08.176902Z INFO permission_broker[1266]: Found claimed interface with
driver: usbhid
2024-04-26T14:33:08.183078Z INFO permission_broker[1266]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T14:33:08.183548Z INFO permission_broker[1266]: Verdict for
/dev/bus/usb/002/002: DENY
2024-04-26T14:33:08.246595Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.gnss@1.1::IGnss/default
2024-04-26T14:33:08.271883Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.gnss@1.0::IGnss/default
2024-04-26T14:33:16.265382Z INFO session_manager[987]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting arc-booted Upstart signal
2024-04-26T14:33:16.370096Z ERR arc-kmsg-logger[3766]: selinux: SELinux: Could not stat
/sys/kernel/debug/tracing/instances/wifi: No such file or directory.
2024-04-26T14:33:16.370110Z ERR arc-kmsg-logger[3766]:
2024-04-26T14:33:16.484999Z INFO minijail0[5425]: libminijail[5425]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T14:33:16.496908Z WARNING minijail0[5425]: libminijail[5425]: failed to create
a ruleset: Function not implemented
2024-04-26T14:33:16.496924Z WARNING minijail0[5425]: libminijail[5425]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:33:16.497364Z WARNING minijail0[5438]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T14:33:16.497397Z WARNING minijail0[5438]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T14:33:16.497409Z INFO minijail0[5438]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFER: false
2024-04-26T14:33:17.494788Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface hardware.google.media.c2@1.0::IComponentStore/software
2024-04-26T14:33:21.442498Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.secure_element@1.0::ISecureElement/eSE1
2024-04-26T14:33:21.443414Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.secure_element@1.0::ISecureElement/SIM1
2024-04-26T14:33:28.714032Z INFO root[6197]: fydeos-license-utils get disk /dev/nvme0n1
serial by lsblk
2024-04-26T14:33:28.730552Z INFO root[6198]: fydeos-license-utils get fix id by disk
serial
2024-04-26T14:33:42.256065Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:33:42.271790Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:33:42.271823Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T14:33:42.271845Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
```

```
2024-04-26T14:33:42.272193Z INFO dlcservice[1321]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:33:42.275143Z WARNING cras_server[1368]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:33:42.275409Z ERR cras_server[1368]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:33:42.275462Z ERR cras_server[1368]: download_supported_dlc: retry 3 times
2024-04-26T14:33:45.970306Z WARNING kernel: [ 177.404863] audit_log_start: 1025
callbacks suppressed
2024-04-26T14:33:45.970374Z WARNING kernel: [ 177.404868] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:33:45.974492Z WARNING kernel: [ 177.409817] audit: audit_lost=1
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:33:45.976132Z ERR kernel: [ 177.413912] audit: backlog limit exceeded
2024-04-26T14:34:05.037641Z WARNING kernel: [ 196.450528] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:34:05.037680Z WARNING kernel: [ 196.454526] audit: audit_lost=2
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:34:05.037684Z WARNING kernel: [ 196.457157] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:34:05.038846Z WARNING kernel: [ 196.482540] audit: audit_lost=3
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:34:05.057984Z ERR kernel: [ 196.484159] audit: backlog limit exceeded
2024-04-26T14:34:05.058006Z ERR kernel: [ 196.489454] audit: backlog limit exceeded
2024-04-26T14:34:25.378295Z WARNING kernel: [ 216.816273] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:34:25.378357Z WARNING kernel: [ 216.820398] audit: audit_lost=4
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:34:25.494598Z ERR kernel: [ 216.827520] audit: backlog limit exceeded
2024-04-26T14:34:42.338186Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:34:42.342020Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:34:42.342085Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T14:34:42.342108Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T14:34:42.342476Z INFO dlcservice[1321]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:34:42.343545Z WARNING cras_server[1368]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:34:42.343614Z ERR cras_server[1368]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:34:42.343633Z ERR cras_server[1368]: download_supported_dlc: retry 4 times
2024-04-26T14:35:03.288316Z NOTICE auditd[458]: Audit daemon rotating log files
2024-04-26T14:35:05.667118Z INFO kernel: [ 257.102239] binder_alloc: 5756:
binder_alloc_buf size 1056768 failed, no address space
2024-04-26T14:35:05.667164Z INFO kernel: [ 257.112178] binder_alloc: allocated: 5592
(num: 22 largest: 1944), free: 1034792 (num: 7 largest: 1030512)
2024-04-26T14:35:05.678728Z INFO kernel: [ 257.128534] binder: 5778:7872 transaction
failed 29201/-28, size 1056768-0 line 3061
2024-04-26T14:35:14.590641Z ERR kernel: [ 266.037914] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:35:14.855110Z NOTICE activate_date[8286]: activate_date failed.
2024-04-26T14:35:17.911501Z ERR kernel: [ 269.333743] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:35:17.911594Z ERR kernel: [ 269.341245] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:35:32.190766Z INFO kernel: [ 283.619609] binder_alloc: 8333:
binder_alloc_buf, no vma
2024-04-26T14:35:32.190852Z INFO kernel: [ 283.641835] binder: 4934:5121 transaction
failed 29189/-3, size 76-0 line 3061
2024-04-26T14:35:42.421525Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:35:42.438195Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
```

```
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:35:42.438286Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T14:35:42.438310Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T14:35:42.438669Z INFO dlcservice[1321]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:35:42.667773Z WARNING cras_server[1368]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:35:42.667880Z ERR cras_server[1368]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:35:42.667897Z ERR cras_server[1368]: download_supported_dlc: retry 5 times
2024-04-26T14:35:55.102921Z WARNING kernel: [ 306.449182] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:35:55.103124Z WARNING kernel: [ 306.460465] audit: audit_lost=5
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:35:55.180150Z ERR kernel: [ 306.564233] audit: backlog limit exceeded
2024-04-26T14:36:04.612067Z WARNING kernel: [ 316.040539] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:36:04.612309Z WARNING kernel: [ 316.044546] audit: audit_lost=6
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:36:04.612627Z ERR kernel: [ 316.053088] audit: backlog limit exceeded
2024-04-26T14:36:04.612758Z WARNING kernel: [ 316.056990] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:36:04.612869Z WARNING kernel: [ 316.061224] audit: audit_lost=7
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:36:04.612975Z ERR kernel: [ 316.068555] audit: backlog limit exceeded
2024-04-26T14:36:04.650246Z WARNING kernel: [ 316.093701] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:36:04.650512Z WARNING kernel: [ 316.111056] audit: audit_lost=8
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:36:04.682391Z ERR kernel: [ 316.122491] audit: backlog limit exceeded
2024-04-26T14:36:04.682658Z WARNING kernel: [ 316.130564] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:36:12.253527Z ERR kernel: [ 323.681786] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:36:12.868329Z WARNING kernel: [ 324.318675] audit_log_start: 11 callbacks
suppressed
2024-04-26T14:36:12.869160Z WARNING kernel: [ 324.318684] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:36:12.890064Z WARNING kernel: [ 324.341982] audit: audit_lost=13
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:36:12.896401Z ERR kernel: [ 324.352165] audit: backlog limit exceeded
2024-04-26T14:36:25.081499Z INFO vm_cicerone[4228]: System timezone changed, updating
container timezones
2024-04-26T14:36:35.745667Z INFO periodic_scheduler[1221]: crash_sender: running
/sbin/crash_sender
2024-04-26T14:36:36.311970Z INFO crash_sender[8967]: Checking metadata: /run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/com_android_vending.20240426.140824.
21676.66188.meta
2024-04-26T14:36:36.342526Z INFO crash_sender[8967]: Removing: Not an official OS version
2024-04-26T14:36:36.364539Z INFO crash_sender[8967]: Checking metadata: /run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/chrome.20240426.142614.75942.1056.me
ta
2024-04-26T14:36:36.364968Z INFO crash_sender[8967]: Removing: Not an official OS version
2024-04-26T14:36:36.366576Z INFO crash_sender[8967]: Checking metadata: /run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/chrome.20240426.143246.26017.1044.me
ta
2024-04-26T14:36:36.366938Z INFO crash_sender[8967]: Removing: Not an official OS version
2024-04-26T14:36:36.603595Z INFO periodic_scheduler[1221]: crash_sender: job completed
2024-04-26T14:36:42.761311Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:36:42.923127Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:36:42.923173Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T14:36:42.923199Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(107)]
```

```
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T14:36:42.923655Z INFO dlcservice[1321]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:36:42.992123Z WARNING cras_server[1368]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:36:42.992193Z ERR cras_server[1368]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:36:42.992219Z ERR cras_server[1368]: download_supported_dlc: retry 6 times
2024-04-26T14:37:04.244262Z WARNING kernel: [ 375.662239] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:37:04.244309Z WARNING kernel: [ 375.669390] audit: audit_lost=14
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:37:04.251333Z ERR kernel: [ 375.708354] audit: backlog limit exceeded
2024-04-26T14:37:15.179785Z INFO cryptohomed[936]: AuthSession: timed out.
2024-04-26T14:37:37.672947Z ERR cras_healthd[1319]: Not implemented reached in void
diagnostics::UdevEventsImpl::OnHdmiChange()
2024-04-26T14:37:43.071839Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:37:43.081010Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:37:43.081050Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T14:37:43.081079Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T14:37:43.081379Z INFO dlcservice[1321]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:37:43.090536Z WARNING cras_server[1368]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:37:43.090617Z ERR cras_server[1368]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:37:43.090637Z ERR cras_server[1368]: download_supported_dlc: retry 7 times
2024-04-26T14:38:00.890508Z ERR kernel: [ 432.338892] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:38:02.189527Z ERR kernel: [ 433.644900] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:38:02.876983Z ERR kernel: [ 434.313372] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:38:03.070510Z ERR kernel: [ 434.525071] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:38:04.737367Z ERR kernel: [ 436.174596] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:38:05.952061Z WARNING cras_server[1368]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1062720 > 1048576
2024-04-26T14:38:07.285496Z ERR kernel: [ 438.738630] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:38:20.659115Z ERR kernel: [ 452.089960] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:38:20.681622Z ERR kernel: [ 452.127524] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:38:20.953241Z ERR kernel: [ 452.163122] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:38:28.080918Z INFO crash_reporter[9845]: developer build - not testing -
always dumping
2024-04-26T14:38:28.083755Z WARNING crash_reporter[9845]: [ARC_java] Received
data_app_anr notification for com.lionsden.gamemaster5 (handling)
2024-04-26T14:38:28.141290Z INFO crash_reporter[9838]: developer build - not testing -
always dumping
2024-04-26T14:38:28.142812Z WARNING crash_reporter[9838]: [ARC_java] Received
system_app_wtf notification for com.android.vending (handling)
2024-04-26T14:38:28.155757Z INFO crash_reporter[9836]: developer build - not testing -
always dumping
2024-04-26T14:38:28.155884Z WARNING crash_reporter[9836]: [ARC_java] Received
system_app_wtf notification for com.android.vending (handling)
2024-04-26T14:38:28.323790Z INFO crash_reporter[9845]: Accessing crash dir '/run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65' via symlinked handle
'/proc/self/fd/10'
2024-04-26T14:38:28.330676Z INFO crash_reporter[9836]: Accessing crash dir '/run/daemon-
```

```
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65' via symlinked handle
'/proc/self/fd/10'
2024-04-26T14:38:28.431334Z INFO crash_reporter[9845]: Finishing crash. Meta file:
/proc/self/fd/10/com_lionsden_gamemaster5.20240426.143828.97942.685596.meta
2024-04-26T14:38:28.445635Z INFO crash_reporter[9838]: Accessing crash dir '/run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65' via symlinked handle
'/proc/self/fd/10'
2024-04-26T14:38:28.449277Z INFO crash_reporter[9836]: Finishing crash. Meta file:
/proc/self/fd/10/com_android_vending.20240426.143828.46765.691683.meta
2024-04-26T14:38:28.460787Z INFO crash_reporter[9838]: Finishing crash. Meta file:
/proc/self/fd/10/com_android_vending.20240426.143828.36498.808935.meta
2024-04-26T14:38:29.532306Z ERR kernel: [ 460.986272] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:38:29.545742Z ERR kernel: [ 460.998171] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:38:32.718119Z WARNING kernel: [ 464.153136] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:38:32.718165Z WARNING kernel: [ 464.171924] audit: audit_lost=15
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:38:32.718176Z ERR kernel: [ 464.176201] audit: backlog limit exceeded
2024-04-26T14:38:42.668507Z WARNING kernel: [ 474.096442] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:38:42.668540Z WARNING kernel: [ 474.119901] audit: audit_lost=16
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:38:42.668545Z ERR kernel: [ 474.123938] audit: backlog limit exceeded
2024-04-26T14:38:43.109894Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:38:43.145201Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:38:43.145242Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T14:38:43.145271Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T14:38:43.145851Z INFO dlcservice[1321]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:38:43.176088Z WARNING cras_server[1368]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:38:43.176839Z ERR cras_server[1368]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:38:43.179297Z ERR cras_server[1368]: download_supported_dlc: retry 8 times
2024-04-26T14:39:08.748237Z INFO kernel: [ 500.201308] binder_alloc: 10090:
binder_alloc_buf, no vma
2024-04-26T14:39:08.748273Z INFO kernel: [ 500.205397] binder: 4934:5121 transaction
failed 29189/-3, size 76-0 line 3061
2024-04-26T14:39:13.843747Z ERR kernel: [ 505.299841] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:39:13.898660Z ERR kernel: [ 505.328042] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:39:14.124678Z INFO kernel: [ 505.580965] binder: undelivered transaction
134152, process died.
2024-04-26T14:39:15.567797Z WARNING kernel: [ 507.024792] sched: RT throttling activated
2024-04-26T14:39:15.742987Z WARNING cras_server[1368]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1081920 > 1048576
2024-04-26T14:39:18.166529Z ERR kernel: [ 509.540635] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:39:18.175852Z ERR kernel: [ 509.628113] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:39:18.299754Z WARNING cras_server[1368]: fetch err: -32 for 100003
2024-04-26T14:39:19.177595Z ERR kernel: [ 510.633738] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:39:22.756051Z WARNING kernel: [ 514.178353] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:39:22.756094Z WARNING kernel: [ 514.178353] audit: audit_lost=17
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:39:22.765012Z ERR kernel: [ 514.221478] audit: backlog limit exceeded
2024-04-26T14:39:24.632042Z WARNING kernel: [ 516.085571] audit: audit_backlog=65 >
audit_backlog_limit=64
```

```
2024-04-26T14:39:24.632086Z WARNING kernel: [ 516.089105] audit: audit_lost=18
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:39:24.650586Z ERR kernel: [ 516.093160] audit: backlog limit exceeded
2024-04-26T14:39:36.889140Z WARNING kernel: [ 528.336121] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:39:36.889183Z WARNING kernel: [ 528.342432] audit: audit_lost=19
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:39:36.938407Z ERR kernel: [ 528.379562] audit: backlog limit exceeded
2024-04-26T14:39:43.769155Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:39:43.891743Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:39:43.891775Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T14:39:43.891794Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T14:39:43.955648Z INFO dlcservice[1321]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:39:43.999933Z WARNING cras_server[1368]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:39:43.999985Z ERR cras_server[1368]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:39:44.000004Z ERR cras_server[1368]: download_supported_dlc: retry 9 times
2024-04-26T14:39:53.201296Z WARNING kernel: [ 544.634108] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:39:53.201499Z WARNING kernel: [ 544.649332] audit: audit_lost=20
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:39:53.201525Z ERR kernel: [ 544.653155] audit: backlog limit exceeded
2024-04-26T14:40:03.719998Z WARNING kernel: [ 555.164225] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:40:03.720094Z WARNING kernel: [ 555.167061] audit: audit_lost=21
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:40:03.720100Z ERR kernel: [ 555.173013] audit: backlog limit exceeded
2024-04-26T14:40:44.084138Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:40:44.098729Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:40:44.098931Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T14:40:44.098951Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T14:40:44.099359Z INFO dlcservice[1321]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:40:44.103255Z WARNING cras_server[1368]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:40:44.103408Z ERR cras_server[1368]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:40:44.103462Z ERR cras_server[1368]: download_supported_dlc: retry 10 times
2024-04-26T14:40:52.700051Z WARNING kernel: [ 604.140113] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:40:52.700758Z WARNING kernel: [ 604.149811] audit: audit_lost=22
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:40:52.700770Z ERR kernel: [ 604.153648] audit: backlog limit exceeded
2024-04-26T14:41:27.451952Z INFO kernel: [ 638.906215] binder_alloc: 6604:
binder_alloc_buf, no vma
2024-04-26T14:41:27.451993Z INFO kernel: [ 638.912169] binder: 7094:7094 transaction
failed 29189/-3, size 4-0 line 3061
2024-04-26T14:41:44.168758Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:41:44.184933Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:41:44.185008Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
```

```
2024-04-26T14:41:44.185030Z ERR dlcservice[1321]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T14:41:44.185537Z INFO dlcservice[1321]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T14:41:44.191025Z WARNING cras_server[1368]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T14:41:44.191100Z ERR cras_server[1368]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T14:41:44.191118Z ERR cras_server[1368]: download_supported_dlc: failed to
install the DLC. Please check the network connection. Restart CRAS to retry.
2024-04-26T14:42:52.742220Z WARNING kernel: [ 724.189745] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:42:52.742351Z WARNING kernel: [ 724.198787] audit: audit_lost=23
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:42:52.745096Z ERR kernel: [ 724.203906] audit: backlog limit exceeded
2024-04-26T14:42:56.481354Z INFO kernel: [ 727.936996] binder: undelivered
TRANSACTION_COMPLETE
2024-04-26T14:42:56.481380Z INFO kernel: [ 727.939851] binder: undelivered transaction
190883, process died.
2024-04-26T14:42:57.391918Z INFO kernel: [ 728.847645] binder: undelivered
TRANSACTION_COMPLETE
2024-04-26T14:42:57.391952Z INFO kernel: [ 728.850085] binder: undelivered transaction
190924, process died.
2024-04-26T14:42:57.394154Z INFO kernel: [ 728.852961] binder: undelivered
TRANSACTION_COMPLETE
2024-04-26T14:42:57.396964Z INFO kernel: [ 728.855096] binder: undelivered transaction
190920, process died.
2024-04-26T14:43:02.733863Z WARNING kernel: [ 734.190421] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:43:02.733894Z WARNING kernel: [ 734.192318] audit: audit_lost=24
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:43:02.744884Z ERR kernel: [ 734.203688] audit: backlog limit exceeded
2024-04-26T14:43:13.644365Z NOTICE auditd[458]: Audit daemon rotating log files
2024-04-26T14:43:32.224720Z ERR cros_healthd[1319]: Not implemented reached in void
diagnostics::UdevEventsImpl::OnHdmiChange()
2024-04-26T14:43:36.121457Z ERR kernel: [ 767.577310] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:36.263500Z ERR kernel: [ 767.721173] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:36.575471Z ERR kernel: [ 768.033588] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:36.665800Z ERR kernel: [ 768.123105] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:38.136576Z ERR kernel: [ 769.594879] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:38.159522Z ERR kernel: [ 769.618008] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:38.169493Z ERR kernel: [ 769.627794] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:40.351664Z ERR kernel: [ 771.807341] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:41.059378Z WARNING cras_server[1368]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1049952 > 1048576
2024-04-26T14:43:41.068473Z ERR kernel: [ 772.526546] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:41.152563Z ERR kernel: [ 772.609913] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:41.157870Z ERR kernel: [ 772.613930] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:41.229461Z ERR kernel: [ 772.688211] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:41.255541Z ERR kernel: [ 772.714063] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:41.269707Z ERR kernel: [ 772.724973] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:41.308522Z ERR kernel: [ 772.766694] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:43.525524Z ERR kernel: [ 774.983898] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
```



```
2024-04-26T14:43:43.643476Z ERR kernel: [ 775.100435] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:45.070988Z ERR kernel: [ 776.526927] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:45.084610Z ERR kernel: [ 776.542653] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:46.545580Z ERR kernel: [ 778.002393] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:46.760018Z ERR kernel: [ 778.216186] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:52.990552Z ERR kernel: [ 784.446236] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:52.998498Z ERR kernel: [ 784.452953] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:53.017602Z ERR kernel: [ 784.473720] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:53.544510Z ERR kernel: [ 785.000674] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:43:53.562504Z ERR kernel: [ 785.018638] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:44:02.726935Z WARNING kernel: [ 794.185091] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:44:02.726965Z WARNING kernel: [ 794.186126] audit: audit_lost=25
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:44:02.726997Z ERR kernel: [ 794.187770] audit: backlog limit exceeded
2024-04-26T14:44:16.240562Z ERR kernel: [ 807.698885] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:45:48.115030Z WARNING cras_server[1368]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1050720 > 1048576
2024-04-26T14:46:17.237003Z ERR kernel: [ 928.695541] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:19.247918Z WARNING cras_server[1368]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1050208 > 1048576
2024-04-26T14:46:19.428492Z ERR kernel: [ 930.886677] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:19.441483Z ERR kernel: [ 930.899502] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:19.493507Z ERR kernel: [ 930.952441] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:20.586339Z ERR kernel: [ 932.042676] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:21.971471Z ERR kernel: [ 933.429058] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:22.042879Z ERR kernel: [ 933.498780] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:23.290911Z ERR kernel: [ 934.745842] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:23.340575Z ERR kernel: [ 934.798505] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:23.447632Z ERR kernel: [ 934.905168] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:28.925759Z ERR kernel: [ 940.383191] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:28.986463Z ERR kernel: [ 940.444751] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:29.185753Z ERR kernel: [ 940.642740] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:30.595466Z ERR kernel: [ 942.053197] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:30.905597Z ERR kernel: [ 942.362651] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:31.669564Z ERR kernel: [ 943.127144] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:40.015999Z ERR kernel: [ 951.472787] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:40.019488Z ERR kernel: [ 951.477461] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:42.005511Z ERR kernel: [ 953.462936] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
```

```
2024-04-26T14:46:42.167531Z ERR kernel: [ 953.621639] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:42.467037Z ERR kernel: [ 953.922695] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:42.467061Z ERR kernel: [ 953.926745] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:43.914471Z ERR kernel: [ 955.371779] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:43.948519Z ERR kernel: [ 955.405565] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:43.955520Z ERR kernel: [ 955.412880] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:44.005489Z ERR kernel: [ 955.463553] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:44.849508Z ERR kernel: [ 956.306248] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:45.144556Z ERR kernel: [ 956.602799] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:46:52.991808Z WARNING debugd[3650]: Failed to open procfs entry of process
14170
2024-04-26T14:46:52.992409Z WARNING debugd[3650]: Failed to open uid map file
/proc/14170/uid_map for process 14170
2024-04-26T14:46:52.993080Z WARNING debugd[3650]: Invalid pid 14170, operation not
allowed
2024-04-26T14:46:54.187862Z WARNING cras_server[1368]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1050720 > 1048576
2024-04-26T14:47:00.420628Z ERR kernel: [ 971.877530] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:00.427500Z ERR kernel: [ 971.884490] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:04.878442Z ERR shill[837]: ERROR shill: [rtnl_message.cc(1103)] RTNL
address message does not have a valid IFA_ADDRESS
2024-04-26T14:47:10.370536Z ERR kernel: [ 981.827909] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:12.145022Z ERR kernel: [ 983.601705] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:12.302481Z ERR kernel: [ 983.754582] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:12.310467Z ERR kernel: [ 983.768435] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:12.332767Z ERR kernel: [ 983.784764] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:12.351371Z ERR kernel: [ 983.805541] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:12.358787Z ERR kernel: [ 983.816563] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:12.372490Z ERR kernel: [ 983.829840] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:12.383505Z ERR kernel: [ 983.841341] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:12.387517Z ERR kernel: [ 983.845710] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:13.227990Z ERR kernel: [ 984.683765] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:13.233958Z ERR kernel: [ 984.691170] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:13.236480Z ERR kernel: [ 984.695077] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:14.381979Z ERR kernel: [ 985.838533] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:15.360606Z ERR kernel: [ 986.816685] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:19.379511Z ERR kernel: [ 990.837609] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:29.058952Z WARNING cras_server[1368]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1049952 > 1048576
2024-04-26T14:47:33.140482Z ERR kernel: [ 1004.598157] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:34.052841Z ERR kernel: [ 1005.510054] [drm:vmw_kms_fb_create] *ERROR*
```

```
failed to create vmw_framebuffer: -22
2024-04-26T14:47:34.615525Z ERR kernel: [ 1006.074133] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:34.696500Z ERR kernel: [ 1006.153579] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:34.707157Z ERR kernel: [ 1006.164558] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:34.744517Z ERR kernel: [ 1006.196136] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:34.752515Z ERR kernel: [ 1006.209548] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:35.197594Z ERR kernel: [ 1006.654928] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:36.512644Z ERR kernel: [ 1007.970707] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:36.597090Z ERR kernel: [ 1008.050645] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:37.397730Z ERR kernel: [ 1008.855526] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:37.420574Z ERR kernel: [ 1008.877732] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:43.352502Z ERR kernel: [ 1014.797867] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:43.447516Z ERR kernel: [ 1014.903979] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:43.455625Z ERR kernel: [ 1014.911069] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:44.123705Z ERR kernel: [ 1015.578990] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:44.139631Z ERR kernel: [ 1015.595895] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:44.162732Z ERR kernel: [ 1015.615849] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:44.446526Z ERR kernel: [ 1015.903115] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:46.594546Z ERR kernel: [ 1018.045946] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:47.153510Z ERR kernel: [ 1018.609322] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:47.187789Z ERR kernel: [ 1018.639728] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:47.206868Z ERR kernel: [ 1018.660426] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:47.252510Z ERR kernel: [ 1018.706608] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:47.352700Z ERR kernel: [ 1018.801718] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:52.591672Z ERR kernel: [ 1024.041826] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:55.610613Z ERR kernel: [ 1027.067809] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:56.521531Z ERR kernel: [ 1027.977970] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:56.603059Z ERR kernel: [ 1028.060728] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:56.626468Z ERR kernel: [ 1028.084141] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:56.632784Z ERR kernel: [ 1028.089768] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:56.647469Z ERR kernel: [ 1028.103631] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:56.811489Z ERR kernel: [ 1028.268555] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:56.836473Z ERR kernel: [ 1028.293938] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:56.849483Z ERR kernel: [ 1028.305560] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:56.926475Z ERR kernel: [ 1028.381666] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
```

```
2024-04-26T14:47:57.090502Z ERR kernel: [ 1028.545001] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:57.105477Z ERR kernel: [ 1028.560596] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:57.141501Z ERR kernel: [ 1028.591570] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:58.374417Z ERR kernel: [ 1029.825696] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:58.491563Z ERR kernel: [ 1029.944852] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:59.116514Z ERR kernel: [ 1030.573195] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:47:59.972252Z WARNING cras_server[1368]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1050208 > 1048576
2024-04-26T14:48:00.733487Z ERR kernel: [ 1032.190062] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:00.740918Z ERR kernel: [ 1032.195659] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:00.745989Z ERR kernel: [ 1032.202818] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:00.759981Z ERR kernel: [ 1032.214214] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:00.769531Z ERR kernel: [ 1032.224600] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:00.775609Z ERR kernel: [ 1032.232838] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:00.932477Z ERR kernel: [ 1032.390018] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:00.949218Z ERR kernel: [ 1032.404304] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:02.205537Z ERR kernel: [ 1033.662598] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:02.233550Z ERR kernel: [ 1033.690999] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:03.605818Z ERR kernel: [ 1035.061369] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:19.133543Z ERR kernel: [ 1050.591553] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:43.213543Z ERR kernel: [ 1074.671057] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:43.247867Z ERR kernel: [ 1074.705744] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:45.655610Z ERR kernel: [ 1077.113804] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:45.792002Z ERR kernel: [ 1077.249004] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:56.341576Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.vibrator@1.0::IVibrator/default
2024-04-26T14:48:58.075502Z ERR kernel: [ 1089.532706] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:58.146517Z ERR kernel: [ 1089.604242] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:59.283535Z ERR kernel: [ 1090.740916] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:59.305520Z ERR kernel: [ 1090.763245] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:59.389865Z ERR kernel: [ 1090.845624] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:48:59.546797Z ERR kernel: [ 1091.003874] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:49:24.325616Z WARNING kernel: [ 1115.779409] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:49:24.325912Z WARNING kernel: [ 1115.781531] audit: audit_lost=26
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:49:24.325919Z ERR kernel: [ 1115.783585] audit: backlog limit exceeded
2024-04-26T14:49:44.297624Z ERR cros_healthd[1319]: Not implemented reached in void
diagnostics::UdevEventsImpl::OnHdmiChange()
2024-04-26T14:50:10.252564Z ERR kernel: [ 1161.710700] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
```

```
2024-04-26T14:50:10.394480Z ERR kernel: [ 1161.853033] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:10.409554Z ERR kernel: [ 1161.866162] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:10.568605Z ERR kernel: [ 1162.024132] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:10.965651Z ERR kernel: [ 1162.423385] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:10.983872Z ERR kernel: [ 1162.439485] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:14.490740Z ERR kernel: [ 1165.946613] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:16.116039Z WARNING cras_server[1368]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1050720 > 1048576
2024-04-26T14:50:16.777624Z ERR kernel: [ 1168.235479] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:16.824034Z ERR kernel: [ 1168.280632] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:18.280590Z ERR kernel: [ 1169.738312] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:18.294582Z ERR kernel: [ 1169.752794] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:18.528096Z ERR kernel: [ 1169.983575] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:19.435520Z ERR kernel: [ 1170.892968] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:19.448478Z ERR kernel: [ 1170.902985] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:19.523697Z ERR kernel: [ 1170.980279] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:19.539505Z ERR kernel: [ 1170.996613] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:19.562503Z ERR kernel: [ 1171.019612] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:19.987492Z ERR kernel: [ 1171.443464] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:20.921557Z ERR kernel: [ 1172.380314] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:20.977485Z ERR kernel: [ 1172.435168] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:21.748484Z ERR kernel: [ 1173.206050] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:26.366466Z ERR kernel: [ 1177.824028] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:26.419966Z ERR kernel: [ 1177.875776] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:26.419987Z ERR kernel: [ 1177.878089] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:26.551699Z ERR kernel: [ 1178.009716] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:26.566534Z ERR kernel: [ 1178.023838] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:27.441677Z ERR kernel: [ 1178.899474] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:28.546518Z ERR kernel: [ 1180.002693] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:28.960495Z ERR kernel: [ 1180.418525] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:29.001781Z ERR kernel: [ 1180.455854] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:29.030463Z ERR kernel: [ 1180.489118] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:29.035847Z ERR kernel: [ 1180.492593] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:29.050590Z ERR kernel: [ 1180.506222] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:29.745483Z ERR kernel: [ 1181.203077] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:30.818482Z ERR kernel: [ 1182.276522] [drm:vmw_kms_fb_create] *ERROR*
```

```
failed to create vmw_framebuffer: -22
2024-04-26T14:50:33.006676Z WARNING kernel: [ 1184.462735] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:50:33.006695Z WARNING kernel: [ 1184.464520] audit: audit_lost=27
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:50:33.006706Z ERR kernel: [ 1184.467528] audit: backlog limit exceeded
2024-04-26T14:50:33.200511Z ERR kernel: [ 1184.657574] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:33.561505Z ERR kernel: [ 1185.019638] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:33.577533Z ERR kernel: [ 1185.035668] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:33.692113Z ERR kernel: [ 1185.149807] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:33.720568Z ERR kernel: [ 1185.178768] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:33.824683Z ERR kernel: [ 1185.281545] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:33.836461Z ERR kernel: [ 1185.295180] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:33.844561Z ERR kernel: [ 1185.301010] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:35.181273Z ERR kernel: [ 1186.632718] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:36.207780Z ERR kernel: [ 1187.664939] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:36.212484Z ERR kernel: [ 1187.670593] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:36.228639Z ERR kernel: [ 1187.686175] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:36.236088Z ERR kernel: [ 1187.692550] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:37.047579Z ERR kernel: [ 1188.502250] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:37.072517Z ERR kernel: [ 1188.525926] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:37.093478Z ERR kernel: [ 1188.550519] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:37.103771Z ERR kernel: [ 1188.560102] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:37.668775Z ERR kernel: [ 1189.123429] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:37.792042Z ERR kernel: [ 1189.246741] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:37.803526Z ERR kernel: [ 1189.260651] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:37.819507Z ERR kernel: [ 1189.274722] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:39.041565Z ERR kernel: [ 1190.499758] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:40.011735Z ERR kernel: [ 1191.468174] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:40.030721Z ERR kernel: [ 1191.487551] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:40.047665Z ERR kernel: [ 1191.503635] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:45.554836Z ERR kernel: [ 1197.009665] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:50:49.603611Z ERR kernel: [ 1201.060234] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:00.311347Z INFO rsyslogd[462]: -- MARK --
2024-04-26T14:51:25.034475Z ERR kernel: [ 1236.492392] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:25.037461Z ERR kernel: [ 1236.495901] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:25.122507Z ERR kernel: [ 1236.577607] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:25.340516Z ERR kernel: [ 1236.798297] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
```

```
2024-04-26T14:51:25.365699Z ERR kernel: [ 1236.813859] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:25.446518Z ERR kernel: [ 1236.904991] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:25.913546Z ERR kernel: [ 1237.371806] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:25.934486Z ERR kernel: [ 1237.392292] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:25.952503Z ERR kernel: [ 1237.410610] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:26.493484Z ERR kernel: [ 1237.951751] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:28.190749Z ERR kernel: [ 1239.648629] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:32.125963Z ERR kernel: [ 1243.577369] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:36.496009Z ERR kernel: [ 1247.950006] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:36.529505Z ERR kernel: [ 1247.985629] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:37.192012Z ERR kernel: [ 1248.642024] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:37.223470Z ERR kernel: [ 1248.679196] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:51:37.231537Z ERR kernel: [ 1248.688924] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:33.214093Z WARNING kernel: [ 1304.670548] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:52:33.214121Z WARNING kernel: [ 1304.673001] audit: audit_lost=28
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:52:33.220678Z ERR kernel: [ 1304.676074] audit: backlog limit exceeded
2024-04-26T14:52:35.508541Z ERR kernel: [ 1306.964296] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:35.585695Z ERR kernel: [ 1307.040636] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:36.626550Z ERR kernel: [ 1308.079766] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:36.645628Z ERR kernel: [ 1308.102343] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:36.667976Z ERR kernel: [ 1308.122170] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:37.985796Z WARNING cras_server[1368]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1050720 > 1048576
2024-04-26T14:52:38.225488Z ERR kernel: [ 1309.680674] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:38.439489Z ERR kernel: [ 1309.896369] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:38.460481Z ERR kernel: [ 1309.917869] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:39.004608Z ERR kernel: [ 1310.457796] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:39.458331Z ERR kernel: [ 1310.907651] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:39.543359Z ERR kernel: [ 1310.999167] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:42.114677Z ERR kernel: [ 1313.571338] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:43.269000Z WARNING kernel: [ 1314.716836] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:52:43.269039Z WARNING kernel: [ 1314.724158] audit: audit_lost=29
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:52:43.271016Z ERR kernel: [ 1314.730205] audit: backlog limit exceeded
2024-04-26T14:52:43.316406Z ERR kernel: [ 1314.770696] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:43.388569Z ERR kernel: [ 1314.806841] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:47.278614Z WARNING cras_server[1368]: fetch err: -32 for 10001a
2024-04-26T14:52:59.491561Z ERR kernel: [ 1330.946353] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
```

```
2024-04-26T14:52:59.604515Z ERR kernel: [ 1331.056500] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:59.927712Z ERR kernel: [ 1331.384493] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:59.943497Z ERR kernel: [ 1331.400984] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:59.983503Z ERR kernel: [ 1331.440461] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:52:59.988486Z ERR kernel: [ 1331.446085] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:00.036476Z ERR kernel: [ 1331.492770] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:00.042532Z ERR kernel: [ 1331.498127] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:03.869541Z ERR kernel: [ 1335.325917] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:07.469491Z ERR kernel: [ 1338.926680] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:07.930504Z ERR kernel: [ 1339.382210] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:08.040494Z ERR kernel: [ 1339.497103] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:08.406478Z ERR kernel: [ 1339.861893] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:09.301497Z ERR kernel: [ 1340.754500] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:09.460542Z ERR kernel: [ 1340.917373] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:11.080493Z ERR kernel: [ 1342.530215] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:11.751612Z ERR kernel: [ 1343.207618] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:11.804574Z ERR kernel: [ 1343.261971] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:13.766571Z NOTICE auditd[458]: Audit daemon rotating log files
2024-04-26T14:53:18.175493Z ERR kernel: [ 1349.630712] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:18.392117Z ERR kernel: [ 1349.848505] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:18.412002Z ERR kernel: [ 1349.868892] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:18.546528Z ERR kernel: [ 1350.002468] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:18.558476Z ERR kernel: [ 1350.010859] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:18.577604Z ERR kernel: [ 1350.034137] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:19.256480Z ERR kernel: [ 1350.712412] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:19.297901Z ERR kernel: [ 1350.749327] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:19.425560Z ERR kernel: [ 1350.881757] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:20.661488Z ERR kernel: [ 1352.118997] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:23.333721Z ERR kernel: [ 1354.770282] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:23.548606Z ERR kernel: [ 1354.997977] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:23.585741Z ERR kernel: [ 1355.040201] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:23.625477Z ERR kernel: [ 1355.080052] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:23.657477Z ERR kernel: [ 1355.113351] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:23.746840Z INFO kernel: [ 1355.198316] binder: undelivered
TRANSACTION_COMPLETE
2024-04-26T14:53:23.746940Z INFO kernel: [ 1355.201708] binder: undelivered transaction
385032, process died.
```



```
2024-04-26T14:53:23.823481Z ERR kernel: [ 1355.276466] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:23.840661Z ERR kernel: [ 1355.297657] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:24.082720Z ERR kernel: [ 1355.537921] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:24.098547Z ERR kernel: [ 1355.555083] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:24.104639Z ERR kernel: [ 1355.560749] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:24.342498Z WARNING kernel: [ 1355.789426] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:53:24.347121Z WARNING kernel: [ 1355.798177] audit: audit_lost=30
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:53:24.347133Z ERR kernel: [ 1355.803035] audit: backlog limit exceeded
2024-04-26T14:53:24.534819Z ERR kernel: [ 1355.985557] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:24.564725Z ERR kernel: [ 1356.015412] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:24.702628Z ERR kernel: [ 1356.156778] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:29.099436Z ERR kernel: [ 1360.552415] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:29.110503Z ERR kernel: [ 1360.567732] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:29.185526Z ERR kernel: [ 1360.639332] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:29.219917Z ERR kernel: [ 1360.669401] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:29.219968Z ERR kernel: [ 1360.678226] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:29.249105Z ERR kernel: [ 1360.700760] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:29.254979Z ERR kernel: [ 1360.710424] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:29.372483Z ERR kernel: [ 1360.827716] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:30.362490Z ERR kernel: [ 1361.812827] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:30.380502Z ERR kernel: [ 1361.835381] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:32.024590Z ERR kernel: [ 1363.482128] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:38.515180Z WARNING cras_server[1368]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1050720 > 1048576
2024-04-26T14:53:38.624505Z ERR kernel: [ 1370.080759] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:38.708463Z ERR kernel: [ 1370.166848] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:38.744500Z ERR kernel: [ 1370.200162] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:39.512475Z ERR kernel: [ 1370.970342] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:44.766483Z ERR kernel: [ 1376.225180] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:44.777522Z ERR kernel: [ 1376.235370] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:48.231652Z ERR kernel: [ 1379.689464] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:48.380494Z ERR kernel: [ 1379.838897] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:48.547477Z ERR kernel: [ 1380.006025] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:49.710483Z ERR kernel: [ 1381.167173] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:49.750634Z ERR kernel: [ 1381.207657] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:49.810503Z ERR kernel: [ 1381.267833] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
```

```
2024-04-26T14:53:50.475620Z ERR kernel: [ 1381.932175] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:50.598604Z ERR kernel: [ 1382.051893] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:52.280514Z ERR kernel: [ 1383.739042] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:53.269351Z WARNING kernel: [ 1384.721799] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:53:53.269380Z WARNING kernel: [ 1384.724089] audit: audit_lost=31
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:53:53.281612Z ERR kernel: [ 1384.741379] audit: backlog limit exceeded
2024-04-26T14:53:56.658471Z ERR kernel: [ 1388.115115] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:53:57.438705Z WARNING cras_server[1368]: fetch err: -32 for 10001d
2024-04-26T14:54:01.517037Z ERR kernel: [ 1392.973933] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:54:24.324858Z WARNING kernel: [ 1415.773996] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:54:24.324887Z WARNING kernel: [ 1415.775655] audit: audit_lost=32
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:54:24.324890Z ERR kernel: [ 1415.777625] audit: backlog limit exceeded
2024-04-26T14:54:24.324891Z WARNING kernel: [ 1415.778864] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:54:24.329547Z WARNING kernel: [ 1415.785412] audit: audit_lost=33
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:54:24.329562Z ERR kernel: [ 1415.789027] audit: backlog limit exceeded
2024-04-26T14:54:54.382020Z WARNING kernel: [ 1445.838657] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:54:54.382046Z WARNING kernel: [ 1445.840611] audit: audit_lost=34
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:54:54.385494Z ERR kernel: [ 1445.842909] audit: backlog limit exceeded
2024-04-26T14:56:04.487637Z WARNING cras_server[1368]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1081920 > 1048576
2024-04-26T14:56:06.979016Z ERR kernel: [ 1518.393443] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:18.236793Z ERR kernel: [ 1529.692364] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:20.251559Z ERR kernel: [ 1531.707675] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:20.318763Z ERR kernel: [ 1531.775565] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:39.136256Z WARNING cras_server[1368]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1050464 > 1048576
2024-04-26T14:56:43.547469Z ERR cras_healthd[1319]: Not implemented reached in void
diagnostics::UdevEventsImpl::OnHdmiChange()
2024-04-26T14:56:47.944473Z ERR kernel: [ 1559.402128] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:48.011465Z ERR kernel: [ 1559.469797] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:48.032531Z ERR kernel: [ 1559.490348] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:48.283499Z ERR kernel: [ 1559.741815] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:48.296472Z ERR kernel: [ 1559.752413] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:48.299465Z ERR kernel: [ 1559.757554] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:50.781496Z ERR kernel: [ 1562.239340] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:51.434468Z ERR kernel: [ 1562.892050] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:51.439498Z ERR kernel: [ 1562.896620] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:51.591547Z ERR kernel: [ 1563.048690] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:51.606494Z ERR kernel: [ 1563.064295] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:51.628748Z ERR kernel: [ 1563.086492] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
```

```
2024-04-26T14:56:51.680482Z ERR kernel: [ 1563.137405] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:51.704675Z ERR kernel: [ 1563.162416] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:51.717464Z ERR kernel: [ 1563.175291] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:51.722655Z ERR kernel: [ 1563.180111] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:51.760514Z ERR kernel: [ 1563.218196] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:51.839477Z ERR kernel: [ 1563.293344] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:53.683828Z ERR kernel: [ 1565.076894] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:53.683881Z ERR kernel: [ 1565.138213] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:54.026581Z ERR kernel: [ 1565.482725] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:54.050635Z ERR kernel: [ 1565.506837] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:54.084675Z ERR kernel: [ 1565.539121] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T14:56:54.292050Z WARNING kernel: [ 1565.738778] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:56:54.292083Z WARNING kernel: [ 1565.743942] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:56:54.292089Z WARNING kernel: [ 1565.749169] audit: audit_lost=35
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:56:54.302515Z WARNING kernel: [ 1565.755761] audit: audit_lost=36
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:56:54.302549Z ERR kernel: [ 1565.760175] audit: backlog limit exceeded
2024-04-26T14:56:54.309588Z ERR kernel: [ 1565.768002] audit: backlog limit exceeded
2024-04-26T14:57:24.221137Z WARNING kernel: [ 1595.678690] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T14:57:24.221155Z WARNING kernel: [ 1595.680079] audit: audit_lost=37
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T14:57:24.222846Z ERR kernel: [ 1595.682593] audit: backlog limit exceeded
2024-04-26T15:02:04.876498Z ERR shill[837]: ERROR shill: [rtnl_message.cc(1103)] RTNL
address message does not have a valid IFA_ADDRESS
2024-04-26T15:04:32.543460Z INFO dbus-daemon[583]: [system] Activating service
name='org.chromium.MachineLearning' requested by ':1.41' (uid=1000 pid=1044
comm="/opt/google/chrome/chrome --enable-webgl-image-chr" label="u:r:cros_browser:s0")
(using servicehelper)
2024-04-26T15:04:32.748909Z NOTICE ml-service[23105]: Pre-start ml-service
task=mojo_service
2024-04-26T15:04:32.818000Z INFO minijail0[23111]: libminijail[23111]: applying policy
for default runtime: /etc/security/minijail/v0.bin
2024-04-26T15:04:32.820109Z WARNING minijail0[23111]: libminijail[23111]: failed to
create a ruleset: Function not implemented
2024-04-26T15:04:32.820136Z WARNING minijail0[23111]: libminijail[23111]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T15:04:32.820162Z WARNING minijail0[23114]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T15:04:32.820173Z WARNING minijail0[23114]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T15:04:32.821356Z INFO minijail0[23114]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFER: false
2024-04-26T15:04:33.029884Z INFO dbus-daemon[583]: [system] Successfully activated
service 'org.chromium.MachineLearning'
2024-04-26T15:05:14.626153Z WARNING kernel: [ 2066.083496] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:05:14.626176Z WARNING kernel: [ 2066.084979] audit: audit_lost=38
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:05:14.626214Z ERR kernel: [ 2066.086993] audit: backlog limit exceeded
2024-04-26T15:05:38.391976Z NOTICE auditd[458]: Audit daemon rotating log files
2024-04-26T15:06:07.605938Z INFO trunksd[753]: Finished saving contexts.
2024-04-26T15:06:28.554293Z NOTICE powerd_suspend[23983]: Going to suspend-to-RAM state:
args=--nosuspend_to_idle --wakeup_count=43579
2024-04-26T15:06:28.860364Z NOTICE powerd_suspend[23983]: Available order 3 pages: 25434
```

```
2024-04-26T15:06:28.866274Z NOTICE powerd_suspend[23983]: Finalizing suspend
2024-04-26T15:06:28.879004Z INFO kernel: [ 2140.337844] PM: suspend entry (s2idle)
2024-04-26T15:06:28.891742Z INFO kernel: [ 2140.350460] Filesystems sync: 0.011 seconds
2024-04-26T15:06:28.891830Z DEBUG kernel: [ 2140.351857] PM: Preparing system for sleep
(s2idle)
2024-04-26T15:41:23.105249Z INFO kernel: [ 2140.418728] Freezing user space processes ...
(elapsed 0.024 seconds) done.
2024-04-26T15:41:23.168883Z INFO kernel: [ 2140.444836] OOM killer disabled.
2024-04-26T15:41:23.168905Z INFO kernel: [ 2140.445408] Freezing remaining freezable
tasks ... (elapsed 0.009 seconds) done.
2024-04-26T15:41:23.168912Z DEBUG kernel: [ 2140.456703] PM: Suspending system (s2idle)
2024-04-26T15:41:23.168919Z INFO kernel: [ 2140.480941] rfkill rfkill0: PM: calling
rfkill_suspend+0x0/0x21 @ 24070, parent: hci0
2024-04-26T15:41:23.168923Z INFO kernel: [ 2140.483589] rfkill rfkill0: PM:
rfkill_suspend+0x0/0x21 returned 0 after 1 usecs
2024-04-26T15:41:23.168926Z INFO kernel: [ 2140.485416] input input10: PM: calling
input_dev_suspend+0x0/0x47 @ 24070, parent: card0
2024-04-26T15:41:23.168929Z INFO kernel: [ 2140.489514] input input10: PM:
input_dev_suspend+0x0/0x47 returned 0 after 555 usecs
2024-04-26T15:41:23.170021Z INFO kernel: [ 2140.490912] input input9: PM: calling
input_dev_suspend+0x0/0x47 @ 24070, parent: card0
2024-04-26T15:41:23.170040Z INFO kernel: [ 2140.492214] input input9: PM:
input_dev_suspend+0x0/0x47 returned 0 after 0 usecs
2024-04-26T15:41:23.170050Z INFO kernel: [ 2140.493478] input input8: PM: calling
input_dev_suspend+0x0/0x47 @ 24070, parent: card0
2024-04-26T15:41:23.170056Z INFO kernel: [ 2140.494779] input input8: PM:
input_dev_suspend+0x0/0x47 returned 0 after 0 usecs
2024-04-26T15:41:23.170596Z INFO kernel: [ 2140.495997] input input7: PM: calling
input_dev_suspend+0x0/0x47 @ 24070, parent: card0
2024-04-26T15:41:23.170691Z INFO kernel: [ 2140.497335] input input7: PM:
input_dev_suspend+0x0/0x47 returned 0 after 0 usecs
2024-04-26T15:41:23.170700Z INFO kernel: [ 2140.498673] input input6: PM: calling
input_dev_suspend+0x0/0x47 @ 24070, parent: card0
2024-04-26T15:41:23.170703Z INFO kernel: [ 2140.500310] input input6: PM:
input_dev_suspend+0x0/0x47 returned 0 after 0 usecs
2024-04-26T15:41:23.171234Z INFO kernel: [ 2140.502143] sound pcmC0D0c: PM: calling
do_pcm_suspend+0x0/0x23 @ 24070, parent: card0
2024-04-26T15:41:23.171246Z INFO kernel: [ 2140.507668] sound pcmC0D0c: PM:
do_pcm_suspend+0x0/0x23 returned 0 after 1606 usecs
2024-04-26T15:41:23.171251Z INFO kernel: [ 2140.509509] sound pcmC0D0p: PM: calling
do_pcm_suspend+0x0/0x23 @ 24070, parent: card0
2024-04-26T15:41:23.227083Z INFO kernel: [ 2140.511343] sound pcmC0D0p: PM:
do_pcm_suspend+0x0/0x23 returned 0 after 0 usecs
2024-04-26T15:41:23.227110Z INFO kernel: [ 2140.515151] platform regulatory.0: PM:
calling platform_pm_suspend+0x0/0x4a @ 24070, parent: platform
2024-04-26T15:41:23.227116Z INFO kernel: [ 2140.518510] platform regulatory.0: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 35 usecs
2024-04-26T15:41:23.227865Z INFO kernel: [ 2140.514381] snd_hda_codec_generic
hdaudioC0D0: PM: calling hda_codec_pm_suspend+0x0/0x19 [snd_hda_codec] @ 15801, parent:
0000:02:02.0
2024-04-26T15:41:23.227878Z INFO kernel: [ 2140.522560] input input5: PM: calling
input_dev_suspend+0x0/0x47 @ 24070, parent: 0003:0E0F:0003.0001
2024-04-26T15:41:23.227882Z INFO kernel: [ 2140.527448] input input5: PM:
input_dev_suspend+0x0/0x47 returned 0 after 0 usecs
2024-04-26T15:41:23.228125Z INFO kernel: [ 2140.527272] usb 2-2.1: PM: calling
usb_dev_suspend+0x0/0x14 @ 22022, parent: 2-2
2024-04-26T15:41:23.228138Z INFO kernel: [ 2140.529731] input input3: PM: calling
input_dev_suspend+0x0/0x47 @ 24070, parent: serio1
2024-04-26T15:41:23.228144Z INFO kernel: [ 2140.533079] usb 2-1: PM: calling
usb_dev_suspend+0x0/0x14 @ 14477, parent: usb2
2024-04-26T15:41:23.266068Z INFO kernel: [ 2140.534046] usb 2-2.1: PM:
usb_dev_suspend+0x0/0x14 returned 0 after 2999 usecs
2024-04-26T15:41:23.266095Z INFO kernel: [ 2140.535650] input input3: PM:
input_dev_suspend+0x0/0x47 returned 0 after 1 usecs
2024-04-26T15:41:23.266100Z INFO kernel: [ 2140.536528] usb 2-2: PM: calling
usb_dev_suspend+0x0/0x14 @ 22024, parent: usb2
2024-04-26T15:41:23.266104Z INFO kernel: [ 2140.538066] input input4: PM: calling
input_dev_suspend+0x0/0x47 @ 24070, parent: serio1
2024-04-26T15:41:23.293597Z INFO kernel: [ 2140.538072] input input4: PM:
```

```
input_dev_suspend+0x0/0x47 returned 0 after 0 usecs
2024-04-26T15:41:23.298587Z INFO kernel: [ 2140.538462] leds input1::scrolllock: PM:
calling led_suspend+0x0/0x3f @ 24070, parent: input1
2024-04-26T15:41:23.298606Z INFO kernel: [ 2140.545570] leds input1::scrolllock: PM:
led_suspend+0x0/0x3f returned 0 after 1396 usecs
2024-04-26T15:41:23.298610Z INFO kernel: [ 2140.546946] leds input1::capslock: PM:
calling led_suspend+0x0/0x3f @ 24070, parent: input1
2024-04-26T15:41:23.298612Z INFO kernel: [ 2140.548392] leds input1::capslock: PM:
led_suspend+0x0/0x3f returned 0 after 0 usecs
2024-04-26T15:41:23.298614Z INFO kernel: [ 2140.550059] leds input1::numlock: PM: calling
led_suspend+0x0/0x3f @ 24070, parent: input1
2024-04-26T15:41:23.298616Z INFO kernel: [ 2140.551420] leds input1::numlock: PM:
led_suspend+0x0/0x3f returned 0 after 0 usecs
2024-04-26T15:41:23.298618Z INFO kernel: [ 2140.553224] input input1: PM: calling
input_dev_suspend+0x0/0x47 @ 24070, parent: serio0
2024-04-26T15:41:23.298620Z INFO kernel: [ 2140.554529] input input1: PM:
input_dev_suspend+0x0/0x47 returned 0 after 0 usecs
2024-04-26T15:41:23.298624Z INFO kernel: [ 2140.558047] alarmtimer alarmtimer.0.auto: PM:
calling platform_pm_suspend+0x0/0x4a @ 24070, parent: rtc0
2024-04-26T15:41:23.298628Z INFO kernel: [ 2140.560989] alarmtimer alarmtimer.0.auto: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 1347 usecs
2024-04-26T15:41:23.298632Z INFO kernel: [ 2140.562587] psmouse serio1: PM: calling
serio_suspend+0x0/0x1d @ 24070, parent: i8042
2024-04-26T15:41:23.298636Z INFO kernel: [ 2140.566893] psmouse serio1: PM:
serio_suspend+0x0/0x1d returned 0 after 2938 usecs
2024-04-26T15:41:23.298639Z INFO kernel: [ 2140.568614] atkbd serio0: PM: calling
serio_suspend+0x0/0x1d @ 24070, parent: i8042
2024-04-26T15:41:23.298643Z INFO kernel: [ 2140.571493] atkbd serio0: PM:
serio_suspend+0x0/0x1d returned 0 after 943 usecs
2024-04-26T15:41:23.298647Z INFO kernel: [ 2140.572702] i8042 i8042: PM: calling
platform_pm_suspend+0x0/0x4a @ 24070, parent: platform
2024-04-26T15:41:23.298650Z INFO kernel: [ 2140.575155] i8042 i8042: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 370 usecs
2024-04-26T15:41:23.298654Z INFO kernel: [ 2140.577318] usb usb1: PM: calling
usb_dev_suspend+0x0/0x14 @ 22022, parent: 0000:02:03.0
2024-04-26T15:41:23.298657Z INFO kernel: [ 2140.577830] platform Fixed MDIO bus.0: PM:
calling platform_pm_suspend+0x0/0x4a @ 24070, parent: platform
2024-04-26T15:41:23.298661Z INFO kernel: [ 2140.581090] platform Fixed MDIO bus.0: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs
2024-04-26T15:41:23.298665Z INFO kernel: [ 2140.583285] ata2: PM: calling
ata_port_pm_suspend+0x0/0x3e @ 11035, parent: 0000:00:07.1
2024-04-26T15:41:23.298668Z INFO kernel: [ 2140.584698] usb 2-2: PM:
usb_dev_suspend+0x0/0x14 returned 0 after 44864 usecs
2024-04-26T15:41:23.298671Z INFO kernel: [ 2140.586201] ata1: PM: calling
ata_port_pm_suspend+0x0/0x3e @ 137, parent: 0000:00:07.1
2024-04-26T15:41:23.298675Z INFO kernel: [ 2140.586616] usb 2-1: PM:
usb_dev_suspend+0x0/0x14 returned 0 after 51799 usecs
2024-04-26T15:41:23.298678Z INFO kernel: [ 2140.587330] usb usb2: PM: calling
usb_dev_suspend+0x0/0x14 @ 22023, parent: 0000:02:00.0
2024-04-26T15:41:23.298682Z INFO kernel: [ 2140.592705] ata2: PM:
ata_port_pm_suspend+0x0/0x3e returned 0 after 7082 usecs
2024-04-26T15:41:23.298685Z INFO kernel: [ 2140.592798] usb usb1: PM:
usb_dev_suspend+0x0/0x14 returned 0 after 13671 usecs
2024-04-26T15:41:23.298689Z INFO kernel: [ 2140.592695] serial8250 serial8250: PM:
calling platform_pm_suspend+0x0/0x4a @ 24070, parent: platform
2024-04-26T15:41:23.298693Z INFO kernel: [ 2140.593093] ata1: PM:
ata_port_pm_suspend+0x0/0x3e returned 0 after 4101 usecs
2024-04-26T15:41:23.298700Z INFO kernel: [ 2140.593105] usb usb2: PM:
usb_dev_suspend+0x0/0x14 returned 0 after 127 usecs
2024-04-26T15:41:23.298703Z INFO kernel: [ 2140.601526] serial8250 serial8250: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 1274 usecs
2024-04-26T15:41:23.298706Z INFO kernel: [ 2140.602985] input input0: PM: calling
input_dev_suspend+0x0/0x47 @ 24070, parent: LNXPOWER0
2024-04-26T15:41:23.298708Z INFO kernel: [ 2140.604361] input input0: PM:
input_dev_suspend+0x0/0x47 returned 0 after 0 usecs
2024-04-26T15:41:23.298710Z INFO kernel: [ 2140.611987] platform intel_rapl_msr.0: PM:
calling platform_pm_suspend+0x0/0x4a @ 24070, parent: platform
2024-04-26T15:41:23.298712Z INFO kernel: [ 2140.613710] platform intel_rapl_msr.0: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs
```

2024-04-26T15:41:23.298714Z INFO kernel: [2140.616065] system 00:05: PM: calling pnp_bus_suspend+0x0/0x14 @ 24070, parent: pnp0
2024-04-26T15:41:23.314825Z INFO kernel: [2140.619753] system 00:05: PM: pnp_bus_suspend+0x0/0x14 returned 0 after 1532 usecs
2024-04-26T15:41:23.314849Z INFO kernel: [2140.621113] system 00:04: PM: calling pnp_bus_suspend+0x0/0x14 @ 24070, parent: pnp0
2024-04-26T15:41:23.314852Z INFO kernel: [2140.622401] system 00:04: PM: pnp_bus_suspend+0x0/0x14 returned 0 after 0 usecs
2024-04-26T15:41:23.314855Z INFO kernel: [2140.623782] i8042 aux 00:03: PM: calling pnp_bus_suspend+0x0/0x14 @ 24070, parent: pnp0
2024-04-26T15:41:23.314858Z INFO kernel: [2140.626237] i8042 aux 00:03: PM: pnp_bus_suspend+0x0/0x14 returned 0 after 1 usecs
2024-04-26T15:41:23.314861Z INFO kernel: [2140.628081] i8042 kbd 00:02: PM: calling pnp_bus_suspend+0x0/0x14 @ 24070, parent: pnp0
2024-04-26T15:41:23.314863Z INFO kernel: [2140.632595] i8042 kbd 00:02: PM: pnp_bus_suspend+0x0/0x14 returned 0 after 1 usecs
2024-04-26T15:41:23.314866Z INFO kernel: [2140.634207] rtc_cmos 00:01: PM: calling pnp_bus_suspend+0x0/0x14 @ 24070, parent: pnp0
2024-04-26T15:41:23.314869Z INFO kernel: [2140.636360] rtc_cmos 00:01: PM: pnp_bus_suspend+0x0/0x14 returned 0 after 751 usecs
2024-04-26T15:41:23.314871Z INFO kernel: [2140.637768] system 00:00: PM: calling pnp_bus_suspend+0x0/0x14 @ 24070, parent: pnp0
2024-04-26T15:41:23.314874Z INFO kernel: [2140.639184] system 00:00: PM: pnp_bus_suspend+0x0/0x14 returned 0 after 0 usecs
2024-04-26T15:41:23.314877Z INFO kernel: [2140.639225] snd_hda_codec_generic hdaudioC0D0: PM: hda_codec_pm_suspend+0x0/0x19 [snd_hda_codec] returned 0 after 113147 usecs
2024-04-26T15:41:23.314880Z INFO kernel: [2140.640665] platform chromeos_acpi: PM: calling platform_pm_suspend+0x0/0x4a @ 24070, parent: platform
2024-04-26T15:41:23.314883Z INFO kernel: [2140.644662] platform chromeos_acpi: PM: platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs
2024-04-26T15:41:23.314885Z INFO kernel: [2140.646264] platform efivars.0: PM: calling platform_pm_suspend+0x0/0x4a @ 24070, parent: platform
2024-04-26T15:41:23.314888Z INFO kernel: [2140.647716] platform efivars.0: PM: platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs
2024-04-26T15:41:23.314891Z INFO kernel: [2140.649406] platform rtc-efi.0: PM: calling platform_pm_suspend+0x0/0x4a @ 24070, parent: platform
2024-04-26T15:41:23.314893Z INFO kernel: [2140.650998] platform rtc-efi.0: PM: platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs
2024-04-26T15:41:23.315212Z INFO kernel: [2140.652309] button LNX_PWRBN:00: PM: calling acpi_button_suspend+0x0/0x19 @ 24070, parent: LNXSYSTEM:00
2024-04-26T15:41:23.315220Z INFO kernel: [2140.654580] button LNX_PWRBN:00: PM: acpi_button_suspend+0x0/0x19 returned 0 after 741 usecs
2024-04-26T15:41:23.315223Z INFO kernel: [2140.659630] platform ACPI0003:00: PM: calling platform_pm_suspend+0x0/0x4a @ 24070, parent: platform
2024-04-26T15:41:23.315333Z INFO kernel: [2140.661142] platform ACPI0003:00: PM: platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs
2024-04-26T15:41:23.315342Z INFO kernel: [2140.662652] platform PNP0800:00: PM: calling platform_pm_suspend+0x0/0x4a @ 24070, parent: 0000:00:07.0
2024-04-26T15:41:23.315347Z INFO kernel: [2140.664149] platform PNP0800:00: PM: platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs
2024-04-26T15:41:23.315354Z INFO kernel: [2140.665738] platform PNP0001:00: PM: calling platform_pm_suspend+0x0/0x4a @ 24070, parent: 0000:00:07.0
2024-04-26T15:41:23.315358Z INFO kernel: [2140.667614] platform PNP0001:00: PM: platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs
2024-04-26T15:41:23.315361Z INFO kernel: [2140.670331] nvme 0000:03:00.0: PM: calling pci_pm_suspend+0x0/0x1da @ 15801, parent: 0000:00:15.0
2024-04-26T15:41:23.315363Z INFO kernel: [2140.670959] ehci-pci 0000:02:03.0: PM: calling pci_pm_suspend+0x0/0x1da @ 11035, parent: 0000:00:11.0
2024-04-26T15:41:23.315785Z INFO kernel: [2140.677287] ehci-pci 0000:02:03.0: PM: pci_pm_suspend+0x0/0x1da returned 0 after 1553 usecs
2024-04-26T15:41:23.315795Z INFO kernel: [2140.679046] snd_hda_intel 0000:02:02.0: PM: calling pci_pm_suspend+0x0/0x1da @ 11035, parent: 0000:00:11.0
2024-04-26T15:41:23.315799Z INFO kernel: [2140.679757] e1000 0000:02:01.0: PM: calling pci_pm_suspend+0x0/0x1da @ 137, parent: 0000:00:11.0
2024-04-26T15:41:23.315802Z INFO kernel: [2140.679802] uhci_hcd 0000:02:00.0: PM: calling pci_pm_suspend+0x0/0x1da @ 22024, parent: 0000:00:11.0
2024-04-26T15:41:23.315805Z INFO kernel: [2140.684844] uhci_hcd 0000:02:00.0: PM: pci_pm_suspend+0x0/0x1da returned 0 after 270 usecs

```
2024-04-26T15:41:23.315809Z INFO kernel: [ 2140.688778] pcieport 0000:00:18.7: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.315812Z INFO kernel: [ 2140.688838] pcieport 0000:00:18.6: PM:
calling pci_pm_suspend+0x0/0x1da @ 22022, parent: pci0000:00
2024-04-26T15:41:23.315816Z INFO kernel: [ 2140.688958] pcieport 0000:00:18.5: PM:
calling pci_pm_suspend+0x0/0x1da @ 14477, parent: pci0000:00
2024-04-26T15:41:23.315819Z INFO kernel: [ 2140.690836] pcieport 0000:00:18.5: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 1868 usecs
2024-04-26T15:41:23.315823Z INFO kernel: [ 2140.691245] pcieport 0000:00:18.4: PM:
calling pci_pm_suspend+0x0/0x1da @ 14477, parent: pci0000:00
2024-04-26T15:41:23.315913Z INFO kernel: [ 2140.691437] pcieport 0000:00:18.7: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 363 usecs
2024-04-26T15:41:23.315921Z INFO kernel: [ 2140.691448] pcieport 0000:00:18.3: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.315925Z INFO kernel: [ 2140.691614] pcieport 0000:00:18.3: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 162 usecs
2024-04-26T15:41:23.315928Z INFO kernel: [ 2140.691621] pcieport 0000:00:18.2: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.315931Z INFO kernel: [ 2140.692103] pcieport 0000:00:18.2: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 478 usecs
2024-04-26T15:41:23.315935Z INFO kernel: [ 2140.692112] pcieport 0000:00:18.1: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.315938Z INFO kernel: [ 2140.692319] pcieport 0000:00:18.1: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 204 usecs
2024-04-26T15:41:23.315941Z INFO kernel: [ 2140.692325] pcieport 0000:00:18.0: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.315943Z INFO kernel: [ 2140.692482] pcieport 0000:00:18.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 153 usecs
2024-04-26T15:41:23.315947Z INFO kernel: [ 2140.692488] pcieport 0000:00:17.7: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.315951Z INFO kernel: [ 2140.692649] pcieport 0000:00:17.7: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 157 usecs
2024-04-26T15:41:23.316543Z INFO kernel: [ 2140.692656] pcieport 0000:00:17.6: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.316816Z INFO kernel: [ 2140.692815] pcieport 0000:00:17.6: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 155 usecs
2024-04-26T15:41:23.316826Z INFO kernel: [ 2140.692821] pcieport 0000:00:17.5: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.316830Z INFO kernel: [ 2140.692972] pcieport 0000:00:17.5: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 148 usecs
2024-04-26T15:41:23.316833Z INFO kernel: [ 2140.692978] pcieport 0000:00:17.4: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.316837Z INFO kernel: [ 2140.693130] pcieport 0000:00:17.4: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 149 usecs
2024-04-26T15:41:23.316840Z INFO kernel: [ 2140.693135] pcieport 0000:00:17.3: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.316844Z INFO kernel: [ 2140.693311] pcieport 0000:00:17.3: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 172 usecs
2024-04-26T15:41:23.316847Z INFO kernel: [ 2140.693316] pcieport 0000:00:17.2: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.316850Z INFO kernel: [ 2140.693472] pcieport 0000:00:17.2: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 152 usecs
2024-04-26T15:41:23.316854Z INFO kernel: [ 2140.693478] pcieport 0000:00:17.1: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.316857Z INFO kernel: [ 2140.693636] pcieport 0000:00:17.1: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 155 usecs
2024-04-26T15:41:23.316861Z INFO kernel: [ 2140.693643] pcieport 0000:00:17.0: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.316865Z INFO kernel: [ 2140.693801] pcieport 0000:00:17.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 155 usecs
2024-04-26T15:41:23.316869Z INFO kernel: [ 2140.693807] pcieport 0000:00:16.7: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.316873Z INFO kernel: [ 2140.694407] pcieport 0000:00:18.6: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 366 usecs
2024-04-26T15:41:23.316876Z INFO kernel: [ 2140.694433] pcieport 0000:00:16.7: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 623 usecs
2024-04-26T15:41:23.316879Z INFO kernel: [ 2140.694442] pcieport 0000:00:16.6: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.316932Z INFO kernel: [ 2140.694689] pcieport 0000:00:16.6: PM:
```

```
pci_pm_suspend+0x0/0x1da returned 0 after 202 usecs
2024-04-26T15:41:23.316939Z INFO kernel: [ 2140.694697] pcieport 0000:00:16.5: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.316943Z INFO kernel: [ 2140.694888] pcieport 0000:00:16.5: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 187 usecs
2024-04-26T15:41:23.316946Z INFO kernel: [ 2140.694895] pcieport 0000:00:16.4: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.316950Z INFO kernel: [ 2140.695124] pcieport 0000:00:16.4: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 188 usecs
2024-04-26T15:41:23.316957Z INFO kernel: [ 2140.695132] pcieport 0000:00:16.3: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.317005Z INFO kernel: [ 2140.695344] pcieport 0000:00:16.3: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 207 usecs
2024-04-26T15:41:23.317009Z INFO kernel: [ 2140.695351] pcieport 0000:00:16.2: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.317011Z INFO kernel: [ 2140.695543] pcieport 0000:00:16.2: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 187 usecs
2024-04-26T15:41:23.317014Z INFO kernel: [ 2140.695549] pcieport 0000:00:16.1: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.317016Z INFO kernel: [ 2140.695772] pcieport 0000:00:16.1: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 218 usecs
2024-04-26T15:41:23.360880Z INFO kernel: [ 2140.695780] pcieport 0000:00:16.0: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.373673Z INFO kernel: [ 2140.695974] pcieport 0000:00:16.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 189 usecs
2024-04-26T15:41:23.374219Z INFO kernel: [ 2140.695980] pcieport 0000:00:15.7: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.374225Z INFO kernel: [ 2140.696170] pcieport 0000:00:15.7: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 185 usecs
2024-04-26T15:41:23.374227Z INFO kernel: [ 2140.696177] pcieport 0000:00:15.6: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.374229Z INFO kernel: [ 2140.696390] pcieport 0000:00:15.6: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 208 usecs
2024-04-26T15:41:23.374231Z INFO kernel: [ 2140.696397] pcieport 0000:00:15.5: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.374233Z INFO kernel: [ 2140.696589] pcieport 0000:00:15.5: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 187 usecs
2024-04-26T15:41:23.374235Z INFO kernel: [ 2140.696596] pcieport 0000:00:15.4: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.374237Z INFO kernel: [ 2140.696787] pcieport 0000:00:15.4: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 186 usecs
2024-04-26T15:41:23.374239Z INFO kernel: [ 2140.696794] pcieport 0000:00:15.3: PM:
calling pci_pm_suspend+0x0/0x1da @ 22023, parent: pci0000:00
2024-04-26T15:41:23.374240Z INFO kernel: [ 2140.696985] pcieport 0000:00:15.3: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 186 usecs
2024-04-26T15:41:23.374242Z INFO kernel: [ 2140.697264] pcieport 0000:00:18.4: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 181 usecs
2024-04-26T15:41:23.374244Z INFO kernel: [ 2140.697272] pcieport 0000:00:15.2: PM:
calling pci_pm_suspend+0x0/0x1da @ 14477, parent: pci0000:00
2024-04-26T15:41:23.374246Z INFO kernel: [ 2140.697329] pcieport 0000:00:15.1: PM:
calling pci_pm_suspend+0x0/0x1da @ 22024, parent: pci0000:00
2024-04-26T15:41:23.374248Z INFO kernel: [ 2140.698385] pcieport 0000:00:15.2: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 1109 usecs
2024-04-26T15:41:23.374250Z INFO kernel: [ 2140.698439] pcieport 0000:00:15.1: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 1102 usecs
2024-04-26T15:41:23.374251Z INFO kernel: [ 2140.698526] pci 0000:00:10.0: PM: calling
pci_pm_suspend+0x0/0x1da @ 24071, parent: pci0000:00
2024-04-26T15:41:23.374253Z INFO kernel: [ 2140.698531] pci 0000:00:10.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 0 usecs
2024-04-26T15:41:23.375597Z INFO kernel: [ 2140.698538] vmwgfx 0000:00:0f.0: PM: calling
pci_pm_suspend+0x0/0x1da @ 24071, parent: pci0000:00
2024-04-26T15:41:23.375614Z INFO kernel: [ 2140.700063] vmwgfx 0000:00:0f.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 1518 usecs
2024-04-26T15:41:23.375618Z INFO kernel: [ 2140.700077] vmw_vmci 0000:00:07.7: PM:
calling pci_pm_suspend+0x0/0x1da @ 24071, parent: pci0000:00
2024-04-26T15:41:23.375622Z INFO kernel: [ 2140.700427] pci 0000:00:07.3: PM: calling
pci_pm_suspend+0x0/0x1da @ 22022, parent: pci0000:00
2024-04-26T15:41:23.375625Z INFO kernel: [ 2140.702470] vmw_vmci 0000:00:07.7: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 2361 usecs
```



```
2024-04-26T15:41:23.375629Z INFO kernel: [ 2140.702489] ata_piix 0000:00:07.1: PM:
calling pci_pm_suspend+0x0/0x1da @ 24071, parent: pci0000:00
2024-04-26T15:41:23.375632Z INFO kernel: [ 2140.703802] snd_hda_intel 0000:02:02.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 16922 usecs
2024-04-26T15:41:23.375636Z INFO kernel: [ 2140.704320] ata_piix 0000:00:07.1: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 1825 usecs
2024-04-26T15:41:23.375639Z INFO kernel: [ 2140.704336] pci 0000:00:07.0: PM: calling
pci_pm_suspend+0x0/0x1da @ 24071, parent: pci0000:00
2024-04-26T15:41:23.375643Z INFO kernel: [ 2140.704340] pci 0000:00:07.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 0 usecs
2024-04-26T15:41:23.375647Z INFO kernel: [ 2140.704347] pci 0000:00:01.0: PM: calling
pci_pm_suspend+0x0/0x1da @ 24071, parent: pci0000:00
2024-04-26T15:41:23.375650Z INFO kernel: [ 2140.704350] pci 0000:00:01.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 0 usecs
2024-04-26T15:41:23.375654Z INFO kernel: [ 2140.704355] pci 0000:00:00.0: PM: calling
pci_pm_suspend+0x0/0x1da @ 24071, parent: pci0000:00
2024-04-26T15:41:23.375657Z INFO kernel: [ 2140.704387] pci 0000:00:00.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 0 usecs
2024-04-26T15:41:23.375661Z INFO kernel: [ 2140.705109] pci 0000:00:07.3: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 0 usecs
2024-04-26T15:41:23.375664Z INFO kernel: [ 2140.733333] e1000 0000:02:01.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 51061 usecs
2024-04-26T15:41:23.375668Z INFO kernel: [ 2140.743085] nvme 0000:03:00.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 69728 usecs
2024-04-26T15:41:23.375672Z INFO kernel: [ 2140.750762] pci 0000:00:11.0: PM: calling
pci_pm_suspend+0x0/0x1da @ 22024, parent: pci0000:00
2024-04-26T15:41:23.375674Z INFO kernel: [ 2140.758292] pcieport 0000:00:15.0: PM:
calling pci_pm_suspend+0x0/0x1da @ 14477, parent: pci0000:00
2024-04-26T15:41:23.375677Z INFO kernel: [ 2140.759896] pci 0000:00:11.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 0 usecs
2024-04-26T15:41:23.375681Z INFO kernel: [ 2140.761889] pcieport 0000:00:15.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 279 usecs
2024-04-26T15:41:23.375683Z DEBUG kernel: [ 2140.864095] PM: suspend of devices complete
after 390.620 msecs
2024-04-26T15:41:23.375742Z DEBUG kernel: [ 2140.864104] PM: start suspend of devices
complete after 406.596 msecs
2024-04-26T15:41:23.375749Z INFO kernel: [ 2140.864617] nvme 0000:03:00.0: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 14477, parent: 0000:00:15.0
2024-04-26T15:41:23.375754Z INFO kernel: [ 2140.864618] ehci-pci 0000:02:03.0: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 24071, parent: 0000:00:11.0
2024-04-26T15:41:23.375758Z INFO kernel: [ 2140.864629] ehci-pci 0000:02:03.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 1 usecs
2024-04-26T15:41:23.375761Z INFO kernel: [ 2140.867063] nvme 0000:03:00.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 1 usecs
2024-04-26T15:41:23.375765Z INFO kernel: [ 2140.868344] snd_hda_intel 0000:02:02.0: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: 0000:00:11.0
2024-04-26T15:41:23.375768Z INFO kernel: [ 2140.868354] snd_hda_intel 0000:02:02.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.375772Z INFO kernel: [ 2140.868399] e1000 0000:02:01.0: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 22024, parent: 0000:00:11.0
2024-04-26T15:41:23.375779Z INFO kernel: [ 2140.868404] e1000 0000:02:01.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.375782Z INFO kernel: [ 2140.868410] uhci_hcd 0000:02:00.0: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: 0000:00:11.0
2024-04-26T15:41:23.375786Z INFO kernel: [ 2140.868415] uhci_hcd 0000:02:00.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.375939Z INFO kernel: [ 2140.868420] pcieport 0000:00:18.7: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.375947Z INFO kernel: [ 2140.868424] pcieport 0000:00:18.7: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.375951Z INFO kernel: [ 2140.868430] pcieport 0000:00:18.6: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.375954Z INFO kernel: [ 2140.868433] pcieport 0000:00:18.6: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.375958Z INFO kernel: [ 2140.868438] pcieport 0000:00:18.5: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.375961Z INFO kernel: [ 2140.868442] pcieport 0000:00:18.5: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.376084Z INFO kernel: [ 2140.868446] pcieport 0000:00:18.4: PM:
```

```
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.376097Z INFO kernel: [ 2140.868450] pcieport 0000:00:18.4: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.376101Z INFO kernel: [ 2140.868455] pcieport 0000:00:18.3: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.376105Z INFO kernel: [ 2140.868458] pcieport 0000:00:18.3: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.376108Z INFO kernel: [ 2140.868463] pcieport 0000:00:18.2: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.376110Z INFO kernel: [ 2140.868466] pcieport 0000:00:18.2: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.376169Z INFO kernel: [ 2140.868471] pcieport 0000:00:18.1: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.376176Z INFO kernel: [ 2140.868474] pcieport 0000:00:18.1: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.376180Z INFO kernel: [ 2140.868479] pcieport 0000:00:18.0: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.376183Z INFO kernel: [ 2140.868483] pcieport 0000:00:18.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.376187Z INFO kernel: [ 2140.868488] pcieport 0000:00:17.7: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.376190Z INFO kernel: [ 2140.868491] pcieport 0000:00:17.7: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.376193Z INFO kernel: [ 2140.868496] pcieport 0000:00:17.6: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.376196Z INFO kernel: [ 2140.868500] pcieport 0000:00:17.6: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.376198Z INFO kernel: [ 2140.868504] pcieport 0000:00:17.5: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.389401Z INFO kernel: [ 2140.868507] pcieport 0000:00:17.5: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.389634Z INFO kernel: [ 2140.868577] pcieport 0000:00:17.4: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.389641Z INFO kernel: [ 2140.868580] pcieport 0000:00:17.4: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.389644Z INFO kernel: [ 2140.868591] pcieport 0000:00:17.3: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.389648Z INFO kernel: [ 2140.868595] pcieport 0000:00:17.3: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.389651Z INFO kernel: [ 2140.868599] pcieport 0000:00:17.2: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.389711Z INFO kernel: [ 2140.868602] pcieport 0000:00:17.2: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.389717Z INFO kernel: [ 2140.868607] pcieport 0000:00:17.1: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.389721Z INFO kernel: [ 2140.868610] pcieport 0000:00:17.1: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.389725Z INFO kernel: [ 2140.868615] pcieport 0000:00:17.0: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.389728Z INFO kernel: [ 2140.868618] pcieport 0000:00:17.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.389731Z INFO kernel: [ 2140.868623] pcieport 0000:00:16.7: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390021Z INFO kernel: [ 2140.868626] pcieport 0000:00:16.7: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390030Z INFO kernel: [ 2140.868659] pcieport 0000:00:16.6: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390034Z INFO kernel: [ 2140.868663] pcieport 0000:00:16.6: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390037Z INFO kernel: [ 2140.868667] pcieport 0000:00:16.5: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390041Z INFO kernel: [ 2140.868671] pcieport 0000:00:16.5: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390096Z INFO kernel: [ 2140.868676] pcieport 0000:00:16.4: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390101Z INFO kernel: [ 2140.868679] pcieport 0000:00:16.4: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390104Z INFO kernel: [ 2140.868684] pcieport 0000:00:16.3: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
```

2024-04-26T15:41:23.390111Z INFO kernel: [2140.868687] pcieport 0000:00:16.3: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390115Z INFO kernel: [2140.868692] pcieport 0000:00:16.2: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390209Z INFO kernel: [2140.868695] pcieport 0000:00:16.2: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390216Z INFO kernel: [2140.868700] pcieport 0000:00:16.1: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390272Z INFO kernel: [2140.868703] pcieport 0000:00:16.1: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390637Z INFO kernel: [2140.868708] pcieport 0000:00:16.0: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390645Z INFO kernel: [2140.868712] pcieport 0000:00:16.0: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390649Z INFO kernel: [2140.868717] pcieport 0000:00:15.7: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390652Z INFO kernel: [2140.868720] pcieport 0000:00:15.7: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390655Z INFO kernel: [2140.868725] pcieport 0000:00:15.6: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390706Z INFO kernel: [2140.868728] pcieport 0000:00:15.6: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390713Z INFO kernel: [2140.868733] pcieport 0000:00:15.5: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390717Z INFO kernel: [2140.868736] pcieport 0000:00:15.5: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390720Z INFO kernel: [2140.868741] pcieport 0000:00:15.4: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390723Z INFO kernel: [2140.868745] pcieport 0000:00:15.4: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390726Z INFO kernel: [2140.868750] pcieport 0000:00:15.3: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390779Z INFO kernel: [2140.868753] pcieport 0000:00:15.3: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390787Z INFO kernel: [2140.868758] pcieport 0000:00:15.2: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390790Z INFO kernel: [2140.868761] pcieport 0000:00:15.2: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390792Z INFO kernel: [2140.868765] pcieport 0000:00:15.1: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390794Z INFO kernel: [2140.868768] pcieport 0000:00:15.1: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390796Z INFO kernel: [2140.869755] pci 0000:00:11.0: PM: calling pci_pm_suspend_late+0x0/0x3a @ 24071, parent: pci0000:00
2024-04-26T15:41:23.390797Z INFO kernel: [2140.871772] pci 0000:00:10.0: PM: calling pci_pm_suspend_late+0x0/0x3a @ 14477, parent: pci0000:00
2024-04-26T15:41:23.390799Z INFO kernel: [2140.871862] pcieport 0000:00:15.0: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390801Z INFO kernel: [2140.871869] pcieport 0000:00:15.0: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390802Z INFO kernel: [2140.871913] vmwgfx 0000:00:0f.0: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390805Z INFO kernel: [2140.871919] vmwgfx 0000:00:0f.0: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.390807Z INFO kernel: [2140.871924] vmw_vmci 0000:00:07.7: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.390808Z INFO kernel: [2140.871928] vmw_vmci 0000:00:07.7: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.391134Z INFO kernel: [2140.871933] pci 0000:00:07.3: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.391145Z INFO kernel: [2140.871999] pci 0000:00:07.3: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.391149Z INFO kernel: [2140.872005] ata_piix 0000:00:07.1: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.391151Z INFO kernel: [2140.872009] ata_piix 0000:00:07.1: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.391153Z INFO kernel: [2140.872014] pci 0000:00:07.0: PM: calling pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.391155Z INFO kernel: [2140.872017] pci 0000:00:07.0: PM:

```
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.391209Z INFO kernel: [ 2140.872022] pci 0000:00:01.0: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.391219Z INFO kernel: [ 2140.872025] pci 0000:00:01.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.391224Z INFO kernel: [ 2140.872030] pci 0000:00:00.0: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 22024, parent: pci0000:00
2024-04-26T15:41:23.391228Z INFO kernel: [ 2140.872033] pci 0000:00:00.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T15:41:23.391231Z INFO kernel: [ 2140.874193] pci 0000:00:11.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 1 usecs
2024-04-26T15:41:23.391238Z INFO kernel: [ 2140.876478] pci 0000:00:10.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 1 usecs
2024-04-26T15:41:23.391339Z DEBUG kernel: [ 2141.032654] PM: late suspend of devices
complete after 168.543 msecs
2024-04-26T15:41:23.391347Z INFO kernel: [ 2141.040922] nvme 0000:03:00.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 22024, parent: 0000:00:15.0
2024-04-26T15:41:23.391351Z INFO kernel: [ 2141.040922] ehci-pci 0000:02:03.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 14477, parent: 0000:00:11.0
2024-04-26T15:41:23.391355Z INFO kernel: [ 2141.041177] e1000 0000:02:01.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 15801, parent: 0000:00:11.0
2024-04-26T15:41:23.391358Z INFO kernel: [ 2141.041492] ehci-pci 0000:02:03.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 556 usecs
2024-04-26T15:41:23.391406Z INFO kernel: [ 2141.041543] uhci_hcd 0000:02:00.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 14477, parent: 0000:00:11.0
2024-04-26T15:41:23.391413Z INFO kernel: [ 2141.041897] uhci_hcd 0000:02:00.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 348 usecs
2024-04-26T15:41:23.391417Z INFO kernel: [ 2141.041940] pcieport 0000:00:18.7: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 14477, parent: pci0000:00
2024-04-26T15:41:23.391420Z INFO kernel: [ 2141.043573] pcieport 0000:00:18.7: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1625 usecs
2024-04-26T15:41:23.391457Z INFO kernel: [ 2141.043630] pcieport 0000:00:18.6: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 14477, parent: pci0000:00
2024-04-26T15:41:23.391465Z INFO kernel: [ 2141.043680] pcieport 0000:00:18.5: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 137, parent: pci0000:00
2024-04-26T15:41:23.391471Z INFO kernel: [ 2141.043722] pcieport 0000:00:18.4: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.391473Z INFO kernel: [ 2141.044442] pcieport 0000:00:18.4: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 713 usecs
2024-04-26T15:41:23.391476Z INFO kernel: [ 2141.044487] pcieport 0000:00:18.3: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.391478Z INFO kernel: [ 2141.045134] pcieport 0000:00:18.3: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 642 usecs
2024-04-26T15:41:23.391481Z INFO kernel: [ 2141.045175] pcieport 0000:00:18.2: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.391484Z INFO kernel: [ 2141.045836] pcieport 0000:00:18.2: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 655 usecs
2024-04-26T15:41:23.391486Z INFO kernel: [ 2141.045877] pcieport 0000:00:18.1: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.391542Z INFO kernel: [ 2141.046538] pcieport 0000:00:18.1: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 656 usecs
2024-04-26T15:41:23.391546Z INFO kernel: [ 2141.046580] pcieport 0000:00:18.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.391548Z INFO kernel: [ 2141.047534] snd_hda_intel 0000:02:02.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 24071, parent: 0000:00:11.0
2024-04-26T15:41:23.391550Z INFO kernel: [ 2141.047606] pcieport 0000:00:18.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1021 usecs
2024-04-26T15:41:23.391552Z INFO kernel: [ 2141.047643] pcieport 0000:00:17.7: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.391554Z INFO kernel: [ 2141.048313] pcieport 0000:00:17.7: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 636 usecs
2024-04-26T15:41:23.391592Z INFO kernel: [ 2141.048350] pcieport 0000:00:17.6: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.391595Z INFO kernel: [ 2141.048866] pcieport 0000:00:17.5: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 11035, parent: pci0000:00
2024-04-26T15:41:23.391598Z INFO kernel: [ 2141.048915] pcieport 0000:00:17.6: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 560 usecs
2024-04-26T15:41:23.391600Z INFO kernel: [ 2141.048960] pcieport 0000:00:17.4: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
```

```
2024-04-26T15:41:23.391602Z INFO kernel: [ 2141.049637] pcieport 0000:00:17.4: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 671 usecs
2024-04-26T15:41:23.391604Z INFO kernel: [ 2141.049681] pcieport 0000:00:17.3: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.392079Z INFO kernel: [ 2141.050363] pcieport 0000:00:17.3: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 677 usecs
2024-04-26T15:41:23.392091Z INFO kernel: [ 2141.050409] pcieport 0000:00:17.2: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.392094Z INFO kernel: [ 2141.050910] pcieport 0000:00:17.2: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 495 usecs
2024-04-26T15:41:23.392097Z INFO kernel: [ 2141.050945] pcieport 0000:00:17.1: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.392099Z INFO kernel: [ 2141.051461] pcieport 0000:00:17.1: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 512 usecs
2024-04-26T15:41:23.392102Z INFO kernel: [ 2141.051494] pcieport 0000:00:17.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.428673Z INFO kernel: [ 2141.051586] pcieport 0000:00:16.7: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.428701Z INFO kernel: [ 2141.051953] pcieport 0000:00:17.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 455 usecs
2024-04-26T15:41:23.428706Z INFO kernel: [ 2141.051986] pcieport 0000:00:16.6: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.428709Z INFO kernel: [ 2141.052524] pcieport 0000:00:16.6: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 531 usecs
2024-04-26T15:41:23.429537Z INFO kernel: [ 2141.052557] pcieport 0000:00:16.5: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.429608Z INFO kernel: [ 2141.053016] pcieport 0000:00:16.5: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 453 usecs
2024-04-26T15:41:23.429617Z INFO kernel: [ 2141.053049] pcieport 0000:00:16.4: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.429619Z INFO kernel: [ 2141.053614] pcieport 0000:00:18.6: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 9977 usecs
2024-04-26T15:41:23.429621Z INFO kernel: [ 2141.053647] pcieport 0000:00:16.3: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 14477, parent: pci0000:00
2024-04-26T15:41:23.429623Z INFO kernel: [ 2141.054293] pcieport 0000:00:16.3: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 581 usecs
2024-04-26T15:41:23.429625Z INFO kernel: [ 2141.055042] pcieport 0000:00:17.5: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1117 usecs
2024-04-26T15:41:23.429627Z INFO kernel: [ 2141.055095] pcieport 0000:00:16.2: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 11035, parent: pci0000:00
2024-04-26T15:41:23.429629Z INFO kernel: [ 2141.055896] pcieport 0000:00:18.5: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 658 usecs
2024-04-26T15:41:23.429631Z INFO kernel: [ 2141.055942] pcieport 0000:00:16.1: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 137, parent: pci0000:00
2024-04-26T15:41:23.429677Z INFO kernel: [ 2141.056744] pcieport 0000:00:16.1: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 797 usecs
2024-04-26T15:41:23.429683Z INFO kernel: [ 2141.057489] pcieport 0000:00:16.4: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 4433 usecs
2024-04-26T15:41:23.429687Z INFO kernel: [ 2141.057503] pcieport 0000:00:16.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.429691Z INFO kernel: [ 2141.057866] pcieport 0000:00:16.7: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1275 usecs
2024-04-26T15:41:23.429694Z INFO kernel: [ 2141.057874] pcieport 0000:00:15.7: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.429756Z INFO kernel: [ 2141.058479] pcieport 0000:00:16.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 971 usecs
2024-04-26T15:41:23.429764Z INFO kernel: [ 2141.058487] pcieport 0000:00:15.6: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.429768Z INFO kernel: [ 2141.059993] pcieport 0000:00:15.7: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 2113 usecs
2024-04-26T15:41:23.429770Z INFO kernel: [ 2141.060008] pcieport 0000:00:15.5: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.429773Z INFO kernel: [ 2141.060187] pcieport 0000:00:15.4: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 14477, parent: pci0000:00
2024-04-26T15:41:23.429776Z INFO kernel: [ 2141.060613] pcieport 0000:00:15.6: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 2121 usecs
2024-04-26T15:41:23.429830Z INFO kernel: [ 2141.060622] pcieport 0000:00:15.3: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.429837Z INFO kernel: [ 2141.061157] pcieport 0000:00:15.5: PM:
```

```
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1144 usecs
2024-04-26T15:41:23.429839Z INFO kernel: [ 2141.061165] pcieport 0000:00:15.2: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.429842Z INFO kernel: [ 2141.061518] pcieport 0000:00:15.3: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 890 usecs
2024-04-26T15:41:23.429843Z INFO kernel: [ 2141.061683] pcieport 0000:00:15.1: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22022, parent: pci0000:00
2024-04-26T15:41:23.429845Z INFO kernel: [ 2141.062804] pcieport 0000:00:15.1: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1116 usecs
2024-04-26T15:41:23.429894Z INFO kernel: [ 2141.062831] pcieport 0000:00:15.2: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1137 usecs
2024-04-26T15:41:23.429901Z INFO kernel: [ 2141.062916] e1000 0000:02:01.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 16212 usecs
2024-04-26T15:41:23.429904Z INFO kernel: [ 2141.063549] pcieport 0000:00:16.2: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 8447 usecs
2024-04-26T15:41:23.429907Z INFO kernel: [ 2141.063558] pci 0000:00:10.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 11035, parent: pci0000:00
2024-04-26T15:41:23.429909Z INFO kernel: [ 2141.064109] vmwgfx 0000:00:0f.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 24072, parent: pci0000:00
2024-04-26T15:41:23.429917Z INFO kernel: [ 2141.064114] vmwgfx 0000:00:0f.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 0 usecs
2024-04-26T15:41:23.429974Z INFO kernel: [ 2141.064118] vmw_vmci 0000:00:07.7: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 24072, parent: pci0000:00
2024-04-26T15:41:23.429982Z INFO kernel: [ 2141.064553] pci 0000:00:10.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 989 usecs
2024-04-26T15:41:23.429984Z INFO kernel: [ 2141.064562] pci 0000:00:07.3: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 11035, parent: pci0000:00
2024-04-26T15:41:23.429986Z INFO kernel: [ 2141.064704] vmw_vmci 0000:00:07.7: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 583 usecs
2024-04-26T15:41:23.429988Z INFO kernel: [ 2141.064710] ata_piix 0000:00:07.1: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 24072, parent: pci0000:00
2024-04-26T15:41:23.429990Z INFO kernel: [ 2141.064713] ata_piix 0000:00:07.1: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 0 usecs
2024-04-26T15:41:23.430036Z INFO kernel: [ 2141.064717] pci 0000:00:07.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 24072, parent: pci0000:00
2024-04-26T15:41:23.430043Z INFO kernel: [ 2141.068269] pci 0000:00:07.3: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 3700 usecs
2024-04-26T15:41:23.430047Z INFO kernel: [ 2141.068401] pci 0000:00:07.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 3679 usecs
2024-04-26T15:41:23.430050Z INFO kernel: [ 2141.068413] pci 0000:00:01.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 24072, parent: pci0000:00
2024-04-26T15:41:23.430054Z INFO kernel: [ 2141.068931] pci 0000:00:01.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 514 usecs
2024-04-26T15:41:23.430057Z INFO kernel: [ 2141.068935] pci 0000:00:00.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 24072, parent: pci0000:00
2024-04-26T15:41:23.430104Z INFO kernel: [ 2141.069371] pcieport 0000:00:15.4: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 4408 usecs
2024-04-26T15:41:23.430111Z INFO kernel: [ 2141.069463] pci 0000:00:00.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 524 usecs
2024-04-26T15:41:23.430114Z INFO kernel: [ 2141.074286] snd_hda_intel 0000:02:02.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 11360 usecs
2024-04-26T15:41:23.430118Z INFO kernel: [ 2141.091717] nvme 0000:03:00.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 22176 usecs
2024-04-26T15:41:23.430121Z INFO kernel: [ 2141.093406] pci 0000:00:11.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 15801, parent: pci0000:00
2024-04-26T15:41:23.430125Z INFO kernel: [ 2141.100157] pcieport 0000:00:15.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.430128Z INFO kernel: [ 2141.102311] pci 0000:00:11.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 409 usecs
2024-04-26T15:41:23.430132Z INFO kernel: [ 2141.104247] pcieport 0000:00:15.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 459 usecs
2024-04-26T15:41:23.430135Z DEBUG kernel: [ 2141.215477] PM: noirq suspend of devices
complete after 175.576 msecs
2024-04-26T15:41:23.430141Z DEBUG kernel: [ 2141.215555] PM: suspend-to-idle
2024-04-26T15:41:23.430147Z ERR kernel: [ 2165.310707] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.430202Z WARNING kernel: [ 2165.312322] hwrng: no data available
2024-04-26T15:41:23.430207Z ERR kernel: [ 2177.597457] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.430209Z WARNING kernel: [ 2177.598450] hwrng: no data available
2024-04-26T15:41:23.430211Z ERR kernel: [ 2189.886061] tpm tpm0: Operation Timed out
```

```
2024-04-26T15:41:23.430213Z WARNING kernel: [ 2189.887188] hwrng: no data available
2024-04-26T15:41:23.430215Z ERR kernel: [ 2202.173396] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.430254Z WARNING kernel: [ 2202.174405] hwrng: no data available
2024-04-26T15:41:23.430259Z ERR kernel: [ 2214.461878] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.430261Z WARNING kernel: [ 2214.462888] hwrng: no data available
2024-04-26T15:41:23.430262Z ERR kernel: [ 2226.749446] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.430264Z WARNING kernel: [ 2226.750449] hwrng: no data available
2024-04-26T15:41:23.430266Z ERR kernel: [ 2239.037362] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.430307Z WARNING kernel: [ 2239.038469] hwrng: no data available
2024-04-26T15:41:23.430313Z ERR kernel: [ 2251.326129] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.430316Z WARNING kernel: [ 2251.327134] hwrng: no data available
2024-04-26T15:41:23.430319Z ERR kernel: [ 2263.614440] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.430322Z WARNING kernel: [ 2263.615459] hwrng: no data available
2024-04-26T15:41:23.430324Z ERR kernel: [ 2275.902081] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.430327Z WARNING kernel: [ 2275.903130] hwrng: no data available
2024-04-26T15:41:23.430728Z ERR kernel: [ 2288.189387] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.430737Z WARNING kernel: [ 2288.190429] hwrng: no data available
2024-04-26T15:41:23.430741Z ERR kernel: [ 2300.477259] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.456877Z WARNING kernel: [ 2300.478347] hwrng: no data available
2024-04-26T15:41:23.456887Z ERR kernel: [ 2312.765696] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.456891Z WARNING kernel: [ 2312.766782] hwrng: no data available
2024-04-26T15:41:23.456894Z ERR kernel: [ 2325.053655] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.456900Z WARNING kernel: [ 2325.060099] hwrng: no data available
2024-04-26T15:41:23.456906Z ERR kernel: [ 2337.341666] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.456934Z WARNING kernel: [ 2337.342753] hwrng: no data available
2024-04-26T15:41:23.456938Z ERR kernel: [ 2349.629545] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.456942Z WARNING kernel: [ 2349.630635] hwrng: no data available
2024-04-26T15:41:23.456944Z ERR kernel: [ 2361.933279] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.456946Z WARNING kernel: [ 2361.934687] hwrng: no data available
2024-04-26T15:41:23.456948Z ERR kernel: [ 2374.205222] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.456949Z WARNING kernel: [ 2374.206364] hwrng: no data available
2024-04-26T15:41:23.456953Z ERR kernel: [ 2386.494018] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.456956Z WARNING kernel: [ 2386.495137] hwrng: no data available
2024-04-26T15:41:23.456959Z ERR kernel: [ 2398.781504] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.456962Z WARNING kernel: [ 2398.782614] hwrng: no data available
2024-04-26T15:41:23.456964Z ERR kernel: [ 2411.071116] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.456965Z WARNING kernel: [ 2411.072282] hwrng: no data available
2024-04-26T15:41:23.456967Z ERR kernel: [ 2423.357897] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.456969Z WARNING kernel: [ 2423.363658] hwrng: no data available
2024-04-26T15:41:23.456971Z ERR kernel: [ 2435.645826] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.456972Z WARNING kernel: [ 2435.647054] hwrng: no data available
2024-04-26T15:41:23.456974Z ERR kernel: [ 2447.942426] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.456975Z WARNING kernel: [ 2447.943780] hwrng: no data available
2024-04-26T15:41:23.456977Z ERR kernel: [ 2460.221722] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.456979Z WARNING kernel: [ 2460.222962] hwrng: no data available
2024-04-26T15:41:23.456980Z ERR kernel: [ 2472.510032] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.456982Z WARNING kernel: [ 2472.513963] hwrng: no data available
2024-04-26T15:41:23.457213Z ERR kernel: [ 2484.798125] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457216Z WARNING kernel: [ 2484.799242] hwrng: no data available
2024-04-26T15:41:23.457218Z ERR kernel: [ 2497.085363] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457220Z WARNING kernel: [ 2497.086493] hwrng: no data available
2024-04-26T15:41:23.457222Z ERR kernel: [ 2509.374023] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457224Z WARNING kernel: [ 2509.375112] hwrng: no data available
2024-04-26T15:41:23.457226Z ERR kernel: [ 2521.661598] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457228Z WARNING kernel: [ 2521.662716] hwrng: no data available
2024-04-26T15:41:23.457230Z ERR kernel: [ 2533.949560] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457233Z WARNING kernel: [ 2533.950699] hwrng: no data available
2024-04-26T15:41:23.457235Z ERR kernel: [ 2546.237398] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457237Z WARNING kernel: [ 2546.238762] hwrng: no data available
2024-04-26T15:41:23.457239Z ERR kernel: [ 2558.690075] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457241Z WARNING kernel: [ 2558.693389] hwrng: no data available
2024-04-26T15:41:23.457243Z ERR kernel: [ 2570.822152] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457245Z WARNING kernel: [ 2570.823643] hwrng: no data available
2024-04-26T15:41:23.457247Z ERR kernel: [ 2583.175761] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457250Z WARNING kernel: [ 2583.178857] hwrng: no data available
2024-04-26T15:41:23.457252Z ERR kernel: [ 2595.389344] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457257Z WARNING kernel: [ 2595.390662] hwrng: no data available
2024-04-26T15:41:23.457259Z ERR kernel: [ 2607.677886] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457261Z WARNING kernel: [ 2607.683960] hwrng: no data available
```

2024-04-26T15:41:23.457263Z ERR kernel: [2619.966962] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457265Z WARNING kernel: [2619.968600] hwrng: no data available
2024-04-26T15:41:23.457268Z ERR kernel: [2632.272449] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457270Z WARNING kernel: [2632.274109] hwrng: no data available
2024-04-26T15:41:23.457272Z ERR kernel: [2644.551873] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457274Z WARNING kernel: [2644.554062] hwrng: no data available
2024-04-26T15:41:23.457276Z ERR kernel: [2656.915417] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457279Z WARNING kernel: [2656.918162] hwrng: no data available
2024-04-26T15:41:23.457281Z ERR kernel: [2669.118128] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457283Z WARNING kernel: [2669.120586] hwrng: no data available
2024-04-26T15:41:23.457285Z ERR kernel: [2681.410570] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457287Z WARNING kernel: [2681.411999] hwrng: no data available
2024-04-26T15:41:23.457289Z ERR kernel: [2693.716866] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457292Z WARNING kernel: [2693.728854] hwrng: no data available
2024-04-26T15:41:23.457365Z ERR kernel: [2706.043157] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457371Z WARNING kernel: [2706.047788] hwrng: no data available
2024-04-26T15:41:23.457373Z ERR kernel: [2718.830062] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457375Z WARNING kernel: [2718.831490] hwrng: no data available
2024-04-26T15:41:23.457377Z ERR kernel: [2731.107177] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457379Z WARNING kernel: [2731.108714] hwrng: no data available
2024-04-26T15:41:23.457381Z ERR kernel: [2743.357872] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457383Z WARNING kernel: [2743.359149] hwrng: no data available
2024-04-26T15:41:23.457385Z ERR kernel: [2755.675948] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457387Z WARNING kernel: [2755.680350] hwrng: no data available
2024-04-26T15:41:23.457393Z ERR kernel: [2767.938240] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457396Z WARNING kernel: [2767.939646] hwrng: no data available
2024-04-26T15:41:23.457398Z ERR kernel: [2780.567425] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457400Z WARNING kernel: [2780.574898] hwrng: no data available
2024-04-26T15:41:23.457402Z ERR kernel: [2793.033728] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457404Z WARNING kernel: [2793.035598] hwrng: no data available
2024-04-26T15:41:23.457484Z ERR kernel: [2805.417165] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457489Z WARNING kernel: [2805.419176] hwrng: no data available
2024-04-26T15:41:23.457495Z ERR kernel: [2817.632455] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457497Z WARNING kernel: [2817.634073] hwrng: no data available
2024-04-26T15:41:23.457499Z ERR kernel: [2829.886206] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457501Z WARNING kernel: [2829.891238] hwrng: no data available
2024-04-26T15:41:23.457503Z ERR kernel: [2842.173982] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457689Z WARNING kernel: [2842.175323] hwrng: no data available
2024-04-26T15:41:23.457695Z ERR kernel: [2854.462175] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457697Z WARNING kernel: [2854.463347] hwrng: no data available
2024-04-26T15:41:23.457699Z ERR kernel: [2866.750396] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.457701Z WARNING kernel: [2866.751627] hwrng: no data available
2024-04-26T15:41:23.457703Z ERR kernel: [2879.040155] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.467677Z WARNING kernel: [2879.042190] hwrng: no data available
2024-04-26T15:41:23.467698Z ERR kernel: [2891.326503] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.467702Z WARNING kernel: [2891.327666] hwrng: no data available
2024-04-26T15:41:23.467704Z ERR kernel: [2903.625053] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.467706Z WARNING kernel: [2903.626606] hwrng: no data available
2024-04-26T15:41:23.467708Z ERR kernel: [2915.901517] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.467767Z WARNING kernel: [2915.902781] hwrng: no data available
2024-04-26T15:41:23.467772Z ERR kernel: [2928.190040] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.467774Z WARNING kernel: [2928.191687] hwrng: no data available
2024-04-26T15:41:23.467776Z ERR kernel: [2940.477444] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.467778Z WARNING kernel: [2940.478620] hwrng: no data available
2024-04-26T15:41:23.467780Z ERR kernel: [2952.765911] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.467782Z WARNING kernel: [2952.772480] hwrng: no data available
2024-04-26T15:41:23.467872Z ERR kernel: [2965.053627] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.467878Z WARNING kernel: [2965.055370] hwrng: no data available
2024-04-26T15:41:23.467880Z ERR kernel: [2977.341641] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.467882Z WARNING kernel: [2977.343013] hwrng: no data available
2024-04-26T15:41:23.467884Z ERR kernel: [2989.640036] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.467885Z WARNING kernel: [2989.642023] hwrng: no data available
2024-04-26T15:41:23.467924Z ERR kernel: [3001.917182] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.467928Z WARNING kernel: [3001.921929] hwrng: no data available
2024-04-26T15:41:23.467930Z ERR kernel: [3014.205788] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.467932Z WARNING kernel: [3014.206989] hwrng: no data available
2024-04-26T15:41:23.467935Z ERR kernel: [3026.493387] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.467937Z WARNING kernel: [3026.494576] hwrng: no data available
2024-04-26T15:41:23.467940Z ERR kernel: [3038.794202] tpm tpm0: Operation Timed out

2024-04-26T15:41:23.467991Z WARNING kernel: [3038.802373] hwrng: no data available
2024-04-26T15:41:23.467992Z ERR kernel: [3051.069401] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468003Z WARNING kernel: [3051.070852] hwrng: no data available
2024-04-26T15:41:23.468006Z ERR kernel: [3063.382632] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468009Z WARNING kernel: [3063.383942] hwrng: no data available
2024-04-26T15:41:23.468013Z ERR kernel: [3075.672182] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468068Z WARNING kernel: [3075.673374] hwrng: no data available
2024-04-26T15:41:23.468076Z ERR kernel: [3087.933323] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468079Z WARNING kernel: [3087.934498] hwrng: no data available
2024-04-26T15:41:23.468082Z ERR kernel: [3100.221673] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468086Z WARNING kernel: [3100.222844] hwrng: no data available
2024-04-26T15:41:23.468088Z ERR kernel: [3112.510617] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468131Z WARNING kernel: [3112.511789] hwrng: no data available
2024-04-26T15:41:23.468137Z ERR kernel: [3124.797464] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468141Z WARNING kernel: [3124.798801] hwrng: no data available
2024-04-26T15:41:23.468144Z ERR kernel: [3137.085766] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468148Z WARNING kernel: [3137.087371] hwrng: no data available
2024-04-26T15:41:23.468151Z ERR kernel: [3149.373728] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468154Z WARNING kernel: [3149.375262] hwrng: no data available
2024-04-26T15:41:23.468203Z ERR kernel: [3161.662002] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468209Z WARNING kernel: [3161.663154] hwrng: no data available
2024-04-26T15:41:23.468213Z ERR kernel: [3173.951298] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468216Z WARNING kernel: [3173.952427] hwrng: no data available
2024-04-26T15:41:23.468220Z ERR kernel: [3186.237558] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468222Z WARNING kernel: [3186.238746] hwrng: no data available
2024-04-26T15:41:23.468270Z ERR kernel: [3198.526137] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468277Z WARNING kernel: [3198.527243] hwrng: no data available
2024-04-26T15:41:23.468280Z ERR kernel: [3210.813431] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468283Z WARNING kernel: [3210.814553] hwrng: no data available
2024-04-26T15:41:23.468287Z ERR kernel: [3223.101396] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468289Z WARNING kernel: [3223.102589] hwrng: no data available
2024-04-26T15:41:23.468290Z ERR kernel: [3235.389339] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468754Z WARNING kernel: [3235.390792] hwrng: no data available
2024-04-26T15:41:23.468766Z ERR kernel: [3247.678094] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468769Z WARNING kernel: [3247.679204] hwrng: no data available
2024-04-26T15:41:23.468771Z ERR kernel: [3259.965718] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468773Z WARNING kernel: [3259.966843] hwrng: no data available
2024-04-26T15:41:23.468775Z ERR kernel: [3272.261873] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468833Z WARNING kernel: [3272.263094] hwrng: no data available
2024-04-26T15:41:23.468837Z ERR kernel: [3284.541597] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468839Z WARNING kernel: [3284.547321] hwrng: no data available
2024-04-26T15:41:23.468841Z ERR kernel: [3296.829353] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468843Z WARNING kernel: [3296.831171] hwrng: no data available
2024-04-26T15:41:23.468845Z ERR kernel: [3309.117293] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468883Z WARNING kernel: [3309.118608] hwrng: no data available
2024-04-26T15:41:23.468887Z ERR kernel: [3321.405707] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468889Z WARNING kernel: [3321.406880] hwrng: no data available
2024-04-26T15:41:23.468890Z ERR kernel: [3333.694465] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468892Z WARNING kernel: [3333.695685] hwrng: no data available
2024-04-26T15:41:23.468894Z ERR kernel: [3345.981326] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468896Z WARNING kernel: [3345.982492] hwrng: no data available
2024-04-26T15:41:23.468897Z ERR kernel: [3358.288125] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468899Z WARNING kernel: [3358.289247] hwrng: no data available
2024-04-26T15:41:23.468900Z ERR kernel: [3370.557725] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468902Z WARNING kernel: [3370.558813] hwrng: no data available
2024-04-26T15:41:23.468904Z ERR kernel: [3382.846262] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468907Z WARNING kernel: [3382.847446] hwrng: no data available
2024-04-26T15:41:23.468909Z ERR kernel: [3395.148600] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468911Z WARNING kernel: [3395.150279] hwrng: no data available
2024-04-26T15:41:23.468913Z ERR kernel: [3407.421456] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468951Z WARNING kernel: [3407.422852] hwrng: no data available
2024-04-26T15:41:23.468955Z ERR kernel: [3419.710007] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468957Z WARNING kernel: [3419.711342] hwrng: no data available
2024-04-26T15:41:23.468958Z ERR kernel: [3431.997746] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468960Z WARNING kernel: [3431.998829] hwrng: no data available
2024-04-26T15:41:23.468962Z ERR kernel: [3444.285556] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.468964Z WARNING kernel: [3444.287101] hwrng: no data available
2024-04-26T15:41:23.469001Z ERR kernel: [3456.573254] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.469005Z WARNING kernel: [3456.574386] hwrng: no data available

2024-04-26T15:41:23.469006Z ERR kernel: [3468.861187] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.469008Z WARNING kernel: [3468.862526] hwrng: no data available
2024-04-26T15:41:23.469009Z ERR kernel: [3481.149242] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.469011Z WARNING kernel: [3481.150334] hwrng: no data available
2024-04-26T15:41:23.469046Z ERR kernel: [3493.437354] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.469049Z WARNING kernel: [3493.438482] hwrng: no data available
2024-04-26T15:41:23.469051Z ERR kernel: [3505.725888] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.469052Z WARNING kernel: [3505.727007] hwrng: no data available
2024-04-26T15:41:23.469054Z ERR kernel: [3518.013236] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.469055Z WARNING kernel: [3518.014366] hwrng: no data available
2024-04-26T15:41:23.469057Z ERR kernel: [3530.301914] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.469092Z WARNING kernel: [3530.302915] hwrng: no data available
2024-04-26T15:41:23.469095Z ERR kernel: [3542.590019] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.469096Z WARNING kernel: [3542.592279] hwrng: no data available
2024-04-26T15:41:23.469098Z ERR kernel: [3554.877667] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.469100Z WARNING kernel: [3554.878787] hwrng: no data available
2024-04-26T15:41:23.469101Z ERR kernel: [3567.165175] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.490399Z WARNING kernel: [3567.166257] hwrng: no data available
2024-04-26T15:41:23.490447Z ERR kernel: [3579.453315] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.490453Z WARNING kernel: [3579.454396] hwrng: no data available
2024-04-26T15:41:23.490457Z ERR kernel: [3591.741930] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.490461Z WARNING kernel: [3591.743246] hwrng: no data available
2024-04-26T15:41:23.490464Z ERR kernel: [3604.039231] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.490734Z WARNING kernel: [3604.049234] hwrng: no data available
2024-04-26T15:41:23.490745Z ERR kernel: [3616.317555] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.490750Z WARNING kernel: [3616.318671] hwrng: no data available
2024-04-26T15:41:23.490753Z ERR kernel: [3628.606001] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.490755Z WARNING kernel: [3628.607202] hwrng: no data available
2024-04-26T15:41:23.490758Z ERR kernel: [3640.893928] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.490761Z WARNING kernel: [3640.894934] hwrng: no data available
2024-04-26T15:41:23.490901Z ERR kernel: [3653.181809] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.490909Z WARNING kernel: [3653.182891] hwrng: no data available
2024-04-26T15:41:23.490913Z ERR kernel: [3665.469400] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.490917Z WARNING kernel: [3665.470591] hwrng: no data available
2024-04-26T15:41:23.490920Z ERR kernel: [3677.759037] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.490923Z WARNING kernel: [3677.762820] hwrng: no data available
2024-04-26T15:41:23.490983Z ERR kernel: [3690.045348] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.490991Z WARNING kernel: [3690.046471] hwrng: no data available
2024-04-26T15:41:23.490993Z ERR kernel: [3702.333738] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.490995Z WARNING kernel: [3702.334810] hwrng: no data available
2024-04-26T15:41:23.490997Z ERR kernel: [3714.621847] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.490999Z WARNING kernel: [3714.622890] hwrng: no data available
2024-04-26T15:41:23.491001Z ERR kernel: [3726.909558] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491048Z WARNING kernel: [3726.910602] hwrng: no data available
2024-04-26T15:41:23.491059Z ERR kernel: [3739.198025] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491063Z WARNING kernel: [3739.199067] hwrng: no data available
2024-04-26T15:41:23.491066Z ERR kernel: [3751.485718] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491073Z WARNING kernel: [3751.486781] hwrng: no data available
2024-04-26T15:41:23.491078Z ERR kernel: [3763.773576] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491132Z WARNING kernel: [3763.774613] hwrng: no data available
2024-04-26T15:41:23.491138Z ERR kernel: [3776.061647] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491142Z WARNING kernel: [3776.062726] hwrng: no data available
2024-04-26T15:41:23.491145Z ERR kernel: [3788.349718] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491149Z WARNING kernel: [3788.350810] hwrng: no data available
2024-04-26T15:41:23.491152Z ERR kernel: [3800.637317] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491199Z WARNING kernel: [3800.638384] hwrng: no data available
2024-04-26T15:41:23.491206Z ERR kernel: [3812.925486] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491209Z WARNING kernel: [3812.926549] hwrng: no data available
2024-04-26T15:41:23.491212Z ERR kernel: [3825.213580] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491215Z WARNING kernel: [3825.214673] hwrng: no data available
2024-04-26T15:41:23.491218Z ERR kernel: [3837.502087] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491221Z WARNING kernel: [3837.503130] hwrng: no data available
2024-04-26T15:41:23.491266Z ERR kernel: [3849.789336] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491272Z WARNING kernel: [3849.790436] hwrng: no data available
2024-04-26T15:41:23.491276Z ERR kernel: [3862.077162] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491279Z WARNING kernel: [3862.078230] hwrng: no data available
2024-04-26T15:41:23.491282Z ERR kernel: [3874.366346] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491286Z WARNING kernel: [3874.367471] hwrng: no data available
2024-04-26T15:41:23.491333Z ERR kernel: [3886.675491] tpm tpm0: Operation Timed out

```
2024-04-26T15:41:23.491339Z WARNING kernel: [ 3886.676595] hwrng: no data available
2024-04-26T15:41:23.491344Z ERR kernel: [ 3898.941227] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491346Z WARNING kernel: [ 3898.942690] hwrng: no data available
2024-04-26T15:41:23.491349Z ERR kernel: [ 3911.229703] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491353Z WARNING kernel: [ 3911.231037] hwrng: no data available
2024-04-26T15:41:23.491357Z ERR kernel: [ 3923.518061] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491402Z WARNING kernel: [ 3923.519331] hwrng: no data available
2024-04-26T15:41:23.491409Z ERR kernel: [ 3935.901750] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491413Z WARNING kernel: [ 3935.903158] hwrng: no data available
2024-04-26T15:41:23.491416Z ERR kernel: [ 3948.097934] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.491419Z WARNING kernel: [ 3948.099052] hwrng: no data available
2024-04-26T15:41:23.518653Z ERR kernel: [ 3960.382527] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.519197Z WARNING kernel: [ 3960.383707] hwrng: no data available
2024-04-26T15:41:23.519208Z ERR kernel: [ 3972.669417] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.519213Z WARNING kernel: [ 3972.670792] hwrng: no data available
2024-04-26T15:41:23.519217Z ERR kernel: [ 3984.957409] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.519220Z WARNING kernel: [ 3984.958565] hwrng: no data available
2024-04-26T15:41:23.519224Z ERR kernel: [ 3997.245866] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.533803Z WARNING kernel: [ 3997.246998] hwrng: no data available
2024-04-26T15:41:23.533825Z ERR kernel: [ 4009.535169] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.533827Z WARNING kernel: [ 4009.536415] hwrng: no data available
2024-04-26T15:41:23.533829Z ERR kernel: [ 4021.821752] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.533831Z WARNING kernel: [ 4021.822952] hwrng: no data available
2024-04-26T15:41:23.533833Z ERR kernel: [ 4034.109155] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.533835Z WARNING kernel: [ 4034.110331] hwrng: no data available
2024-04-26T15:41:23.534290Z ERR kernel: [ 4046.398197] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.534302Z WARNING kernel: [ 4046.399633] hwrng: no data available
2024-04-26T15:41:23.534304Z ERR kernel: [ 4058.685707] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.534306Z WARNING kernel: [ 4058.686811] hwrng: no data available
2024-04-26T15:41:23.534308Z ERR kernel: [ 4070.973356] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.534310Z WARNING kernel: [ 4070.974511] hwrng: no data available
2024-04-26T15:41:23.554498Z ERR kernel: [ 4083.261340] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.554519Z WARNING kernel: [ 4083.262935] hwrng: no data available
2024-04-26T15:41:23.554524Z ERR kernel: [ 4095.549189] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.554527Z WARNING kernel: [ 4095.550313] hwrng: no data available
2024-04-26T15:41:23.554530Z ERR kernel: [ 4107.842163] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.554532Z WARNING kernel: [ 4107.843873] hwrng: no data available
2024-04-26T15:41:23.554537Z ERR kernel: [ 4120.125957] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.554907Z WARNING kernel: [ 4120.127107] hwrng: no data available
2024-04-26T15:41:23.554916Z ERR kernel: [ 4132.413280] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.554921Z WARNING kernel: [ 4132.414405] hwrng: no data available
2024-04-26T15:41:23.554924Z ERR kernel: [ 4144.702009] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.554927Z WARNING kernel: [ 4144.707837] hwrng: no data available
2024-04-26T15:41:23.554930Z ERR kernel: [ 4156.989314] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.554982Z WARNING kernel: [ 4156.990788] hwrng: no data available
2024-04-26T15:41:23.554988Z ERR kernel: [ 4169.328447] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.554991Z WARNING kernel: [ 4169.329888] hwrng: no data available
2024-04-26T15:41:23.554995Z ERR kernel: [ 4181.578876] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.554999Z WARNING kernel: [ 4181.584293] hwrng: no data available
2024-04-26T15:41:23.555002Z ERR kernel: [ 4193.853815] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.555387Z WARNING kernel: [ 4193.854937] hwrng: no data available
2024-04-26T15:41:23.555396Z ERR kernel: [ 4206.142853] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.555399Z WARNING kernel: [ 4206.150491] hwrng: no data available
2024-04-26T15:41:23.555402Z ERR kernel: [ 4218.429306] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.555405Z WARNING kernel: [ 4218.430425] hwrng: no data available
2024-04-26T15:41:23.555409Z ERR kernel: [ 4230.717220] tpm tpm0: Operation Timed out
2024-04-26T15:41:23.555413Z WARNING kernel: [ 4230.719771] hwrng: no data available
2024-04-26T15:41:23.555545Z WARNING kernel: [ 4232.355235] PM: pm_system_irq_wakeup: 12
triggered i8042
2024-04-26T15:41:23.555553Z DEBUG kernel: [ 4232.370817] PM: Wakeup unrelated to ACPI SCI
2024-04-26T15:41:23.555556Z DEBUG kernel: [ 4232.370886] PM: resume from suspend-to-idle
2024-04-26T15:41:23.555559Z INFO kernel: [ 4232.437487] vmw_vmci 0000:00:07.7: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 24074, parent: pci0000:00
2024-04-26T15:41:23.555565Z INFO kernel: [ 4232.437487] pci 0000:00:01.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.555570Z INFO kernel: [ 4232.437644] pci 0000:00:07.3: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 24079, parent: pci0000:00
2024-04-26T15:41:23.556003Z INFO kernel: [ 4232.440307] pci 0000:00:00.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 22023, parent: pci0000:00
```

2024-04-26T15:41:23.556012Z INFO kernel: [4232.451325] vmwgfx 0000:00:0f.0: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24080, parent: pci0000:00

2024-04-26T15:41:23.556016Z INFO kernel: [4232.451690] pci 0000:00:07.0: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24077, parent: pci0000:00

2024-04-26T15:41:23.556018Z INFO kernel: [4232.452248] pci 0000:00:01.0: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 12139 usecs

2024-04-26T15:41:23.556021Z INFO kernel: [4232.452699] pci 0000:00:10.0: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24076, parent: pci0000:00

2024-04-26T15:41:23.556026Z INFO kernel: [4232.454595] pci 0000:00:10.0: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 1889 usecs

2024-04-26T15:41:23.556029Z INFO kernel: [4232.454606] pci 0000:00:11.0: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24076, parent: pci0000:00

2024-04-26T15:41:23.556080Z INFO kernel: [4232.454611] pci 0000:00:11.0: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 0 usecs

2024-04-26T15:41:23.556087Z INFO kernel: [4232.454662] pcieport 0000:00:15.0: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24076, parent: pci0000:00

2024-04-26T15:41:23.556091Z INFO kernel: [4232.456599] pcieport 0000:00:15.0: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 1898 usecs

2024-04-26T15:41:23.556094Z INFO kernel: [4232.456864] vmw_vmci 0000:00:07.7: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 11997 usecs

2024-04-26T15:41:23.556096Z INFO kernel: [4232.456881] pcieport 0000:00:15.1: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24074, parent: pci0000:00

2024-04-26T15:41:23.556100Z INFO kernel: [4232.457294] pcieport 0000:00:15.1: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 406 usecs

2024-04-26T15:41:23.556653Z INFO kernel: [4232.457306] pcieport 0000:00:15.2: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24074, parent: pci0000:00

2024-04-26T15:41:23.556666Z INFO kernel: [4232.457448] pcieport 0000:00:15.2: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 136 usecs

2024-04-26T15:41:23.556669Z INFO kernel: [4232.457455] pcieport 0000:00:15.3: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24074, parent: pci0000:00

2024-04-26T15:41:23.556672Z INFO kernel: [4232.457764] pcieport 0000:00:15.3: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 303 usecs

2024-04-26T15:41:23.556675Z INFO kernel: [4232.457772] pcieport 0000:00:15.4: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24074, parent: pci0000:00

2024-04-26T15:41:23.556677Z INFO kernel: [4232.457866] pcieport 0000:00:15.4: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 89 usecs

2024-04-26T15:41:23.557210Z INFO kernel: [4232.457872] pcieport 0000:00:15.5: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24074, parent: pci0000:00

2024-04-26T15:41:23.557222Z INFO kernel: [4232.458054] pcieport 0000:00:15.5: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 177 usecs

2024-04-26T15:41:23.557226Z INFO kernel: [4232.458062] pcieport 0000:00:15.6: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24074, parent: pci0000:00

2024-04-26T15:41:23.557230Z INFO kernel: [4232.458187] pcieport 0000:00:15.6: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 120 usecs

2024-04-26T15:41:23.557233Z INFO kernel: [4232.458193] pcieport 0000:00:15.7: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24074, parent: pci0000:00

2024-04-26T15:41:23.557236Z INFO kernel: [4232.458321] pcieport 0000:00:15.7: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 123 usecs

2024-04-26T15:41:23.577126Z INFO kernel: [4232.458949] pcieport 0000:00:16.0: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24074, parent: pci0000:00

2024-04-26T15:41:23.577146Z INFO kernel: [4232.459613] pcieport 0000:00:16.0: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 655 usecs

2024-04-26T15:41:23.577150Z INFO kernel: [4232.459630] pcieport 0000:00:16.1: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24074, parent: pci0000:00

2024-04-26T15:41:23.577152Z INFO kernel: [4232.459830] pcieport 0000:00:16.1: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 192 usecs

2024-04-26T15:41:23.577154Z INFO kernel: [4232.459841] pcieport 0000:00:16.2: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24074, parent: pci0000:00

2024-04-26T15:41:23.577157Z INFO kernel: [4232.459946] pcieport 0000:00:16.2: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 99 usecs

2024-04-26T15:41:23.577741Z INFO kernel: [4232.459954] pcieport 0000:00:16.3: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24074, parent: pci0000:00

2024-04-26T15:41:23.577757Z INFO kernel: [4232.460095] pcieport 0000:00:16.3: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 136 usecs

2024-04-26T15:41:23.577760Z INFO kernel: [4232.460104] pcieport 0000:00:16.4: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 24074, parent: pci0000:00

2024-04-26T15:41:23.577763Z INFO kernel: [4232.460238] pcieport 0000:00:16.4: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 128 usecs

2024-04-26T15:41:23.577765Z INFO kernel: [4232.460787] ata_piix 0000:00:07.1: PM:

```
calling pci_pm_resume_noirq+0x0/0xf1 @ 24078, parent: pci0000:00
2024-04-26T15:41:23.577767Z INFO kernel: [ 4232.461291] pci 0000:00:00.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 20973 usecs
2024-04-26T15:41:23.578150Z INFO kernel: [ 4232.461303] pcieport 0000:00:16.5: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.578161Z INFO kernel: [ 4232.461588] pcieport 0000:00:16.5: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 279 usecs
2024-04-26T15:41:23.578165Z INFO kernel: [ 4232.461596] pcieport 0000:00:16.6: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.578167Z INFO kernel: [ 4232.461778] pcieport 0000:00:16.6: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 178 usecs
2024-04-26T15:41:23.578169Z INFO kernel: [ 4232.461785] pcieport 0000:00:16.7: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.578171Z INFO kernel: [ 4232.461906] pcieport 0000:00:16.7: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 117 usecs
2024-04-26T15:41:23.578749Z INFO kernel: [ 4232.461912] pcieport 0000:00:17.0: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.578760Z INFO kernel: [ 4232.462368] pcieport 0000:00:17.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 450 usecs
2024-04-26T15:41:23.578764Z INFO kernel: [ 4232.462377] pcieport 0000:00:17.1: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.578766Z INFO kernel: [ 4232.462557] pcieport 0000:00:17.1: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 175 usecs
2024-04-26T15:41:23.578768Z INFO kernel: [ 4232.462564] pcieport 0000:00:17.2: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.578866Z INFO kernel: [ 4232.462694] pcieport 0000:00:17.2: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 125 usecs
2024-04-26T15:41:23.578872Z INFO kernel: [ 4232.462700] pcieport 0000:00:17.3: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.578874Z INFO kernel: [ 4232.462871] ata_piix 0000:00:07.1: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 1982 usecs
2024-04-26T15:41:23.578876Z INFO kernel: [ 4232.462885] pcieport 0000:00:17.4: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 24078, parent: pci0000:00
2024-04-26T15:41:23.578877Z INFO kernel: [ 4232.463070] pcieport 0000:00:17.3: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 365 usecs
2024-04-26T15:41:23.578879Z INFO kernel: [ 4232.463077] pcieport 0000:00:17.5: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.578925Z INFO kernel: [ 4232.463082] pcieport 0000:00:17.4: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 188 usecs
2024-04-26T15:41:23.578930Z INFO kernel: [ 4232.463092] pcieport 0000:00:17.6: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 24078, parent: pci0000:00
2024-04-26T15:41:23.578932Z INFO kernel: [ 4232.463693] pcieport 0000:00:17.5: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 611 usecs
2024-04-26T15:41:23.578934Z INFO kernel: [ 4232.463701] pcieport 0000:00:17.7: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.578936Z INFO kernel: [ 4232.463704] pcieport 0000:00:17.6: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 605 usecs
2024-04-26T15:41:23.578938Z INFO kernel: [ 4232.463714] pcieport 0000:00:18.0: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 24078, parent: pci0000:00
2024-04-26T15:41:23.578979Z INFO kernel: [ 4232.463908] pcieport 0000:00:17.7: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 202 usecs
2024-04-26T15:41:23.578983Z INFO kernel: [ 4232.463928] pcieport 0000:00:18.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 208 usecs
2024-04-26T15:41:23.578985Z INFO kernel: [ 4232.463937] pcieport 0000:00:18.1: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.578987Z INFO kernel: [ 4232.464464] pcieport 0000:00:18.2: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 24078, parent: pci0000:00
2024-04-26T15:41:23.578989Z INFO kernel: [ 4232.464780] pcieport 0000:00:18.1: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 317 usecs
2024-04-26T15:41:23.578991Z INFO kernel: [ 4232.464781] pcieport 0000:00:18.2: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 309 usecs
2024-04-26T15:41:23.579385Z INFO kernel: [ 4232.464790] pcieport 0000:00:18.3: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 24078, parent: pci0000:00
2024-04-26T15:41:23.579395Z INFO kernel: [ 4232.464790] pcieport 0000:00:18.4: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.579398Z INFO kernel: [ 4232.464998] pcieport 0000:00:18.4: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 201 usecs
2024-04-26T15:41:23.579400Z INFO kernel: [ 4232.465011] pcieport 0000:00:18.3: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 215 usecs
```

```
2024-04-26T15:41:23.579402Z INFO kernel: [ 4232.465031] pcieport 0000:00:18.7: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 24078, parent: pci0000:00
2024-04-26T15:41:23.579404Z INFO kernel: [ 4232.465046] pcieport 0000:00:18.5: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.579407Z INFO kernel: [ 4232.465074] pcieport 0000:00:18.6: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.576526Z ERR shill[837]: ERROR shill: [dhcp_controller.cc(437)] DHCP
lease expired on eth0; restarting DHCP client instance.
2024-04-26T15:41:23.619836Z INFO kernel: [ 4232.465346] pcieport 0000:00:18.5: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 261 usecs
2024-04-26T15:41:23.624019Z INFO kernel: [ 4232.465386] uhci_hcd 0000:02:00.0: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 22023, parent: 0000:00:11.0
2024-04-26T15:41:23.624038Z INFO kernel: [ 4232.465424] pcieport 0000:00:18.6: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 340 usecs
2024-04-26T15:41:23.624042Z INFO kernel: [ 4232.465473] e1000 0000:02:01.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 24076, parent: 0000:00:11.0
2024-04-26T15:41:23.624045Z INFO kernel: [ 4232.465795] uhci_hcd 0000:02:00.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 402 usecs
2024-04-26T15:41:23.624048Z INFO kernel: [ 4232.466392] snd_hda_intel 0000:02:02.0: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 22023, parent: 0000:00:11.0
2024-04-26T15:41:23.624051Z INFO kernel: [ 4232.467051] vmwgfx 0000:00:0f.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 50 usecs
2024-04-26T15:41:23.624055Z INFO kernel: [ 4232.467065] ehci-pci 0000:02:03.0: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 24080, parent: 0000:00:11.0
2024-04-26T15:41:23.624058Z INFO kernel: [ 4232.467072] ehci-pci 0000:02:03.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 0 usecs
2024-04-26T15:41:23.624069Z INFO kernel: [ 4232.467151] nvme 0000:03:00.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 24080, parent: 0000:00:15.0
2024-04-26T15:41:23.624073Z INFO kernel: [ 4232.487041] e1000 0000:02:01.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 21518 usecs
2024-04-26T15:41:23.624076Z INFO kernel: [ 4232.487468] snd_hda_intel 0000:02:02.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 21064 usecs
2024-04-26T15:41:23.624080Z INFO kernel: [ 4232.488563] pci 0000:00:07.3: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 954 usecs
2024-04-26T15:41:23.624083Z INFO kernel: [ 4232.489002] pci 0000:00:07.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 408 usecs
2024-04-26T15:41:23.624086Z INFO kernel: [ 4232.489732] pcieport 0000:00:18.7: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 191 usecs
2024-04-26T15:41:23.624090Z INFO kernel: [ 4232.493637] i8042 i8042: PM: calling
i8042_pm_resume_noirq+0x0/0x21 @ 24070, parent: platform
2024-04-26T15:41:23.624093Z INFO kernel: [ 4232.504285] nvme 0000:03:00.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 37122 usecs
2024-04-26T15:41:23.624100Z INFO kernel: [ 4232.506827] i8042 i8042: PM:
i8042_pm_resume_noirq+0x0/0x21 returned 0 after 1192 usecs
2024-04-26T15:41:23.624104Z DEBUG kernel: [ 4232.826782] PM: noirq resume of devices
complete after 454.944 msecs
2024-04-26T15:41:23.624107Z INFO kernel: [ 4232.855845] pci 0000:00:11.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 24080, parent: pci0000:00
2024-04-26T15:41:23.624110Z INFO kernel: [ 4232.855855] pci 0000:00:00.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 24077, parent: pci0000:00
2024-04-26T15:41:23.624113Z INFO kernel: [ 4232.855981] ata_piix 0000:00:07.1: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.624116Z INFO kernel: [ 4232.856198] pci 0000:00:07.3: PM: calling
pci_pm_resume_early+0x0/0x29 @ 24082, parent: pci0000:00
2024-04-26T15:41:23.624121Z INFO kernel: [ 4232.856478] ata_piix 0000:00:07.1: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 484 usecs
2024-04-26T15:41:23.624124Z INFO kernel: [ 4232.856493] pcieport 0000:00:15.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.624133Z INFO kernel: [ 4232.856501] pcieport 0000:00:15.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624137Z INFO kernel: [ 4232.856562] pcieport 0000:00:15.1: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.624140Z INFO kernel: [ 4232.856569] pcieport 0000:00:15.1: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 1 usecs
2024-04-26T15:41:23.624143Z INFO kernel: [ 4232.856576] pcieport 0000:00:15.2: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.624299Z INFO kernel: [ 4232.856582] pcieport 0000:00:15.2: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624337Z INFO kernel: [ 4232.856589] pcieport 0000:00:15.3: PM:
```



```
2024-04-26T15:41:23.624520Z INFO kernel: [ 4232.856885] pcieport 0000:00:17.4: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624523Z INFO kernel: [ 4232.856891] pcieport 0000:00:17.5: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.624526Z INFO kernel: [ 4232.856896] pcieport 0000:00:17.5: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624530Z INFO kernel: [ 4232.856903] pcieport 0000:00:17.6: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.624533Z INFO kernel: [ 4232.856909] pcieport 0000:00:17.6: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624536Z INFO kernel: [ 4232.856914] pcieport 0000:00:17.7: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.624540Z INFO kernel: [ 4232.856921] pcieport 0000:00:17.7: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624543Z INFO kernel: [ 4232.856927] pcieport 0000:00:18.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.624546Z INFO kernel: [ 4232.856933] pcieport 0000:00:18.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624550Z INFO kernel: [ 4232.856939] pcieport 0000:00:18.1: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.624554Z INFO kernel: [ 4232.856944] pcieport 0000:00:18.1: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624558Z INFO kernel: [ 4232.856951] pcieport 0000:00:18.2: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.624564Z INFO kernel: [ 4232.856957] pcieport 0000:00:18.2: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624569Z INFO kernel: [ 4232.856963] pcieport 0000:00:18.3: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.624571Z INFO kernel: [ 4232.856968] pcieport 0000:00:18.3: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624574Z INFO kernel: [ 4232.856975] pcieport 0000:00:18.4: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.624576Z INFO kernel: [ 4232.856980] pcieport 0000:00:18.4: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624578Z INFO kernel: [ 4232.856986] pcieport 0000:00:18.5: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.624580Z INFO kernel: [ 4232.856991] pcieport 0000:00:18.5: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624582Z INFO kernel: [ 4232.856998] pcieport 0000:00:18.6: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.624584Z INFO kernel: [ 4232.857003] pcieport 0000:00:18.6: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624586Z INFO kernel: [ 4232.857051] pcieport 0000:00:18.7: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: pci0000:00
2024-04-26T15:41:23.624589Z INFO kernel: [ 4232.857058] pcieport 0000:00:18.7: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624592Z INFO kernel: [ 4232.857104] vmwgfx 0000:00:0f.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 24079, parent: pci0000:00
2024-04-26T15:41:23.624594Z INFO kernel: [ 4232.857110] vmwgfx 0000:00:0f.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624597Z INFO kernel: [ 4232.857164] pci 0000:00:10.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 22023, parent: pci0000:00
2024-04-26T15:41:23.624600Z INFO kernel: [ 4232.857170] pci 0000:00:10.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624603Z INFO kernel: [ 4232.857243] vmw_vmci 0000:00:07.7: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24081, parent: pci0000:00
2024-04-26T15:41:23.624607Z INFO kernel: [ 4232.857249] vmw_vmci 0000:00:07.7: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624610Z INFO kernel: [ 4232.861017] nvme 0000:03:00.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 24074, parent: 0000:00:15.0
2024-04-26T15:41:23.624612Z INFO kernel: [ 4232.861033] nvme 0000:03:00.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 1 usecs
2024-04-26T15:41:23.624619Z INFO kernel: [ 4232.861110] pci 0000:00:07.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 24083, parent: pci0000:00
2024-04-26T15:41:23.624624Z INFO kernel: [ 4232.861449] pci 0000:00:07.3: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 5241 usecs
2024-04-26T15:41:23.624627Z INFO kernel: [ 4232.861474] pci 0000:00:01.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 24078, parent: pci0000:00
2024-04-26T15:41:23.624630Z INFO kernel: [ 4232.861481] pci 0000:00:01.0: PM:
```



```
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624632Z INFO kernel: [ 4232.865034] pci 0000:00:00.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 1 usecs
2024-04-26T15:41:23.624639Z INFO kernel: [ 4232.871937] pci 0000:00:11.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 1 usecs
2024-04-26T15:41:23.624645Z INFO kernel: [ 4232.873202] pci 0000:00:07.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624649Z INFO kernel: [ 4232.882461] e1000 0000:02:01.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 24079, parent: 0000:00:11.0
2024-04-26T15:41:23.624652Z INFO kernel: [ 4232.883234] snd_hda_intel 0000:02:02.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 22023, parent: 0000:00:11.0
2024-04-26T15:41:23.624656Z INFO kernel: [ 4232.883249] snd_hda_intel 0000:02:02.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 1 usecs
2024-04-26T15:41:23.624936Z INFO kernel: [ 4232.885625] ehci-pci 0000:02:03.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24081, parent: 0000:00:11.0
2024-04-26T15:41:23.624946Z INFO kernel: [ 4232.889562] e1000 0000:02:01.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 1 usecs
2024-04-26T15:41:23.624949Z INFO kernel: [ 4232.889593] uhci_hcd 0000:02:00.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 24076, parent: 0000:00:11.0
2024-04-26T15:41:23.624951Z INFO kernel: [ 4232.889601] uhci_hcd 0000:02:00.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T15:41:23.624954Z INFO kernel: [ 4233.228542] ehci-pci 0000:02:03.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 66 usecs
2024-04-26T15:41:23.624955Z DEBUG kernel: [ 4233.232606] PM: early resume of devices
complete after 395.591 msecs
2024-04-26T15:41:23.624958Z INFO kernel: [ 4233.238753] pci 0000:00:00.0: PM: calling
pci_pm_resume+0x0/0xed @ 24078, parent: pci0000:00
2024-04-26T15:41:23.624960Z INFO kernel: [ 4233.238753] pci 0000:00:07.0: PM: calling
pci_pm_resume+0x0/0xed @ 24080, parent: pci0000:00
2024-04-26T15:41:23.624962Z INFO kernel: [ 4233.238772] pci 0000:00:00.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 2 usecs
2024-04-26T15:41:23.624964Z INFO kernel: [ 4233.242158] ata_piix 0000:00:07.1: PM:
calling pci_pm_resume+0x0/0xed @ 24084, parent: pci0000:00
2024-04-26T15:41:23.624966Z INFO kernel: [ 4233.242339] pci 0000:00:01.0: PM: calling
pci_pm_resume+0x0/0xed @ 24083, parent: pci0000:00
2024-04-26T15:41:23.624968Z INFO kernel: [ 4233.242351] pci 0000:00:01.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 1 usecs
2024-04-26T15:41:23.624970Z INFO kernel: [ 4233.242363] pci 0000:00:07.3: PM: calling
pci_pm_resume+0x0/0xed @ 24083, parent: pci0000:00
2024-04-26T15:41:23.625508Z INFO kernel: [ 4233.242370] pci 0000:00:07.3: PM:
pci_pm_resume+0x0/0xed returned 0 after 0 usecs
2024-04-26T15:41:23.625519Z INFO kernel: [ 4233.242377] vmw_vmci 0000:00:07.7: PM:
calling pci_pm_resume+0x0/0xed @ 24083, parent: pci0000:00
2024-04-26T15:41:23.625524Z INFO kernel: [ 4233.242617] vmwgfx 0000:00:0f.0: PM: calling
pci_pm_resume+0x0/0xed @ 22023, parent: pci0000:00
2024-04-26T15:41:23.625528Z INFO kernel: [ 4233.242887] vmw_vmci 0000:00:07.7: PM:
pci_pm_resume+0x0/0xed returned 0 after 497 usecs
2024-04-26T15:41:23.625531Z INFO kernel: [ 4233.242899] pci 0000:00:10.0: PM: calling
pci_pm_resume+0x0/0xed @ 24083, parent: pci0000:00
2024-04-26T15:41:23.625535Z INFO kernel: [ 4233.242905] pci 0000:00:10.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 0 usecs
2024-04-26T15:41:23.625538Z INFO kernel: [ 4233.242911] pci 0000:00:11.0: PM: calling
pci_pm_resume+0x0/0xed @ 24083, parent: pci0000:00
2024-04-26T15:41:23.625541Z INFO kernel: [ 4233.245463] pci 0000:00:11.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 2544 usecs
2024-04-26T15:41:23.625545Z INFO kernel: [ 4233.245482] pcieport 0000:00:15.0: PM:
calling pci_pm_resume+0x0/0xed @ 24083, parent: pci0000:00
2024-04-26T15:41:23.625548Z INFO kernel: [ 4233.245892] ata_piix 0000:00:07.1: PM:
pci_pm_resume+0x0/0xed returned 0 after 3716 usecs
2024-04-26T15:41:23.625551Z INFO kernel: [ 4233.245905] pcieport 0000:00:15.1: PM:
calling pci_pm_resume+0x0/0xed @ 24082, parent: pci0000:00
2024-04-26T15:41:23.625555Z INFO kernel: [ 4233.246381] pcieport 0000:00:15.2: PM:
calling pci_pm_resume+0x0/0xed @ 24077, parent: pci0000:00
2024-04-26T15:41:23.625559Z INFO kernel: [ 4233.249117] pcieport 0000:00:15.3: PM:
calling pci_pm_resume+0x0/0xed @ 24074, parent: pci0000:00
2024-04-26T15:41:23.625562Z INFO kernel: [ 4233.250432] pcieport 0000:00:15.2: PM:
pci_pm_resume+0x0/0xed returned 0 after 4041 usecs
2024-04-26T15:41:23.625565Z INFO kernel: [ 4233.250448] pcieport 0000:00:15.4: PM:
calling pci_pm_resume+0x0/0xed @ 24077, parent: pci0000:00
```

```
2024-04-26T15:41:23.625568Z INFO kernel: [ 4233.250606] pcieport 0000:00:15.1: PM:
pci_pm_resume+0x0/0xed returned 0 after 4626 usecs
2024-04-26T15:41:23.625572Z INFO kernel: [ 4233.250618] pcieport 0000:00:15.5: PM:
calling pci_pm_resume+0x0/0xed @ 24082, parent: pci0000:00
2024-04-26T15:41:23.625575Z INFO kernel: [ 4233.252507] pcieport 0000:00:15.6: PM:
calling pci_pm_resume+0x0/0xed @ 24081, parent: pci0000:00
2024-04-26T15:41:23.625578Z INFO kernel: [ 4233.253257] pcieport 0000:00:16.0: PM:
calling pci_pm_resume+0x0/0xed @ 24085, parent: pci0000:00
2024-04-26T15:41:23.625581Z INFO kernel: [ 4233.253334] ac ACPI0003:00: PM: calling
acpi_ac_resume+0x0/0x58 @ 24070, parent: LNXSYBUS:00
2024-04-26T15:41:23.625585Z INFO kernel: [ 4233.255237] pcieport 0000:00:15.6: PM:
pci_pm_resume+0x0/0xed returned 0 after 2716 usecs
2024-04-26T15:41:23.625588Z INFO kernel: [ 4233.255251] pcieport 0000:00:16.1: PM:
calling pci_pm_resume+0x0/0xed @ 24081, parent: pci0000:00
2024-04-26T15:41:23.625592Z INFO kernel: [ 4233.257098] pcieport 0000:00:16.1: PM:
pci_pm_resume+0x0/0xed returned 0 after 1840 usecs
2024-04-26T15:41:23.625595Z INFO kernel: [ 4233.257110] pcieport 0000:00:16.2: PM:
calling pci_pm_resume+0x0/0xed @ 24081, parent: pci0000:00
2024-04-26T15:41:23.625598Z INFO kernel: [ 4233.257794] pcieport 0000:00:16.3: PM:
calling pci_pm_resume+0x0/0xed @ 24079, parent: pci0000:00
2024-04-26T15:41:23.625602Z INFO kernel: [ 4233.262402] pcieport 0000:00:16.3: PM:
pci_pm_resume+0x0/0xed returned 0 after 4595 usecs
2024-04-26T15:41:23.625605Z INFO kernel: [ 4233.263531] vmwgfx 0000:00:0f.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 3805 usecs
2024-04-26T15:41:23.625609Z INFO kernel: [ 4233.263549] pcieport 0000:00:16.4: PM:
calling pci_pm_resume+0x0/0xed @ 22023, parent: pci0000:00
2024-04-26T15:41:23.625612Z INFO kernel: [ 4233.263704] pcieport 0000:00:15.7: PM:
calling pci_pm_resume+0x0/0xed @ 24087, parent: pci0000:00
2024-04-26T15:41:23.625616Z INFO kernel: [ 4233.264444] pcieport 0000:00:15.4: PM:
pci_pm_resume+0x0/0xed returned 0 after 13987 usecs
2024-04-26T15:41:23.625619Z INFO kernel: [ 4233.264456] pcieport 0000:00:16.5: PM:
calling pci_pm_resume+0x0/0xed @ 24077, parent: pci0000:00
2024-04-26T15:41:23.625622Z INFO kernel: [ 4233.265166] pcieport 0000:00:16.6: PM:
calling pci_pm_resume+0x0/0xed @ 24086, parent: pci0000:00
2024-04-26T15:41:23.625626Z INFO kernel: [ 4233.267863] pcieport 0000:00:16.5: PM:
pci_pm_resume+0x0/0xed returned 0 after 3400 usecs
2024-04-26T15:41:23.625629Z INFO kernel: [ 4233.268730] ac ACPI0003:00: PM:
acpi_ac_resume+0x0/0x58 returned 0 after 15316 usecs
2024-04-26T15:41:23.625633Z INFO kernel: [ 4233.269081] pcieport 0000:00:16.7: PM:
calling pci_pm_resume+0x0/0xed @ 24079, parent: pci0000:00
2024-04-26T15:41:23.625636Z INFO kernel: [ 4233.272246] pcieport 0000:00:16.7: PM:
pci_pm_resume+0x0/0xed returned 0 after 3156 usecs
2024-04-26T15:41:23.625639Z INFO kernel: [ 4233.277356] pcieport 0000:00:17.0: PM:
calling pci_pm_resume+0x0/0xed @ 24078, parent: pci0000:00
2024-04-26T15:41:23.625642Z INFO kernel: [ 4233.277451] pci 0000:00:07.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 2 usecs
2024-04-26T15:41:23.625645Z INFO kernel: [ 4233.277493] pcieport 0000:00:17.1: PM:
calling pci_pm_resume+0x0/0xed @ 24080, parent: pci0000:00
2024-04-26T15:41:23.625652Z INFO kernel: [ 4233.280212] pcieport 0000:00:15.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 34721 usecs
2024-04-26T15:41:23.625658Z INFO kernel: [ 4233.280005] platform PNP0001:00: PM: calling
platform_pm_resume+0x0/0x41 @ 24070, parent: 0000:00:07.0
2024-04-26T15:41:23.625662Z INFO kernel: [ 4233.280963] pcieport 0000:00:17.1: PM:
pci_pm_resume+0x0/0xed returned 0 after 3460 usecs
2024-04-26T15:41:23.625665Z INFO kernel: [ 4233.280976] pcieport 0000:00:17.2: PM:
calling pci_pm_resume+0x0/0xed @ 24080, parent: pci0000:00
2024-04-26T15:41:23.625668Z INFO kernel: [ 4233.281008] platform PNP0001:00: PM:
platform_pm_resume+0x0/0x41 returned 0 after 437 usecs
2024-04-26T15:41:23.625671Z INFO kernel: [ 4233.281021] platform PNP0800:00: PM: calling
platform_pm_resume+0x0/0x41 @ 24070, parent: 0000:00:07.0
2024-04-26T15:41:23.625675Z INFO kernel: [ 4233.281030] platform PNP0800:00: PM:
platform_pm_resume+0x0/0x41 returned 0 after 0 usecs
2024-04-26T15:41:23.625678Z INFO kernel: [ 4233.281037] platform ACPI0003:00: PM: calling
platform_pm_resume+0x0/0x41 @ 24070, parent: platform
2024-04-26T15:41:23.625682Z INFO kernel: [ 4233.281044] platform ACPI0003:00: PM:
platform_pm_resume+0x0/0x41 returned 0 after 0 usecs
2024-04-26T15:41:23.625685Z INFO kernel: [ 4233.281161] button LNX_PWRB0:00: PM: calling
acpi_button_resume+0x0/0xa9 @ 24070, parent: LNXSYSTM:00
2024-04-26T15:41:23.625688Z INFO kernel: [ 4233.281675] button LNX_PWRB0:00: PM:
```

```
acpi_button_resume+0x0/0xa9 returned 0 after 501 usecs
2024-04-26T15:41:23.625692Z INFO kernel: [ 4233.281687] platform rtc-efi.0: PM: calling
platform_pm_resume+0x0/0x41 @ 24070, parent: platform
2024-04-26T15:41:23.625696Z INFO kernel: [ 4233.281695] platform rtc-efi.0: PM:
platform_pm_resume+0x0/0x41 returned 0 after 0 usecs
2024-04-26T15:41:23.625699Z INFO kernel: [ 4233.281702] platform efivars.0: PM: calling
platform_pm_resume+0x0/0x41 @ 24070, parent: platform
2024-04-26T15:41:23.625703Z INFO kernel: [ 4233.281708] platform efivars.0: PM:
platform_pm_resume+0x0/0x41 returned 0 after 0 usecs
2024-04-26T15:41:23.625789Z INFO kernel: [ 4233.281714] platform chromeos_acpi: PM:
calling platform_pm_resume+0x0/0x41 @ 24070, parent: platform
2024-04-26T15:41:23.625799Z INFO kernel: [ 4233.281759] platform chromeos_acpi: PM:
platform_pm_resume+0x0/0x41 returned 0 after 0 usecs
2024-04-26T15:41:23.625803Z INFO kernel: [ 4233.282193] system 00:00: PM: calling
pnp_bus_resume+0x0/0x9d @ 24070, parent: pnp0
2024-04-26T15:41:23.625806Z INFO kernel: [ 4233.283184] pcieport 0000:00:16.4: PM:
pci_pm_resume+0x0/0xed returned 0 after 19629 usecs
2024-04-26T15:41:23.625812Z INFO kernel: [ 4233.283194] pcieport 0000:00:17.3: PM:
calling pci_pm_resume+0x0/0xed @ 22023, parent: pci0000:00
2024-04-26T15:41:23.625817Z INFO kernel: [ 4233.283335] system 00:00: PM:
pnp_bus_resume+0x0/0x9d returned 0 after 1078 usecs
2024-04-26T15:41:23.625821Z INFO kernel: [ 4233.283349] rtc_cmos 00:01: PM: calling
pnp_bus_resume+0x0/0x9d @ 24070, parent: pnp0
2024-04-26T15:41:23.625824Z INFO kernel: [ 4233.283817] rtc_cmos 00:01: PM:
pnp_bus_resume+0x0/0x9d returned 0 after 457 usecs
2024-04-26T15:41:23.625828Z INFO kernel: [ 4233.283828] i8042 kbd 00:02: PM: calling
pnp_bus_resume+0x0/0x9d @ 24070, parent: pnp0
2024-04-26T15:41:23.625831Z INFO kernel: [ 4233.284294] i8042 kbd 00:02: PM:
pnp_bus_resume+0x0/0x9d returned 0 after 1 usecs
2024-04-26T15:41:23.625834Z INFO kernel: [ 4233.284304] i8042 aux 00:03: PM: calling
pnp_bus_resume+0x0/0x9d @ 24070, parent: pnp0
2024-04-26T15:41:23.625838Z INFO kernel: [ 4233.284361] i8042 aux 00:03: PM:
pnp_bus_resume+0x0/0x9d returned 0 after 0 usecs
2024-04-26T15:41:23.625842Z INFO kernel: [ 4233.284409] system 00:04: PM: calling
pnp_bus_resume+0x0/0x9d @ 24070, parent: pnp0
2024-04-26T15:41:23.625845Z INFO kernel: [ 4233.284417] system 00:04: PM:
pnp_bus_resume+0x0/0x9d returned 0 after 0 usecs
2024-04-26T15:41:23.625848Z INFO kernel: [ 4233.284424] system 00:05: PM: calling
pnp_bus_resume+0x0/0x9d @ 24070, parent: pnp0
2024-04-26T15:41:23.626090Z INFO kernel: [ 4233.284431] system 00:05: PM:
pnp_bus_resume+0x0/0x9d returned 0 after 0 usecs
2024-04-26T15:41:23.626099Z INFO kernel: [ 4233.284480] platform intel_rapl_msr.0: PM:
calling platform_pm_resume+0x0/0x41 @ 24070, parent: platform
2024-04-26T15:41:23.626105Z INFO kernel: [ 4233.284489] platform intel_rapl_msr.0: PM:
platform_pm_resume+0x0/0x41 returned 0 after 0 usecs
2024-04-26T15:41:23.626108Z INFO kernel: [ 4233.284936] pcieport 0000:00:17.3: PM:
pci_pm_resume+0x0/0xed returned 0 after 1736 usecs
2024-04-26T15:41:23.626112Z INFO kernel: [ 4233.284944] pcieport 0000:00:17.4: PM:
calling pci_pm_resume+0x0/0xed @ 22023, parent: pci0000:00
2024-04-26T15:41:23.626115Z INFO kernel: [ 4233.284611] input input0: PM: calling
input_dev_resume+0x0/0x42 @ 24070, parent: LNXPPWRBN:00
2024-04-26T15:41:23.626119Z INFO kernel: [ 4233.285612] pcieport 0000:00:17.5: PM:
calling pci_pm_resume+0x0/0xed @ 24084, parent: pci0000:00
2024-04-26T15:41:23.626122Z INFO kernel: [ 4233.289363] pcieport 0000:00:16.6: PM:
pci_pm_resume+0x0/0xed returned 0 after 24188 usecs
2024-04-26T15:41:23.626126Z INFO kernel: [ 4233.290140] input input0: PM:
input_dev_resume+0x0/0x42 returned 0 after 2 usecs
2024-04-26T15:41:23.626129Z INFO kernel: [ 4233.290213] serial8250 serial8250: PM:
calling platform_pm_resume+0x0/0x41 @ 24070, parent: platform
2024-04-26T15:41:23.626134Z INFO kernel: [ 4233.291279] pcieport 0000:00:16.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 4494 usecs
2024-04-26T15:41:23.626136Z INFO kernel: [ 4233.291297] pcieport 0000:00:17.6: PM:
calling pci_pm_resume+0x0/0xed @ 24085, parent: pci0000:00
2024-04-26T15:41:23.626140Z INFO kernel: [ 4233.291469] serial8250 serial8250: PM:
platform_pm_resume+0x0/0x41 returned 0 after 764 usecs
2024-04-26T15:41:23.626144Z INFO kernel: [ 4233.292961] pcieport 0000:00:15.5: PM:
pci_pm_resume+0x0/0xed returned 0 after 42337 usecs
2024-04-26T15:41:23.626148Z INFO kernel: [ 4233.293031] pcieport 0000:00:17.7: PM:
calling pci_pm_resume+0x0/0xed @ 24082, parent: pci0000:00
```

```
2024-04-26T15:41:23.626152Z INFO kernel: [ 4233.296331] pcieport 0000:00:17.7: PM:
pci_pm_resume+0x0/0xed returned 0 after 3289 usecs
2024-04-26T15:41:23.626155Z INFO kernel: [ 4233.298864] pcieport 0000:00:15.3: PM:
pci_pm_resume+0x0/0xed returned 0 after 25928 usecs
2024-04-26T15:41:23.626159Z INFO kernel: [ 4233.299421] pcieport 0000:00:16.2: PM:
pci_pm_resume+0x0/0xed returned 0 after 42283 usecs
2024-04-26T15:41:23.626163Z INFO kernel: [ 4233.299438] pcieport 0000:00:18.0: PM:
calling pci_pm_resume+0x0/0xed @ 24081, parent: pci0000:00
2024-04-26T15:41:23.626166Z INFO kernel: [ 4233.299568] pcieport 0000:00:18.1: PM:
calling pci_pm_resume+0x0/0xed @ 24076, parent: pci0000:00
2024-04-26T15:41:23.626170Z INFO kernel: [ 4233.300197] pcieport 0000:00:18.2: PM:
calling pci_pm_resume+0x0/0xed @ 24077, parent: pci0000:00
2024-04-26T15:41:23.626174Z INFO kernel: [ 4233.303360] pcieport 0000:00:18.1: PM:
pci_pm_resume+0x0/0xed returned 0 after 3779 usecs
2024-04-26T15:41:23.626177Z INFO kernel: [ 4233.304745] pcieport 0000:00:18.2: PM:
pci_pm_resume+0x0/0xed returned 0 after 4540 usecs
2024-04-26T15:41:23.626180Z INFO kernel: [ 4233.304760] pcieport 0000:00:18.3: PM:
calling pci_pm_resume+0x0/0xed @ 24077, parent: pci0000:00
2024-04-26T15:41:23.626185Z INFO kernel: [ 4233.306846] pcieport 0000:00:17.2: PM:
pci_pm_resume+0x0/0xed returned 0 after 25863 usecs
2024-04-26T15:41:23.626188Z INFO kernel: [ 4233.309749] pcieport 0000:00:18.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 10302 usecs
2024-04-26T15:41:23.626191Z INFO kernel: [ 4233.309769] pcieport 0000:00:18.4: PM:
calling pci_pm_resume+0x0/0xed @ 24081, parent: pci0000:00
2024-04-26T15:41:23.626195Z INFO kernel: [ 4233.309907] pcieport 0000:00:17.6: PM:
pci_pm_resume+0x0/0xed returned 0 after 18603 usecs
2024-04-26T15:41:23.626198Z INFO kernel: [ 4233.309922] pcieport 0000:00:18.5: PM:
calling pci_pm_resume+0x0/0xed @ 24085, parent: pci0000:00
2024-04-26T15:41:23.626202Z INFO kernel: [ 4233.313275] pcieport 0000:00:17.5: PM:
pci_pm_resume+0x0/0xed returned 0 after 4489 usecs
2024-04-26T15:41:23.626205Z INFO kernel: [ 4233.313682] pcieport 0000:00:18.6: PM:
calling pci_pm_resume+0x0/0xed @ 24083, parent: pci0000:00
2024-04-26T15:41:23.626209Z INFO kernel: [ 4233.316822] pcieport 0000:00:18.6: PM:
pci_pm_resume+0x0/0xed returned 0 after 3067 usecs
2024-04-26T15:41:23.626212Z INFO kernel: [ 4233.316835] pcieport 0000:00:18.7: PM:
calling pci_pm_resume+0x0/0xed @ 24083, parent: pci0000:00
2024-04-26T15:41:23.626215Z INFO kernel: [ 4233.318810] pcieport 0000:00:17.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 5068 usecs
2024-04-26T15:41:23.626219Z INFO kernel: [ 4233.319388] pcieport 0000:00:18.3: PM:
pci_pm_resume+0x0/0xed returned 0 after 14620 usecs
2024-04-26T15:41:23.626222Z INFO kernel: [ 4233.319402] uhci_hcd 0000:02:00.0: PM:
calling pci_pm_resume+0x0/0xed @ 24077, parent: 0000:00:11.0
2024-04-26T15:41:23.626225Z INFO kernel: [ 4233.321144] e1000 0000:02:01.0: PM: calling
pci_pm_resume+0x0/0xed @ 24076, parent: 0000:00:11.0
2024-04-26T15:41:23.626229Z INFO kernel: [ 4233.323749] pcieport 0000:00:17.4: PM:
pci_pm_resume+0x0/0xed returned 0 after 38797 usecs
2024-04-26T15:41:23.626232Z INFO kernel: [ 4233.324799] pcieport 0000:00:18.4: PM:
pci_pm_resume+0x0/0xed returned 0 after 15021 usecs
2024-04-26T15:41:23.626239Z INFO kernel: [ 4233.324824] snd_hda_intel 0000:02:02.0: PM:
calling pci_pm_resume+0x0/0xed @ 24081, parent: 0000:00:11.0
2024-04-26T15:41:23.626243Z INFO kernel: [ 4233.326312] platform Fixed MDIO bus.0: PM:
calling platform_pm_resume+0x0/0x41 @ 24070, parent: platform
2024-04-26T15:41:23.626245Z INFO kernel: [ 4233.326327] platform Fixed MDIO bus.0: PM:
platform_pm_resume+0x0/0x41 returned 0 after 0 usecs
2024-04-26T15:41:23.626248Z INFO kernel: [ 4233.326345] i8042 i8042: PM: calling
platform_pm_resume+0x0/0x41 @ 24070, parent: platform
2024-04-26T15:41:23.626249Z INFO kernel: [ 4233.326410] i8042 i8042: PM:
platform_pm_resume+0x0/0x41 returned 0 after 3 usecs
2024-04-26T15:41:23.626251Z INFO kernel: [ 4233.326941] atkbd serio0: PM: calling
serio_resume+0x0/0x94 @ 24070, parent: i8042
2024-04-26T15:41:23.626253Z INFO kernel: [ 4233.328163] ehci-pci 0000:02:03.0: PM:
calling pci_pm_resume+0x0/0xed @ 24079, parent: 0000:00:11.0
2024-04-26T15:41:23.626256Z INFO kernel: [ 4233.328528] nvme 0000:03:00.0: PM: calling
pci_pm_resume+0x0/0xed @ 24088, parent: 0000:00:15.0
2024-04-26T15:41:23.626257Z INFO kernel: [ 4233.329108] nvme 0000:03:00.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 567 usecs
2024-04-26T15:41:23.626259Z INFO kernel: [ 4233.329244] ata1: PM: calling
ata_port_pm_resume+0x0/0x56 @ 24088, parent: 0000:00:07.1
2024-04-26T15:41:23.626261Z INFO kernel: [ 4233.329858] pcieport 0000:00:15.7: PM:
```

```
pci_pm_resume+0x0/0xed returned 0 after 27819 usecs
2024-04-26T15:41:23.626263Z INFO kernel: [ 4233.329873] ata2: PM: calling
ata_port_pm_resume+0x0/0x56 @ 24087, parent: 0000:00:07.1
2024-04-26T15:41:23.626264Z INFO kernel: [ 4233.330963] ata1: PM:
ata_port_pm_resume+0x0/0x56 returned 0 after 1600 usecs
2024-04-26T15:41:23.626266Z INFO kernel: [ 4233.331800] atkbd serio0: PM:
serio_resume+0x0/0x94 returned 0 after 4323 usecs
2024-04-26T15:41:23.626267Z INFO kernel: [ 4233.332009] ehci-pci 0000:02:03.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 3833 usecs
2024-04-26T15:41:23.626269Z INFO kernel: [ 4233.331818] psmouse serio1: PM: calling
serio_resume+0x0/0x94 @ 24070, parent: i8042
2024-04-26T15:41:23.626271Z INFO kernel: [ 4233.332500] ata2: PM:
ata_port_pm_resume+0x0/0x56 returned 0 after 2617 usecs
2024-04-26T15:41:23.626272Z INFO kernel: [ 4233.333925] pcieport 0000:00:18.5: PM:
pci_pm_resume+0x0/0xed returned 0 after 23996 usecs
2024-04-26T15:41:23.626274Z INFO kernel: [ 4233.339103] psmouse serio1: PM:
serio_resume+0x0/0x94 returned 0 after 6787 usecs
2024-04-26T15:41:23.626276Z INFO kernel: [ 4233.341316] pcieport 0000:00:18.7: PM:
pci_pm_resume+0x0/0xed returned 0 after 24472 usecs
2024-04-26T15:41:23.626278Z INFO kernel: [ 4233.343919] alarmtimer alarmtimer.0.auto: PM:
calling platform_pm_resume+0x0/0x41 @ 24070, parent: rtc0
2024-04-26T15:41:23.626280Z NOTICE kernel: [ 4233.348992] usb usb2: root hub lost power
or was reset
2024-04-26T15:41:23.626282Z INFO kernel: [ 4233.355398] alarmtimer alarmtimer.0.auto: PM:
platform_pm_resume+0x0/0x41 returned 0 after 4561 usecs
2024-04-26T15:41:23.626284Z INFO kernel: [ 4233.372030] uhci_hcd 0000:02:00.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 52617 usecs
2024-04-26T15:41:23.626286Z INFO kernel: [ 4233.372345] usb usb2: PM: calling
usb_dev_resume+0x0/0x14 @ 22023, parent: 0000:02:00.0
2024-04-26T15:41:23.626288Z INFO kernel: [ 4233.384240] usb usb1: PM: calling
usb_dev_resume+0x0/0x14 @ 24088, parent: 0000:02:03.0
2024-04-26T15:41:23.626290Z INFO kernel: [ 4233.396527] input input1: PM: calling
input_dev_resume+0x0/0x42 @ 24070, parent: serio0
2024-04-26T15:41:23.626291Z ERR kernel: [ 4233.407941] snd_hda_intel 0000:02:02.0: CORB
reset timeout#1, CORBRP = 0
2024-04-26T15:41:23.626293Z INFO kernel: [ 4233.431220] input input1: PM:
input_dev_resume+0x0/0x42 returned 0 after 1251 usecs
2024-04-26T15:41:23.626295Z INFO kernel: [ 4233.432636] snd_hda_intel 0000:02:02.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 107799 usecs
2024-04-26T15:41:23.626306Z INFO kernel: [ 4233.436423] leds input1::numlock: PM: calling
led_resume+0x0/0x20 @ 24070, parent: input1
2024-04-26T15:41:23.640619Z INFO kernel: [ 4233.447061] e1000 0000:02:01.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 125902 usecs
2024-04-26T15:41:23.640644Z INFO kernel: [ 4233.448050] e1000: eth0 NIC Link is Up 1000
Mbps Full Duplex, Flow Control: None
2024-04-26T15:41:23.640649Z INFO kernel: [ 4233.459952] leds input1::numlock: PM:
led_resume+0x0/0x20 returned 0 after 4389 usecs
2024-04-26T15:41:23.640653Z INFO kernel: [ 4233.460226] snd_hda_codec_generic
hdaudioC0D0: PM: calling hda_codec_pm_resume+0x0/0x19 [snd_hda_codec] @ 24100, parent:
0000:02:02.0
2024-04-26T15:41:23.640657Z INFO kernel: [ 4233.467261] leds input1::capslock: PM:
calling led_resume+0x0/0x20 @ 24070, parent: input1
2024-04-26T15:41:23.640660Z INFO kernel: [ 4233.482017] usb usb1: PM:
usb_dev_resume+0x0/0x14 returned 0 after 43756 usecs
2024-04-26T15:41:23.640736Z INFO kernel: [ 4233.485540] leds input1::capslock: PM:
led_resume+0x0/0x20 returned 0 after 0 usecs
2024-04-26T15:41:23.640745Z INFO kernel: [ 4233.486070] leds input1::scrolllock: PM:
calling led_resume+0x0/0x20 @ 24070, parent: input1
2024-04-26T15:41:23.640749Z INFO kernel: [ 4233.486081] leds input1::scrolllock: PM:
led_resume+0x0/0x20 returned 0 after 0 usecs
2024-04-26T15:41:23.640752Z INFO kernel: [ 4233.486091] input input4: PM: calling
input_dev_resume+0x0/0x42 @ 24070, parent: serio1
2024-04-26T15:41:23.640760Z INFO kernel: [ 4233.486100] input input4: PM:
input_dev_resume+0x0/0x42 returned 0 after 0 usecs
2024-04-26T15:41:23.640764Z INFO kernel: [ 4233.486108] input input3: PM: calling
input_dev_resume+0x0/0x42 @ 24070, parent: serio1
2024-04-26T15:41:23.640766Z INFO kernel: [ 4233.486147] input input3: PM:
input_dev_resume+0x0/0x42 returned 0 after 0 usecs
2024-04-26T15:41:23.659535Z INFO kernel: [ 4233.506333] nvme nvme0: 8/0/0
```

```
default/read/poll queues
2024-04-26T15:41:23.659559Z INFO kernel: [ 4233.577752] usb usb2: PM:
usb_dev_resume+0x0/0x14 returned 0 after 188895 usecs
2024-04-26T15:41:23.659564Z INFO kernel: [ 4233.607364] snd_hda_codec_generic
hdaudioC0D0: PM: hda_codec_pm_resume+0x0/0x19 [snd_hda_codec] returned 0 after 135933
usecs
2024-04-26T15:41:23.659567Z INFO kernel: [ 4233.612699] usb 2-1: PM: calling
usb_dev_resume+0x0/0x14 @ 24091, parent: usb2
2024-04-26T15:41:23.659569Z INFO kernel: [ 4233.639252] usb 2-2: PM: calling
usb_dev_resume+0x0/0x14 @ 24094, parent: usb2
2024-04-26T15:41:23.659572Z INFO kernel: [ 4233.642831] usb 2-1: PM:
usb_dev_resume+0x0/0x14 returned 0 after 0 usecs
2024-04-26T15:41:23.660926Z INFO kernel: [ 4233.816739] usb 2-2: reset full-speed USB
device number 3 using uhci_hcd
2024-04-26T15:41:23.660940Z INFO kernel: [ 4233.818108] input input5: PM: calling
input_dev_resume+0x0/0x42 @ 24070, parent: 0003:0E0F:0003.0001
2024-04-26T15:41:23.660945Z INFO kernel: [ 4234.166753] input input5: PM:
input_dev_resume+0x0/0x42 returned 0 after 1 usecs
2024-04-26T15:41:23.660949Z INFO kernel: [ 4234.179403] platform regulatory.0: PM:
calling platform_pm_resume+0x0/0x41 @ 24070, parent: platform
2024-04-26T15:41:23.660952Z INFO kernel: [ 4234.186248] platform regulatory.0: PM:
platform_pm_resume+0x0/0x41 returned 0 after 1 usecs
2024-04-26T15:41:23.660955Z INFO kernel: [ 4234.198714] input input6: PM: calling
input_dev_resume+0x0/0x42 @ 24070, parent: card0
2024-04-26T15:41:23.660962Z INFO kernel: [ 4234.203233] input input6: PM:
input_dev_resume+0x0/0x42 returned 0 after 1 usecs
2024-04-26T15:41:23.660984Z INFO kernel: [ 4234.208306] input input7: PM: calling
input_dev_resume+0x0/0x42 @ 24070, parent: card0
2024-04-26T15:41:23.660988Z INFO kernel: [ 4234.212641] input input7: PM:
input_dev_resume+0x0/0x42 returned 0 after 1 usecs
2024-04-26T15:41:23.660989Z INFO kernel: [ 4234.217611] input input8: PM: calling
input_dev_resume+0x0/0x42 @ 24070, parent: card0
2024-04-26T15:41:23.660991Z INFO kernel: [ 4234.222018] usb 2-2: PM:
usb_dev_resume+0x0/0x14 returned 0 after 574149 usecs
2024-04-26T15:41:23.660993Z INFO kernel: [ 4234.222482] input input8: PM:
input_dev_resume+0x0/0x42 returned 0 after 1 usecs
2024-04-26T15:41:23.660995Z INFO kernel: [ 4234.222502] input input9: PM: calling
input_dev_resume+0x0/0x42 @ 24070, parent: card0
2024-04-26T15:41:23.661485Z INFO kernel: [ 4234.222510] input input9: PM:
input_dev_resume+0x0/0x42 returned 0 after 0 usecs
2024-04-26T15:41:23.661498Z INFO kernel: [ 4234.222518] input input10: PM: calling
input_dev_resume+0x0/0x42 @ 24070, parent: card0
2024-04-26T15:41:23.661501Z INFO kernel: [ 4234.222525] input input10: PM:
input_dev_resume+0x0/0x42 returned 0 after 0 usecs
2024-04-26T15:41:23.661503Z INFO kernel: [ 4234.248314] usb 2-2.1: PM: calling
usb_dev_resume+0x0/0x14 @ 24076, parent: 2-2
2024-04-26T15:41:23.661504Z INFO kernel: [ 4234.253345] usb 2-2.1: PM:
usb_dev_resume+0x0/0x14 returned 0 after 1 usecs
2024-04-26T15:41:23.661506Z INFO kernel: [ 4234.258653] rfkill rfkill0: PM: calling
rfkill_resume+0x0/0x69 @ 24070, parent: hci0
2024-04-26T15:41:23.662381Z INFO kernel: [ 4234.265795] rfkill rfkill0: PM:
rfkill_resume+0x0/0x69 returned 0 after 1781 usecs
2024-04-26T15:41:23.662393Z DEBUG kernel: [ 4234.271739] PM: resume of devices complete
after 1038.594 msecs
2024-04-26T15:41:23.662396Z DEBUG kernel: [ 4234.276534] PM: Finishing wakeup.
2024-04-26T15:41:23.662399Z INFO kernel: [ 4234.276543] OOM killer enabled.
2024-04-26T15:41:23.662402Z INFO kernel: [ 4234.278130] Restarting tasks ...
2024-04-26T15:41:23.662405Z INFO kernel: [ 4234.280641] usb 2-1: USB disconnect, device
number 2
2024-04-26T15:41:23.662408Z INFO kernel: [ 4234.286960] usb 2-2.1: USB disconnect, device
number 4
2024-04-26T15:41:23.645826Z INFO periodic_scheduler[3233]: cros-machine-id-regen: running
/usr/sbin/cros-machine-id-regen -r periodic -t 21600
2024-04-26T15:41:23.683050Z WARNING trunksd[753]: Received command CC 0x17a while
suspended.
2024-04-26T15:41:23.683168Z WARNING trunksd[753]: Auto-resuming Resource Manager.
2024-04-26T15:41:23.694955Z WARNING kernel: [ 4234.732498] done.
2024-04-26T15:41:23.700751Z INFO kernel: [ 4234.763738] Resume caused by IRQ 12, i8042
2024-04-26T15:41:23.700765Z INFO kernel: [ 4234.860503] PM: suspend exit
```

```
2024-04-26T15:41:23.700768Z INFO kernel: [ 4234.896487] usb 2-2.1: new full-speed USB
device number 5 using uhci_hcd
2024-04-26T15:41:23.700770Z INFO kernel: [ 4235.013828] usb 2-2.1: New USB device found,
idVendor=0e0f, idProduct=0008, bcdDevice= 1.00
2024-04-26T15:41:23.700772Z INFO kernel: [ 4235.017733] usb 2-2.1: New USB device
strings: Mfr=1, Product=2, SerialNumber=3
2024-04-26T15:41:23.700774Z INFO kernel: [ 4235.021424] usb 2-2.1: Product: Virtual
Bluetooth Adapter
2024-04-26T15:41:23.700776Z INFO kernel: [ 4235.024045] usb 2-2.1: Manufacturer: VMware
2024-04-26T15:41:23.700779Z INFO kernel: [ 4235.065913] usb 2-2.1: SerialNumber:
000650268328
2024-04-26T15:41:23.700780Z DEBUG kernel: [ 4235.100044] usb 2-2.1: GPIO lookup for
consumer reset
2024-04-26T15:41:23.700782Z DEBUG kernel: [ 4235.100271] usb 2-2.1: using lookup tables
for GPIO lookup
2024-04-26T15:41:23.700900Z DEBUG kernel: [ 4235.101341] usb 2-2.1: No GPIO consumer
reset found
2024-04-26T15:41:23.700906Z INFO kernel: [ 4235.109494] usb 2-1: new full-speed USB
device number 6 using uhci_hcd
2024-04-26T15:41:23.697953Z ERR missed[3476]: Failed to call method:
org.chromium.ChromeReportingServiceInterface.UploadEncryptedRecord: object_path=
/org/chromium/ChromeReportingService: org.freedesktop.DBus.Error.NoReply: Did not receive
a reply. Possible causes include: the remote application did not send a reply, the
message bus security policy blocked the reply, the reply timeout expired, or the network
connection was broken.
2024-04-26T15:41:23.745674Z INFO tpm_managerd[797]:
PeriodicResetDictionaryAttackCounterTask: DA reset succeeded.
2024-04-26T15:41:23.763572Z INFO periodic_scheduler[1221]: crash_sender: running
/sbin/crash_sender
2024-04-26T15:41:23.790200Z ERR dhcpcd[3848]: eth0: DHCP lease expired
2024-04-26T15:41:23.793351Z ERR /usr/bin/shill[877]: eth0: DHCP lease expired
2024-04-26T15:41:23.808841Z INFO kernel: [ 4235.262405] usb 2-1: New USB device found,
idVendor=0e0f, idProduct=0003, bcdDevice= 1.03
2024-04-26T15:41:23.808882Z INFO kernel: [ 4235.266221] usb 2-1: New USB device strings:
Mfr=1, Product=2, SerialNumber=0
2024-04-26T15:41:23.813556Z INFO kernel: [ 4235.269545] usb 2-1: Product: VMware Virtual
USB Mouse
2024-04-26T15:41:23.813605Z INFO kernel: [ 4235.272356] usb 2-1: Manufacturer: VMware
2024-04-26T15:41:23.881675Z INFO kernel: [ 4235.328213] input: VMware VMware Virtual USB
Mouse as /devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-1/2-
1:1.0/0003:0E0F:0003.0002/input/input11
2024-04-26T15:41:23.902175Z INFO kernel: [ 4235.346686] hid-generic 0003:0E0F:0003.0002:
input,hidraw0: USB HID v1.10 Mouse [VMware VMware Virtual USB Mouse] on usb-0000:02:00.0-
1/input0
2024-04-26T15:41:24.073838Z ERR kernel: [ 4235.528603] Bluetooth: hci0: unexpected cc
0xc12 length: 2 < 3
2024-04-26T15:41:24.073918Z ERR kernel: [ 4235.531352] Bluetooth: hci0: Opcode 0x c12
failed: -38
2024-04-26T15:41:24.337394Z NOTICE cros-machine-id-regen[24131]: Not regenerating since
we did so 4191 seconds ago.
2024-04-26T15:41:24.400016Z INFO periodic_scheduler[3233]: cros-machine-id-regen: job
completed
2024-04-26T15:41:24.525474Z NOTICE powerd_suspend[23983]: Resume finished
2024-04-26T15:41:24.550174Z WARNING kernel: [ 4235.992764] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:41:24.550206Z WARNING kernel: [ 4236.007881] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:41:24.550212Z WARNING kernel: [ 4236.008082] audit: audit_lost=39
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:41:24.558574Z WARNING kernel: [ 4236.015817] audit: audit_lost=40
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:41:24.560646Z ERR kernel: [ 4236.019366] audit: backlog limit exceeded
2024-04-26T15:41:24.624087Z ERR kernel: [ 4236.059171] audit: backlog limit exceeded
2024-04-26T15:41:24.718276Z WARNING secanomalyd[1296]: Bus::SendWithReplyAndBlock took
1048ms to process message: type=method_call, path=/org/chromium/SessionManager,
interface=org.chromium.SessionManagerInterface, member=RetrieveActiveSessions
2024-04-26T15:41:24.754479Z INFO crash_sender[24142]: Checking metadata: /run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/com_android_vending.20240426.143828.
46765.691683.meta
```

```
2024-04-26T15:41:24.755747Z INFO crash_sender[24142]: Removing: Not an official OS
version
2024-04-26T15:41:24.812120Z INFO crash_sender[24142]: Checking metadata: /run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/com_lionsden_gamemaster5.20240426.14
3828.97942.685596.meta
2024-04-26T15:41:24.812605Z INFO crash_sender[24142]: Removing: Not an official OS
version
2024-04-26T15:41:24.837681Z INFO crash_sender[24142]: Checking metadata: /run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/com_android_vending.20240426.143828.
36498.808935.meta
2024-04-26T15:41:24.838096Z INFO crash_sender[24142]: Removing: Not an official OS
version
2024-04-26T15:41:25.126712Z INFO periodic_scheduler[1221]: crash_sender: job completed
2024-04-26T15:41:25.400789Z ERR shill[837]: ERROR shill: [rtnl_message.cc(1103)] RTNL
address message does not have a valid IFA_ADDRESS
2024-04-26T15:41:26.808617Z INFO usb_bouncer[24226]: Reporting metrics for
/devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-1
2024-04-26T15:41:26.829055Z INFO usb_bouncer[24249]: Reporting metrics for
/devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-2/2-2.1
2024-04-26T15:41:27.025701Z NOTICE send_metrics_on_resume[24295]: Unable to get
firmware_resume_time
2024-04-26T15:41:29.596685Z NOTICE dbus-daemon[583]: [system] Rejected send message, 2
matched rules; type="method_return", sender=":1.41" (uid=1000 pid=1044
comm="/opt/google/chrome/chrome --enable-webgl-image-chr" label="u:r:cros_browser:s0")
interface="(unset)" member="(unset)" error name="(unset)" requested_reply="0"
destination=":1.102" (uid=20172 pid=3476 comm="/usr/bin/missived "
label="u:r:cros_missived:s0")
2024-04-26T15:41:30.962616Z INFO permission_broker[1266]:
ProcessPath(/dev/bus/usb/002/006)
2024-04-26T15:41:33.442514Z INFO permission_broker[1266]: AllowUsbDeviceRule: ALLOW
2024-04-26T15:41:33.442813Z INFO permission_broker[1266]: AllowTtyDeviceRule: IGNORE
2024-04-26T15:41:33.448988Z INFO permission_broker[1266]: Found claimed interface with
driver: usbhid
2024-04-26T15:41:33.473806Z INFO permission_broker[1266]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T15:41:33.474053Z INFO permission_broker[1266]: Verdict for
/dev/bus/usb/002/006: DENY
2024-04-26T15:41:33.474393Z INFO permission_broker[1266]:
ProcessPath(/dev/bus/usb/002/006)
2024-04-26T15:41:34.404002Z INFO permission_broker[1266]: AllowUsbDeviceRule: ALLOW
2024-04-26T15:41:34.404272Z INFO permission_broker[1266]: AllowTtyDeviceRule: IGNORE
2024-04-26T15:41:34.408812Z INFO permission_broker[1266]: Found claimed interface with
driver: usbhid
2024-04-26T15:41:34.413878Z INFO permission_broker[1266]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T15:41:34.414099Z INFO permission_broker[1266]: Verdict for
/dev/bus/usb/002/006: DENY
2024-04-26T15:41:34.414396Z INFO permission_broker[1266]:
ProcessPath(/dev/bus/usb/002/006)
2024-04-26T15:41:35.076486Z INFO vm_cicerone[4228]: System timezone changed, updating
container timezones
2024-04-26T15:41:35.504182Z INFO permission_broker[1266]: AllowUsbDeviceRule: ALLOW
2024-04-26T15:41:35.504642Z INFO permission_broker[1266]: AllowTtyDeviceRule: IGNORE
2024-04-26T15:41:35.509276Z INFO permission_broker[1266]: Found claimed interface with
driver: usbhid
2024-04-26T15:41:35.518089Z INFO permission_broker[1266]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T15:41:35.518511Z INFO permission_broker[1266]: Verdict for
/dev/bus/usb/002/006: DENY
2024-04-26T15:41:35.519921Z INFO permission_broker[1266]:
ProcessPath(/dev/bus/usb/002/005)
2024-04-26T15:41:36.385702Z INFO permission_broker[1266]: AllowUsbDeviceRule: ALLOW
2024-04-26T15:41:36.386138Z INFO permission_broker[1266]: AllowTtyDeviceRule: IGNORE
2024-04-26T15:41:36.391230Z INFO permission_broker[1266]: Found claimed interface with
driver: btusb
2024-04-26T15:41:36.403400Z INFO permission_broker[1266]: Found claimed interface with
driver: btusb
2024-04-26T15:41:36.407268Z INFO permission_broker[1266]: DenyClaimedUsbDeviceRule:
DENY
```



```
2024-04-26T15:41:36.407383Z INFO permission_broker[1266]: Verdict for
/dev/bus/usb/002/005: DENY
2024-04-26T15:41:36.407696Z INFO permission_broker[1266]:
ProcessPath(/dev/bus/usb/002/005)
2024-04-26T15:41:37.417626Z INFO permission_broker[1266]: AllowUsbDeviceRule: ALLOW
2024-04-26T15:41:37.417820Z INFO permission_broker[1266]: AllowTtyDeviceRule: IGNORE
2024-04-26T15:41:37.432860Z INFO permission_broker[1266]: Found claimed interface with
driver: btusb
2024-04-26T15:41:37.443691Z INFO permission_broker[1266]: Found claimed interface with
driver: btusb
2024-04-26T15:41:37.453182Z INFO permission_broker[1266]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T15:41:37.453363Z INFO permission_broker[1266]: Verdict for
/dev/bus/usb/002/005: DENY
2024-04-26T15:41:37.453630Z INFO permission_broker[1266]:
ProcessPath(/dev/bus/usb/002/005)
2024-04-26T15:41:38.031464Z ERR cross_healthd[1319]: Not implemented reached in void
diagnostics::UdevEventsImpl::OnHdmiChange()
2024-04-26T15:41:38.867199Z INFO permission_broker[1266]: AllowUsbDeviceRule: ALLOW
2024-04-26T15:41:38.867351Z INFO permission_broker[1266]: AllowTtyDeviceRule: IGNORE
2024-04-26T15:41:38.876329Z INFO permission_broker[1266]: Found claimed interface with
driver: btusb
2024-04-26T15:41:38.879339Z INFO permission_broker[1266]: Found claimed interface with
driver: btusb
2024-04-26T15:41:38.882775Z INFO permission_broker[1266]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T15:41:38.882963Z INFO permission_broker[1266]: Verdict for
/dev/bus/usb/002/005: DENY
2024-04-26T15:41:40.346063Z INFO minijail0[24394]: libminijail[24394]: applying policy
for default runtime: /etc/security/minijail/v0.bin
2024-04-26T15:41:40.359918Z ERR debugd[3650]: Problem waiting for pid 24394: No child
processes (10)
2024-04-26T15:41:40.361172Z ERR debugd[3650]: Unable to send signal to 24394: No such
process (3)
2024-04-26T15:41:42.112120Z ERR kernel: [ 4253.564526] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T15:41:42.122488Z ERR kernel: [ 4253.577320] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T15:41:42.129520Z ERR kernel: [ 4253.584477] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T15:41:43.838501Z ERR kernel: [ 4255.294730] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T15:41:43.948481Z ERR kernel: [ 4255.405528] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T15:41:44.772488Z ERR kernel: [ 4256.229557] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T15:41:44.834484Z ERR kernel: [ 4256.291015] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T15:41:47.046413Z INFO kernel: [ 4258.502012] binder: release 4934:5200
transaction 478321 out, still active
2024-04-26T15:41:47.046452Z INFO kernel: [ 4258.504971] binder: undelivered
TRANSACTION_COMPLETE
2024-04-26T15:41:47.197747Z INFO kernel: [ 4258.621241] binder: 4951:4951 transaction
failed 29189/-22, size 60-0 line 2893
2024-04-26T15:41:48.098747Z INFO kernel: [ 4259.548732] binder: 4951:5598 transaction
failed 29189/-22, size 60-0 line 2893
2024-04-26T15:41:48.411948Z ERR arc-kmsg-logger[3766]: init: failed to set pid 18647
ioprio=1,4: Operation not permitted
2024-04-26T15:41:48.457800Z ERR arc-kmsg-logger[3766]: init: failed to set pid 18649
ioprio=1,4: Operation not permitted
2024-04-26T15:41:48.471802Z ERR arc-kmsg-logger[3766]: init: couldn't write 18648 to
/dev/cpuset/camera-daemon/tasks: No such file or directory
2024-04-26T15:41:48.478621Z ERR arc-kmsg-logger[3766]: init: failed to set pid 18648
ioprio=1,4: Operation not permitted
2024-04-26T15:41:48.493278Z ERR arc-kmsg-logger[3766]: init: failed to set pid 18652
ioprio=1,4: Operation not permitted
2024-04-26T15:41:50.403411Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.camera.provider@2.4::ICameraProvider/external/0
2024-04-26T15:41:50.988337Z ERR arc-kmsg-logger[3766]: init: Could not find service
```

```
hosting interface android.hardware.audio@4.0::IDevicesFactory/default
2024-04-26T15:41:51.017589Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.audio@2.0::IDevicesFactory/msd
2024-04-26T15:41:51.018306Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.audio.effect@4.0::IEffectsFactory/default
2024-04-26T15:41:51.246178Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.audio.effect@4.0::IEffectsFactory/default
2024-04-26T15:41:57.201535Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.power@1.0::IPower/default
2024-04-26T15:42:07.409950Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.light@2.0::ILight/default
2024-04-26T15:42:13.988146Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.soundtrigger@2.0::ISoundTriggerHw/default
2024-04-26T15:42:13.993583Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.health@2.0::IHealth/default
2024-04-26T15:42:14.057727Z INFO kernel: [ 4285.512574] binder: release 4993:4993
transaction 478321 in, still active
2024-04-26T15:42:14.057801Z INFO kernel: [ 4285.515556] binder: send failed reply for
transaction 478321, target dead
2024-04-26T15:42:14.061512Z INFO kernel: [ 4285.518537] binder: release 4993:5195
transaction 484716 in, still active
2024-04-26T15:42:14.065504Z INFO kernel: [ 4285.522265] binder: send failed reply for
transaction 484716 to 24564:24624
2024-04-26T15:42:14.324737Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.vibrator@1.0::IVibrator/default
2024-04-26T15:42:14.328603Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.vibrator@1.0::IVibrator/default
2024-04-26T15:42:14.330504Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.vibrator@1.0::IVibrator/default
2024-04-26T15:42:14.331413Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.ir@1.0::IConsumerIr/default
2024-04-26T15:42:14.367373Z INFO iioservice[730]: INFO iioservice: [iio_sensor.cc(56)]
(2) Request(): Received SensorService from Mojo Service Manager
2024-04-26T15:42:14.380710Z INFO iioservice[730]: INFO iioservice:
[sensor_service_impl.cc(417)] (2) OnSensorServiceDisconnect(): SensorDevice disconnected.
ReceiverId: 5
2024-04-26T15:42:14.638974Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.vr@1.0::IVr/default
2024-04-26T15:42:14.924387Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.oemlock@1.0::IOemLock/default
2024-04-26T15:42:15.530874Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.thermal@1.0::IThermal/default
2024-04-26T15:42:15.592113Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.contexthub@1.0::IContexthub/default
2024-04-26T15:42:15.803057Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.weaver@1.0::IWeaver/default
2024-04-26T15:42:15.805200Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.authsecret@1.0::IAuthSecret/default
2024-04-26T15:42:16.980881Z INFO permission_broker[1266]:
ProcessPath(/dev/bus/usb/002/005)
2024-04-26T15:42:17.504171Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.gnss@1.1::IGnss/default
2024-04-26T15:42:17.509300Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.gnss@1.0::IGnss/default
2024-04-26T15:42:17.724037Z INFO permission_broker[1266]: AllowUsbDeviceRule: ALLOW
2024-04-26T15:42:17.724316Z INFO permission_broker[1266]: AllowTtyDeviceRule: IGNORE
2024-04-26T15:42:17.728685Z INFO permission_broker[1266]: Found claimed interface with
driver: btusb
2024-04-26T15:42:17.731153Z INFO permission_broker[1266]: Found claimed interface with
driver: btusb
2024-04-26T15:42:17.732700Z INFO permission_broker[1266]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T15:42:17.732955Z INFO permission_broker[1266]: Verdict for
/dev/bus/usb/002/005: DENY
2024-04-26T15:42:17.733252Z INFO permission_broker[1266]:
ProcessPath(/dev/bus/usb/002/006)
2024-04-26T15:42:18.270083Z INFO permission_broker[1266]: AllowUsbDeviceRule: ALLOW
2024-04-26T15:42:18.270317Z INFO permission_broker[1266]: AllowTtyDeviceRule: IGNORE
2024-04-26T15:42:18.277196Z INFO permission_broker[1266]: Found claimed interface with
```


```
driver: usbhid
2024-04-26T15:42:18.283722Z INFO permission_broker[1266]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T15:42:18.284011Z INFO permission_broker[1266]: Verdict for
/dev/bus/usb/002/006: DENY
2024-04-26T15:42:18.894805Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface hardware.google.media.c2@1.0::IComponentStore/software
2024-04-26T15:42:21.076207Z INFO session_manager[987]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting arc-booted Upstart signal
2024-04-26T15:42:21.264949Z INFO minijail0[24945]: libminijail[24945]: applying policy
for default runtime: /etc/security/minijail/v0.bin
2024-04-26T15:42:21.267396Z WARNING minijail0[24945]: libminijail[24945]: failed to
create a ruleset: Function not implemented
2024-04-26T15:42:21.267412Z WARNING minijail0[24945]: libminijail[24945]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T15:42:21.270667Z WARNING minijail0[24954]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T15:42:21.271079Z WARNING minijail0[24954]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T15:42:21.271162Z INFO minijail0[24954]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T15:42:23.564333Z WARNING kernel: [ 4295.014471] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:42:23.564368Z WARNING kernel: [ 4295.017560] audit: audit_lost=41
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:42:23.564373Z ERR kernel: [ 4295.020756] audit: backlog limit exceeded
2024-04-26T15:42:23.564379Z WARNING kernel: [ 4295.024495] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:42:23.659552Z WARNING kernel: [ 4295.032487] audit: audit_lost=42
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:42:23.659599Z ERR kernel: [ 4295.036251] audit: backlog limit exceeded
2024-04-26T15:42:23.659604Z WARNING kernel: [ 4295.038351] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:42:23.659607Z WARNING kernel: [ 4295.041288] audit: audit_lost=43
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:42:23.659610Z ERR kernel: [ 4295.101479] audit: backlog limit exceeded
2024-04-26T15:42:26.229774Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.secure_element@1.0::ISecureElement/eSE1
2024-04-26T15:42:26.230901Z ERR arc-kmsg-logger[3766]: init: Could not find service
hosting interface android.hardware.secure_element@1.0::ISecureElement/SIM1
2024-04-26T15:42:29.863888Z WARNING kernel: [ 4301.270000] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:42:29.863970Z WARNING kernel: [ 4301.320805] audit: audit_lost=44
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:42:29.866094Z ERR kernel: [ 4301.324874] audit: backlog limit exceeded
2024-04-26T15:42:37.022133Z INFO vm_cicerone[4228]: System timezone changed, updating
container timezones
2024-04-26T15:42:48.737663Z INFO kernel: [ 4320.181929] binder_alloc: 25608:
binder_alloc_buf, no vma
2024-04-26T15:42:48.737700Z INFO kernel: [ 4320.184718] binder: 24564:24586 transaction
failed 29189/-3, size 1728-8 line 3061
2024-04-26T15:42:49.983137Z WARNING kernel: [ 4321.431224] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:42:49.983175Z WARNING kernel: [ 4321.433861] audit: audit_lost=45
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:42:49.983180Z WARNING kernel: [ 4321.434314] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:42:50.145724Z WARNING kernel: [ 4321.448808] audit: audit_lost=46
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:42:50.171339Z ERR kernel: [ 4321.467431] audit: backlog limit exceeded
2024-04-26T15:42:50.171357Z ERR kernel: [ 4321.595986] audit: backlog limit exceeded
2024-04-26T15:43:03.678717Z INFO kernel: [ 4335.128809] binder_alloc: 25809:
binder_alloc_buf, no vma
2024-04-26T15:43:03.678756Z INFO kernel: [ 4335.136098] binder: 24564:25595 transaction
failed 29189/-3, size 76-0 line 3061
2024-04-26T15:43:19.835851Z WARNING kernel: [ 4351.261887] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:43:19.835883Z WARNING kernel: [ 4351.290389] audit: audit_lost=47
audit_rate_limit=0 audit_backlog_limit=64
```

```
2024-04-26T15:43:19.835887Z ERR kernel: [ 4351.293376] audit: backlog limit exceeded
2024-04-26T15:43:23.515889Z INFO kernel: [ 4354.970477] binder_alloc: 26265:
binder_alloc_buf, no vma
2024-04-26T15:43:23.515920Z INFO kernel: [ 4354.973418] binder: 24564:24586 transaction
failed 29189/-3, size 76-0 line 3061
2024-04-26T15:43:40.545227Z WARNING kernel: [ 4371.994687] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:43:40.545261Z WARNING kernel: [ 4372.000267] audit: audit_lost=48
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:43:40.545267Z ERR kernel: [ 4372.007432] audit: backlog limit exceeded
2024-04-26T15:43:49.844702Z WARNING kernel: [ 4381.294486] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:43:49.845074Z WARNING kernel: [ 4381.299118] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:43:49.845090Z WARNING kernel: [ 4381.302837] audit: audit_lost=49
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:43:49.845092Z ERR kernel: [ 4381.305631] audit: backlog limit exceeded
2024-04-26T15:43:49.870190Z WARNING kernel: [ 4381.328909] audit: audit_lost=50
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:43:49.870220Z ERR kernel: [ 4381.333179] audit: backlog limit exceeded
2024-04-26T15:44:09.941490Z WARNING kernel: [ 4401.398379] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:44:09.941543Z WARNING kernel: [ 4401.401394] audit: audit_lost=51
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:44:09.947175Z ERR kernel: [ 4401.408101] audit: backlog limit exceeded
2024-04-26T15:44:13.119493Z INFO kernel: [ 4404.548201] binder_alloc: 24992:
binder_alloc_buf size 1056768 failed, no address space
2024-04-26T15:44:13.119528Z INFO kernel: [ 4404.580639] binder_alloc: allocated: 11312
(num: 17 largest: 3920), free: 1029072 (num: 9 largest: 1024352)
2024-04-26T15:44:13.128806Z INFO kernel: [ 4404.590528] binder: 25257:27497 transaction
failed 29201/-28, size 1056768-0 line 3061
2024-04-26T15:44:17.998862Z INFO crash_reporter[27788]: developer build - not testing -
always dumping
2024-04-26T15:44:18.182394Z WARNING crash_reporter[27788]: [ARC_java] Received
system_server_watchdog notification for system_server (handling)
2024-04-26T15:44:18.191879Z INFO crash_reporter[27788]: Accessing crash dir '/run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65' via symlinked handle
'/proc/self/fd/10'
2024-04-26T15:44:18.305799Z INFO crash_reporter[27788]: Finishing crash. Meta file:
/proc/self/fd/10/system_server.20240426.154418.81752.553004.meta
2024-04-26T15:44:19.793379Z WARNING kernel: [ 4411.230646] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:44:19.793410Z WARNING kernel: [ 4411.234854] audit: audit_lost=52
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:44:19.793417Z ERR kernel: [ 4411.256172] audit: backlog limit exceeded
2024-04-26T15:44:31.251920Z WARNING kernel: [ 4422.630809] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:44:31.251970Z WARNING kernel: [ 4422.665414] audit: audit_lost=53
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:44:31.251976Z ERR kernel: [ 4422.700637] audit: backlog limit exceeded
2024-04-26T15:44:31.389596Z WARNING kernel: [ 4422.810357] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:44:31.389631Z WARNING kernel: [ 4422.816320] audit: audit_lost=54
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:44:31.389637Z ERR kernel: [ 4422.820986] audit: backlog limit exceeded
2024-04-26T15:44:31.389642Z WARNING kernel: [ 4422.823943] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:44:31.389649Z WARNING kernel: [ 4422.838640] audit: audit_lost=55
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:44:31.389652Z ERR kernel: [ 4422.851392] audit: backlog limit exceeded
2024-04-26T15:44:31.389655Z WARNING kernel: [ 4422.853577] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:44:36.282385Z INFO kernel: [ 4427.706703] binder: 4918:4918 transaction
failed 29189/-22, size 140-0 line 2893
2024-04-26T15:44:39.137105Z ERR cros_healthd[1319]: Not implemented reached in void
diagnostics::UdevEventsImpl::OnHdmiChange()
2024-04-26T15:44:49.855160Z INFO kernel: [ 4441.313500] binder_alloc: 28248:
binder_alloc_buf, no vma
2024-04-26T15:44:49.855194Z INFO kernel: [ 4441.315691] binder: 24564:24586 transaction
```

```

failed 29189/-3, size 76-0 line 3061
2024-04-26T15:45:02.175673Z ERR kernel: [ 4453.636350] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T15:45:02.302227Z ERR kernel: [ 4453.753764] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T15:45:03.666627Z ERR kernel: [ 4455.125295] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T15:45:19.664633Z WARNING kernel: [ 4471.130098] audit_log_start: 2 callbacks
suppressed
2024-04-26T15:45:19.664673Z WARNING kernel: [ 4471.130102] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:45:19.668892Z WARNING kernel: [ 4471.132788] audit: audit_lost=57
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:45:19.668968Z ERR kernel: [ 4471.135568] audit: backlog limit exceeded
2024-04-26T15:45:23.328460Z WARNING kernel: [ 4474.789648] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:45:23.328486Z WARNING kernel: [ 4474.792763] audit: audit_lost=58
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:45:23.328491Z ERR kernel: [ 4474.794952] audit: backlog limit exceeded
2024-04-26T15:45:54.948246Z WARNING kernel: [ 4506.408408] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:45:54.948283Z WARNING kernel: [ 4506.411625] audit: audit_lost=59
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:45:54.961345Z ERR kernel: [ 4506.415341] audit: backlog limit exceeded
2024-04-26T15:45:55.052759Z WARNING kernel: [ 4506.506196] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:45:55.052791Z WARNING kernel: [ 4506.511378] audit: audit_lost=60
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:45:55.058768Z ERR kernel: [ 4506.523366] audit: backlog limit exceeded
2024-04-26T15:46:00.221150Z WARNING kernel: [ 4511.672290] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:46:00.221180Z WARNING kernel: [ 4511.684664] audit: audit_lost=61
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:46:00.223014Z ERR kernel: [ 4511.687913] audit: backlog limit exceeded
2024-04-26T15:46:51.063552Z NOTICE auditd[458]: Audit daemon rotating log files
2024-04-26T15:47:54.912872Z WARNING kernel: [ 4626.375229] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:47:54.912940Z WARNING kernel: [ 4626.376740] audit: audit_lost=62
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:47:54.912945Z ERR kernel: [ 4626.378621] audit: backlog limit exceeded
2024-04-26T15:49:22.975610Z INFO vm_cicerone[4228]: System timezone changed, updating
container timezones
2024-04-26T15:51:21.233479Z INFO kernel: [ 4832.694551] binder_alloc: 31355:
binder_alloc_buf, no vma
2024-04-26T15:51:21.233679Z INFO kernel: [ 4832.699054] binder: 24564:24586 transaction
failed 29189/-3, size 76-0 line 3061
2024-04-26T15:51:24.450621Z WARNING kernel: [ 4835.895179] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:51:24.450662Z WARNING kernel: [ 4835.899294] audit: audit_lost=63
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:51:24.472080Z ERR kernel: [ 4835.921736] audit: backlog limit exceeded
2024-04-26T15:51:30.215819Z WARNING kernel: [ 4841.673558] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T15:51:30.215916Z WARNING kernel: [ 4841.679557] audit: audit_lost=64
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T15:51:30.217890Z ERR kernel: [ 4841.682638] audit: backlog limit exceeded
2024-04-26T15:53:14.659201Z INFO trunksd[753]: Finished saving contexts.
2024-04-26T15:53:37.024877Z NOTICE powerd_suspend[32198]: Going to suspend-to-RAM state:
args=--nosuspend_to_idle --wakeup_count=47945
2024-04-26T15:53:37.629175Z NOTICE powerd_suspend[32198]: Available order 3 pages: 32869
2024-04-26T15:53:37.641376Z NOTICE powerd_suspend[32198]: Finalizing suspend

```



```
2024-04-26T16:01:06.380899Z NOTICE kernel: [
0.000000] Linux version 5.15.108-18907-gba143be42d3a-dirty (builty@fydebeast) (Chromium
OS 16.0_pre484197_p20230405-r7 clang version 16.0.0 (/var/tmp/portage/sys-devel/llvm-
16.0_pre484197_p20230405-r7/work/llvm-16.0_pre484197_p20230405/clang
2916b99182752b1aece8cc4479d8d6a20b5e02da), LLD 16.0.0) #1 SMP PREEMPT Mon Jul 31 23:34:32
CST 2023
2024-04-26T16:01:06.403183Z INFO kernel: [ 0.000000] Command line:
BOOT_IMAGE=/syslinux/vmlinuz.A init=/sbin/init boot=local rootwait ro noresume noswap
loglevel=7 noinitrd earlyprintk=ttyS0,115200 console=ttyS0,115200 i915.modeset=1 cros_efi
cros_debug root=PARTUUID=5C728CA9-A521-2846-A29C-35E25A13FB4C
2024-04-26T16:01:06.403196Z INFO kernel: [ 0.000000] KERNEL supported cpus:
2024-04-26T16:01:06.403200Z INFO kernel: [ 0.000000] Intel GenuineIntel
2024-04-26T16:01:06.403204Z INFO kernel: [ 0.000000] Disabled fast string operations
2024-04-26T16:01:06.403207Z INFO kernel: [ 0.000000] x86/fpu: Supporting XSAVE feature
0x001: 'x87 floating point registers'
2024-04-26T16:01:06.419820Z INFO kernel: [ 0.000000] x86/fpu: Supporting XSAVE feature
0x002: 'SSE registers'
2024-04-26T16:01:06.419838Z INFO kernel: [ 0.000000] x86/fpu: Supporting XSAVE feature
0x004: 'AVX registers'
2024-04-26T16:01:06.419842Z INFO kernel: [ 0.000000] x86/fpu: xstate_offset[2]: 576,
xstate_sizes[2]: 256
2024-04-26T16:01:06.419846Z INFO kernel: [ 0.000000] x86/fpu: Enabled xstate features
```

```
0x7, context size is 832 bytes, using 'compact' format.
2024-04-26T16:01:06.419848Z INFO kernel: [ 0.000000] signal: max sigframe size: 1776
2024-04-26T16:01:06.419850Z INFO kernel: [ 0.000000] BIOS-provided physical RAM map:
2024-04-26T16:01:06.419857Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000000000-0x0000000000000fff] ACPI NVS
2024-04-26T16:01:06.419860Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000001000-0x000000000001ffff] reserved
2024-04-26T16:01:06.419864Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x000000000002000-0x000000000009ffff] usable
2024-04-26T16:01:06.419866Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x00000000000c0000-0x00000000000fffff] reserved
2024-04-26T16:01:06.419868Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000100000-0x0000000000e5e7ffff] usable
2024-04-26T16:01:06.419869Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000e5e8000-0x0000000000e604ffff] ACPI data
2024-04-26T16:01:06.419871Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000e605000-0x0000000000ef99ffff] usable
2024-04-26T16:01:06.419876Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000ef9a000-0x0000000000ef9dffff] type 20
2024-04-26T16:01:06.419878Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000ef9e000-0x0000000000efacffff] usable
2024-04-26T16:01:06.419880Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000efad000-0x0000000000efb1ffff] type 20
2024-04-26T16:01:06.419882Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000efb2000-0x0000000000efb6ffff] ACPI NVS
2024-04-26T16:01:06.419884Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000efb7000-0x0000000000fee4ffff] usable
2024-04-26T16:01:06.419886Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000fee5000-0x0000000000ff04ffff] type 20
2024-04-26T16:01:06.419892Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000ff05000-0x0000000000ff54ffff] reserved
2024-04-26T16:01:06.419894Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000ff55000-0x0000000000ff73ffff] usable
2024-04-26T16:01:06.419896Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000ff74000-0x0000000000ff74ffff] ACPI NVS
2024-04-26T16:01:06.419898Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000ff75000-0x000000000bfffffff] usable
2024-04-26T16:01:06.419899Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x0000000000ffc00000-0x0000000000ffc29ffff] reserved
2024-04-26T16:01:06.419901Z INFO kernel: [ 0.000000] BIOS-e820: [mem
0x00000000100000000-0x000000001c9bfffffff] usable
2024-04-26T16:01:06.419903Z INFO kernel: [ 0.000000] printk: bootconsole [earlyser0]
enabled
2024-04-26T16:01:06.419908Z INFO kernel: [ 0.000000] NX (Execute Disable) protection:
active
2024-04-26T16:01:06.419910Z INFO kernel: [ 0.000000] efi: EFI v2.40 by VMware, Inc.
2024-04-26T16:01:06.419912Z INFO kernel: [ 0.000000] efi: SMBIOS=0xefb2000 ACPI
2.0=0xe5e8000 MEMATTR=0xe624198
2024-04-26T16:01:06.419914Z INFO kernel: [ 0.000000] SMBIOS 2.7 present.
2024-04-26T16:01:06.419916Z INFO kernel: [ 0.000000] DMI: VMware, Inc. VMware7,1/440BX
Desktop Reference Platform, BIOS VMW71.00V.21805430.B64.2305221826 05/22/2023
2024-04-26T16:01:06.419918Z INFO kernel: [ 0.000000] vmware: hypercall mode: 0x00
2024-04-26T16:01:06.419923Z INFO kernel: [ 0.000000] Hypervisor detected: VMware
2024-04-26T16:01:06.419927Z INFO kernel: [ 0.000000] vmware: TSC freq read from
hypervisor : 1607.999 MHz
2024-04-26T16:01:06.419930Z INFO kernel: [ 0.000000] vmware: Host bus clock speed read
from hypervisor : 66000000 Hz
2024-04-26T16:01:06.419933Z INFO kernel: [ 0.000000] vmware: using clock offset of
14095001545 ns
2024-04-26T16:01:06.419936Z INFO kernel: [ 0.007757] tsc: Detected 1607.999 MHz
processor
2024-04-26T16:01:06.419939Z DEBUG kernel: [ 1.807386] e820: update [mem 0x00000000-
0x000000fff] usable ==> reserved
2024-04-26T16:01:06.419944Z DEBUG kernel: [ 1.807435] e820: remove [mem 0x000a0000-
0x000fffff] usable
2024-04-26T16:01:06.419948Z INFO kernel: [ 1.807469] last_pfn = 0x1c9c00 max_arch_pfn
= 0x400000000
2024-04-26T16:01:06.419951Z INFO kernel: [ 1.808629] x86/PAT: Configuration [0-7]: WB
WC UC- UC WB WP UC- WT
```

```
2024-04-26T16:01:06.419954Z DEBUG kernel: [ 1.809993] e820: update [mem 0xc0000000-0xffffffff] usable ==> reserved
2024-04-26T16:01:06.419957Z INFO kernel: [ 1.810699] last_pfn = 0xc0000 max_arch_pfn = 0x400000000
2024-04-26T16:01:06.419960Z INFO kernel: [ 1.860794] Using GB pages for direct mapping
2024-04-26T16:01:06.419963Z INFO kernel: [ 1.862083] Secure boot disabled
2024-04-26T16:01:06.419970Z INFO kernel: [ 1.862732] ACPI: Early table checksum verification disabled
2024-04-26T16:01:06.419973Z INFO kernel: [ 1.897225] ACPI: RSDP 0x0000000000E5E800000024 (v02 VMWARE)
2024-04-26T16:01:06.419977Z INFO kernel: [ 1.898388] ACPI: XSDT 0x0000000000E5E806400005C (v01 INTEL 440BX 06040000 VMW 01324272)
2024-04-26T16:01:06.419980Z INFO kernel: [ 1.900103] ACPI: SRAT 0x0000000000E5E80C00008D0 (v03 VMWARE EFISRAT 06040001 VMW 000007CE)
2024-04-26T16:01:06.403000Z WARNING rsyslogd[468]: warning: ~ action is deprecated, consider using the 'stop' statement instead [v8.2112.0 try https://www.rsyslog.com/e/2307]
2024-04-26T16:01:06.419984Z INFO kernel: [ 1.902004] ACPI: FACP 0x0000000000E603BF80000F4 (v04 INTEL 440BX 06040000 PTL 000F4240)
2024-04-26T16:01:06.420077Z INFO kernel: [ 1.903947] ACPI: DSDT 0x0000000000E5E899001B268 (v01 PTLTD Custom 00000000 INTL 20130823)
2024-04-26T16:01:06.420088Z INFO kernel: [ 1.905679] ACPI: FACS 0x0000000000FF7400000040
2024-04-26T16:01:06.420168Z INFO kernel: [ 1.906619] ACPI: FACS 0x0000000000FF7400000040
2024-04-26T16:01:06.420171Z INFO kernel: [ 1.907593] ACPI: APIC 0x0000000000E604000000742 (v03 VMWARE EFIAPIC 06040001 VMW 000007CE)
2024-04-26T16:01:06.420173Z INFO kernel: [ 1.909307] ACPI: MCFG 0x0000000000E60474200003C (v01 VMWARE EFIMCFG 06040001 VMW 000007CE)
2024-04-26T16:01:06.420174Z INFO kernel: [ 1.911056] ACPI: HPET 0x0000000000E60477E000038 (v01 VMWARE VMW HPET 00000000 VMW 00000000)
2024-04-26T16:01:06.420176Z INFO kernel: [ 1.912787] ACPI: WAET 0x0000000000E6047B6000028 (v01 VMWARE VMW WAET 06040001 VMW 00000001)
2024-04-26T16:01:06.420182Z INFO kernel: [ 1.947878] ACPI: WSMT 0x0000000000E6047DE000028 (v01 VMWARE VMW WSMT 06040001 VMW 00000001)
2024-04-26T16:01:06.420185Z INFO kernel: [ 1.949601] ACPI: Reserving SRAT table memory at [mem 0xe5e80c0-0xe5e898f]
2024-04-26T16:01:06.420188Z INFO kernel: [ 1.951078] ACPI: Reserving FACP table memory at [mem 0xe603bf8-0xe603ceb]
2024-04-26T16:01:06.420192Z INFO kernel: [ 1.952449] ACPI: Reserving DSDT table memory at [mem 0xe5e8990-0xe603bf7]
2024-04-26T16:01:06.420196Z INFO kernel: [ 1.953808] ACPI: Reserving FACS table memory at [mem 0xff74000-0xff7403f]
2024-04-26T16:01:06.403055Z WARNING rsyslogd[468]: warning: ~ action is deprecated, consider using the 'stop' statement instead [v8.2112.0 try https://www.rsyslog.com/e/2307]
2024-04-26T16:01:06.403063Z INFO rsyslogd[468]: rsyslogd's groupid changed to 202
2024-04-26T16:01:06.420205Z INFO kernel: [ 1.955171] ACPI: Reserving FACS table memory at [mem 0xff74000-0xff7403f]
2024-04-26T16:01:06.420211Z INFO kernel: [ 1.956529] ACPI: Reserving APIC table memory at [mem 0xe604000-0xe604741]
2024-04-26T16:01:06.420218Z INFO kernel: [ 1.957885] ACPI: Reserving MCFG table memory at [mem 0xe604742-0xe60477d]
2024-04-26T16:01:06.403074Z INFO rsyslogd[468]: rsyslogd's userid changed to 202
2024-04-26T16:01:06.420225Z INFO kernel: [ 1.959246] ACPI: Reserving HPET table memory at [mem 0xe60477e-0xe6047b5]
2024-04-26T16:01:06.420232Z INFO kernel: [ 1.960603] ACPI: Reserving WAET table memory at [mem 0xe6047b6-0xe6047dd]
2024-04-26T16:01:06.420235Z INFO kernel: [ 1.961965] ACPI: Reserving WSMT table memory at [mem 0xe6047de-0xe604805]
2024-04-26T16:01:06.420240Z DEBUG kernel: [ 1.963386] system APIC only can use physical flat
2024-04-26T16:01:06.420242Z INFO kernel: [ 1.963396] Setting APIC routing to physical flat.
2024-04-26T16:01:06.403084Z INFO rsyslogd[468]: [origin software="rsyslogd" swVersion="8.2112.0" x-pid="468" x-info="https://www.rsyslog.com"] start
2024-04-26T16:01:06.420253Z INFO kernel: [ 1.998524] Zone ranges:
2024-04-26T16:01:06.420284Z INFO kernel: [ 1.999040] DMA [mem 0x0000000000002000-0x0000000000ffffff]
```



```

2024-04-26T16:01:06.420318Z INFO kernel: [ 2.000286] DMA32 [mem
0x0000000001000000-0x00000000ffffffff]
2024-04-26T16:01:06.420322Z INFO kernel: [ 2.001540] Normal [mem
0x0000000010000000-0x00000001c9bfffffff]
2024-04-26T16:01:06.420326Z INFO kernel: [ 2.002776] Movable zone start for each node
2024-04-26T16:01:06.420328Z INFO kernel: [ 2.003657] Early memory node ranges
2024-04-26T16:01:06.420331Z INFO kernel: [ 2.004367] node 0: [mem
0x0000000000000200-0x0000000000009ffff]
2024-04-26T16:01:06.420341Z INFO kernel: [ 2.005605] node 0: [mem
0x0000000000100000-0x0000000000e5e7fff]
2024-04-26T16:01:06.420345Z INFO kernel: [ 2.006840] node 0: [mem
0x0000000000e605000-0x0000000000ef99fff]
2024-04-26T16:01:06.420352Z INFO kernel: [ 2.008076] node 0: [mem
0x0000000000ef9e000-0x0000000000efacfff]
2024-04-26T16:01:06.420356Z INFO kernel: [ 2.009325] node 0: [mem
0x0000000000efb7000-0x0000000000fee4fff]
2024-04-26T16:01:06.420359Z INFO kernel: [ 2.010561] node 0: [mem
0x0000000000ff55000-0x0000000000ff73fff]
2024-04-26T16:01:06.420361Z INFO kernel: [ 2.011801] node 0: [mem
0x0000000000ff75000-0x000000000bfffffff]
2024-04-26T16:01:06.420369Z INFO kernel: [ 2.013050] node 0: [mem
0x00000000100000000-0x00000001c9bfffffff]
2024-04-26T16:01:06.420373Z INFO kernel: [ 2.047655] Initmem setup node 0 [mem
0x00000000000002000-0x00000001c9bfffffff]
2024-04-26T16:01:06.420374Z INFO kernel: [ 2.049557] On node 0, zone DMA: 2 pages in
unavailable ranges
2024-04-26T16:01:06.420376Z INFO kernel: [ 2.055929] On node 0, zone DMA: 96 pages in
unavailable ranges
2024-04-26T16:01:06.420378Z INFO kernel: [ 2.153403] On node 0, zone DMA32: 29 pages
in unavailable ranges
2024-04-26T16:01:06.420381Z INFO kernel: [ 2.154613] On node 0, zone DMA32: 4 pages in
unavailable ranges
2024-04-26T16:01:06.420388Z INFO kernel: [ 2.161315] On node 0, zone DMA32: 10 pages
in unavailable ranges
2024-04-26T16:01:06.420391Z INFO kernel: [ 2.163145] On node 0, zone DMA32: 112 pages
in unavailable ranges
2024-04-26T16:01:06.420392Z INFO kernel: [ 3.807570] On node 0, zone DMA32: 1 pages in
unavailable ranges
2024-04-26T16:01:06.420394Z INFO kernel: [ 5.252732] On node 0, zone Normal: 25600
pages in unavailable ranges
2024-04-26T16:01:06.420396Z INFO kernel: [ 5.299216] ACPI: PM-Timer IO Port: 0x448
2024-04-26T16:01:06.420397Z DEBUG kernel: [ 5.301201] system APIC only can use
physical flat
2024-04-26T16:01:06.420401Z INFO kernel: [ 5.301223] ACPI: LAPIC_NMI (acpi_id[0x00]
high edge lint[0x1])
2024-04-26T16:01:06.420406Z INFO kernel: [ 5.302351] ACPI: LAPIC_NMI (acpi_id[0x01]
high edge lint[0x1])
2024-04-26T16:01:06.420408Z INFO kernel: [ 5.303474] ACPI: LAPIC_NMI (acpi_id[0x02]
high edge lint[0x1])
2024-04-26T16:01:06.420554Z INFO kernel: [ 5.304597] ACPI: LAPIC_NMI (acpi_id[0x03]
high edge lint[0x1])
2024-04-26T16:01:06.420557Z INFO kernel: [ 5.305718] ACPI: LAPIC_NMI (acpi_id[0x04]
high edge lint[0x1])
2024-04-26T16:01:06.420559Z INFO kernel: [ 5.306845] ACPI: LAPIC_NMI (acpi_id[0x05]
high edge lint[0x1])
2024-04-26T16:01:06.420561Z INFO kernel: [ 5.307967] ACPI: LAPIC_NMI (acpi_id[0x06]
high edge lint[0x1])
2024-04-26T16:01:06.420566Z INFO kernel: [ 5.309464] ACPI: LAPIC_NMI (acpi_id[0x07]
high edge lint[0x1])
2024-04-26T16:01:06.420569Z INFO kernel: [ 5.310742] ACPI: LAPIC_NMI (acpi_id[0x08]
high edge lint[0x1])
2024-04-26T16:01:06.420571Z INFO kernel: [ 5.312149] ACPI: LAPIC_NMI (acpi_id[0x09]
high edge lint[0x1])
2024-04-26T16:01:06.420572Z INFO kernel: [ 5.313272] ACPI: LAPIC_NMI (acpi_id[0x0a]
high edge lint[0x1])
2024-04-26T16:01:06.420574Z INFO kernel: [ 5.347820] ACPI: LAPIC_NMI (acpi_id[0x0b]
high edge lint[0x1])
2024-04-26T16:01:06.420576Z INFO kernel: [ 5.348963] ACPI: LAPIC_NMI (acpi_id[0x0c]
high edge lint[0x1])

```

```
2024-04-26T16:01:06.420578Z INFO kernel: [ 5.350093] ACPI: LAPIC_NMI (acpi_id[0x0d]
high edge lint[0x1])
2024-04-26T16:01:06.420584Z INFO kernel: [ 5.351223] ACPI: LAPIC_NMI (acpi_id[0x0e]
high edge lint[0x1])
2024-04-26T16:01:06.420586Z INFO kernel: [ 5.352358] ACPI: LAPIC_NMI (acpi_id[0x0f]
high edge lint[0x1])
2024-04-26T16:01:06.420588Z INFO kernel: [ 5.353487] ACPI: LAPIC_NMI (acpi_id[0x10]
high edge lint[0x1])
2024-04-26T16:01:06.420616Z INFO kernel: [ 5.354616] ACPI: LAPIC_NMI (acpi_id[0x11]
high edge lint[0x1])
2024-04-26T16:01:06.420618Z INFO kernel: [ 5.355769] ACPI: LAPIC_NMI (acpi_id[0x12]
high edge lint[0x1])
2024-04-26T16:01:06.420620Z INFO kernel: [ 5.356942] ACPI: LAPIC_NMI (acpi_id[0x13]
high edge lint[0x1])
2024-04-26T16:01:06.420627Z INFO kernel: [ 5.358097] ACPI: LAPIC_NMI (acpi_id[0x14]
high edge lint[0x1])
2024-04-26T16:01:06.420629Z INFO kernel: [ 5.359235] ACPI: LAPIC_NMI (acpi_id[0x15]
high edge lint[0x1])
2024-04-26T16:01:06.420631Z INFO kernel: [ 5.360369] ACPI: LAPIC_NMI (acpi_id[0x16]
high edge lint[0x1])
2024-04-26T16:01:06.420658Z INFO kernel: [ 5.361513] ACPI: LAPIC_NMI (acpi_id[0x17]
high edge lint[0x1])
2024-04-26T16:01:06.420660Z INFO kernel: [ 5.362645] ACPI: LAPIC_NMI (acpi_id[0x18]
high edge lint[0x1])
2024-04-26T16:01:06.420661Z INFO kernel: [ 5.363768] ACPI: LAPIC_NMI (acpi_id[0x19]
high edge lint[0x1])
2024-04-26T16:01:06.420668Z INFO kernel: [ 5.398287] ACPI: LAPIC_NMI (acpi_id[0x1a]
high edge lint[0x1])
2024-04-26T16:01:06.420673Z INFO kernel: [ 5.399422] ACPI: LAPIC_NMI (acpi_id[0x1b]
high edge lint[0x1])
2024-04-26T16:01:06.420677Z INFO kernel: [ 5.400554] ACPI: LAPIC_NMI (acpi_id[0x1c]
high edge lint[0x1])
2024-04-26T16:01:06.420679Z INFO kernel: [ 5.401685] ACPI: LAPIC_NMI (acpi_id[0x1d]
high edge lint[0x1])
2024-04-26T16:01:06.420681Z INFO kernel: [ 5.402816] ACPI: LAPIC_NMI (acpi_id[0x1e]
high edge lint[0x1])
2024-04-26T16:01:06.420683Z INFO kernel: [ 5.403945] ACPI: LAPIC_NMI (acpi_id[0x1f]
high edge lint[0x1])
2024-04-26T16:01:06.420686Z INFO kernel: [ 5.405076] ACPI: LAPIC_NMI (acpi_id[0x20]
high edge lint[0x1])
2024-04-26T16:01:06.420692Z INFO kernel: [ 5.406206] ACPI: LAPIC_NMI (acpi_id[0x21]
high edge lint[0x1])
2024-04-26T16:01:06.420694Z INFO kernel: [ 5.407781] ACPI: LAPIC_NMI (acpi_id[0x22]
high edge lint[0x1])
2024-04-26T16:01:06.420696Z INFO kernel: [ 5.408917] ACPI: LAPIC_NMI (acpi_id[0x23]
high edge lint[0x1])
2024-04-26T16:01:06.420698Z INFO kernel: [ 5.410049] ACPI: LAPIC_NMI (acpi_id[0x24]
high edge lint[0x1])
2024-04-26T16:01:06.420700Z INFO kernel: [ 5.411210] ACPI: LAPIC_NMI (acpi_id[0x25]
high edge lint[0x1])
2024-04-26T16:01:06.420702Z INFO kernel: [ 5.412350] ACPI: LAPIC_NMI (acpi_id[0x26]
high edge lint[0x1])
2024-04-26T16:01:06.420707Z INFO kernel: [ 5.413470] ACPI: LAPIC_NMI (acpi_id[0x27]
high edge lint[0x1])
2024-04-26T16:01:06.420710Z INFO kernel: [ 5.447951] ACPI: LAPIC_NMI (acpi_id[0x28]
high edge lint[0x1])
2024-04-26T16:01:06.420711Z INFO kernel: [ 5.449135] ACPI: LAPIC_NMI (acpi_id[0x29]
high edge lint[0x1])
2024-04-26T16:01:06.420713Z INFO kernel: [ 5.450265] ACPI: LAPIC_NMI (acpi_id[0x2a]
high edge lint[0x1])
2024-04-26T16:01:06.420715Z INFO kernel: [ 5.451395] ACPI: LAPIC_NMI (acpi_id[0x2b]
high edge lint[0x1])
2024-04-26T16:01:06.420717Z INFO kernel: [ 5.452523] ACPI: LAPIC_NMI (acpi_id[0x2c]
high edge lint[0x1])
2024-04-26T16:01:06.420719Z INFO kernel: [ 5.453648] ACPI: LAPIC_NMI (acpi_id[0x2d]
high edge lint[0x1])
2024-04-26T16:01:06.420724Z INFO kernel: [ 5.454776] ACPI: LAPIC_NMI (acpi_id[0x2e]
high edge lint[0x1])
2024-04-26T16:01:06.420726Z INFO kernel: [ 5.455938] ACPI: LAPIC_NMI (acpi_id[0x2f]
```

```
high edge lint[0x1])
2024-04-26T16:01:06.420728Z INFO kernel: [ 5.457068] ACPI: LAPIC_NMI (acpi_id[0x30]
high edge lint[0x1])
2024-04-26T16:01:06.420730Z INFO kernel: [ 5.458198] ACPI: LAPIC_NMI (acpi_id[0x31]
high edge lint[0x1])
2024-04-26T16:01:06.420732Z INFO kernel: [ 5.459323] ACPI: LAPIC_NMI (acpi_id[0x32]
high edge lint[0x1])
2024-04-26T16:01:06.420738Z INFO kernel: [ 5.460454] ACPI: LAPIC_NMI (acpi_id[0x33]
high edge lint[0x1])
2024-04-26T16:01:06.420745Z INFO kernel: [ 5.461584] ACPI: LAPIC_NMI (acpi_id[0x34]
high edge lint[0x1])
2024-04-26T16:01:06.420747Z INFO kernel: [ 5.462717] ACPI: LAPIC_NMI (acpi_id[0x35]
high edge lint[0x1])
2024-04-26T16:01:06.420749Z INFO kernel: [ 5.497216] ACPI: LAPIC_NMI (acpi_id[0x36]
high edge lint[0x1])
2024-04-26T16:01:06.420752Z INFO kernel: [ 5.498351] ACPI: LAPIC_NMI (acpi_id[0x37]
high edge lint[0x1])
2024-04-26T16:01:06.420755Z INFO kernel: [ 5.499478] ACPI: LAPIC_NMI (acpi_id[0x38]
high edge lint[0x1])
2024-04-26T16:01:06.420758Z INFO kernel: [ 5.500609] ACPI: LAPIC_NMI (acpi_id[0x39]
high edge lint[0x1])
2024-04-26T16:01:06.420764Z INFO kernel: [ 5.501740] ACPI: LAPIC_NMI (acpi_id[0x3a]
high edge lint[0x1])
2024-04-26T16:01:06.420767Z INFO kernel: [ 5.502870] ACPI: LAPIC_NMI (acpi_id[0x3b]
high edge lint[0x1])
2024-04-26T16:01:06.420770Z INFO kernel: [ 5.504015] ACPI: LAPIC_NMI (acpi_id[0x3c]
high edge lint[0x1])
2024-04-26T16:01:06.420772Z INFO kernel: [ 5.505171] ACPI: LAPIC_NMI (acpi_id[0x3d]
high edge lint[0x1])
2024-04-26T16:01:06.420775Z INFO kernel: [ 5.506302] ACPI: LAPIC_NMI (acpi_id[0x3e]
high edge lint[0x1])
2024-04-26T16:01:06.420777Z INFO kernel: [ 5.507452] ACPI: LAPIC_NMI (acpi_id[0x3f]
high edge lint[0x1])
2024-04-26T16:01:06.420780Z INFO kernel: [ 5.508584] ACPI: LAPIC_NMI (acpi_id[0x40]
high edge lint[0x1])
2024-04-26T16:01:06.420785Z INFO kernel: [ 5.509715] ACPI: LAPIC_NMI (acpi_id[0x41]
high edge lint[0x1])
2024-04-26T16:01:06.420788Z INFO kernel: [ 5.510847] ACPI: LAPIC_NMI (acpi_id[0x42]
high edge lint[0x1])
2024-04-26T16:01:06.420789Z INFO kernel: [ 5.511985] ACPI: LAPIC_NMI (acpi_id[0x43]
high edge lint[0x1])
2024-04-26T16:01:06.420791Z INFO kernel: [ 5.513126] ACPI: LAPIC_NMI (acpi_id[0x44]
high edge lint[0x1])
2024-04-26T16:01:06.420793Z INFO kernel: [ 5.547618] ACPI: LAPIC_NMI (acpi_id[0x45]
high edge lint[0x1])
2024-04-26T16:01:06.420795Z INFO kernel: [ 5.548748] ACPI: LAPIC_NMI (acpi_id[0x46]
high edge lint[0x1])
2024-04-26T16:01:06.420800Z INFO kernel: [ 5.549882] ACPI: LAPIC_NMI (acpi_id[0x47]
high edge lint[0x1])
2024-04-26T16:01:06.420802Z INFO kernel: [ 5.551012] ACPI: LAPIC_NMI (acpi_id[0x48]
high edge lint[0x1])
2024-04-26T16:01:06.420804Z INFO kernel: [ 5.552143] ACPI: LAPIC_NMI (acpi_id[0x49]
high edge lint[0x1])
2024-04-26T16:01:06.420806Z INFO kernel: [ 5.553328] ACPI: LAPIC_NMI (acpi_id[0x4a]
high edge lint[0x1])
2024-04-26T16:01:06.420808Z INFO kernel: [ 5.554464] ACPI: LAPIC_NMI (acpi_id[0x4b]
high edge lint[0x1])
2024-04-26T16:01:06.420810Z INFO kernel: [ 5.555595] ACPI: LAPIC_NMI (acpi_id[0x4c]
high edge lint[0x1])
2024-04-26T16:01:06.420812Z INFO kernel: [ 5.556722] ACPI: LAPIC_NMI (acpi_id[0x4d]
high edge lint[0x1])
2024-04-26T16:01:06.420818Z INFO kernel: [ 5.557858] ACPI: LAPIC_NMI (acpi_id[0x4e]
high edge lint[0x1])
2024-04-26T16:01:06.420820Z INFO kernel: [ 5.558988] ACPI: LAPIC_NMI (acpi_id[0x4f]
high edge lint[0x1])
2024-04-26T16:01:06.420822Z INFO kernel: [ 5.560120] ACPI: LAPIC_NMI (acpi_id[0x50]
high edge lint[0x1])
2024-04-26T16:01:06.420824Z INFO kernel: [ 5.561250] ACPI: LAPIC_NMI (acpi_id[0x51]
high edge lint[0x1])
```

```
2024-04-26T16:01:06.420826Z INFO kernel: [ 5.562382] ACPI: LAPIC_NMI (acpi_id[0x52]
high edge lint[0x1])
2024-04-26T16:01:06.420828Z INFO kernel: [ 5.563509] ACPI: LAPIC_NMI (acpi_id[0x53]
high edge lint[0x1])
2024-04-26T16:01:06.420833Z INFO kernel: [ 5.598012] ACPI: LAPIC_NMI (acpi_id[0x54]
high edge lint[0x1])
2024-04-26T16:01:06.420837Z INFO kernel: [ 5.599141] ACPI: LAPIC_NMI (acpi_id[0x55]
high edge lint[0x1])
2024-04-26T16:01:06.420839Z INFO kernel: [ 5.600268] ACPI: LAPIC_NMI (acpi_id[0x56]
high edge lint[0x1])
2024-04-26T16:01:06.420841Z INFO kernel: [ 5.601394] ACPI: LAPIC_NMI (acpi_id[0x57]
high edge lint[0x1])
2024-04-26T16:01:06.420844Z INFO kernel: [ 5.602629] ACPI: LAPIC_NMI (acpi_id[0x58]
high edge lint[0x1])
2024-04-26T16:01:06.420846Z INFO kernel: [ 5.603785] ACPI: LAPIC_NMI (acpi_id[0x59]
high edge lint[0x1])
2024-04-26T16:01:06.420854Z INFO kernel: [ 5.604917] ACPI: LAPIC_NMI (acpi_id[0x5a]
high edge lint[0x1])
2024-04-26T16:01:06.420857Z INFO kernel: [ 5.606044] ACPI: LAPIC_NMI (acpi_id[0x5b]
high edge lint[0x1])
2024-04-26T16:01:06.420858Z INFO kernel: [ 5.607169] ACPI: LAPIC_NMI (acpi_id[0x5c]
high edge lint[0x1])
2024-04-26T16:01:06.420861Z INFO kernel: [ 5.608298] ACPI: LAPIC_NMI (acpi_id[0x5d]
high edge lint[0x1])
2024-04-26T16:01:06.420862Z INFO kernel: [ 5.609435] ACPI: LAPIC_NMI (acpi_id[0x5e]
high edge lint[0x1])
2024-04-26T16:01:06.420864Z INFO kernel: [ 5.610560] ACPI: LAPIC_NMI (acpi_id[0x5f]
high edge lint[0x1])
2024-04-26T16:01:06.420867Z INFO kernel: [ 5.611694] ACPI: LAPIC_NMI (acpi_id[0x60]
high edge lint[0x1])
2024-04-26T16:01:06.420874Z INFO kernel: [ 5.612824] ACPI: LAPIC_NMI (acpi_id[0x61]
high edge lint[0x1])
2024-04-26T16:01:06.420876Z INFO kernel: [ 5.647316] ACPI: LAPIC_NMI (acpi_id[0x62]
high edge lint[0x1])
2024-04-26T16:01:06.420878Z INFO kernel: [ 5.648450] ACPI: LAPIC_NMI (acpi_id[0x63]
high edge lint[0x1])
2024-04-26T16:01:06.420880Z INFO kernel: [ 5.649582] ACPI: LAPIC_NMI (acpi_id[0x64]
high edge lint[0x1])
2024-04-26T16:01:06.420881Z INFO kernel: [ 5.650700] ACPI: LAPIC_NMI (acpi_id[0x65]
high edge lint[0x1])
2024-04-26T16:01:06.420883Z INFO kernel: [ 5.652271] ACPI: LAPIC_NMI (acpi_id[0x66]
high edge lint[0x1])
2024-04-26T16:01:06.420897Z INFO kernel: [ 5.653408] ACPI: LAPIC_NMI (acpi_id[0x67]
high edge lint[0x1])
2024-04-26T16:01:06.420900Z INFO kernel: [ 5.654546] ACPI: LAPIC_NMI (acpi_id[0x68]
high edge lint[0x1])
2024-04-26T16:01:06.420902Z INFO kernel: [ 5.655679] ACPI: LAPIC_NMI (acpi_id[0x69]
high edge lint[0x1])
2024-04-26T16:01:06.420906Z INFO kernel: [ 5.656818] ACPI: LAPIC_NMI (acpi_id[0x6a]
high edge lint[0x1])
2024-04-26T16:01:06.420908Z INFO kernel: [ 5.657949] ACPI: LAPIC_NMI (acpi_id[0x6b]
high edge lint[0x1])
2024-04-26T16:01:06.420910Z INFO kernel: [ 5.659085] ACPI: LAPIC_NMI (acpi_id[0x6c]
high edge lint[0x1])
2024-04-26T16:01:06.420911Z INFO kernel: [ 5.660219] ACPI: LAPIC_NMI (acpi_id[0x6d]
high edge lint[0x1])
2024-04-26T16:01:06.420920Z INFO kernel: [ 5.661344] ACPI: LAPIC_NMI (acpi_id[0x6e]
high edge lint[0x1])
2024-04-26T16:01:06.420922Z INFO kernel: [ 5.662488] ACPI: LAPIC_NMI (acpi_id[0x6f]
high edge lint[0x1])
2024-04-26T16:01:06.420924Z INFO kernel: [ 5.696983] ACPI: LAPIC_NMI (acpi_id[0x70]
high edge lint[0x1])
2024-04-26T16:01:06.420925Z INFO kernel: [ 5.698122] ACPI: LAPIC_NMI (acpi_id[0x71]
high edge lint[0x1])
2024-04-26T16:01:06.420927Z INFO kernel: [ 5.699259] ACPI: LAPIC_NMI (acpi_id[0x72]
high edge lint[0x1])
2024-04-26T16:01:06.420928Z INFO kernel: [ 5.700439] ACPI: LAPIC_NMI (acpi_id[0x73]
high edge lint[0x1])
2024-04-26T16:01:06.424195Z INFO kernel: [ 5.701602] ACPI: LAPIC_NMI (acpi_id[0x74]
```

```

high edge lint[0x1])
2024-04-26T16:01:06.427753Z INFO kernel: [ 5.702733] ACPI: LAPIC_NMI (acpi_id[0x75]
high edge lint[0x1])
2024-04-26T16:01:06.432144Z INFO kernel: [ 5.703865] ACPI: LAPIC_NMI (acpi_id[0x76]
high edge lint[0x1])
2024-04-26T16:01:06.432596Z INFO kernel: [ 5.704995] ACPI: LAPIC_NMI (acpi_id[0x77]
high edge lint[0x1])
2024-04-26T16:01:06.432615Z INFO kernel: [ 5.706140] ACPI: LAPIC_NMI (acpi_id[0x78]
high edge lint[0x1])
2024-04-26T16:01:06.432618Z INFO kernel: [ 5.707270] ACPI: LAPIC_NMI (acpi_id[0x79]
high edge lint[0x1])
2024-04-26T16:01:06.432621Z INFO kernel: [ 5.708409] ACPI: LAPIC_NMI (acpi_id[0x7a]
high edge lint[0x1])
2024-04-26T16:01:06.432622Z INFO kernel: [ 5.709542] ACPI: LAPIC_NMI (acpi_id[0x7b]
high edge lint[0x1])
2024-04-26T16:01:06.432624Z INFO kernel: [ 5.710672] ACPI: LAPIC_NMI (acpi_id[0x7c]
high edge lint[0x1])
2024-04-26T16:01:06.432626Z INFO kernel: [ 5.711807] ACPI: LAPIC_NMI (acpi_id[0x7d]
high edge lint[0x1])
2024-04-26T16:01:06.432628Z INFO kernel: [ 5.712940] ACPI: LAPIC_NMI (acpi_id[0x7e]
high edge lint[0x1])
2024-04-26T16:01:06.432636Z INFO kernel: [ 5.747441] ACPI: LAPIC_NMI (acpi_id[0x7f]
high edge lint[0x1])
2024-04-26T16:01:06.432638Z INFO kernel: [ 5.748761] IOAPIC[0]: apic_id 128, version
32, address 0xfec00000, GSI 0-23
2024-04-26T16:01:06.432640Z INFO kernel: [ 5.750185] ACPI: INT_SRC_OVR (bus 0 bus_irq
0 global_irq 2 high edge)
2024-04-26T16:01:06.432642Z INFO kernel: [ 5.751438] ACPI: Using ACPI (MADT) for SMP
configuration information
2024-04-26T16:01:06.432644Z INFO kernel: [ 5.752661] ACPI: HPET id: 0x8086af01 base:
0xfed00000
2024-04-26T16:01:06.432646Z WARNING kernel: [ 5.753648] smpboot: 128 Processors
exceeds NR_CPUS limit of 8
2024-04-26T16:01:06.432648Z INFO kernel: [ 5.754757] smpboot: Allowing 8 CPUs, 4
hotplug CPUs
2024-04-26T16:01:06.432650Z INFO kernel: [ 5.755756] [mem 0xc0000000-0xffbfffff]
available for PCI devices
2024-04-26T16:01:06.432652Z INFO kernel: [ 5.756914] Booting paravirtualized kernel on
VMware hypervisor
2024-04-26T16:01:06.432654Z INFO kernel: [ 5.758039] clocksource: refined-jiffies:
mask: 0xffffffff max_cycles: 0xffffffff, max_idle_ns: 1910969940391419 ns
2024-04-26T16:01:06.432656Z INFO kernel: [ 5.798064] setup_percpu: NR_CPUS:8
nr_cpumask_bits:8 nr_cpu_ids:8 nr_node_ids:1
2024-04-26T16:01:06.432658Z INFO kernel: [ 5.860079] percpu: Embedded 53 pages/cpu
s179864 r8192 d29032 u262144
2024-04-26T16:01:06.432666Z DEBUG kernel: [ 5.861367] pcpu-alloc: s179864 r8192 d29032
u262144 alloc=1*2097152
2024-04-26T16:01:06.432668Z DEBUG kernel: [ 5.861386] pcpu-alloc: [0] 0 1 2 3 4 5 6 7
2024-04-26T16:01:06.432670Z INFO kernel: [ 5.861857] Built 1 zonelists, mobility
grouping on. Total pages: 1587190
2024-04-26T16:01:06.432672Z NOTICE kernel: [ 5.863180] Kernel command line:
BOOT_IMAGE=/syslinux/vmlinuz.A init=/sbin/init boot=local rootwait ro noresume noswap
loglevel=7 noinitrd earlyprintk=ttyS0,115200 console=ttyS0,115200 i915.modeset=1 cros_efi
cros_debug root=PARTUUID=5C728CA9-A521-2846-A29C-35E25A13FB4C
2024-04-26T16:01:06.432675Z NOTICE kernel: [ 5.901198] Unknown kernel command line
parameters "noresume noswap cros_efi cros_debug BOOT_IMAGE=/syslinux/vmlinuz.A
boot=local", will be passed to user space.
2024-04-26T16:01:06.432677Z INFO kernel: [ 6.002761] Dentry cache hash table entries:
1048576 (order: 11, 8388608 bytes, linear)
2024-04-26T16:01:06.432679Z INFO kernel: [ 6.255345] Inode-cache hash table entries:
524288 (order: 10, 4194304 bytes, linear)
2024-04-26T16:01:06.432681Z INFO kernel: [ 6.256989] mem auto-init: stack:off, heap
alloc:off, heap free:off
2024-04-26T16:01:06.432683Z INFO kernel: [ 8.047659] Memory: 6216784K/6450184K
available (14348K kernel code, 2385K rwdatas, 3664K rodata, 1784K init, 1424K bss, 233140K
reserved, 0K cma-reserved)
2024-04-26T16:01:06.432685Z INFO kernel: [ 8.050797] SLUB: HWalign=64, Order=0-3,
MinObjects=0, CPUs=8, Nodes=1
2024-04-26T16:01:06.432687Z INFO kernel: [ 8.052737] Kernel/User page tables

```

```

isolation: enabled
2024-04-26T16:01:06.432695Z INFO kernel: [ 8.054461] ftrace: allocating 46981 entries
in 184 pages
2024-04-26T16:01:06.432697Z INFO kernel: [ 8.152376] ftrace: allocated 184 pages with
4 groups
2024-04-26T16:01:06.432699Z INFO kernel: [ 8.157628] rcu: Preemptible hierarchical RCU
implementation.
2024-04-26T16:01:06.432701Z INFO kernel: [ 8.159107] Trampoline variant of
Tasks RCU enabled.
2024-04-26T16:01:06.432703Z INFO kernel: [ 8.160652] Rude variant of Tasks RCU
enabled.
2024-04-26T16:01:06.432705Z INFO kernel: [ 8.162040] Tracing variant of Tasks
RCU enabled.
2024-04-26T16:01:06.432707Z INFO kernel: [ 8.163480] rcu: RCU calculated value of
scheduler-enlistment delay is 100 jiffies.
2024-04-26T16:01:06.432709Z INFO kernel: [ 8.211844] NR_IRQS: 4352, nr_irqs: 488,
preallocated irqs: 16
2024-04-26T16:01:06.432711Z INFO kernel: [ 8.247157] ACPI: Core revision 20210730
2024-04-26T16:01:06.432713Z INFO kernel: [ 8.252930] clocksource: hpet: mask:
0xffffffff max_cycles: 0xffffffff, max_idle_ns: 133484882848 ns
2024-04-26T16:01:06.432715Z INFO kernel: [ 8.265483] APIC: Switch to symmetric I/O
mode setup
2024-04-26T16:01:06.432717Z INFO kernel: [ 8.276678] ..TIMER: vector=0x30 apic1=0
pin1=2 apic2=-1 pin2=-1
2024-04-26T16:01:06.432718Z INFO kernel: [ 8.279699] clocksource: tsc-early: mask:
0xffffffffffffffff max_cycles: 0x172da94f0e2, max_idle_ns: 440795278248 ns
2024-04-26T16:01:06.432720Z INFO kernel: [ 8.285598] Calibrating delay loop (skipped)
preset value.. 3215.99 BogoMIPS (lpj=1607999)
2024-04-26T16:01:06.432722Z INFO kernel: [ 8.286637] pid_max: default: 32768 minimum:
301
2024-04-26T16:01:06.432724Z INFO kernel: [ 8.294693] LSM: Security Framework
initializing
2024-04-26T16:01:06.432725Z INFO kernel: [ 8.295636] Yama: becoming mindful.
2024-04-26T16:01:06.432727Z INFO kernel: [ 8.296617] LoadPin: ready to pin (currently
not enforcing)
2024-04-26T16:01:06.432729Z INFO kernel: [ 8.297632] Chromium OS LSM: enabled
2024-04-26T16:01:06.432731Z INFO kernel: [ 8.297642] overlayfs: SELinux:
Initializing.
2024-04-26T16:01:06.432732Z INFO kernel: [ 8.301704] Mount-cache hash table entries:
16384 (order: 5, 131072 bytes, linear)
2024-04-26T16:01:06.432734Z INFO kernel: [ 8.305648] Mountpoint-cache hash table
entries: 16384 (order: 5, 131072 bytes, linear)
2024-04-26T16:01:06.432736Z INFO kernel: [ 8.313980] Disabled fast string operations
2024-04-26T16:01:06.432737Z INFO kernel: [ 8.314636] Last level iTLB entries: 4KB 64,
2MB 8, 4MB 8
2024-04-26T16:01:06.433175Z INFO kernel: [ 8.315621] Last level dTLB entries: 4KB 64,
2MB 0, 4MB 0, 1GB 4
2024-04-26T16:01:06.433187Z INFO kernel: [ 8.316622] Spectre V1 : Mitigation:
usercopy/swaps barriers and __user pointer sanitization
2024-04-26T16:01:06.433190Z INFO kernel: [ 8.317624] Spectre V2 : Mitigation: IBRS
2024-04-26T16:01:06.433193Z INFO kernel: [ 8.318622] Spectre V2 : Spectre v2 /
SpectreRSB mitigation: Filling RSB on context switch
2024-04-26T16:01:06.433196Z INFO kernel: [ 8.319623] Spectre V2 : Spectre v2 /
SpectreRSB : Filling RSB on VMEXIT
2024-04-26T16:01:06.433198Z INFO kernel: [ 8.321621] RETbleed: Mitigation: IBRS
2024-04-26T16:01:06.433200Z INFO kernel: [ 8.322623] Spectre V2 : mitigation: Enabling
conditional Indirect Branch Prediction Barrier
2024-04-26T16:01:06.433202Z INFO kernel: [ 8.323623] Speculative Store Bypass:
Mitigation: Speculative Store Bypass disabled via prctl and seccomp
2024-04-26T16:01:06.433204Z INFO kernel: [ 8.324623] MDS: Mitigation: Clear CPU
buffers
2024-04-26T16:01:06.433206Z INFO kernel: [ 8.325621] MMIO Stale Data: Mitigation:
Clear CPU buffers
2024-04-26T16:01:06.433208Z INFO kernel: [ 8.326622] SRBDS: Unknown: Dependent on
hypervisor status
2024-04-26T16:01:06.433209Z INFO kernel: [ 8.371715] Freeing SMP alternatives memory:
40K
2024-04-26T16:01:06.433211Z INFO kernel: [ 8.375586] smpboot: CPU0: Intel(R) Core(TM)
m3-8100Y CPU @ 1.10GHz (family: 0x6, model: 0x8e, stepping: 0x9)

```

```

2024-04-26T16:01:06.433213Z INFO kernel: [ 8.379977] Performance Events: Skylake
events, core PMU driver.
2024-04-26T16:01:06.433215Z WARNING kernel: [ 8.380616] core: CPUID marked event: 'cpu
cycles' unavailable
2024-04-26T16:01:06.433217Z WARNING kernel: [ 8.381614] core: CPUID marked event:
'instructions' unavailable
2024-04-26T16:01:06.433219Z WARNING kernel: [ 8.382615] core: CPUID marked event: 'bus
cycles' unavailable
2024-04-26T16:01:06.433223Z WARNING kernel: [ 8.383636] core: CPUID marked event:
'cache references' unavailable
2024-04-26T16:01:06.433227Z WARNING kernel: [ 8.384614] core: CPUID marked event:
'cache misses' unavailable
2024-04-26T16:01:06.433230Z WARNING kernel: [ 8.385614] core: CPUID marked event:
'branch instructions' unavailable
2024-04-26T16:01:06.433234Z WARNING kernel: [ 8.386616] core: CPUID marked event:
'branch misses' unavailable
2024-04-26T16:01:06.433236Z INFO kernel: [ 8.387619] ... version: 1
2024-04-26T16:01:06.433239Z INFO kernel: [ 8.388614] ... bit width: 48
2024-04-26T16:01:06.433242Z INFO kernel: [ 8.389614] ... generic registers: 4
2024-04-26T16:01:06.433245Z INFO kernel: [ 8.390614] ... value mask:
0000ffffffffffff
2024-04-26T16:01:06.433248Z INFO kernel: [ 8.391628] ... max period:
000000007fffffff
2024-04-26T16:01:06.433254Z INFO kernel: [ 8.392629] ... fixed-purpose events: 0
2024-04-26T16:01:06.433256Z INFO kernel: [ 8.393629] ... event mask:
0000000000000000f
2024-04-26T16:01:06.433260Z INFO kernel: [ 8.396633] rcu: Hierarchical SRCU
implementation.
2024-04-26T16:01:06.433263Z INFO kernel: [ 8.399681] NMI watchdog: Perf NMI watchdog
permanently disabled
2024-04-26T16:01:06.433265Z INFO kernel: [ 8.404291] smp: Bringing up secondary CPUs
...
2024-04-26T16:01:06.433267Z INFO kernel: [ 8.408180] x86: Booting SMP configuration:
2024-04-26T16:01:06.433268Z INFO kernel: [ 8.408617] .... node #0, CPUs: #1
2024-04-26T16:01:06.433270Z INFO kernel: [ 0.034583] Disabled fast string operations
2024-04-26T16:01:06.433271Z INFO kernel: [ 0.034583] smpboot: CPU 1 Converting
physical 2 to logical package 1
2024-04-26T16:01:06.433273Z INFO kernel: [ 0.034583] smpboot: CPU 1 Converting
physical 0 to logical die 1
2024-04-26T16:01:06.433275Z WARNING kernel: [ 8.416677] #2
2024-04-26T16:01:06.433278Z INFO kernel: [ 0.034583] Disabled fast string operations
2024-04-26T16:01:06.433281Z INFO kernel: [ 0.034583] smpboot: CPU 2 Converting
physical 4 to logical package 2
2024-04-26T16:01:06.433283Z INFO kernel: [ 0.034583] smpboot: CPU 2 Converting
physical 0 to logical die 2
2024-04-26T16:01:06.433285Z WARNING kernel: [ 8.426733] #3
2024-04-26T16:01:06.433287Z INFO kernel: [ 0.034583] Disabled fast string operations
2024-04-26T16:01:06.433288Z INFO kernel: [ 0.034583] smpboot: CPU 3 Converting
physical 6 to logical package 3
2024-04-26T16:01:06.433290Z INFO kernel: [ 0.034583] smpboot: CPU 3 Converting
physical 0 to logical die 3
2024-04-26T16:01:06.433292Z INFO kernel: [ 8.432153] smp: Brought up 1 node, 4 CPUs
2024-04-26T16:01:06.433294Z INFO kernel: [ 8.436629] smpboot: Max logical packages:
128
2024-04-26T16:01:06.433296Z INFO kernel: [ 8.437616] smpboot: Total of 4 processors
activated (12863.99 BogoMIPS)
2024-04-26T16:01:06.433297Z INFO kernel: [ 8.442628] devtmpfs: initialized
2024-04-26T16:01:06.433299Z INFO kernel: [ 8.445847] ACPI: PM: Registering ACPI NVS
region [mem 0x00000000-0x00000fff] (4096 bytes)
2024-04-26T16:01:06.433301Z INFO kernel: [ 8.446617] ACPI: PM: Registering ACPI NVS
region [mem 0x0efb2000-0x0efb6fff] (20480 bytes)
2024-04-26T16:01:06.433304Z INFO kernel: [ 8.447616] ACPI: PM: Registering ACPI NVS
region [mem 0x0ff74000-0x0ff74fff] (4096 bytes)
2024-04-26T16:01:06.433307Z INFO kernel: [ 8.448952] clocksource: jiffies: mask:
0xffffffff max_cycles: 0xffffffff, max_idle_ns: 1911260446275000 ns
2024-04-26T16:01:06.433309Z INFO kernel: [ 8.449627] futex hash table entries: 2048
(order: 5, 131072 bytes, linear)
2024-04-26T16:01:06.433311Z INFO kernel: [ 8.454030] pinctrl core: initialized pinctrl
subsystem

```

```

2024-04-26T16:01:06.433882Z INFO kernel: [ 8.455125] PM: RTC time: 16:00:49, date:
2024-04-26
2024-04-26T16:01:06.433891Z INFO kernel: [ 8.458936] NET: Registered
PF_NETLINK/PF_ROUTE protocol family
2024-04-26T16:01:06.433895Z INFO kernel: [ 8.460996] audit: initializing netlink
subsys (disabled)
2024-04-26T16:01:06.433898Z NOTICE kernel: [ 8.463688] audit: type=2000
audit(1714147249.183:1): state=initialized audit_enabled=0 res=1
2024-04-26T16:01:06.433901Z INFO kernel: [ 8.464174] thermal_sys: Registered thermal
governor 'step_wise'
2024-04-26T16:01:06.433907Z INFO kernel: [ 8.464619] thermal_sys: Registered thermal
governor 'user_space'
2024-04-26T16:01:06.433909Z INFO kernel: [ 8.465671] cpuidle: using governor ladder
2024-04-26T16:01:06.433912Z INFO kernel: [ 8.468604] cpuidle: using governor menu
2024-04-26T16:01:06.433915Z INFO kernel: [ 8.469976] ACPI: bus type PCI registered
2024-04-26T16:01:06.433917Z INFO kernel: [ 8.470638] acpiphp: ACPI Hot Plug PCI
Controller Driver version: 0.5
2024-04-26T16:01:06.433920Z INFO kernel: [ 8.472055] PCI: MMCONFIG for domain 0000
[bus 00-7f] at [mem 0xe0000000-0xe7ffffff] (base 0xe0000000)
2024-04-26T16:01:06.433923Z INFO kernel: [ 8.472619] PCI: not using MMCONFIG
2024-04-26T16:01:06.433926Z INFO kernel: [ 8.473517] PCI: Using configuration type 1
for base access
2024-04-26T16:01:06.433931Z INFO kernel: [ 8.495840] cryptd: max_cpu_qlen set to 1000
2024-04-26T16:01:06.433932Z INFO kernel: [ 8.518008] ACPI: Added _OSI(Module Device)
2024-04-26T16:01:06.433935Z INFO kernel: [ 8.518627] ACPI: Added _OSI(Processor
Device)
2024-04-26T16:01:06.433937Z INFO kernel: [ 8.519615] ACPI: Added _OSI(3.0 _SCP
Extensions)
2024-04-26T16:01:06.433939Z INFO kernel: [ 8.521615] ACPI: Added _OSI(Processor
Aggregator Device)
2024-04-26T16:01:06.433942Z INFO kernel: [ 8.522617] ACPI: Added _OSI(Linux-Dell-
Video)
2024-04-26T16:01:06.433946Z INFO kernel: [ 8.523616] ACPI: Added _OSI(Linux-Lenovo-NV-
HDMI-Audio)
2024-04-26T16:01:06.433949Z INFO kernel: [ 8.525614] ACPI: Added _OSI(Linux-HPI-
Hybrid-Graphics)
2024-04-26T16:01:06.433952Z INFO kernel: [ 8.559147] ACPI: 1 ACPI AML tables
successfully acquired and loaded
2024-04-26T16:01:06.433955Z NOTICE kernel: [ 8.563698] ACPI: [Firmware Bug]: BIOS
_OSI(Linux) query ignored
2024-04-26T16:01:06.433959Z NOTICE kernel: [ 8.564631] ACPI: BIOS _OSI(Darwin) query
ignored
2024-04-26T16:01:06.433962Z INFO kernel: [ 8.605738] ACPI: Interpreter enabled
2024-04-26T16:01:06.433964Z INFO kernel: [ 8.606713] ACPI: PM: (supports S0 S1 S5)
2024-04-26T16:01:06.433966Z INFO kernel: [ 8.607616] ACPI: Using IOAPIC for interrupt
routing
2024-04-26T16:01:06.433968Z INFO kernel: [ 8.608676] PCI: MMCONFIG for domain 0000
[bus 00-7f] at [mem 0xe0000000-0xe7ffffff] (base 0xe0000000)
2024-04-26T16:01:06.433969Z INFO kernel: [ 8.612400] PCI: MMCONFIG at [mem 0xe0000000-
0xe7ffffff] reserved in ACPI motherboard resources
2024-04-26T16:01:06.433971Z WARNING kernel: [ 8.613619] pmd_set_huge: Cannot satisfy
[mem 0xe0000000-0xe0200000] with a huge-page mapping due to MTRR override.
2024-04-26T16:01:06.433973Z INFO kernel: [ 8.618627] PCI: Using host bridge windows
from ACPI; if necessary, use "pci=nocrs" and report a bug
2024-04-26T16:01:06.433975Z INFO kernel: [ 8.622334] ACPI: Enabled 4 GPEs in block 00
to 0F
2024-04-26T16:01:06.433977Z INFO kernel: [ 8.936888] ACPI: PCI Root Bridge [PCI0]
(domain 0000 [bus 00-7f])
2024-04-26T16:01:06.433979Z INFO kernel: [ 8.937624] acpi PNP0A03:00: _OSC: OS
supports [ExtendedConfig ASPM ClockPM Segments MSI HPX-Type3]
2024-04-26T16:01:06.433981Z INFO kernel: [ 8.938916] acpi PNP0A03:00: _OSC: platform
does not support [AER LTR]
2024-04-26T16:01:06.433983Z INFO kernel: [ 8.939954] acpi PNP0A03:00: _OSC: OS now
controls [PCIeHotplug PME PCIeCapability]
2024-04-26T16:01:06.433986Z INFO kernel: [ 8.941895] PCI host bridge to bus 0000:00
2024-04-26T16:01:06.433989Z INFO kernel: [ 8.942617] pci_bus 0000:00: root bus
resource [io 0x0d00-0xffff window]
2024-04-26T16:01:06.433991Z INFO kernel: [ 8.943618] pci_bus 0000:00: root bus
resource [io 0x0000-0x0cf7 window]

```



```

2024-04-26T16:01:06.433993Z INFO kernel: [ 8.944617] pci_bus 0000:00: root bus
resource [mem 0xfef00000-0xffdfffff window]
2024-04-26T16:01:06.433995Z INFO kernel: [ 8.945620] pci_bus 0000:00: root bus
resource [mem 0xfed45000-0xfedfffff window]
2024-04-26T16:01:06.433997Z INFO kernel: [ 8.946617] pci_bus 0000:00: root bus
resource [mem 0xfec10000-0xfed3ffff window]
2024-04-26T16:01:06.433999Z INFO kernel: [ 8.947618] pci_bus 0000:00: root bus
resource [mem 0xfa400000-0xfebfffff window]
2024-04-26T16:01:06.434002Z INFO kernel: [ 8.948617] pci_bus 0000:00: root bus
resource [mem 0xf0000000-0xfa3fffff pref window]
2024-04-26T16:01:06.434004Z INFO kernel: [ 8.949628] pci_bus 0000:00: root bus
resource [mem 0xc0000000-0xefffffff window]
2024-04-26T16:01:06.434006Z INFO kernel: [ 8.950619] pci_bus 0000:00: root bus
resource [mem 0x000a0000-0x000bffff window]
2024-04-26T16:01:06.441524Z INFO kernel: [ 8.951619] pci_bus 0000:00: root bus
resource [mem 0x000c4000-0x000c7fff window]
2024-04-26T16:01:06.441530Z INFO kernel: [ 8.952618] pci_bus 0000:00: root bus
resource [mem 0x000c8000-0x000cbfff window]
2024-04-26T16:01:06.441532Z INFO kernel: [ 8.953618] pci_bus 0000:00: root bus
resource [mem 0x000d4000-0x000d7fff window]
2024-04-26T16:01:06.441535Z INFO kernel: [ 8.954618] pci_bus 0000:00: root bus
resource [mem 0x000d8000-0x000dbfff window]
2024-04-26T16:01:06.441537Z INFO kernel: [ 8.955618] pci_bus 0000:00: root bus
resource [mem 0x000e4000-0x000e7fff window]
2024-04-26T16:01:06.441539Z INFO kernel: [ 8.956618] pci_bus 0000:00: root bus
resource [mem 0x000e8000-0x000ebfff window]
2024-04-26T16:01:06.441541Z INFO kernel: [ 8.957618] pci_bus 0000:00: root bus
resource [mem 0x000ec000-0x000effff window]
2024-04-26T16:01:06.441544Z INFO kernel: [ 8.958618] pci_bus 0000:00: root bus
resource [bus 00-7f]
2024-04-26T16:01:06.441546Z INFO kernel: [ 8.960819] pci 0000:00:00.0: [8086:7190]
type 00 class 0x060000
2024-04-26T16:01:06.441548Z INFO kernel: [ 8.963973] pci 0000:00:01.0: [8086:7191]
type 01 class 0x060400
2024-04-26T16:01:06.441550Z INFO kernel: [ 8.966222] pci 0000:00:07.0: [8086:7110]
type 00 class 0x060100
2024-04-26T16:01:06.441552Z INFO kernel: [ 8.968752] pci 0000:00:07.1: [8086:7111]
type 00 class 0x01018a
2024-04-26T16:01:06.441554Z INFO kernel: [ 8.973641] pci 0000:00:07.1: reg 0x20: [io
0x2150-0x215f]
2024-04-26T16:01:06.457815Z INFO kernel: [ 8.976616] pci 0000:00:07.1: legacy IDE
quirk: reg 0x10: [io 0x01f0-0x01f7]
2024-04-26T16:01:06.457827Z INFO kernel: [ 8.978616] pci 0000:00:07.1: legacy IDE
quirk: reg 0x14: [io 0x03f6]
2024-04-26T16:01:06.457831Z INFO kernel: [ 8.979617] pci 0000:00:07.1: legacy IDE
quirk: reg 0x18: [io 0x0170-0x0177]
2024-04-26T16:01:06.457834Z INFO kernel: [ 8.980617] pci 0000:00:07.1: legacy IDE
quirk: reg 0x1c: [io 0x0376]
2024-04-26T16:01:06.457838Z INFO kernel: [ 8.982758] pci 0000:00:07.3: [8086:7113]
type 00 class 0x068000
2024-04-26T16:01:06.457841Z INFO kernel: [ 8.985436] pci 0000:00:07.3: quirk: [io
0x0440-0x047f] claimed by PIIX4 ACPI
2024-04-26T16:01:06.457845Z INFO kernel: [ 8.987432] pci 0000:00:07.7: [15ad:0740]
type 00 class 0x088000
2024-04-26T16:01:06.457848Z INFO kernel: [ 8.987956] pci 0000:00:07.7: reg 0x10: [io
0x2100-0x213f]
2024-04-26T16:01:06.457850Z INFO kernel: [ 8.988787] pci 0000:00:07.7: reg 0x14: [mem
0xffbe0000-0xffbe1fff 64bit]
2024-04-26T16:01:06.457853Z INFO kernel: [ 8.993006] pci 0000:00:0f.0: [15ad:0405]
type 00 class 0x030000
2024-04-26T16:01:06.457857Z INFO kernel: [ 8.997604] pci 0000:00:0f.0: reg 0x10: [io
0x2140-0x214f]
2024-04-26T16:01:06.457860Z INFO kernel: [ 9.000637] pci 0000:00:0f.0: reg 0x14: [mem
0xf0000000-0xf7fffff pref]
2024-04-26T16:01:06.457861Z INFO kernel: [ 9.005641] pci 0000:00:0f.0: reg 0x18: [mem
0xfb800000-0xfbfffff]
2024-04-26T16:01:06.457864Z INFO kernel: [ 9.016643] pci 0000:00:0f.0: reg 0x30: [mem
0xffff8000-0xfffffff pref]
2024-04-26T16:01:06.457867Z INFO kernel: [ 9.018184] pci 0000:00:0f.0: Video device

```

```
with shadowed ROM at [mem 0x000c0000-0x000dffff]
2024-04-26T16:01:06.457869Z INFO kernel: [ 9.020541] pci 0000:00:10.0: [1000:0030]
type 00 class 0x010000
2024-04-26T16:01:06.457871Z INFO kernel: [ 9.022046] pci 0000:00:10.0: reg 0x10: [io
0x2000-0x20ff]
2024-04-26T16:01:06.457873Z INFO kernel: [ 9.023481] pci 0000:00:10.0: reg 0x14: [mem
0xffbc0000-0xffbdffff 64bit]
2024-04-26T16:01:06.457876Z INFO kernel: [ 9.025586] pci 0000:00:10.0: reg 0x1c: [mem
0xffba0000-0xffbbffff 64bit]
2024-04-26T16:01:06.457879Z INFO kernel: [ 9.028062] pci 0000:00:10.0: reg 0x30: [mem
0xffffc000-0xfffffff pref]
2024-04-26T16:01:06.457882Z INFO kernel: [ 9.029966] pci 0000:00:11.0: [15ad:0790]
type 01 class 0x060401
2024-04-26T16:01:06.457885Z INFO kernel: [ 9.033656] pci 0000:00:15.0: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.457888Z INFO kernel: [ 9.036986] pci 0000:00:15.0: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.457891Z INFO kernel: [ 9.039493] pci 0000:00:15.1: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.457894Z INFO kernel: [ 9.041810] pci 0000:00:15.1: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.457898Z INFO kernel: [ 9.044316] pci 0000:00:15.2: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.457901Z INFO kernel: [ 9.046603] pci 0000:00:15.2: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.457904Z INFO kernel: [ 9.049044] pci 0000:00:15.3: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.457908Z INFO kernel: [ 9.052416] pci 0000:00:15.3: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.457911Z INFO kernel: [ 9.053954] pci 0000:00:15.4: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.457913Z INFO kernel: [ 9.056986] pci 0000:00:15.4: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.457917Z INFO kernel: [ 9.059267] pci 0000:00:15.5: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.457920Z INFO kernel: [ 9.061322] pci 0000:00:15.5: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.457922Z INFO kernel: [ 9.062965] pci 0000:00:15.6: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.457925Z INFO kernel: [ 9.066349] pci 0000:00:15.6: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.457926Z INFO kernel: [ 9.067868] pci 0000:00:15.7: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.457928Z INFO kernel: [ 9.070964] pci 0000:00:15.7: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.457930Z INFO kernel: [ 9.073251] pci 0000:00:16.0: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.457932Z INFO kernel: [ 9.075313] pci 0000:00:16.0: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.457935Z INFO kernel: [ 9.076663] pci 0000:00:16.1: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.457938Z INFO kernel: [ 9.079707] pci 0000:00:16.1: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.457940Z INFO kernel: [ 9.082586] pci 0000:00:16.2: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.457943Z INFO kernel: [ 9.085191] pci 0000:00:16.2: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.457945Z INFO kernel: [ 9.087444] pci 0000:00:16.3: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.458606Z INFO kernel: [ 9.089628] pci 0000:00:16.3: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.458616Z INFO kernel: [ 9.092061] pci 0000:00:16.4: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.458618Z INFO kernel: [ 9.095167] pci 0000:00:16.4: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.458620Z INFO kernel: [ 9.097586] pci 0000:00:16.5: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.458622Z INFO kernel: [ 9.099776] pci 0000:00:16.5: PME# supported
from D0 D3hot D3cold
```

```
2024-04-26T16:01:06.458623Z INFO kernel: [ 9.102313] pci 0000:00:16.6: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.458958Z INFO kernel: [ 9.104567] pci 0000:00:16.6: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459070Z INFO kernel: [ 9.107002] pci 0000:00:16.7: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459082Z INFO kernel: [ 9.110343] pci 0000:00:16.7: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459087Z INFO kernel: [ 9.112257] pci 0000:00:17.0: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459089Z INFO kernel: [ 9.114821] pci 0000:00:17.0: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459091Z INFO kernel: [ 9.117354] pci 0000:00:17.1: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459093Z INFO kernel: [ 9.119670] pci 0000:00:17.1: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459164Z INFO kernel: [ 9.122181] pci 0000:00:17.2: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459173Z INFO kernel: [ 9.124473] pci 0000:00:17.2: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459176Z INFO kernel: [ 9.125976] pci 0000:00:17.3: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459180Z INFO kernel: [ 9.129331] pci 0000:00:17.3: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459183Z INFO kernel: [ 9.130779] pci 0000:00:17.4: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459186Z INFO kernel: [ 9.134046] pci 0000:00:17.4: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459244Z INFO kernel: [ 9.135980] pci 0000:00:17.5: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459251Z INFO kernel: [ 9.139475] pci 0000:00:17.5: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459255Z INFO kernel: [ 9.141088] pci 0000:00:17.6: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459258Z INFO kernel: [ 9.143419] pci 0000:00:17.6: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459261Z INFO kernel: [ 9.144860] pci 0000:00:17.7: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459264Z INFO kernel: [ 9.148276] pci 0000:00:17.7: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459268Z INFO kernel: [ 9.150041] pci 0000:00:18.0: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459323Z INFO kernel: [ 9.153384] pci 0000:00:18.0: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459330Z INFO kernel: [ 9.154986] pci 0000:00:18.1: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459334Z INFO kernel: [ 9.158466] pci 0000:00:18.1: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459337Z INFO kernel: [ 9.160018] pci 0000:00:18.2: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459340Z INFO kernel: [ 9.162471] pci 0000:00:18.2: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459343Z INFO kernel: [ 9.164083] pci 0000:00:18.3: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459398Z INFO kernel: [ 9.166751] pci 0000:00:18.3: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459405Z INFO kernel: [ 9.169804] pci 0000:00:18.4: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459409Z INFO kernel: [ 9.173242] pci 0000:00:18.4: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459411Z INFO kernel: [ 9.175131] pci 0000:00:18.5: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459414Z INFO kernel: [ 9.177716] pci 0000:00:18.5: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459417Z INFO kernel: [ 9.180396] pci 0000:00:18.6: [15ad:07a0]
type 01 class 0x060400
2024-04-26T16:01:06.459420Z INFO kernel: [ 9.182822] pci 0000:00:18.6: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459470Z INFO kernel: [ 9.185414] pci 0000:00:18.7: [15ad:07a0]
```

```
type 01 class 0x060400
2024-04-26T16:01:06.459476Z INFO kernel: [ 9.187798] pci 0000:00:18.7: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.459479Z INFO kernel: [ 9.190682] pci_bus 0000:01: extended config
space not accessible
2024-04-26T16:01:06.459482Z INFO kernel: [ 9.192878] pci 0000:00:01.0: PCI bridge to
[bus 01]
2024-04-26T16:01:06.459484Z INFO kernel: [ 9.194087] pci_bus 0000:02: extended config
space not accessible
2024-04-26T16:01:06.459486Z INFO kernel: [ 9.194696] acpiphp: Slot [32] registered
2024-04-26T16:01:06.459533Z INFO kernel: [ 9.195657] acpiphp: Slot [33] registered
2024-04-26T16:01:06.459538Z INFO kernel: [ 9.196649] acpiphp: Slot [34] registered
2024-04-26T16:01:06.459541Z INFO kernel: [ 9.198677] acpiphp: Slot [35] registered
2024-04-26T16:01:06.459543Z INFO kernel: [ 9.199663] acpiphp: Slot [36] registered
2024-04-26T16:01:06.459546Z INFO kernel: [ 9.200657] acpiphp: Slot [37] registered
2024-04-26T16:01:06.459548Z INFO kernel: [ 9.201725] acpiphp: Slot [38] registered
2024-04-26T16:01:06.460085Z INFO kernel: [ 9.202654] acpiphp: Slot [39] registered
2024-04-26T16:01:06.460143Z INFO kernel: [ 9.203649] acpiphp: Slot [40] registered
2024-04-26T16:01:06.460189Z INFO kernel: [ 9.204650] acpiphp: Slot [41] registered
2024-04-26T16:01:06.460196Z INFO kernel: [ 9.206680] acpiphp: Slot [42] registered
2024-04-26T16:01:06.460199Z INFO kernel: [ 9.207652] acpiphp: Slot [43] registered
2024-04-26T16:01:06.460201Z INFO kernel: [ 9.208650] acpiphp: Slot [44] registered
2024-04-26T16:01:06.460204Z INFO kernel: [ 9.209686] acpiphp: Slot [45] registered
2024-04-26T16:01:06.460273Z INFO kernel: [ 9.210680] acpiphp: Slot [46] registered
2024-04-26T16:01:06.460279Z INFO kernel: [ 9.211650] acpiphp: Slot [47] registered
2024-04-26T16:01:06.460282Z INFO kernel: [ 9.212650] acpiphp: Slot [48] registered
2024-04-26T16:01:06.460284Z INFO kernel: [ 9.214622] acpiphp: Slot [49] registered
2024-04-26T16:01:06.460286Z INFO kernel: [ 9.215650] acpiphp: Slot [50] registered
2024-04-26T16:01:06.460289Z INFO kernel: [ 9.216649] acpiphp: Slot [51] registered
2024-04-26T16:01:06.460336Z INFO kernel: [ 9.217677] acpiphp: Slot [52] registered
2024-04-26T16:01:06.460341Z INFO kernel: [ 9.218727] acpiphp: Slot [53] registered
2024-04-26T16:01:06.460344Z INFO kernel: [ 9.219678] acpiphp: Slot [54] registered
2024-04-26T16:01:06.460347Z INFO kernel: [ 9.220650] acpiphp: Slot [55] registered
2024-04-26T16:01:06.460349Z INFO kernel: [ 9.222631] acpiphp: Slot [56] registered
2024-04-26T16:01:06.460352Z INFO kernel: [ 9.223661] acpiphp: Slot [57] registered
2024-04-26T16:01:06.460354Z INFO kernel: [ 9.224652] acpiphp: Slot [58] registered
2024-04-26T16:01:06.460399Z INFO kernel: [ 9.225661] acpiphp: Slot [59] registered
2024-04-26T16:01:06.460405Z INFO kernel: [ 9.226684] acpiphp: Slot [60] registered
2024-04-26T16:01:06.460407Z INFO kernel: [ 9.227649] acpiphp: Slot [61] registered
2024-04-26T16:01:06.460452Z INFO kernel: [ 9.228661] acpiphp: Slot [62] registered
2024-04-26T16:01:06.460461Z INFO kernel: [ 9.229679] acpiphp: Slot [63] registered
2024-04-26T16:01:06.460465Z INFO kernel: [ 9.231616] pci 0000:02:00.0: [15ad:0774]
type 00 class 0x0c0300
2024-04-26T16:01:06.460534Z INFO kernel: [ 9.236107] pci 0000:02:00.0: reg 0x20: [io
0x1040-0x105f]
2024-04-26T16:01:06.460539Z INFO kernel: [ 9.239674] pci 0000:02:01.0: [8086:100f]
type 00 class 0x020000
2024-04-26T16:01:06.460540Z INFO kernel: [ 9.242109] pci 0000:02:01.0: reg 0x10: [mem
0xfc000000-0xfc01ffff 64bit]
2024-04-26T16:01:06.460542Z INFO kernel: [ 9.244126] pci 0000:02:01.0: reg 0x18: [mem
0xfc020000-0xfc02ffff 64bit]
2024-04-26T16:01:06.460543Z INFO kernel: [ 9.245639] pci 0000:02:01.0: reg 0x20: [io
0x1000-0x103f]
2024-04-26T16:01:06.460544Z INFO kernel: [ 9.248639] pci 0000:02:01.0: reg 0x30: [mem
0xffff0000-0xffffffff pref]
2024-04-26T16:01:06.460594Z INFO kernel: [ 9.250355] pci 0000:02:01.0: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.460599Z INFO kernel: [ 9.252144] pci 0000:02:02.0: [15ad:1977]
type 00 class 0x040300
2024-04-26T16:01:06.460601Z INFO kernel: [ 9.253361] pci 0000:02:02.0: reg 0x10: [mem
0xfc040000-0xfc043fff 64bit]
2024-04-26T16:01:06.460602Z INFO kernel: [ 9.257807] pci 0000:02:02.0: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.460604Z INFO kernel: [ 9.260487] pci 0000:02:03.0: [15ad:0770]
type 00 class 0x0c0320
2024-04-26T16:01:06.460606Z INFO kernel: [ 9.261794] pci 0000:02:03.0: reg 0x10: [mem
0xfc044000-0xfc044fff]
2024-04-26T16:01:06.460608Z INFO kernel: [ 9.268136] pci 0000:00:11.0: PCI bridge to
[bus 02] (subtractive decode)
```

```
2024-04-26T16:01:06.460663Z INFO kernel: [ 9.268664] pci 0000:00:11.0: bridge window
[io 0x1000-0x1fff]
2024-04-26T16:01:06.460671Z INFO kernel: [ 9.270637] pci 0000:00:11.0: bridge window
[mem 0xfc000000-0xfc9ffffff]
2024-04-26T16:01:06.460674Z INFO kernel: [ 9.271686] pci 0000:00:11.0: bridge window
[mem 0xf8000000-0xf84ffffff 64bit pref]
2024-04-26T16:01:06.460677Z INFO kernel: [ 9.272620] pci 0000:00:11.0: bridge window
[io 0x0d00-0xffff window] (subtractive decode)
2024-04-26T16:01:06.460679Z INFO kernel: [ 9.273617] pci 0000:00:11.0: bridge window
[io 0x0000-0x0cf7 window] (subtractive decode)
2024-04-26T16:01:06.460686Z INFO kernel: [ 9.274617] pci 0000:00:11.0: bridge window
[mem 0xfef00000-0xffdfffffff window] (subtractive decode)
2024-04-26T16:01:06.461688Z INFO kernel: [ 9.275616] pci 0000:00:11.0: bridge window
[mem 0xfed45000-0xfedffffff window] (subtractive decode)
2024-04-26T16:01:06.461698Z INFO kernel: [ 9.276639] pci 0000:00:11.0: bridge window
[mem 0xfec10000-0xfed3ffff window] (subtractive decode)
2024-04-26T16:01:06.461701Z INFO kernel: [ 9.278615] pci 0000:00:11.0: bridge window
[mem 0xfa400000-0xfefbffffff window] (subtractive decode)
2024-04-26T16:01:06.461704Z INFO kernel: [ 9.279616] pci 0000:00:11.0: bridge window
[mem 0xf0000000-0xfa3ffffff pref window] (subtractive decode)
2024-04-26T16:01:06.461706Z INFO kernel: [ 9.280625] pci 0000:00:11.0: bridge window
[mem 0xc0000000-0xefffffff window] (subtractive decode)
2024-04-26T16:01:06.461768Z INFO kernel: [ 9.281638] pci 0000:00:11.0: bridge window
[mem 0x000a0000-0x000bffff window] (subtractive decode)
2024-04-26T16:01:06.461774Z INFO kernel: [ 9.282616] pci 0000:00:11.0: bridge window
[mem 0x000c4000-0x000c7fff window] (subtractive decode)
2024-04-26T16:01:06.461777Z INFO kernel: [ 9.283616] pci 0000:00:11.0: bridge window
[mem 0x000c8000-0x000cbfff window] (subtractive decode)
2024-04-26T16:01:06.461780Z INFO kernel: [ 9.284616] pci 0000:00:11.0: bridge window
[mem 0x000d4000-0x000d7fff window] (subtractive decode)
2024-04-26T16:01:06.461782Z INFO kernel: [ 9.285619] pci 0000:00:11.0: bridge window
[mem 0x000d8000-0x000dbfff window] (subtractive decode)
2024-04-26T16:01:06.461785Z INFO kernel: [ 9.286616] pci 0000:00:11.0: bridge window
[mem 0x000e4000-0x000e7fff window] (subtractive decode)
2024-04-26T16:01:06.461831Z INFO kernel: [ 9.287616] pci 0000:00:11.0: bridge window
[mem 0x000e8000-0x000ebfff window] (subtractive decode)
2024-04-26T16:01:06.461837Z INFO kernel: [ 9.288616] pci 0000:00:11.0: bridge window
[mem 0x000ec000-0x000effff window] (subtractive decode)
2024-04-26T16:01:06.461840Z INFO kernel: [ 9.292026] pci 0000:03:00.0: [15ad:07f0]
type 00 class 0x010802
2024-04-26T16:01:06.461842Z INFO kernel: [ 9.293638] pci 0000:03:00.0: reg 0x10: [mem
0xfea00000-0xfea03fff 64bit]
2024-04-26T16:01:06.461845Z INFO kernel: [ 9.296364] pci 0000:03:00.0: reg 0x18: [io
0x3000-0x3007]
2024-04-26T16:01:06.461847Z INFO kernel: [ 9.299639] pci 0000:03:00.0: reg 0x30: [mem
0xfffffe00-0xffffffff pref]
2024-04-26T16:01:06.461892Z INFO kernel: [ 9.302463] pci 0000:03:00.0: PME# supported
from D0 D3hot D3cold
2024-04-26T16:01:06.461899Z INFO kernel: [ 9.304092] pci 0000:03:00.0: disabling ASPM
on pre-1.1 PCIe device. You can enable it with 'pcie_aspm=force'
2024-04-26T16:01:06.461903Z INFO kernel: [ 9.304725] pci 0000:00:15.0: PCI bridge to
[bus 03]
2024-04-26T16:01:06.461906Z INFO kernel: [ 9.305705] pci 0000:00:15.0: bridge window
[io 0x3000-0x3fff]
2024-04-26T16:01:06.461909Z INFO kernel: [ 9.306663] pci 0000:00:15.0: bridge window
[mem 0xfea00000-0xfeafffff]
2024-04-26T16:01:06.461913Z INFO kernel: [ 9.308370] pci 0000:00:15.1: PCI bridge to
[bus 04]
2024-04-26T16:01:06.461982Z INFO kernel: [ 9.308704] pci 0000:00:15.1: bridge window
[mem 0xfe900000-0xfe9ffffff]
2024-04-26T16:01:06.462361Z INFO kernel: [ 9.310639] pci 0000:00:15.1: bridge window
[mem 0xfa300000-0xfa3ffffff 64bit pref]
2024-04-26T16:01:06.462370Z INFO kernel: [ 9.312324] pci 0000:00:15.2: PCI bridge to
[bus 05]
2024-04-26T16:01:06.462374Z INFO kernel: [ 9.312704] pci 0000:00:15.2: bridge window
[mem 0xfe800000-0xfe8ffffff]
2024-04-26T16:01:06.462377Z INFO kernel: [ 9.314604] pci 0000:00:15.2: bridge window
[mem 0xfa200000-0xfa2ffffff 64bit pref]
2024-04-26T16:01:06.462380Z INFO kernel: [ 9.317287] pci 0000:00:15.3: PCI bridge to
```

```
[bus 06]
2024-04-26T16:01:06.462464Z INFO kernel: [ 9.317708] pci 0000:00:15.3: bridge window
[mem 0xfe700000-0xfe7ffffff]
2024-04-26T16:01:06.462471Z INFO kernel: [ 9.318688] pci 0000:00:15.3: bridge window
[mem 0xfa100000-0xfa1ffffff 64bit pref]
2024-04-26T16:01:06.462475Z INFO kernel: [ 9.320344] pci 0000:00:15.4: PCI bridge to
[bus 07]
2024-04-26T16:01:06.462478Z INFO kernel: [ 9.320705] pci 0000:00:15.4: bridge window
[mem 0xfe600000-0xfe6ffffff]
2024-04-26T16:01:06.462481Z INFO kernel: [ 9.321694] pci 0000:00:15.4: bridge window
[mem 0xfa000000-0xfa0ffffff 64bit pref]
2024-04-26T16:01:06.462484Z INFO kernel: [ 9.323756] pci 0000:00:15.5: PCI bridge to
[bus 08]
2024-04-26T16:01:06.462488Z INFO kernel: [ 9.325586] pci 0000:00:15.5: bridge window
[mem 0xfe500000-0xfe5ffffff]
2024-04-26T16:01:06.462543Z INFO kernel: [ 9.325688] pci 0000:00:15.5: bridge window
[mem 0xf9f00000-0xf9ffffff 64bit pref]
2024-04-26T16:01:06.462550Z INFO kernel: [ 9.327778] pci 0000:00:15.6: PCI bridge to
[bus 09]
2024-04-26T16:01:06.462554Z INFO kernel: [ 9.328793] pci 0000:00:15.6: bridge window
[mem 0xfe400000-0xfe4ffffff]
2024-04-26T16:01:06.462557Z INFO kernel: [ 9.329687] pci 0000:00:15.6: bridge window
[mem 0xf9e00000-0xf9effffff 64bit pref]
2024-04-26T16:01:06.462560Z INFO kernel: [ 9.331767] pci 0000:00:15.7: PCI bridge to
[bus 0a]
2024-04-26T16:01:06.462563Z INFO kernel: [ 9.332785] pci 0000:00:15.7: bridge window
[mem 0xfe300000-0xfe3ffffff]
2024-04-26T16:01:06.462619Z INFO kernel: [ 9.333688] pci 0000:00:15.7: bridge window
[mem 0xf9d00000-0xf9dffffff 64bit pref]
2024-04-26T16:01:06.462631Z INFO kernel: [ 9.335712] pci 0000:00:16.0: PCI bridge to
[bus 0b]
2024-04-26T16:01:06.462635Z INFO kernel: [ 9.336788] pci 0000:00:16.0: bridge window
[mem 0xfe200000-0xfe2ffffff]
2024-04-26T16:01:06.462638Z INFO kernel: [ 9.337687] pci 0000:00:16.0: bridge window
[mem 0xf9c00000-0xf9cffffff 64bit pref]
2024-04-26T16:01:06.462640Z INFO kernel: [ 9.339795] pci 0000:00:16.1: PCI bridge to
[bus 0c]
2024-04-26T16:01:06.462642Z INFO kernel: [ 9.340764] pci 0000:00:16.1: bridge window
[mem 0xfe100000-0xfe1ffffff]
2024-04-26T16:01:06.483330Z INFO kernel: [ 9.341702] pci 0000:00:16.1: bridge window
[mem 0xf9b00000-0xf9bffffff 64bit pref]
2024-04-26T16:01:06.483352Z INFO kernel: [ 9.343784] pci 0000:00:16.2: PCI bridge to
[bus 0d]
2024-04-26T16:01:06.483356Z INFO kernel: [ 9.344787] pci 0000:00:16.2: bridge window
[mem 0xfe000000-0xfe0ffffff]
2024-04-26T16:01:06.483359Z INFO kernel: [ 9.345688] pci 0000:00:16.2: bridge window
[mem 0xf9a00000-0xf9affffff 64bit pref]
2024-04-26T16:01:06.483366Z INFO kernel: [ 9.348224] pci 0000:00:16.3: PCI bridge to
[bus 0e]
2024-04-26T16:01:06.483370Z INFO kernel: [ 9.349659] pci 0000:00:16.3: bridge window
[mem 0xfdf00000-0xfdfffffff]
2024-04-26T16:01:06.483374Z INFO kernel: [ 9.350688] pci 0000:00:16.3: bridge window
[mem 0xf9900000-0xf99ffffff 64bit pref]
2024-04-26T16:01:06.483394Z INFO kernel: [ 9.353342] pci 0000:00:16.4: PCI bridge to
[bus 0f]
2024-04-26T16:01:06.483402Z INFO kernel: [ 9.353704] pci 0000:00:16.4: bridge window
[mem 0xfde00000-0xfdeffffff]
2024-04-26T16:01:06.483408Z INFO kernel: [ 9.355661] pci 0000:00:16.4: bridge window
[mem 0xf9800000-0xf98ffffff 64bit pref]
2024-04-26T16:01:06.483410Z INFO kernel: [ 9.357306] pci 0000:00:16.5: PCI bridge to
[bus 10]
2024-04-26T16:01:06.483413Z INFO kernel: [ 9.357704] pci 0000:00:16.5: bridge window
[mem 0xfdd00000-0xfddffffff]
2024-04-26T16:01:06.483416Z INFO kernel: [ 9.358689] pci 0000:00:16.5: bridge window
[mem 0xf9700000-0xf97ffffff 64bit pref]
2024-04-26T16:01:06.483429Z INFO kernel: [ 9.360357] pci 0000:00:16.6: PCI bridge to
[bus 11]
2024-04-26T16:01:06.483433Z INFO kernel: [ 9.360705] pci 0000:00:16.6: bridge window
[mem 0xfdc00000-0xfdcffffff]
```

```
2024-04-26T16:01:06.483437Z INFO kernel: [ 9.361687] pci 0000:00:16.6: bridge window
[mem 0xf9600000-0xf96fffff 64bit pref]
2024-04-26T16:01:06.483440Z INFO kernel: [ 9.363331] pci 0000:00:16.7: PCI bridge to
[bus 12]
2024-04-26T16:01:06.483443Z INFO kernel: [ 9.363704] pci 0000:00:16.7: bridge window
[mem 0xfdb00000-0xfdbffffff]
2024-04-26T16:01:06.483446Z INFO kernel: [ 9.364688] pci 0000:00:16.7: bridge window
[mem 0xf9500000-0xf95fffff 64bit pref]
2024-04-26T16:01:06.483449Z INFO kernel: [ 9.366310] pci 0000:00:17.0: PCI bridge to
[bus 13]
2024-04-26T16:01:06.483460Z INFO kernel: [ 9.366727] pci 0000:00:17.0: bridge window
[mem 0xfda00000-0xfdaffffff]
2024-04-26T16:01:06.483464Z INFO kernel: [ 9.367687] pci 0000:00:17.0: bridge window
[mem 0xf9400000-0xf94fffff 64bit pref]
2024-04-26T16:01:06.483468Z INFO kernel: [ 9.370344] pci 0000:00:17.1: PCI bridge to
[bus 14]
2024-04-26T16:01:06.483471Z INFO kernel: [ 9.370710] pci 0000:00:17.1: bridge window
[mem 0xfd900000-0xfd9ffffff]
2024-04-26T16:01:06.483474Z INFO kernel: [ 9.371788] pci 0000:00:17.1: bridge window
[mem 0xf9300000-0xf93fffff 64bit pref]
2024-04-26T16:01:06.483482Z INFO kernel: [ 9.373742] pci 0000:00:17.2: PCI bridge to
[bus 15]
2024-04-26T16:01:06.483492Z INFO kernel: [ 9.374755] pci 0000:00:17.2: bridge window
[mem 0xfd800000-0xfd8ffffff]
2024-04-26T16:01:06.483496Z INFO kernel: [ 9.375687] pci 0000:00:17.2: bridge window
[mem 0xf9200000-0xf92fffff 64bit pref]
2024-04-26T16:01:06.483499Z INFO kernel: [ 9.377780] pci 0000:00:17.3: PCI bridge to
[bus 16]
2024-04-26T16:01:06.483502Z INFO kernel: [ 9.378765] pci 0000:00:17.3: bridge window
[mem 0xfd700000-0xfd7ffffff]
2024-04-26T16:01:06.483505Z INFO kernel: [ 9.379685] pci 0000:00:17.3: bridge window
[mem 0xf9100000-0xf91fffff 64bit pref]
2024-04-26T16:01:06.483510Z INFO kernel: [ 9.381668] pci 0000:00:17.4: PCI bridge to
[bus 17]
2024-04-26T16:01:06.483521Z INFO kernel: [ 9.382720] pci 0000:00:17.4: bridge window
[mem 0xfd600000-0xfd6ffffff]
2024-04-26T16:01:06.483524Z INFO kernel: [ 9.383685] pci 0000:00:17.4: bridge window
[mem 0xf9000000-0xf90fffff 64bit pref]
2024-04-26T16:01:06.483522Z INFO kernel: [ 9.386328] pci 0000:00:17.5: PCI bridge to
[bus 18]
2024-04-26T16:01:06.483572Z INFO kernel: [ 9.386708] pci 0000:00:17.5: bridge window
[mem 0xfd500000-0xfd5ffffff]
2024-04-26T16:01:06.483575Z INFO kernel: [ 9.387688] pci 0000:00:17.5: bridge window
[mem 0xf8f00000-0xf8ffffff 64bit pref]
2024-04-26T16:01:06.483595Z INFO kernel: [ 9.389362] pci 0000:00:17.6: PCI bridge to
[bus 19]
2024-04-26T16:01:06.483598Z INFO kernel: [ 9.389704] pci 0000:00:17.6: bridge window
[mem 0xfd400000-0xfd4ffffff]
2024-04-26T16:01:06.483646Z INFO kernel: [ 9.390687] pci 0000:00:17.6: bridge window
[mem 0xf8e00000-0xf8efffff 64bit pref]
2024-04-26T16:01:06.483668Z INFO kernel: [ 9.392333] pci 0000:00:17.7: PCI bridge to
[bus 1a]
2024-04-26T16:01:06.483672Z INFO kernel: [ 9.392705] pci 0000:00:17.7: bridge window
[mem 0xfd300000-0xfd3ffffff]
2024-04-26T16:01:06.483675Z INFO kernel: [ 9.393689] pci 0000:00:17.7: bridge window
[mem 0xf8d00000-0xf8dfffff 64bit pref]
2024-04-26T16:01:06.483678Z INFO kernel: [ 9.395325] pci 0000:00:18.0: PCI bridge to
[bus 1b]
2024-04-26T16:01:06.483681Z INFO kernel: [ 9.395705] pci 0000:00:18.0: bridge window
[mem 0xfd200000-0xfd2ffffff]
2024-04-26T16:01:06.483694Z INFO kernel: [ 9.396687] pci 0000:00:18.0: bridge window
[mem 0xf8c00000-0xf8cfffff 64bit pref]
2024-04-26T16:01:06.483699Z INFO kernel: [ 9.398342] pci 0000:00:18.1: PCI bridge to
[bus 1c]
2024-04-26T16:01:06.483702Z INFO kernel: [ 9.398704] pci 0000:00:18.1: bridge window
[mem 0xfd100000-0xfd1ffffff]
2024-04-26T16:01:06.483704Z INFO kernel: [ 9.399687] pci 0000:00:18.1: bridge window
[mem 0xf8b00000-0xf8bfffff 64bit pref]
2024-04-26T16:01:06.483707Z INFO kernel: [ 9.401331] pci 0000:00:18.2: PCI bridge to
```

```
[bus 1d]
2024-04-26T16:01:06.483710Z INFO kernel: [ 9.401704] pci 0000:00:18.2: bridge window
[mem 0xfd000000-0xfd0fffff]
2024-04-26T16:01:06.483712Z INFO kernel: [ 9.402688] pci 0000:00:18.2: bridge window
[mem 0xf8a00000-0xf8afffff 64bit pref]
2024-04-26T16:01:06.483721Z INFO kernel: [ 9.404316] pci 0000:00:18.3: PCI bridge to
[bus 1e]
2024-04-26T16:01:06.483725Z INFO kernel: [ 9.404704] pci 0000:00:18.3: bridge window
[mem 0xfc000000-0xfcfffff]
2024-04-26T16:01:06.483728Z INFO kernel: [ 9.406685] pci 0000:00:18.3: bridge window
[mem 0xf8900000-0xf89fffff 64bit pref]
2024-04-26T16:01:06.483731Z INFO kernel: [ 9.408287] pci 0000:00:18.4: PCI bridge to
[bus 1f]
2024-04-26T16:01:06.483734Z INFO kernel: [ 9.408704] pci 0000:00:18.4: bridge window
[mem 0xfce00000-0xfcefffff]
2024-04-26T16:01:06.483737Z INFO kernel: [ 9.410642] pci 0000:00:18.4: bridge window
[mem 0xf8800000-0xf88fffff 64bit pref]
2024-04-26T16:01:06.483747Z INFO kernel: [ 9.412712] pci 0000:00:18.5: PCI bridge to
[bus 20]
2024-04-26T16:01:06.483752Z INFO kernel: [ 9.413724] pci 0000:00:18.5: bridge window
[mem 0xfcd00000-0xfcdfffff]
2024-04-26T16:01:06.483754Z INFO kernel: [ 9.414761] pci 0000:00:18.5: bridge window
[mem 0xf8700000-0xf87fffff 64bit pref]
2024-04-26T16:01:06.483758Z INFO kernel: [ 9.416985] pci 0000:00:18.6: PCI bridge to
[bus 21]
2024-04-26T16:01:06.483761Z INFO kernel: [ 9.417705] pci 0000:00:18.6: bridge window
[mem 0xfcc00000-0xfccfffff]
2024-04-26T16:01:06.483763Z INFO kernel: [ 9.418718] pci 0000:00:18.6: bridge window
[mem 0xf8600000-0xf86fffff 64bit pref]
2024-04-26T16:01:06.483776Z INFO kernel: [ 9.421011] pci 0000:00:18.7: PCI bridge to
[bus 22]
2024-04-26T16:01:06.483780Z INFO kernel: [ 9.421704] pci 0000:00:18.7: bridge window
[mem 0xfcb00000-0xfcbfffff]
2024-04-26T16:01:06.483784Z INFO kernel: [ 9.422726] pci 0000:00:18.7: bridge window
[mem 0xf8500000-0xf85fffff 64bit pref]
2024-04-26T16:01:06.483787Z DEBUG kernel: [ 9.428094] pci_bus 0000:00: on NUMA node 0
2024-04-26T16:01:06.483790Z INFO kernel: [ 9.428500] ACPI: PCI: Interrupt link LNKA
configured for IRQ 0
2024-04-26T16:01:06.483793Z INFO kernel: [ 9.428616] ACPI: PCI: Interrupt link LNKA
disabled
2024-04-26T16:01:06.483796Z INFO kernel: [ 9.429752] ACPI: PCI: Interrupt link LNKB
configured for IRQ 0
2024-04-26T16:01:06.483808Z INFO kernel: [ 9.430619] ACPI: PCI: Interrupt link LNKB
disabled
2024-04-26T16:01:06.483812Z INFO kernel: [ 9.431754] ACPI: PCI: Interrupt link LNKC
configured for IRQ 0
2024-04-26T16:01:06.483814Z INFO kernel: [ 9.432630] ACPI: PCI: Interrupt link LNKC
disabled
2024-04-26T16:01:06.483817Z INFO kernel: [ 9.434603] ACPI: PCI: Interrupt link LNKD
configured for IRQ 0
2024-04-26T16:01:06.483820Z INFO kernel: [ 9.435638] ACPI: PCI: Interrupt link LNKD
disabled
2024-04-26T16:01:06.483824Z NOTICE kernel: [ 9.496867] SCSI subsystem initialized
2024-04-26T16:01:06.483834Z DEBUG kernel: [ 9.498790] libata version 3.00 loaded.
2024-04-26T16:01:06.483838Z INFO kernel: [ 9.499047] ACPI: bus type USB registered
2024-04-26T16:01:06.483841Z INFO kernel: [ 9.499662] usbcore: registered new interface
driver usbfs
2024-04-26T16:01:06.483847Z INFO kernel: [ 9.500651] usbcore: registered new interface
driver hub
2024-04-26T16:01:06.483850Z INFO kernel: [ 9.501632] usbcore: registered new device
driver usb
2024-04-26T16:01:06.483853Z INFO kernel: [ 9.502857] mc: Linux media interface: v0.10
2024-04-26T16:01:06.483856Z INFO kernel: [ 9.503636] videodev: Linux video capture
interface: v2.00
2024-04-26T16:01:06.483889Z INFO kernel: [ 9.504840] Registered efivars operations
2024-04-26T16:01:06.483914Z INFO kernel: [ 9.505921] chromeos_acpi: installed
2024-04-26T16:01:06.484329Z INFO kernel: [ 9.506768] Advanced Linux Sound Architecture
Driver Initialized.
2024-04-26T16:01:06.484337Z INFO kernel: [ 9.509812] PCI: Using ACPI for IRQ routing
```



```
2024-04-26T16:01:06.484343Z DEBUG kernel: [ 9.581394] PCI: pci_cache_line_size set to
64 bytes
2024-04-26T16:01:06.484348Z DEBUG kernel: [ 9.584434] e820: reserve RAM buffer [mem
0x0e5e8000-0xffffffff]
2024-04-26T16:01:06.484369Z DEBUG kernel: [ 9.584464] e820: reserve RAM buffer [mem
0x0ef9a000-0xffffffff]
2024-04-26T16:01:06.484375Z DEBUG kernel: [ 9.584479] e820: reserve RAM buffer [mem
0x0efad000-0xffffffff]
2024-04-26T16:01:06.484379Z DEBUG kernel: [ 9.584494] e820: reserve RAM buffer [mem
0x0fee5000-0xffffffff]
2024-04-26T16:01:06.484382Z DEBUG kernel: [ 9.584508] e820: reserve RAM buffer [mem
0x0ff74000-0xffffffff]
2024-04-26T16:01:06.484385Z DEBUG kernel: [ 9.584524] e820: reserve RAM buffer [mem
0x1c9c00000-0x1cbffffff]
2024-04-26T16:01:06.484388Z INFO kernel: [ 9.585636] hpet0: at MMIO 0xfed00000, IRQs
2, 8, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0
2024-04-26T16:01:06.484400Z INFO kernel: [ 9.587616] hpet0: 16 comparators, 64-bit
14.318180 MHz counter
2024-04-26T16:01:06.484404Z INFO kernel: [ 9.592788] clocksource: Switched to
clocksource tsc-early
2024-04-26T16:01:06.484407Z NOTICE kernel: [ 10.134864] VFS: Disk quotas dquot_6.6.0
2024-04-26T16:01:06.484410Z INFO kernel: [ 10.136958] VFS: Dquot-cache hash table
entries: 512 (order 0, 4096 bytes)
2024-04-26T16:01:06.484413Z INFO kernel: [ 10.139539] pnp: PnP ACPI init
2024-04-26T16:01:06.484416Z INFO kernel: [ 10.140855] system 00:00: [io 0x0440-0x047f]
has been reserved
2024-04-26T16:01:06.484419Z INFO kernel: [ 10.142441] system 00:00: [io 0x5658-0x5659]
has been reserved
2024-04-26T16:01:06.484429Z INFO kernel: [ 10.144020] system 00:00: [io 0x5670] has
been reserved
2024-04-26T16:01:06.484433Z INFO kernel: [ 10.145413] system 00:00: [io 0x0cf0-0x0cf1]
has been reserved
2024-04-26T16:01:06.484436Z INFO kernel: [ 10.147731] system 00:04: [mem 0xfed00000-
0xfed003ff] has been reserved
2024-04-26T16:01:06.484439Z INFO kernel: [ 10.185861] system 00:05: [io 0x0400-0x041f]
has been reserved
2024-04-26T16:01:06.484442Z INFO kernel: [ 10.187444] system 00:05: [mem 0xe0000000-
0xe7ffffff] has been reserved
2024-04-26T16:01:06.484446Z INFO kernel: [ 10.189177] system 00:05: [mem 0xffc00000-
0xffdfffff] could not be reserved
2024-04-26T16:01:06.484456Z INFO kernel: [ 10.294887] pnp: PnP ACPI: found 6 devices
2024-04-26T16:01:06.484460Z INFO kernel: [ 10.339473] clocksource: acpi_pm: mask:
0xffffffff max_cycles: 0xffffffff, max_idle_ns: 2085701024 ns
2024-04-26T16:01:06.484463Z INFO kernel: [ 10.341955] NET: Registered PF_INET protocol
family
2024-04-26T16:01:06.484466Z INFO kernel: [ 10.393089] IP idents hash table entries:
131072 (order: 8, 1048576 bytes, linear)
2024-04-26T16:01:06.484469Z INFO kernel: [ 10.398301] tcp_listen_portaddr_hash hash
table entries: 4096 (order: 4, 65536 bytes, linear)
2024-04-26T16:01:06.484473Z INFO kernel: [ 10.435424] Table-perturb hash table entries:
65536 (order: 6, 262144 bytes, linear)
2024-04-26T16:01:06.484475Z INFO kernel: [ 10.437435] TCP established hash table
entries: 65536 (order: 7, 524288 bytes, linear)
2024-04-26T16:01:06.484486Z INFO kernel: [ 10.448882] TCP bind hash table entries:
65536 (order: 8, 1048576 bytes, linear)
2024-04-26T16:01:06.484490Z INFO kernel: [ 10.533842] TCP: Hash tables configured
(established 65536 bind 65536)
2024-04-26T16:01:06.484492Z INFO kernel: [ 10.536398] UDP hash table entries: 4096
(order: 5, 131072 bytes, linear)
2024-04-26T16:01:06.484494Z INFO kernel: [ 10.538876] UDP-Lite hash table entries: 4096
(order: 5, 131072 bytes, linear)
2024-04-26T16:01:06.484497Z INFO kernel: [ 10.541490] NET: Registered PF_UNIX/PF_LOCAL
protocol family
2024-04-26T16:01:06.484500Z INFO kernel: [ 10.543024] pci 0000:00:10.0: can't claim BAR
6 [mem 0xffffc000-0xffffffff pref]: no compatible bridge window
2024-04-26T16:01:06.484511Z INFO kernel: [ 10.545718] pci 0000:02:01.0: can't claim BAR
6 [mem 0xffff0000-0xffffffff pref]: no compatible bridge window
2024-04-26T16:01:06.484513Z INFO kernel: [ 10.548270] pci 0000:03:00.0: can't claim BAR
6 [mem 0xffffe000-0xffffffff pref]: no compatible bridge window
```

```
2024-04-26T16:01:06.484516Z INFO kernel: [ 10.584579] pci 0000:00:15.0: bridge window
[mem 0x00100000-0x000fffff 64bit pref] to [bus 03] add_size 200000 add_align 100000
2024-04-26T16:01:06.484520Z INFO kernel: [ 10.588316] pci 0000:00:15.1: bridge window
[io 0x1000-0x0fff] to [bus 04] add_size 1000
2024-04-26T16:01:06.484523Z INFO kernel: [ 10.590440] pci 0000:00:15.2: bridge window
[io 0x1000-0x0fff] to [bus 05] add_size 1000
2024-04-26T16:01:06.484526Z INFO kernel: [ 10.592537] pci 0000:00:15.3: bridge window
[io 0x1000-0x0fff] to [bus 06] add_size 1000
2024-04-26T16:01:06.484536Z INFO kernel: [ 10.594708] pci 0000:00:15.4: bridge window
[io 0x1000-0x0fff] to [bus 07] add_size 1000
2024-04-26T16:01:06.484540Z INFO kernel: [ 10.596800] pci 0000:00:15.5: bridge window
[io 0x1000-0x0fff] to [bus 08] add_size 1000
2024-04-26T16:01:06.484544Z INFO kernel: [ 10.598897] pci 0000:00:15.6: bridge window
[io 0x1000-0x0fff] to [bus 09] add_size 1000
2024-04-26T16:01:06.484547Z INFO kernel: [ 10.634374] pci 0000:00:15.7: bridge window
[io 0x1000-0x0fff] to [bus 0a] add_size 1000
2024-04-26T16:01:06.484549Z INFO kernel: [ 10.636473] pci 0000:00:16.0: bridge window
[io 0x1000-0x0fff] to [bus 0b] add_size 1000
2024-04-26T16:01:06.484553Z INFO kernel: [ 10.638686] pci 0000:00:16.1: bridge window
[io 0x1000-0x0fff] to [bus 0c] add_size 1000
2024-04-26T16:01:06.484564Z INFO kernel: [ 10.640950] pci 0000:00:16.2: bridge window
[io 0x1000-0x0fff] to [bus 0d] add_size 1000
2024-04-26T16:01:06.484567Z INFO kernel: [ 10.643053] pci 0000:00:16.3: bridge window
[io 0x1000-0x0fff] to [bus 0e] add_size 1000
2024-04-26T16:01:06.484571Z INFO kernel: [ 10.645148] pci 0000:00:16.4: bridge window
[io 0x1000-0x0fff] to [bus 0f] add_size 1000
2024-04-26T16:01:06.484573Z INFO kernel: [ 10.647236] pci 0000:00:16.5: bridge window
[io 0x1000-0x0fff] to [bus 10] add_size 1000
2024-04-26T16:01:06.484577Z INFO kernel: [ 10.649325] pci 0000:00:16.6: bridge window
[io 0x1000-0x0fff] to [bus 11] add_size 1000
2024-04-26T16:01:06.484580Z INFO kernel: [ 10.684826] pci 0000:00:16.7: bridge window
[io 0x1000-0x0fff] to [bus 12] add_size 1000
2024-04-26T16:01:06.484591Z INFO kernel: [ 10.686967] pci 0000:00:17.0: bridge window
[io 0x1000-0x0fff] to [bus 13] add_size 1000
2024-04-26T16:01:06.484595Z INFO kernel: [ 10.689075] pci 0000:00:17.1: bridge window
[io 0x1000-0x0fff] to [bus 14] add_size 1000
2024-04-26T16:01:06.484598Z INFO kernel: [ 10.691181] pci 0000:00:17.2: bridge window
[io 0x1000-0x0fff] to [bus 15] add_size 1000
2024-04-26T16:01:06.484602Z INFO kernel: [ 10.693286] pci 0000:00:17.3: bridge window
[io 0x1000-0x0fff] to [bus 16] add_size 1000
2024-04-26T16:01:06.484605Z INFO kernel: [ 10.695386] pci 0000:00:17.4: bridge window
[io 0x1000-0x0fff] to [bus 17] add_size 1000
2024-04-26T16:01:06.484607Z INFO kernel: [ 10.697483] pci 0000:00:17.5: bridge window
[io 0x1000-0x0fff] to [bus 18] add_size 1000
2024-04-26T16:01:06.484610Z INFO kernel: [ 10.732977] pci 0000:00:17.6: bridge window
[io 0x1000-0x0fff] to [bus 19] add_size 1000
2024-04-26T16:01:06.484621Z INFO kernel: [ 10.735095] pci 0000:00:17.7: bridge window
[io 0x1000-0x0fff] to [bus 1a] add_size 1000
2024-04-26T16:01:06.484623Z INFO kernel: [ 10.737200] pci 0000:00:18.0: bridge window
[io 0x1000-0x0fff] to [bus 1b] add_size 1000
2024-04-26T16:01:06.484624Z INFO kernel: [ 10.739324] pci 0000:00:18.1: bridge window
[io 0x1000-0x0fff] to [bus 1c] add_size 1000
2024-04-26T16:01:06.484626Z INFO kernel: [ 10.741419] pci 0000:00:18.2: bridge window
[io 0x1000-0x0fff] to [bus 1d] add_size 1000
2024-04-26T16:01:06.484629Z INFO kernel: [ 10.743519] pci 0000:00:18.3: bridge window
[io 0x1000-0x0fff] to [bus 1e] add_size 1000
2024-04-26T16:01:06.484632Z INFO kernel: [ 10.745689] pci 0000:00:18.4: bridge window
[io 0x1000-0x0fff] to [bus 1f] add_size 1000
2024-04-26T16:01:06.484643Z INFO kernel: [ 10.747781] pci 0000:00:18.5: bridge window
[io 0x1000-0x0fff] to [bus 20] add_size 1000
2024-04-26T16:01:06.484646Z INFO kernel: [ 10.783257] pci 0000:00:18.6: bridge window
[io 0x1000-0x0fff] to [bus 21] add_size 1000
2024-04-26T16:01:06.484650Z INFO kernel: [ 10.785367] pci 0000:00:18.7: bridge window
[io 0x1000-0x0fff] to [bus 22] add_size 1000
2024-04-26T16:01:06.484653Z INFO kernel: [ 10.787496] pci 0000:00:15.0: BAR 9: assigned
[mem 0xfef00000-0xfffffff 64bit pref]
2024-04-26T16:01:06.484656Z INFO kernel: [ 10.789489] pci 0000:00:10.0: BAR 6: assigned
[mem 0xff100000-0xff103fff pref]
2024-04-26T16:01:06.484660Z INFO kernel: [ 10.791352] pci 0000:00:15.1: BAR 7: assigned
```

```
[io 0x4000-0x4fff]
2024-04-26T16:01:06.484662Z INFO kernel: [ 10.792943] pci 0000:00:15.2: BAR 7: assigned
[io 0x6000-0x6fff]
2024-04-26T16:01:06.484673Z INFO kernel: [ 10.794524] pci 0000:00:15.3: BAR 7: assigned
[io 0x7000-0x7fff]
2024-04-26T16:01:06.484675Z INFO kernel: [ 10.796108] pci 0000:00:15.4: BAR 7: assigned
[io 0x8000-0x8fff]
2024-04-26T16:01:06.484679Z INFO kernel: [ 10.797718] pci 0000:00:15.5: BAR 7: assigned
[io 0x9000-0x9fff]
2024-04-26T16:01:06.484681Z INFO kernel: [ 10.799309] pci 0000:00:15.6: BAR 7: assigned
[io 0xa000-0xafff]
2024-04-26T16:01:06.484682Z INFO kernel: [ 10.834438] pci 0000:00:15.7: BAR 7: assigned
[io 0xb000-0xbfff]
2024-04-26T16:01:06.484684Z INFO kernel: [ 10.836046] pci 0000:00:16.0: BAR 7: assigned
[io 0xc000-0xcfff]
2024-04-26T16:01:06.484692Z INFO kernel: [ 10.837725] pci 0000:00:16.1: BAR 7: assigned
[io 0xd000-0xdfff]
2024-04-26T16:01:06.484696Z INFO kernel: [ 10.839327] pci 0000:00:16.2: BAR 7: assigned
[io 0xe000-0xefff]
2024-04-26T16:01:06.484700Z INFO kernel: [ 10.840927] pci 0000:00:16.3: BAR 7: assigned
[io 0xf000-0xffff]
2024-04-26T16:01:06.484703Z INFO kernel: [ 10.842529] pci 0000:00:16.4: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.484706Z INFO kernel: [ 10.844096] pci 0000:00:16.4: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.484708Z INFO kernel: [ 10.845748] pci 0000:00:16.5: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.484719Z INFO kernel: [ 10.847318] pci 0000:00:16.5: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.484723Z INFO kernel: [ 10.848975] pci 0000:00:16.6: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.484726Z INFO kernel: [ 10.883973] pci 0000:00:16.6: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.484729Z INFO kernel: [ 10.885711] pci 0000:00:16.7: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.484732Z INFO kernel: [ 10.887288] pci 0000:00:16.7: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.484735Z INFO kernel: [ 10.888949] pci 0000:00:17.0: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.484764Z INFO kernel: [ 10.890526] pci 0000:00:17.0: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.484864Z INFO kernel: [ 10.892187] pci 0000:00:17.1: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.484913Z INFO kernel: [ 10.893760] pci 0000:00:17.1: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.484938Z INFO kernel: [ 10.895416] pci 0000:00:17.2: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.484943Z INFO kernel: [ 10.896989] pci 0000:00:17.2: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.485246Z INFO kernel: [ 10.898684] pci 0000:00:17.3: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.485254Z INFO kernel: [ 10.933719] pci 0000:00:17.3: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.485270Z INFO kernel: [ 10.935370] pci 0000:00:17.4: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.485274Z INFO kernel: [ 10.936941] pci 0000:00:17.4: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.485277Z INFO kernel: [ 10.938667] pci 0000:00:17.5: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.485280Z INFO kernel: [ 10.940237] pci 0000:00:17.5: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.485283Z INFO kernel: [ 10.941891] pci 0000:00:17.6: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.485286Z INFO kernel: [ 10.943461] pci 0000:00:17.6: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.485289Z INFO kernel: [ 10.945115] pci 0000:00:17.7: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.485300Z INFO kernel: [ 10.946684] pci 0000:00:17.7: BAR 7: failed
to assign [io size 0x1000]
```

```
2024-04-26T16:01:06.485304Z INFO kernel: [ 10.948338] pci 0000:00:18.0: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.485307Z INFO kernel: [ 10.983331] pci 0000:00:18.0: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.485310Z INFO kernel: [ 10.984981] pci 0000:00:18.1: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.485313Z INFO kernel: [ 10.986550] pci 0000:00:18.1: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.485315Z INFO kernel: [ 10.988201] pci 0000:00:18.2: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.485325Z INFO kernel: [ 10.989783] pci 0000:00:18.2: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.485328Z INFO kernel: [ 10.991428] pci 0000:00:18.3: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.485330Z INFO kernel: [ 10.992995] pci 0000:00:18.3: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.485332Z INFO kernel: [ 10.994666] pci 0000:00:18.4: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.485335Z INFO kernel: [ 10.996248] pci 0000:00:18.4: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.485337Z INFO kernel: [ 10.997911] pci 0000:00:18.5: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.485345Z INFO kernel: [ 10.999529] pci 0000:00:18.5: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.485348Z INFO kernel: [ 11.001221] pci 0000:00:18.6: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.485351Z INFO kernel: [ 11.002787] pci 0000:00:18.6: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.485353Z INFO kernel: [ 11.004439] pci 0000:00:18.7: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.485355Z INFO kernel: [ 11.006009] pci 0000:00:18.7: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.485358Z INFO kernel: [ 11.007661] pci 0000:00:18.7: BAR 7: assigned
[io 0x4000-0x4fff]
2024-04-26T16:01:06.485360Z INFO kernel: [ 11.009187] pci 0000:00:18.6: BAR 7: assigned
[io 0x6000-0x6fff]
2024-04-26T16:01:06.485369Z INFO kernel: [ 11.010729] pci 0000:00:18.5: BAR 7: assigned
[io 0x7000-0x7fff]
2024-04-26T16:01:06.485372Z INFO kernel: [ 11.012329] pci 0000:00:18.4: BAR 7: assigned
[io 0x8000-0x8fff]
2024-04-26T16:01:06.485375Z INFO kernel: [ 11.013870] pci 0000:00:18.3: BAR 7: assigned
[io 0x9000-0x9fff]
2024-04-26T16:01:06.498358Z INFO kernel: [ 11.015397] pci 0000:00:18.2: BAR 7: assigned
[io 0xa000-0xaaff]
2024-04-26T16:01:06.498379Z INFO kernel: [ 11.016976] pci 0000:00:18.1: BAR 7: assigned
[io 0xb000-0xbfff]
2024-04-26T16:01:06.498382Z INFO kernel: [ 11.018502] pci 0000:00:18.0: BAR 7: assigned
[io 0xc000-0xcfff]
2024-04-26T16:01:06.498450Z INFO kernel: [ 11.020030] pci 0000:00:17.7: BAR 7: assigned
[io 0xd000-0xdfff]
2024-04-26T16:01:06.498456Z INFO kernel: [ 11.021554] pci 0000:00:17.6: BAR 7: assigned
[io 0xe000-0xefff]
2024-04-26T16:01:06.498457Z INFO kernel: [ 11.023082] pci 0000:00:17.5: BAR 7: assigned
[io 0xf000-0xffff]
2024-04-26T16:01:06.498458Z INFO kernel: [ 11.024710] pci 0000:00:17.4: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498459Z INFO kernel: [ 11.026274] pci 0000:00:17.4: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498460Z INFO kernel: [ 11.028016] pci 0000:00:17.3: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498461Z INFO kernel: [ 11.029544] pci 0000:00:17.3: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498502Z INFO kernel: [ 11.031151] pci 0000:00:17.2: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498507Z INFO kernel: [ 11.031525] pci 0000:00:17.2: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498508Z INFO kernel: [ 11.032008] pci 0000:00:17.1: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498510Z INFO kernel: [ 11.032084] pci 0000:00:17.1: BAR 7: failed
```

```
to assign [io size 0x1000]
2024-04-26T16:01:06.498511Z INFO kernel: [ 11.032134] pci 0000:00:17.0: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498513Z INFO kernel: [ 11.032168] pci 0000:00:17.0: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498578Z INFO kernel: [ 11.032191] pci 0000:00:16.7: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498586Z INFO kernel: [ 11.032206] pci 0000:00:16.7: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498590Z INFO kernel: [ 11.032216] pci 0000:00:16.6: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498593Z INFO kernel: [ 11.032223] pci 0000:00:16.6: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498596Z INFO kernel: [ 11.032227] pci 0000:00:16.5: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498599Z INFO kernel: [ 11.032230] pci 0000:00:16.5: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498663Z INFO kernel: [ 11.032232] pci 0000:00:16.4: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498672Z INFO kernel: [ 11.032234] pci 0000:00:16.4: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498675Z INFO kernel: [ 11.032235] pci 0000:00:16.3: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498679Z INFO kernel: [ 11.032235] pci 0000:00:16.3: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498682Z INFO kernel: [ 11.032236] pci 0000:00:16.2: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498685Z INFO kernel: [ 11.032236] pci 0000:00:16.2: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498689Z INFO kernel: [ 11.032236] pci 0000:00:16.1: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498751Z INFO kernel: [ 11.032236] pci 0000:00:16.1: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498760Z INFO kernel: [ 11.032236] pci 0000:00:16.0: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498764Z INFO kernel: [ 11.032236] pci 0000:00:16.0: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498767Z INFO kernel: [ 11.032237] pci 0000:00:15.7: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498771Z INFO kernel: [ 11.032237] pci 0000:00:15.7: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498774Z INFO kernel: [ 11.032237] pci 0000:00:15.6: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498832Z INFO kernel: [ 11.032237] pci 0000:00:15.6: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498840Z INFO kernel: [ 11.032237] pci 0000:00:15.5: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498843Z INFO kernel: [ 11.032237] pci 0000:00:15.5: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498869Z INFO kernel: [ 11.032237] pci 0000:00:15.4: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498873Z INFO kernel: [ 11.032237] pci 0000:00:15.4: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.498876Z INFO kernel: [ 11.032237] pci 0000:00:15.3: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.498901Z INFO kernel: [ 11.032237] pci 0000:00:15.3: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.526665Z INFO kernel: [ 11.032237] pci 0000:00:15.2: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.535134Z INFO kernel: [ 11.032237] pci 0000:00:15.2: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.535148Z INFO kernel: [ 11.032237] pci 0000:00:15.1: BAR 7: no space
for [io size 0x1000]
2024-04-26T16:01:06.535150Z INFO kernel: [ 11.032237] pci 0000:00:15.1: BAR 7: failed
to assign [io size 0x1000]
2024-04-26T16:01:06.535152Z INFO kernel: [ 11.032237] pci 0000:00:01.0: PCI bridge to
[bus 01]
2024-04-26T16:01:06.535154Z INFO kernel: [ 11.032237] pci 0000:02:01.0: BAR 6: assigned
[mem 0xfc030000-0xfc03ffff pref]
```

```
2024-04-26T16:01:06.535177Z INFO kernel: [ 11.032237] pci 0000:00:11.0: PCI bridge to
[bus 02]
2024-04-26T16:01:06.535182Z INFO kernel: [ 11.032237] pci 0000:00:11.0: bridge window
[io 0x1000-0x1fff]
2024-04-26T16:01:06.535201Z INFO kernel: [ 11.032237] pci 0000:00:11.0: bridge window
[mem 0xfc000000-0xfc9fffffff]
2024-04-26T16:01:06.535203Z INFO kernel: [ 11.032237] pci 0000:00:11.0: bridge window
[mem 0xf8000000-0xf84fffffff 64bit pref]
2024-04-26T16:01:06.535205Z INFO kernel: [ 11.032237] pci 0000:03:00.0: BAR 6: assigned
[mem 0xfea04000-0xfea05fff pref]
2024-04-26T16:01:06.535207Z INFO kernel: [ 11.032237] pci 0000:00:15.0: PCI bridge to
[bus 03]
2024-04-26T16:01:06.535209Z INFO kernel: [ 11.032237] pci 0000:00:15.0: bridge window
[io 0x3000-0x3fff]
2024-04-26T16:01:06.535211Z INFO kernel: [ 11.032237] pci 0000:00:15.0: bridge window
[mem 0xfea00000-0xfeaffffff]
2024-04-26T16:01:06.535212Z INFO kernel: [ 11.032237] pci 0000:00:15.0: bridge window
[mem 0xfef00000-0xff0fffffff 64bit pref]
2024-04-26T16:01:06.535214Z INFO kernel: [ 11.032237] pci 0000:00:15.1: PCI bridge to
[bus 04]
2024-04-26T16:01:06.535216Z INFO kernel: [ 11.032237] pci 0000:00:15.1: bridge window
[mem 0xfe900000-0xfe9fffffff]
2024-04-26T16:01:06.535218Z INFO kernel: [ 11.032237] pci 0000:00:15.1: bridge window
[mem 0xfa300000-0xfa3fffffff 64bit pref]
2024-04-26T16:01:06.535220Z INFO kernel: [ 11.032237] pci 0000:00:15.2: PCI bridge to
[bus 05]
2024-04-26T16:01:06.535221Z INFO kernel: [ 11.032237] pci 0000:00:15.2: bridge window
[mem 0xfe800000-0xfe8fffffff]
2024-04-26T16:01:06.535223Z INFO kernel: [ 11.032237] pci 0000:00:15.2: bridge window
[mem 0xfa200000-0xfa2fffffff 64bit pref]
2024-04-26T16:01:06.535225Z INFO kernel: [ 11.032237] pci 0000:00:15.3: PCI bridge to
[bus 06]
2024-04-26T16:01:06.535227Z INFO kernel: [ 11.032237] pci 0000:00:15.3: bridge window
[mem 0xfe700000-0xfe7fffffff]
2024-04-26T16:01:06.535229Z INFO kernel: [ 11.032237] pci 0000:00:15.3: bridge window
[mem 0xfa100000-0xfa1fffffff 64bit pref]
2024-04-26T16:01:06.535231Z INFO kernel: [ 11.032237] pci 0000:00:15.4: PCI bridge to
[bus 07]
2024-04-26T16:01:06.535233Z INFO kernel: [ 11.032237] pci 0000:00:15.4: bridge window
[mem 0xfe600000-0xfe6fffffff]
2024-04-26T16:01:06.535234Z INFO kernel: [ 11.032237] pci 0000:00:15.4: bridge window
[mem 0xfa000000-0xfa0fffffff 64bit pref]
2024-04-26T16:01:06.535236Z INFO kernel: [ 11.032237] pci 0000:00:15.5: PCI bridge to
[bus 08]
2024-04-26T16:01:06.535238Z INFO kernel: [ 11.032237] pci 0000:00:15.5: bridge window
[mem 0xfe500000-0xfe5fffffff]
2024-04-26T16:01:06.535239Z INFO kernel: [ 11.032237] pci 0000:00:15.5: bridge window
[mem 0xf9f00000-0xf9fffffff 64bit pref]
2024-04-26T16:01:06.535241Z INFO kernel: [ 11.032237] pci 0000:00:15.6: PCI bridge to
[bus 09]
2024-04-26T16:01:06.535243Z INFO kernel: [ 11.032237] pci 0000:00:15.6: bridge window
[mem 0xfe400000-0xfe4fffffff]
2024-04-26T16:01:06.535245Z INFO kernel: [ 11.032237] pci 0000:00:15.6: bridge window
[mem 0xf9e00000-0xf9effffff 64bit pref]
2024-04-26T16:01:06.535247Z INFO kernel: [ 11.032237] pci 0000:00:15.7: PCI bridge to
[bus 0a]
2024-04-26T16:01:06.535557Z INFO kernel: [ 11.032237] pci 0000:00:15.7: bridge window
[mem 0xfe300000-0xfe3fffffff]
2024-04-26T16:01:06.535566Z INFO kernel: [ 11.032237] pci 0000:00:15.7: bridge window
[mem 0xf9d00000-0xf9dfffffff 64bit pref]
2024-04-26T16:01:06.535569Z INFO kernel: [ 11.032237] pci 0000:00:16.0: PCI bridge to
[bus 0b]
2024-04-26T16:01:06.535573Z INFO kernel: [ 11.032237] pci 0000:00:16.0: bridge window
[mem 0xfe200000-0xfe2fffffff]
2024-04-26T16:01:06.535576Z INFO kernel: [ 11.032237] pci 0000:00:16.0: bridge window
[mem 0xf9c00000-0xf9cfffffff 64bit pref]
2024-04-26T16:01:06.535579Z INFO kernel: [ 11.032237] pci 0000:00:16.1: PCI bridge to
[bus 0c]
2024-04-26T16:01:06.535583Z INFO kernel: [ 11.032237] pci 0000:00:16.1: bridge window
```

```
[mem 0xfe100000-0xfe1ffffff]
2024-04-26T16:01:06.535587Z INFO kernel: [ 11.032237] pci 0000:00:16.1: bridge window
[mem 0xf9b00000-0xf9bffffff 64bit pref]
2024-04-26T16:01:06.535590Z INFO kernel: [ 11.032237] pci 0000:00:16.2: PCI bridge to
[bus 0d]
2024-04-26T16:01:06.535594Z INFO kernel: [ 11.032237] pci 0000:00:16.2: bridge window
[mem 0xfe000000-0xfe0ffffff]
2024-04-26T16:01:06.535597Z INFO kernel: [ 11.032237] pci 0000:00:16.2: bridge window
[mem 0xf9a00000-0xf9affffff 64bit pref]
2024-04-26T16:01:06.535600Z INFO kernel: [ 11.032237] pci 0000:00:16.3: PCI bridge to
[bus 0e]
2024-04-26T16:01:06.535604Z INFO kernel: [ 11.032237] pci 0000:00:16.3: bridge window
[mem 0xfdf00000-0xfdfffffff]
2024-04-26T16:01:06.535607Z INFO kernel: [ 11.032237] pci 0000:00:16.3: bridge window
[mem 0xf9900000-0xf99ffffff 64bit pref]
2024-04-26T16:01:06.535610Z INFO kernel: [ 11.032237] pci 0000:00:16.4: PCI bridge to
[bus 0f]
2024-04-26T16:01:06.535613Z INFO kernel: [ 11.032237] pci 0000:00:16.4: bridge window
[mem 0xfde00000-0xfdeffffff]
2024-04-26T16:01:06.535616Z INFO kernel: [ 11.032237] pci 0000:00:16.4: bridge window
[mem 0xf9800000-0xf98ffffff 64bit pref]
2024-04-26T16:01:06.535619Z INFO kernel: [ 11.032237] pci 0000:00:16.5: PCI bridge to
[bus 10]
2024-04-26T16:01:06.535623Z INFO kernel: [ 11.032237] pci 0000:00:16.5: bridge window
[mem 0xfdd00000-0xfddffffff]
2024-04-26T16:01:06.535626Z INFO kernel: [ 11.032237] pci 0000:00:16.5: bridge window
[mem 0xf9700000-0xf97ffffff 64bit pref]
2024-04-26T16:01:06.535629Z INFO kernel: [ 11.032237] pci 0000:00:16.6: PCI bridge to
[bus 11]
2024-04-26T16:01:06.535633Z INFO kernel: [ 11.032237] pci 0000:00:16.6: bridge window
[mem 0xfdc00000-0xfdcffffff]
2024-04-26T16:01:06.535636Z INFO kernel: [ 11.032237] pci 0000:00:16.6: bridge window
[mem 0xf9600000-0xf96ffffff 64bit pref]
2024-04-26T16:01:06.535639Z INFO kernel: [ 11.032237] pci 0000:00:16.7: PCI bridge to
[bus 12]
2024-04-26T16:01:06.535642Z INFO kernel: [ 11.032237] pci 0000:00:16.7: bridge window
[mem 0xfdb00000-0xfdbffffff]
2024-04-26T16:01:06.535646Z INFO kernel: [ 11.032237] pci 0000:00:16.7: bridge window
[mem 0xf9500000-0xf95ffffff 64bit pref]
2024-04-26T16:01:06.535649Z INFO kernel: [ 11.032237] pci 0000:00:17.0: PCI bridge to
[bus 13]
2024-04-26T16:01:06.535653Z INFO kernel: [ 11.032237] pci 0000:00:17.0: bridge window
[mem 0xfda00000-0xfdaffffff]
2024-04-26T16:01:06.535656Z INFO kernel: [ 11.032237] pci 0000:00:17.0: bridge window
[mem 0xf9400000-0xf94ffffff 64bit pref]
2024-04-26T16:01:06.535660Z INFO kernel: [ 11.032237] pci 0000:00:17.1: PCI bridge to
[bus 14]
2024-04-26T16:01:06.535662Z INFO kernel: [ 11.032237] pci 0000:00:17.1: bridge window
[mem 0xfd900000-0xfd9ffffff]
2024-04-26T16:01:06.535666Z INFO kernel: [ 11.032237] pci 0000:00:17.1: bridge window
[mem 0xf9300000-0xf93ffffff 64bit pref]
2024-04-26T16:01:06.535670Z INFO kernel: [ 11.032237] pci 0000:00:17.2: PCI bridge to
[bus 15]
2024-04-26T16:01:06.535673Z INFO kernel: [ 11.032237] pci 0000:00:17.2: bridge window
[mem 0xfd800000-0xfd8ffffff]
2024-04-26T16:01:06.535676Z INFO kernel: [ 11.032237] pci 0000:00:17.2: bridge window
[mem 0xf9200000-0xf92ffffff 64bit pref]
2024-04-26T16:01:06.535680Z INFO kernel: [ 11.032237] pci 0000:00:17.3: PCI bridge to
[bus 16]
2024-04-26T16:01:06.535683Z INFO kernel: [ 11.032237] pci 0000:00:17.3: bridge window
[mem 0xfd700000-0xfd7ffffff]
2024-04-26T16:01:06.535686Z INFO kernel: [ 11.032237] pci 0000:00:17.3: bridge window
[mem 0xf9100000-0xf91ffffff 64bit pref]
2024-04-26T16:01:06.535690Z INFO kernel: [ 11.032237] pci 0000:00:17.4: PCI bridge to
[bus 17]
2024-04-26T16:01:06.535693Z INFO kernel: [ 11.032237] pci 0000:00:17.4: bridge window
[mem 0xfd600000-0xfd6ffffff]
2024-04-26T16:01:06.535696Z INFO kernel: [ 11.032237] pci 0000:00:17.4: bridge window
[mem 0xf9000000-0xf90ffffff 64bit pref]
```

```
2024-04-26T16:01:06.535700Z INFO kernel: [ 11.032237] pci 0000:00:17.5: PCI bridge to
[bus 18]
2024-04-26T16:01:06.535703Z INFO kernel: [ 11.032237] pci 0000:00:17.5: bridge window
[io 0xf000-0xffff]
2024-04-26T16:01:06.535707Z INFO kernel: [ 11.032237] pci 0000:00:17.5: bridge window
[mem 0xfd500000-0xfd5ffffff]
2024-04-26T16:01:06.535710Z INFO kernel: [ 11.032237] pci 0000:00:17.5: bridge window
[mem 0xf8f00000-0xf8fffffff 64bit pref]
2024-04-26T16:01:06.535717Z INFO kernel: [ 11.032237] pci 0000:00:17.6: PCI bridge to
[bus 19]
2024-04-26T16:01:06.535721Z INFO kernel: [ 11.032237] pci 0000:00:17.6: bridge window
[io 0xe000-0xefff]
2024-04-26T16:01:06.535725Z INFO kernel: [ 11.032237] pci 0000:00:17.6: bridge window
[mem 0xfd400000-0xfd4ffffff]
2024-04-26T16:01:06.535728Z INFO kernel: [ 11.032237] pci 0000:00:17.6: bridge window
[mem 0xf8e00000-0xf8efffff 64bit pref]
2024-04-26T16:01:06.535731Z INFO kernel: [ 11.032237] pci 0000:00:17.7: PCI bridge to
[bus 1a]
2024-04-26T16:01:06.535734Z INFO kernel: [ 11.032237] pci 0000:00:17.7: bridge window
[io 0xd000-0xdfff]
2024-04-26T16:01:06.535808Z INFO kernel: [ 11.032237] pci 0000:00:17.7: bridge window
[mem 0xfd300000-0xfd3ffffff]
2024-04-26T16:01:06.535813Z INFO kernel: [ 11.032237] pci 0000:00:17.7: bridge window
[mem 0xf8d00000-0xf8dfffff 64bit pref]
2024-04-26T16:01:06.535816Z INFO kernel: [ 11.032237] pci 0000:00:18.0: PCI bridge to
[bus 1b]
2024-04-26T16:01:06.535819Z INFO kernel: [ 11.032237] pci 0000:00:18.0: bridge window
[io 0xc000-0xcfff]
2024-04-26T16:01:06.535823Z INFO kernel: [ 11.032237] pci 0000:00:18.0: bridge window
[mem 0xfd200000-0xfd2ffffff]
2024-04-26T16:01:06.535826Z INFO kernel: [ 11.032237] pci 0000:00:18.0: bridge window
[mem 0xf8c00000-0xf8cfffff 64bit pref]
2024-04-26T16:01:06.535829Z INFO kernel: [ 11.032237] pci 0000:00:18.1: PCI bridge to
[bus 1c]
2024-04-26T16:01:06.535832Z INFO kernel: [ 11.032237] pci 0000:00:18.1: bridge window
[io 0xb000-0xbfff]
2024-04-26T16:01:06.535836Z INFO kernel: [ 11.032237] pci 0000:00:18.1: bridge window
[mem 0xfd100000-0xfd1ffffff]
2024-04-26T16:01:06.535839Z INFO kernel: [ 11.032237] pci 0000:00:18.1: bridge window
[mem 0xf8b00000-0xf8bfffff 64bit pref]
2024-04-26T16:01:06.535845Z INFO kernel: [ 11.032237] pci 0000:00:18.2: PCI bridge to
[bus 1d]
2024-04-26T16:01:06.535850Z INFO kernel: [ 11.032237] pci 0000:00:18.2: bridge window
[io 0xa000-0xaaff]
2024-04-26T16:01:06.535853Z INFO kernel: [ 11.032237] pci 0000:00:18.2: bridge window
[mem 0xfd000000-0xfd0ffffff]
2024-04-26T16:01:06.535855Z INFO kernel: [ 11.032237] pci 0000:00:18.2: bridge window
[mem 0xf8a00000-0xf8afffff 64bit pref]
2024-04-26T16:01:06.535857Z INFO kernel: [ 11.032237] pci 0000:00:18.3: PCI bridge to
[bus 1e]
2024-04-26T16:01:06.535859Z INFO kernel: [ 11.032237] pci 0000:00:18.3: bridge window
[io 0x9000-0x9fff]
2024-04-26T16:01:06.535861Z INFO kernel: [ 11.032237] pci 0000:00:18.3: bridge window
[mem 0xfc000000-0xfcffffff]
2024-04-26T16:01:06.535862Z INFO kernel: [ 11.032237] pci 0000:00:18.3: bridge window
[mem 0xf8900000-0xf89fffff 64bit pref]
2024-04-26T16:01:06.535864Z INFO kernel: [ 11.032237] pci 0000:00:18.4: PCI bridge to
[bus 1f]
2024-04-26T16:01:06.535866Z INFO kernel: [ 11.032237] pci 0000:00:18.4: bridge window
[io 0x8000-0x8fff]
2024-04-26T16:01:06.535868Z INFO kernel: [ 11.032237] pci 0000:00:18.4: bridge window
[mem 0xfce00000-0xfceffffff]
2024-04-26T16:01:06.535870Z INFO kernel: [ 11.032237] pci 0000:00:18.4: bridge window
[mem 0xf8800000-0xf88fffff 64bit pref]
2024-04-26T16:01:06.535872Z INFO kernel: [ 11.032237] pci 0000:00:18.5: PCI bridge to
[bus 20]
2024-04-26T16:01:06.535874Z INFO kernel: [ 11.032237] pci 0000:00:18.5: bridge window
[io 0x7000-0x7fff]
2024-04-26T16:01:06.535876Z INFO kernel: [ 11.032237] pci 0000:00:18.5: bridge window
```



```
[mem 0xfcd00000-0xfcdfffff]
2024-04-26T16:01:06.535878Z INFO kernel: [ 11.032237] pci 0000:00:18.5: bridge window
[mem 0xf8700000-0xf87fffff 64bit pref]
2024-04-26T16:01:06.535881Z INFO kernel: [ 11.032237] pci 0000:00:18.6: PCI bridge to
[bus 21]
2024-04-26T16:01:06.535884Z INFO kernel: [ 11.032237] pci 0000:00:18.6: bridge window
[io 0x6000-0x6fff]
2024-04-26T16:01:06.535886Z INFO kernel: [ 11.032237] pci 0000:00:18.6: bridge window
[mem 0xfcc00000-0xfccfffff]
2024-04-26T16:01:06.535889Z INFO kernel: [ 11.032237] pci 0000:00:18.6: bridge window
[mem 0xf8600000-0xf86fffff 64bit pref]
2024-04-26T16:01:06.535892Z INFO kernel: [ 11.032237] pci 0000:00:18.7: PCI bridge to
[bus 22]
2024-04-26T16:01:06.535894Z INFO kernel: [ 11.032237] pci 0000:00:18.7: bridge window
[io 0x4000-0x4fff]
2024-04-26T16:01:06.535898Z INFO kernel: [ 11.032237] pci 0000:00:18.7: bridge window
[mem 0xfcb00000-0xfcbfffff]
2024-04-26T16:01:06.535901Z INFO kernel: [ 11.032237] pci 0000:00:18.7: bridge window
[mem 0xf8500000-0xf85fffff 64bit pref]
2024-04-26T16:01:06.535903Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 4 [io
0x0d00-0xffff window]
2024-04-26T16:01:06.535906Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 5 [io
0x0000-0x0cf7 window]
2024-04-26T16:01:06.535909Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 6 [mem
0xfef00000-0xffdfffff window]
2024-04-26T16:01:06.535912Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 7 [mem
0xfed45000-0xfedfffff window]
2024-04-26T16:01:06.535915Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 8 [mem
0xfec10000-0xfed3ffff window]
2024-04-26T16:01:06.535917Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 9 [mem
0xfa400000-0xfebfffff window]
2024-04-26T16:01:06.535920Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 10 [mem
0xf0000000-0xfa3fffff pref window]
2024-04-26T16:01:06.535923Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 11 [mem
0xc0000000-0xefffffff window]
2024-04-26T16:01:06.535926Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 12 [mem
0x000a0000-0x000bffff window]
2024-04-26T16:01:06.535929Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 13 [mem
0x000c4000-0x000c7fff window]
2024-04-26T16:01:06.535931Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 14 [mem
0x000c8000-0x000cbfff window]
2024-04-26T16:01:06.535934Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 15 [mem
0x000d4000-0x000d7fff window]
2024-04-26T16:01:06.535936Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 16 [mem
0x000d8000-0x000dbfff window]
2024-04-26T16:01:06.535939Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 17 [mem
0x000e4000-0x000e7fff window]
2024-04-26T16:01:06.535941Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 18 [mem
0x000e8000-0x000ebfff window]
2024-04-26T16:01:06.535968Z INFO kernel: [ 11.032237] pci_bus 0000:00: resource 19 [mem
0x000ec000-0x000effff window]
2024-04-26T16:01:06.535972Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 0 [io
0x1000-0x1fff]
2024-04-26T16:01:06.535974Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 1 [mem
0xfc000000-0xfc9fffff]
2024-04-26T16:01:06.535977Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 2 [mem
0xf8000000-0xf84fffff 64bit pref]
2024-04-26T16:01:06.535979Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 4 [io
0x0d00-0xffff window]
2024-04-26T16:01:06.536328Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 5 [io
0x0000-0x0cf7 window]
2024-04-26T16:01:06.536336Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 6 [mem
0xfef00000-0xffdfffff window]
2024-04-26T16:01:06.536339Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 7 [mem
0xfed45000-0xfedfffff window]
2024-04-26T16:01:06.536341Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 8 [mem
0xfec10000-0xfed3ffff window]
2024-04-26T16:01:06.536344Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 9 [mem
0xfa400000-0xfebfffff window]
```

```
2024-04-26T16:01:06.536346Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 10 [mem
0xf0000000-0xfa3ffffff pref window]
2024-04-26T16:01:06.536349Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 11 [mem
0xc0000000-0xefffffff window]
2024-04-26T16:01:06.536352Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 12 [mem
0x000a0000-0x000bffff window]
2024-04-26T16:01:06.536354Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 13 [mem
0x000c4000-0x000c7fff window]
2024-04-26T16:01:06.536357Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 14 [mem
0x000c8000-0x000cbfff window]
2024-04-26T16:01:06.536360Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 15 [mem
0x000d4000-0x000d7fff window]
2024-04-26T16:01:06.536362Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 16 [mem
0x000d8000-0x000dbfff window]
2024-04-26T16:01:06.536365Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 17 [mem
0x000e4000-0x000e7fff window]
2024-04-26T16:01:06.536368Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 18 [mem
0x000e8000-0x000ebfff window]
2024-04-26T16:01:06.536370Z INFO kernel: [ 11.032237] pci_bus 0000:02: resource 19 [mem
0x000ec000-0x000effff window]
2024-04-26T16:01:06.536373Z INFO kernel: [ 11.032237] pci_bus 0000:03: resource 0 [io
0x3000-0x3fff]
2024-04-26T16:01:06.536375Z INFO kernel: [ 11.032237] pci_bus 0000:03: resource 1 [mem
0xfea00000-0xfeafffff]
2024-04-26T16:01:06.536379Z INFO kernel: [ 11.032237] pci_bus 0000:03: resource 2 [mem
0xfef00000-0xff0fffff 64bit pref]
2024-04-26T16:01:06.536381Z INFO kernel: [ 11.032237] pci_bus 0000:04: resource 1 [mem
0xfe900000-0xfe9fffff]
2024-04-26T16:01:06.536384Z INFO kernel: [ 11.032237] pci_bus 0000:04: resource 2 [mem
0xfa300000-0xfa3fffff 64bit pref]
2024-04-26T16:01:06.536387Z INFO kernel: [ 11.032237] pci_bus 0000:05: resource 1 [mem
0xfe800000-0xfe8fffff]
2024-04-26T16:01:06.536393Z INFO kernel: [ 11.032237] pci_bus 0000:05: resource 2 [mem
0xfa200000-0xfa2fffff 64bit pref]
2024-04-26T16:01:06.536466Z INFO kernel: [ 11.032237] pci_bus 0000:06: resource 1 [mem
0xfe700000-0xfe7fffff]
2024-04-26T16:01:06.536473Z INFO kernel: [ 11.032237] pci_bus 0000:06: resource 2 [mem
0xfa100000-0xfa1fffff 64bit pref]
2024-04-26T16:01:06.536474Z INFO kernel: [ 11.032237] pci_bus 0000:07: resource 1 [mem
0xfe600000-0xfe6fffff]
2024-04-26T16:01:06.536476Z INFO kernel: [ 11.032237] pci_bus 0000:07: resource 2 [mem
0xfa000000-0xfa0fffff 64bit pref]
2024-04-26T16:01:06.536478Z INFO kernel: [ 11.032237] pci_bus 0000:08: resource 1 [mem
0xfe500000-0xfe5fffff]
2024-04-26T16:01:06.536480Z INFO kernel: [ 11.032237] pci_bus 0000:08: resource 2 [mem
0xf9f00000-0xf9fffff 64bit pref]
2024-04-26T16:01:06.536537Z INFO kernel: [ 11.032237] pci_bus 0000:09: resource 1 [mem
0xfe400000-0xfe4fffff]
2024-04-26T16:01:06.536546Z INFO kernel: [ 11.032237] pci_bus 0000:09: resource 2 [mem
0xf9e00000-0xf9efffff 64bit pref]
2024-04-26T16:01:06.536549Z INFO kernel: [ 11.032237] pci_bus 0000:0a: resource 1 [mem
0xfe300000-0xfe3fffff]
2024-04-26T16:01:06.536552Z INFO kernel: [ 11.032237] pci_bus 0000:0a: resource 2 [mem
0xf9d00000-0xf9dfffff 64bit pref]
2024-04-26T16:01:06.536555Z INFO kernel: [ 11.032237] pci_bus 0000:0b: resource 1 [mem
0xfe200000-0xfe2fffff]
2024-04-26T16:01:06.536558Z INFO kernel: [ 11.032237] pci_bus 0000:0b: resource 2 [mem
0xf9c00000-0xf9cfffff 64bit pref]
2024-04-26T16:01:06.536561Z INFO kernel: [ 11.032237] pci_bus 0000:0c: resource 1 [mem
0xfe100000-0xfe1fffff]
2024-04-26T16:01:06.536658Z INFO kernel: [ 11.032237] pci_bus 0000:0c: resource 2 [mem
0xf9b00000-0xf9bfffff 64bit pref]
2024-04-26T16:01:06.536667Z INFO kernel: [ 11.032237] pci_bus 0000:0d: resource 1 [mem
0xfe000000-0xfe0fffff]
2024-04-26T16:01:06.536670Z INFO kernel: [ 11.032237] pci_bus 0000:0d: resource 2 [mem
0xf9a00000-0xf9afffff 64bit pref]
2024-04-26T16:01:06.536673Z INFO kernel: [ 11.032237] pci_bus 0000:0e: resource 1 [mem
0xfd000000-0xfdfffff]
2024-04-26T16:01:06.536675Z INFO kernel: [ 11.032237] pci_bus 0000:0e: resource 2 [mem
```

```
0xf9900000-0xf99fffff 64bit pref]
2024-04-26T16:01:06.536681Z INFO kernel: [ 11.032237] pci_bus 0000:0f: resource 1 [mem
0xfde00000-0xfdefffff]
2024-04-26T16:01:06.536760Z INFO kernel: [ 11.032237] pci_bus 0000:0f: resource 2 [mem
0xf9800000-0xf98fffff 64bit pref]
2024-04-26T16:01:06.536769Z INFO kernel: [ 11.032237] pci_bus 0000:10: resource 1 [mem
0xfdd00000-0xfddfffff]
2024-04-26T16:01:06.536774Z INFO kernel: [ 11.032237] pci_bus 0000:10: resource 2 [mem
0xf9700000-0xf97fffff 64bit pref]
2024-04-26T16:01:06.536777Z INFO kernel: [ 11.032237] pci_bus 0000:11: resource 1 [mem
0xfdc00000-0xfdcfffff]
2024-04-26T16:01:06.536780Z INFO kernel: [ 11.032237] pci_bus 0000:11: resource 2 [mem
0xf9600000-0xf96fffff 64bit pref]
2024-04-26T16:01:06.536783Z INFO kernel: [ 11.032237] pci_bus 0000:12: resource 1 [mem
0xfdb00000-0xfdbfffff]
2024-04-26T16:01:06.536837Z INFO kernel: [ 11.032237] pci_bus 0000:12: resource 2 [mem
0xf9500000-0xf95fffff 64bit pref]
2024-04-26T16:01:06.536910Z INFO kernel: [ 11.032237] pci_bus 0000:13: resource 1 [mem
0xfda00000-0xfdafffff]
2024-04-26T16:01:06.536917Z INFO kernel: [ 11.032237] pci_bus 0000:13: resource 2 [mem
0xf9400000-0xf94fffff 64bit pref]
2024-04-26T16:01:06.536921Z INFO kernel: [ 11.032237] pci_bus 0000:14: resource 1 [mem
0xfd900000-0xfd9fffff]
2024-04-26T16:01:06.536944Z INFO kernel: [ 11.032237] pci_bus 0000:14: resource 2 [mem
0xf9300000-0xf93fffff 64bit pref]
2024-04-26T16:01:06.536947Z INFO kernel: [ 11.032237] pci_bus 0000:15: resource 1 [mem
0xfd800000-0xfd8fffff]
2024-04-26T16:01:06.536950Z INFO kernel: [ 11.032237] pci_bus 0000:15: resource 2 [mem
0xf9200000-0xf92fffff 64bit pref]
2024-04-26T16:01:06.537067Z INFO kernel: [ 11.032237] pci_bus 0000:16: resource 1 [mem
0xfd700000-0xfd7fffff]
2024-04-26T16:01:06.537075Z INFO kernel: [ 11.032237] pci_bus 0000:16: resource 2 [mem
0xf9100000-0xf91fffff 64bit pref]
2024-04-26T16:01:06.537078Z INFO kernel: [ 11.032237] pci_bus 0000:17: resource 1 [mem
0xfd600000-0xfd6fffff]
2024-04-26T16:01:06.537079Z INFO kernel: [ 11.032237] pci_bus 0000:17: resource 2 [mem
0xf9000000-0xf90fffff 64bit pref]
2024-04-26T16:01:06.537082Z INFO kernel: [ 11.032237] pci_bus 0000:18: resource 0 [io
0xf000-0xffff]
2024-04-26T16:01:06.537088Z INFO kernel: [ 11.032237] pci_bus 0000:18: resource 1 [mem
0xfd500000-0xfd5fffff]
2024-04-26T16:01:06.537185Z INFO kernel: [ 11.032237] pci_bus 0000:18: resource 2 [mem
0xf8f00000-0xf8fffff 64bit pref]
2024-04-26T16:01:06.537195Z INFO kernel: [ 11.032237] pci_bus 0000:19: resource 0 [io
0xe000-0xefff]
2024-04-26T16:01:06.537197Z INFO kernel: [ 11.032237] pci_bus 0000:19: resource 1 [mem
0xfd400000-0xfd4fffff]
2024-04-26T16:01:06.537199Z INFO kernel: [ 11.032237] pci_bus 0000:19: resource 2 [mem
0xf8e00000-0xf8efffff 64bit pref]
2024-04-26T16:01:06.537200Z INFO kernel: [ 11.032237] pci_bus 0000:1a: resource 0 [io
0xd000-0xdfff]
2024-04-26T16:01:06.537202Z INFO kernel: [ 11.032237] pci_bus 0000:1a: resource 1 [mem
0xfd300000-0xfd3fffff]
2024-04-26T16:01:06.537204Z INFO kernel: [ 11.032237] pci_bus 0000:1a: resource 2 [mem
0xf8d00000-0xf8dfffff 64bit pref]
2024-04-26T16:01:06.538327Z INFO kernel: [ 11.032237] pci_bus 0000:1b: resource 0 [io
0xc000-0xcfff]
2024-04-26T16:01:06.538340Z INFO kernel: [ 11.032237] pci_bus 0000:1b: resource 1 [mem
0xfd200000-0xfd2fffff]
2024-04-26T16:01:06.538344Z INFO kernel: [ 11.032237] pci_bus 0000:1b: resource 2 [mem
0xf8c00000-0xf8cfffff 64bit pref]
2024-04-26T16:01:06.538348Z INFO kernel: [ 11.032237] pci_bus 0000:1c: resource 0 [io
0xb000-0xbfff]
2024-04-26T16:01:06.538351Z INFO kernel: [ 11.032237] pci_bus 0000:1c: resource 1 [mem
0xfd100000-0xfd1fffff]
2024-04-26T16:01:06.538354Z INFO kernel: [ 11.032237] pci_bus 0000:1c: resource 2 [mem
0xf8b00000-0xf8bfffff 64bit pref]
2024-04-26T16:01:06.538422Z INFO kernel: [ 11.032237] pci_bus 0000:1d: resource 0 [io
0xa000-0xffff]
```

```
2024-04-26T16:01:06.538430Z INFO kernel: [ 11.032237] pci_bus 0000:1d: resource 1 [mem
0xfd000000-0xfd0fffff]
2024-04-26T16:01:06.538434Z INFO kernel: [ 11.032237] pci_bus 0000:1d: resource 2 [mem
0xf8a00000-0xf8afffff 64bit pref]
2024-04-26T16:01:06.538438Z INFO kernel: [ 11.032237] pci_bus 0000:1e: resource 0 [io
0x9000-0x9fff]
2024-04-26T16:01:06.538440Z INFO kernel: [ 11.032237] pci_bus 0000:1e: resource 1 [mem
0xfc000000-0xfcffffff]
2024-04-26T16:01:06.538443Z INFO kernel: [ 11.032237] pci_bus 0000:1e: resource 2 [mem
0xf8900000-0xf89fffff 64bit pref]
2024-04-26T16:01:06.538446Z INFO kernel: [ 11.032237] pci_bus 0000:1f: resource 0 [io
0x8000-0x8fff]
2024-04-26T16:01:06.538504Z INFO kernel: [ 11.032237] pci_bus 0000:1f: resource 1 [mem
0xfce00000-0xfcefffff]
2024-04-26T16:01:06.538512Z INFO kernel: [ 11.032237] pci_bus 0000:1f: resource 2 [mem
0xf8800000-0xf88fffff 64bit pref]
2024-04-26T16:01:06.538516Z INFO kernel: [ 11.032237] pci_bus 0000:20: resource 0 [io
0x7000-0x7fff]
2024-04-26T16:01:06.538519Z INFO kernel: [ 11.032237] pci_bus 0000:20: resource 1 [mem
0xfcd00000-0xfcdfffff]
2024-04-26T16:01:06.538523Z INFO kernel: [ 11.032237] pci_bus 0000:20: resource 2 [mem
0xf8700000-0xf87fffff 64bit pref]
2024-04-26T16:01:06.538525Z INFO kernel: [ 11.032237] pci_bus 0000:21: resource 0 [io
0x6000-0x6fff]
2024-04-26T16:01:06.538581Z INFO kernel: [ 11.032237] pci_bus 0000:21: resource 1 [mem
0xfcc00000-0xfccfffff]
2024-04-26T16:01:06.538608Z INFO kernel: [ 11.032237] pci_bus 0000:21: resource 2 [mem
0xf8600000-0xf86fffff 64bit pref]
2024-04-26T16:01:06.538612Z INFO kernel: [ 11.032237] pci_bus 0000:22: resource 0 [io
0x4000-0x4fff]
2024-04-26T16:01:06.538615Z INFO kernel: [ 11.032237] pci_bus 0000:22: resource 1 [mem
0xfcb00000-0xfcbfffff]
2024-04-26T16:01:06.538637Z INFO kernel: [ 11.032237] pci_bus 0000:22: resource 2 [mem
0xf8500000-0xf85fffff 64bit pref]
2024-04-26T16:01:06.538640Z INFO kernel: [ 11.032237] pci 0000:00:00.0: Limiting direct
PCI/PCI transfers
2024-04-26T16:01:06.538719Z INFO kernel: [ 11.032242] pci 0000:02:01.0: CLS mismatch
(32 != 64), using 64 bytes
2024-04-26T16:01:06.538729Z INFO kernel: [ 11.032242] PCI-DMA: Using software bounce
buffering for IO (SWIOTLB)
2024-04-26T16:01:06.538732Z INFO kernel: [ 11.032242] software IO TLB: mapped [mem
0x00000000bc000000-0x00000000c0000000] (64MB)
2024-04-26T16:01:06.538733Z INFO kernel: [ 11.032242] ACPI: bus type thunderbolt
registered
2024-04-26T16:01:06.538735Z INFO kernel: [ 11.032298] RAPL PMU: API unit is 2^-32
Joules, 0 fixed counters, 10737418240 ms ovfl timer
2024-04-26T16:01:06.538736Z ERR kernel: [ 11.032298] kvm: no hardware support
2024-04-26T16:01:06.538737Z INFO kernel: [ 11.032298] has_svm: not amd or hygon
2024-04-26T16:01:06.538785Z ERR kernel: [ 11.032298] kvm: no hardware support
2024-04-26T16:01:06.538789Z INFO kernel: [ 11.032298] clocksource: tsc: mask:
0xffffffffffffffff max_cycles: 0x172da94f0e2, max_idle_ns: 440795278248 ns
2024-04-26T16:01:06.538791Z INFO kernel: [ 11.032298] clocksource: Switched to
clocksource tsc
2024-04-26T16:01:06.538792Z INFO kernel: [ 11.587786] workingset: timestamp_bits=62
max_order=21 bucket_order=0
2024-04-26T16:01:06.538793Z INFO kernel: [ 11.635712] squashfs: version 4.0
(2009/01/31) Phillip Lougher
2024-04-26T16:01:06.538794Z INFO kernel: [ 11.638826] Registering esdfs 0.2
2024-04-26T16:01:06.538962Z INFO kernel: [ 11.639941] alt_syscall: table
'read_write_test' available.
2024-04-26T16:01:06.538969Z INFO kernel: [ 11.641365] alt_syscall: table 'android'
available.
2024-04-26T16:01:06.538971Z INFO kernel: [ 11.643252] alt_syscall: table
'android_permissive' available.
2024-04-26T16:01:06.538973Z INFO kernel: [ 11.644716] alt_syscall: table 'third_party'
available.
2024-04-26T16:01:06.538975Z INFO kernel: [ 11.646045] alt_syscall: table
'third_party_permissive' available.
2024-04-26T16:01:06.538976Z INFO kernel: [ 11.647690] alt_syscall: table 'complete'
```

available.

```
2024-04-26T16:01:06.538978Z INFO kernel: [ 11.683107] alt_syscall: table
'complete_permissive' available.
2024-04-26T16:01:06.539072Z INFO kernel: [ 11.798262] Block layer SCSI generic (bsg)
driver version 0.4 loaded (major 248)
2024-04-26T16:01:06.539081Z INFO kernel: [ 11.833549] io scheduler mq-deadline
registered
2024-04-26T16:01:06.539084Z INFO kernel: [ 11.834845] io scheduler kyber registered
2024-04-26T16:01:06.539086Z INFO kernel: [ 11.835990] io scheduler bfq registered
2024-04-26T16:01:06.539093Z INFO kernel: [ 11.841125] pci 0000:00:01.0: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.539097Z INFO kernel: [ 11.845820] pci 0000:00:11.0: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.539160Z INFO kernel: [ 11.849016] pci 0000:00:15.0: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.539168Z INFO kernel: [ 11.888134] pcieport 0000:00:15.0: PME:
Signaling with IRQ 24
2024-04-26T16:01:06.539172Z INFO kernel: [ 11.889882] pcieport 0000:00:15.0: pciehp:
Slot #160 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.539175Z INFO kernel: [ 11.895459] pci 0000:00:15.1: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.539179Z INFO kernel: [ 11.898355] pcieport 0000:00:15.1: PME:
Signaling with IRQ 25
2024-04-26T16:01:06.539181Z INFO kernel: [ 11.933420] pcieport 0000:00:15.1: pciehp:
Slot #161 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548183Z INFO kernel: [ 11.938460] pci 0000:00:15.2: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548214Z INFO kernel: [ 11.941397] pcieport 0000:00:15.2: PME:
Signaling with IRQ 26
2024-04-26T16:01:06.548219Z INFO kernel: [ 11.942994] pcieport 0000:00:15.2: pciehp:
Slot #162 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548222Z INFO kernel: [ 11.948548] pci 0000:00:15.3: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548224Z INFO kernel: [ 11.985767] pcieport 0000:00:15.3: PME:
Signaling with IRQ 27
2024-04-26T16:01:06.548251Z INFO kernel: [ 11.987366] pcieport 0000:00:15.3: pciehp:
Slot #163 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548349Z INFO kernel: [ 11.992509] pci 0000:00:15.4: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548357Z INFO kernel: [ 11.995475] pcieport 0000:00:15.4: PME:
Signaling with IRQ 28
2024-04-26T16:01:06.548364Z INFO kernel: [ 11.997972] pcieport 0000:00:15.4: pciehp:
Slot #164 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548368Z INFO kernel: [ 12.037101] pci 0000:00:15.5: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548370Z INFO kernel: [ 12.039889] pcieport 0000:00:15.5: PME:
Signaling with IRQ 29
2024-04-26T16:01:06.548373Z INFO kernel: [ 12.041389] pcieport 0000:00:15.5: pciehp:
Slot #165 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548386Z INFO kernel: [ 12.046207] pci 0000:00:15.6: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548389Z INFO kernel: [ 12.049033] pcieport 0000:00:15.6: PME:
Signaling with IRQ 30
2024-04-26T16:01:06.548392Z INFO kernel: [ 12.084066] pcieport 0000:00:15.6: pciehp:
Slot #166 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548395Z INFO kernel: [ 12.089562] pci 0000:00:15.7: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548397Z INFO kernel: [ 12.093040] pcieport 0000:00:15.7: PME:
Signaling with IRQ 31
2024-04-26T16:01:06.548400Z INFO kernel: [ 12.094694] pcieport 0000:00:15.7: pciehp:
Slot #167 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
```

2024-04-26T16:01:06.548411Z INFO kernel: [12.099777] pci 0000:00:16.0: attach allowed to drvr pcieport [internal device]
2024-04-26T16:01:06.548415Z INFO kernel: [12.135700] pcieport 0000:00:16.0: PME: Signaling with IRQ 32
2024-04-26T16:01:06.548418Z INFO kernel: [12.137251] pcieport 0000:00:16.0: pciehp: Slot #192 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+
2024-04-26T16:01:06.548421Z INFO kernel: [12.142905] pci 0000:00:16.1: attach allowed to drvr pcieport [internal device]
2024-04-26T16:01:06.548424Z INFO kernel: [12.145742] pcieport 0000:00:16.1: PME: Signaling with IRQ 33
2024-04-26T16:01:06.548433Z INFO kernel: [12.147291] pcieport 0000:00:16.1: pciehp: Slot #193 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+
2024-04-26T16:01:06.548437Z INFO kernel: [12.185719] pci 0000:00:16.2: attach allowed to drvr pcieport [internal device]
2024-04-26T16:01:06.548440Z INFO kernel: [12.188507] pcieport 0000:00:16.2: PME: Signaling with IRQ 34
2024-04-26T16:01:06.548443Z INFO kernel: [12.190034] pcieport 0000:00:16.2: pciehp: Slot #194 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+
2024-04-26T16:01:06.548447Z INFO kernel: [12.195395] pci 0000:00:16.3: attach allowed to drvr pcieport [internal device]
2024-04-26T16:01:06.548450Z INFO kernel: [12.198524] pcieport 0000:00:16.3: PME: Signaling with IRQ 35
2024-04-26T16:01:06.548460Z INFO kernel: [12.233504] pcieport 0000:00:16.3: pciehp: Slot #195 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+
2024-04-26T16:01:06.548464Z INFO kernel: [12.238378] pci 0000:00:16.4: attach allowed to drvr pcieport [internal device]
2024-04-26T16:01:06.548467Z INFO kernel: [12.241143] pcieport 0000:00:16.4: PME: Signaling with IRQ 36
2024-04-26T16:01:06.548471Z INFO kernel: [12.242828] pcieport 0000:00:16.4: pciehp: Slot #196 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+
2024-04-26T16:01:06.548474Z INFO kernel: [12.248211] pci 0000:00:16.5: attach allowed to drvr pcieport [internal device]
2024-04-26T16:01:06.548480Z INFO kernel: [12.284543] pcieport 0000:00:16.5: PME: Signaling with IRQ 37
2024-04-26T16:01:06.548493Z INFO kernel: [12.286070] pcieport 0000:00:16.5: pciehp: Slot #197 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+
2024-04-26T16:01:06.548497Z INFO kernel: [12.292031] pci 0000:00:16.6: attach allowed to drvr pcieport [internal device]
2024-04-26T16:01:06.548498Z INFO kernel: [12.294800] pcieport 0000:00:16.6: PME: Signaling with IRQ 38
2024-04-26T16:01:06.548500Z INFO kernel: [12.296401] pcieport 0000:00:16.6: pciehp: Slot #198 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+
2024-04-26T16:01:06.548502Z INFO kernel: [12.335419] pci 0000:00:16.7: attach allowed to drvr pcieport [internal device]
2024-04-26T16:01:06.548503Z INFO kernel: [12.338809] pcieport 0000:00:16.7: PME: Signaling with IRQ 39
2024-04-26T16:01:06.548510Z INFO kernel: [12.340348] pcieport 0000:00:16.7: pciehp: Slot #199 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+
2024-04-26T16:01:06.548511Z INFO kernel: [12.345483] pci 0000:00:17.0: attach allowed to drvr pcieport [internal device]
2024-04-26T16:01:06.548512Z INFO kernel: [12.348265] pcieport 0000:00:17.0: PME: Signaling with IRQ 40
2024-04-26T16:01:06.548514Z INFO kernel: [12.383189] pcieport 0000:00:17.0: pciehp: Slot #224 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+ IbPresDis- LLActRep+
2024-04-26T16:01:06.548515Z INFO kernel: [12.388198] pci 0000:00:17.1: attach allowed to drvr pcieport [internal device]
2024-04-26T16:01:06.548516Z INFO kernel: [12.390983] pcieport 0000:00:17.1: PME: Signaling with IRQ 41
2024-04-26T16:01:06.548521Z INFO kernel: [12.392557] pcieport 0000:00:17.1: pciehp: Slot #225 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+

```
IbPresDis- LLActRep+
2024-04-26T16:01:06.548523Z INFO kernel: [ 12.398062] pci 0000:00:17.2: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548524Z INFO kernel: [ 12.434321] pcieport 0000:00:17.2: PME:
Signaling with IRQ 42
2024-04-26T16:01:06.548525Z INFO kernel: [ 12.435869] pcieport 0000:00:17.2: pciehp:
Slot #226 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548526Z INFO kernel: [ 12.441457] pci 0000:00:17.3: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548527Z INFO kernel: [ 12.444745] pcieport 0000:00:17.3: PME:
Signaling with IRQ 43
2024-04-26T16:01:06.548533Z INFO kernel: [ 12.446279] pcieport 0000:00:17.3: pciehp:
Slot #227 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548534Z INFO kernel: [ 12.485032] pci 0000:00:17.4: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548535Z INFO kernel: [ 12.487865] pcieport 0000:00:17.4: PME:
Signaling with IRQ 44
2024-04-26T16:01:06.548536Z INFO kernel: [ 12.490064] pcieport 0000:00:17.4: pciehp:
Slot #228 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548537Z INFO kernel: [ 12.495399] pci 0000:00:17.5: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548538Z INFO kernel: [ 12.498189] pcieport 0000:00:17.5: PME:
Signaling with IRQ 45
2024-04-26T16:01:06.548545Z INFO kernel: [ 12.533135] pcieport 0000:00:17.5: pciehp:
Slot #229 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548547Z INFO kernel: [ 12.538231] pci 0000:00:17.6: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548549Z INFO kernel: [ 12.541054] pcieport 0000:00:17.6: PME:
Signaling with IRQ 46
2024-04-26T16:01:06.548551Z INFO kernel: [ 12.542716] pcieport 0000:00:17.6: pciehp:
Slot #230 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548850Z INFO kernel: [ 12.548433] pci 0000:00:17.7: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548870Z INFO kernel: [ 12.585204] pcieport 0000:00:17.7: PME:
Signaling with IRQ 47
2024-04-26T16:01:06.548875Z INFO kernel: [ 12.586850] pcieport 0000:00:17.7: pciehp:
Slot #231 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548879Z INFO kernel: [ 12.591812] pci 0000:00:18.0: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548882Z INFO kernel: [ 12.594659] pcieport 0000:00:18.0: PME:
Signaling with IRQ 48
2024-04-26T16:01:06.548885Z INFO kernel: [ 12.596237] pcieport 0000:00:18.0: pciehp:
Slot #256 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548888Z INFO kernel: [ 12.634981] pci 0000:00:18.1: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548899Z INFO kernel: [ 12.637903] pcieport 0000:00:18.1: PME:
Signaling with IRQ 49
2024-04-26T16:01:06.548905Z INFO kernel: [ 12.640008] pcieport 0000:00:18.1: pciehp:
Slot #257 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548908Z INFO kernel: [ 12.645268] pci 0000:00:18.2: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548910Z INFO kernel: [ 12.648091] pcieport 0000:00:18.2: PME:
Signaling with IRQ 50
2024-04-26T16:01:06.548913Z INFO kernel: [ 12.683043] pcieport 0000:00:18.2: pciehp:
Slot #258 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548916Z INFO kernel: [ 12.687976] pci 0000:00:18.3: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548925Z INFO kernel: [ 12.690743] pcieport 0000:00:18.3: PME:
Signaling with IRQ 51
2024-04-26T16:01:06.548929Z INFO kernel: [ 12.692289] pcieport 0000:00:18.3: pciehp:
```

```
Slot #259 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548933Z INFO kernel: [ 12.697416] pci 0000:00:18.4: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548936Z INFO kernel: [ 12.733732] pcieport 0000:00:18.4: PME:
Signaling with IRQ 52
2024-04-26T16:01:06.548939Z INFO kernel: [ 12.735336] pcieport 0000:00:18.4: pciehp:
Slot #260 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548942Z INFO kernel: [ 12.740408] pci 0000:00:18.5: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548954Z INFO kernel: [ 12.743198] pcieport 0000:00:18.5: PME:
Signaling with IRQ 53
2024-04-26T16:01:06.548957Z INFO kernel: [ 12.744799] pcieport 0000:00:18.5: pciehp:
Slot #261 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548960Z INFO kernel: [ 12.784977] pci 0000:00:18.6: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548963Z INFO kernel: [ 12.787769] pcieport 0000:00:18.6: PME:
Signaling with IRQ 54
2024-04-26T16:01:06.548966Z INFO kernel: [ 12.789379] pcieport 0000:00:18.6: pciehp:
Slot #262 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548969Z INFO kernel: [ 12.794816] pci 0000:00:18.7: attach allowed
to drvr pcieport [internal device]
2024-04-26T16:01:06.548980Z INFO kernel: [ 12.797692] pcieport 0000:00:18.7: PME:
Signaling with IRQ 55
2024-04-26T16:01:06.548983Z INFO kernel: [ 12.799194] pcieport 0000:00:18.7: pciehp:
Slot #263 AttnBtn+ PwrCtrl+ MRL- AttnInd- PwrInd- HotPlug+ Surprise- Interlock- NoCompl+
IbPresDis- LLActRep+
2024-04-26T16:01:06.548985Z INFO kernel: [ 12.841417] ACPI: AC: AC Adapter [ACAD] (on-
line)
2024-04-26T16:01:06.548988Z INFO kernel: [ 12.842988] input: Power Button as
/devices/LNXSYSTM:00/LNXPWRBN:00/input/input0
2024-04-26T16:01:06.548990Z INFO kernel: [ 12.846178] ACPI: button: Power Button [PWRFB]
2024-04-26T16:01:06.548992Z INFO kernel: [ 12.883098] Serial: 8250/16550 driver, 4
ports, IRQ sharing disabled
2024-04-26T16:01:06.549001Z INFO kernel: [ 12.887314] Non-volatile memory driver v1.3
2024-04-26T16:01:06.549004Z INFO kernel: [ 13.841224] ACPI: bus type drm_connector
registered
2024-04-26T16:01:06.549032Z INFO kernel: [ 13.842492] pci 0000:00:0f.0: attach allowed
to drvr vmwgfx [internal device]
2024-04-26T16:01:06.549035Z INFO kernel: [ 13.847222] vmwgfx 0000:00:0f.0: [drm] FIFO
at 0x00000000fb800000 size is 8192 kiB
2024-04-26T16:01:06.549038Z INFO kernel: [ 13.883205] vmwgfx 0000:00:0f.0: [drm] VRAM
at 0x00000000f0000000 size is 131072 kiB
2024-04-26T16:01:06.549040Z INFO kernel: [ 13.885175] vmwgfx 0000:00:0f.0: [drm]
Running on SVGA version 2.
2024-04-26T16:01:06.549049Z INFO kernel: [ 13.886716] vmwgfx 0000:00:0f.0: [drm]
Capabilities: rect copy, cursor, cursor bypass, cursor bypass 2, 8bit emulation, alpha
cursor, 3D, extended fifo, multimon, pitchlock, irq mask, display topology, gmr, traces,
gmr2, screen object 2, command buffers, command buffers 2, gobject, dx, hp cmd queue, no
bb restriction, cap2 register,
2024-04-26T16:01:06.549052Z INFO kernel: [ 13.893726] vmwgfx 0000:00:0f.0: [drm]
Capabilities2: grow otable, intra surface copy,
2024-04-26T16:01:06.549055Z INFO kernel: [ 13.895670] vmwgfx 0000:00:0f.0: [drm] DMA
map mode: Caching DMA mappings.
2024-04-26T16:01:06.549057Z INFO kernel: [ 13.898925] vmwgfx 0000:00:0f.0: [drm] Legacy
memory limits: VRAM = 4096 kB, FIFO = 256 kB, surface = 0 kB
2024-04-26T16:01:06.549060Z INFO kernel: [ 13.935064] vmwgfx 0000:00:0f.0: [drm] MOB
limits: max mob size = 131072 kB, max mob pages = 196608
2024-04-26T16:01:06.549063Z INFO kernel: [ 13.937684] vmwgfx 0000:00:0f.0: [drm] Max
GMR ids is 64
2024-04-26T16:01:06.549071Z INFO kernel: [ 13.939261] vmwgfx 0000:00:0f.0: [drm] Max
number of GMR pages is 65536
2024-04-26T16:01:06.549073Z INFO kernel: [ 13.940881] vmwgfx 0000:00:0f.0: [drm]
Maximum display memory size is 262144 kiB
2024-04-26T16:01:06.549076Z INFO kernel: [ 14.049225] vmwgfx 0000:00:0f.0: [drm] Screen
Target display unit initialized
```



```
2024-04-26T16:01:06.549078Z INFO kernel: [ 14.087226] vmwgfx 0000:00:0f.0: [drm] Fifo
max 0x00040000 min 0x00001000 cap 0x0000077f
2024-04-26T16:01:06.549081Z INFO kernel: [ 14.136058] vmwgfx 0000:00:0f.0: [drm] Using
command buffers with DMA pool.
2024-04-26T16:01:06.549083Z INFO kernel: [ 14.138326] vmwgfx 0000:00:0f.0: [drm]
Available shader model: SM4.
2024-04-26T16:01:06.549091Z INFO kernel: [ 14.144228] [drm] Initialized vmwgfx 2.20.0
20211206 for 0000:00:0f.0 on minor 0
2024-04-26T16:01:06.549094Z INFO kernel: [ 14.248729] loop: module loaded
2024-04-26T16:01:06.549096Z INFO kernel: [ 14.284192] lkdtm: No crash points
registered, enable through debugfs
2024-04-26T16:01:06.549099Z INFO kernel: [ 14.286901] pci 0000:00:07.7: attach allowed
to drvr vmw_vmci [internal device]
2024-04-26T16:01:06.549101Z INFO kernel: [ 14.289122] vmw_vmci 0000:00:07.7: enabling
device (0000 -> 0003)
2024-04-26T16:01:06.549104Z INFO kernel: [ 14.296035] vmw_vmci 0000:00:07.7: Found VMCI
PCI device at 0x12100, irq 16
2024-04-26T16:01:06.549106Z INFO kernel: [ 14.333099] vmw_vmci 0000:00:07.7: Using
capabilities 0xc
2024-04-26T16:01:06.549114Z INFO kernel: [ 14.336943] Guest personality initialized and
is active
2024-04-26T16:01:06.549117Z INFO kernel: [ 14.339070] VMCI host device registered
(name=vmci, major=10, minor=126)
2024-04-26T16:01:06.549119Z INFO kernel: [ 14.341388] Initialized host personality
2024-04-26T16:01:06.549122Z INFO kernel: [ 14.344167] VMware PVSCSI driver - version
1.0.7.0-k
2024-04-26T16:01:06.549124Z INFO kernel: [ 14.384938] pci 0000:03:00.0: attach allowed
to drvr nvme [internal device]
2024-04-26T16:01:06.549127Z INFO kernel: [ 14.388066] nvme nvme0: pci function
0000:03:00.0
2024-04-26T16:01:06.549135Z INFO kernel: [ 14.390780] pci 0000:00:07.1: attach allowed
to drvr ata_piix [internal device]
2024-04-26T16:01:06.549137Z DEBUG kernel: [ 14.393746] ata_piix 0000:00:07.1: version
2.13
2024-04-26T16:01:06.549140Z INFO kernel: [ 14.436007] scsi host0: ata_piix
2024-04-26T16:01:06.549142Z INFO kernel: [ 14.440885] scsi host1: ata_piix
2024-04-26T16:01:06.549145Z INFO kernel: [ 14.442560] ata1: PATA max UDMA/33 cmd 0x1f0
ctl 0x3f6 bmdma 0x2150 irq 14
2024-04-26T16:01:06.549147Z INFO kernel: [ 14.445259] ata2: PATA max UDMA/33 cmd 0x170
ctl 0x376 bmdma 0x2158 irq 15
2024-04-26T16:01:06.549150Z INFO kernel: [ 14.445968] nvme nvme0: 8/0/0
default/read/poll queues
2024-04-26T16:01:06.549158Z INFO kernel: [ 14.448204] ata_piix 0000:00:07.1: attach
allowed to drvr ata_generic [internal device]
2024-04-26T16:01:06.549161Z DEBUG kernel: [ 14.489163] mdio_bus fixed-0: GPIO lookup
for consumer reset
2024-04-26T16:01:06.549163Z DEBUG kernel: [ 14.489186] mdio_bus fixed-0: using lookup
tables for GPIO lookup
2024-04-26T16:01:06.549165Z DEBUG kernel: [ 14.489214] mdio_bus fixed-0: No GPIO
consumer reset found
2024-04-26T16:01:06.549168Z INFO kernel: [ 14.489255] PPP generic driver version 2.4.2
2024-04-26T16:01:06.549170Z INFO kernel: [ 14.492040] PPP MPPE Compression module
registered
2024-04-26T16:01:06.549178Z INFO kernel: [ 14.493692] VMware vmxnet3 virtual NIC driver
- version 1.6.0.0-k-NAPI
2024-04-26T16:01:06.549181Z INFO kernel: [ 14.497330] ehci_hcd: USB 2.0 'Enhanced' Host
Controller (EHCI) Driver
2024-04-26T16:01:06.549184Z INFO kernel: [ 14.533110] ehci-pci: EHCI PCI platform
driver
2024-04-26T16:01:06.549186Z INFO kernel: [ 14.534843] pci 0000:02:03.0: attach allowed
to drvr ehci-pci [internal device]
2024-04-26T16:01:06.549189Z INFO kernel: [ 14.539339] ehci-pci 0000:02:03.0: EHCI Host
Controller
2024-04-26T16:01:06.549191Z INFO kernel: [ 14.542834] ehci-pci 0000:02:03.0: new USB
bus registered, assigned bus number 1
2024-04-26T16:01:06.549199Z INFO kernel: [ 14.547164] ehci-pci 0000:02:03.0: irq 17, io
mem 0xfc044000
2024-04-26T16:01:06.549202Z INFO kernel: [ 14.589302] nvme0n1: p1 p2 p3 p4 p5 p6 p7 p8
p9 p10 p11 p12
```

```
2024-04-26T16:01:06.549204Z INFO kernel: [ 14.590105] ehci-pci 0000:02:03.0: USB 2.0
started, EHCI 1.00
2024-04-26T16:01:06.549207Z INFO kernel: [ 14.594050] usb usb1: New USB device found,
idVendor=1d6b, idProduct=0002, bcdDevice= 5.15
2024-04-26T16:01:06.549209Z INFO kernel: [ 14.597470] usb usb1: New USB device strings:
Mfr=3, Product=2, SerialNumber=1
2024-04-26T16:01:06.549212Z INFO kernel: [ 14.634329] usb usb1: Product: EHCI Host
Controller
2024-04-26T16:01:06.549214Z INFO kernel: [ 14.636237] usb usb1: Manufacturer: Linux
5.15.108-18907-gba143be42d3a-dirty ehci_hcd
2024-04-26T16:01:06.549222Z INFO kernel: [ 14.639222] usb usb1: SerialNumber:
0000:02:03.0
2024-04-26T16:01:06.549225Z INFO kernel: [ 14.642830] hub 1-0:1.0: USB hub found
2024-04-26T16:01:06.549227Z INFO kernel: [ 14.644207] hub 1-0:1.0: 6 ports detected
2024-04-26T16:01:06.549230Z INFO kernel: [ 14.647555] ohci_hcd: USB 1.1 'Open' Host
Controller (OHCI) Driver
2024-04-26T16:01:06.549232Z INFO kernel: [ 14.684159] ohci-pci: OHCI PCI platform
driver
2024-04-26T16:01:06.549235Z INFO kernel: [ 14.685899] uhci_hcd: USB Universal Host
Controller Interface driver
2024-04-26T16:01:06.549243Z INFO kernel: [ 14.687802] pci 0000:02:00.0: attach allowed
to drvr uhci_hcd [internal device]
2024-04-26T16:01:06.549246Z INFO kernel: [ 14.691068] uhci_hcd 0000:02:00.0: UHCI Host
Controller
2024-04-26T16:01:06.549474Z INFO kernel: [ 14.692767] uhci_hcd 0000:02:00.0: new USB
bus registered, assigned bus number 2
2024-04-26T16:01:06.549481Z INFO kernel: [ 14.695565] uhci_hcd 0000:02:00.0: irq 18, io
base 0x00001040
2024-04-26T16:01:06.549483Z INFO kernel: [ 14.698414] usb usb2: New USB device found,
idVendor=1d6b, idProduct=0001, bcdDevice= 5.15
2024-04-26T16:01:06.549486Z INFO kernel: [ 14.735002] usb usb2: New USB device strings:
Mfr=3, Product=2, SerialNumber=1
2024-04-26T16:01:06.549488Z INFO kernel: [ 14.737684] usb usb2: Product: UHCI Host
Controller
2024-04-26T16:01:06.549499Z INFO kernel: [ 14.739590] usb usb2: Manufacturer: Linux
5.15.108-18907-gba143be42d3a-dirty uhci_hcd
2024-04-26T16:01:06.549502Z INFO kernel: [ 14.742859] usb usb2: SerialNumber:
0000:02:00.0
2024-04-26T16:01:06.549504Z INFO kernel: [ 14.745355] hub 2-0:1.0: USB hub found
2024-04-26T16:01:06.549507Z INFO kernel: [ 14.746864] hub 2-0:1.0: 2 ports detected
2024-04-26T16:01:06.549509Z INFO kernel: [ 14.784293] usbcore: registered new interface
driver cdc_acm
2024-04-26T16:01:06.549512Z INFO kernel: [ 14.786508] cdc_acm: USB Abstract Control
Model driver for USB modems and ISDN adapters
2024-04-26T16:01:06.549520Z INFO kernel: [ 14.796926] usbcore: registered new interface
driver uas
2024-04-26T16:01:06.549522Z INFO kernel: [ 14.798598] usbcore: registered new interface
driver usb-storage
2024-04-26T16:01:06.549525Z INFO kernel: [ 14.833931] usbcore: registered new interface
driver ums-realtek
2024-04-26T16:01:06.549527Z INFO kernel: [ 14.835859] usbcore: registered new interface
driver usbserial_generic
2024-04-26T16:01:06.549530Z INFO kernel: [ 14.837675] usbserial: USB Serial support
registered for generic
2024-04-26T16:01:06.549532Z INFO kernel: [ 14.839697] i8042: PNP: PS/2 Controller
[PNP0303:KBC,PNP0f13:MOUS] at 0x60,0x64 irq 1,12
2024-04-26T16:01:06.549542Z INFO kernel: [ 14.946549] serio: i8042 KBD port at
0x60,0x64 irq 1
2024-04-26T16:01:06.549545Z INFO kernel: [ 14.948409] serio: i8042 AUX port at
0x60,0x64 irq 12
2024-04-26T16:01:06.549547Z INFO kernel: [ 14.990399] rtc_cmos 00:01: registered as
rtc0
2024-04-26T16:01:06.549550Z DEBUG kernel: [ 14.991806] rtc_cmos 00:01: GPIO lookup for
consumer wp
2024-04-26T16:01:06.549552Z DEBUG kernel: [ 14.991825] rtc_cmos 00:01: using ACPI for
GPIO lookup
2024-04-26T16:01:06.549555Z DEBUG kernel: [ 14.991840] acpi PNP0B00:00: GPIO: looking
up wp-gpios
2024-04-26T16:01:06.549557Z DEBUG kernel: [ 14.991876] acpi PNP0B00:00: GPIO: looking
```

```
up wp-gpio
2024-04-26T16:01:06.549565Z DEBUG kernel: [ 14.991891] rtc_cmos 00:01: using lookup
tables for GPIO lookup
2024-04-26T16:01:06.549568Z DEBUG kernel: [ 14.991903] rtc_cmos 00:01: No GPIO consumer
wp found
2024-04-26T16:01:06.549570Z INFO kernel: [ 14.992119] rtc_cmos 00:01: alarms up to one
month, y3k, 242 bytes nvram
2024-04-26T16:01:06.549573Z INFO kernel: [ 14.994489] i2c_dev: i2c /dev entries driver
2024-04-26T16:01:06.549575Z INFO kernel: [ 14.997573] IR NEC protocol handler
initialized
2024-04-26T16:01:06.549577Z INFO kernel: [ 14.998937] IR RC5(x/sz) protocol handler
initialized
2024-04-26T16:01:06.549586Z INFO kernel: [ 15.034325] IR RC6 protocol handler
initialized
2024-04-26T16:01:06.549589Z INFO kernel: [ 15.036471] IR JVC protocol handler
initialized
2024-04-26T16:01:06.549591Z INFO kernel: [ 15.038456] IR Sony protocol handler
initialized
2024-04-26T16:01:06.549594Z INFO kernel: [ 15.040146] IR SANYO protocol handler
initialized
2024-04-26T16:01:06.549596Z INFO kernel: [ 15.041727] IR Sharp protocol handler
initialized
2024-04-26T16:01:06.549599Z INFO kernel: [ 15.043354] IR MCE Keyboard/mouse protocol
handler initialized
2024-04-26T16:01:06.549601Z INFO kernel: [ 15.045185] IR XMP protocol handler
initialized
2024-04-26T16:01:06.549609Z INFO kernel: [ 15.047233] iTCO_vendor_support: vendor-
support=0
2024-04-26T16:01:06.549612Z INFO kernel: [ 15.083115] device-mapper: ioctl: 4.45.0-
ioctl (2021-03-22) initialised: dm-devel@redhat.com
2024-04-26T16:01:06.549614Z INFO kernel: [ 15.083178] input: AT Translated Set 2
keyboard as /devices/platform/i8042/serio0/input/input1
2024-04-26T16:01:06.549617Z INFO kernel: [ 15.087722] device-mapper: verity-chromeos:
dm-verity-chromeos registered
2024-04-26T16:01:06.549619Z INFO kernel: [ 15.089521] usb 2-1: new full-speed USB
device number 2 using uhci_hcd
2024-04-26T16:01:06.549622Z INFO kernel: [ 15.091477] intel_pstate: CPU model not
supported
2024-04-26T16:01:06.549630Z INFO kernel: [ 15.091803] sdhci: Secure Digital Host
Controller Interface driver
2024-04-26T16:01:06.549633Z INFO kernel: [ 15.098716] sdhci: Copyright(c) Pierre Ossman
2024-04-26T16:01:06.549635Z INFO kernel: [ 15.134337] EFI Variables Facility v0.08
2004-May-17
2024-04-26T16:01:06.549637Z INFO kernel: [ 15.134895] input: VirtualPS/2 VMware VMMouse
as /devices/platform/i8042/serio1/input/input4
2024-04-26T16:01:06.549640Z INFO kernel: [ 15.144039] input: VirtualPS/2 VMware VMMouse
as /devices/platform/i8042/serio1/input/input3
2024-04-26T16:01:06.549643Z INFO kernel: [ 15.397150] usb 2-1: New USB device found,
idVendor=0e0f, idProduct=0003, bcdDevice= 1.03
2024-04-26T16:01:06.549651Z INFO kernel: [ 15.433906] usb 2-1: New USB device strings:
Mfr=1, Product=2, SerialNumber=0
2024-04-26T16:01:06.549653Z INFO kernel: [ 15.436708] usb 2-1: Product: VMware Virtual
USB Mouse
2024-04-26T16:01:06.549656Z INFO kernel: [ 15.438765] usb 2-1: Manufacturer: VMware
2024-04-26T16:01:06.549658Z INFO kernel: [ 15.440782] pstore: Registered efi as
persistent store backend
2024-04-26T16:01:06.549661Z INFO kernel: [ 15.443108] hid: raw HID events driver (C)
Jiri Kosina
2024-04-26T16:01:06.549663Z INFO kernel: [ 15.487374] input: VMware VMware Virtual USB
Mouse as /devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-1/2-
1:1.0/0003:0E0F:0003.0001/input/input5
2024-04-26T16:01:06.549666Z INFO kernel: [ 15.491979] hid-generic 0003:0E0F:0003.0001:
input,hidraw0: USB HID v1.10 Mouse [VMware VMware Virtual USB Mouse] on usb-0000:02:00.0-
1/input0
2024-04-26T16:01:06.549675Z INFO kernel: [ 15.497459] usbcore: registered new interface
driver usbhid
2024-04-26T16:01:06.549679Z INFO kernel: [ 15.533245] usbhid: USB HID core driver
2024-04-26T16:01:06.549682Z INFO kernel: [ 15.536363] ashmem: initialized
2024-04-26T16:01:06.549685Z ERR kernel: [ 15.545876] cros_ec_lpcs: unsupported system.
```

```

2024-04-26T16:01:06.549687Z INFO kernel: [ 15.588248] GACT probability NOT on
2024-04-26T16:01:06.549690Z INFO kernel: [ 15.738286] usb 2-2: new full-speed USB
device number 3 using uhci_hcd
2024-04-26T16:01:06.549703Z INFO kernel: [ 15.794973] xt_time: kernel timezone is -0000
2024-04-26T16:01:06.549710Z INFO kernel: [ 15.797750] Initializing XFRM netlink socket
2024-04-26T16:01:06.549713Z INFO kernel: [ 15.834730] NET: Registered PF_INET6 protocol
family
2024-04-26T16:01:06.549716Z INFO kernel: [ 15.843277] Segment Routing with IPv6
2024-04-26T16:01:06.549719Z INFO kernel: [ 15.844625] In-situ OAM (IOAM) with IPv6
2024-04-26T16:01:06.549722Z INFO kernel: [ 15.846520] NET: Registered PF_PACKET
protocol family
2024-04-26T16:01:06.549735Z INFO kernel: [ 15.848490] NET: Registered PF_KEY protocol
family
2024-04-26T16:01:06.549740Z INFO kernel: [ 15.888008] IPI shorthand broadcast: enabled
2024-04-26T16:01:06.549743Z INFO kernel: [ 15.889458] AVX2 version of gcm_enc/dec
engaged.
2024-04-26T16:01:06.549746Z INFO kernel: [ 15.891739] AES CTR mode by8 optimization
enabled
2024-04-26T16:01:06.549747Z INFO kernel: [ 15.942937] usb 2-2: New USB device found,
idVendor=0e0f, idProduct=0002, bcdDevice= 1.00
2024-04-26T16:01:06.549749Z INFO kernel: [ 15.946509] usb 2-2: New USB device strings:
Mfr=1, Product=2, SerialNumber=0
2024-04-26T16:01:06.549758Z INFO kernel: [ 15.984201] usb 2-2: Product: VMware Virtual
USB Hub
2024-04-26T16:01:06.549760Z INFO kernel: [ 15.986917] usb 2-2: Manufacturer: VMware,
Inc.
2024-04-26T16:01:06.549762Z INFO kernel: [ 15.996466] hub 2-2:1.0: USB hub found
2024-04-26T16:01:06.549764Z INFO kernel: [ 15.998433] sched_clock: Marking stable
(15964469495, 33583187)->(19328241243, -3330188561)
2024-04-26T16:01:06.549766Z INFO kernel: [ 16.036872] registered taskstats version 1
2024-04-26T16:01:06.549768Z INFO kernel: [ 16.038043] hub 2-2:1.0: 7 ports detected
2024-04-26T16:01:06.549769Z NOTICE kernel: [ 16.043858] Key type .fscrypt registered
2024-04-26T16:01:06.549777Z NOTICE kernel: [ 16.045485] Key type fscrypt-provisioning
registered
2024-04-26T16:01:06.549781Z INFO kernel: [ 16.088439] pstore: Using crash dump
compression: deflate
2024-04-26T16:01:06.549783Z NOTICE kernel: [ 16.097029] Key type encrypted registered
2024-04-26T16:01:06.549785Z INFO kernel: [ 16.133445] PM: Magic number: 4:600:35
2024-04-26T16:01:06.549787Z INFO kernel: [ 16.135154] bdi 7:0: hash matches
2024-04-26T16:01:06.549790Z INFO kernel: [ 16.138184] ALSA device list:
2024-04-26T16:01:06.549799Z INFO kernel: [ 16.139266] No soundcards found.
2024-04-26T16:01:06.549801Z ERR kernel: [ 16.141767] Warning: unable to open an initial
console.
2024-04-26T16:01:06.549805Z INFO kernel: [ 16.145915] EXT4-fs (nvme0n1p3): mounting
ext2 file system using the ext4 subsystem
2024-04-26T16:01:06.549807Z INFO kernel: [ 16.191895] EXT4-fs (nvme0n1p3): mounted
filesystem without journal. Opts: (null). Quota mode: none.
2024-04-26T16:01:06.549810Z INFO kernel: [ 16.195411] VFS: Mounted root (ext2
filesystem) readonly on device 259:3.
2024-04-26T16:01:06.549812Z INFO kernel: [ 16.236052] devtmpfs: mounted
2024-04-26T16:01:06.549816Z INFO kernel: [ 16.243777] Freeing unused kernel image
(initmem) memory: 1784K
2024-04-26T16:01:06.549822Z INFO kernel: [ 16.245856] Write protecting the kernel read-
only data: 20480k
2024-04-26T16:01:06.549824Z INFO kernel: [ 16.283495] Freeing unused kernel image
(text/rodata gap) memory: 2032K
2024-04-26T16:01:06.549825Z INFO kernel: [ 16.287099] Freeing unused kernel image
(rodata/data gap) memory: 432K
2024-04-26T16:01:06.549827Z INFO kernel: [ 16.289377] Run /sbin/init as init process
2024-04-26T16:01:06.549829Z DEBUG kernel: [ 16.291140] with arguments:
2024-04-26T16:01:06.549831Z DEBUG kernel: [ 16.291157] /sbin/init
2024-04-26T16:01:06.549839Z DEBUG kernel: [ 16.291174] noresume
2024-04-26T16:01:06.549841Z DEBUG kernel: [ 16.291197] noswap
2024-04-26T16:01:06.549843Z DEBUG kernel: [ 16.291213] cros_efi
2024-04-26T16:01:06.549845Z DEBUG kernel: [ 16.291228] cros_debug
2024-04-26T16:01:06.549846Z DEBUG kernel: [ 16.291251] with environment:
2024-04-26T16:01:06.549848Z DEBUG kernel: [ 16.291270] HOME=/
2024-04-26T16:01:06.549856Z DEBUG kernel: [ 16.291291] TERM=linux
2024-04-26T16:01:06.549858Z DEBUG kernel: [ 16.291312]

```

```
BOOT_IMAGE=/syslinux/vmlinuz.A
2024-04-26T16:01:06.549860Z DEBUG kernel: [ 16.291345] boot=local
2024-04-26T16:01:06.549862Z INFO kernel: [ 16.683216] usb 2-2.1: new full-speed USB
device number 4 using uhci_hcd
2024-04-26T16:01:06.549864Z INFO kernel: [ 16.987929] usb 2-2.1: New USB device found,
idVendor=0e0f, idProduct=0008, bcdDevice= 1.00
2024-04-26T16:01:06.549866Z INFO kernel: [ 16.990326] SELinux: Permission
nlmsg_getneigh in class netlink_route_socket not defined in policy.
2024-04-26T16:01:06.549868Z INFO kernel: [ 16.991416] usb 2-2.1: New USB device
strings: Mfr=1, Product=2, SerialNumber=3
2024-04-26T16:01:06.549878Z INFO kernel: [ 16.995168] SELinux: Permission perfmon in
class capability2 not defined in policy.
2024-04-26T16:01:06.549880Z INFO kernel: [ 16.997557] usb 2-2.1: Product: Virtual
Bluetooth Adapter
2024-04-26T16:01:06.549882Z INFO kernel: [ 17.033874] SELinux: Permission bpf in class
capability2 not defined in policy.
2024-04-26T16:01:06.549884Z INFO kernel: [ 17.035956] usb 2-2.1: Manufacturer: VMware
2024-04-26T16:01:06.549885Z INFO kernel: [ 17.038862] SELinux: Permission
checkpoint_restore in class capability2 not defined in policy.
2024-04-26T16:01:06.549887Z INFO kernel: [ 17.040883] usb 2-2.1: SerialNumber:
000650268328
2024-04-26T16:01:06.549895Z INFO kernel: [ 17.044373] SELinux: Permission perfmon in
class cap2_userns not defined in policy.
2024-04-26T16:01:06.549897Z INFO kernel: [ 17.082792] SELinux: Permission bpf in class
cap2_userns not defined in policy.
2024-04-26T16:01:06.549899Z INFO kernel: [ 17.085701] SELinux: Permission
checkpoint_restore in class cap2_userns not defined in policy.
2024-04-26T16:01:06.549900Z INFO kernel: [ 17.089120] SELinux: Class mctp_socket not
defined in policy.
2024-04-26T16:01:06.549994Z INFO kernel: [ 17.091040] SELinux: Class anon_inode not
defined in policy.
2024-04-26T16:01:06.550001Z INFO kernel: [ 17.092934] SELinux: the above unknown
classes and permissions will be allowed
2024-04-26T16:01:06.550041Z INFO kernel: [ 17.243151] SELinux: policy capability
network_peer_controls=1
2024-04-26T16:01:06.550045Z INFO kernel: [ 17.245614] SELinux: policy capability
open_perms=1
2024-04-26T16:01:06.550047Z INFO kernel: [ 17.247657] SELinux: policy capability
extended_socket_class=1
2024-04-26T16:01:06.550049Z INFO kernel: [ 17.283306] SELinux: policy capability
always_check_network=0
2024-04-26T16:01:06.550050Z INFO kernel: [ 17.286364] SELinux: policy capability
cgroup_seclabel=0
2024-04-26T16:01:06.550052Z INFO kernel: [ 17.289065] SELinux: policy capability
nnp_nosuid_transition=1
2024-04-26T16:01:06.550054Z INFO kernel: [ 17.291884] SELinux: policy capability
genfs_seclabel_symlinks=0
2024-04-26T16:01:06.550062Z INFO kernel: [ 17.294718] SELinux: policy capability
ioctl_skip_cloexec=0
2024-04-26T16:01:06.550064Z NOTICE kernel: [ 17.748501] audit: type=1403
audit(1714147258.466:2): auid=4294967295 ses=4294967295 lsm=selinux res=1
2024-04-26T16:01:06.550066Z NOTICE kernel: [ 17.793331] audit: type=1400
audit(1714147258.511:3): avc: denied { read } for pid=1 comm="init" name="/"
dev="devpts" ino=1 scontext=u:r:kernel:s0 tcontext=u:object_r:devpts:s0 tclass=dir
permissive=1
2024-04-26T16:01:06.550068Z NOTICE kernel: [ 17.836106] audit: type=1400
audit(1714147258.511:4): avc: denied { open } for pid=1 comm="init" path="/dev/pts"
dev="devpts" ino=1 scontext=u:r:kernel:s0 tcontext=u:object_r:devpts:s0 tclass=dir
permissive=1
2024-04-26T16:01:06.550070Z NOTICE kernel: [ 17.844790] audit: type=1400
audit(1714147258.512:5): avc: denied { getattr } for pid=1 comm="init"
path="/dev/pts/ptmx" dev="devpts" ino=2 scontext=u:r:kernel:s0
tcontext=u:object_r:devpts:s0 tclass=chr_file permissive=1
2024-04-26T16:01:06.550079Z NOTICE kernel: [ 17.887361] audit: type=1400
audit(1714147258.553:6): avc: denied { relabelfrom } for pid=1 comm="init" name="/"
dev="tmpfs" ino=1 scontext=u:r:kernel:s0 tcontext=u:object_r:tmpfs:s0 tclass=dir
permissive=1
2024-04-26T16:01:06.550086Z NOTICE kernel: [ 17.896635] audit: type=1400
audit(1714147258.553:7): avc: denied { relabelto } for pid=1 comm="init" name="/"
```

```
dev="tmpfs" ino=1 scontext=u:r:kernel:s0 tcontext=u:object_r:cross_run:s0 tclass=dir
permissive=1
2024-04-26T16:01:06.550091Z NOTICE kernel: [ 17.939426] audit: type=1400
audit(1714147258.554:8): avc: denied { relabelto } for pid=1 comm="init" name="lock"
dev="tmpfs" ino=2 scontext=u:r:kernel:s0 tcontext=u:object_r:cross_run_lock:s0 tclass=dir
permissive=1
2024-04-26T16:01:06.550093Z NOTICE kernel: [ 17.984289] audit: type=1400
audit(1714147258.563:9): avc: denied { setattr } for pid=1 comm="init" name="lock"
dev="tmpfs" ino=2 scontext=u:r:cross_init:s0 tcontext=u:object_r:cross_run_lock:s0
tclass=dir permissive=1
2024-04-26T16:01:06.550095Z NOTICE kernel: [ 17.994131] audit: type=1400
audit(1714147258.563:10): avc: denied { search } for pid=1 comm="init" name="features"
dev="sysfs" ino=30728 scontext=u:r:cross_init:s0
tcontext=u:object_r:sysfs_fs_ext4_features:s0 tclass=dir permissive=1
2024-04-26T16:01:06.550106Z NOTICE kernel: [ 18.038817] audit: type=1400
audit(1714147258.563:11): avc: denied { search } for pid=1 comm="init"
scontext=u:r:cross_init:s0 tcontext=u:r:kernel:s0 tclass=key permissive=1
2024-04-26T16:01:06.550108Z NOTICE kernel: [ 18.739734] random: init: uninitialized
urandom read (12 bytes read)
2024-04-26T16:01:06.550110Z INFO kernel: [ 20.840539] loop0: detected capacity change
from 0 to 8
2024-04-26T16:01:06.550112Z INFO kernel: [ 21.087707] udevd[194]: starting version 225
2024-04-26T16:01:06.550113Z NOTICE kernel: [ 21.135476] random: udevadm: uninitialized
urandom read (16 bytes read)
2024-04-26T16:01:06.550115Z NOTICE kernel: [ 21.138645] random: udevadm: uninitialized
urandom read (16 bytes read)
2024-04-26T16:01:06.550180Z NOTICE kernel: [ 21.141760] random: udevd: uninitialized
urandom read (16 bytes read)
2024-04-26T16:01:06.550186Z INFO kernel: [ 21.874640] EXT4-fs (nvme0n1p1): recovery
complete
2024-04-26T16:01:06.550188Z WARNING kernel: [ 21.877470] EXT4-fs (nvme0n1p1): mounting
with "discard" option, but the device does not support discard
2024-04-26T16:01:06.550190Z INFO kernel: [ 21.881936] EXT4-fs (nvme0n1p1): mounted
filesystem with ordered data mode. Opts: commit=600,discard. Quota mode: journalled.
2024-04-26T16:01:06.550192Z INFO kernel: [ 21.919339] EXT4-fs (nvme0n1p8): orphan
cleanup on readonly fs
2024-04-26T16:01:06.550194Z INFO kernel: [ 21.921970] EXT4-fs (nvme0n1p8): mounted
filesystem with ordered data mode. Opts: . Quota mode: none.
2024-04-26T16:01:06.550251Z INFO kernel: [ 21.997791] EXT4-fs (nvme0n1p1): re-mounted.
Opts: . Quota mode: journalled.
2024-04-26T16:01:06.550255Z NOTICE kernel: [ 22.188945] random: udevd: uninitialized
urandom read (16 bytes read)
2024-04-26T16:01:06.550256Z NOTICE kernel: [ 22.192115] random: udevd: uninitialized
urandom read (16 bytes read)
2024-04-26T16:01:06.550257Z NOTICE kernel: [ 22.195470] random: udevd: uninitialized
urandom read (16 bytes read)
2024-04-26T16:01:06.550258Z INFO kernel: [ 22.215976] loop1: detected capacity change
from 0 to 2048
2024-04-26T16:01:06.550260Z WARNING kernel: [ 22.237186] EXT4-fs (loop1): warning:
mounting unchecked fs, running e2fsck is recommended
2024-04-26T16:01:06.550324Z INFO kernel: [ 22.252677] EXT4-fs (loop1): mounted
filesystem without journal. Opts: (null). Quota mode: none.
2024-04-26T16:01:06.550332Z INFO kernel: [ 22.511030] LoadPin: nvme0n1p3 (259:3):
writable
2024-04-26T16:01:06.550334Z INFO kernel: [ 22.513297] LoadPin: enforcement can be
disabled.
2024-04-26T16:01:06.550335Z NOTICE kernel: [ 22.515442] LoadPin: kernel-module pinned
obj="/lib/modules/5.15.108-18907-gba143be42d3a-dirty/kernel/drivers/input/joydev.ko"
pid=238 cmdline="udevd --daemon"
2024-04-26T16:01:06.550336Z NOTICE kernel: [ 22.813627] random: crng init done
2024-04-26T16:01:06.550337Z NOTICE kernel: [ 22.815506] random: 724 urandom warning(s)
missed due to ratelimiting
2024-04-26T16:01:06.550710Z WARNING kernel: [ 22.818847] kauditd_printk_skb: 628
callbacks suppressed
2024-04-26T16:01:06.550719Z NOTICE kernel: [ 22.818853] audit: type=1400
audit(1714147263.534:640): avc: denied { execute } for pid=339 comm="is_developer_en"
name="crosssystem" dev="nvme0n1p3" ino=8862 scontext=u:r:chromeos:s0
tcontext=u:object_r:cross_crosssystem_exec:s0 tclass=file permissive=1
2024-04-26T16:01:06.550722Z NOTICE kernel: [ 22.833670] audit: type=1400
```

```
audit(1714147263.534:641): avc: denied { execute_no_trans } for pid=339
comm="is_developer_en" path="/usr/bin/crossystem" dev="nvme0n1p3" ino=8862
scontext=u:r:chromeos:s0 tcontext=u:object_r:cros_crosssystem_exec:s0 tclass=file
permissive=1
2024-04-26T16:01:06.550724Z NOTICE kernel: [ 22.848763] audit: type=1400
audit(1714147263.534:642): avc: denied { map } for pid=339 comm="crossystem"
path="/usr/bin/crossystem" dev="nvme0n1p3" ino=8862 scontext=u:r:chromeos:s0
tcontext=u:object_r:cros_crosssystem_exec:s0 tclass=file permissive=1
2024-04-26T16:01:06.550726Z ERR kernel: [ 22.852589] tpm tpm0: A TPM error (256)
occurred attempting the self test
2024-04-26T16:01:06.550793Z NOTICE kernel: [ 22.857787] audit: type=1400
audit(1714147263.541:643): avc: denied { use } for pid=340 comm="frecon"
path="/sbin/frecon" dev="nvme0n1p3" ino=8774 scontext=u:r:frecon:s0
tcontext=u:r:cros_init_scripts:s0 tclass=fd permissive=1
2024-04-26T16:01:06.550801Z INFO kernel: [ 22.860671] tpm tpm0: starting up the TPM
manually
2024-04-26T16:01:06.550805Z NOTICE kernel: [ 22.867636] audit: type=1400
audit(1714147263.551:644): avc: denied { create } for pid=341 comm="haveged"
name="haveged.pid" scontext=u:r:chromeos:s0 tcontext=u:object_r:cros_run:s0 tclass=file
permissive=1
2024-04-26T16:01:06.550870Z NOTICE kernel: [ 22.878570] audit: type=1400
audit(1714147263.551:645): avc: denied { open } for pid=341 comm="haveged"
path="/run/haveged.pid" dev="tmpfs" ino=171 scontext=u:r:chromeos:s0
tcontext=u:object_r:cros_run:s0 tclass=file permissive=1
2024-04-26T16:01:06.550874Z NOTICE kernel: [ 22.888411] audit: type=1400
audit(1714147263.551:646): avc: denied { getattr } for pid=341 comm="haveged"
path="/run/haveged.pid" dev="tmpfs" ino=171 scontext=u:r:chromeos:s0
tcontext=u:object_r:cros_run:s0 tclass=file permissive=1
2024-04-26T16:01:06.550986Z NOTICE kernel: [ 22.902292] audit: type=1400
audit(1714147263.553:647): avc: denied { read } for pid=211 comm="tpm2-simulator"
name="/" dev="loop1" ino=2 scontext=u:r:cros_tpm2_simulator:s0
tcontext=u:object_r:unlabeled:s0 tclass=dir permissive=1
2024-04-26T16:01:06.550996Z NOTICE kernel: [ 22.916064] audit: type=1400
audit(1714147263.553:648): avc: denied { open } for pid=211 comm="tpm2-simulator"
path="/mnt/stateful_partition/unencrypted/tpm2-simulator/NVChip_mount" dev="loop1" ino=2
scontext=u:r:cros_tpm2_simulator:s0 tcontext=u:object_r:unlabeled:s0 tclass=dir
permissive=1
2024-04-26T16:01:06.551000Z NOTICE kernel: [ 22.929949] audit: type=1400
audit(1714147263.553:649): avc: denied { getattr } for pid=211 comm="tpm2-simulator"
path="/mnt/stateful_partition/unencrypted/tpm2-simulator/NVChip_mount" dev="loop1" ino=2
scontext=u:r:cros_tpm2_simulator:s0 tcontext=u:object_r:unlabeled:s0 tclass=dir
permissive=1
2024-04-26T16:01:06.551003Z INFO kernel: [ 22.947872] frecon[343]: Frecon using drm
driver vmwgfx, version 2.20, date(20211206), desc(Linux drm driver for VMware graphics
devices)
2024-04-26T16:01:06.551054Z INFO kernel: [ 23.048911] loop2: detected capacity change
from 0 to 10587264
2024-04-26T16:01:06.551121Z INFO kernel: [ 24.414377] EXT4-fs (dm-0): 3 orphan inodes
deleted
2024-04-26T16:01:06.551128Z INFO kernel: [ 24.415791] EXT4-fs (dm-0): recovery complete
2024-04-26T16:01:06.551130Z INFO kernel: [ 24.430183] EXT4-fs (dm-0): mounted
filesystem with ordered data mode. Opts: discard,commit=600. Quota mode: none.
2024-04-26T16:01:06.551132Z INFO kernel: [ 25.158874] EXT4-fs (nvme0n1p1): re-mounted.
Opts: discard,resgid=20119,commit=600. Quota mode: journalled.
2024-04-26T16:01:06.551133Z INFO kernel: [ 25.302200] low_mem: threshold[0] 316 MB
2024-04-26T16:01:06.551135Z INFO kernel: [ 25.303761] low_mem: threshold[1] 2438 MB
2024-04-26T16:01:06.551207Z INFO kernel: [ 25.467289] loop3: detected capacity change
from 0 to 754088
2024-04-26T16:01:06.551259Z INFO kernel: [ 25.483433] zram: Added device: zram0
2024-04-26T16:01:06.647116Z INFO crash_reporter[545]: Enabling user crash handling
2024-04-26T16:01:06.714291Z INFO kernel: [ 25.989501] overlayfs: "xino" feature enabled
using 32 upper inode bits.
2024-04-26T16:01:06.949999Z NOTICE fydeos-shell-daemon[591]: shell daemon starting...
2024-04-26T16:01:07.279066Z INFO kernel: [ 26.551015] loop4: detected capacity change
from 0 to 212568
2024-04-26T16:01:07.795400Z INFO kernel: [ 27.070642] overlayfs: "xino" feature enabled
using 32 upper inode bits.
2024-04-26T16:01:08.290482Z INFO kernel: [ 27.560509] loop5: detected capacity change
from 0 to 8
```

2024-04-26T16:01:08.345416Z INFO kernel: [27.622872] loop6: detected capacity change from 0 to 8

2024-04-26T16:01:08.421292Z INFO kernel: [27.697882] zram0: detected capacity change from 0 to 24384240

2024-04-26T16:01:08.570769Z INFO kernel: [27.845325] Adding 12192116k swap on /dev/zram0. Priority:-2 extents:1 across:12192116k SS

2024-04-26T16:01:08.725385Z NOTICE cr50-result[661]: cr50-result for non-GSC case performs no-ops.

2024-04-26T16:01:08.905179Z WARNING minijail0[678]: libminijail[678]: failed to create a ruleset: Function not implemented

2024-04-26T16:01:08.908403Z WARNING minijail0[678]: libminijail[678]: Landlock is not supported by the current kernel: Function not implemented

2024-04-26T16:01:08.911581Z WARNING minijail0[702]: libminijail[1]: failed to create a ruleset: Function not implemented

2024-04-26T16:01:08.911938Z WARNING minijail0[702]: libminijail[1]: Landlock is not supported by the current kernel: Function not implemented

2024-04-26T16:01:08.912194Z INFO minijail0[702]: libminijail[1]: Landlock support for LANDLOCK_ACCESS_FS_REFERER: false

2024-04-26T16:01:08.958731Z INFO minijail0[710]: libminijail[710]: applying policy for default runtime: /etc/security/minijail/v0.bin

2024-04-26T16:01:08.961256Z WARNING minijail0[710]: libminijail[710]: failed to create a ruleset: Function not implemented

2024-04-26T16:01:08.961325Z WARNING minijail0[710]: libminijail[710]: Landlock is not supported by the current kernel: Function not implemented

2024-04-26T16:01:08.965645Z WARNING minijail0[713]: libminijail[713]: failed to create a ruleset: Function not implemented

2024-04-26T16:01:08.965670Z WARNING minijail0[713]: libminijail[713]: Landlock is not supported by the current kernel: Function not implemented

2024-04-26T16:01:08.965682Z INFO minijail0[713]: libminijail[713]: Landlock support for LANDLOCK_ACCESS_FS_REFERER: false

2024-04-26T16:01:09.182796Z INFO trunksd[718]: Initialized last errno: 0

2024-04-26T16:01:09.183103Z INFO trunksd[718]: TPM: /dev/tpm0 opened successfully

2024-04-26T16:01:09.193678Z INFO minijail0[695]: libminijail[695]: applying policy for default runtime: /etc/security/minijail/v0.bin

2024-04-26T16:01:09.201892Z INFO trunksd[746]: Trunks service started.

2024-04-26T16:01:09.267443Z WARNING trunksd[746]: TpmBasicInit: WARNING: The last TPM shutdown was not orderly.

2024-04-26T16:01:09.267560Z INFO trunksd[746]: CheckState: TPM State verified.

2024-04-26T16:01:09.298642Z INFO iioservice[712]: INFO iioservice: [main.cc(19)] (2) main(): Daemon started

2024-04-26T16:01:09.319985Z ERR iioservice[712]: ERROR iioservice: [connect.cc(61)] Failed to connect to service manager unix socket: No such file or directory (2)

2024-04-26T16:01:09.321914Z ERR iioservice[712]: ERROR iioservice: [connect.cc(61)] Failed to connect to service manager unix socket: No such file or directory (2)

2024-04-26T16:01:09.327218Z INFO mojo_service_manager[720]: DevMode is enabled, load extra configs from /usr/local/etc/mojo/service_manager/policy

2024-04-26T16:01:09.355195Z INFO mojo_service_manager[720]: mojo_service_manager started.

2024-04-26T16:01:09.358247Z INFO mojo_service_manager[720]: Receive connection from: u:r:cros_iioservice:s0

2024-04-26T16:01:09.361375Z INFO local_data_migration[757]: local data migration is non-applicable and performs no-ops.

2024-04-26T16:01:09.368485Z ERR spaced[673]: Failed to run command: No such file or directory (2)

2024-04-26T16:01:09.368589Z ERR spaced[673]: Failed to get output from pvdisplay

2024-04-26T16:01:09.423069Z INFO check_tpm_preinit_condition[765]: Not Booting from removable device. Quitting.

2024-04-26T16:01:09.549332Z WARNING minijail0[770]: libminijail[770]: failed to create a ruleset: Function not implemented

2024-04-26T16:01:09.549518Z WARNING minijail0[770]: libminijail[770]: Landlock is not supported by the current kernel: Function not implemented

2024-04-26T16:01:09.551113Z WARNING minijail0[772]: libminijail[1]: failed to create a ruleset: Function not implemented

2024-04-26T16:01:09.551344Z WARNING minijail0[772]: libminijail[1]: Landlock is not supported by the current kernel: Function not implemented

2024-04-26T16:01:09.551411Z INFO minijail0[772]: libminijail[1]: Landlock support for LANDLOCK_ACCESS_FS_REFERER: false

2024-04-26T16:01:09.563810Z INFO minijail0[773]: libminijail[773]: applying policy for default runtime: /etc/security/minijail/v0.bin

2024-04-26T16:01:09.684871Z INFO tpm_managerd[772]: Starting TPM Manager...


```
2024-04-26T16:01:09.736668Z WARNING tpm_managerd[772]: WARNING: Verified boot PCR 2 is not initialized.
2024-04-26T16:01:09.740547Z WARNING tpm_managerd[772]: WARNING: Verified boot PCR 3 is not initialized.
2024-04-26T16:01:09.787651Z ERR spaced[673]: Failed to run command: No such file or directory (2)
2024-04-26T16:01:09.787748Z ERR spaced[673]: Failed to get output from pvdisplay
2024-04-26T16:01:09.910975Z INFO tpm_managerd[772]: Ownership taken signal is sent.
2024-04-26T16:01:09.949946Z INFO minijail0[783]: libminijail[783]: applying policy for default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:09.960663Z ERR tpm_managerd[772]: Unknown alerts family: 0
2024-04-26T16:01:09.960687Z INFO tpm_managerd[772]: The TPM chip does not support GetAlertsData. Stop UploadAlertsData task.
2024-04-26T16:01:09.999863Z INFO tpm_managerd[772]: PeriodicResetDictionaryAttackCounterTask: DA reset succeeded.
2024-04-26T16:01:10.022828Z WARNING minijail0[788]: libminijail[1]: failed to create a ruleset: Function not implemented
2024-04-26T16:01:10.024192Z WARNING minijail0[785]: libminijail[785]: failed to create a ruleset: Function not implemented
2024-04-26T16:01:10.024197Z WARNING minijail0[788]: libminijail[1]: Landlock is not supported by the current kernel: Function not implemented
2024-04-26T16:01:10.024233Z WARNING minijail0[785]: libminijail[785]: Landlock is not supported by the current kernel: Function not implemented
2024-04-26T16:01:10.024775Z INFO minijail0[788]: libminijail[1]: Landlock support for LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:01:10.100074Z INFO kernel: [ 29.375230] e1000: Intel(R) PRO/1000 Network Driver
2024-04-26T16:01:10.100148Z INFO kernel: [ 29.377948] e1000: Copyright (c) 1999-2006 Intel Corporation.
2024-04-26T16:01:10.105289Z INFO kernel: [ 29.381097] Bluetooth: Core ver 2.22
2024-04-26T16:01:10.109644Z INFO kernel: [ 29.386293] NET: Registered PF_BLUETOOTH protocol family
2024-04-26T16:01:10.109718Z INFO kernel: [ 29.386431] pci 0000:02:01.0: attach allowed to driver e1000 [internal device]
2024-04-26T16:01:10.117729Z INFO kernel: [ 29.390317] Bluetooth: HCI device and connection manager initialized
2024-04-26T16:01:10.122003Z INFO kernel: [ 29.398510] Bluetooth: HCI socket layer initialized
2024-04-26T16:01:10.127285Z INFO kernel: [ 29.402673] Bluetooth: L2CAP socket layer initialized
2024-04-26T16:01:10.137796Z INFO kernel: [ 29.408151] Bluetooth: SCO socket layer initialized
2024-04-26T16:01:10.141270Z INFO bluetoothd[750]: Bluetooth daemon 5.54
2024-04-26T16:01:10.142933Z WARNING bluetoothd[750]: Unknown key MaxControllers for group General in /var/lib/bluetooth/main.conf
2024-04-26T16:01:10.143513Z INFO bluetoothd[750]: PageScanType=1(1)
2024-04-26T16:01:10.143542Z INFO bluetoothd[750]: PageScanInterval=1024(1024)
2024-04-26T16:01:10.143564Z INFO bluetoothd[750]: PageScanWindow=18(18)
2024-04-26T16:01:10.143605Z INFO bluetoothd[750]: EirMaxNameLength=180(180)
2024-04-26T16:01:10.143625Z INFO bluetoothd[750]: MinAdvertisementInterval=290(290)
2024-04-26T16:01:10.143645Z INFO bluetoothd[750]: MaxAdvertisementInterval=290(290)
2024-04-26T16:01:10.143668Z INFO bluetoothd[750]: ScanIntervalAutoConnect=588(588)
2024-04-26T16:01:10.143689Z INFO bluetoothd[750]: ScanWindowAutoConnect=60(60)
2024-04-26T16:01:10.143744Z INFO bluetoothd[750]: ScanIntervalDiscovery=36(36)
2024-04-26T16:01:10.143767Z INFO bluetoothd[750]: ScanWindowDiscovery=18(18)
2024-04-26T16:01:10.143787Z INFO bluetoothd[750]: ScanIntervalAdvMonitor=40(40)
2024-04-26T16:01:10.143806Z INFO bluetoothd[750]: ScanWindowAdvMonitor=20(20)
2024-04-26T16:01:10.143832Z INFO bluetoothd[750]: MinConnectionInterval=6(6)
2024-04-26T16:01:10.143876Z INFO bluetoothd[750]: MaxConnectionInterval=16(16)
2024-04-26T16:01:10.143902Z INFO bluetoothd[750]: ConnectionSupervisionTimeout=200(200)
2024-04-26T16:01:10.143934Z INFO bluetoothd[750]: Autoconnecttimeout=5000(5000)
2024-04-26T16:01:10.143967Z INFO bluetoothd[750]: EnableAdvMonInterleaveScan=1(1)
2024-04-26T16:01:10.149318Z INFO bluetoothd[750]: Starting SDP server
2024-04-26T16:01:10.247845Z INFO bluetoothd[750]: Applied debug levels: bluez(0), kernel(0)
2024-04-26T16:01:10.306833Z NOTICE boot-update-firmware[815]: Update fwupd firmware.
2024-04-26T16:01:10.316431Z INFO bluetoothd[750]: Bluetooth management interface 1.21 initialized
2024-04-26T16:01:10.498509Z INFO minijail0[845]: libminijail[845]: applying policy for
```

```

default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:10.553537Z WARNING minijail0[853]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:01:10.553590Z WARNING minijail0[853]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:10.553612Z INFO minijail0[853]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:01:10.556807Z INFO minijail0[854]: libminijail[854]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:10.557577Z WARNING minijail0[840]: libminijail[840]: failed to create a
ruleset: Function not implemented
2024-04-26T16:01:10.557629Z WARNING minijail0[840]: libminijail[840]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:10.639239Z INFO chapsd[834]: Starting PKCS #11 services.
2024-04-26T16:01:10.640057Z INFO chapsd[834]: Starting D-Bus dispatcher.
2024-04-26T16:01:10.657367Z INFO chapsd[834]: Adding slot: 0
2024-04-26T16:01:10.657451Z INFO chapsd[834]: Adding slot: 1
2024-04-26T16:01:10.774287Z INFO chapsd[834]: Opening database in: /var/lib/chaps
2024-04-26T16:01:10.789367Z INFO chapsd[834]: leveldb /var/lib/chaps/database dump:#012
/var/lib/chaps/database/LOG (184 bytes, 2024-04-26 14:31:30.000 UTC)#012
/var/lib/chaps/database/CURRENT (16 bytes, 2024-04-26 14:31:30.000 UTC)#012
/var/lib/chaps/database/LOG.old (184 bytes, 2024-04-26 13:59:02.000 UTC)#012
/var/lib/chaps/database/000005.ldb (393 bytes, 2024-03-26 12:57:11.000 UTC)#012
/var/lib/chaps/database/MANIFEST-000037 (92 bytes, 2024-04-26 14:31:30.000 UTC)#012
/var/lib/chaps/database/LOCK (0 bytes, 2024-03-26 12:25:52.000 UTC)#012
/var/lib/chaps/database/000038.log (0 bytes, 2024-04-26 14:31:30.000 UTC)
2024-04-26T16:01:10.831729Z INFO rollback_cleanup[844]: Failed to get enterprise rollback
space state: This space is not preparable
2024-04-26T16:01:10.864629Z INFO chapsd[834]: leveldb.stats:#012
Compactions#012Level Files Size(MB) Time(sec) Read(MB) Write(MB)#012-----
-----#012 0 1 0 0 0 0 #012
2024-04-26T16:01:10.867439Z INFO chapsd[834]: leveldb contains 5 keys.
2024-04-26T16:01:10.872198Z INFO chapsd[834]: Slot 0 ready for token at /var/lib/chaps
2024-04-26T16:01:10.889472Z INFO chapsd[834]: Created lock file:
/run/lock/power_override/chapsd_token_init_slot_0.lock
2024-04-26T16:01:10.893803Z INFO bootlockboxd[853]: BootLockboxd started
2024-04-26T16:01:10.927940Z INFO chapsd[834]: Root key is ready for token at
/var/lib/chaps
2024-04-26T16:01:10.928398Z INFO chapsd[834]: Deleted lock file:
/run/lock/power_override/chapsd_token_init_slot_0.lock
2024-04-26T16:01:10.947517Z NOTICE write-machine-info[906]: Fallback to WPSW_BOOT (-1),
which may be invalid
2024-04-26T16:01:10.990035Z INFO mojo_service_manager[720]: Receive connection from:
u:r:cros_shill:s0
2024-04-26T16:01:11.016352Z ERR shill[784]: ERROR shill: [object_proxy.cc(590)] Failed to
call method: org.chromium.PatchPanel.GetTrafficCounters: object_path=
/org/chromium.PatchPanel: org.freedesktop.DBus.Error.ServiceUnknown: The name
org.chromium.PatchPanel was not provided by any .service files
2024-04-26T16:01:11.016420Z ERR shill[784]: ERROR shill: [client.cc(379)] Failed to send
TrafficCountersRequest message to patchpanel service
2024-04-26T16:01:11.095238Z NOTICE chaps-restore[903]: PKCS #11 restore TPM tokens call
failed: (dbus, org.freedesktop.DBus.Error.ServiceUnknown, Error calling D-Bus method:
org.chromium.CryptohomePkcs11Interface.Pkcs11RestoreTpmTokens: The name
org.chromium.UserDataAuth was not provided by any .service files).
2024-04-26T16:01:11.123511Z INFO minijail0[928]: libminijail[928]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:11.206944Z INFO minijail0[959]: libminijail[959]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:11.244722Z WARNING attestationd[927]: Get: attested_device_id missing in
RO_VPD.
2024-04-26T16:01:11.244865Z INFO attestationd[927]: No ADID found.
2024-04-26T16:01:11.244961Z INFO attestationd[927]: Setting ADID to
fake_attested_device_id_for_simulator.
2024-04-26T16:01:11.245883Z INFO attestationd[927]: Attestation Daemon Started.
2024-04-26T16:01:11.266776Z INFO attestationd[927]: Attestation service started.
2024-04-26T16:01:11.289125Z INFO attestationd[927]: OnSignalConnected: Connected dbus
signal successfully.
2024-04-26T16:01:11.297603Z WARNING powerd[952]: libminijail[952]: SECURE_NOROOT not set,
not dropping bounding set

```

2024-04-26T16:01:11.314194Z INFO attestatond[927]: Loading attestation database.
2024-04-26T16:01:11.336830Z WARNING minijail0[973]: libminijail[973]: failed to create a ruleset: Function not implemented
2024-04-26T16:01:11.336869Z WARNING minijail0[973]: libminijail[973]: Landlock is not supported by the current kernel: Function not implemented
2024-04-26T16:01:11.338320Z WARNING minijail0[977]: libminijail[1]: failed to create a ruleset: Function not implemented
2024-04-26T16:01:11.338340Z WARNING minijail0[977]: libminijail[1]: Landlock is not supported by the current kernel: Function not implemented
2024-04-26T16:01:11.338355Z INFO minijail0[977]: libminijail[1]: Landlock support for LANDLOCK_ACCESS_FS_REFER: false
2024-04-26T16:01:11.340323Z INFO root[978]: fydeos-license-utils get disk /dev/nvme0n1 serial by lsblk
2024-04-26T16:01:11.352232Z NOTICE cros-machine-id-regen[979]: Regenerated /var/lib/dbus/machine-id (reason: network).
2024-04-26T16:01:11.356667Z INFO root[980]: fydeos-license-utils get fix id by disk serial
2024-04-26T16:01:11.381933Z WARNING attestatond[927]: Could not read hwid property.
2024-04-26T16:01:11.430511Z ERR cryptohomed[954]: quotactl failed for user 0: No such process (3)
2024-04-26T16:01:11.433224Z ERR cryptohomed[954]: Device is not mounted with quota feature enabled.
2024-04-26T16:01:11.532646Z INFO vtpmd[977]: OnSignalConnected: Connected dbus signal successfully.
2024-04-26T16:01:11.628686Z INFO cryptohomed[954]: Valid secure install attributes cache found.
2024-04-26T16:01:11.734515Z INFO mojo_service_manager[720]: Receive connection from: u:r:cros_powerd:s0
2024-04-26T16:01:11.808813Z INFO kernel: [31.081935] e1000 0000:02:01.0 eth0: (PCI:66MHz:32-bit) 00:0c:29:17:b2:95
2024-04-26T16:01:11.808856Z INFO kernel: [31.085175] e1000 0000:02:01.0 eth0: Intel(R) PRO/1000 Network Connection
2024-04-26T16:01:11.872990Z INFO iioservice[712]: INFO iioservice: [iio_sensor.cc(56)] (2) Request(): Received SensorService from Mojo Service Manager
2024-04-26T16:01:11.926231Z INFO kernel: [31.180623] e1000: eth0 NIC Link is Up 1000 Mbps Full Duplex, Flow Control: None
2024-04-26T16:01:11.946109Z INFO kernel: [31.217926] IPv6: ADDRCONF(NETDEV_CHANGE): eth0: link becomes ready
2024-04-26T16:01:11.963079Z INFO kernel: [31.238015] loop7: detected capacity change from 0 to 192888
2024-04-26T16:01:11.980099Z ERR session_manager[1034]: ERROR session_manager: [safe_fd.cc(701)] unlinkat failed: No such file or directory (2)
2024-04-26T16:01:11.980236Z ERR session_manager[1034]: ERROR session_manager: [safe_fd.cc(701)] unlinkat failed: No such file or directory (2)
2024-04-26T16:01:11.983768Z WARNING session_manager[1034]: WARNING session_manager: [chrome_setup.cc(240)] Could not find both paths: /usr/share/chromeos-assets/wallpaper/oem_large.jpg and /usr/share/chromeos-assets/wallpaper/oem_small.jpg
2024-04-26T16:01:11.983851Z WARNING session_manager[1034]: WARNING session_manager: [chrome_setup.cc(249)] Could not find both paths: /usr/share/chromeos-assets/wallpaper/oem_large.png and /usr/share/chromeos-assets/wallpaper/oem_small.png
2024-04-26T16:01:11.983890Z WARNING session_manager[1034]: WARNING session_manager: [chrome_setup.cc(240)] Could not find both paths: /usr/share/chromeos-assets/wallpaper/default_large.jpg and /usr/share/chromeos-assets/wallpaper/default_small.jpg
2024-04-26T16:01:11.995082Z ERR kernel: [31.271524] Filesystem uses "zstd" compression. This is not supported
2024-04-26T16:01:12.063883Z ERR shill[784]: ERROR shill: [object_proxy.cc(590)] Failed to call method: org.chromium.PatchPanel.GetTrafficCounters: object_path=/org/chromium/PatchPanel: org.freedesktop.DBus.Error.ServiceUnknown: The name org.chromium.PatchPanel was not provided by any .service files
2024-04-26T16:01:12.063959Z INFO session_manager[1034]: INFO session_manager: [session_manager_main.cc(234)] Mount namespace created at /run/namespaces/mnt_chrome
2024-04-26T16:01:12.063988Z ERR shill[784]: ERROR shill: [client.cc(379)] Failed to send TrafficCountersRequest message to patchpanel service
2024-04-26T16:01:12.077499Z INFO cups_launcher[1056]: Waiting for events on /run/cups/cups.sock
2024-04-26T16:01:12.085682Z ERR shill[784]: ERROR shill: [object_proxy.cc(590)] Failed to call method: org.chromium.PatchPanel.GetTrafficCounters: object_path=/org/chromium/PatchPanel: org.freedesktop.DBus.Error.ServiceUnknown: The name

```
org.chromium.PatchPanel was not provided by any .service files
2024-04-26T16:01:12.085832Z ERR shill[784]: ERROR shill: [client.cc(379)] Failed to send
TrafficCountersRequest message to patchpanel service
2024-04-26T16:01:12.089312Z INFO session_manager[1034]: INFO session_manager:
[session_manager_service.cc(183)] SessionManagerService starting
2024-04-26T16:01:12.103208Z INFO kernel: [ 31.381275] 8021q: 802.1Q VLAN Support v1.8
2024-04-26T16:01:12.103285Z INFO kernel: [ 31.383724] 8021q: adding VLAN 0 to HW filter
on device eth0
2024-04-26T16:01:12.104599Z INFO session_manager[1034]: INFO session_manager:
[dev_mode_unblock_broker.cc(68)] DevModeUnblockBroker
awaiting_unblock_init_state_determination: 1 awaiting_unblock_enrollment: 1
awaiting_unblock_carrier_lock: 0
2024-04-26T16:01:12.120134Z INFO session_manager[1034]: INFO session_manager:
[browser_job.cc(224)] Running browser /opt/google/chrome/chrome --enable-webgl-image-
chromium --enable-
features=Pepper3DImageChromium,UmaStorageDimensions,ArcAdbSideload,Crostini,CrostiniGp
uSupport,SmartDim --gpu-sandbox-failures-fatal=no --enable-logging --log-level=1 --use-
cras --enable-wayland-server --user-data-dir=/home/chronos --system-developer-mode --
disable-mojo-broker --ash-use-cros-mojo-service-manager --cros-healthd-uses-service-
manager --login-profile=user --aura-legacy-power-button --guest-wallpaper-
large=/usr/share/chromeos-assets/wallpaper/guest_large.jpg --guest-wallpaper-
small=/usr/share/chromeos-assets/wallpaper/guest_small.jpg --child-wallpaper-
large=/usr/share/chromeos-assets/wallpaper/child_large.jpg --child-wallpaper-
small=/usr/share/chromeos-assets/wallpaper/child_small.jpg --default-wallpaper-
large=/usr/share/chromeos-assets/wallpaper/default_large.png --default-wallpaper-
small=/usr/share/chromeos-assets/wallpaper/default_small.png --fyde-dynamic-default-
wallpaper --enable-consumer-kiosk --device-help-content-id=fydeos --ozone-nnpalm-
properties={} --arc-availability=officially-supported --enable-houdini --enable-houdini64
--enterprise-enrollment-initial-modulus=15 --enterprise-enrollment-modulus-limit=19 --
enable-crashpad --ml_service=enabled --ondevice_handwriting=use_rootfs --
ondevice_document_scanner=use_rootfs --disable-features=FederatedService --remote-
debugging-port=9229 --drm-virtual-connector-is-external --enable-zero-copy --disable-arc-
opt-in-verification --enable-hardware-overlays=single-fullscreen --login-manager --
feature-flags=["scheduler-configuration@2"] --first-exec-after-boot --enable-
features=Pepper3DImageChromium,UmaStorageDimensions,ArcAdbSideload,Crostini,CrostiniGp
uSupport,SmartDim --disable-features=FederatedService
2024-04-26T16:01:12.121642Z INFO session_manager[1034]: INFO session_manager:
[session_manager_service.cc(304)] Browser is 1061
2024-04-26T16:01:12.134367Z ERR cryptohomed[954]: Failed to get FWMP state: No owner
password
2024-04-26T16:01:12.138365Z ERR session_manager[1034]: ERROR session_manager:
[dev_mode_unblock_broker.cc(193)] Failed to get firmware management parameters:26
2024-04-26T16:01:12.138436Z INFO session_manager[1034]: INFO session_manager:
[dev_mode_unblock_broker.cc(140)] block_devmode_fwmp 0
2024-04-26T16:01:12.138712Z ERR session_manager[1034]: ERROR session_manager:
[dev_mode_unblock_broker.cc(155)] Failed to read block_devmode flag!
2024-04-26T16:01:12.138737Z INFO session_manager[1034]: INFO session_manager:
[dev_mode_unblock_broker.cc(157)] block_devmode_system -1
2024-04-26T16:01:12.293179Z ERR shill[784]: ERROR shill: [object_proxy.cc(590)] Failed to
call method: org.chromium.PatchPanel.GetTrafficCounters: object_path=
/org/chromium/PatchPanel: org.freedesktop.DBus.Error.ServiceUnknown: The name
org.chromium.PatchPanel was not provided by any .service files
2024-04-26T16:01:12.293386Z ERR shill[784]: ERROR shill: [client.cc(379)] Failed to send
TrafficCountersRequest message to patchpanel service
2024-04-26T16:01:12.486742Z ERR shill[784]: ERROR shill: [object_proxy.cc(590)] Failed to
call method: org.chromium.PatchPanel.GetTrafficCounters: object_path=
/org/chromium/PatchPanel: org.freedesktop.DBus.Error.ServiceUnknown: The name
org.chromium.PatchPanel was not provided by any .service files
2024-04-26T16:01:12.486769Z ERR shill[784]: ERROR shill: [client.cc(379)] Failed to send
TrafficCountersRequest message to patchpanel service
2024-04-26T16:01:13.880148Z INFO mojo_service_manager[720]: Receive connection from:
u:r:cros_browser:s0
2024-04-26T16:01:14.233653Z INFO dbus-daemon[569]: [system] Activating service
name='org.chromium.Rgbkbd' requested by ':1.41' (uid=1000 pid=1061
comm="/opt/google/chrome/chrome --enable-webgl-image-chr" label="u:r:cros_browser:s0")
(using servicehelper)
2024-04-26T16:01:14.294904Z INFO minijail0[1152]: libminijail[1152]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:14.347710Z INFO rgbkbd[1153]: Starting Chrome OS RGB Keyboard Daemon
```

```
2024-04-26T16:01:14.355801Z INFO dbus-daemon[569]: [system] Successfully activated
service 'org.chromium.Rgbkbd'
2024-04-26T16:01:14.356769Z INFO rgbkbd[1153]: Checking RgbKeyboardCapabilities.
2024-04-26T16:01:14.356812Z INFO rgbkbd[1153]: Deducing Communication type
2024-04-26T16:01:14.356849Z ERR rgbkbd[1153]: Failed to open FD for EC with errno=2
2024-04-26T16:01:14.367378Z WARNING rgbkbd[1153]: Failed to initialize USB Endpoint after
retry #2
2024-04-26T16:01:14.367423Z INFO rgbkbd[1153]: Failed to initialize EC USB Endpoint.
2024-04-26T16:01:14.367823Z ERR rgbkbd[1153]: Failed to deduce communication type for
internal RGB Keyboard
2024-04-26T16:01:14.367890Z INFO rgbkbd[1153]: Device does not support an internal RGB
keyboard
2024-04-26T16:01:14.371050Z INFO rgbkbd[1153]: Chrome OS RGB Keyboard Daemon exited
successfully
2024-04-26T16:01:14.572922Z INFO session_manager[1034]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting ash-initialized Upstart signal
2024-04-26T16:01:15.222322Z INFO iioservice[712]: INFO iioservice: [iio_sensor.cc(56)]
(2) Request(): Received SensorService from Mojo Service Manager
2024-04-26T16:01:15.229876Z INFO btmanagerd[713]: Set floss devcoredump to false
2024-04-26T16:01:15.270712Z INFO bluetoothd[750]: Bluetooth devcoredump state set to 0
2024-04-26T16:01:15.271352Z INFO bluetoothd[750]: LL Privacy status not changed: 0
2024-04-26T16:01:15.314186Z INFO minijail0[1225]: libminijail[1225]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:15.318779Z WARNING minijail0[1226]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:01:15.318807Z WARNING minijail0[1225]: libminijail[1225]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:15.318808Z WARNING minijail0[1226]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:15.318825Z WARNING minijail0[1225]: libminijail[1225]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:15.318825Z INFO minijail0[1226]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:01:15.800835Z INFO session_manager[1034]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting login-prompt-visible Upstart signal
2024-04-26T16:01:15.913933Z INFO kernel: [ 35.189245] EXT4-fs (nvme0n1p8): re-mounted.
Opts: . Quota mode: none.
2024-04-26T16:01:16.114608Z ERR cryptohomed[954]: Failed to call method:
org.chromium.ChromeFeaturesServiceInterface.IsFeatureEnabled: object_path=
/org/chromium/ChromeFeaturesService: org.freedesktop.DBus.Error.InvalidArgs: Unexpected
feature name.
2024-04-26T16:01:16.115411Z WARNING cryptohomed[954]: No valid keysets on disk for
521ac76c473ca5ff9c03ccc71d8ad8646690ad65
2024-04-26T16:01:16.229610Z INFO minijail0[1273]: libminijail[1273]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:16.275357Z INFO kernel: [ 35.550538] EXT4-fs (nvme0n1p8): re-mounted.
Opts: . Quota mode: none.
2024-04-26T16:01:16.326445Z INFO minijail0[1275]: libminijail[1275]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:16.435220Z WARNING minijail0[1282]: libminijail[1282]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:16.435547Z WARNING minijail0[1282]: libminijail[1282]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:16.441434Z WARNING minijail0[1339]: libminijail[1339]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:16.441854Z WARNING minijail0[1339]: libminijail[1339]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:16.442035Z INFO minijail0[1339]: libminijail[1339]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:01:16.544810Z INFO minijail0[1310]: libminijail[1310]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:16.545463Z WARNING minijail0[1310]: libminijail[1310]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:16.545593Z WARNING minijail0[1310]: libminijail[1310]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:16.546312Z WARNING minijail0[1351]: libminijail[1351]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:16.546508Z WARNING minijail0[1351]: libminijail[1351]: Landlock is not
supported by the current kernel: Function not implemented
```

```
2024-04-26T16:01:16.546642Z INFO minijail0[1351]: libminijail[1351]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:01:16.608380Z NOTICE cros-disks[1358]: Loading FUSE module
2024-04-26T16:01:16.636622Z WARNING secanomalyd[1330]: Landlock is not supported by the
kernel.
2024-04-26T16:01:16.643703Z INFO minijail0[1360]: libminijail[1360]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:16.646090Z WARNING minijail0[1360]: libminijail[1360]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:16.650648Z WARNING minijail0[1360]: libminijail[1360]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:16.652110Z INFO avahi-daemon[1351]: Found user 'avahi' (UID 238) and
group 'avahi' (GID 238).
2024-04-26T16:01:16.663191Z INFO avahi-daemon[1351]: Successfully dropped root
privileges.
2024-04-26T16:01:16.674457Z WARNING minijail0[1364]: libminijail[1364]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:16.674484Z WARNING minijail0[1364]: libminijail[1364]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:16.674498Z INFO minijail0[1364]: libminijail[1364]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:01:16.697037Z WARNING minijail0[1356]: libminijail[1356]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:16.697743Z WARNING minijail0[1356]: libminijail[1356]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:16.699990Z WARNING minijail0[1365]: libminijail[1365]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:16.701105Z WARNING minijail0[1365]: libminijail[1365]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:16.701281Z INFO minijail0[1365]: libminijail[1365]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:01:16.785624Z INFO avahi-daemon[1351]: avahi-daemon 0.8 starting up.
2024-04-26T16:01:16.819861Z INFO sshd[1343]: Server listening on 0.0.0.0 port 22.
2024-04-26T16:01:16.822200Z INFO sshd[1343]: Server listening on :: port 22.
2024-04-26T16:01:16.913393Z INFO avahi-daemon[1351]: Successfully called chroot().
2024-04-26T16:01:16.913616Z INFO avahi-daemon[1351]: Successfully dropped remaining
capabilities.
2024-04-26T16:01:16.916893Z ERR avahi-daemon[1368]: chroot.c: open() failed: No such file
or directory
2024-04-26T16:01:16.920106Z WARNING avahi-daemon[1351]: Failed to open /etc/resolv.conf:
Invalid argument
2024-04-26T16:01:16.925662Z INFO avahi-daemon[1351]: No service file found in
/etc/avahi/services.
2024-04-26T16:01:16.968492Z WARNING kernel: [ 36.246366] audit_log_start: 771 callbacks
suppressed
2024-04-26T16:01:16.968555Z WARNING kernel: [ 36.246374] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:01:16.968564Z WARNING kernel: [ 36.248754] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:01:16.977636Z WARNING kernel: [ 36.254836] audit: audit_lost=1
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:01:16.988453Z INFO avahi-daemon[1351]: Joining mDNS multicast group on
interface eth0.IPv4 with address 192.168.9.128.
2024-04-26T16:01:17.000015Z ERR kernel: [ 36.278014] audit: backlog limit exceeded
2024-04-26T16:01:17.006067Z WARNING kernel: [ 36.283127] audit: audit_lost=2
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:01:17.020388Z WARNING contrack-tools[1373]: scheduler configuration
failed: Operation not permitted. Likely a bug in contrackd, please report it. Continuing
with system default scheduler.
2024-04-26T16:01:17.020889Z NOTICE contrack-tools[1373]: configuring helper `mdns' with
queuenum=6 and queuelen=10240
2024-04-26T16:01:17.021104Z NOTICE contrack-tools[1373]: policy name=mdns
expect_timeout=30 expect_max=8
2024-04-26T16:01:17.021304Z NOTICE contrack-tools[1373]: helper `mdns' configured
successfully
2024-04-26T16:01:17.021580Z NOTICE contrack-tools[1373]: configuring helper `ssdp' with
queuenum=5 and queuelen=10240
2024-04-26T16:01:17.021788Z NOTICE contrack-tools[1373]: policy name=ssdp
expect_timeout=300 expect_max=8
```

```
2024-04-26T16:01:17.022041Z NOTICE contrack-tools[1373]: helper `ssdp' configured
successfully
2024-04-26T16:01:17.022228Z NOTICE contrack-tools[1373]: configuring helper `ssdp' with
queuenum=5 and queuelen=10240
2024-04-26T16:01:17.022390Z NOTICE contrack-tools[1373]: policy name=ssdp
expect_timeout=300 expect_max=8
2024-04-26T16:01:17.022592Z NOTICE contrack-tools[1373]: helper `ssdp' configured
successfully
2024-04-26T16:01:17.022750Z NOTICE contrack-tools[1373]: initialization completed
2024-04-26T16:01:17.022913Z NOTICE contrack-tools[1373]: -- starting in console mode --
2024-04-26T16:01:17.023497Z ERR contrack-tools[1373]: failed to process message
2024-04-26T16:01:17.026836Z ERR kernel: [ 36.305100] audit: backlog limit exceeded
2024-04-26T16:01:17.040708Z INFO avahi-daemon[1351]: New relevant interface eth0.IPv4 for
mDNS.
2024-04-26T16:01:17.041266Z INFO avahi-daemon[1351]: Joining mDNS multicast group on
interface lo.IPv4 with address 127.0.0.1.
2024-04-26T16:01:17.041369Z INFO avahi-daemon[1351]: New relevant interface lo.IPv4 for
mDNS.
2024-04-26T16:01:17.042263Z INFO avahi-daemon[1351]: Network interface enumeration
completed.
2024-04-26T16:01:17.042431Z INFO avahi-daemon[1351]: Registering new address record for
192.168.9.128 on eth0.IPv4.
2024-04-26T16:01:17.042829Z INFO avahi-daemon[1351]: Registering new address record for
127.0.0.1 on lo.IPv4.
2024-04-26T16:01:17.191123Z INFO kernel: [ 36.467168] fuse: init (API version 7.34)
2024-04-26T16:01:17.400973Z INFO minijail0[1315]: libminijail[1315]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:17.403505Z INFO minijail0[1422]: libminijail[1422]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:17.639191Z INFO mojo_service_manager[720]: Receive connection from:
u:r:cros_healthd:s0
2024-04-26T16:01:17.889906Z INFO avahi-daemon[1351]: Server startup complete. Host name
is 09a014580c71e9f69fb5da92662bcfc7.local. Local service cookie is 149483886.
2024-04-26T16:01:17.900539Z INFO cros_healthd[1335]: CrosHealthdDiagnosticsService is
ready.
2024-04-26T16:01:17.934575Z INFO iioservice[712]: INFO iioservice: [iio_sensor.cc(56)]
(2) Request(): Received SensorService from Mojo Service Manager
2024-04-26T16:01:18.394792Z INFO root[1501]: fydeos-license-utils get disk /dev/nvme0n1
serial by lsblk
2024-04-26T16:01:18.417854Z INFO root[1511]: fydeos-license-utils get fix id by disk
serial
2024-04-26T16:01:18.537170Z INFO cras_server[1439]: cras_feature_tier initialized with
board="FydeOS" cpu="Intel(R)_Core(TM)_m3-8100Y_CPU_@_1.10GHz"
2024-04-26T16:01:18.622703Z INFO dlcservice[1365]: INFO dlcservice: [dlc_service.cc(92)]
Update Engine service available=1
2024-04-26T16:01:18.633785Z INFO dlcservice[1365]: INFO dlcservice: [dlc_service.cc(388)]
Got update_engine status: IDLE
2024-04-26T16:01:21.813138Z WARNING kernel: [ 41.076386] -----[ cut here ]-----
-----
2024-04-26T16:01:21.813174Z WARNING kernel: [ 41.078375] refcount_t: addition on 0;
use-after-free.
2024-04-26T16:01:21.813183Z WARNING kernel: [ 41.081316] WARNING: CPU: 1 PID: 1129 at
lib/refcount.c:25 refcount_warn_saturate+0x9a/0x104
2024-04-26T16:01:21.813188Z WARNING kernel: [ 41.085617] Modules linked in:
ip6table_nat fuse 8021q bluetooth e1000 cfg80211 ecdh_generic ecc lzo_rle lzo_compress
zram joydev
2024-04-26T16:01:21.813192Z WARNING kernel: [ 41.091345] CPU: 1 PID: 1129 Comm: chrome
Not tainted 5.15.108-18907-gba143be42d3a-dirty #1
2024-04-26T16:01:21.924924Z WARNING kernel: [ 41.095512] Hardware name: VMware, Inc.
VMware7,1/440BX Desktop Reference Platform, BIOS VMW71.00V.21805430.B64.2305221826
05/22/2023
2024-04-26T16:01:21.924962Z WARNING kernel: [ 41.107791] RIP:
0010:refcount_warn_saturate+0x9a/0x104
2024-04-26T16:01:21.924968Z WARNING kernel: [ 41.113970] Code: c7 44 63 90 88 e8 bd 4f
ea ff 0f 0b eb 69 80 3d e6 f0 2f 01 00 75 60 c6 05 dd f0 2f 01 01 48 c7 c7 29 a1 86 88 e8
9d 4f ea ff <0f> 0b eb 49 80 3d c7 f0 2f 01 00 75 40 c6 05 be f0 2f 01 01 48 c7
2024-04-26T16:01:21.924972Z WARNING kernel: [ 41.128062] RSP: 0018:ffffb722c09f7a60
EFLAGS: 00010246
2024-04-26T16:01:21.924976Z WARNING kernel: [ 41.130793] RAX: 87f49b3f88625f00 RBX:
```

```

0000000000000001 RCX: ffffffff88a5daa8
2024-04-26T16:01:21.924980Z WARNING kernel: [ 41.138024] RDX: fffffb722c09f7838 RSI:
0000000000000000 RDI: 0000000000000001
2024-04-26T16:01:21.924985Z WARNING kernel: [ 41.142550] RBP: fffffb722c09f7a60 R08:
0000000000000000 R09: fffffb722c09f7830
2024-04-26T16:01:21.924989Z WARNING kernel: [ 41.153033] R10: 00000000ffffdfff R11:
ffffffff88a8dd50 R12: ffff90d8c5a6f640
2024-04-26T16:01:21.924993Z WARNING kernel: [ 41.164518] R13: ffff90d8ec7d4c00 R14:
0000000000000000 R15: fffffb722c09f7ac4
2024-04-26T16:01:21.924996Z WARNING kernel: [ 41.170555] FS: 00007d6bf3c0c040(0000)
GS:ffff90d983440000(0000) knlGS:0000000000000000
2024-04-26T16:01:21.924999Z WARNING kernel: [ 41.174486] CS: 0010 DS: 0000 ES: 0000
CR0: 0000000080050033
2024-04-26T16:01:21.925002Z WARNING kernel: [ 41.177289] CR2: 00001f840233d400 CR3:
0000000112a98006 CR4: 00000000003706e0
2024-04-26T16:01:21.925051Z WARNING kernel: [ 41.180907] Call Trace:
2024-04-26T16:01:21.925055Z WARNING kernel: [ 41.182113] <TASK>
2024-04-26T16:01:21.925059Z WARNING kernel: [ 41.183048] objects_lookup+0x92/0xc6
2024-04-26T16:01:21.925063Z WARNING kernel: [ 41.184851]
drm_gem_object_lookup+0x3c/0x5e
2024-04-26T16:01:21.925066Z WARNING kernel: [ 41.188096]
vmw_user_bo_noref_lookup+0x16/0xb4
2024-04-26T16:01:21.925071Z WARNING kernel: [ 41.198379]
vmw_translate_mob_ptr+0x34/0xfc
2024-04-26T16:01:21.925075Z WARNING kernel: [ 41.202665]
vmw_cmd_res_switch_backup+0x4e/0x96
2024-04-26T16:01:21.936818Z WARNING kernel: [ 41.208449]
vmw_cmd_dx_bind_shader+0x110/0x143
2024-04-26T16:01:21.936933Z WARNING kernel: [ 41.215115]
vmw_execbuf_process+0x55d/0xf8c
2024-04-26T16:01:21.936954Z WARNING kernel: [ 41.217329] ?
avc_has_extended_perms+0x297/0x4c8
2024-04-26T16:01:21.941392Z WARNING kernel: [ 41.219823] vmw_execbuf_ioctl+0x67/0x11d
2024-04-26T16:01:21.941440Z WARNING kernel: [ 41.221939] ?
vmw_execbuf_release_pinned_bo+0x3e/0x3e
2024-04-26T16:01:21.945986Z WARNING kernel: [ 41.224466] drm_ioctl_kernel+0xd9/0x14c
2024-04-26T16:01:21.946055Z WARNING kernel: [ 41.226606] drm_ioctl+0x23c/0x3a4
2024-04-26T16:01:21.949517Z WARNING kernel: [ 41.228016] ?
vmw_execbuf_release_pinned_bo+0x3e/0x3e
2024-04-26T16:01:21.952802Z WARNING kernel: [ 41.230067] __x64_sys_ioctl+0x7b/0xc8
2024-04-26T16:01:21.952819Z WARNING kernel: [ 41.231723] do_syscall_64+0x58/0xa5
2024-04-26T16:01:21.956420Z WARNING kernel: [ 41.233392]
entry_SYSCALL_64_after_hwframe+0x5c/0xc6
2024-04-26T16:01:21.956436Z WARNING kernel: [ 41.235530] RIP: 0033:0x7d6bf4412649
2024-04-26T16:01:21.956439Z WARNING kernel: [ 41.236966] Code: 04 25 28 00 00 00 48 89
45 c8 31 c0 48 8d 45 10 c7 45 b0 10 00 00 48 89 45 b8 48 8d 45 d0 48 89 45 c0 b8 10 00
00 00 0f 05 <41> 89 c0 3d 00 f0 ff ff 77 1d 48 8b 45 c8 64 48 2b 04 25 28 00 00
2024-04-26T16:01:21.967084Z WARNING kernel: [ 41.244268] RSP: 002b:00007ffd32b3aab0
EFLAGS: 00000246 ORIG_RAX: 0000000000000010
2024-04-26T16:01:21.967185Z WARNING kernel: [ 41.247238] RAX: ffffffffffffffffda RBX:
0000000000000000 RCX: 00007d6bf4412649
2024-04-26T16:01:21.985478Z WARNING kernel: [ 41.252714] RDX: 00007ffd32b3ab68 RSI:
000000004028644c RDI: 000000000000000d
2024-04-26T16:01:21.985510Z WARNING kernel: [ 41.255852] RBP: 00007ffd32b3ab00 R08:
00000000000001018 R09: 00007ffd32b3ac18
2024-04-26T16:01:21.985516Z WARNING kernel: [ 41.259462] R10: 0000000000000003 R11:
0000000000000246 R12: 000000000000000d
2024-04-26T16:01:21.985520Z WARNING kernel: [ 41.262636] R13: 00007ffd32b3ac68 R14:
000000004028644c R15: 00007ffd32b3ab68
2024-04-26T16:01:22.006040Z WARNING kernel: [ 41.275091] </TASK>
2024-04-26T16:01:22.011793Z WARNING kernel: [ 41.286788] ---[ end trace
50841adad66cebf1 ]---
2024-04-26T16:01:22.040538Z WARNING kernel: [ 41.312980] -----[ cut here ]-----
-----
2024-04-26T16:01:22.040631Z WARNING kernel: [ 41.317632] refcount_t: underflow; use-
after-free.
2024-04-26T16:01:22.070846Z WARNING kernel: [ 41.321461] WARNING: CPU: 1 PID: 1129 at
lib/refcount.c:28 refcount_warn_saturate+0xba/0x104
2024-04-26T16:01:22.070898Z WARNING kernel: [ 41.339899] Modules linked in:

```



```

xt_MASQUERADE ip6table_nat fuse 8021q bluetooth e1000 cfg80211 ecdh_generic ecc lzo_rle
lzo_compress zram joydev
2024-04-26T16:01:22.085079Z WARNING kernel: [ 41.355080] CPU: 1 PID: 1129 Comm: chrome
Tainted: G          W          5.15.108-18907-gba143be42d3a-dirty #1
2024-04-26T16:01:22.118526Z WARNING kernel: [ 41.378937] Hardware name: VMware, Inc.
VMware7,1/440BX Desktop Reference Platform, BIOS VMW71.00V.21805430.B64.2305221826
05/22/2023
2024-04-26T16:01:22.118600Z WARNING kernel: [ 41.397423] RIP:
0010:refcount_warn_saturate+0xba/0x104
2024-04-26T16:01:22.132695Z WARNING kernel: [ 41.400614] Code: c7 29 a1 86 88 e8 9d 4f
ea ff 0f 0b eb 49 80 3d c7 f0 2f 01 00 75 40 c6 05 be f0 2f 01 01 48 c7 c7 6c 63 90 88 e8
7d 4f ea ff <0f> 0b eb 29 80 3d a4 f0 2f 01 00 75 20 c6 05 9b f0 2f 01 01 48 c7
2024-04-26T16:01:22.156089Z WARNING kernel: [ 41.436564] RSP: 0018:ffffb722c09f7ad8
EFLAGS: 00010246
2024-04-26T16:01:22.163922Z WARNING kernel: [ 41.440329] RAX: 87f49b3f88625f00 RBX:
ffff90d8ec7d4c00 RCX: ffffffff88a5daa8
2024-04-26T16:01:22.163975Z WARNING kernel: [ 41.444457] RDX: fffffb722c09f78b8 RSI:
0000000000000000 RDI: 0000000000000001
2024-04-26T16:01:22.233944Z WARNING kernel: [ 41.511340] RBP: fffffb722c09f7ad8 R08:
0000000000000000 R09: fffffb722c09f78b0
2024-04-26T16:01:22.244817Z WARNING kernel: [ 41.521268] R10: 00000000ffffdfff R11:
ffffffff88a8dd50 R12: ffff90d8c33009d8
2024-04-26T16:01:22.245079Z WARNING kernel: [ 41.524220] R13: ffff90d8c08a2000 R14:
ffff90d8ec7d4c00 R15: 0000000000000002
2024-04-26T16:01:22.261102Z WARNING kernel: [ 41.536453] FS: 00007d6bf3c0c040(0000)
GS:ffff90d983400000(0000) knlGS:0000000000000000
2024-04-26T16:01:22.287741Z WARNING kernel: [ 41.559747] CS: 0010 DS: 0000 ES: 0000
CR0: 0000000080050033
2024-04-26T16:01:22.287795Z WARNING kernel: [ 41.566869] CR2: 00002eb803921000 CR3:
00000000112a98002 CR4: 00000000003706f0
2024-04-26T16:01:22.293898Z WARNING kernel: [ 41.571708] Call Trace:
2024-04-26T16:01:22.293953Z WARNING kernel: [ 41.573254] <TASK>
2024-04-26T16:01:22.322098Z WARNING kernel: [ 41.588632]
vmw_user_bo_noref_lookup+0x7b/0xb4
2024-04-26T16:01:22.322155Z WARNING kernel: [ 41.590951]
vmw_translate_mob_ptr+0x34/0xfc
2024-04-26T16:01:22.322162Z WARNING kernel: [ 41.593031]
vmw_cmd_res_switch_backup+0x4e/0x96
2024-04-26T16:01:22.376804Z WARNING kernel: [ 41.655124]
vmw_cmd_dx_bind_shader+0x110/0x143
2024-04-26T16:01:22.387757Z WARNING kernel: [ 41.663859]
vmw_execbuf_process+0x55d/0xf8c
2024-04-26T16:01:22.387788Z WARNING kernel: [ 41.665951] ?
avc_has_extended_perms+0x297/0x4c8
2024-04-26T16:01:22.390124Z INFO dbus-daemon[569]: [system] Activating service
name='org.chromium.MachineLearning' requested by ':1.41' (uid=1000 pid=1061
comm="/opt/google/chrome/chrome --enable-webgl-image-chr" label="u:r:cros_browser:s0")
(using servicehelper)
2024-04-26T16:01:22.406152Z WARNING kernel: [ 41.684617] vmw_execbuf_ioctl+0x67/0x11d
2024-04-26T16:01:22.406227Z WARNING kernel: [ 41.686690] ?
vmw_execbuf_release_pinned_bo+0x3e/0x3e
2024-04-26T16:01:22.412862Z WARNING kernel: [ 41.689239] drm_ioctl_kernel+0xd9/0x14c
2024-04-26T16:01:22.462716Z WARNING kernel: [ 41.735467] drm_ioctl+0x23c/0x3a4
2024-04-26T16:01:22.462791Z WARNING kernel: [ 41.737226] ?
vmw_execbuf_release_pinned_bo+0x3e/0x3e
2024-04-26T16:01:22.462796Z WARNING kernel: [ 41.739612] __x64_sys_ioctl+0x7b/0xc8
2024-04-26T16:01:22.462798Z WARNING kernel: [ 41.741313] do_syscall_64+0x58/0xa5
2024-04-26T16:01:22.462802Z WARNING kernel: [ 41.742925]
entry_SYSCALL_64_after_hwframe+0x5c/0xc6
2024-04-26T16:01:22.483485Z INFO kernel: [ 41.753950] loop7: detected capacity change
from 0 to 12728
2024-04-26T16:01:22.497828Z WARNING kernel: [ 41.775645] RIP: 0033:0x7d6bf4412649
2024-04-26T16:01:22.510279Z WARNING kernel: [ 41.780097] Code: 04 25 28 00 00 00 48 89
45 c8 31 c0 48 8d 45 10 c7 45 b0 10 00 00 00 48 89 45 b8 48 8d 45 d0 48 89 45 c0 b8 10 00
00 00 0f 05 <41> 89 c0 3d 00 f0 ff ff 77 1d 48 8b 45 c8 64 48 2b 04 25 28 00 00
2024-04-26T16:01:22.552619Z WARNING kernel: [ 41.828354] RSP: 002b:00007ffd32b3aab0
EFLAGS: 00000246 ORIG_RAX: 0000000000000010
2024-04-26T16:01:22.594951Z WARNING kernel: [ 41.869772] RAX: ffffffffffffffffda RBX:
0000000000000000 RCX: 00007d6bf4412649

```

```

2024-04-26T16:01:22.595037Z WARNING kernel: [ 41.873683] RDX: 00007ffd32b3ab68 RSI:
000000004028644c RDI: 000000000000000d
2024-04-26T16:01:22.630215Z WARNING kernel: [ 41.898270] RBP: 00007ffd32b3ab00 R08:
0000000000001018 R09: 00007ffd32b3ac18
2024-04-26T16:01:22.647952Z WARNING kernel: [ 41.924707] R10: 0000000000000003 R11:
0000000000000246 R12: 000000000000000d
2024-04-26T16:01:22.670796Z WARNING kernel: [ 41.928747] R13: 00007ffd32b3ac68 R14:
000000004028644c R15: 00007ffd32b3ab68
2024-04-26T16:01:22.670903Z WARNING kernel: [ 41.947644] </TASK>
2024-04-26T16:01:22.670913Z WARNING kernel: [ 41.949985] ---[ end trace
50841adad66cebf2 ]---
2024-04-26T16:01:22.677129Z WARNING kernel: [ 41.955647] -----[ cut here ]-----
-----
2024-04-26T16:01:22.677151Z WARNING kernel: [ 41.957666] refcount_t: saturated; leaking
memory.
2024-04-26T16:01:22.684514Z WARNING kernel: [ 41.959907] WARNING: CPU: 0 PID: 1129 at
lib/refcount.c:22 refcount_warn_saturate+0x7a/0x104
2024-04-26T16:01:22.684536Z WARNING kernel: [ 41.963532] Modules linked in:
xt_MASQUERADE ip6table_nat fuse 8021q bluetooth e1000 cfg80211 ecdh_generic ecc lzo_rle
lzo_compress zram joydev
2024-04-26T16:01:22.693304Z WARNING kernel: [ 41.969193] CPU: 0 PID: 1129 Comm: chrome
Tainted: G W 5.15.108-18907-gba143be42d3a-dirty #1
2024-04-26T16:01:22.693356Z WARNING kernel: [ 41.973842] Hardware name: VMware, Inc.
VMware7,1/440BX Desktop Reference Platform, BIOS VMW71.00V.21805430.B64.2305221826
05/22/2023
2024-04-26T16:01:22.921591Z WARNING kernel: [ 41.979535] RIP:
0010:refcount_warn_saturate+0x7a/0x104
2024-04-26T16:01:22.921676Z WARNING kernel: [ 41.982235] Code: 6d 83 fe 01 0f 85 84 00
00 00 80 3d 09 f1 2f 01 00 0f 85 80 00 00 00 c6 05 fc f0 2f 01 01 48 c7 c7 44 63 90 88 e8
bd 4f ea ff <0f> 0b eb 69 80 3d e6 f0 2f 01 00 75 60 c6 05 dd f0 2f 01 01 48 c7
2024-04-26T16:01:22.921684Z WARNING kernel: [ 42.118304] RSP: 0018:ffffb722c09f7a60
EFLAGS: 00010246
2024-04-26T16:01:22.921688Z WARNING kernel: [ 42.151964] RAX: 87f49b3f88625f00 RBX:
0000000000000001 RCX: 0000000000000000
2024-04-26T16:01:22.921691Z WARNING kernel: [ 42.198728] RDX: ffff90d9834271f8 RSI:
ffff90d98341b4a0 RDI: ffff90d98341b4a0
2024-04-26T16:01:22.921712Z WARNING kernel: [ 42.202232] RBP: fffffb722c09f7a60 R08:
0000000000000000 R09: fffffb722c09f7830
2024-04-26T16:01:22.938243Z WARNING kernel: [ 42.215354] R10: 00000000ffffdfff R11:
ffffffff88a8dd50 R12: ffff90d8c5a6f640
2024-04-26T16:01:22.938265Z WARNING kernel: [ 42.218370] R13: ffff90d8ec7d4c00 R14:
0000000000000000 R15: fffffb722c09f7ac4
2024-04-26T16:01:22.997330Z WARNING kernel: [ 42.256900] FS: 00007d6bf3c0c040(0000)
GS:ffff90d983400000(0000) knlGS:0000000000000000
2024-04-26T16:01:22.997420Z WARNING kernel: [ 42.263426] CS: 0010 DS: 0000 ES: 0000
CR0: 0000000080050033
2024-04-26T16:01:22.997426Z WARNING kernel: [ 42.269144] CR2: 00007fff4e6725e8 CR3:
00000000112a98002 CR4: 00000000003706f0
2024-04-26T16:01:23.034913Z WARNING kernel: [ 42.282394] Call Trace:
2024-04-26T16:01:23.034935Z WARNING kernel: [ 42.286141] <TASK>
2024-04-26T16:01:23.034941Z WARNING kernel: [ 42.294481] objects_lookup+0x92/0xc6
2024-04-26T16:01:23.034945Z WARNING kernel: [ 42.296416]
drm_gem_object_lookup+0x3c/0x5e
2024-04-26T16:01:23.046658Z WARNING kernel: [ 42.319378]
vmw_user_bo_noref_lookup+0x16/0xb4
2024-04-26T16:01:23.169625Z WARNING kernel: [ 42.327218]
vmw_translate_mob_ptr+0x34/0xfc
2024-04-26T16:01:23.169733Z WARNING kernel: [ 42.329633]
vmw_cmd_res_switch_backup+0x4e/0x96
2024-04-26T16:01:23.169748Z WARNING kernel: [ 42.354655]
vmw_cmd_dx_bind_shader+0x110/0x143
2024-04-26T16:01:23.169754Z WARNING kernel: [ 42.358509]
vmw_execbuf_process+0x55d/0xf8c
2024-04-26T16:01:23.169758Z WARNING kernel: [ 42.362365] ?
avc_has_extended_perms+0x297/0x4c8
2024-04-26T16:01:23.169761Z WARNING kernel: [ 42.365602] vmw_execbuf_ioctl+0x67/0x11d
2024-04-26T16:01:23.169813Z WARNING kernel: [ 42.368204] ?
vmw_execbuf_release_pinned_bo+0x3e/0x3e
2024-04-26T16:01:23.169821Z WARNING kernel: [ 42.374210] drm_ioctl_kernel+0xd9/0x14c

```

```
2024-04-26T16:01:23.169824Z WARNING kernel: [ 42.379613] drm_ioctl+0x23c/0x3a4
2024-04-26T16:01:23.169835Z WARNING kernel: [ 42.381579] ?
vmw_execbuf_release_pinned_bo+0x3e/0x3e
2024-04-26T16:01:23.169845Z WARNING kernel: [ 42.385429] __x64_sys_ioctl+0x7b/0xc8
2024-04-26T16:01:23.169849Z WARNING kernel: [ 42.389783] do_syscall_64+0x58/0xa5
2024-04-26T16:01:23.169852Z WARNING kernel: [ 42.397597]
entry_SYSCALL_64_after_hwframe+0x5c/0xc6
2024-04-26T16:01:23.169859Z WARNING kernel: [ 42.399994] RIP: 0033:0x7d6bf4412649
2024-04-26T16:01:23.169870Z WARNING kernel: [ 42.415064] Code: 04 25 28 00 00 00 48 89
45 c8 31 c0 48 8d 45 10 c7 45 b0 10 00 00 00 48 89 45 b8 48 8d 45 d0 48 89 45 c0 b8 10 00
00 00 0f 05 <41> 89 c0 3d 00 f0 ff ff 77 1d 48 8b 45 c8 64 48 2b 04 25 28 00 00
2024-04-26T16:01:23.204882Z WARNING kernel: [ 42.467540] RSP: 002b:00007ffd32b3aab0
EFLAGS: 00000246 ORIG_RAX: 0000000000000010
2024-04-26T16:01:23.204979Z WARNING kernel: [ 42.485407] RAX: ffffffffda RBX:
0000000000000000 RCX: 00007d6bf4412649
2024-04-26T16:01:23.246178Z WARNING kernel: [ 42.502308] RDX: 00007ffd32b3ab68 RSI:
000000004028644c RDI: 000000000000000d
2024-04-26T16:01:23.246593Z WARNING kernel: [ 42.519310] RBP: 00007ffd32b3ab00 R08:
00000000000001018 R09: 00007ffd32b3ac18
2024-04-26T16:01:23.279951Z WARNING kernel: [ 42.530753] R10: 0000000000000003 R11:
0000000000000246 R12: 000000000000000d
2024-04-26T16:01:23.279991Z WARNING kernel: [ 42.549428] R13: 00007ffd32b3ac68 R14:
000000004028644c R15: 00007ffd32b3ab68
2024-04-26T16:01:23.309108Z WARNING kernel: [ 42.583611] </TASK>
2024-04-26T16:01:23.309132Z WARNING kernel: [ 42.589614] ---[ end trace
50841adad66ceb3 ]---
2024-04-26T16:01:23.555366Z NOTICE ml-service[1881]: Pre-start ml-service
task=mojo_service
2024-04-26T16:01:23.579860Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:01:23.582873Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:01:23.582941Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T16:01:23.582963Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T16:01:23.583276Z INFO dlcservice[1365]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T16:01:23.583821Z WARNING cras_server[1439]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:01:23.584047Z ERR cras_server[1439]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T16:01:23.584102Z ERR cras_server[1439]: download_supported_dlc: retry 1 times
2024-04-26T16:01:23.901707Z ERR patchpanel[1281]: ERROR patchpanel: [datapath.cc(416)]
Failed to create fwmark tagging rule for uid {source: UPDATE_ENGINE, uid: , classid:
65537, is_on_vpn: false} in apply_local_source_mark
2024-04-26T16:01:23.927837Z NOTICE ml-service[1910]: ERROR: system services not running,
quit.
2024-04-26T16:01:23.987852Z NOTICE ml-service[1916]: Post-stop ml-service
task=mojo_service
2024-04-26T16:01:25.770878Z INFO minijail0[854]: libminijail[854]: child process 856
exited with status 1
2024-04-26T16:01:26.664736Z INFO kernel: [ 45.938502] IPv6: ADDRCONF(NETDEV_CHANGE):
arc_ns0: link becomes ready
2024-04-26T16:01:26.664793Z INFO kernel: [ 45.942141] IPv6: ADDRCONF(NETDEV_CHANGE):
veth0: link becomes ready
2024-04-26T16:01:27.198146Z INFO kernel: [ 46.472057] IPv6: ADDRCONF(NETDEV_CHANGE):
veth1: link becomes ready
2024-04-26T16:01:27.960548Z CRIT root[2350]: No new logout-started signal received after
10 seconds.
2024-04-26T16:01:33.270103Z INFO kernel: [ 52.524905] pci 0000:00:07.3: attach allowed
to drvr piix4_smbus [internal device]
2024-04-26T16:01:33.333710Z ERR kernel: [ 52.559503] piix4_smbus 0000:00:07.3: SMBus
base address uninitialized - upgrade BIOS or use force_addr=0xaddr
2024-04-26T16:01:33.868043Z INFO kernel: [ 53.142742] pci 0000:02:02.0: attach allowed
to drvr snd_hda_intel [internal device]
2024-04-26T16:01:33.924299Z ERR kernel: [ 53.196016] snd_hda_intel 0000:02:02.0: CORB
```

```
reset timeout#1, CORBRP = 0
2024-04-26T16:01:34.015479Z ERR usb_bouncer[2937]: Owner uid is 0 instead of 20124
2024-04-26T16:01:34.054937Z ERR usb_bouncer[2995]: No active user session.
2024-04-26T16:01:34.259748Z INFO kernel: [ 53.531126] snd_hda_codec_generic
hdaudioC0D0: autoconfig for Generic: line_outs=4 (0x14/0x15/0x16/0x17/0x0) type:line
2024-04-26T16:01:34.259783Z INFO kernel: [ 53.536237] snd_hda_codec_generic
hdaudioC0D0: speaker_outs=0 (0x0/0x0/0x0/0x0/0x0)
2024-04-26T16:01:34.262792Z ERR usb_bouncer[3022]: No active user session.
2024-04-26T16:01:34.269855Z INFO kernel: [ 53.545106] snd_hda_codec_generic
hdaudioC0D0: hp_outs=0 (0x0/0x0/0x0/0x0/0x0)
2024-04-26T16:01:34.278076Z INFO kernel: [ 53.555375] snd_hda_codec_generic
hdaudioC0D0: mono: mono_out=0x0
2024-04-26T16:01:34.278107Z INFO kernel: [ 53.558602] snd_hda_codec_generic
hdaudioC0D0: inputs:
2024-04-26T16:01:34.284812Z INFO kernel: [ 53.561088] snd_hda_codec_generic
hdaudioC0D0: Mic=0x18
2024-04-26T16:01:34.399223Z INFO kernel: [ 53.674619] input: HD-Audio Generic Mic as
/devices/pci0000:00/0000:00:11.0/0000:02:02.0/sound/card0/input6
2024-04-26T16:01:34.418137Z INFO kernel: [ 53.680059] input: HD-Audio Generic Line Out
Front as /devices/pci0000:00/0000:00:11.0/0000:02:02.0/sound/card0/input7
2024-04-26T16:01:34.418174Z INFO kernel: [ 53.692937] input: HD-Audio Generic Line Out
Surround as /devices/pci0000:00/0000:00:11.0/0000:02:02.0/sound/card0/input8
2024-04-26T16:01:34.471063Z INFO kernel: [ 53.745446] input: HD-Audio Generic Line Out
CLFE as /devices/pci0000:00/0000:00:11.0/0000:02:02.0/sound/card0/input9
2024-04-26T16:01:34.477182Z INFO kernel: [ 53.752049] input: HD-Audio Generic Line Out
Side as /devices/pci0000:00/0000:00:11.0/0000:02:02.0/sound/card0/input10
2024-04-26T16:01:34.583075Z ERR usb_bouncer[3075]: No active user session.
2024-04-26T16:01:34.655816Z ERR usb_bouncer[3093]: No active user session.
2024-04-26T16:01:35.012070Z WARNING kernel: [ 54.278810] udevd[1594]: Process
'/bin/chown resourced:resourced /sys/devices/system/cpu/cpu2/cpufreq/scaling_governor'
failed with exit code 1.
2024-04-26T16:01:35.012101Z WARNING kernel: [ 54.282163] udevd[1611]: Process
'/bin/chown resourced:resourced /sys/devices/system/cpu/cpu3/cpufreq/scaling_governor'
failed with exit code 1.
2024-04-26T16:01:35.070545Z ERR usb_bouncer[3188]: No active user session.
2024-04-26T16:01:35.125183Z WARNING kernel: [ 54.392869] udevd[1563]: Process
'/bin/chown resourced:resourced /sys/devices/system/cpu/cpu0/cpufreq/scaling_governor'
failed with exit code 1.
2024-04-26T16:01:35.175230Z WARNING kernel: [ 54.441300] udevd[1611]: Process
'/bin/chown -R root:wilco_dtc /sys/firmware/dmi/tables' failed with exit code 1.
2024-04-26T16:01:35.194280Z DEBUG kernel: [ 54.474506] usb 2-2.1: GPIO lookup for
consumer reset
2024-04-26T16:01:35.194311Z DEBUG kernel: [ 54.474516] usb 2-2.1: using lookup tables
for GPIO lookup
2024-04-26T16:01:35.194317Z DEBUG kernel: [ 54.474566] usb 2-2.1: No GPIO consumer
reset found
2024-04-26T16:01:35.201083Z INFO kernel: [ 54.478279] usbcore: registered new interface
driver btusb
2024-04-26T16:01:35.347797Z WARNING kernel: [ 54.590751] udevd[1604]: Process
'/bin/chown resourced:resourced /sys/devices/system/cpu/cpu1/cpufreq/scaling_governor'
failed with exit code 1.
2024-04-26T16:01:35.768134Z ERR kernel: [ 55.044780] Bluetooth: hci0: unexpected cc
0x0c12 length: 2 < 3
2024-04-26T16:01:35.768168Z ERR kernel: [ 55.047808] Bluetooth: hci0: Opcode 0x c12
failed: -38
2024-04-26T16:01:35.849053Z INFO permission_broker[1313]:
ProcessPath(/dev/bus/usb/002/004)
2024-04-26T16:01:35.939082Z INFO kernel: [ 55.214952] NET: Registered PF_VSOCK protocol
family
2024-04-26T16:01:35.958896Z WARNING cras_server[1439]: [alsa-lib] uc_mgr_config_load() ->
could not open open configuration file /usr/share/alsa/ucm2/HD-Audio Generic/HD-Audio
Generic.conf
2024-04-26T16:01:35.959296Z WARNING cras_server[1439]: [alsa-lib] load_master_config() ->
error: could not parse configuration for card HD-Audio Generic
2024-04-26T16:01:35.959427Z WARNING cras_server[1439]: [alsa-lib] snd_use_case_mgr_open()
-> error: failed to import HD-Audio Generic use case configuration -2
2024-04-26T16:01:35.959539Z WARNING cras_server[1439]: Can not open ucm for card HD-Audio
Generic, rc = -2
2024-04-26T16:01:35.959609Z WARNING cras_server[1439]: No ucm config on internal card HD-
```

Audio Generic

```
2024-04-26T16:01:36.468860Z INFO minijail0[3426]: libminijail[3426]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:36.470847Z WARNING minijail0[3426]: libminijail[3426]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:36.470864Z WARNING minijail0[3426]: libminijail[3426]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:36.472640Z WARNING minijail0[3430]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:01:36.472664Z WARNING minijail0[3430]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:36.472678Z INFO minijail0[3430]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:01:36.600243Z NOTICE temp_logger[3465]: Exiting temp_logger, system does
not have any temp sensor.
2024-04-26T16:01:36.628096Z WARNING minijail0[3477]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:01:36.628127Z WARNING minijail0[3477]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:36.628140Z INFO minijail0[3477]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:01:36.628153Z WARNING minijail0[3326]: libminijail[3326]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:36.628188Z WARNING minijail0[3326]: libminijail[3326]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:36.685974Z INFO minijail0[3491]: libminijail[3491]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:36.788106Z WARNING minijail0[3491]: libminijail[3491]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:36.788127Z WARNING minijail0[3491]: libminijail[3491]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:36.799517Z WARNING minijail0[3495]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:01:36.799588Z WARNING minijail0[3495]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:36.799602Z INFO minijail0[3495]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:01:36.809697Z WARNING minijail0[3473]: libminijail[3473]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:36.809765Z WARNING minijail0[3473]: libminijail[3473]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:36.812909Z WARNING minijail0[3494]: libminijail[3494]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:36.812982Z WARNING minijail0[3494]: libminijail[3494]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:36.812998Z INFO minijail0[3494]: libminijail[3494]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:01:36.827656Z INFO minijail0[3323]: libminijail[3323]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:36.839451Z WARNING minijail0[3323]: libminijail[3323]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:36.839592Z WARNING minijail0[3323]: libminijail[3323]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:36.842902Z WARNING minijail0[3553]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:01:36.844549Z NOTICE chromeos-startup[3550]: 2024-04-26T16:01:02.645049Z
WARNING chromeos_startup: [chromeos_startup.cc(793)] Failed to get boot information from
crossystem
2024-04-26T16:01:36.845153Z WARNING minijail0[3553]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:36.845190Z INFO minijail0[3553]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:01:36.845591Z NOTICE chromeos-startup[3550]: 2024-04-26T16:01:05.175036Z
ERROR chromeos_startup: [safe_fd.cc(701)] unlinkat failed: No such file or directory (2)
2024-04-26T16:01:36.845863Z NOTICE chromeos-startup[3550]: 2024-04-26T16:01:05.335987Z
WARNING chromeos_startup: [chromeos_startup.cc(703)] Unable to collect early logs and
crashes.: No such file or directory (2)
2024-04-26T16:01:36.858659Z NOTICE send-boot-metrics[3549]: Missing timestamp in firmware
log
```

```
2024-04-26T16:01:36.870487Z INFO minijail0[3529]: libminijail[3529]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:36.929881Z NOTICE /usr/share/cros/init/crx-import.sh[3561]: CRX Cache
exists. No import performed.
2024-04-26T16:01:37.144823Z INFO missed[3548]: Starting Missive Service.
2024-04-26T16:01:37.180960Z WARNING missed[3548]: Service became available
2024-04-26T16:01:37.190234Z WARNING missed[3548]: Parameters updated
2024-04-26T16:01:37.207604Z WARNING missed[3548]: Flag `controlled_degradation` is
initially disabled
2024-04-26T16:01:37.207825Z WARNING missed[3548]: Flag `compression` is initially
enabled
2024-04-26T16:01:37.207847Z WARNING missed[3548]: Flag `encryption` is initially
enabled
2024-04-26T16:01:37.207962Z WARNING missed[3548]: Flag `legacy_storage_enabled` is
initially enabled
2024-04-26T16:01:37.212262Z WARNING missed[3548]: Encryption is enabled, but the key is
not available yet, status=NOT_FOUND:No valid encryption key found
2024-04-26T16:01:37.258460Z INFO u2fd[3553]: INFO u2fd: [main.cc(34)] Daemon version
0.0.1-r1817-635ba60101
2024-04-26T16:01:37.275217Z WARNING minijail0[3586]: libminijail[3586]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:37.275300Z WARNING minijail0[3586]: libminijail[3586]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:37.278890Z WARNING minijail0[3644]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:01:37.278969Z WARNING minijail0[3644]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:37.278986Z INFO minijail0[3644]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:01:37.281917Z INFO permission_broker[1313]: AllowUsbDeviceRule: ALLOW
2024-04-26T16:01:37.283067Z INFO permission_broker[1313]: AllowTtyDeviceRule: IGNORE
2024-04-26T16:01:37.304563Z INFO permission_broker[1313]: Found claimed interface with
driver: btusb
2024-04-26T16:01:37.316297Z INFO permission_broker[1313]: Found claimed interface with
driver: btusb
2024-04-26T16:01:37.342863Z INFO u2fd[3553]: INFO u2fd: [u2f_daemon.cc(367)] Requested
Mode: Policy[unset], force_u2f[0], force_g2f[0]
2024-04-26T16:01:37.343224Z INFO u2fd[3553]: INFO u2fd: [u2f_daemon.cc(381)] Mode:
Disabled (not supported)
2024-04-26T16:01:37.351365Z INFO permission_broker[1313]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T16:01:37.351461Z INFO permission_broker[1313]: Verdict for
/dev/bus/usb/002/004: DENY
2024-04-26T16:01:37.351700Z INFO permission_broker[1313]:
ProcessPath(/dev/bus/usb/002/004)
2024-04-26T16:01:37.456796Z INFO resourced[3605]: Starting resourced
2024-04-26T16:01:37.588053Z NOTICE mount-vmware-share[3687]: mount vmware /run/vmware-
share
2024-04-26T16:01:37.614353Z INFO minijail0[3470]: libminijail[3470]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:37.794922Z INFO minijail0[3728]: libminijail[3728]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:37.858601Z INFO minijail0[3727]: libminijail[3727]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:37.911884Z INFO minijail0[3739]: libminijail[3739]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:37.939420Z WARNING minijail0[3745]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:01:37.939459Z WARNING minijail0[3745]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:37.939473Z INFO minijail0[3745]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:01:37.940626Z WARNING minijail0[3739]: libminijail[3739]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:37.940651Z WARNING minijail0[3739]: libminijail[3739]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:38.010633Z ERR cryptohomed[954]: Failed to call method:
org.chromium.ChromeFeaturesServiceInterface.IsFeatureEnabled: object_path=
/org/chromium/ChromeFeaturesService: org.freedesktop.DBus.Error.InvalidArgs: Unexpected
```

feature name.

```
2024-04-26T16:01:38.010956Z WARNING cryptohomed[954]: No valid keysets on disk for
521ac76c473ca5ff9c03ccc71d8ad8646690ad65
2024-04-26T16:01:38.019460Z INFO cryptohomed[954]: AuthSession: started with
is_ephemeral_user=0 intent=decrypt user_exists=1 factors=gaia(type 0 uss).
2024-04-26T16:01:38.066425Z INFO cryptohomed[954]: AuthSession: decrypt authentication
attempt via gaia
2024-04-26T16:01:38.150172Z INFO root[3763]: fydeos-license-utils get disk /dev/nvme0n1
serial by lsblk
2024-04-26T16:01:38.177711Z INFO root[3767]: fydeos-license-utils get fix id by disk
serial
2024-04-26T16:01:38.368626Z INFO session_manager[1034]: INFO session_manager:
[device_identifier_generator.cc(132)] Stable device secret missing!
2024-04-26T16:01:38.368962Z ERR session_manager[1034]: ERROR session_manager:
[device_identifier_generator.cc(263)] No stable device secret available.
2024-04-26T16:01:38.613573Z INFO minijail0[3801]: libminijail[3801]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:38.621786Z INFO crash_reporter[3793]: Running boot collector
2024-04-26T16:01:38.622503Z INFO crash_reporter[3793]: developer build - not testing -
always dumping
2024-04-26T16:01:38.622729Z WARNING crash_reporter[3793]: Last shutdown was not clean
2024-04-26T16:01:38.760224Z ERR crash_reporter[3793]: Failed to run ectool. Error: '1'
2024-04-26T16:01:38.764297Z INFO crash_reporter[3793]: Unsupported GSC present on board.
Unable to query GSC crashes.
2024-04-26T16:01:38.765591Z INFO crash_reporter[3793]: Failed to get the GSC flog output.
2024-04-26T16:01:38.766142Z INFO crash_reporter[3793]: Enabling kernel crash handling
2024-04-26T16:01:38.766826Z INFO crash_reporter[3793]: Found 2 kernel crashes in efi-
pstore.
2024-04-26T16:01:38.770338Z INFO crash_reporter[3793]: Generating kernel efi crash
id:171414722301001
2024-04-26T16:01:38.771602Z INFO crash_reporter[3793]: Reporting kernel efi crash
id:171414722301001 type:Panic
2024-04-26T16:01:38.817380Z INFO minijail0[3809]: libminijail[3809]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:38.841587Z NOTICE dbus-daemon[569]: [system] Rejected send message, 2
matched rules; type="method_call", sender=":1.111" (uid=20130 pid=3741
comm="/usr/libexec/fwupd/fwupd " label="u:r:cros_fwupd:s0")
interface="org.freedesktop.DBus.ObjectManager" member="GetManagedObjects" error name="
(unset)" requested_reply="0" destination=":1.10" (uid=218 pid=750
comm="/usr/libexec/bluetooth/bluetoothd --nodetach --co" label="u:r:cros_bluetoothd:s0")
2024-04-26T16:01:38.864687Z WARNING crash_reporter[3793]: Found no crashing function
2024-04-26T16:01:38.866308Z WARNING crash_reporter[3793]: Found no panic message
2024-04-26T16:01:38.866502Z WARNING crash_reporter[3793]: Found no human readable string,
using empty string
2024-04-26T16:01:38.866921Z INFO crash_reporter[3793]: Received prior crash notification
from kernel (signature kernel--FC8C61CF) (handling)
2024-04-26T16:01:38.875237Z ERR crash_reporter[3793]: Could not get user crash
directories
2024-04-26T16:01:38.875718Z INFO crash_reporter[3793]: Accessing crash dir
'/var/spool/crash' via symlinked handle '/proc/self/fd/11'
2024-04-26T16:01:38.913986Z INFO permission_broker[1313]: AllowUsbDeviceRule: ALLOW
2024-04-26T16:01:38.924059Z INFO permission_broker[1313]: AllowTtyDeviceRule: IGNORE
2024-04-26T16:01:38.944343Z INFO minijail0[3812]: libminijail[3812]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:38.949513Z INFO permission_broker[1313]: Found claimed interface with
driver: btusb
2024-04-26T16:01:38.991643Z INFO permission_broker[1313]: Found claimed interface with
driver: btusb
2024-04-26T16:01:39.054572Z INFO permission_broker[1313]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T16:01:39.062636Z INFO crash_reporter[3793]: Finishing crash. Meta file:
/proc/self/fd/11/kernel.20240426.160138.56522.0.meta
2024-04-26T16:01:39.070630Z INFO permission_broker[1313]: Verdict for
/dev/bus/usb/002/004: DENY
2024-04-26T16:01:39.071628Z INFO permission_broker[1313]:
ProcessPath(/dev/bus/usb/002/002)
2024-04-26T16:01:39.078348Z ERR crash_reporter[3793]: Could not get user home
directories, using default.
2024-04-26T16:01:39.084174Z INFO minijail0[3812]: libminijail[3812]: child process 3816
```

```
exited with status 1
2024-04-26T16:01:39.085567Z ERR debugd[3800]: RunHelper(...): Domain=dbus,
Code=org.chromium.debugd.SchedulerConfigurationPolicyError, Message=ERROR
scheduler_configuration_helper: [scheduler_configuration_utils.cc(276)] Failed to open:
/sys/devices/system/cpu/cpu1/online: Permission denied (13)#012ERROR
scheduler_configuration_helper: [scheduler_configuration_helper.cc(118)] Failed to open
CPU control files.#012
2024-04-26T16:01:39.085706Z ERR debugd[3800]: SetPolicy(...): Domain=dbus,
Code=org.chromium.debugd.SchedulerConfigurationPolicyError,
Message=scheduler_configuration_helper failed: stdout=
2024-04-26T16:01:39.093037Z INFO crash_reporter[3793]: Stored kcrash to
/proc/self/fd/11/kernel.20240426.160138.56522.0.kcrash
2024-04-26T16:01:39.095595Z INFO minijail0[3818]: libminijail[3818]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:39.100188Z INFO crash_reporter[3793]: Generating kernel efi crash
id:171414722401001
2024-04-26T16:01:39.152444Z INFO crash_reporter[3793]: /sys/firmware/log does not exist,
skipping BIOS crash check. (This is normal for older boards.)
2024-04-26T16:01:39.152563Z WARNING crash_reporter[3793]: No console-ramoops file found
after watchdog reset
2024-04-26T16:01:39.153686Z INFO crash_reporter[3793]: Examining
/run/crash_reporter/crash for crashes
2024-04-26T16:01:39.153787Z INFO crash_reporter[3793]: Examining
/mnt/stateful_partition/reboot_vault/crash for crashes
2024-04-26T16:01:39.175142Z INFO session_manager[1034]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting start-arc-instance Upstart signal
2024-04-26T16:01:39.185724Z ERR debugd[3800]: AllowToolUse(...): Domain=dbus,
Code=org.chromium.debugd.error.AccessDenied, Message=Unavailable after device has an
owner or boot lockbox is finalized.
2024-04-26T16:01:39.186580Z INFO session_manager[1034]: INFO session_manager:
[android_oci_wrapper.cc(125)] run_oci PID: 3826
2024-04-26T16:01:39.345990Z WARNING minijail0[3824]: libminijail[3824]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:39.346082Z WARNING minijail0[3824]: libminijail[3824]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:39.346622Z WARNING minijail0[3837]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:01:39.346642Z WARNING minijail0[3837]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:39.346657Z INFO minijail0[3837]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFER: false
2024-04-26T16:01:39.404820Z INFO minijail0[3836]: libminijail[3836]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:39.405680Z WARNING minijail0[3839]: libminijail[3839]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:39.405700Z WARNING minijail0[3839]: libminijail[3839]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:39.405714Z INFO minijail0[3839]: libminijail[3839]: Landlock support for
LANDLOCK_ACCESS_FS_REFER: false
2024-04-26T16:01:39.408218Z WARNING minijail0[3836]: libminijail[3836]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:39.408265Z WARNING minijail0[3836]: libminijail[3836]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:39.535374Z WARNING minijail0[3841]: libminijail[3841]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:39.535421Z WARNING minijail0[3841]: libminijail[3841]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:39.536352Z WARNING minijail0[3842]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:01:39.536392Z WARNING minijail0[3842]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:39.536407Z INFO minijail0[3842]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFER: false
2024-04-26T16:01:39.594436Z INFO cryptohomed[954]: AuthSession: authorized for
decrypt,verify-only.
2024-04-26T16:01:39.603163Z WARNING memd[3843]: memd started
2024-04-26T16:01:39.698463Z WARNING metrics_daemon[3839]: WARNING metrics_daemon:
[vmlog_writer.cc(464)] Failed to open scaling_cur_freq for logical core 0: No such file
or directory (2)
```


2024-04-26T16:01:39.698524Z WARNING metrics_daemon[3839]: WARNING metrics_daemon: [vmlog_writer.cc(464)] Failed to open scaling_cur_freq for logical core 1: No such file or directory (2)

2024-04-26T16:01:39.698552Z WARNING metrics_daemon[3839]: WARNING metrics_daemon: [vmlog_writer.cc(464)] Failed to open scaling_cur_freq for logical core 2: No such file or directory (2)

2024-04-26T16:01:39.698576Z WARNING metrics_daemon[3839]: WARNING metrics_daemon: [vmlog_writer.cc(464)] Failed to open scaling_cur_freq for logical core 3: No such file or directory (2)

2024-04-26T16:01:39.698659Z ERR metrics_daemon[3839]: ERROR metrics_daemon: [vmlog_writer.cc(266)] RAPL info disabled (b/168594119).: No such file or directory (2)

2024-04-26T16:01:39.730779Z INFO cryptohomed[954]: Preparing persistent vault

2024-04-26T16:01:40.031895Z INFO cryptohomed[954]: Started mounting for: 521ac76c473ca5ff9c03ccc71d8ad8646690ad65

2024-04-26T16:01:40.327282Z ERR cryptohome-namespace-mounter[3871]: Owner uid is 0 instead of 1000

2024-04-26T16:01:40.401327Z INFO kernel: [59.676450] fscrypt: AES-256-CTS-CBC using implementation "cts-cbc-aes-aesni"

2024-04-26T16:01:40.328588Z ERR cryptohome-namespace-mounter[3871]: Owner uid is 0 instead of 1000

2024-04-26T16:01:40.450431Z ERR cros_camera_service[3646]: InitializeOnGpuThread(): Failed to create EGL context

2024-04-26T16:01:40.455002Z INFO cros_camera_service[3646]: LoadCameraHal(): Try to load camera hal /usr/lib64/camera_hal/usb.so

2024-04-26T16:01:40.491447Z INFO cryptohome-namespace-mounter[3871]: Not a first mount, since found: /home/.shadow/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/mount/user/Shortcuts-journal

2024-04-26T16:01:40.492991Z INFO cros_camera_service[3646]: LoadCameraHal(): Running camera HAL adapter on 2

2024-04-26T16:01:40.518566Z INFO cros_camera_service[3646]: Start(): Effects are not enabled, DLC will not be installed.

2024-04-26T16:01:40.610477Z INFO cryptohomed[954]: OOP mount helper started successfully

2024-04-26T16:01:40.614630Z INFO cryptohomed[954]: Restoring SELinux contexts for: /home/.shadow/521ac76c473ca5ff9c03ccc71d8ad8646690ad65, recursive=true

2024-04-26T16:01:40.639109Z INFO cros_camera_service[3646]: StartOnThread(): Camera module "V4L2 UVC Camera HAL v3" has 0 built-in camera(s)

2024-04-26T16:01:40.640894Z INFO cros_camera_service[3646]: StartOnThread(): SuperHAL started with 1 modules, 0 built-in cameras and 0 unexposed physical cameras

2024-04-26T16:01:40.646562Z INFO cros_camera_service[3646]: main(): Started camera HAL v3 adapter

2024-04-26T16:01:40.649761Z INFO cros_camera_service[3646]: CreateClientUnixDomainSocket(): Connect the camera socket successfully. Socket info: creation_time: 2024-04-26 16:01:14.031 UTC last_accessed: 2024-04-26 16:01:40.646 UTC last_modified: 2024-04-26 16:01:14.030 UTC

2024-04-26T16:01:40.698223Z ERR arc-setup-prepare[3848]: ERROR arc-setup: [safe_fd.cc(701)] unlinkat failed: No such file or directory (2)

2024-04-26T16:01:40.704117Z INFO cryptohomed[954]: Mount succeeded.

2024-04-26T16:01:40.708321Z INFO cros_camera_service[3646]: OnServerRegistered(): Successfully registered camera server.

2024-04-26T16:01:40.720570Z INFO chapsd[834]: Opening database in: /run/daemon-store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65

2024-04-26T16:01:40.758561Z INFO cros_camera_service[3646]: BindOnThread(): Bridge ready

2024-04-26T16:01:40.769683Z INFO chapsd[834]: leveldb /run/daemon-store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database dump:#012 /run/daemon-store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/LOCK (0 bytes, 2024-03-26 12:37:20.000 UTC)#012 /run/daemon-store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/CURRENT (16 bytes, 2024-04-26 14:32:15.000 UTC)#012 /run/daemon-store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/000008.ldb (614 bytes, 2024-03-26 13:05:31.000 UTC)#012 /run/daemon-store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/LOG.old (184 bytes, 2024-04-26 14:00:49.000 UTC)#012 /run/daemon-store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/000037.log (0 bytes, 2024-04-26 14:32:15.000 UTC)#012 /run/daemon-store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/MANIFEST-000036 (138 bytes, 2024-04-26 14:32:15.000 UTC)#012 /run/daemon-store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/000005.ldb (393 bytes, 2024-03-26 12:58:13.000 UTC)#012 /run/daemon-store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/database/LOG (184 bytes, 2024-04-26

```

14:32:15.000 UTC)
2024-04-26T16:01:40.880099Z INFO permission_broker[1313]: AllowUsbDeviceRule: ALLOW
2024-04-26T16:01:40.883504Z INFO permission_broker[1313]: AllowTtyDeviceRule: IGNORE
2024-04-26T16:01:40.916137Z INFO permission_broker[1313]: Found claimed interface with
driver: usbhid
2024-04-26T16:01:40.920744Z INFO permission_broker[1313]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T16:01:40.921067Z INFO permission_broker[1313]: Verdict for
/dev/bus/usb/002/002: DENY
2024-04-26T16:01:40.921366Z INFO permission_broker[1313]:
ProcessPath(/dev/bus/usb/002/002)
2024-04-26T16:01:40.965520Z INFO kernel: [ 60.242505] fscrypt: AES-256-XTS using
implementation "xts-aes-aesni"
2024-04-26T16:01:41.035990Z INFO chapsd[834]: leveldb.stats:#012
Compactions#012Level Files Size(MB) Time(sec) Read(MB) Write(MB)#012-----
-----#012 0 2 0 0 0 0#012
2024-04-26T16:01:41.071555Z INFO chapsd[834]: leveldb contains 6 keys.
2024-04-26T16:01:41.073692Z INFO chapsd[834]: Slot 1 ready for token at /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65
2024-04-26T16:01:41.075544Z INFO chapsd[834]: Created lock file:
/run/lock/power_override/chapsd_token_init_slot_1.lock
2024-04-26T16:01:41.077907Z INFO cryptohomed[954]: PKCS#11 initialization succeeded.
2024-04-26T16:01:41.096232Z INFO chapsd[834]: Root key is ready for token at /run/daemon-
store/chaps/521ac76c473ca5ff9c03ccc71d8ad8646690ad65
2024-04-26T16:01:41.096555Z INFO chapsd[834]: Deleted lock file:
/run/lock/power_override/chapsd_token_init_slot_1.lock
2024-04-26T16:01:41.109833Z ERR arc-setup-prepare[3848]: ERROR arc-setup:
[safe_fd.cc(138)] Owner uid is 0 instead of 603
2024-04-26T16:01:41.654479Z INFO permission_broker[1313]: AllowUsbDeviceRule: ALLOW
2024-04-26T16:01:41.654525Z INFO permission_broker[1313]: AllowTtyDeviceRule: IGNORE
2024-04-26T16:01:41.659604Z INFO permission_broker[1313]: Found claimed interface with
driver: usbhid
2024-04-26T16:01:41.688125Z INFO permission_broker[1313]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T16:01:41.688694Z INFO permission_broker[1313]: Verdict for
/dev/bus/usb/002/002: DENY
2024-04-26T16:01:41.930312Z INFO bluetoothd[750]: Applied debug levels: bluez(0),
kernel(0)
2024-04-26T16:01:41.931979Z ERR bluetoothd[750]: No default adapter. Skip setting quality
debug.
2024-04-26T16:01:42.046116Z INFO dbus-daemon[569]: [system] Activating service
name='org.chromium.SmbProvider' requested by ':1.41' (uid=1000 pid=1061
comm="/opt/google/chrome/chrome --enable-webgl-image-chr" label="u:r:cros_browser:s0")
(using servicehelper)
2024-04-26T16:01:42.106205Z WARNING cros-disks[3907]: libminijail[1]: ioctl(SIOCSIFFLAGS)
failed: Operation not permitted
2024-04-26T16:01:42.510435Z INFO fusebox[3912]: fusebox /dev/fd/11 [2]
2024-04-26T16:01:42.515789Z INFO fusebox[3912]: fusebox fuse_daemonizing
2024-04-26T16:01:42.716662Z WARNING minijail0[3922]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:01:42.716893Z WARNING minijail0[3922]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:42.717083Z INFO minijail0[3922]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:01:42.727078Z WARNING minijail0[3921]: libminijail[3921]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:42.727105Z WARNING minijail0[3921]: libminijail[3921]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:42.804187Z INFO minijail0[3923]: libminijail[3923]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:43.192788Z INFO minijail0[3931]: libminijail[3931]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:01:45.672651Z WARNING minijail0[3941]: libminijail[3941]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:45.673854Z WARNING minijail0[3941]: libminijail[3941]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:01:45.677230Z WARNING minijail0[3945]: libminijail[3945]: failed to create
a ruleset: Function not implemented
2024-04-26T16:01:45.678766Z WARNING minijail0[3945]: libminijail[3945]: Landlock is not

```

supported by the current kernel: Function not implemented
2024-04-26T16:01:45.679348Z INFO minijail0[3945]: libminijail[3945]: Landlock support for LANDLOCK_ACCESS_FS_REFER: false
2024-04-26T16:01:45.933422Z INFO minijail0[3931]: libminijail[3931]: child process 3934 exited with status 1
2024-04-26T16:01:45.934270Z ERR debugd[3800]: Problem waiting for pid 3931: No child processes (10)
2024-04-26T16:01:45.934382Z ERR debugd[3800]: Unable to send signal to 3931: No such process (3)
2024-04-26T16:01:46.318755Z INFO kernel: [65.597334] loop8: detected capacity change from 0 to 754088
2024-04-26T16:01:46.497076Z INFO kernel: [65.759450] loop9: detected capacity change from 0 to 212568
2024-04-26T16:01:46.520935Z INFO smbproviderd[3922]: NTLM protocol is disabled
2024-04-26T16:01:46.522678Z INFO dbus-daemon[569]: [system] Successfully activated service 'org.chromium.SmbProvider'
2024-04-26T16:01:47.148746Z INFO kernel: [66.411375] loop10: detected capacity change from 0 to 8
2024-04-26T16:01:47.391053Z NOTICE dbus-daemon[569]: [system] Failed to activate service 'org.chromium.MachineLearning': timed out (service_start_timeout=25000ms)
2024-04-26T16:01:47.816097Z WARNING kernel: [67.088859] hrtimer: interrupt took 3404675 ns
2024-04-26T16:01:49.387129Z ERR tpm_managerd[772]:
ClearOwnerPasswordAndReplaceWithRandomPasswordIfPossible: missing owner password.
2024-04-26T16:01:49.387163Z INFO tpm_managerd[772]:
ClearStoredOwnerPasswordTaskReplaceOwnerPasswordResult: kFail
2024-04-26T16:01:50.785313Z INFO root[4078]: fydeos-license-utils get disk /dev/nvme0n1 serial by lsblk
2024-04-26T16:01:50.797162Z INFO root[4079]: fydeos-license-utils get fix id by disk serial
2024-04-26T16:01:50.817309Z ERR bluetoothd[750]: No default adapter. Skip setting quality debug.
2024-04-26T16:01:52.485121Z WARNING kernel: [71.767266] memfd_create() without MFD_EXEC nor MFD_NOEXEC_SEAL, pid=1096 'chrome_crashpad'
2024-04-26T16:01:52.811229Z INFO crash_reporter[4136]: developer build - not testing - always dumping
2024-04-26T16:01:52.820977Z WARNING crash_reporter[4136]: Received crash notification for chrome[1061] user 1000 (called directly)
2024-04-26T16:01:52.962318Z INFO iioservice[712]: INFO iioservice: [iio_sensor.cc(56)] (2) Request(): Received SensorService from Mojo Service Manager
2024-04-26T16:01:54.719223Z NOTICE dbus-daemon[569]: [system] Rejected send message, 1 matched rules; type="method_call", sender=":1.41" (uid=1000 pid=1061 comm="/opt/google/chrome/chrome --enable-webgl-image-chr" label="u:r:cros_browser:s0") interface="com.ubuntu.Upstart0_6.Job" member="Start" error name="(unset)" requested_reply="0" destination="com.ubuntu.Upstart" (uid=0 pid=1 comm="/sbin/init" label="u:r:cros_init:s0")
2024-04-26T16:01:55.301587Z ERR bluetoothd[750]: No default adapter. Skip setting quality debug.
2024-04-26T16:01:58.417680Z ERR bluetoothd[750]: No default adapter. Skip setting quality debug.
2024-04-26T16:02:01.420885Z ERR bluetoothd[750]: No default adapter. Skip setting quality debug.
2024-04-26T16:02:04.426613Z ERR bluetoothd[750]: No default adapter. Skip setting quality debug.
2024-04-26T16:02:05.268510Z INFO iioservice[712]: INFO iioservice: [sensor_service_impl.cc(417)] (2) OnSensorServiceDisconnect(): SensorDevice disconnected. ReceiverId: 3
2024-04-26T16:02:07.442618Z ERR bluetoothd[750]: No default adapter. Skip setting quality debug.
2024-04-26T16:02:08.972179Z NOTICE preload-network[4341]: WiFi interface not found after 30 seconds.
2024-04-26T16:02:09.701606Z WARNING metrics_daemon[3839]: WARNING metrics_daemon: [metrics_daemon.cc(709)] cannot read /sys/devices/system/cpu/cpu0/cpufreq/cpuinfo_max_freq
2024-04-26T16:02:10.508377Z ERR bluetoothd[750]: No default adapter. Skip setting quality debug.
2024-04-26T16:02:12.149609Z NOTICE auditd[458]: Audit daemon rotating log files
2024-04-26T16:02:12.202417Z INFO session_manager[1034]: INFO session_manager: [android_oci_wrapper.cc(181)] Container PID: 4346

```
2024-04-26T16:02:12.202483Z INFO session_manager[1034]: INFO session_manager:
[session_manager_impl.cc(2180)] Started Android container with PID 4346
2024-04-26T16:02:12.212872Z INFO session_manager[1034]: INFO session_manager:
[policy_key.cc(49)] No policy key on disk at /run/daemon-
store/session_manager/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/policy/key
2024-04-26T16:02:12.234878Z INFO session_manager[1034]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting start-user-session Upstart signal
2024-04-26T16:02:12.260196Z INFO session_manager[1034]: INFO session_manager:
[session_manager_impl.cc(772)] Starting user session
2024-04-26T16:02:12.260592Z INFO session_manager[1034]: INFO session_manager:
[session_manager_impl.cc(780)] Emitting D-Bus signal SessionStateChanged: started
2024-04-26T16:02:12.269830Z INFO debugd[3800]: Deleting the ARC bug report backup
2024-04-26T16:02:12.306699Z INFO session_manager[1034]: INFO session_manager:
[session_manager_impl.cc(872)] LoadShillProfile() method called.
2024-04-26T16:02:12.306741Z INFO session_manager[1034]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting load-shill-profile Upstart signal
2024-04-26T16:02:12.344244Z INFO session_manager[1034]: INFO session_manager:
[session_manager_impl.cc(1609)] Android container is running with PID 4346
2024-04-26T16:02:12.344661Z WARNING crash_reporter[4136]: Bus::SendWithReplyAndBlock took
19511ms to process message: type=method_call, path=/org/chromium/SessionManager,
interface=org.chromium.SessionManagerInterface, member=RetrieveActiveSessions
2024-04-26T16:02:12.344810Z WARNING secanomalyd[1330]: Bus::SendWithReplyAndBlock took
21438ms to process message: type=method_call, path=/org/chromium/SessionManager,
interface=org.chromium.SessionManagerInterface, member=RetrieveActiveSessions
2024-04-26T16:02:12.345041Z INFO crash_reporter[4136]: Accessing crash dir '/run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65' via symlinked handle
'/proc/self/fd/10'
2024-04-26T16:02:12.451426Z INFO minijail0[4381]: libminijail[4381]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:02:12.521705Z INFO minijail0[4384]: libminijail[4384]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:02:12.569078Z INFO crosdns[4376]: Starting CrOS DNS daemon
2024-04-26T16:02:12.641697Z INFO minijail0[4390]: libminijail[4390]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:02:12.654244Z ERR arc-kmsg-logger[3892]: selinux: SELinux: Could not stat
/dev/block: No such file or directory.
2024-04-26T16:02:12.654294Z ERR arc-kmsg-logger[3892]:
2024-04-26T16:02:12.658837Z ERR arc-kmsg-logger[3892]: init: waitid failed: No child
processes
2024-04-26T16:02:12.661158Z ERR arc-kmsg-logger[3892]: init: Unable to set property
'ro.boot.container' to '1' in property file '/default.prop': Read-only property was
already set
2024-04-26T16:02:12.726771Z ERR arc-kmsg-logger[3892]: init: Unable to read config file
'/vendor/etc/init/init.cpusets.rc': open() failed: No such file or directory
2024-04-26T16:02:12.726807Z ERR arc-kmsg-logger[3892]: init: /init.rc: 2: Could not
import file '/vendor/etc/init/init.cpusets.rc': No such file or directory
2024-04-26T16:02:12.732453Z ERR arc-kmsg-logger[3892]: init: Unable to read config file
'/vendor/etc/init/hw/init.cheets.rc': open() failed: No such file or directory
2024-04-26T16:02:12.732527Z ERR arc-kmsg-logger[3892]: init: /init.rc: 10: Could not
import file '/vendor/etc/init/hw/init.cheets.rc': No such file or directory
2024-04-26T16:02:12.783333Z ERR arc-kmsg-logger[3892]: init: Unable to read config file
'/product/etc/init': open() failed: No such file or directory
2024-04-26T16:02:12.784312Z ERR arc-kmsg-logger[3892]: init: Unable to read config file
'/odm/etc/init': open() failed: No such file or directory
2024-04-26T16:02:12.802052Z INFO kernel: [ 92.093713] SELinux: Context is not valid
(left unmapped).
2024-04-26T16:02:12.811944Z INFO session_manager[1034]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting continue-arc-boot Upstart signal
2024-04-26T16:02:12.959730Z ERR kernel: [ 92.165134] cgroup: Unknown subsys name
'memory'
2024-04-26T16:02:12.972370Z ERR featured[1274]: Failed to call method:
org.chromium.ChromeFeaturesServiceInterface.IsFeatureEnabled: object_path=
/org/chromium/ChromeFeaturesService: org.freedesktop.DBus.Error.InvalidArgs: Unexpected
feature name.
2024-04-26T16:02:12.977145Z INFO vmlog_forwarder[4386]: Connecting to dbus signal
VmStartingUpSignal
2024-04-26T16:02:12.983552Z INFO vmlog_forwarder[4386]: Connecting to dbus signal
VmStoppedSignal
2024-04-26T16:02:12.989002Z INFO vmlog_forwarder[4386]: Started RotateLogs timer
```

```
2024-04-26T16:02:12.997149Z ERR arc-kmsg-logger[3892]: init: Subcontext init could not
set 'ro.opengles.version' to '131072': Read-only property was already set
2024-04-26T16:02:12.997667Z ERR arc-kmsg-logger[3892]: init: Subcontext init could not
set 'ro.hardware.egl' to 'mesa': Read-only property was already set
2024-04-26T16:02:13.011198Z INFO vmlog_forwarder[4386]: VM log forwarder listening on
port 9999
2024-04-26T16:02:13.014089Z ERR arc-kmsg-logger[3892]: ueventd: Unable to read config
file '/vendor/ueventd.rc': open() failed: No such file or directory
2024-04-26T16:02:13.021728Z ERR arc-kmsg-logger[3892]: ueventd: Unable to read config
file '/odm/ueventd.rc': open() failed: No such file or directory
2024-04-26T16:02:13.047626Z ERR kernel: [ 92.332953] cgroup: Unknown subsys name
'schedtune'
2024-04-26T16:02:13.054355Z ERR featured[1274]: Failed to call method:
org.chromium.ChromeFeaturesServiceInterface.IsFeatureEnabled: object_path=
/org/chromium/ChromeFeaturesService: org.freedesktop.DBus.Error.InvalidArgs: Unexpected
feature name.
2024-04-26T16:02:13.066074Z WARNING kernel: [ 92.356361] new mount options do not match
the existing superblock, will be ignored
2024-04-26T16:02:13.092440Z ERR arc-kmsg-logger[3892]: init: Init cannot set
'ro.opengles.version' to '196608': Read-only property was already set
2024-04-26T16:02:13.110327Z ERR featured[1274]: Failed to call method:
org.chromium.ChromeFeaturesServiceInterface.IsFeatureEnabled: object_path=
/org/chromium/ChromeFeaturesService: org.freedesktop.DBus.Error.InvalidArgs: Unexpected
feature name.
2024-04-26T16:02:13.177969Z ERR arc-kmsg-logger[3892]: init: Unable to set property
'ro.product.board' to 'fydeos' in property file '/vendor/build.prop': Read-only property
was already set
2024-04-26T16:02:13.177978Z ERR arc-kmsg-logger[3892]: init: Unable to set property
'ro.oem.key1' to 'fydeos' in property file '/vendor/build.prop': Read-only property was
already set
2024-04-26T16:02:13.178044Z ERR arc-kmsg-logger[3892]: init: /recovery not specified in
fstab
2024-04-26T16:02:13.366250Z ERR arc-kmsg-logger[3892]: init: Failed to open file
'/proc/kmsg': Permission denied
2024-04-26T16:02:13.541951Z ERR bluetoothd[750]: No default adapter. Skip setting quality
debug.
2024-04-26T16:02:13.582400Z ERR arc-kmsg-logger[3892]: selinux: SELinux: Could not stat
/metadata: No such file or directory.
2024-04-26T16:02:13.582433Z ERR arc-kmsg-logger[3892]:
2024-04-26T16:02:13.674526Z ERR arc-kmsg-logger[3892]: init: Failed to bind socket
'pdx/system/vr/display/client': No such file or directory
2024-04-26T16:02:13.674714Z ERR arc-kmsg-logger[3892]: init: Failed to bind socket
'pdx/system/vr/display/manager': No such file or directory
2024-04-26T16:02:13.674911Z ERR arc-kmsg-logger[3892]: init: Failed to bind socket
'pdx/system/vr/display/vsync': No such file or directory
2024-04-26T16:02:13.731819Z WARNING minijail0[4461]: libminijail[4461]:
realpath(/dev/kvm) failed: No such file or directory
2024-04-26T16:02:13.734532Z INFO minijail0[4461]: libminijail[4461]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:02:13.812706Z WARNING minijail0[4469]: libminijail[4469]: stat(/dev/kvm)
failed: No such file or directory
2024-04-26T16:02:13.814699Z WARNING minijail0[4469]: libminijail[4469]: cannot create
mount target '/tmp/minijail.dev.s2rvf4/kvm'
2024-04-26T16:02:13.814817Z WARNING minijail0[4469]: libminijail[4469]: mount_one failed
with /dev at '/tmp/minijail.dev.s2rvf4'
2024-04-26T16:02:13.982381Z INFO kernel: [ 93.134960] EXT4-fs (nvme0n1p1): re-mounted.
Opts: . Quota mode: journalled.
2024-04-26T16:02:13.982404Z INFO kernel: [ 93.143028] EXT4-fs (nvme0n1p1): re-mounted.
Opts: . Quota mode: journalled.
2024-04-26T16:02:13.982409Z INFO kernel: [ 93.148965] EXT4-fs (nvme0n1p1): re-mounted.
Opts: . Quota mode: journalled.
2024-04-26T16:02:14.162268Z WARNING minijail0[4475]: libminijail[4475]: failed to create
a ruleset: Function not implemented
2024-04-26T16:02:14.162269Z WARNING minijail0[4478]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:02:14.162322Z WARNING minijail0[4475]: libminijail[4475]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:02:14.162325Z WARNING minijail0[4478]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
```

```
2024-04-26T16:02:14.162343Z INFO minijail0[4478]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFER: false
2024-04-26T16:02:14.732536Z INFO vm_cicerone[4486]: Server listening on
vsock:4294967295:8889, unix:///run/vm_cicerone/client/host.sock
2024-04-26T16:02:14.734393Z INFO vm_cicerone[4486]: Server listening on
vsock:4294967295:7778
2024-04-26T16:02:14.743594Z INFO vm_cicerone[4486]: Server listening on
vsock:4294967295:7779
2024-04-26T16:02:14.745469Z INFO vm_cicerone[4486]: Started tremplin grpc server
2024-04-26T16:02:14.816179Z INFO minijail0[4515]: libminijail[4515]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:02:15.130482Z INFO crash_reporter[4136]: Finishing crash. Meta file:
/proc/self/fd/10/chrome.20240426.160212.67534.1061.meta
2024-04-26T16:02:16.626835Z ERR bluetoothd[750]: No default adapter. Skip setting quality
debug.
2024-04-26T16:02:17.150628Z ERR arc-kmsg-logger[3892]: vdc: Failed: Status(-8): '0: '
2024-04-26T16:02:17.156836Z ERR arc-kmsg-logger[3892]: init: Failure (reboot suppressed):
init_user0_failed
2024-04-26T16:02:17.235928Z ERR arc-kmsg-logger[3892]: init: Could not load single
persistent property file, trying legacy directory: Unable to read persistent property
file: open() failed: No such file or directory
2024-04-26T16:02:17.235937Z ERR arc-kmsg-logger[3892]: init: Unable to load legacy
persistent properties: Unable to open persistent property directory "/data/property": No
such file or directory
2024-04-26T16:02:17.358257Z ERR arc-kmsg-logger[3892]: init: Could not start service
'vendor.hwcomposer-2-1' as part of class 'hal': File
/vendor/bin/hw/android.hardware.graphics.composer@2.1-service-cheets(labeled
"u:object_r:vendor_file:s0") has incorrect label or no domain transition from u:r:init:s0
to another SELinux domain defined. Have you configured your service correctly?
https://source.android.com/security/selinux/device-
policy#label_new_services_and_address_denials
2024-04-26T16:02:17.358342Z ERR arc-kmsg-logger[3892]: init: couldn't write 32 to
/dev/cpuset/camera-daemon/tasks: No such file or directory
2024-04-26T16:02:17.358348Z ERR arc-kmsg-logger[3892]: init: failed to set pid 32
ioprio=1,4: Operation not permitted
2024-04-26T16:02:17.402158Z ERR arc-kmsg-logger[3892]: init: failed to set pid 34
ioprio=1,4: Operation not permitted
2024-04-26T16:02:17.402547Z ERR arc-kmsg-logger[3892]: init: failed to set pid 33
ioprio=1,4: Operation not permitted
2024-04-26T16:02:17.402555Z ERR arc-kmsg-logger[3892]: init: failed to set pid 36
ioprio=1,4: Operation not permitted
2024-04-26T16:02:17.402908Z ERR arc-kmsg-logger[3892]: init: failed to set pid 31
ioprio=1,4: Operation not permitted
2024-04-26T16:02:17.415825Z ERR arc-kmsg-logger[3892]: init: failed to set pid 35
ioprio=1,4: Operation not permitted
2024-04-26T16:02:17.435832Z ERR arc-kmsg-logger[3892]: init: failed to set pid 40
ioprio=1,4: Operation not permitted
2024-04-26T16:02:17.620713Z ERR arc-kmsg-logger[3892]: init: failed to set pid 42
ioprio=1,4: Operation not permitted
2024-04-26T16:02:17.684548Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.health@1.0::IHealth/default
2024-04-26T16:02:17.695463Z ERR arc-kmsg-logger[3892]: android.hardware.health@2.0-impl:
wakealarm_init: timerfd_create failed
2024-04-26T16:02:17.875278Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:17.883412Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:18.043138Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.thermal@1.1::IThermal/default
2024-04-26T16:02:19.635632Z ERR bluetoothd[750]: No default adapter. Skip setting quality
debug.
2024-04-26T16:02:22.204251Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.graphics.composer@2.1::IComposer/default
2024-04-26T16:02:23.367407Z ERR arc-kmsg-logger[3892]: init: No such service 'bootanim'
for ctl.start
2024-04-26T16:02:23.615512Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:02:23.619309Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
```

```
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:02:23.619357Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T16:02:23.619372Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T16:02:23.619932Z INFO dlcservice[1365]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T16:02:23.620943Z WARNING cras_server[1439]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:02:23.621206Z ERR cras_server[1439]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T16:02:23.621242Z ERR cras_server[1439]: download_supported_dlc: retry 2 times
2024-04-26T16:02:23.625966Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:23.747289Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.audio@4.0::IDevicesFactory/default
2024-04-26T16:02:23.754877Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.audio@2.0::IDevicesFactory/msd
2024-04-26T16:02:23.770946Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.audio.effect@4.0::IEffectsFactory/default
2024-04-26T16:02:23.962236Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.audio.effect@4.0::IEffectsFactory/default
2024-04-26T16:02:26.643377Z INFO root[4677]: fydeos-license-utils get disk /dev/nvme0n1
serial by lsblk
2024-04-26T16:02:26.650151Z INFO root[4678]: fydeos-license-utils get fix id by disk
serial
2024-04-26T16:02:26.901162Z INFO minijail0[4694]: libminijail[4694]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:02:26.903956Z WARNING minijail0[4694]: libminijail[4694]: failed to create
a ruleset: Function not implemented
2024-04-26T16:02:26.904276Z WARNING minijail0[4694]: libminijail[4694]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:02:26.905887Z WARNING minijail0[4695]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:02:26.908192Z WARNING minijail0[4695]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:02:26.909667Z INFO minijail0[4695]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:02:26.970884Z ERR hardware_verifier[4696]: Failed to read the verification
payload file.
2024-04-26T16:02:26.971198Z ERR hardware_verifier[4696]: Failed to read the verification
payload file.
2024-04-26T16:02:26.985683Z INFO minijail0[4694]: libminijail[4694]: child process 4695
exited with status 2
2024-04-26T16:02:27.007886Z NOTICE hardware_verifier[4699]: hardware_verifier exits with
status 2.
2024-04-26T16:02:34.435488Z INFO kernel: [ 113.733100] capability: warning: `main' uses
32-bit capabilities (legacy support in use)
2024-04-26T16:02:35.799622Z ERR arc-kmsg-logger[3892]: selinux: avc: denied { set } for
property=ro.wait_for_property_service pid=16 uid=0 gid=0 scontext=u:r:cros_arc_setup:s0
tcontext=u:object_r:default_prop:s0 tclass=property_service permissive=1
2024-04-26T16:02:35.799664Z ERR arc-kmsg-logger[3892]:
2024-04-26T16:02:35.801683Z ERR arc-kmsg-logger[3892]: selinux: avc: denied { set } for
property=ro.serialno pid=16 uid=0 gid=0 scontext=u:r:cros_arc_setup:s0
tcontext=u:object_r:serialno_prop:s0 tclass=property_service permissive=1
2024-04-26T16:02:35.801696Z ERR arc-kmsg-logger[3892]:
2024-04-26T16:02:35.802511Z ERR arc-kmsg-logger[3892]: selinux: avc: denied { set } for
property=ro.vendor.arc_boot_type pid=16 uid=0 gid=0 scontext=u:r:cros_arc_setup:s0
tcontext=u:object_r:vendor_default_prop:s0 tclass=property_service permissive=1
2024-04-26T16:02:35.802525Z ERR arc-kmsg-logger[3892]:
2024-04-26T16:02:35.884189Z INFO kernel: [ 115.190247] tun: Universal TUN/TAP device
driver, 1.6
2024-04-26T16:02:35.903254Z ERR arc-kmsg-logger[3892]: init: Init cannot set
'ro.persistent_properties.ready' to 'true': Read-only property was already set
2024-04-26T16:02:35.969149Z INFO kernel: [ 115.269550] IPv6: ADDRCONF(NETDEV_CHANGE):
vetharc0: link becomes ready
2024-04-26T16:02:35.969323Z INFO kernel: [ 115.273467] IPv6: ADDRCONF(NETDEV_CHANGE):
arc0: link becomes ready
```

```
2024-04-26T16:02:36.099152Z INFO kernel: [ 115.402347] arcbr0: port 1(vetharc0) entered blocking state
2024-04-26T16:02:36.099186Z INFO kernel: [ 115.405191] arcbr0: port 1(vetharc0) entered disabled state
2024-04-26T16:02:36.103128Z INFO kernel: [ 115.408816] device vetharc0 entered promiscuous mode
2024-04-26T16:02:36.108314Z INFO kernel: [ 115.412000] arcbr0: port 1(vetharc0) entered blocking state
2024-04-26T16:02:36.108349Z INFO kernel: [ 115.414348] arcbr0: port 1(vetharc0) entered forwarding state
2024-04-26T16:02:36.154459Z ERR arc-kmsg-logger[3892]: init: Could not start service 'flash_recovery' as part of class 'main': Cannot find '/system/bin/install-recovery.sh': No such file or directory
2024-04-26T16:02:36.174793Z ERR arc-kmsg-logger[3892]: init: couldn't write 112 to /dev/cpuset/camera-daemon/tasks: No such file or directory
2024-04-26T16:02:36.175046Z ERR arc-kmsg-logger[3892]: init: failed to set pid 112 ioprio=1,4: Operation not permitted
2024-04-26T16:02:36.243732Z ERR arc-kmsg-logger[3892]: init: failed to set pid 118 ioprio=1,4: Operation not permitted
2024-04-26T16:02:36.302472Z ERR arc-kmsg-logger[3892]: init: failed to set pid 117 ioprio=1,4: Operation not permitted
2024-04-26T16:02:36.346704Z ERR arc-kmsg-logger[3892]: init: failed to set pid 124 ioprio=1,4: Operation not permitted
2024-04-26T16:02:36.356042Z ERR arc-kmsg-logger[3892]: init: failed to set pid 120 ioprio=1,4: Operation not permitted
2024-04-26T16:02:36.414342Z ERR arc-kmsg-logger[3892]: init: Failed to open file '/d/mmc0/mmc0:0001/ext_csd': No such file or directory
2024-04-26T16:02:36.550880Z ERR arc-kmsg-logger[3892]: init: failed to set pid 145 ioprio=1,4: Operation not permitted
2024-04-26T16:02:36.614712Z INFO kernel: [ 115.918608] IPv6: ADDRCONF(NETDEV_CHANGE): eth0: link becomes ready
2024-04-26T16:02:36.627413Z INFO kernel: [ 115.926501] arc_eth0: port 1(vetheth0) entered blocking state
2024-04-26T16:02:36.627443Z INFO kernel: [ 115.933102] arc_eth0: port 1(vetheth0) entered disabled state
2024-04-26T16:02:36.657165Z INFO kernel: [ 115.961156] device vetheth0 entered promiscuous mode
2024-04-26T16:02:36.663109Z INFO kernel: [ 115.966385] arc_eth0: port 1(vetheth0) entered blocking state
2024-04-26T16:02:36.663140Z INFO kernel: [ 115.969039] arc_eth0: port 1(vetheth0) entered forwarding state
2024-04-26T16:02:36.689097Z ERR arc-kmsg-logger[3892]: init: failed to set pid 149 ioprio=1,4: Operation not permitted
2024-04-26T16:02:36.901774Z INFO kernel: [ 116.199929] ESDFS-fs (esdfs): mounted on top of /opt/google/containers/android/rootfs/android-data/data/media type ext4
2024-04-26T16:02:36.901808Z INFO kernel: [ 116.205750] ESDFS-fs (esdfs): mounted on top of /opt/google/containers/android/rootfs/android-data/data/media type ext4
2024-04-26T16:02:36.937735Z INFO kernel: [ 116.212180] ESDFS-fs (esdfs): mounted on top of /opt/google/containers/android/rootfs/android-data/data/media type ext4
2024-04-26T16:02:37.052698Z ERR arc-kmsg-logger[3892]: init: Could not find service hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:37.052979Z ERR arc-kmsg-logger[3892]: init: Could not find service hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:37.065471Z INFO minijail0[4850]: libminijail[4850]: applying policy for default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:02:37.068081Z WARNING minijail0[4850]: libminijail[4850]: failed to create a ruleset: Function not implemented
2024-04-26T16:02:37.068178Z WARNING minijail0[4850]: libminijail[4850]: Landlock is not supported by the current kernel: Function not implemented
2024-04-26T16:02:37.079965Z WARNING minijail0[4860]: libminijail[4860]: failed to create a ruleset: Function not implemented
2024-04-26T16:02:37.080072Z WARNING minijail0[4860]: libminijail[4860]: Landlock is not supported by the current kernel: Function not implemented
2024-04-26T16:02:37.080085Z INFO minijail0[4860]: libminijail[4860]: Landlock support for LANDLOCK_ACCESS_FS_REFER: false
2024-04-26T16:02:37.095384Z INFO minijail0[4856]: libminijail[4856]: applying policy for default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:02:37.096205Z WARNING minijail0[4856]: libminijail[4856]: failed to create a ruleset: Function not implemented
```



```
2024-04-26T16:02:37.096270Z WARNING minijail0[4862]: libminijail[4862]: failed to create
a ruleset: Function not implemented
2024-04-26T16:02:37.096324Z WARNING minijail0[4856]: libminijail[4856]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:02:37.096325Z WARNING minijail0[4862]: libminijail[4862]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:02:37.096341Z INFO minijail0[4862]: libminijail[4862]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:02:37.130135Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:37.130155Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:37.133985Z INFO minijail0[4857]: libminijail[4857]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:02:37.135604Z WARNING minijail0[4857]: libminijail[4857]: failed to create
a ruleset: Function not implemented
2024-04-26T16:02:37.135658Z WARNING minijail0[4857]: libminijail[4857]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:02:37.135933Z WARNING minijail0[4864]: libminijail[4864]: failed to create
a ruleset: Function not implemented
2024-04-26T16:02:37.135978Z WARNING minijail0[4864]: libminijail[4864]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:02:37.135995Z INFO minijail0[4864]: libminijail[4864]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:02:37.143550Z INFO minijail0[4859]: libminijail[4859]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:02:37.144490Z WARNING minijail0[4859]: libminijail[4859]: failed to create
a ruleset: Function not implemented
2024-04-26T16:02:37.144536Z WARNING minijail0[4859]: libminijail[4859]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:02:37.145232Z WARNING minijail0[4866]: libminijail[4866]: failed to create
a ruleset: Function not implemented
2024-04-26T16:02:37.145274Z WARNING minijail0[4866]: libminijail[4866]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:02:37.145288Z INFO minijail0[4866]: libminijail[4866]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:02:37.152731Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:37.258711Z INFO minijail0[4871]: libminijail[4871]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:02:37.264122Z WARNING session_manager[1034]: WARNING session_manager:
[bus.cc(644)] Bus::SendWithReplyAndBlock took 24406ms to process message:
type=method_call, path=/com/ubuntu/Upstart, interface=com.ubuntu.Upstart0_6,
member=EmitEvent
2024-04-26T16:02:37.265301Z INFO debugd[3800]: Deleting the ARC bug report backup
2024-04-26T16:02:37.284690Z WARNING u2fd[3553]: WARNING u2fd: [bus.cc(644)]
Bus::SendWithReplyAndBlock took 25020ms to process message: type=method_call,
path=/org/chromium/SessionManager, interface=org.chromium.SessionManagerInterface,
member=RetrievePrimarySession
2024-04-26T16:02:37.293260Z WARNING minijail0[4871]: libminijail[4871]: failed to create
a ruleset: Function not implemented
2024-04-26T16:02:37.293302Z WARNING minijail0[4871]: libminijail[4871]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:02:37.295884Z WARNING minijail0[4883]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:02:37.296238Z WARNING minijail0[4883]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:02:37.296263Z INFO minijail0[4883]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:02:37.300171Z INFO session_manager[1034]: INFO session_manager:
[resilient_policy_store.cc(140)] Deleted old device policy file:
/var/lib/devicesettings/policy.14
2024-04-26T16:02:37.307494Z WARNING usb_bouncer[4414]: Bus::SendWithReplyAndBlock took
24552ms to process message: type=method_call, path=/org/chromium/SessionManager,
interface=org.chromium.SessionManagerInterface, member=RetrievePrimarySession
2024-04-26T16:02:37.330724Z INFO minijail0[4880]: libminijail[4880]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:02:37.430509Z INFO kernel: [ 116.734483] IPv6: ADDRCONF(NETDEV_CHANGE):
veth2: link becomes ready
```

2024-04-26T16:02:37.433236Z INFO session_manager[1034]: INFO session_manager: [policy_store.cc(85)] Persisted policy to disk, path: /var/lib/devicesettings/policy.17

2024-04-26T16:02:37.455647Z INFO u2fd[3553]: INFO u2fd: [u2f_daemon.cc(367)] Requested Mode: Policy[unset], force_u2f[0], force_g2f[0]

2024-04-26T16:02:37.455702Z INFO u2fd[3553]: INFO u2fd: [u2f_daemon.cc(381)] Mode: Disabled (not supported)

2024-04-26T16:02:37.484637Z INFO usb_bouncer[4414]: Reporting metrics for /devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2

2024-04-26T16:02:37.486608Z INFO usb_bouncer[4414]: Reporting metrics for /devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-2/2-2.1

2024-04-26T16:02:37.489740Z INFO usb_bouncer[4414]: Reporting metrics for /devices/pci0000:00/0000:00:11.0/0000:02:03.0/usb1

2024-04-26T16:02:37.491492Z INFO usb_bouncer[4414]: Reporting metrics for /devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-1

2024-04-26T16:02:37.508298Z INFO usb_bouncer[4414]: Reporting metrics for /devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-2

2024-04-26T16:02:37.565582Z INFO minijail0[4891]: libminijail[4891]: applying policy for default runtime: /etc/security/minijail/v0.bin

2024-04-26T16:02:37.568251Z WARNING minijail0[4891]: libminijail[4891]: failed to create a ruleset: Function not implemented

2024-04-26T16:02:37.568352Z WARNING minijail0[4891]: libminijail[4891]: Landlock is not supported by the current kernel: Function not implemented

2024-04-26T16:02:37.569407Z WARNING minijail0[4911]: libminijail[4911]: failed to create a ruleset: Function not implemented

2024-04-26T16:02:37.569426Z WARNING minijail0[4911]: libminijail[4911]: Landlock is not supported by the current kernel: Function not implemented

2024-04-26T16:02:37.569445Z INFO minijail0[4911]: libminijail[4911]: Landlock support for LANDLOCK_ACCESS_FS_REFERER: false

2024-04-26T16:02:37.705741Z ERR arc-kmsg-logger[3892]: init: Could not find service hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default

2024-04-26T16:02:37.705772Z ERR arc-kmsg-logger[3892]: init: Could not find service hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default

2024-04-26T16:02:37.705797Z ERR arc-kmsg-logger[3892]: init: Could not find service hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default

2024-04-26T16:02:37.705823Z ERR arc-kmsg-logger[3892]: init: Could not find service hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default

2024-04-26T16:02:37.705852Z ERR arc-kmsg-logger[3892]: init: Could not find service hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default

2024-04-26T16:02:37.705880Z ERR arc-kmsg-logger[3892]: init: Could not find service hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default

2024-04-26T16:02:37.705908Z ERR arc-kmsg-logger[3892]: init: Could not find service hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default

2024-04-26T16:02:37.819990Z WARNING minijail0[4861]: libminijail[4861]: failed to create a ruleset: Function not implemented

2024-04-26T16:02:37.820108Z WARNING minijail0[4861]: libminijail[4861]: Landlock is not supported by the current kernel: Function not implemented

2024-04-26T16:02:37.821251Z WARNING minijail0[4932]: libminijail[1]: failed to create a ruleset: Function not implemented

2024-04-26T16:02:37.821271Z WARNING minijail0[4932]: libminijail[1]: Landlock is not supported by the current kernel: Function not implemented

2024-04-26T16:02:37.821285Z INFO minijail0[4932]: libminijail[1]: Landlock support for LANDLOCK_ACCESS_FS_REFERER: false

2024-04-26T16:02:37.909489Z ERR arc-kmsg-logger[3892]: init: Could not find service hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default

2024-04-26T16:02:37.915300Z INFO minijail0[4919]: libminijail[4919]: applying policy for default runtime: /etc/security/minijail/v0.bin

2024-04-26T16:02:37.916724Z WARNING minijail0[4919]: libminijail[4919]: failed to create a ruleset: Function not implemented

2024-04-26T16:02:37.916725Z WARNING minijail0[4941]: libminijail[4941]: failed to create a ruleset: Function not implemented

2024-04-26T16:02:37.916758Z WARNING minijail0[4919]: libminijail[4919]: Landlock is not supported by the current kernel: Function not implemented

2024-04-26T16:02:37.916758Z WARNING minijail0[4941]: libminijail[4941]: Landlock is not supported by the current kernel: Function not implemented

2024-04-26T16:02:37.916773Z INFO minijail0[4941]: libminijail[4941]: Landlock support for LANDLOCK_ACCESS_FS_REFERER: false

2024-04-26T16:02:37.979890Z ERR arc-kmsg-logger[3892]: init: Could not find service hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default

2024-04-26T16:02:38.046787Z INFO minijail0[4868]: libminijail[4868]: applying policy for

```
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:02:38.166705Z INFO minijail0[4934]: libminijail[4934]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:02:38.167537Z WARNING minijail0[4934]: libminijail[4934]: failed to create
a ruleset: Function not implemented
2024-04-26T16:02:38.167576Z WARNING minijail0[4934]: libminijail[4934]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:02:38.167727Z WARNING minijail0[4955]: libminijail[4955]: failed to create
a ruleset: Function not implemented
2024-04-26T16:02:38.167775Z WARNING minijail0[4955]: libminijail[4955]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:02:38.167792Z INFO minijail0[4955]: libminijail[4955]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:02:38.185235Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:38.298182Z INFO minijail0[4922]: libminijail[4922]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:02:38.299286Z WARNING minijail0[4922]: libminijail[4922]: failed to create
a ruleset: Function not implemented
2024-04-26T16:02:38.299303Z WARNING minijail0[4922]: libminijail[4922]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:02:38.299387Z WARNING minijail0[4966]: libminijail[4966]: failed to create
a ruleset: Function not implemented
2024-04-26T16:02:38.299405Z WARNING minijail0[4966]: libminijail[4966]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:02:38.299422Z INFO minijail0[4966]: libminijail[4966]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:02:38.350681Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.health@2.0::IHealth/default
2024-04-26T16:02:38.350998Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:38.688549Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:38.688585Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.usb.gadget@1.0::IUsbGadget/default
2024-04-26T16:02:38.688612Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:38.704169Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:38.884423Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.gatekeeper@1.0::IGatekeeper/default
2024-04-26T16:02:38.884455Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:38.890646Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:38.890969Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:39.035165Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:39.035194Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:39.118847Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:39.118873Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:39.262333Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:39.265963Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:39.371774Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:39.462072Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:39.468765Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:39.584818Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:39.596169Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
```

```
2024-04-26T16:02:39.696557Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:39.721456Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:39.873580Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:39.873603Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:39.910496Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.keymaster@4.0::IKeymasterDevice/default
2024-04-26T16:02:40.015462Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.015484Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.137868Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.154593Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.237249Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.248942Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.344736Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.379596Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.469130Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.474106Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.590231Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.591547Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.690812Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.736854Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.800694Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.811159Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.981947Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:40.983685Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:41.088115Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:41.088140Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:41.203800Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:41.212179Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:41.302869Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:41.306816Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:41.415585Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:41.415867Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface vendor.google_arc.arcbridge@1.0::IArcBridgeService/default
2024-04-26T16:02:41.617482Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.camera.provider@2.4::ICameraProvider/legacy/0
2024-04-26T16:02:41.617512Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.camera.provider@2.4::ICameraProvider/legacy/0
2024-04-26T16:02:42.428738Z INFO iioservice[712]: INFO iioservice: [iio_sensor.cc(56)]
(2) Request(): Received SensorService from Mojo Service Manager
2024-04-26T16:02:42.432601Z INFO iioservice[712]: INFO iioservice:
```

```
[sensor_service_impl.cc(417)] (2) OnSensorServiceDisconnect(): SensorDevice disconnected.
ReceiverId: 4
2024-04-26T16:02:43.150522Z INFO cros_camera_service[3646]: BindOnThread(): Bridge ready
2024-04-26T16:02:43.809129Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.camera.provider@2.4::ICameraProvider/external/0
2024-04-26T16:02:47.642207Z WARNING kernel: [ 127.019873] NOHZ tick-stop error: Non-RCU
local softirq work is pending, handler #10!!!
2024-04-26T16:02:51.765546Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.power@1.0::IPower/default
2024-04-26T16:02:53.997295Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.light@2.0::ILight/default
2024-04-26T16:02:56.690157Z INFO root[5148]: fydeos-license-utils get disk /dev/nvme0n1
serial by lsblk
2024-04-26T16:02:56.730310Z INFO root[5149]: fydeos-license-utils get fix id by disk
serial
2024-04-26T16:02:58.356510Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.soundtrigger@2.0::ISoundTriggerHw/default
2024-04-26T16:02:58.371787Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.health@2.0::IHealth/default
2024-04-26T16:02:58.869471Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.vibrator@1.0::IVibrator/default
2024-04-26T16:02:58.869616Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.vibrator@1.0::IVibrator/default
2024-04-26T16:02:58.869775Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.vibrator@1.0::IVibrator/default
2024-04-26T16:02:58.875130Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.ir@1.0::IConsumerIr/default
2024-04-26T16:02:59.133951Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.vr@1.0::IVr/default
2024-04-26T16:02:59.326358Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.oemlock@1.0::IOemLock/default
2024-04-26T16:03:00.062497Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.thermal@1.0::IThermal/default
2024-04-26T16:03:00.137686Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.contexthub@1.0::IContexthub/default
2024-04-26T16:03:00.312236Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.weaver@1.0::IWeaver/default
2024-04-26T16:03:00.318239Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.authsecret@1.0::IAuthSecret/default
2024-04-26T16:03:01.850414Z INFO permission_broker[1313]:
ProcessPath(/dev/bus/usb/002/004)
2024-04-26T16:03:02.135746Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.gnss@1.0::IGnss/default
2024-04-26T16:03:02.142057Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.gnss@1.1::IGnss/default
2024-04-26T16:03:02.565547Z INFO permission_broker[1313]: AllowUsbDeviceRule: ALLOW
2024-04-26T16:03:02.565718Z INFO permission_broker[1313]: AllowTtyDeviceRule: IGNORE
2024-04-26T16:03:02.570329Z INFO permission_broker[1313]: Found claimed interface with
driver: btusb
2024-04-26T16:03:02.572875Z INFO permission_broker[1313]: Found claimed interface with
driver: btusb
2024-04-26T16:03:02.576613Z INFO permission_broker[1313]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T16:03:02.576751Z INFO permission_broker[1313]: Verdict for
/dev/bus/usb/002/004: DENY
2024-04-26T16:03:02.577118Z INFO permission_broker[1313]:
ProcessPath(/dev/bus/usb/002/002)
2024-04-26T16:03:02.773367Z INFO kernel: [ 142.257034] binder: undelivered
TRANSACTION_COMPLETE
2024-04-26T16:03:02.773405Z INFO kernel: [ 142.259524] binder: undelivered transaction
7780, process died.
2024-04-26T16:03:03.637142Z INFO permission_broker[1313]: AllowUsbDeviceRule: ALLOW
2024-04-26T16:03:03.637295Z INFO permission_broker[1313]: AllowTtyDeviceRule: IGNORE
2024-04-26T16:03:03.644883Z INFO permission_broker[1313]: Found claimed interface with
driver: usbhid
2024-04-26T16:03:03.651332Z INFO permission_broker[1313]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T16:03:03.651507Z INFO permission_broker[1313]: Verdict for
/dev/bus/usb/002/002: DENY
```

```
2024-04-26T16:03:07.093422Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface hardware.google.media.c2@1.0::IComponentStore/software
2024-04-26T16:03:07.408804Z INFO session_manager[1034]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting arc-booted Upstart signal
2024-04-26T16:03:07.414366Z ERR arc-kmsg-logger[3892]: selinux: SELinux: Could not stat
/sys/kernel/debug/tracing/instances/wifi: No such file or directory.
2024-04-26T16:03:07.414370Z ERR arc-kmsg-logger[3892]:
2024-04-26T16:03:07.516889Z INFO minijail0[5433]: libminijail[5433]: applying policy for
default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:03:07.526923Z WARNING minijail0[5444]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:03:07.527071Z WARNING minijail0[5444]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:03:07.527086Z INFO minijail0[5444]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
2024-04-26T16:03:07.527229Z WARNING minijail0[5433]: libminijail[5433]: failed to create
a ruleset: Function not implemented
2024-04-26T16:03:07.527244Z WARNING minijail0[5433]: libminijail[5433]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:03:10.267398Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.secure_element@1.0::ISecureElement/eSE1
2024-04-26T16:03:10.350490Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.secure_element@1.0::ISecureElement/SIM1
2024-04-26T16:03:19.769286Z WARNING kernel: [ 159.374872] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:03:19.769358Z WARNING kernel: [ 159.380128] audit: audit_lost=3
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:03:19.769364Z ERR kernel: [ 159.383282] audit: backlog limit exceeded
2024-04-26T16:03:23.701860Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:03:23.709224Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:03:23.709253Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T16:03:23.709275Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T16:03:23.710720Z INFO dlcservice[1365]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T16:03:23.711540Z WARNING cras_server[1439]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:03:23.711778Z ERR cras_server[1439]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T16:03:23.711798Z ERR cras_server[1439]: download_supported_dlc: retry 3 times
2024-04-26T16:03:39.718175Z WARNING kernel: [ 179.462519] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:03:39.718265Z WARNING kernel: [ 179.475599] audit: audit_lost=4
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:03:39.718272Z ERR kernel: [ 179.478753] audit: backlog limit exceeded
2024-04-26T16:03:41.080553Z INFO vm_cicerone[4486]: System timezone changed, updating
container timezones
2024-04-26T16:04:18.970658Z INFO kernel: [ 218.826532] binder: undelivered transaction
60825, process died.
2024-04-26T16:04:18.970701Z INFO kernel: [ 218.857307] binder: undelivered transaction
60826, process died.
2024-04-26T16:04:18.970707Z INFO kernel: [ 218.875697] binder: undelivered transaction
60829, process died.
2024-04-26T16:04:19.016991Z INFO kernel: [ 218.886427] binder: undelivered transaction
60842, process died.
2024-04-26T16:04:24.138612Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:04:24.149443Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:04:24.149474Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T16:04:24.149491Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(107)]
```

```
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T16:04:24.149784Z INFO dlcservice[1365]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T16:04:24.150518Z WARNING cras_server[1439]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:04:24.150590Z ERR cras_server[1439]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T16:04:24.150607Z ERR cras_server[1439]: download_supported_dlc: retry 4 times
2024-04-26T16:04:30.325933Z WARNING kernel: [ 230.179948] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:04:30.325998Z WARNING kernel: [ 230.183561] audit: audit_lost=5
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:04:30.326037Z ERR kernel: [ 230.222667] audit: backlog limit exceeded
2024-04-26T16:04:30.337155Z WARNING kernel: [ 230.283953] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:04:30.337245Z WARNING kernel: [ 230.289012] audit: audit_lost=6
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:04:30.383771Z ERR kernel: [ 230.294530] audit: backlog limit exceeded
2024-04-26T16:04:30.406504Z WARNING kernel: [ 230.341899] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:04:30.406528Z WARNING kernel: [ 230.358100] audit: audit_lost=7
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:04:30.413054Z ERR kernel: [ 230.368093] audit: backlog limit exceeded
2024-04-26T16:04:37.944104Z WARNING kernel: [ 237.901900] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:04:37.944159Z WARNING kernel: [ 237.913829] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:04:37.944165Z WARNING kernel: [ 237.928680] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:04:37.944168Z WARNING kernel: [ 237.928687] audit: audit_lost=8
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:04:37.944171Z ERR kernel: [ 237.928690] audit: backlog limit exceeded
2024-04-26T16:04:37.944174Z WARNING kernel: [ 237.928693] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:04:37.944177Z WARNING kernel: [ 237.928695] audit: audit_lost=9
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:04:37.944182Z ERR kernel: [ 237.928697] audit: backlog limit exceeded
2024-04-26T16:04:37.949141Z WARNING kernel: [ 237.933877] audit: audit_lost=10
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:04:37.949174Z ERR kernel: [ 237.933884] audit: backlog limit exceeded
2024-04-26T16:04:50.545882Z WARNING kernel: [ 250.550001] audit_log_start: 95 callbacks
suppressed
2024-04-26T16:04:50.545925Z WARNING kernel: [ 250.550007] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:04:50.552413Z WARNING kernel: [ 250.556237] audit: audit_lost=43
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:04:50.554341Z ERR kernel: [ 250.562091] audit: backlog limit exceeded
2024-04-26T16:04:52.848290Z INFO kernel: [ 252.826210] binder_alloc: 5557:
binder_alloc_buf size 1056768 failed, no address space
2024-04-26T16:04:52.848323Z INFO kernel: [ 252.851124] binder_alloc: allocated: 7840
(num: 22 largest: 2896), free: 1032544 (num: 6 largest: 1027136)
2024-04-26T16:04:52.881832Z INFO kernel: [ 252.865380] binder: 5786:7936 transaction
failed 29201/-28, size 1056768-0 line 3061
2024-04-26T16:04:59.363559Z NOTICE activate_date[8565]: activate_date failed.
2024-04-26T16:05:08.039964Z WARNING kernel: [ 268.070364] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:05:08.039997Z WARNING kernel: [ 268.074955] audit: audit_lost=44
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:05:08.043447Z ERR kernel: [ 268.083731] audit: backlog limit exceeded
2024-04-26T16:05:09.969060Z WARNING kernel: [ 269.960093] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:05:09.969093Z WARNING kernel: [ 269.986266] audit: audit_lost=45
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:05:09.969097Z ERR kernel: [ 269.995645] audit: backlog limit exceeded
2024-04-26T16:05:24.290931Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:05:24.322871Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
```

```
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:05:24.322915Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T16:05:24.322936Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T16:05:24.335992Z INFO dlcservice[1365]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T16:05:24.397545Z WARNING cras_server[1439]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:05:24.397602Z ERR cras_server[1439]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T16:05:24.397618Z ERR cras_server[1439]: download_supported_dlc: retry 5 times
2024-04-26T16:05:30.010780Z WARNING kernel: [ 290.082749] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:05:30.010815Z WARNING kernel: [ 290.089204] audit: audit_lost=46
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:05:30.025389Z ERR kernel: [ 290.108084] audit: backlog limit exceeded
2024-04-26T16:05:49.957232Z WARNING kernel: [ 310.052892] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:05:49.957266Z WARNING kernel: [ 310.064022] audit: audit_lost=47
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:05:49.960556Z ERR kernel: [ 310.068211] audit: backlog limit exceeded
2024-04-26T16:06:09.886605Z WARNING kernel: [ 330.002495] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:06:09.886639Z WARNING kernel: [ 330.011015] audit: audit_lost=48
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:06:09.892317Z ERR kernel: [ 330.018199] audit: backlog limit exceeded
2024-04-26T16:06:10.720834Z NOTICE auditd[458]: Audit daemon rotating log files
2024-04-26T16:06:16.458487Z INFO periodic_scheduler[1276]: crash_sender: running
/sbin/crash_sender
2024-04-26T16:06:16.776559Z INFO crash_sender[9979]: Checking metadata: /run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/system_server.20240426.154418.81752.
553004.meta
2024-04-26T16:06:16.777614Z INFO crash_sender[9979]: Removing: Not an official OS version
2024-04-26T16:06:16.791297Z INFO crash_sender[9979]: Checking metadata: /run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65/chrome.20240426.160212.67534.1061.me
ta
2024-04-26T16:06:16.791553Z INFO crash_sender[9979]: Removing: Not an official OS version
2024-04-26T16:06:16.805498Z INFO crash_sender[9979]: Checking metadata:
/var/spool/crash/kernel.20240426.160138.56522.0.meta
2024-04-26T16:06:16.805792Z INFO crash_sender[9979]: Removing: Not an official OS version
2024-04-26T16:06:16.890613Z INFO periodic_scheduler[1276]: crash_sender: job completed
2024-04-26T16:06:19.863484Z WARNING kernel: [ 339.995420] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:06:19.863516Z WARNING kernel: [ 339.998356] audit: audit_lost=49
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:06:19.872374Z ERR kernel: [ 340.008104] audit: backlog limit exceeded
2024-04-26T16:06:24.463295Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:06:24.468154Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:06:24.468273Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T16:06:24.468292Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T16:06:24.468588Z INFO dlcservice[1365]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T16:06:24.469735Z WARNING cras_server[1439]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:06:24.469773Z ERR cras_server[1439]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T16:06:24.469787Z ERR cras_server[1439]: download_supported_dlc: retry 6 times
2024-04-26T16:06:37.103297Z INFO kernel: [ 357.244895] binder_alloc: 10100:
binder_alloc_buf, no vma
2024-04-26T16:06:37.103363Z INFO kernel: [ 357.250724] binder: 4781:5103 transaction
failed 29189/-3, size 76-0 line 3061
2024-04-26T16:06:39.641984Z INFO cryptohomed[954]: AuthSession: timed out.
```



```
2024-04-26T16:06:49.819144Z WARNING kernel: [ 369.971422] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:06:49.819183Z WARNING kernel: [ 369.974886] audit: audit_lost=50
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:06:49.819227Z ERR kernel: [ 369.979175] audit: backlog limit exceeded
2024-04-26T16:07:24.574169Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:07:24.600932Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:07:24.600962Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T16:07:24.600979Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T16:07:24.601381Z INFO dlcservice[1365]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T16:07:24.622645Z WARNING cras_server[1439]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:07:24.622811Z ERR cras_server[1439]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T16:07:24.623413Z ERR cras_server[1439]: download_supported_dlc: retry 7 times
2024-04-26T16:08:24.687571Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:08:24.699946Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:08:24.699988Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T16:08:24.700054Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T16:08:24.700485Z INFO dlcservice[1365]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T16:08:24.701413Z WARNING cras_server[1439]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:08:24.701524Z ERR cras_server[1439]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T16:08:24.701542Z ERR cras_server[1439]: download_supported_dlc: retry 8 times
2024-04-26T16:09:07.292573Z INFO dbus-daemon[569]: [system] Activating service
name='org.chromium.MachineLearning' requested by ':1.41' (uid=1000 pid=1061
comm="/opt/google/chrome/chrome --enable-webgl-image-chr" label="u:r:chrome:s0")
(using servicehelper)
2024-04-26T16:09:07.412336Z NOTICE ml-service[11653]: Pre-start ml-service
task=mojo_service
2024-04-26T16:09:07.493328Z INFO minijail0[11658]: libminijail[11658]: applying policy
for default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:09:07.495460Z WARNING minijail0[11658]: libminijail[11658]: failed to
create a ruleset: Function not implemented
2024-04-26T16:09:07.495502Z WARNING minijail0[11658]: libminijail[11658]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:09:07.496386Z WARNING minijail0[11659]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:09:07.496431Z WARNING minijail0[11659]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:09:07.496446Z INFO minijail0[11659]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFER: false
2024-04-26T16:09:07.867695Z INFO dbus-daemon[569]: [system] Successfully activated
service 'org.chromium.MachineLearning'
2024-04-26T16:09:21.267261Z WARNING kernel: [ 521.407719] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:09:21.267441Z WARNING kernel: [ 521.416485] audit: audit_lost=51
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:09:21.267453Z ERR kernel: [ 521.449367] audit: backlog limit exceeded
2024-04-26T16:09:24.769144Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:09:24.773573Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
```

```
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:09:24.773669Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T16:09:24.773696Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T16:09:24.773982Z INFO dlcservice[1365]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T16:09:24.774727Z WARNING cras_server[1439]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:09:24.774767Z ERR cras_server[1439]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T16:09:24.774786Z ERR cras_server[1439]: download_supported_dlc: retry 9 times
2024-04-26T16:09:56.563132Z INFO kernel: [ 556.763553] binder_alloc: 10641:
binder_alloc_buf, no vma
2024-04-26T16:09:56.563160Z INFO kernel: [ 556.764919] binder: release 10641:10789
transaction 219048 out, still active
2024-04-26T16:09:56.569333Z INFO kernel: [ 556.769989] binder: undelivered
TRANSACTION_COMPLETE
2024-04-26T16:09:56.569368Z INFO kernel: [ 556.772701] binder: 4781:5155 transaction
failed 29189/-3, size 108-0 line 3061
2024-04-26T16:09:56.573243Z INFO kernel: [ 556.776985] binder_alloc: 10641:
binder_alloc_buf, no vma
2024-04-26T16:09:56.592503Z INFO kernel: [ 556.792018] binder: 4781:8031 transaction
failed 29189/-3, size 1500-0 line 3061
2024-04-26T16:09:56.592536Z INFO kernel: [ 556.795476] binder: send failed reply for
transaction 219048, target dead
2024-04-26T16:09:57.281954Z INFO kernel: [ 557.477645] binder_alloc: 10451:
binder_alloc_buf, no vma
2024-04-26T16:09:57.281989Z INFO kernel: [ 557.481581] binder: 4781:5103 transaction
failed 29189/-3, size 96-0 line 3061
2024-04-26T16:09:57.281997Z INFO kernel: [ 557.481615] binder_alloc: 10451:
binder_alloc_buf, no vma
2024-04-26T16:09:57.287168Z INFO kernel: [ 557.487737] binder: 4781:5096 transaction
failed 29189/-3, size 76-0 line 3061
2024-04-26T16:09:57.367931Z INFO kernel: [ 557.566696] binder: undelivered transaction
219040, process died.
2024-04-26T16:09:57.368088Z INFO kernel: [ 557.570892] binder: undelivered
TRANSACTION_COMPLETE
2024-04-26T16:09:57.375995Z INFO kernel: [ 557.573847] binder: undelivered transaction
219009, process died.
2024-04-26T16:09:57.376939Z INFO kernel: [ 557.580231] binder: undelivered
TRANSACTION_COMPLETE
2024-04-26T16:09:57.385416Z INFO kernel: [ 557.582871] binder: undelivered transaction
219021, process died.
2024-04-26T16:09:57.409233Z INFO kernel: [ 557.598297] binder: undelivered transaction
219041, process died.
2024-04-26T16:10:00.304742Z WARNING kernel: [ 560.485413] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:10:00.304773Z WARNING kernel: [ 560.501188] audit: audit_lost=52
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:10:00.314103Z ERR kernel: [ 560.516534] audit: backlog limit exceeded
2024-04-26T16:10:08.110158Z WARNING kernel: [ 568.299597] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:10:08.110210Z WARNING kernel: [ 568.308944] audit: audit_lost=53
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:10:08.110216Z ERR kernel: [ 568.312244] audit: backlog limit exceeded
2024-04-26T16:10:21.371153Z INFO kernel: [ 581.568763] binder: 12103:12378 transaction
failed 29189/-22, size 152-0 line 2893
2024-04-26T16:10:24.808761Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:10:24.811656Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:10:24.811959Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T16:10:24.812072Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T16:10:24.812297Z INFO dlcservice[1365]: INFO dlcservice: [metrics.cc(74)]
```

```
InstallResult metric sent:5
2024-04-26T16:10:24.813885Z WARNING cras_server[1439]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:10:24.814131Z ERR cras_server[1439]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T16:10:24.814146Z ERR cras_server[1439]: download_supported_dlc: retry 10 times
2024-04-26T16:10:42.460227Z INFO trunksd[746]: Finished saving contexts.
2024-04-26T16:10:50.069080Z INFO kernel: [ 610.270642] binder: 12103:12730 transaction
failed 29189/-22, size 152-0 line 2893
2024-04-26T16:10:54.486941Z NOTICE powerd_suspend[12996]: Going to suspend-to-RAM state:
args=-nosuspend_to_idle --wakeup_count=477
2024-04-26T16:10:54.921183Z DEBUG kernel: [ 615.129090] PM: last active wakeup source:
serio1
2024-04-26T16:10:54.931375Z NOTICE powerd_suspend[12996]: Aborting suspend, wake event
received
2024-04-26T16:10:54.950790Z NOTICE powerd_suspend[12996]: wakeup_count is 600
2024-04-26T16:10:54.963703Z NOTICE powerd_suspend[12996]: Cancel suspend at kernel
2024-04-26T16:10:54.981877Z NOTICE powerd_suspend[12996]: Resume finished
2024-04-26T16:10:56.055777Z ERR shill[784]: ERROR shill: [rtnl_message.cc(1103)] RTNL
address message does not have a valid IFA_ADDRESS
2024-04-26T16:11:01.213303Z INFO vm_cicerone[4486]: System timezone changed, updating
container timezones
2024-04-26T16:11:03.517379Z ERR kernel: [ 623.713386] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:11:03.680071Z ERR kernel: [ 623.883303] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:11:09.966346Z ERR kernel: [ 630.162891] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:11:24.861346Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:11:24.879997Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_manager.cc(106)]
GetDlc(...): Domain=dbus, Code=org.chromium.DlcServiceInterface.INVALID_DLC,
Message=Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:11:24.880246Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(128)]
Failed to install DLC=nc-ap-dlc
2024-04-26T16:11:24.880292Z ERR dlcservice[1365]: ERROR dlcservice: [dlc_service.cc(107)]
[CoreServicesAlert<install>] Failed to install DLC=nc-ap-dlc
2024-04-26T16:11:24.881386Z INFO dlcservice[1365]: INFO dlcservice: [metrics.cc(74)]
InstallResult metric sent:5
2024-04-26T16:11:24.895206Z WARNING cras_server[1439]: cras_dlc_install(nc-ap-dlc)
failed: D-Bus failure: Passed unsupported DLC=nc-ap-dlc
2024-04-26T16:11:24.895253Z ERR cras_server[1439]: download_supported_dlc: unable to
connect to dlcservice during `cras_dlc_install`.
2024-04-26T16:11:24.895267Z ERR cras_server[1439]: download_supported_dlc: failed to
install the DLC. Please check the network connection. Restart CRAS to retry.
2024-04-26T16:12:17.021813Z INFO vm_cicerone[4486]: System timezone changed, updating
container timezones
2024-04-26T16:13:01.093596Z ERR cross_healthd[1335]: Not implemented reached in void
diagnostics::UdevEventsImpl::OnHdmiChange()
2024-04-26T16:13:30.855844Z ERR cross_healthd[1335]: Not implemented reached in void
diagnostics::UdevEventsImpl::OnHdmiChange()
2024-04-26T16:15:46.311300Z ERR cross_healthd[1335]: Not implemented reached in void
diagnostics::UdevEventsImpl::OnHdmiChange()
2024-04-26T16:15:59.104567Z ERR cross_healthd[1335]: Not implemented reached in void
diagnostics::UdevEventsImpl::OnHdmiChange()
2024-04-26T16:16:15.248755Z ERR cross_healthd[1335]: Not implemented reached in void
diagnostics::UdevEventsImpl::OnHdmiChange()
2024-04-26T16:17:09.792260Z NOTICE auditd[458]: Audit daemon rotating log files
2024-04-26T16:17:22.795122Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.vibrator@1.0::IVibrator/default
2024-04-26T16:17:22.923579Z ERR kernel: [ 1003.126916] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:17:22.941120Z ERR kernel: [ 1003.144127] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:17:22.971319Z ERR kernel: [ 1003.169375] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:18:06.286399Z ERR cross_healthd[1335]: Not implemented reached in void
diagnostics::UdevEventsImpl::OnHdmiChange()
```

```
2024-04-26T16:18:08.190495Z WARNING kernel: [ 1048.390440] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:18:08.190540Z WARNING kernel: [ 1048.395338] audit: audit_lost=54
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:18:08.190547Z ERR kernel: [ 1048.398607] audit: backlog limit exceeded
2024-04-26T16:20:55.233408Z INFO vm_cicerone[4486]: System timezone changed, updating
container timezones
2024-04-26T16:21:06.486866Z INFO rsyslogd[468]: -- MARK --
2024-04-26T16:23:48.808429Z ERR kernel: [ 1389.012517] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:24:28.221119Z ERR cryptohomed[954]: Failed to call method:
org.chromium.ChromeFeaturesServiceInterface.IsFeatureEnabled: object_path=
/org/chromium/ChromeFeaturesService: org.freedesktop.DBus.Error.InvalidArgs: Unexpected
feature name.
2024-04-26T16:24:28.230540Z WARNING cryptohomed[954]: No valid keysets on disk for
521ac76c473ca5ff9c03ccc71d8ad8646690ad65
2024-04-26T16:24:28.425646Z ERR cryptohomed[954]: Failed to call method:
org.chromium.ChromeFeaturesServiceInterface.IsFeatureEnabled: object_path=
/org/chromium/ChromeFeaturesService: org.freedesktop.DBus.Error.InvalidArgs: Unexpected
feature name.
2024-04-26T16:24:28.425797Z WARNING cryptohomed[954]: No valid keysets on disk for
521ac76c473ca5ff9c03ccc71d8ad8646690ad65
2024-04-26T16:24:35.531850Z INFO root[19387]: fydeos-license-utils get disk /dev/nvme0n1
serial by lsblk
2024-04-26T16:24:35.535202Z INFO root[19388]: fydeos-license-utils get fix id by disk
serial
2024-04-26T16:24:42.678304Z INFO ml_service[11661]: SIGKILL sent to the worker process: 4
2024-04-26T16:24:58.063620Z ERR cros_healthd[1335]: Not implemented reached in void
diagnostics::UdevEventsImpl::OnHdmiChange()
2024-04-26T16:25:12.884220Z ERR cros_healthd[1335]: Not implemented reached in void
diagnostics::UdevEventsImpl::OnHdmiChange()
2024-04-26T16:25:55.923840Z ERR shill[784]: ERROR shill: [rtnl_message.cc(1103)] RTNL
address message does not have a valid IFA_ADDRESS
2024-04-26T16:26:11.217787Z INFO kernel: [ 1531.351282] binder_alloc: 20234:
binder_alloc_buf, no vma
2024-04-26T16:26:11.217825Z INFO kernel: [ 1531.422008] binder: 4781:5103 transaction
failed 29189/-3, size 76-0 line 3061
2024-04-26T16:26:26.397651Z ERR kernel: [ 1546.599766] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:26:51.969685Z WARNING kernel: [ 1572.163849] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:26:51.969754Z WARNING kernel: [ 1572.168304] audit: audit_lost=55
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:26:51.969759Z ERR kernel: [ 1572.172887] audit: backlog limit exceeded
2024-04-26T16:27:10.902201Z INFO kernel: [ 1591.102130] binder_alloc: 4781:
binder_alloc_buf size 2083888 failed, no address space
2024-04-26T16:27:10.902257Z INFO kernel: [ 1591.105755] binder_alloc: allocated: 72 (num:
6 largest: 32), free: 1040312 (num: 1 largest: 1040312)
2024-04-26T16:27:10.902872Z INFO kernel: [ 1591.109874] binder: 5724:19434 transaction
failed 29201/-28, size 2083884-0 line 3061
2024-04-26T16:27:12.175815Z INFO crash_reporter[20674]: developer build - not testing -
always dumping
2024-04-26T16:27:12.178141Z WARNING crash_reporter[20674]: [ARC_java] Received
system_app_crash notification for org.chromium.arc.intent_helper (handling)
2024-04-26T16:27:12.184733Z INFO crash_reporter[20674]: Accessing crash dir '/run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65' via symlinked handle
'/proc/self/fd/10'
2024-04-26T16:27:12.189822Z INFO crash_reporter[20674]: Finishing crash. Meta file:
/proc/self/fd/10/org_chromium_arc_intent_helper.20240426.162712.52250.432387.meta
2024-04-26T16:27:37.641254Z INFO kernel: [ 1617.844507] traps: Chrome_ChildIOT[20214]
trap invalid opcode ip:57ecc816fd03 sp:7de224491440 error:0
2024-04-26T16:27:37.657298Z INFO crash_reporter[20853]: developer build - not testing -
always dumping
2024-04-26T16:27:37.658628Z WARNING crash_reporter[20853]: Received crash notification
for chrome[20211] user 1000 (called directly)
2024-04-26T16:27:37.681128Z INFO crash_reporter[20853]: Accessing crash dir '/run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65' via symlinked handle
'/proc/self/fd/10'
2024-04-26T16:27:37.944380Z INFO crash_reporter[20854]: developer build - not testing -
```

always dumping

```
2024-04-26T16:27:37.946467Z WARNING crash_reporter[20854]: [user] Received crash
notification for chrome[20211] sig 4, user 1000 group 1000 (ignoring call by kernel -
chrome crash; waiting for chrome to call us directly)
2024-04-26T16:27:38.712766Z INFO minijail0[20882]: libminijail[20882]: applying policy
for default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:27:39.010547Z INFO crash_reporter[20853]: Finishing crash. Meta file:
/proc/self/fd/10/chrome.20240426.162737.13497.20211.meta
2024-04-26T16:28:11.526143Z ERR kernel: [ 1651.731635] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:28:37.172608Z ERR kernel: [ 1677.375970] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:28:41.203643Z ERR kernel: [ 1681.406813] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:28:41.231095Z ERR kernel: [ 1681.434116] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:28:41.258122Z ERR kernel: [ 1681.459706] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:28:41.277290Z ERR kernel: [ 1681.475480] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:28:41.339388Z ERR kernel: [ 1681.541775] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:28:50.441128Z ERR kernel: [ 1690.644993] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:28:50.573184Z ERR kernel: [ 1690.758912] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:28:50.584083Z ERR kernel: [ 1690.782479] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:28:52.984154Z ERR kernel: [ 1693.186078] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:28:53.249082Z ERR kernel: [ 1693.452799] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:28:53.781726Z WARNING kernel: [ 1693.938967] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:28:53.781785Z WARNING kernel: [ 1693.949128] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:28:53.782657Z WARNING kernel: [ 1693.979530] audit: audit_lost=56
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:28:53.782727Z WARNING kernel: [ 1693.981331] audit: audit_lost=57
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:28:53.788444Z ERR kernel: [ 1693.994424] audit: backlog limit exceeded
2024-04-26T16:28:53.813161Z ERR kernel: [ 1693.998691] audit: backlog limit exceeded
2024-04-26T16:28:54.561156Z ERR kernel: [ 1694.732537] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:29:17.098153Z ERR kernel: [ 1717.276904] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:29:17.629247Z ERR kernel: [ 1717.819777] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:29:18.205091Z ERR kernel: [ 1718.403081] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:29:18.360128Z ERR kernel: [ 1718.554654] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:29:18.531179Z ERR kernel: [ 1718.723327] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:29:27.544114Z ERR kernel: [ 1727.733381] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:29:43.112550Z WARNING kernel: [ 1743.317489] sched: RT throttling activated
2024-04-26T16:29:43.923900Z WARNING cras_server[1439]: pcm_avail returned frames larger
than buf_size: HD-Audio Generic: Generic Analog:0,0: 1098720 > 1048576
2024-04-26T16:29:47.172307Z INFO kernel: [ 1747.373347] binder_alloc: 15955:
binder_alloc_buf size 2083760 failed, no address space
2024-04-26T16:29:47.172345Z INFO kernel: [ 1747.379797] binder_alloc: allocated: 1312
(num: 9 largest: 760), free: 1039072 (num: 4 largest: 1036616)
2024-04-26T16:29:47.185813Z INFO kernel: [ 1747.389550] binder: 4781:5226 transaction
failed 29201/-28, size 2083752-8 line 3061
2024-04-26T16:29:47.185974Z INFO kernel: [ 1747.393974] binder: send failed reply for
transaction 363145 to 15955:15955
2024-04-26T16:29:50.051310Z INFO kernel: [ 1750.228205] binder_alloc: 15955:
binder_alloc_buf, no vma
```

```
2024-04-26T16:29:50.051355Z INFO kernel: [ 1750.249311] binder: 4781:5104 transaction
failed 29189/-3, size 60-0 line 3061
2024-04-26T16:29:50.051366Z INFO kernel: [ 1750.252387] binder_alloc: 15955:
binder_alloc_buf, no vma
2024-04-26T16:29:50.143061Z INFO kernel: [ 1750.345793] binder: 4781:5190 transaction
failed 29189/-3, size 140-8 line 3061
2024-04-26T16:29:50.188583Z INFO kernel: [ 1750.388330] binder_alloc: 15955:
binder_alloc_buf, no vma
2024-04-26T16:29:50.188620Z INFO kernel: [ 1750.392696] binder: 4781:5103 transaction
failed 29189/-3, size 96-0 line 3061
2024-04-26T16:29:51.253084Z INFO crash_reporter[21782]: developer build - not testing -
always dumping
2024-04-26T16:29:51.255696Z WARNING crash_reporter[21782]: [ARC_java] Received
data_app_crash notification for com.whatsapp (handling)
2024-04-26T16:29:51.287192Z INFO crash_reporter[21782]: Accessing crash dir '/run/daemon-
store/crash/521ac76c473ca5ff9c03ccc71d8ad8646690ad65' via symlinked handle
'/proc/self/fd/10'
2024-04-26T16:29:51.300861Z INFO crash_reporter[21782]: Finishing crash. Meta file:
/proc/self/fd/10/com_whatsapp.20240426.162951.65135.534427.meta
2024-04-26T16:29:51.477072Z INFO kernel: [ 1751.665223] binder_alloc: 21749:
binder_alloc_buf, no vma
2024-04-26T16:29:51.477136Z INFO kernel: [ 1751.681022] binder: 4781:5103 transaction
failed 29189/-3, size 76-0 line 3061
2024-04-26T16:30:19.222315Z INFO kernel: [ 1779.332577] binder_alloc: 12120:
binder_alloc_buf size 1056768 failed, no address space
2024-04-26T16:30:19.222369Z INFO kernel: [ 1779.426366] binder_alloc: allocated: 19472
(num: 10 largest: 3856), free: 1020912 (num: 5 largest: 1013376)
2024-04-26T16:30:19.262255Z INFO kernel: [ 1779.465993] binder: 12103:12423 transaction
failed 29201/-28, size 1056768-0 line 3061
2024-04-26T16:30:19.277082Z INFO kernel: [ 1779.480871] binder: send failed reply for
transaction 365203 to 12120:12329
2024-04-26T16:30:55.481912Z INFO kernel: [ 1815.667458] binder_alloc: 22097:
binder_alloc_buf, no vma
2024-04-26T16:30:55.481949Z INFO kernel: [ 1815.673641] binder: 4781:5103 transaction
failed 29189/-3, size 76-0 line 3061
2024-04-26T16:30:58.355234Z NOTICE auditd[458]: Audit daemon rotating log files
2024-04-26T16:31:06.396195Z INFO kernel: [ 1826.507812] binder_alloc: 22146:
binder_alloc_buf, no vma
2024-04-26T16:31:06.396250Z INFO kernel: [ 1826.576895] binder: 4781:5103 transaction
failed 29189/-3, size 76-0 line 3061
2024-04-26T16:31:28.342925Z ERR kernel: [ 1848.541092] [drm:vmw_kms_fb_create] *ERROR*
failed to create vmw_framebuffer: -22
2024-04-26T16:31:41.852797Z WARNING kernel: [ 1862.011909] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:31:41.852846Z WARNING kernel: [ 1862.014694] audit: audit_lost=58
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:31:41.852854Z ERR kernel: [ 1862.018105] audit: backlog limit exceeded
2024-04-26T16:31:41.852858Z WARNING kernel: [ 1862.020216] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:31:41.852863Z WARNING kernel: [ 1862.022958] audit: audit_lost=59
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:31:41.852870Z ERR kernel: [ 1862.026308] audit: backlog limit exceeded
2024-04-26T16:31:41.852874Z WARNING kernel: [ 1862.028369] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:31:41.852878Z WARNING kernel: [ 1862.031097] audit: audit_lost=60
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:31:41.852882Z ERR kernel: [ 1862.034404] audit: backlog limit exceeded
2024-04-26T16:31:41.852885Z WARNING kernel: [ 1862.036438] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:37:38.231555Z WARNING kernel: [ 2218.385653] audit_log_start: 161 callbacks
suppressed
2024-04-26T16:37:38.231632Z WARNING kernel: [ 2218.385660] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:37:38.231636Z WARNING kernel: [ 2218.388697] audit: audit_lost=115
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:37:38.231639Z ERR kernel: [ 2218.390695] audit: backlog limit exceeded
2024-04-26T16:37:38.231643Z WARNING kernel: [ 2218.391988] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:37:38.231645Z WARNING kernel: [ 2218.393720] audit: audit_lost=116
```

```
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:37:38.231647Z ERR kernel: [ 2218.395832] audit: backlog limit exceeded
2024-04-26T16:37:38.231649Z WARNING kernel: [ 2218.397183] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:37:38.231651Z WARNING kernel: [ 2218.398927] audit: audit_lost=117
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:37:38.231653Z ERR kernel: [ 2218.401144] audit: backlog limit exceeded
2024-04-26T16:37:38.231655Z WARNING kernel: [ 2218.402536] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:38:54.642535Z WARNING kernel: [ 2294.849009] audit_log_start: 173 callbacks
suppressed
2024-04-26T16:38:54.642563Z WARNING kernel: [ 2294.849015] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:38:54.646246Z WARNING kernel: [ 2294.852372] audit: audit_lost=176
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:38:54.648648Z ERR kernel: [ 2294.855456] audit: backlog limit exceeded
2024-04-26T16:39:13.421276Z INFO trunksd[746]: Finished saving contexts.
2024-04-26T16:39:36.746277Z NOTICE powerd_suspend[25615]: Going to suspend-to-RAM state:
args=-nosuspend_to_idle --wakeup_count=43590
2024-04-26T16:39:37.032124Z NOTICE powerd_suspend[25615]: Available order 3 pages: 47018
2024-04-26T16:39:37.036978Z NOTICE powerd_suspend[25615]: Finalizing suspend
2024-04-26T16:39:37.046169Z INFO kernel: [ 2337.250965] PM: suspend entry (s2idle)
2024-04-26T16:39:37.058633Z INFO kernel: [ 2337.264212] Filesystems sync: 0.011 seconds
2024-04-26T16:39:37.058662Z DEBUG kernel: [ 2337.265961] PM: Preparing system for sleep
(s2idle)
2024-04-26T16:45:33.369103Z INFO kernel: [ 2337.356052] Freezing user space processes ...
(elapsed 0.028 seconds) done.
2024-04-26T16:45:33.369390Z INFO kernel: [ 2337.385589] OOM killer disabled.
2024-04-26T16:45:33.369405Z INFO kernel: [ 2337.386122] Freezing remaining freezable
tasks ... (elapsed 0.010 seconds) done.
2024-04-26T16:45:33.369410Z DEBUG kernel: [ 2337.398957] PM: Suspending system (s2idle)
2024-04-26T16:45:33.369415Z INFO kernel: [ 2337.426208] rfkill rfkill0: PM: calling
rfkill_suspend+0x0/0x21 @ 25702, parent: hci0
2024-04-26T16:45:33.369420Z INFO kernel: [ 2337.429186] rfkill rfkill0: PM:
rfkill_suspend+0x0/0x21 returned 0 after 1 usecs
2024-04-26T16:45:33.369424Z INFO kernel: [ 2337.432377] input input10: PM: calling
input_dev_suspend+0x0/0x47 @ 25702, parent: card0
2024-04-26T16:45:33.369433Z INFO kernel: [ 2337.436993] input input10: PM:
input_dev_suspend+0x0/0x47 returned 0 after 1209 usecs
2024-04-26T16:45:33.369438Z INFO kernel: [ 2337.438483] input input9: PM: calling
input_dev_suspend+0x0/0x47 @ 25702, parent: card0
2024-04-26T16:45:33.369442Z INFO kernel: [ 2337.439802] input input9: PM:
input_dev_suspend+0x0/0x47 returned 0 after 0 usecs
2024-04-26T16:45:33.369446Z INFO kernel: [ 2337.441175] input input8: PM: calling
input_dev_suspend+0x0/0x47 @ 25702, parent: card0
2024-04-26T16:45:33.369450Z INFO kernel: [ 2337.442709] input input8: PM:
input_dev_suspend+0x0/0x47 returned 0 after 0 usecs
2024-04-26T16:45:33.369454Z INFO kernel: [ 2337.444641] input input7: PM: calling
input_dev_suspend+0x0/0x47 @ 25702, parent: card0
2024-04-26T16:45:33.369541Z INFO kernel: [ 2337.446074] input input7: PM:
input_dev_suspend+0x0/0x47 returned 0 after 0 usecs
2024-04-26T16:45:33.451044Z INFO kernel: [ 2337.448072] input input6: PM: calling
input_dev_suspend+0x0/0x47 @ 25702, parent: card0
2024-04-26T16:45:33.451135Z INFO kernel: [ 2337.449878] input input6: PM:
input_dev_suspend+0x0/0x47 returned 0 after 0 usecs
2024-04-26T16:45:33.451144Z INFO kernel: [ 2337.452423] sound pcmC0D0c: PM: calling
do_pcm_suspend+0x0/0x23 @ 25702, parent: card0
2024-04-26T16:45:33.451148Z INFO kernel: [ 2337.457260] sound pcmC0D0c: PM:
do_pcm_suspend+0x0/0x23 returned 0 after 1527 usecs
2024-04-26T16:45:33.451152Z INFO kernel: [ 2337.458513] sound pcmC0D0p: PM: calling
do_pcm_suspend+0x0/0x23 @ 25702, parent: card0
2024-04-26T16:45:33.451156Z INFO kernel: [ 2337.459750] sound pcmC0D0p: PM:
do_pcm_suspend+0x0/0x23 returned 0 after 0 usecs
2024-04-26T16:45:33.451160Z INFO kernel: [ 2337.463441] platform regulatory.0: PM:
calling platform_pm_suspend+0x0/0x4a @ 25702, parent: platform
2024-04-26T16:45:33.451287Z INFO kernel: [ 2337.465749] platform regulatory.0: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 22 usecs
2024-04-26T16:45:33.451294Z INFO kernel: [ 2337.462612] snd_hda_codec_generic
hdaudioC0D0: PM: calling hda_codec_pm_suspend+0x0/0x19 [snd_hda_codec] @ 9, parent:
```

0000:02:02.0

2024-04-26T16:45:33.451299Z INFO kernel: [2337.470597] input input5: PM: calling input_dev_suspend+0x0/0x47 @ 25702, parent: 0003:0E0F:0003.0001
2024-04-26T16:45:33.452158Z INFO kernel: [2337.470354] usb 2-2.1: PM: calling usb_dev_suspend+0x0/0x14 @ 22324, parent: 2-2
2024-04-26T16:45:33.452170Z INFO kernel: [2337.473643] input input5: PM: input_dev_suspend+0x0/0x47 returned 0 after 1 usecs
2024-04-26T16:45:33.452175Z INFO kernel: [2337.477114] input input3: PM: calling input_dev_suspend+0x0/0x47 @ 25702, parent: serio1
2024-04-26T16:45:33.452180Z INFO kernel: [2337.477587] usb 2-1: PM: calling usb_dev_suspend+0x0/0x14 @ 18922, parent: usb2
2024-04-26T16:45:33.452185Z INFO kernel: [2337.478041] usb 2-2.1: PM: usb_dev_suspend+0x0/0x14 returned 0 after 2671 usecs
2024-04-26T16:45:33.452191Z INFO kernel: [2337.478127] usb 2-2: PM: calling usb_dev_suspend+0x0/0x14 @ 25613, parent: usb2
2024-04-26T16:45:33.452196Z INFO kernel: [2337.480231] input input3: PM: input_dev_suspend+0x0/0x47 returned 0 after 1 usecs
2024-04-26T16:45:33.452201Z INFO kernel: [2337.485678] input input4: PM: calling input_dev_suspend+0x0/0x47 @ 25702, parent: serio1
2024-04-26T16:45:33.452207Z INFO kernel: [2337.487251] input input4: PM: input_dev_suspend+0x0/0x47 returned 0 after 0 usecs
2024-04-26T16:45:33.452211Z INFO kernel: [2337.489299] leds input1::scrolllock: PM: calling led_suspend+0x0/0x3f @ 25702, parent: input1
2024-04-26T16:45:33.492556Z INFO kernel: [2337.493419] leds input1::scrolllock: PM: led_suspend+0x0/0x3f returned 0 after 704 usecs
2024-04-26T16:45:33.492579Z INFO kernel: [2337.495579] leds input1::capslock: PM: calling led_suspend+0x0/0x3f @ 25702, parent: input1
2024-04-26T16:45:33.492584Z INFO kernel: [2337.497045] leds input1::capslock: PM: led_suspend+0x0/0x3f returned 0 after 0 usecs
2024-04-26T16:45:33.494167Z INFO kernel: [2337.498332] leds input1::numlock: PM: calling led_suspend+0x0/0x3f @ 25702, parent: input1
2024-04-26T16:45:33.494189Z INFO kernel: [2337.499740] leds input1::numlock: PM: led_suspend+0x0/0x3f returned 0 after 0 usecs
2024-04-26T16:45:33.494194Z INFO kernel: [2337.501357] input input1: PM: calling input_dev_suspend+0x0/0x47 @ 25702, parent: serio0
2024-04-26T16:45:33.499563Z INFO kernel: [2337.502952] input input1: PM: input_dev_suspend+0x0/0x47 returned 0 after 1 usecs
2024-04-26T16:45:33.499580Z INFO kernel: [2337.504394] alarmtimer alarmtimer.0.auto: PM: calling platform_pm_suspend+0x0/0x4a @ 25702, parent: rtc0
2024-04-26T16:45:33.499585Z INFO kernel: [2337.507276] alarmtimer alarmtimer.0.auto: PM: platform_pm_suspend+0x0/0x4a returned 0 after 1221 usecs
2024-04-26T16:45:33.499588Z INFO kernel: [2337.510047] psmouse serio1: PM: calling serio_suspend+0x0/0x1d @ 25702, parent: i8042
2024-04-26T16:45:33.499591Z INFO kernel: [2337.523591] psmouse serio1: PM: serio_suspend+0x0/0x1d returned 0 after 11883 usecs
2024-04-26T16:45:33.499593Z INFO kernel: [2337.525061] atkbd serio0: PM: calling serio_suspend+0x0/0x1d @ 25702, parent: i8042
2024-04-26T16:45:33.499596Z INFO kernel: [2337.528256] atkbd serio0: PM: serio_suspend+0x0/0x1d returned 0 after 1138 usecs
2024-04-26T16:45:33.499599Z INFO kernel: [2337.529675] i8042 i8042: PM: calling platform_pm_suspend+0x0/0x4a @ 25702, parent: platform
2024-04-26T16:45:33.499601Z INFO kernel: [2337.534308] i8042 i8042: PM: platform_pm_suspend+0x0/0x4a returned 0 after 2946 usecs
2024-04-26T16:45:33.499604Z INFO kernel: [2337.550100] usb usb1: PM: calling usb_dev_suspend+0x0/0x14 @ 22324, parent: 0000:02:03.0
2024-04-26T16:45:33.499607Z INFO kernel: [2337.550129] platform Fixed MDIO bus.0: PM: calling platform_pm_suspend+0x0/0x4a @ 25702, parent: platform
2024-04-26T16:45:33.499609Z INFO kernel: [2337.560277] platform Fixed MDIO bus.0: PM: platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs
2024-04-26T16:45:33.499706Z INFO kernel: [2337.563385] usb 2-2: PM: usb_dev_suspend+0x0/0x14 returned 0 after 85246 usecs
2024-04-26T16:45:33.499713Z INFO kernel: [2337.563429] usb 2-1: PM: usb_dev_suspend+0x0/0x14 returned 0 after 82729 usecs
2024-04-26T16:45:33.499781Z INFO kernel: [2337.564247] ata2: PM: calling ata_port_pm_suspend+0x0/0x3e @ 18922, parent: 0000:00:07.1
2024-04-26T16:45:33.504786Z INFO kernel: [2337.565186] serial8250 serial8250: PM: calling platform_pm_suspend+0x0/0x4a @ 25702, parent: platform
2024-04-26T16:45:33.504813Z INFO kernel: [2337.565985] ata1: PM: calling ata_port_pm_suspend+0x0/0x3e @ 25613, parent: 0000:00:07.1


```
2024-04-26T16:45:33.504818Z INFO kernel: [ 2337.566022] usb usb2: PM: calling
usb_dev_suspend+0x0/0x14 @ 25576, parent: 0000:02:00.0
2024-04-26T16:45:33.504821Z INFO kernel: [ 2337.566248] usb usb2: PM:
usb_dev_suspend+0x0/0x14 returned 0 after 215 usecs
2024-04-26T16:45:33.504824Z INFO kernel: [ 2337.566249] serial8250 serial8250: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 723 usecs
2024-04-26T16:45:33.504831Z INFO kernel: [ 2337.566263] input input0: PM: calling
input_dev_suspend+0x0/0x47 @ 25702, parent: LNXPPWRBN:00
2024-04-26T16:45:33.504837Z INFO kernel: [ 2337.566272] input input0: PM:
input_dev_suspend+0x0/0x47 returned 0 after 0 usecs
2024-04-26T16:45:33.504841Z INFO kernel: [ 2337.569405] platform intel_rapl_msr.0: PM:
calling platform_pm_suspend+0x0/0x4a @ 25702, parent: platform
2024-04-26T16:45:33.518693Z INFO kernel: [ 2337.575122] ata1: PM:
ata_port_pm_suspend+0x0/0x3e returned 0 after 3821 usecs
2024-04-26T16:45:33.518724Z INFO kernel: [ 2337.575314] usb usb1: PM:
usb_dev_suspend+0x0/0x14 returned 0 after 18787 usecs
2024-04-26T16:45:33.518730Z INFO kernel: [ 2337.577150] platform intel_rapl_msr.0: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs
2024-04-26T16:45:33.518735Z INFO kernel: [ 2337.578302] ata2: PM:
ata_port_pm_suspend+0x0/0x3e returned 0 after 9343 usecs
2024-04-26T16:45:33.518740Z INFO kernel: [ 2337.580591] system 00:05: PM: calling
pnp_bus_suspend+0x0/0x14 @ 25702, parent: pnp0
2024-04-26T16:45:33.527304Z INFO kernel: [ 2337.597524] system 00:05: PM:
pnp_bus_suspend+0x0/0x14 returned 0 after 3157 usecs
2024-04-26T16:45:33.527328Z INFO kernel: [ 2337.598821] system 00:04: PM: calling
pnp_bus_suspend+0x0/0x14 @ 25702, parent: pnp0
2024-04-26T16:45:33.527334Z INFO kernel: [ 2337.600298] system 00:04: PM:
pnp_bus_suspend+0x0/0x14 returned 0 after 0 usecs
2024-04-26T16:45:33.527338Z INFO kernel: [ 2337.601920] snd_hda_codec_generic
hdaudioC0D0: PM: hda_codec_pm_suspend+0x0/0x19 [snd_hda_codec] returned 0 after 131517
usecs
2024-04-26T16:45:33.527342Z INFO kernel: [ 2337.601802] i8042 aux 00:03: PM: calling
pnp_bus_suspend+0x0/0x14 @ 25702, parent: pnp0
2024-04-26T16:45:33.527345Z INFO kernel: [ 2337.605768] i8042 aux 00:03: PM:
pnp_bus_suspend+0x0/0x14 returned 0 after 0 usecs
2024-04-26T16:45:33.527349Z INFO kernel: [ 2337.606994] i8042 kbd 00:02: PM: calling
pnp_bus_suspend+0x0/0x14 @ 25702, parent: pnp0
2024-04-26T16:45:33.527352Z INFO kernel: [ 2337.609107] i8042 kbd 00:02: PM:
pnp_bus_suspend+0x0/0x14 returned 0 after 0 usecs
2024-04-26T16:45:33.527356Z INFO kernel: [ 2337.610355] rtc_cmos 00:01: PM: calling
pnp_bus_suspend+0x0/0x14 @ 25702, parent: pnp0
2024-04-26T16:45:33.527359Z INFO kernel: [ 2337.612910] rtc_cmos 00:01: PM:
pnp_bus_suspend+0x0/0x14 returned 0 after 278 usecs
2024-04-26T16:45:33.527362Z INFO kernel: [ 2337.614286] system 00:00: PM: calling
pnp_bus_suspend+0x0/0x14 @ 25702, parent: pnp0
2024-04-26T16:45:33.527365Z INFO kernel: [ 2337.615552] system 00:00: PM:
pnp_bus_suspend+0x0/0x14 returned 0 after 0 usecs
2024-04-26T16:45:33.527368Z INFO kernel: [ 2337.616792] platform chromeos_acpi: PM:
calling platform_pm_suspend+0x0/0x4a @ 25702, parent: platform
2024-04-26T16:45:33.535830Z INFO kernel: [ 2337.618310] platform chromeos_acpi: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs
2024-04-26T16:45:33.535855Z INFO kernel: [ 2337.619735] platform efivars.0: PM: calling
platform_pm_suspend+0x0/0x4a @ 25702, parent: platform
2024-04-26T16:45:33.535860Z INFO kernel: [ 2337.621412] platform efivars.0: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs
2024-04-26T16:45:33.535864Z INFO kernel: [ 2337.622965] platform rtc-efi.0: PM: calling
platform_pm_suspend+0x0/0x4a @ 25702, parent: platform
2024-04-26T16:45:33.535867Z INFO kernel: [ 2337.624543] platform rtc-efi.0: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs
2024-04-26T16:45:33.536551Z INFO kernel: [ 2337.625880] button LNXPPWRBN:00: PM: calling
acpi_button_suspend+0x0/0x19 @ 25702, parent: LNXSYSTM:00
2024-04-26T16:45:33.536566Z INFO kernel: [ 2337.628022] button LNXPPWRBN:00: PM:
acpi_button_suspend+0x0/0x19 returned 0 after 518 usecs
2024-04-26T16:45:33.536570Z INFO kernel: [ 2337.633405] platform ACPI0003:00: PM: calling
platform_pm_suspend+0x0/0x4a @ 25702, parent: platform
2024-04-26T16:45:33.536574Z INFO kernel: [ 2337.634981] platform ACPI0003:00: PM:
platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs
2024-04-26T16:45:33.536578Z INFO kernel: [ 2337.636314] platform PNP0800:00: PM: calling
platform_pm_suspend+0x0/0x4a @ 25702, parent: 0000:00:07.0
```

2024-04-26T16:45:33.536643Z INFO kernel: [2337.637925] platform PNP0800:00: PM: platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs

2024-04-26T16:45:33.536650Z INFO kernel: [2337.639272] platform PNP0001:00: PM: calling platform_pm_suspend+0x0/0x4a @ 25702, parent: 0000:00:07.0

2024-04-26T16:45:33.536655Z INFO kernel: [2337.641146] platform PNP0001:00: PM: platform_pm_suspend+0x0/0x4a returned 0 after 0 usecs

2024-04-26T16:45:33.536658Z INFO kernel: [2337.644572] nvme 0000:03:00.0: PM: calling pci_pm_suspend+0x0/0x1da @ 9, parent: 0000:00:15.0

2024-04-26T16:45:33.536661Z INFO kernel: [2337.645258] ehci-pci 0000:02:03.0: PM: calling pci_pm_suspend+0x0/0x1da @ 18922, parent: 0000:00:11.0

2024-04-26T16:45:33.536665Z INFO kernel: [2337.649505] e1000 0000:02:01.0: PM: calling pci_pm_suspend+0x0/0x1da @ 22324, parent: 0000:00:11.0

2024-04-26T16:45:33.536668Z INFO kernel: [2337.649434] snd_hda_intel 0000:02:02.0: PM: calling pci_pm_suspend+0x0/0x1da @ 25613, parent: 0000:00:11.0

2024-04-26T16:45:33.536672Z INFO kernel: [2337.655593] uhci_hcd 0000:02:00.0: PM: calling pci_pm_suspend+0x0/0x1da @ 25703, parent: 0000:00:11.0

2024-04-26T16:45:33.536675Z INFO kernel: [2337.655662] pcieport 0000:00:18.7: PM: calling pci_pm_suspend+0x0/0x1da @ 25576, parent: pci0000:00

2024-04-26T16:45:33.536679Z INFO kernel: [2337.661061] uhci_hcd 0000:02:00.0: PM: pci_pm_suspend+0x0/0x1da returned 0 after 3054 usecs

2024-04-26T16:45:33.536778Z INFO kernel: [2337.663661] pcieport 0000:00:18.7: PM: pci_pm_suspend+0x0/0x1da returned 0 after 3294 usecs

2024-04-26T16:45:33.536786Z INFO kernel: [2337.663813] pcieport 0000:00:18.6: PM: calling pci_pm_suspend+0x0/0x1da @ 25703, parent: pci0000:00

2024-04-26T16:45:33.536790Z INFO kernel: [2337.664255] pcieport 0000:00:18.5: PM: calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00

2024-04-26T16:45:33.536793Z INFO kernel: [2337.664548] pcieport 0000:00:18.5: PM: pci_pm_suspend+0x0/0x1da returned 0 after 285 usecs

2024-04-26T16:45:33.536797Z INFO kernel: [2337.664947] pcieport 0000:00:18.4: PM: calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00

2024-04-26T16:45:33.536800Z INFO kernel: [2337.665277] pcieport 0000:00:18.4: PM: pci_pm_suspend+0x0/0x1da returned 0 after 322 usecs

2024-04-26T16:45:33.536856Z INFO kernel: [2337.665287] pcieport 0000:00:18.3: PM: calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00

2024-04-26T16:45:33.539395Z INFO kernel: [2337.665487] pcieport 0000:00:18.3: PM: pci_pm_suspend+0x0/0x1da returned 0 after 194 usecs

2024-04-26T16:45:33.539421Z INFO kernel: [2337.665494] pcieport 0000:00:18.2: PM: calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00

2024-04-26T16:45:33.539428Z INFO kernel: [2337.666020] pcieport 0000:00:18.1: PM: calling pci_pm_suspend+0x0/0x1da @ 25576, parent: pci0000:00

2024-04-26T16:45:33.539433Z INFO kernel: [2337.666053] pcieport 0000:00:18.2: PM: pci_pm_suspend+0x0/0x1da returned 0 after 554 usecs

2024-04-26T16:45:33.539437Z INFO kernel: [2337.666060] pcieport 0000:00:18.0: PM: calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00

2024-04-26T16:45:33.539442Z INFO kernel: [2337.666270] pcieport 0000:00:18.0: PM: pci_pm_suspend+0x0/0x1da returned 0 after 206 usecs

2024-04-26T16:45:33.539446Z INFO kernel: [2337.666276] pcieport 0000:00:17.7: PM: calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00

2024-04-26T16:45:33.539450Z INFO kernel: [2337.666429] pcieport 0000:00:17.7: PM: pci_pm_suspend+0x0/0x1da returned 0 after 150 usecs

2024-04-26T16:45:33.539456Z INFO kernel: [2337.666435] pcieport 0000:00:17.6: PM: calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00

2024-04-26T16:45:33.539460Z INFO kernel: [2337.666591] pcieport 0000:00:17.6: PM: pci_pm_suspend+0x0/0x1da returned 0 after 152 usecs

2024-04-26T16:45:33.539545Z INFO kernel: [2337.666596] pcieport 0000:00:17.5: PM: calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00

2024-04-26T16:45:33.539555Z INFO kernel: [2337.666749] pcieport 0000:00:17.5: PM: pci_pm_suspend+0x0/0x1da returned 0 after 150 usecs

2024-04-26T16:45:33.539560Z INFO kernel: [2337.667227] pcieport 0000:00:17.4: PM: calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00

2024-04-26T16:45:33.539564Z INFO kernel: [2337.667397] pcieport 0000:00:17.4: PM: pci_pm_suspend+0x0/0x1da returned 0 after 165 usecs

2024-04-26T16:45:33.539569Z INFO kernel: [2337.667403] pcieport 0000:00:17.3: PM: calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00

2024-04-26T16:45:33.539573Z INFO kernel: [2337.667558] pcieport 0000:00:17.3: PM: pci_pm_suspend+0x0/0x1da returned 0 after 151 usecs

2024-04-26T16:45:33.539577Z INFO kernel: [2337.667563] pcieport 0000:00:17.2: PM: calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00

2024-04-26T16:45:33.539708Z INFO kernel: [2337.667718] pcieport 0000:00:17.2: PM:

```
pci_pm_suspend+0x0/0x1da returned 0 after 152 usecs
2024-04-26T16:45:33.539720Z INFO kernel: [ 2337.667723] pcieport 0000:00:17.1: PM:
calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00
2024-04-26T16:45:33.539724Z INFO kernel: [ 2337.667904] pcieport 0000:00:17.1: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 177 usecs
2024-04-26T16:45:33.539727Z INFO kernel: [ 2337.667910] pcieport 0000:00:17.0: PM:
calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00
2024-04-26T16:45:33.539730Z INFO kernel: [ 2337.668060] pcieport 0000:00:17.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 147 usecs
2024-04-26T16:45:33.539733Z INFO kernel: [ 2337.668066] pcieport 0000:00:16.7: PM:
calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00
2024-04-26T16:45:33.539737Z INFO kernel: [ 2337.668236] pcieport 0000:00:16.7: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 167 usecs
2024-04-26T16:45:33.539743Z INFO kernel: [ 2337.668242] pcieport 0000:00:16.6: PM:
calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00
2024-04-26T16:45:33.539747Z INFO kernel: [ 2337.668419] pcieport 0000:00:16.6: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 174 usecs
2024-04-26T16:45:33.539751Z INFO kernel: [ 2337.668634] ehci-pci 0000:02:03.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 259 usecs
2024-04-26T16:45:33.539860Z INFO kernel: [ 2337.668646] pcieport 0000:00:16.5: PM:
calling pci_pm_suspend+0x0/0x1da @ 18922, parent: pci0000:00
2024-04-26T16:45:33.539876Z INFO kernel: [ 2337.668821] pcieport 0000:00:16.5: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 168 usecs
2024-04-26T16:45:33.539881Z INFO kernel: [ 2337.669225] pcieport 0000:00:16.4: PM:
calling pci_pm_suspend+0x0/0x1da @ 18922, parent: pci0000:00
2024-04-26T16:45:33.539885Z INFO kernel: [ 2337.669404] pcieport 0000:00:16.4: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 141 usecs
2024-04-26T16:45:33.539888Z INFO kernel: [ 2337.669445] pcieport 0000:00:16.3: PM:
calling pci_pm_suspend+0x0/0x1da @ 18922, parent: pci0000:00
2024-04-26T16:45:33.539892Z INFO kernel: [ 2337.669659] pcieport 0000:00:16.3: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 208 usecs
2024-04-26T16:45:33.540690Z INFO kernel: [ 2337.669665] pcieport 0000:00:16.2: PM:
calling pci_pm_suspend+0x0/0x1da @ 18922, parent: pci0000:00
2024-04-26T16:45:33.540707Z INFO kernel: [ 2337.669827] pcieport 0000:00:16.2: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 159 usecs
2024-04-26T16:45:33.540712Z INFO kernel: [ 2337.669833] pcieport 0000:00:16.1: PM:
calling pci_pm_suspend+0x0/0x1da @ 18922, parent: pci0000:00
2024-04-26T16:45:33.540716Z INFO kernel: [ 2337.670623] pcieport 0000:00:16.1: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 786 usecs
2024-04-26T16:45:33.540720Z INFO kernel: [ 2337.670637] pcieport 0000:00:16.0: PM:
calling pci_pm_suspend+0x0/0x1da @ 18922, parent: pci0000:00
2024-04-26T16:45:33.540725Z INFO kernel: [ 2337.670842] pcieport 0000:00:16.0: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 201 usecs
2024-04-26T16:45:33.540729Z INFO kernel: [ 2337.670851] pcieport 0000:00:15.7: PM:
calling pci_pm_suspend+0x0/0x1da @ 18922, parent: pci0000:00
2024-04-26T16:45:33.540733Z INFO kernel: [ 2337.671098] pcieport 0000:00:15.7: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 242 usecs
2024-04-26T16:45:33.547183Z INFO kernel: [ 2337.671789] pcieport 0000:00:18.1: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 312 usecs
2024-04-26T16:45:33.547214Z INFO kernel: [ 2337.671804] pcieport 0000:00:15.6: PM:
calling pci_pm_suspend+0x0/0x1da @ 25576, parent: pci0000:00
2024-04-26T16:45:33.547645Z INFO kernel: [ 2337.672434] pcieport 0000:00:15.6: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 624 usecs
2024-04-26T16:45:33.547658Z INFO kernel: [ 2337.672447] pcieport 0000:00:15.5: PM:
calling pci_pm_suspend+0x0/0x1da @ 25576, parent: pci0000:00
2024-04-26T16:45:33.547664Z INFO kernel: [ 2337.672767] pcieport 0000:00:15.5: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 315 usecs
2024-04-26T16:45:33.547673Z INFO kernel: [ 2337.674189] pcieport 0000:00:15.4: PM:
calling pci_pm_suspend+0x0/0x1da @ 25576, parent: pci0000:00
2024-04-26T16:45:33.547678Z INFO kernel: [ 2337.674521] pcieport 0000:00:15.4: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 320 usecs
2024-04-26T16:45:33.547681Z INFO kernel: [ 2337.679142] pcieport 0000:00:15.3: PM:
calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00
2024-04-26T16:45:33.548294Z INFO kernel: [ 2337.683097] pcieport 0000:00:15.2: PM:
calling pci_pm_suspend+0x0/0x1da @ 25576, parent: pci0000:00
2024-04-26T16:45:33.548308Z INFO kernel: [ 2337.683588] pcieport 0000:00:15.1: PM:
calling pci_pm_suspend+0x0/0x1da @ 25704, parent: pci0000:00
2024-04-26T16:45:33.548312Z INFO kernel: [ 2337.685845] pcieport 0000:00:15.2: PM:
pci_pm_suspend+0x0/0x1da returned 0 after 235 usecs
```

2024-04-26T16:45:33.548314Z INFO kernel: [2337.687199] pcieport 0000:00:15.3: PM: pci_pm_suspend+0x0/0x1da returned 0 after 433 usecs

2024-04-26T16:45:33.548317Z INFO kernel: [2337.689051] pcieport 0000:00:15.1: PM: pci_pm_suspend+0x0/0x1da returned 0 after 888 usecs

2024-04-26T16:45:33.548319Z INFO kernel: [2337.689122] pci 0000:00:10.0: PM: calling pci_pm_suspend+0x0/0x1da @ 25706, parent: pci0000:00

2024-04-26T16:45:33.548321Z INFO kernel: [2337.689131] pci 0000:00:10.0: PM: pci_pm_suspend+0x0/0x1da returned 0 after 0 usecs

2024-04-26T16:45:33.548324Z INFO kernel: [2337.689141] vmwgfx 0000:00:0f.0: PM: calling pci_pm_suspend+0x0/0x1da @ 25706, parent: pci0000:00

2024-04-26T16:45:33.548500Z INFO kernel: [2337.690812] vmwgfx 0000:00:0f.0: PM: pci_pm_suspend+0x0/0x1da returned 0 after 1664 usecs

2024-04-26T16:45:33.548509Z INFO kernel: [2337.693341] pcieport 0000:00:18.6: PM: pci_pm_suspend+0x0/0x1da returned 0 after 261 usecs

2024-04-26T16:45:33.548512Z INFO kernel: [2337.695288] vmw_vmci 0000:00:07.7: PM: calling pci_pm_suspend+0x0/0x1da @ 25706, parent: pci0000:00

2024-04-26T16:45:33.556646Z INFO kernel: [2337.697406] pci 0000:00:07.3: PM: calling pci_pm_suspend+0x0/0x1da @ 25703, parent: pci0000:00

2024-04-26T16:45:33.556672Z INFO kernel: [2337.699209] ata_piix 0000:00:07.1: PM: calling pci_pm_suspend+0x0/0x1da @ 25576, parent: pci0000:00

2024-04-26T16:45:33.556678Z INFO kernel: [2337.700238] pci 0000:00:07.0: PM: calling pci_pm_suspend+0x0/0x1da @ 18922, parent: pci0000:00

2024-04-26T16:45:33.556682Z INFO kernel: [2337.700246] pci 0000:00:07.0: PM: pci_pm_suspend+0x0/0x1da returned 0 after 0 usecs

2024-04-26T16:45:33.556686Z INFO kernel: [2337.700256] pci 0000:00:01.0: PM: calling pci_pm_suspend+0x0/0x1da @ 18922, parent: pci0000:00

2024-04-26T16:45:33.556690Z INFO kernel: [2337.700261] pci 0000:00:01.0: PM: pci_pm_suspend+0x0/0x1da returned 0 after 0 usecs

2024-04-26T16:45:33.556693Z INFO kernel: [2337.700268] pci 0000:00:00.0: PM: calling pci_pm_suspend+0x0/0x1da @ 18922, parent: pci0000:00

2024-04-26T16:45:33.557272Z INFO kernel: [2337.700272] pci 0000:00:00.0: PM: pci_pm_suspend+0x0/0x1da returned 0 after 0 usecs

2024-04-26T16:45:33.557291Z INFO kernel: [2337.701349] vmw_vmci 0000:00:07.7: PM: pci_pm_suspend+0x0/0x1da returned 0 after 1982 usecs

2024-04-26T16:45:33.557295Z INFO kernel: [2337.702554] snd_hda_intel 0000:02:02.0: PM: pci_pm_suspend+0x0/0x1da returned 0 after 25843 usecs

2024-04-26T16:45:33.557297Z INFO kernel: [2337.709887] nvme 0000:03:00.0: PM: pci_pm_suspend+0x0/0x1da returned 0 after 62579 usecs

2024-04-26T16:45:33.557300Z INFO kernel: [2337.710440] pci 0000:00:07.3: PM: pci_pm_suspend+0x0/0x1da returned 0 after 0 usecs

2024-04-26T16:45:33.557303Z INFO kernel: [2337.713154] pcieport 0000:00:15.0: PM: calling pci_pm_suspend+0x0/0x1da @ 771, parent: pci0000:00

2024-04-26T16:45:33.557434Z INFO kernel: [2337.713449] ata_piix 0000:00:07.1: PM: pci_pm_suspend+0x0/0x1da returned 0 after 9169 usecs

2024-04-26T16:45:33.557447Z INFO kernel: [2337.719008] e1000 0000:02:01.0: PM: pci_pm_suspend+0x0/0x1da returned 0 after 65902 usecs

2024-04-26T16:45:33.557451Z INFO kernel: [2337.720281] pcieport 0000:00:15.0: PM: pci_pm_suspend+0x0/0x1da returned 0 after 301 usecs

2024-04-26T16:45:33.557454Z INFO kernel: [2337.727976] pci 0000:00:11.0: PM: calling pci_pm_suspend+0x0/0x1da @ 25705, parent: pci0000:00

2024-04-26T16:45:33.557457Z INFO kernel: [2337.822880] pci 0000:00:11.0: PM: pci_pm_suspend+0x0/0x1da returned 0 after 1 usecs

2024-04-26T16:45:33.557460Z DEBUG kernel: [2337.824279] PM: suspend of devices complete after 412.482 msecs

2024-04-26T16:45:33.557464Z DEBUG kernel: [2337.824285] PM: start suspend of devices complete after 424.670 msecs

2024-04-26T16:45:33.557467Z INFO kernel: [2337.824824] nvme 0000:03:00.0: PM: calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: 0000:00:15.0

2024-04-26T16:45:33.557470Z INFO kernel: [2337.825284] ehci-pci 0000:02:03.0: PM: calling pci_pm_suspend_late+0x0/0x3a @ 25705, parent: 0000:00:11.0

2024-04-26T16:45:33.557476Z INFO kernel: [2337.825286] snd_hda_intel 0000:02:02.0: PM: calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: 0000:00:11.0

2024-04-26T16:45:33.557481Z INFO kernel: [2337.825323] e1000 0000:02:01.0: PM: calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: 0000:00:11.0

2024-04-26T16:45:33.557485Z INFO kernel: [2337.825369] e1000 0000:02:01.0: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 39 usecs

2024-04-26T16:45:33.557563Z INFO kernel: [2337.825368] snd_hda_intel 0000:02:02.0: PM: pci_pm_suspend_late+0x0/0x3a returned 0 after 74 usecs

2024-04-26T16:45:33.557573Z INFO kernel: [2337.825379] uhci_hcd 0000:02:00.0: PM:

```
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: 0000:00:11.0
2024-04-26T16:45:33.557577Z INFO kernel: [ 2337.825381] pcieport 0000:00:18.7: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.557582Z INFO kernel: [ 2337.825383] uhci_hcd 0000:02:00.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.557586Z INFO kernel: [ 2337.825386] pcieport 0000:00:18.7: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.557589Z INFO kernel: [ 2337.825400] pcieport 0000:00:18.6: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.558441Z INFO kernel: [ 2337.825404] pcieport 0000:00:18.6: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.558461Z INFO kernel: [ 2337.825408] pcieport 0000:00:18.5: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.558466Z INFO kernel: [ 2337.825410] pcieport 0000:00:18.4: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.558469Z INFO kernel: [ 2337.825412] pcieport 0000:00:18.5: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.558472Z INFO kernel: [ 2337.825414] pcieport 0000:00:18.4: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.558475Z INFO kernel: [ 2337.825426] pcieport 0000:00:18.3: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.558558Z INFO kernel: [ 2337.825430] pcieport 0000:00:18.3: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.558568Z INFO kernel: [ 2337.825435] pcieport 0000:00:18.2: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.558572Z INFO kernel: [ 2337.825470] pcieport 0000:00:18.2: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.558575Z INFO kernel: [ 2337.825483] pcieport 0000:00:18.1: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.558577Z INFO kernel: [ 2337.825487] pcieport 0000:00:18.1: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.558580Z INFO kernel: [ 2337.825494] pcieport 0000:00:18.0: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.559274Z INFO kernel: [ 2337.825498] pcieport 0000:00:18.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.559300Z INFO kernel: [ 2337.825504] pcieport 0000:00:17.7: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.559306Z INFO kernel: [ 2337.825508] pcieport 0000:00:17.7: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.559309Z INFO kernel: [ 2337.825512] pcieport 0000:00:17.6: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.559314Z INFO kernel: [ 2337.825516] pcieport 0000:00:17.6: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.559319Z INFO kernel: [ 2337.825523] pcieport 0000:00:17.5: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.560374Z INFO kernel: [ 2337.825527] pcieport 0000:00:17.5: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.560390Z INFO kernel: [ 2337.825531] pcieport 0000:00:17.4: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.560393Z INFO kernel: [ 2337.825535] pcieport 0000:00:17.4: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.560396Z INFO kernel: [ 2337.825542] pcieport 0000:00:17.3: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.564635Z INFO kernel: [ 2337.825545] pcieport 0000:00:17.3: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.564650Z INFO kernel: [ 2337.825550] pcieport 0000:00:17.2: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.564656Z INFO kernel: [ 2337.825554] pcieport 0000:00:17.2: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.564660Z INFO kernel: [ 2337.825574] pcieport 0000:00:17.1: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.564664Z INFO kernel: [ 2337.825578] pcieport 0000:00:17.1: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.564744Z INFO kernel: [ 2337.825583] pcieport 0000:00:17.0: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.564751Z INFO kernel: [ 2337.825587] pcieport 0000:00:17.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.564755Z INFO kernel: [ 2337.825592] pcieport 0000:00:16.7: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
```

```
2024-04-26T16:45:33.564763Z INFO kernel: [ 2337.825596] pcieport 0000:00:16.7: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.564767Z INFO kernel: [ 2337.825611] pcieport 0000:00:16.6: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.564771Z INFO kernel: [ 2337.825614] pcieport 0000:00:16.6: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.564775Z INFO kernel: [ 2337.825618] pcieport 0000:00:16.5: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.564780Z INFO kernel: [ 2337.825651] pcieport 0000:00:16.5: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.564785Z INFO kernel: [ 2337.825664] pcieport 0000:00:16.4: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.564789Z INFO kernel: [ 2337.825668] pcieport 0000:00:16.4: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.564793Z INFO kernel: [ 2337.825674] pcieport 0000:00:16.3: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.564797Z INFO kernel: [ 2337.825678] pcieport 0000:00:16.3: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.564801Z INFO kernel: [ 2337.825683] pcieport 0000:00:16.2: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.564805Z INFO kernel: [ 2337.825687] pcieport 0000:00:16.2: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.564810Z INFO kernel: [ 2337.825692] pcieport 0000:00:16.1: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.564814Z INFO kernel: [ 2337.825693] pcieport 0000:00:16.0: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.564819Z INFO kernel: [ 2337.825695] pcieport 0000:00:16.1: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.564823Z INFO kernel: [ 2337.825697] pcieport 0000:00:16.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.564992Z INFO kernel: [ 2337.825710] pcieport 0000:00:15.7: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.565005Z INFO kernel: [ 2337.825713] pcieport 0000:00:15.7: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.565082Z INFO kernel: [ 2337.825718] pcieport 0000:00:15.6: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.565090Z INFO kernel: [ 2337.825722] pcieport 0000:00:15.6: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.565094Z INFO kernel: [ 2337.825729] pcieport 0000:00:15.5: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.565098Z INFO kernel: [ 2337.825732] pcieport 0000:00:15.5: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.565101Z INFO kernel: [ 2337.825737] pcieport 0000:00:15.4: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.565106Z INFO kernel: [ 2337.825741] pcieport 0000:00:15.4: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.565109Z INFO kernel: [ 2337.825748] pcieport 0000:00:15.3: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.565113Z INFO kernel: [ 2337.825751] pcieport 0000:00:15.3: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.565117Z INFO kernel: [ 2337.825755] pcieport 0000:00:15.2: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.565587Z INFO kernel: [ 2337.825759] pcieport 0000:00:15.2: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.565602Z INFO kernel: [ 2337.825767] pcieport 0000:00:15.1: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.565608Z INFO kernel: [ 2337.825771] pcieport 0000:00:15.1: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.565613Z INFO kernel: [ 2337.826761] nvme 0000:03:00.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.565617Z INFO kernel: [ 2337.828832] ehci-pci 0000:02:03.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.565622Z INFO kernel: [ 2337.830845] pci 0000:00:10.0: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T16:45:33.565693Z INFO kernel: [ 2337.830852] pci 0000:00:10.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.565701Z INFO kernel: [ 2337.830858] vmwgfx 0000:00:0f.0: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T16:45:33.565706Z INFO kernel: [ 2337.830863] vmwgfx 0000:00:0f.0: PM:
```

```
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.565710Z INFO kernel: [ 2337.830870] vmw_vmci 0000:00:07.7: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 9, parent: pci0000:00
2024-04-26T16:45:33.565713Z INFO kernel: [ 2337.830913] pcieport 0000:00:15.0: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.565718Z INFO kernel: [ 2337.830921] pcieport 0000:00:15.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.566557Z INFO kernel: [ 2337.830933] pci 0000:00:07.3: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.566572Z INFO kernel: [ 2337.830937] pci 0000:00:07.3: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.566576Z INFO kernel: [ 2337.830947] ata_piix 0000:00:07.1: PM:
calling pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.566580Z INFO kernel: [ 2337.830951] ata_piix 0000:00:07.1: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.566585Z INFO kernel: [ 2337.830960] pci 0000:00:07.0: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.566587Z INFO kernel: [ 2337.830964] pci 0000:00:07.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.566661Z INFO kernel: [ 2337.830972] pci 0000:00:01.0: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.566670Z INFO kernel: [ 2337.830976] pci 0000:00:01.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.566675Z INFO kernel: [ 2337.830983] pci 0000:00:00.0: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 18922, parent: pci0000:00
2024-04-26T16:45:33.566679Z INFO kernel: [ 2337.830987] pci 0000:00:00.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 0 usecs
2024-04-26T16:45:33.566682Z INFO kernel: [ 2337.833649] pci 0000:00:11.0: PM: calling
pci_pm_suspend_late+0x0/0x3a @ 771, parent: pci0000:00
2024-04-26T16:45:33.566687Z INFO kernel: [ 2337.835270] vmw_vmci 0000:00:07.7: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 1 usecs
2024-04-26T16:45:33.566690Z INFO kernel: [ 2337.978626] pci 0000:00:11.0: PM:
pci_pm_suspend_late+0x0/0x3a returned 0 after 1 usecs
2024-04-26T16:45:33.566692Z DEBUG kernel: [ 2337.980013] PM: late suspend of devices
complete after 155.725 msecs
2024-04-26T16:45:33.566695Z INFO kernel: [ 2337.983970] nvme 0000:03:00.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 771, parent: 0000:00:15.0
2024-04-26T16:45:33.566700Z INFO kernel: [ 2337.983970] ehci-pci 0000:02:03.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 18922, parent: 0000:00:11.0
2024-04-26T16:45:33.566704Z INFO kernel: [ 2337.984212] snd_hda_intel 0000:02:02.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 9, parent: 0000:00:11.0
2024-04-26T16:45:33.566709Z INFO kernel: [ 2337.984503] e1000 0000:02:01.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 22324, parent: 0000:00:11.0
2024-04-26T16:45:33.566712Z INFO kernel: [ 2337.985005] uhci_hcd 0000:02:00.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25705, parent: 0000:00:11.0
2024-04-26T16:45:33.566782Z INFO kernel: [ 2337.985514] uhci_hcd 0000:02:00.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 503 usecs
2024-04-26T16:45:33.566790Z INFO kernel: [ 2337.987508] pcieport 0000:00:18.7: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25705, parent: pci0000:00
2024-04-26T16:45:33.566795Z INFO kernel: [ 2337.989668] pcieport 0000:00:18.6: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25708, parent: pci0000:00
2024-04-26T16:45:33.566799Z INFO kernel: [ 2337.989709] pcieport 0000:00:18.5: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25707, parent: pci0000:00
2024-04-26T16:45:33.566803Z INFO kernel: [ 2337.990985] pcieport 0000:00:18.5: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1266 usecs
2024-04-26T16:45:33.576539Z INFO kernel: [ 2337.991012] pcieport 0000:00:18.4: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25707, parent: pci0000:00
2024-04-26T16:45:33.576571Z INFO kernel: [ 2337.991681] pcieport 0000:00:18.4: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 661 usecs
2024-04-26T16:45:33.576576Z INFO kernel: [ 2337.991694] pcieport 0000:00:18.3: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25707, parent: pci0000:00
2024-04-26T16:45:33.576579Z INFO kernel: [ 2337.992719] pcieport 0000:00:18.3: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1018 usecs
2024-04-26T16:45:33.576582Z INFO kernel: [ 2337.992734] pcieport 0000:00:18.2: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25707, parent: pci0000:00
2024-04-26T16:45:33.576586Z INFO kernel: [ 2337.993295] pcieport 0000:00:18.2: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 556 usecs
2024-04-26T16:45:33.579116Z INFO kernel: [ 2337.993301] pcieport 0000:00:18.1: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25707, parent: pci0000:00
```

```
2024-04-26T16:45:33.579142Z INFO kernel: [ 2337.993983] pcieport 0000:00:18.1: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 678 usecs
2024-04-26T16:45:33.579148Z INFO kernel: [ 2337.994666] pcieport 0000:00:18.7: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 873 usecs
2024-04-26T16:45:33.579153Z INFO kernel: [ 2337.994676] pcieport 0000:00:18.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25705, parent: pci0000:00
2024-04-26T16:45:33.579157Z INFO kernel: [ 2337.995294] pcieport 0000:00:18.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 615 usecs
2024-04-26T16:45:33.579312Z INFO kernel: [ 2337.995300] pcieport 0000:00:17.7: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25705, parent: pci0000:00
2024-04-26T16:45:33.579853Z INFO kernel: [ 2337.995819] pcieport 0000:00:17.7: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 515 usecs
2024-04-26T16:45:33.579869Z INFO kernel: [ 2337.995824] pcieport 0000:00:17.6: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25705, parent: pci0000:00
2024-04-26T16:45:33.579874Z INFO kernel: [ 2337.996214] e1000 0000:02:01.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 11702 usecs
2024-04-26T16:45:33.579878Z INFO kernel: [ 2337.996220] pcieport 0000:00:17.5: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 22324, parent: pci0000:00
2024-04-26T16:45:33.579883Z INFO kernel: [ 2337.996758] pcieport 0000:00:17.4: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25703, parent: pci0000:00
2024-04-26T16:45:33.579886Z INFO kernel: [ 2337.996773] pcieport 0000:00:17.5: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 527 usecs
2024-04-26T16:45:33.579956Z INFO kernel: [ 2337.997620] pcieport 0000:00:17.4: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 852 usecs
2024-04-26T16:45:33.579963Z INFO kernel: [ 2337.997631] pcieport 0000:00:17.3: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25703, parent: pci0000:00
2024-04-26T16:45:33.579967Z INFO kernel: [ 2337.998334] pcieport 0000:00:17.3: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 697 usecs
2024-04-26T16:45:33.579971Z INFO kernel: [ 2337.998342] pcieport 0000:00:17.2: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25703, parent: pci0000:00
2024-04-26T16:45:33.579975Z INFO kernel: [ 2337.999257] nvme 0000:03:00.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 12698 usecs
2024-04-26T16:45:33.579980Z INFO kernel: [ 2337.999272] pcieport 0000:00:17.1: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 771, parent: pci0000:00
2024-04-26T16:45:33.579984Z INFO kernel: [ 2337.999374] pcieport 0000:00:17.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25707, parent: pci0000:00
2024-04-26T16:45:33.579989Z INFO kernel: [ 2337.999404] pcieport 0000:00:17.2: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1057 usecs
2024-04-26T16:45:33.579995Z INFO kernel: [ 2337.999466] pcieport 0000:00:16.7: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25703, parent: pci0000:00
2024-04-26T16:45:33.580000Z INFO kernel: [ 2338.000429] pcieport 0000:00:17.1: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1152 usecs
2024-04-26T16:45:33.580004Z INFO kernel: [ 2338.000766] pcieport 0000:00:16.7: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1294 usecs
2024-04-26T16:45:33.580110Z INFO kernel: [ 2338.000784] pcieport 0000:00:16.6: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25703, parent: pci0000:00
2024-04-26T16:45:33.580527Z INFO kernel: [ 2338.001196] pcieport 0000:00:16.5: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25613, parent: pci0000:00
2024-04-26T16:45:33.580538Z INFO kernel: [ 2338.001456] pcieport 0000:00:17.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 2073 usecs
2024-04-26T16:45:33.580541Z INFO kernel: [ 2338.001473] pcieport 0000:00:16.4: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25707, parent: pci0000:00
2024-04-26T16:45:33.580545Z INFO kernel: [ 2338.002536] pcieport 0000:00:16.5: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1334 usecs
2024-04-26T16:45:33.580613Z INFO kernel: [ 2338.002636] pcieport 0000:00:16.3: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25613, parent: pci0000:00
2024-04-26T16:45:33.580620Z INFO kernel: [ 2338.002642] pcieport 0000:00:16.4: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1163 usecs
2024-04-26T16:45:33.580624Z INFO kernel: [ 2338.002654] pcieport 0000:00:16.2: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25707, parent: pci0000:00
2024-04-26T16:45:33.580628Z INFO kernel: [ 2338.002821] pcieport 0000:00:16.1: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25576, parent: pci0000:00
2024-04-26T16:45:33.580632Z INFO kernel: [ 2338.003756] pcieport 0000:00:16.3: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1114 usecs
2024-04-26T16:45:33.580636Z INFO kernel: [ 2338.003790] pcieport 0000:00:16.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25613, parent: pci0000:00
2024-04-26T16:45:33.580688Z INFO kernel: [ 2338.003833] pcieport 0000:00:16.2: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1175 usecs
2024-04-26T16:45:33.580695Z INFO kernel: [ 2338.003845] pcieport 0000:00:15.7: PM:
```



```
calling pci_pm_suspend_noirq+0x0/0x200 @ 25707, parent: pci0000:00
2024-04-26T16:45:33.580698Z INFO kernel: [ 2338.004840] pcieport 0000:00:16.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1045 usecs
2024-04-26T16:45:33.580702Z INFO kernel: [ 2338.004858] pcieport 0000:00:15.6: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25613, parent: pci0000:00
2024-04-26T16:45:33.580705Z INFO kernel: [ 2338.004979] pcieport 0000:00:15.7: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1128 usecs
2024-04-26T16:45:33.580709Z INFO kernel: [ 2338.004991] pcieport 0000:00:15.5: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25707, parent: pci0000:00
2024-04-26T16:45:33.580762Z INFO kernel: [ 2338.005181] pcieport 0000:00:15.4: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25704, parent: pci0000:00
2024-04-26T16:45:33.580769Z INFO kernel: [ 2338.005532] pcieport 0000:00:15.3: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 771, parent: pci0000:00
2024-04-26T16:45:33.580773Z INFO kernel: [ 2338.006068] pcieport 0000:00:15.5: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1072 usecs
2024-04-26T16:45:33.580776Z INFO kernel: [ 2338.006079] pcieport 0000:00:15.2: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25707, parent: pci0000:00
2024-04-26T16:45:33.580780Z INFO kernel: [ 2338.006247] pcieport 0000:00:15.4: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1062 usecs
2024-04-26T16:45:33.580784Z INFO kernel: [ 2338.006281] pcieport 0000:00:15.1: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25704, parent: pci0000:00
2024-04-26T16:45:33.581364Z INFO kernel: [ 2338.006929] pcieport 0000:00:15.2: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 846 usecs
2024-04-26T16:45:33.581375Z INFO kernel: [ 2338.006938] pcieport 0000:00:15.0: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25707, parent: pci0000:00
2024-04-26T16:45:33.581381Z INFO kernel: [ 2338.007442] pcieport 0000:00:15.1: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1156 usecs
2024-04-26T16:45:33.581386Z INFO kernel: [ 2338.008007] pcieport 0000:00:15.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1065 usecs
2024-04-26T16:45:33.581390Z INFO kernel: [ 2338.008016] pci 0000:00:10.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 25707, parent: pci0000:00
2024-04-26T16:45:33.581600Z INFO kernel: [ 2338.008174] pcieport 0000:00:15.6: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 3312 usecs
2024-04-26T16:45:33.581611Z INFO kernel: [ 2338.008711] vmwgfx 0000:00:0f.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 25613, parent: pci0000:00
2024-04-26T16:45:33.581615Z INFO kernel: [ 2338.008717] vmwgfx 0000:00:0f.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 0 usecs
2024-04-26T16:45:33.581620Z INFO kernel: [ 2338.008723] vmw_vmci 0000:00:07.7: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25613, parent: pci0000:00
2024-04-26T16:45:33.581622Z INFO kernel: [ 2338.009019] pcieport 0000:00:16.1: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 837 usecs
2024-04-26T16:45:33.581625Z INFO kernel: [ 2338.009026] pci 0000:00:07.3: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 25576, parent: pci0000:00
2024-04-26T16:45:33.581691Z INFO kernel: [ 2338.009426] vmw_vmci 0000:00:07.7: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 698 usecs
2024-04-26T16:45:33.581699Z INFO kernel: [ 2338.009434] ata_piix 0000:00:07.1: PM:
calling pci_pm_suspend_noirq+0x0/0x200 @ 25613, parent: pci0000:00
2024-04-26T16:45:33.581704Z INFO kernel: [ 2338.009439] ata_piix 0000:00:07.1: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 0 usecs
2024-04-26T16:45:33.581708Z INFO kernel: [ 2338.009445] pci 0000:00:07.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 25613, parent: pci0000:00
2024-04-26T16:45:33.581712Z INFO kernel: [ 2338.010120] pci 0000:00:07.3: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1089 usecs
2024-04-26T16:45:33.581717Z INFO kernel: [ 2338.010172] pci 0000:00:01.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 22324, parent: pci0000:00
2024-04-26T16:45:33.611415Z INFO kernel: [ 2338.010459] pci 0000:00:07.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1009 usecs
2024-04-26T16:45:33.611438Z INFO kernel: [ 2338.010466] pci 0000:00:00.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 25613, parent: pci0000:00
2024-04-26T16:45:33.611442Z INFO kernel: [ 2338.010851] pci 0000:00:00.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 382 usecs
2024-04-26T16:45:33.611445Z INFO kernel: [ 2338.011857] pcieport 0000:00:16.6: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 11068 usecs
2024-04-26T16:45:33.611448Z INFO kernel: [ 2338.012497] pcieport 0000:00:15.3: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1575 usecs
2024-04-26T16:45:33.611450Z INFO kernel: [ 2338.013310] pci 0000:00:01.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 3132 usecs
2024-04-26T16:45:33.616286Z INFO kernel: [ 2338.013749] pcieport 0000:00:17.6: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 17920 usecs
```

```
2024-04-26T16:45:33.616378Z INFO kernel: [ 2338.015102] ehci-pci 0000:02:03.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 31119 usecs
2024-04-26T16:45:33.616392Z INFO kernel: [ 2338.015284] pcieport 0000:00:18.6: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 2207 usecs
2024-04-26T16:45:33.616396Z INFO kernel: [ 2338.015357] pci 0000:00:10.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 1180 usecs
2024-04-26T16:45:33.616399Z INFO kernel: [ 2338.028283] snd_hda_intel 0000:02:02.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 11882 usecs
2024-04-26T16:45:33.616402Z INFO kernel: [ 2338.158385] pci 0000:00:11.0: PM: calling
pci_pm_suspend_noirq+0x0/0x200 @ 25704, parent: pci0000:00
2024-04-26T16:45:33.616480Z INFO kernel: [ 2338.161488] pci 0000:00:11.0: PM:
pci_pm_suspend_noirq+0x0/0x200 returned 0 after 397 usecs
2024-04-26T16:45:33.616488Z DEBUG kernel: [ 2338.164547] PM: noirq suspend of devices
complete after 180.894 msecs
2024-04-26T16:45:33.616497Z DEBUG kernel: [ 2338.164617] PM: suspend-to-idle
2024-04-26T16:45:33.616504Z ERR kernel: [ 2359.226898] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616507Z WARNING kernel: [ 2359.228790] hwrng: no data available
2024-04-26T16:45:33.616511Z ERR kernel: [ 2371.497517] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616584Z WARNING kernel: [ 2371.498672] hwrng: no data available
2024-04-26T16:45:33.616594Z ERR kernel: [ 2383.784367] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616599Z WARNING kernel: [ 2383.785538] hwrng: no data available
2024-04-26T16:45:33.616604Z ERR kernel: [ 2396.072016] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616608Z WARNING kernel: [ 2396.073221] hwrng: no data available
2024-04-26T16:45:33.616613Z ERR kernel: [ 2408.361998] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616617Z WARNING kernel: [ 2408.364382] hwrng: no data available
2024-04-26T16:45:33.616714Z ERR kernel: [ 2420.648065] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616722Z WARNING kernel: [ 2420.649854] hwrng: no data available
2024-04-26T16:45:33.616727Z ERR kernel: [ 2432.935198] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616731Z WARNING kernel: [ 2432.936622] hwrng: no data available
2024-04-26T16:45:33.616735Z ERR kernel: [ 2445.284540] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616740Z WARNING kernel: [ 2445.286768] hwrng: no data available
2024-04-26T16:45:33.616809Z ERR kernel: [ 2457.512004] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616819Z WARNING kernel: [ 2457.513172] hwrng: no data available
2024-04-26T16:45:33.616822Z ERR kernel: [ 2469.799298] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616826Z WARNING kernel: [ 2469.800777] hwrng: no data available
2024-04-26T16:45:33.616829Z ERR kernel: [ 2482.098324] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616832Z WARNING kernel: [ 2482.099893] hwrng: no data available
2024-04-26T16:45:33.616887Z ERR kernel: [ 2494.375404] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616894Z WARNING kernel: [ 2494.376627] hwrng: no data available
2024-04-26T16:45:33.616897Z ERR kernel: [ 2506.663558] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616901Z WARNING kernel: [ 2506.679070] hwrng: no data available
2024-04-26T16:45:33.616905Z ERR kernel: [ 2518.951288] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616909Z WARNING kernel: [ 2518.952905] hwrng: no data available
2024-04-26T16:45:33.616912Z ERR kernel: [ 2531.239951] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616966Z WARNING kernel: [ 2531.241240] hwrng: no data available
2024-04-26T16:45:33.616974Z ERR kernel: [ 2543.527591] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616979Z WARNING kernel: [ 2543.531532] hwrng: no data available
2024-04-26T16:45:33.616982Z ERR kernel: [ 2555.817112] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.616985Z WARNING kernel: [ 2555.819215] hwrng: no data available
2024-04-26T16:45:33.616988Z ERR kernel: [ 2568.104036] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.617555Z WARNING kernel: [ 2568.105612] hwrng: no data available
2024-04-26T16:45:33.617574Z ERR kernel: [ 2580.392131] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.617648Z WARNING kernel: [ 2580.394136] hwrng: no data available
2024-04-26T16:45:33.617654Z ERR kernel: [ 2592.699582] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.617656Z WARNING kernel: [ 2592.701212] hwrng: no data available
2024-04-26T16:45:33.617659Z ERR kernel: [ 2604.973916] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.617661Z WARNING kernel: [ 2604.975605] hwrng: no data available
2024-04-26T16:45:33.617783Z ERR kernel: [ 2617.255939] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.617853Z WARNING kernel: [ 2617.345451] hwrng: no data available
2024-04-26T16:45:33.617928Z ERR kernel: [ 2629.551019] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.617935Z WARNING kernel: [ 2629.553611] hwrng: no data available
2024-04-26T16:45:33.617938Z ERR kernel: [ 2641.831275] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.617941Z WARNING kernel: [ 2641.833085] hwrng: no data available
2024-04-26T16:45:33.617945Z ERR kernel: [ 2654.143164] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.618082Z WARNING kernel: [ 2654.145855] hwrng: no data available
2024-04-26T16:45:33.618092Z ERR kernel: [ 2666.408000] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.618097Z WARNING kernel: [ 2666.412984] hwrng: no data available
2024-04-26T16:45:33.618101Z ERR kernel: [ 2678.695413] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.618105Z WARNING kernel: [ 2678.700203] hwrng: no data available
```

```
2024-04-26T16:45:33.618270Z WARNING kernel: [ 2690.501558] PM: pm_system_irq_wakeup: 12
triggered i8042
2024-04-26T16:45:33.618278Z DEBUG kernel: [ 2690.538561] PM: Wakeup unrelated to ACPI SCI
2024-04-26T16:45:33.618362Z DEBUG kernel: [ 2690.538570] PM: resume from suspend-to-idle
2024-04-26T16:45:33.618371Z INFO kernel: [ 2690.540842] pci 0000:00:00.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 25704, parent: pci0000:00
2024-04-26T16:45:33.618376Z INFO kernel: [ 2690.543560] pci 0000:00:01.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 25613, parent: pci0000:00
2024-04-26T16:45:33.618380Z INFO kernel: [ 2690.555431] pci 0000:00:00.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 8644 usecs
2024-04-26T16:45:33.618385Z INFO kernel: [ 2690.556171] pci 0000:00:01.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 679 usecs
2024-04-26T16:45:33.618389Z INFO kernel: [ 2690.561517] pci 0000:00:07.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 25704, parent: pci0000:00
2024-04-26T16:45:33.618455Z INFO kernel: [ 2690.562042] pci 0000:00:07.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 506 usecs
2024-04-26T16:45:33.618463Z INFO kernel: [ 2690.566412] ata_piix 0000:00:07.1: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25710, parent: pci0000:00
2024-04-26T16:45:33.618468Z INFO kernel: [ 2690.566450] pci 0000:00:07.3: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 25613, parent: pci0000:00
2024-04-26T16:45:33.618472Z INFO kernel: [ 2690.567018] ata_piix 0000:00:07.1: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 588 usecs
2024-04-26T16:45:33.618474Z INFO kernel: [ 2690.567033] vmw_vmci 0000:00:07.7: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25710, parent: pci0000:00
2024-04-26T16:45:33.618531Z INFO kernel: [ 2690.570967] vmw_vmci 0000:00:07.7: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 3923 usecs
2024-04-26T16:45:33.618537Z INFO kernel: [ 2690.570990] vmwgfx 0000:00:0f.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 25710, parent: pci0000:00
2024-04-26T16:45:33.618542Z INFO kernel: [ 2690.570999] vmwgfx 0000:00:0f.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 1 usecs
2024-04-26T16:45:33.618545Z INFO kernel: [ 2690.571005] pci 0000:00:10.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 25710, parent: pci0000:00
2024-04-26T16:45:33.618549Z INFO kernel: [ 2690.571616] pci 0000:00:10.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 604 usecs
2024-04-26T16:45:33.618553Z INFO kernel: [ 2690.571626] pci 0000:00:11.0: PM: calling
pci_pm_resume_noirq+0x0/0xf1 @ 25710, parent: pci0000:00
2024-04-26T16:45:33.629000Z INFO kernel: [ 2690.571632] pci 0000:00:11.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 0 usecs
2024-04-26T16:45:33.629073Z INFO kernel: [ 2690.571639] pcieport 0000:00:15.0: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25710, parent: pci0000:00
2024-04-26T16:45:33.629081Z INFO kernel: [ 2690.571833] pcieport 0000:00:15.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 187 usecs
2024-04-26T16:45:33.629085Z INFO kernel: [ 2690.571841] pcieport 0000:00:15.1: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25710, parent: pci0000:00
2024-04-26T16:45:33.629089Z INFO kernel: [ 2690.571913] pcieport 0000:00:15.1: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 67 usecs
2024-04-26T16:45:33.629093Z INFO kernel: [ 2690.571920] pcieport 0000:00:15.2: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25710, parent: pci0000:00
2024-04-26T16:45:33.629176Z INFO kernel: [ 2690.571991] pcieport 0000:00:15.2: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 65 usecs
2024-04-26T16:45:33.629183Z INFO kernel: [ 2690.571998] pcieport 0000:00:15.3: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25710, parent: pci0000:00
2024-04-26T16:45:33.629186Z INFO kernel: [ 2690.572282] pcieport 0000:00:15.3: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 277 usecs
2024-04-26T16:45:33.629190Z INFO kernel: [ 2690.572290] pcieport 0000:00:15.4: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25710, parent: pci0000:00
2024-04-26T16:45:33.629194Z INFO kernel: [ 2690.572380] pcieport 0000:00:15.4: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 84 usecs
2024-04-26T16:45:33.629198Z INFO kernel: [ 2690.572403] pcieport 0000:00:15.5: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25704, parent: pci0000:00
2024-04-26T16:45:33.629261Z INFO kernel: [ 2690.572542] pcieport 0000:00:15.5: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 123 usecs
2024-04-26T16:45:33.629270Z INFO kernel: [ 2690.572555] pcieport 0000:00:15.6: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25704, parent: pci0000:00
2024-04-26T16:45:33.629275Z INFO kernel: [ 2690.572672] pcieport 0000:00:15.6: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 107 usecs
2024-04-26T16:45:33.629279Z INFO kernel: [ 2690.572682] pcieport 0000:00:15.7: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25704, parent: pci0000:00
2024-04-26T16:45:33.629284Z INFO kernel: [ 2690.572775] pcieport 0000:00:15.7: PM:
```

```
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 85 usecs
2024-04-26T16:45:33.629287Z INFO kernel: [ 2690.572819] i8042 i8042: PM: calling
i8042_pm_resume_noirq+0x0/0x21 @ 25702, parent: platform
2024-04-26T16:45:33.629344Z INFO kernel: [ 2690.574218] i8042 i8042: PM:
i8042_pm_resume_noirq+0x0/0x21 returned 0 after 232 usecs
2024-04-26T16:45:33.629350Z INFO kernel: [ 2690.574279] pcieport 0000:00:16.0: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629354Z INFO kernel: [ 2690.574392] pcieport 0000:00:16.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 104 usecs
2024-04-26T16:45:33.629358Z INFO kernel: [ 2690.574403] pcieport 0000:00:16.1: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629363Z INFO kernel: [ 2690.574495] pcieport 0000:00:16.1: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 83 usecs
2024-04-26T16:45:33.629367Z INFO kernel: [ 2690.574505] pcieport 0000:00:16.2: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629428Z INFO kernel: [ 2690.574596] pcieport 0000:00:16.2: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 84 usecs
2024-04-26T16:45:33.629435Z INFO kernel: [ 2690.574606] pcieport 0000:00:16.3: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629438Z INFO kernel: [ 2690.574693] pcieport 0000:00:16.3: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 79 usecs
2024-04-26T16:45:33.629440Z INFO kernel: [ 2690.574701] pcieport 0000:00:16.4: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629443Z INFO kernel: [ 2690.574786] pcieport 0000:00:16.4: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 78 usecs
2024-04-26T16:45:33.629446Z INFO kernel: [ 2690.574795] pcieport 0000:00:16.5: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629504Z INFO kernel: [ 2690.574881] pcieport 0000:00:16.5: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 79 usecs
2024-04-26T16:45:33.629514Z INFO kernel: [ 2690.574890] pcieport 0000:00:16.6: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629520Z INFO kernel: [ 2690.574975] pcieport 0000:00:16.6: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 79 usecs
2024-04-26T16:45:33.629523Z INFO kernel: [ 2690.574984] pcieport 0000:00:16.7: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629525Z INFO kernel: [ 2690.575070] pcieport 0000:00:16.7: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 79 usecs
2024-04-26T16:45:33.629527Z INFO kernel: [ 2690.575080] pcieport 0000:00:17.0: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629586Z INFO kernel: [ 2690.575231] pcieport 0000:00:17.0: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 144 usecs
2024-04-26T16:45:33.629590Z INFO kernel: [ 2690.575241] pcieport 0000:00:17.1: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629593Z INFO kernel: [ 2690.575329] pcieport 0000:00:17.1: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 81 usecs
2024-04-26T16:45:33.629595Z INFO kernel: [ 2690.575338] pcieport 0000:00:17.2: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629598Z INFO kernel: [ 2690.575425] pcieport 0000:00:17.2: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 80 usecs
2024-04-26T16:45:33.629652Z INFO kernel: [ 2690.575434] pcieport 0000:00:17.3: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629658Z INFO kernel: [ 2690.575520] pcieport 0000:00:17.3: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 78 usecs
2024-04-26T16:45:33.629661Z INFO kernel: [ 2690.575529] pcieport 0000:00:17.4: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629664Z INFO kernel: [ 2690.575614] pcieport 0000:00:17.4: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 77 usecs
2024-04-26T16:45:33.629666Z INFO kernel: [ 2690.575625] pcieport 0000:00:17.5: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629669Z INFO kernel: [ 2690.575712] pcieport 0000:00:17.5: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 79 usecs
2024-04-26T16:45:33.629721Z INFO kernel: [ 2690.575720] pcieport 0000:00:17.6: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629727Z INFO kernel: [ 2690.575805] pcieport 0000:00:17.6: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 77 usecs
2024-04-26T16:45:33.629730Z INFO kernel: [ 2690.575814] pcieport 0000:00:17.7: PM:
calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629734Z INFO kernel: [ 2690.575900] pcieport 0000:00:17.7: PM:
pci_pm_resume_noirq+0x0/0xf1 returned 0 after 80 usecs
```

2024-04-26T16:45:33.629739Z INFO kernel: [2690.575909] pcieport 0000:00:18.0: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629744Z INFO kernel: [2690.575994] pcieport 0000:00:18.0: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 77 usecs
2024-04-26T16:45:33.629806Z INFO kernel: [2690.576002] pcieport 0000:00:18.1: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629815Z INFO kernel: [2690.576087] pcieport 0000:00:18.1: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 79 usecs
2024-04-26T16:45:33.629819Z INFO kernel: [2690.576096] pcieport 0000:00:18.2: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629823Z INFO kernel: [2690.576249] pcieport 0000:00:18.2: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 146 usecs
2024-04-26T16:45:33.629828Z INFO kernel: [2690.576259] pcieport 0000:00:18.3: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.629831Z INFO kernel: [2690.576346] pcieport 0000:00:18.3: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 80 usecs
2024-04-26T16:45:33.629885Z INFO kernel: [2690.576439] pcieport 0000:00:18.4: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.630111Z INFO kernel: [2690.576529] pcieport 0000:00:18.4: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 82 usecs
2024-04-26T16:45:33.630119Z INFO kernel: [2690.576538] pcieport 0000:00:18.5: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.630122Z INFO kernel: [2690.576626] pcieport 0000:00:18.5: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 81 usecs
2024-04-26T16:45:33.630124Z INFO kernel: [2690.576697] pcieport 0000:00:18.6: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.630127Z INFO kernel: [2690.576794] pcieport 0000:00:18.6: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 90 usecs
2024-04-26T16:45:33.630130Z INFO kernel: [2690.576802] pcieport 0000:00:18.7: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: pci0000:00
2024-04-26T16:45:33.630133Z INFO kernel: [2690.576926] pcieport 0000:00:18.7: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 117 usecs
2024-04-26T16:45:33.630135Z INFO kernel: [2690.576938] uhci_hcd 0000:02:00.0: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: 0000:00:11.0
2024-04-26T16:45:33.630138Z INFO kernel: [2690.576946] uhci_hcd 0000:02:00.0: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 1 usecs
2024-04-26T16:45:33.630140Z INFO kernel: [2690.576956] e1000 0000:02:01.0: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 25711, parent: 0000:00:11.0
2024-04-26T16:45:33.631840Z INFO kernel: [2690.578384] pci 0000:00:07.3: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 1557 usecs
2024-04-26T16:45:33.631860Z INFO kernel: [2690.580851] snd_hda_intel 0000:02:02.0: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 25704, parent: 0000:00:11.0
2024-04-26T16:45:33.631865Z INFO kernel: [2690.583675] ehci-pci 0000:02:03.0: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 25710, parent: 0000:00:11.0
2024-04-26T16:45:33.631868Z INFO kernel: [2690.583918] nvme 0000:03:00.0: PM: calling pci_pm_resume_noirq+0x0/0xf1 @ 25712, parent: 0000:00:15.0
2024-04-26T16:45:33.631872Z INFO kernel: [2690.602149] e1000 0000:02:01.0: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 25182 usecs
2024-04-26T16:45:33.631875Z INFO kernel: [2690.602568] nvme 0000:03:00.0: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 18635 usecs
2024-04-26T16:45:33.631998Z INFO kernel: [2690.603944] snd_hda_intel 0000:02:02.0: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 22940 usecs
2024-04-26T16:45:33.632069Z INFO kernel: [2690.606174] ehci-pci 0000:02:03.0: PM: pci_pm_resume_noirq+0x0/0xf1 returned 0 after 2 usecs
2024-04-26T16:45:33.632075Z ERR kernel: [2690.984208] tpm tpm0: Operation Timed out
2024-04-26T16:45:33.632079Z DEBUG kernel: [2690.993921] PM: noirq resume of devices complete after 455.289 msecs
2024-04-26T16:45:33.632082Z WARNING kernel: [2691.001637] hwrng: no data available
2024-04-26T16:45:33.632086Z INFO kernel: [2691.015427] pci 0000:00:00.0: PM: calling pci_pm_resume_early+0x0/0x29 @ 25716, parent: pci0000:00
2024-04-26T16:45:33.632705Z INFO kernel: [2691.015891] pci 0000:00:01.0: PM: calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.632722Z INFO kernel: [2691.016505] pci 0000:00:01.0: PM: pci_pm_resume_early+0x0/0x29 returned 0 after 600 usecs
2024-04-26T16:45:33.632726Z INFO kernel: [2691.016523] pci 0000:00:07.0: PM: calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.632730Z INFO kernel: [2691.016531] pci 0000:00:07.0: PM: pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.632733Z INFO kernel: [2691.016612] ata_piix 0000:00:07.1: PM:

```
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.632737Z INFO kernel: [ 2691.016622] ata_piix 0000:00:07.1: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.632809Z INFO kernel: [ 2691.016630] pci 0000:00:07.3: PM: calling
pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.632817Z INFO kernel: [ 2691.016637] pci 0000:00:07.3: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.632822Z INFO kernel: [ 2691.016644] vmw_vmci 0000:00:07.7: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.632825Z INFO kernel: [ 2691.016652] vmw_vmci 0000:00:07.7: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.632827Z INFO kernel: [ 2691.016659] vmwgfx 0000:00:0f.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.632830Z INFO kernel: [ 2691.016667] vmwgfx 0000:00:0f.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.638663Z INFO kernel: [ 2691.016676] pci 0000:00:10.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.638688Z INFO kernel: [ 2691.016682] pci 0000:00:10.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.638693Z INFO kernel: [ 2691.016689] pci 0000:00:11.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.638699Z INFO kernel: [ 2691.016695] pci 0000:00:11.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.638703Z INFO kernel: [ 2691.016705] pcieport 0000:00:15.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.639435Z INFO kernel: [ 2691.016712] pcieport 0000:00:15.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.639454Z INFO kernel: [ 2691.017232] pcieport 0000:00:15.1: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.639460Z INFO kernel: [ 2691.017241] pcieport 0000:00:15.1: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.639464Z INFO kernel: [ 2691.017297] pcieport 0000:00:15.2: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.639469Z INFO kernel: [ 2691.017303] pcieport 0000:00:15.2: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.639473Z INFO kernel: [ 2691.017309] pcieport 0000:00:15.3: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.639557Z INFO kernel: [ 2691.017314] pcieport 0000:00:15.3: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.639571Z INFO kernel: [ 2691.017320] pcieport 0000:00:15.4: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.639578Z INFO kernel: [ 2691.017325] pcieport 0000:00:15.4: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.639582Z INFO kernel: [ 2691.017330] pcieport 0000:00:15.5: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.639585Z INFO kernel: [ 2691.017335] pcieport 0000:00:15.5: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.639632Z INFO kernel: [ 2691.017382] pcieport 0000:00:15.6: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.639704Z INFO kernel: [ 2691.017387] pcieport 0000:00:15.6: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.639715Z INFO kernel: [ 2691.017393] pcieport 0000:00:15.7: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.639720Z INFO kernel: [ 2691.017397] pcieport 0000:00:15.7: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.639724Z INFO kernel: [ 2691.017403] pcieport 0000:00:16.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.639728Z INFO kernel: [ 2691.017408] pcieport 0000:00:16.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.639731Z INFO kernel: [ 2691.017413] pcieport 0000:00:16.1: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.640268Z INFO kernel: [ 2691.017418] pcieport 0000:00:16.1: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.640285Z INFO kernel: [ 2691.017423] pcieport 0000:00:16.2: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.640291Z INFO kernel: [ 2691.017428] pcieport 0000:00:16.2: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.640295Z INFO kernel: [ 2691.017434] pcieport 0000:00:16.3: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
```



```
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.641712Z INFO kernel: [ 2691.017735] pcieport 0000:00:18.5: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.641714Z INFO kernel: [ 2691.017740] pcieport 0000:00:18.5: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.641766Z INFO kernel: [ 2691.017746] pcieport 0000:00:18.6: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.641771Z INFO kernel: [ 2691.017750] pcieport 0000:00:18.6: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.641774Z INFO kernel: [ 2691.017756] pcieport 0000:00:18.7: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: pci0000:00
2024-04-26T16:45:33.641777Z INFO kernel: [ 2691.017760] pcieport 0000:00:18.7: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.641779Z INFO kernel: [ 2691.017766] uhci_hcd 0000:02:00.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: 0000:00:11.0
2024-04-26T16:45:33.642416Z INFO kernel: [ 2691.017771] uhci_hcd 0000:02:00.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.642433Z INFO kernel: [ 2691.017777] e1000 0000:02:01.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 25714, parent: 0000:00:11.0
2024-04-26T16:45:33.642437Z INFO kernel: [ 2691.017783] e1000 0000:02:01.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.642439Z INFO kernel: [ 2691.017789] snd_hda_intel 0000:02:02.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: 0000:00:11.0
2024-04-26T16:45:33.642441Z INFO kernel: [ 2691.017795] snd_hda_intel 0000:02:02.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.642444Z INFO kernel: [ 2691.017800] ehci-pci 0000:02:03.0: PM:
calling pci_pm_resume_early+0x0/0x29 @ 25714, parent: 0000:00:11.0
2024-04-26T16:45:33.643635Z INFO kernel: [ 2691.017805] ehci-pci 0000:02:03.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.643653Z INFO kernel: [ 2691.017811] nvme 0000:03:00.0: PM: calling
pci_pm_resume_early+0x0/0x29 @ 25714, parent: 0000:00:15.0
2024-04-26T16:45:33.643658Z INFO kernel: [ 2691.017818] nvme 0000:03:00.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 0 usecs
2024-04-26T16:45:33.643661Z INFO kernel: [ 2692.379469] pci 0000:00:00.0: PM:
pci_pm_resume_early+0x0/0x29 returned 0 after 1 usecs
2024-04-26T16:45:33.643665Z DEBUG kernel: [ 2692.384628] PM: early resume of devices
complete after 1369.905 msecs
2024-04-26T16:45:33.643668Z INFO kernel: [ 2692.386243] pci 0000:00:00.0: PM: calling
pci_pm_resume+0x0/0xed @ 25717, parent: pci0000:00
2024-04-26T16:45:33.643762Z INFO kernel: [ 2692.386376] ac ACPI0003:00: PM: calling
acpi_ac_resume+0x0/0x58 @ 25702, parent: LNXSYBUS:00
2024-04-26T16:45:33.643772Z INFO kernel: [ 2692.391669] pci 0000:00:00.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 3 usecs
2024-04-26T16:45:33.643776Z INFO kernel: [ 2692.395769] pci 0000:00:01.0: PM: calling
pci_pm_resume+0x0/0xed @ 25714, parent: pci0000:00
2024-04-26T16:45:33.643778Z INFO kernel: [ 2692.395791] pci 0000:00:01.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 3 usecs
2024-04-26T16:45:33.643780Z INFO kernel: [ 2692.395809] pci 0000:00:07.0: PM: calling
pci_pm_resume+0x0/0xed @ 25714, parent: pci0000:00
2024-04-26T16:45:33.643783Z INFO kernel: [ 2692.395818] pci 0000:00:07.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 0 usecs
2024-04-26T16:45:33.643785Z INFO kernel: [ 2692.395829] ata_piix 0000:00:07.1: PM:
calling pci_pm_resume+0x0/0xed @ 25714, parent: pci0000:00
2024-04-26T16:45:33.643857Z INFO kernel: [ 2692.396781] pci 0000:00:07.3: PM: calling
pci_pm_resume+0x0/0xed @ 25716, parent: pci0000:00
2024-04-26T16:45:33.643868Z INFO kernel: [ 2692.397617] ac ACPI0003:00: PM:
acpi_ac_resume+0x0/0x58 returned 0 after 603 usecs
2024-04-26T16:45:33.643877Z INFO kernel: [ 2692.398588] platform PNP0001:00: PM: calling
platform_pm_resume+0x0/0x41 @ 25702, parent: 0000:00:07.0
2024-04-26T16:45:33.643883Z INFO kernel: [ 2692.398711] platform PNP0001:00: PM:
platform_pm_resume+0x0/0x41 returned 0 after 1 usecs
2024-04-26T16:45:33.643886Z INFO kernel: [ 2692.398728] platform PNP0800:00: PM: calling
platform_pm_resume+0x0/0x41 @ 25702, parent: 0000:00:07.0
2024-04-26T16:45:33.643889Z INFO kernel: [ 2692.398738] platform PNP0800:00: PM:
platform_pm_resume+0x0/0x41 returned 0 after 0 usecs
2024-04-26T16:45:33.643966Z INFO kernel: [ 2692.398748] platform ACPI0003:00: PM: calling
platform_pm_resume+0x0/0x41 @ 25702, parent: platform
2024-04-26T16:45:33.643977Z INFO kernel: [ 2692.398757] platform ACPI0003:00: PM:
platform_pm_resume+0x0/0x41 returned 0 after 0 usecs
```


2024-04-26T16:45:33.643982Z INFO kernel: [2692.398789] button LNX_PWRBN:00: PM: calling acpi_button_resume+0x0/0xa9 @ 25702, parent: LNX_SYSTEM:00

2024-04-26T16:45:33.643986Z INFO kernel: [2692.398808] button LNX_PWRBN:00: PM: acpi_button_resume+0x0/0xa9 returned 0 after 1 usecs

2024-04-26T16:45:33.643991Z INFO kernel: [2692.398824] platform rtc-efi.0: PM: calling platform_pm_resume+0x0/0x41 @ 25702, parent: platform

2024-04-26T16:45:33.643995Z INFO kernel: [2692.398836] platform rtc-efi.0: PM: platform_pm_resume+0x0/0x41 returned 0 after 0 usecs

2024-04-26T16:45:33.644114Z INFO kernel: [2692.398900] platform efivars.0: PM: calling platform_pm_resume+0x0/0x41 @ 25702, parent: platform

2024-04-26T16:45:33.644123Z INFO kernel: [2692.398909] platform efivars.0: PM: platform_pm_resume+0x0/0x41 returned 0 after 0 usecs

2024-04-26T16:45:33.644128Z INFO kernel: [2692.398917] platform chromeos_acpi: PM: calling platform_pm_resume+0x0/0x41 @ 25702, parent: platform

2024-04-26T16:45:33.644133Z INFO kernel: [2692.398924] platform chromeos_acpi: PM: platform_pm_resume+0x0/0x41 returned 0 after 0 usecs

2024-04-26T16:45:33.644137Z INFO kernel: [2692.398935] system 00:00: PM: calling pnp_bus_resume+0x0/0x9d @ 25702, parent: pnp0

2024-04-26T16:45:33.644141Z INFO kernel: [2692.398948] system 00:00: PM: pnp_bus_resume+0x0/0x9d returned 0 after 2 usecs

2024-04-26T16:45:33.644218Z INFO kernel: [2692.398956] rtc_cmos 00:01: PM: calling pnp_bus_resume+0x0/0x9d @ 25702, parent: pnp0

2024-04-26T16:45:33.644227Z INFO kernel: [2692.398967] rtc_cmos 00:01: PM: pnp_bus_resume+0x0/0x9d returned 0 after 2 usecs

2024-04-26T16:45:33.644232Z INFO kernel: [2692.398975] i8042 kbd 00:02: PM: calling pnp_bus_resume+0x0/0x9d @ 25702, parent: pnp0

2024-04-26T16:45:33.644236Z INFO kernel: [2692.399056] i8042 kbd 00:02: PM: pnp_bus_resume+0x0/0x9d returned 0 after 0 usecs

2024-04-26T16:45:33.644240Z INFO kernel: [2692.399065] i8042 aux 00:03: PM: calling pnp_bus_resume+0x0/0x9d @ 25702, parent: pnp0

2024-04-26T16:45:33.644244Z INFO kernel: [2692.399073] i8042 aux 00:03: PM: pnp_bus_resume+0x0/0x9d returned 0 after 0 usecs

2024-04-26T16:45:33.644317Z INFO kernel: [2692.399081] system 00:04: PM: calling pnp_bus_resume+0x0/0x9d @ 25702, parent: pnp0

2024-04-26T16:45:33.644327Z INFO kernel: [2692.399089] system 00:04: PM: pnp_bus_resume+0x0/0x9d returned 0 after 0 usecs

2024-04-26T16:45:33.644330Z INFO kernel: [2692.399097] system 00:05: PM: calling pnp_bus_resume+0x0/0x9d @ 25702, parent: pnp0

2024-04-26T16:45:33.644332Z INFO kernel: [2692.399105] system 00:05: PM: pnp_bus_resume+0x0/0x9d returned 0 after 0 usecs

2024-04-26T16:45:33.644334Z INFO kernel: [2692.399157] platform intel_rapl_msr.0: PM: calling platform_pm_resume+0x0/0x41 @ 25702, parent: platform

2024-04-26T16:45:33.644336Z INFO kernel: [2692.399166] platform intel_rapl_msr.0: PM: platform_pm_resume+0x0/0x41 returned 0 after 0 usecs

2024-04-26T16:45:33.644338Z INFO kernel: [2692.399198] input input0: PM: calling input_dev_resume+0x0/0x42 @ 25702, parent: LNX_PWRBN:00

2024-04-26T16:45:33.644825Z INFO kernel: [2692.399212] input input0: PM: input_dev_resume+0x0/0x42 returned 0 after 1 usecs

2024-04-26T16:45:33.644841Z INFO kernel: [2692.399223] serial8250 serial8250: PM: calling platform_pm_resume+0x0/0x41 @ 25702, parent: platform

2024-04-26T16:45:33.644844Z INFO kernel: [2692.399297] serial8250 serial8250: PM: platform_pm_resume+0x0/0x41 returned 0 after 65 usecs

2024-04-26T16:45:33.644847Z INFO kernel: [2692.399328] platform Fixed MDIO bus.0: PM: calling platform_pm_resume+0x0/0x41 @ 25702, parent: platform

2024-04-26T16:45:33.644849Z INFO kernel: [2692.399336] platform Fixed MDIO bus.0: PM: platform_pm_resume+0x0/0x41 returned 0 after 0 usecs

2024-04-26T16:45:33.644852Z INFO kernel: [2692.399354] i8042 i8042: PM: calling platform_pm_resume+0x0/0x41 @ 25702, parent: platform

2024-04-26T16:45:33.644932Z INFO kernel: [2692.399367] i8042 i8042: PM: platform_pm_resume+0x0/0x41 returned 0 after 3 usecs

2024-04-26T16:45:33.645276Z INFO kernel: [2692.399383] atkbd serio0: PM: calling serio_resume+0x0/0x94 @ 25702, parent: i8042

2024-04-26T16:45:33.645286Z INFO kernel: [2692.399547] pci 0000:00:07.3: PM: pci_pm_resume+0x0/0xed returned 0 after 2746 usecs

2024-04-26T16:45:33.645290Z INFO kernel: [2692.399573] vmw_vmci 0000:00:07.7: PM: calling pci_pm_resume+0x0/0xed @ 25716, parent: pci0000:00

2024-04-26T16:45:33.645294Z INFO kernel: [2692.400325] atkbd serio0: PM: serio_resume+0x0/0x94 returned 0 after 929 usecs

2024-04-26T16:45:33.645297Z INFO kernel: [2692.400343] psmouse serio1: PM: calling

```
serio_resume+0x0/0x94 @ 25702, parent: i8042
2024-04-26T16:45:33.645378Z INFO kernel: [ 2692.400578] vmw_vmci 0000:00:07.7: PM:
pci_pm_resume+0x0/0xed returned 0 after 993 usecs
2024-04-26T16:45:33.645386Z INFO kernel: [ 2692.400600] vmwgfx 0000:00:0f.0: PM: calling
pci_pm_resume+0x0/0xed @ 25716, parent: pci0000:00
2024-04-26T16:45:33.645390Z INFO kernel: [ 2692.400948] psmouse serio1: PM:
serio_resume+0x0/0x94 returned 0 after 594 usecs
2024-04-26T16:45:33.645394Z INFO kernel: [ 2692.400968] alarmtimer alarmtimer.0.auto: PM:
calling platform_pm_resume+0x0/0x41 @ 25702, parent: rtc0
2024-04-26T16:45:33.645397Z INFO kernel: [ 2692.401547] alarmtimer alarmtimer.0.auto: PM:
platform_pm_resume+0x0/0x41 returned 0 after 564 usecs
2024-04-26T16:45:33.645401Z INFO kernel: [ 2692.401640] input input1: PM: calling
input_dev_resume+0x0/0x42 @ 25702, parent: serio0
2024-04-26T16:45:33.645466Z INFO kernel: [ 2692.402099] input input1: PM:
input_dev_resume+0x0/0x42 returned 0 after 445 usecs
2024-04-26T16:45:33.645476Z INFO kernel: [ 2692.402155] leds input1::numlock: PM: calling
led_resume+0x0/0x20 @ 25702, parent: input1
2024-04-26T16:45:33.645479Z INFO kernel: [ 2692.402170] leds input1::numlock: PM:
led_resume+0x0/0x20 returned 0 after 0 usecs
2024-04-26T16:45:33.645481Z INFO kernel: [ 2692.402180] leds input1::capslock: PM:
calling led_resume+0x0/0x20 @ 25702, parent: input1
2024-04-26T16:45:33.645483Z INFO kernel: [ 2692.402190] leds input1::capslock: PM:
led_resume+0x0/0x20 returned 0 after 0 usecs
2024-04-26T16:45:33.645486Z INFO kernel: [ 2692.402200] leds input1::scrolllock: PM:
calling led_resume+0x0/0x20 @ 25702, parent: input1
2024-04-26T16:45:33.645488Z INFO kernel: [ 2692.402209] leds input1::scrolllock: PM:
led_resume+0x0/0x20 returned 0 after 0 usecs
2024-04-26T16:45:33.645553Z INFO kernel: [ 2692.402219] input input4: PM: calling
input_dev_resume+0x0/0x42 @ 25702, parent: serio1
2024-04-26T16:45:33.645561Z INFO kernel: [ 2692.402230] input input4: PM:
input_dev_resume+0x0/0x42 returned 0 after 0 usecs
2024-04-26T16:45:33.645564Z INFO kernel: [ 2692.402240] input input3: PM: calling
input_dev_resume+0x0/0x42 @ 25702, parent: serio1
2024-04-26T16:45:33.645574Z INFO kernel: [ 2692.402248] input input3: PM:
input_dev_resume+0x0/0x42 returned 0 after 0 usecs
2024-04-26T16:45:33.645579Z INFO kernel: [ 2692.423994] pci 0000:00:10.0: PM: calling
pci_pm_resume+0x0/0xed @ 25712, parent: pci0000:00
2024-04-26T16:45:33.645582Z INFO kernel: [ 2692.424024] pci 0000:00:11.0: PM: calling
pci_pm_resume+0x0/0xed @ 25715, parent: pci0000:00
2024-04-26T16:45:33.645660Z INFO kernel: [ 2692.425052] pci 0000:00:11.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 1014 usecs
2024-04-26T16:45:33.645670Z INFO kernel: [ 2692.425070] pcieport 0000:00:15.0: PM:
calling pci_pm_resume+0x0/0xed @ 25715, parent: pci0000:00
2024-04-26T16:45:33.645675Z INFO kernel: [ 2692.428027] pcieport 0000:00:15.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 2947 usecs
2024-04-26T16:45:33.645680Z INFO kernel: [ 2692.428048] pcieport 0000:00:15.1: PM:
calling pci_pm_resume+0x0/0xed @ 25715, parent: pci0000:00
2024-04-26T16:45:33.645684Z INFO kernel: [ 2692.433184] pcieport 0000:00:15.2: PM:
calling pci_pm_resume+0x0/0xed @ 25704, parent: pci0000:00
2024-04-26T16:45:33.645688Z INFO kernel: [ 2692.438793] pcieport 0000:00:15.2: PM:
pci_pm_resume+0x0/0xed returned 0 after 5474 usecs
2024-04-26T16:45:33.645752Z INFO kernel: [ 2692.438821] pcieport 0000:00:15.3: PM:
calling pci_pm_resume+0x0/0xed @ 25704, parent: pci0000:00
2024-04-26T16:45:33.645765Z INFO kernel: [ 2692.439059] pcieport 0000:00:15.4: PM:
calling pci_pm_resume+0x0/0xed @ 25717, parent: pci0000:00
2024-04-26T16:45:33.645769Z INFO kernel: [ 2692.439269] pcieport 0000:00:15.5: PM:
calling pci_pm_resume+0x0/0xed @ 25713, parent: pci0000:00
2024-04-26T16:45:33.645772Z INFO kernel: [ 2692.442209] pcieport 0000:00:15.5: PM:
pci_pm_resume+0x0/0xed returned 0 after 2927 usecs
2024-04-26T16:45:33.645774Z INFO kernel: [ 2692.442228] pcieport 0000:00:15.6: PM:
calling pci_pm_resume+0x0/0xed @ 25713, parent: pci0000:00
2024-04-26T16:45:33.645777Z INFO kernel: [ 2692.443938] pcieport 0000:00:15.7: PM:
calling pci_pm_resume+0x0/0xed @ 25613, parent: pci0000:00
2024-04-26T16:45:33.645779Z INFO kernel: [ 2692.457535] pcieport 0000:00:16.0: PM:
calling pci_pm_resume+0x0/0xed @ 25710, parent: pci0000:00
2024-04-26T16:45:33.645851Z INFO kernel: [ 2692.474040] pcieport 0000:00:15.3: PM:
pci_pm_resume+0x0/0xed returned 0 after 35206 usecs
2024-04-26T16:45:33.645861Z INFO kernel: [ 2692.474073] pcieport 0000:00:16.1: PM:
calling pci_pm_resume+0x0/0xed @ 25704, parent: pci0000:00
```

```
2024-04-26T16:45:33.645866Z INFO kernel: [ 2692.476512] pcieport 0000:00:16.2: PM:
calling pci_pm_resume+0x0/0xed @ 25711, parent: pci0000:00
2024-04-26T16:45:33.645870Z INFO kernel: [ 2692.476540] pcieport 0000:00:16.3: PM:
calling pci_pm_resume+0x0/0xed @ 25719, parent: pci0000:00
2024-04-26T16:45:33.645874Z INFO kernel: [ 2692.485267] pcieport 0000:00:15.1: PM:
pci_pm_resume+0x0/0xed returned 0 after 57207 usecs
2024-04-26T16:45:33.645878Z INFO kernel: [ 2692.494886] vmwgfx 0000:00:0f.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 94275 usecs
2024-04-26T16:45:33.651075Z INFO kernel: [ 2692.501066] pcieport 0000:00:16.1: PM:
pci_pm_resume+0x0/0xed returned 0 after 26976 usecs
2024-04-26T16:45:33.651095Z INFO kernel: [ 2692.507823] pcieport 0000:00:16.4: PM:
calling pci_pm_resume+0x0/0xed @ 25716, parent: pci0000:00
2024-04-26T16:45:33.651098Z INFO kernel: [ 2692.513744] pcieport 0000:00:16.5: PM:
calling pci_pm_resume+0x0/0xed @ 25715, parent: pci0000:00
2024-04-26T16:45:33.651101Z INFO kernel: [ 2692.517690] pci 0000:00:10.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 2 usecs
2024-04-26T16:45:33.651104Z INFO kernel: [ 2692.517719] pcieport 0000:00:16.6: PM:
calling pci_pm_resume+0x0/0xed @ 25712, parent: pci0000:00
2024-04-26T16:45:33.651106Z INFO kernel: [ 2692.523932] pcieport 0000:00:16.6: PM:
pci_pm_resume+0x0/0xed returned 0 after 6200 usecs
2024-04-26T16:45:33.651937Z INFO kernel: [ 2692.523963] pcieport 0000:00:16.7: PM:
calling pci_pm_resume+0x0/0xed @ 25712, parent: pci0000:00
2024-04-26T16:45:33.653579Z INFO kernel: [ 2692.529604] pcieport 0000:00:16.7: PM:
pci_pm_resume+0x0/0xed returned 0 after 5532 usecs
2024-04-26T16:45:33.654771Z INFO kernel: [ 2692.529636] pcieport 0000:00:17.0: PM:
calling pci_pm_resume+0x0/0xed @ 25712, parent: pci0000:00
2024-04-26T16:45:33.654785Z INFO kernel: [ 2692.551925] pcieport 0000:00:15.4: PM:
pci_pm_resume+0x0/0xed returned 0 after 103834 usecs
2024-04-26T16:45:33.654789Z INFO kernel: [ 2692.557566] pcieport 0000:00:17.1: PM:
calling pci_pm_resume+0x0/0xed @ 25704, parent: pci0000:00
2024-04-26T16:45:33.654791Z INFO kernel: [ 2692.561295] pcieport 0000:00:17.2: PM:
calling pci_pm_resume+0x0/0xed @ 25717, parent: pci0000:00
2024-04-26T16:45:33.654794Z INFO kernel: [ 2692.563939] pcieport 0000:00:15.7: PM:
pci_pm_resume+0x0/0xed returned 0 after 3835 usecs
2024-04-26T16:45:33.654797Z INFO kernel: [ 2692.563968] pcieport 0000:00:17.3: PM:
calling pci_pm_resume+0x0/0xed @ 25613, parent: pci0000:00
2024-04-26T16:45:33.654799Z INFO kernel: [ 2692.566936] pcieport 0000:00:17.3: PM:
pci_pm_resume+0x0/0xed returned 0 after 2956 usecs
2024-04-26T16:45:33.654802Z INFO kernel: [ 2692.566965] pcieport 0000:00:17.4: PM:
calling pci_pm_resume+0x0/0xed @ 25613, parent: pci0000:00
2024-04-26T16:45:33.654807Z INFO kernel: [ 2692.570743] pcieport 0000:00:16.2: PM:
pci_pm_resume+0x0/0xed returned 0 after 94207 usecs
2024-04-26T16:45:33.654809Z INFO kernel: [ 2692.573920] pcieport 0000:00:17.1: PM:
pci_pm_resume+0x0/0xed returned 0 after 5893 usecs
2024-04-26T16:45:33.654812Z INFO kernel: [ 2692.573951] pcieport 0000:00:17.5: PM:
calling pci_pm_resume+0x0/0xed @ 25704, parent: pci0000:00
2024-04-26T16:45:33.654815Z INFO kernel: [ 2692.574728] ata_piix 0000:00:07.1: PM:
pci_pm_resume+0x0/0xed returned 0 after 178889 usecs
2024-04-26T16:45:33.654818Z INFO kernel: [ 2692.577108] pcieport 0000:00:17.5: PM:
pci_pm_resume+0x0/0xed returned 0 after 3146 usecs
2024-04-26T16:45:33.654821Z INFO kernel: [ 2692.577163] pcieport 0000:00:17.6: PM:
calling pci_pm_resume+0x0/0xed @ 25704, parent: pci0000:00
2024-04-26T16:45:33.654824Z INFO kernel: [ 2692.580285] pcieport 0000:00:16.4: PM:
pci_pm_resume+0x0/0xed returned 0 after 61040 usecs
2024-04-26T16:45:33.654827Z INFO kernel: [ 2692.581394] pcieport 0000:00:17.4: PM:
pci_pm_resume+0x0/0xed returned 0 after 14417 usecs
2024-04-26T16:45:33.654830Z INFO kernel: [ 2692.581456] pcieport 0000:00:17.7: PM:
calling pci_pm_resume+0x0/0xed @ 25613, parent: pci0000:00
2024-04-26T16:45:33.654832Z INFO kernel: [ 2692.584040] pcieport 0000:00:17.7: PM:
pci_pm_resume+0x0/0xed returned 0 after 2573 usecs
2024-04-26T16:45:33.654835Z INFO kernel: [ 2692.584061] pcieport 0000:00:18.0: PM:
calling pci_pm_resume+0x0/0xed @ 25613, parent: pci0000:00
2024-04-26T16:45:33.654838Z INFO kernel: [ 2692.586818] pcieport 0000:00:18.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 2748 usecs
2024-04-26T16:45:33.654840Z INFO kernel: [ 2692.591884] pcieport 0000:00:17.2: PM:
pci_pm_resume+0x0/0xed returned 0 after 5737 usecs
2024-04-26T16:45:33.654843Z INFO kernel: [ 2692.591910] pcieport 0000:00:18.1: PM:
calling pci_pm_resume+0x0/0xed @ 25717, parent: pci0000:00
2024-04-26T16:45:33.654846Z INFO kernel: [ 2692.595527] pcieport 0000:00:16.3: PM:
```

```
pci_pm_resume+0x0/0xed returned 0 after 118970 usecs
2024-04-26T16:45:33.654848Z INFO kernel: [ 2692.597732] pcieport 0000:00:15.6: PM:
pci_pm_resume+0x0/0xed returned 0 after 155494 usecs
2024-04-26T16:45:33.654851Z INFO kernel: [ 2692.597752] pcieport 0000:00:18.2: PM:
calling pci_pm_resume+0x0/0xed @ 25713, parent: pci0000:00
2024-04-26T16:45:33.654854Z INFO kernel: [ 2692.602534] pcieport 0000:00:18.2: PM:
pci_pm_resume+0x0/0xed returned 0 after 4687 usecs
2024-04-26T16:45:33.654856Z INFO kernel: [ 2692.602564] pcieport 0000:00:18.3: PM:
calling pci_pm_resume+0x0/0xed @ 25713, parent: pci0000:00
2024-04-26T16:45:33.654859Z INFO kernel: [ 2692.611868] pcieport 0000:00:18.4: PM:
calling pci_pm_resume+0x0/0xed @ 25716, parent: pci0000:00
2024-04-26T16:45:33.654862Z INFO kernel: [ 2692.612846] pcieport 0000:00:17.6: PM:
pci_pm_resume+0x0/0xed returned 0 after 35670 usecs
2024-04-26T16:45:33.654865Z INFO kernel: [ 2692.612873] pcieport 0000:00:18.5: PM:
calling pci_pm_resume+0x0/0xed @ 25704, parent: pci0000:00
2024-04-26T16:45:33.654867Z INFO kernel: [ 2692.614255] pcieport 0000:00:18.6: PM:
calling pci_pm_resume+0x0/0xed @ 25711, parent: pci0000:00
2024-04-26T16:45:33.657539Z INFO kernel: [ 2692.624922] pcieport 0000:00:16.5: PM:
pci_pm_resume+0x0/0xed returned 0 after 29376 usecs
2024-04-26T16:45:33.657565Z INFO kernel: [ 2692.624956] pcieport 0000:00:18.7: PM:
calling pci_pm_resume+0x0/0xed @ 25715, parent: pci0000:00
2024-04-26T16:45:33.657572Z INFO kernel: [ 2692.627859] pcieport 0000:00:17.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 98213 usecs
2024-04-26T16:45:33.657576Z INFO kernel: [ 2692.627883] uhci_hcd 0000:02:00.0: PM:
calling pci_pm_resume+0x0/0xed @ 25712, parent: 0000:00:11.0
2024-04-26T16:45:33.657580Z NOTICE kernel: [ 2692.632155] usb usb2: root hub lost power
or was reset
2024-04-26T16:45:33.657584Z INFO kernel: [ 2692.632773] pcieport 0000:00:18.5: PM:
pci_pm_resume+0x0/0xed returned 0 after 19886 usecs
2024-04-26T16:45:33.657587Z INFO kernel: [ 2692.632800] e1000 0000:02:01.0: PM: calling
pci_pm_resume+0x0/0xed @ 25704, parent: 0000:00:11.0
2024-04-26T16:45:33.657591Z INFO kernel: [ 2692.632967] uhci_hcd 0000:02:00.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 5075 usecs
2024-04-26T16:45:33.657594Z INFO kernel: [ 2692.632982] snd_hda_intel 0000:02:02.0: PM:
calling pci_pm_resume+0x0/0xed @ 25712, parent: 0000:00:11.0
2024-04-26T16:45:33.657600Z INFO kernel: [ 2692.635973] pcieport 0000:00:18.7: PM:
pci_pm_resume+0x0/0xed returned 0 after 11003 usecs
2024-04-26T16:45:33.657604Z INFO kernel: [ 2692.636010] ehci-pci 0000:02:03.0: PM:
calling pci_pm_resume+0x0/0xed @ 25715, parent: 0000:00:11.0
2024-04-26T16:45:33.657608Z INFO kernel: [ 2692.637196] pcieport 0000:00:18.6: PM:
pci_pm_resume+0x0/0xed returned 0 after 22922 usecs
2024-04-26T16:45:33.657612Z INFO kernel: [ 2692.637221] nvme 0000:03:00.0: PM: calling
pci_pm_resume+0x0/0xed @ 25711, parent: 0000:00:15.0
2024-04-26T16:45:33.657616Z INFO kernel: [ 2692.637236] nvme 0000:03:00.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 5 usecs
2024-04-26T16:45:33.657619Z INFO kernel: [ 2692.640255] ehci-pci 0000:02:03.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 4228 usecs
2024-04-26T16:45:33.657623Z INFO kernel: [ 2692.642778] ata2: PM: calling
ata_port_pm_resume+0x0/0x56 @ 25715, parent: 0000:00:07.1
2024-04-26T16:45:33.657626Z INFO kernel: [ 2692.642943] usb usb1: PM: calling
usb_dev_resume+0x0/0x14 @ 25718, parent: 0000:02:03.0
2024-04-26T16:45:33.657630Z INFO kernel: [ 2692.643365] ata1: PM: calling
ata_port_pm_resume+0x0/0x56 @ 25711, parent: 0000:00:07.1
2024-04-26T16:45:33.657640Z INFO kernel: [ 2692.646669] usb usb1: PM:
usb_dev_resume+0x0/0x14 returned 0 after 3676 usecs
2024-04-26T16:45:33.657645Z INFO kernel: [ 2692.646714] usb usb2: PM: calling
usb_dev_resume+0x0/0x14 @ 25718, parent: 0000:02:00.0
2024-04-26T16:45:33.657648Z INFO kernel: [ 2692.648729] ata1: PM:
ata_port_pm_resume+0x0/0x56 returned 0 after 5278 usecs
2024-04-26T16:45:33.657652Z INFO kernel: [ 2692.650801] pcieport 0000:00:18.1: PM:
pci_pm_resume+0x0/0xed returned 0 after 58845 usecs
2024-04-26T16:45:33.657655Z INFO kernel: [ 2692.651937] pcieport 0000:00:18.3: PM:
pci_pm_resume+0x0/0xed returned 0 after 49361 usecs
2024-04-26T16:45:33.657660Z INFO kernel: [ 2692.678745] ata2: PM:
ata_port_pm_resume+0x0/0x56 returned 0 after 95 usecs
2024-04-26T16:45:33.657669Z INFO kernel: [ 2692.699701] pcieport 0000:00:16.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 176479 usecs
2024-04-26T16:45:33.657809Z ERR kernel: [ 2692.727109] snd_hda_intel 0000:02:02.0: CORB
reset timeout#1, CORBRP = 0
```

```
2024-04-26T16:45:33.657822Z INFO kernel: [ 2692.731764] pcieport 0000:00:18.4: PM:
pci_pm_resume+0x0/0xed returned 0 after 3482 usecs
2024-04-26T16:45:33.657827Z INFO kernel: [ 2692.737624] snd_hda_intel 0000:02:02.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 104629 usecs
2024-04-26T16:45:33.657832Z INFO kernel: [ 2692.762827] e1000 0000:02:01.0: PM:
pci_pm_resume+0x0/0xed returned 0 after 130016 usecs
2024-04-26T16:45:33.657836Z INFO kernel: [ 2692.768312] e1000: eth0 NIC Link is Up 1000
Mbps Full Duplex, Flow Control: None
2024-04-26T16:45:33.657841Z INFO kernel: [ 2692.775425] usb usb2: PM:
usb_dev_resume+0x0/0x14 returned 0 after 128699 usecs
2024-04-26T16:45:33.657846Z INFO kernel: [ 2692.779206] snd_hda_codec_generic
hdaudioC0D0: PM: calling hda_codec_pm_resume+0x0/0x19 [snd_hda_codec] @ 25730, parent:
0000:02:02.0
2024-04-26T16:45:33.657851Z INFO kernel: [ 2692.784488] usb 2-2: PM: calling
usb_dev_resume+0x0/0x14 @ 25715, parent: usb2
2024-04-26T16:45:33.657855Z INFO kernel: [ 2692.784799] usb 2-1: PM: calling
usb_dev_resume+0x0/0x14 @ 25613, parent: usb2
2024-04-26T16:45:33.657860Z INFO kernel: [ 2692.784812] usb 2-1: PM:
usb_dev_resume+0x0/0x14 returned 0 after 1 usecs
2024-04-26T16:45:33.657864Z INFO kernel: [ 2692.786987] nvme nvme0: 8/0/0
default/read/poll queues
2024-04-26T16:45:33.657869Z INFO kernel: [ 2692.804652] input input5: PM: calling
input_dev_resume+0x0/0x42 @ 25702, parent: 0003:0E0F:0003.0001
2024-04-26T16:45:33.657873Z INFO kernel: [ 2692.914651] snd_hda_codec_generic
hdaudioC0D0: PM: hda_codec_pm_resume+0x0/0x19 [snd_hda_codec] returned 0 after 124186
usecs
2024-04-26T16:45:33.657878Z INFO kernel: [ 2692.915223] input input5: PM:
input_dev_resume+0x0/0x42 returned 0 after 1 usecs
2024-04-26T16:45:33.657882Z INFO kernel: [ 2692.972422] usb 2-2: reset full-speed USB
device number 3 using uhci_hcd
2024-04-26T16:45:33.659931Z INFO kernel: [ 2692.976547] platform regulatory.0: PM:
calling platform_pm_resume+0x0/0x41 @ 25702, parent: platform
2024-04-26T16:45:33.659943Z INFO kernel: [ 2693.343335] usb 2-2: PM:
usb_dev_resume+0x0/0x14 returned 0 after 558820 usecs
2024-04-26T16:45:33.659948Z INFO kernel: [ 2693.345441] platform regulatory.0: PM:
platform_pm_resume+0x0/0x41 returned 0 after 1 usecs
2024-04-26T16:45:33.659953Z INFO kernel: [ 2693.350985] usb 2-2.1: PM: calling
usb_dev_resume+0x0/0x14 @ 25728, parent: 2-2
2024-04-26T16:45:33.659957Z INFO kernel: [ 2693.358550] input input6: PM: calling
input_dev_resume+0x0/0x42 @ 25702, parent: card0
2024-04-26T16:45:33.659961Z INFO kernel: [ 2693.363709] usb 2-2.1: PM:
usb_dev_resume+0x0/0x14 returned 0 after 1 usecs
2024-04-26T16:45:33.659966Z INFO kernel: [ 2693.368794] input input6: PM:
input_dev_resume+0x0/0x42 returned 0 after 1 usecs
2024-04-26T16:45:33.659971Z INFO kernel: [ 2693.483744] input input7: PM: calling
input_dev_resume+0x0/0x42 @ 25702, parent: card0
2024-04-26T16:45:33.659975Z INFO kernel: [ 2693.491937] input input7: PM:
input_dev_resume+0x0/0x42 returned 0 after 2 usecs
2024-04-26T16:45:33.659978Z INFO kernel: [ 2693.497805] input input8: PM: calling
input_dev_resume+0x0/0x42 @ 25702, parent: card0
2024-04-26T16:45:33.659982Z INFO kernel: [ 2693.518864] input input8: PM:
input_dev_resume+0x0/0x42 returned 0 after 2 usecs
2024-04-26T16:45:33.659986Z INFO kernel: [ 2693.523457] input input9: PM: calling
input_dev_resume+0x0/0x42 @ 25702, parent: card0
2024-04-26T16:45:33.659992Z INFO kernel: [ 2693.528429] input input9: PM:
input_dev_resume+0x0/0x42 returned 0 after 1 usecs
2024-04-26T16:45:33.659996Z INFO kernel: [ 2693.533611] input input10: PM: calling
input_dev_resume+0x0/0x42 @ 25702, parent: card0
2024-04-26T16:45:33.660001Z INFO kernel: [ 2693.538756] input input10: PM:
input_dev_resume+0x0/0x42 returned 0 after 1 usecs
2024-04-26T16:45:33.660005Z INFO kernel: [ 2693.543300] rfkill rfkill0: PM: calling
rfkill_resume+0x0/0x69 @ 25702, parent: hci0
2024-04-26T16:45:33.660048Z INFO kernel: [ 2693.550333] rfkill rfkill0: PM:
rfkill_resume+0x0/0x69 returned 0 after 1943 usecs
2024-04-26T16:45:33.660054Z DEBUG kernel: [ 2693.555290] PM: resume of devices complete
after 1169.832 msecs
2024-04-26T16:45:33.660058Z DEBUG kernel: [ 2693.559040] PM: Finishing wakeup.
2024-04-26T16:45:33.660064Z INFO kernel: [ 2693.559051] OOM killer enabled.
2024-04-26T16:45:33.660068Z INFO kernel: [ 2693.561061] Restarting tasks ...
```

```
2024-04-26T16:45:33.660072Z INFO kernel: [ 2693.562748] usb 2-1: USB disconnect, device
number 2
2024-04-26T16:45:33.660076Z INFO kernel: [ 2693.613108] usb 2-2.1: USB disconnect, device
number 4
2024-04-26T16:45:33.660080Z WARNING kernel: [ 2693.678713] done.
2024-04-26T16:45:33.660083Z INFO kernel: [ 2693.686871] Resume caused by IRQ 12, i8042
2024-04-26T16:45:33.660089Z INFO kernel: [ 2693.762436] PM: suspend exit
2024-04-26T16:45:33.660094Z INFO kernel: [ 2693.796192] usb 2-2.1: new full-speed USB
device number 5 using uhci_hcd
2024-04-26T16:45:33.670272Z INFO periodic_scheduler[3410]: cros-machine-id-regen: running
/usr/sbin/cros-machine-id-regen -r periodic -t 21600
2024-04-26T16:45:33.707398Z NOTICE powerd_suspend[25615]: Resume finished
2024-04-26T16:45:33.735169Z INFO kernel: [ 2693.919398] usb 2-2.1: New USB device found,
idVendor=0e0f, idProduct=0008, bcdDevice= 1.00
2024-04-26T16:45:33.735193Z INFO kernel: [ 2693.933179] usb 2-2.1: New USB device
strings: Mfr=1, Product=2, SerialNumber=3
2024-04-26T16:45:33.742516Z INFO kernel: [ 2693.944327] usb 2-2.1: Product: Virtual
Bluetooth Adapter
2024-04-26T16:45:33.770349Z INFO kernel: [ 2693.977876] usb 2-2.1: Manufacturer: VMware
2024-04-26T16:45:33.776219Z INFO kernel: [ 2693.981086] usb 2-2.1: SerialNumber:
000650268328
2024-04-26T16:45:33.790424Z DEBUG kernel: [ 2693.997426] usb 2-2.1: GPIO lookup for
consumer reset
2024-04-26T16:45:33.790448Z DEBUG kernel: [ 2693.997548] usb 2-2.1: using lookup tables
for GPIO lookup
2024-04-26T16:45:33.790452Z DEBUG kernel: [ 2693.997659] usb 2-2.1: No GPIO consumer
reset found
2024-04-26T16:45:33.813818Z INFO kernel: [ 2694.015944] usb 2-1: new full-speed USB
device number 6 using uhci_hcd
2024-04-26T16:45:33.894554Z ERR kernel: [ 2694.094349] Bluetooth: hci0: unexpected cc
0x0c12 length: 2 < 3
2024-04-26T16:45:33.894723Z ERR kernel: [ 2694.098377] Bluetooth: hci0: Opcode 0x c12
failed: -38
2024-04-26T16:45:33.969755Z INFO kernel: [ 2694.166756] usb 2-1: New USB device found,
idVendor=0e0f, idProduct=0003, bcdDevice= 1.03
2024-04-26T16:45:33.969859Z INFO kernel: [ 2694.172979] usb 2-1: New USB device strings:
Mfr=1, Product=2, SerialNumber=0
2024-04-26T16:45:33.975409Z INFO kernel: [ 2694.180193] usb 2-1: Product: VMware Virtual
USB Mouse
2024-04-26T16:45:33.978555Z INFO kernel: [ 2694.183961] usb 2-1: Manufacturer: VMware
2024-04-26T16:45:34.015131Z INFO kernel: [ 2694.210384] input: VMware VMware Virtual USB
Mouse as /devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-1/2-
1:1.0/0003:0E0F:0003.0002/input/input11
2024-04-26T16:45:34.064220Z INFO kernel: [ 2694.251593] hid-generic 0003:0E0F:0003.0002:
input,hidraw0: USB HID v1.10 Mouse [VMware VMware Virtual USB Mouse] on usb-0000:02:00.0-
1/input0
2024-04-26T16:45:34.102757Z ERR shill[784]: ERROR shill: [rtnl_message.cc(1103)] RTNL
address message does not have a valid IFA_ADDRESS
2024-04-26T16:45:35.132401Z ERR shill[784]: ERROR shill: [rtnl_message.cc(1103)] RTNL
address message does not have a valid IFA_ADDRESS
2024-04-26T16:45:35.221283Z NOTICE cros-machine-id-regen[25775]: Not regenerating since
we did so 2663 seconds ago.
2024-04-26T16:45:35.346399Z INFO periodic_scheduler[3410]: cros-machine-id-regen: job
completed
2024-04-26T16:45:39.948651Z INFO minijail0[25839]: libminijail[25839]: applying policy
for default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:45:40.262770Z ERR debugd[3800]: Problem waiting for pid 25839: No child
processes (10)
2024-04-26T16:45:40.265991Z ERR debugd[3800]: Unable to send signal to 25839: No such
process (3)
2024-04-26T16:45:41.316249Z INFO usb_bouncer[25852]: Reporting metrics for
/devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-2/2-2.1
2024-04-26T16:45:41.323692Z INFO usb_bouncer[25851]: Reporting metrics for
/devices/pci0000:00/0000:00:11.0/0000:02:00.0/usb2/2-1
2024-04-26T16:45:42.530665Z NOTICE send_metrics_on_resume[25968]: Unable to get
firmware_resume_time
2024-04-26T16:45:43.581639Z INFO permission_broker[1313]:
ProcessPath(/dev/bus/usb/002/005)
2024-04-26T16:45:43.763544Z WARNING kernel: [ 2703.964540] audit: audit_backlog=65 >
```

```
audit_backlog_limit=64
2024-04-26T16:45:43.763632Z WARNING kernel: [ 2703.967791] audit: audit_lost=177
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:45:43.781655Z WARNING kernel: [ 2703.971679] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:45:43.782275Z WARNING kernel: [ 2703.980362] audit: audit_lost=178
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:45:43.782296Z ERR kernel: [ 2703.982081] audit: backlog limit exceeded
2024-04-26T16:45:43.782303Z ERR kernel: [ 2703.986838] audit: backlog limit exceeded
2024-04-26T16:45:46.739792Z INFO permission_broker[1313]: AllowUsbDeviceRule: ALLOW
2024-04-26T16:45:46.740590Z INFO permission_broker[1313]: AllowTtyDeviceRule: IGNORE
2024-04-26T16:45:46.747643Z INFO permission_broker[1313]: Found claimed interface with
driver: btusb
2024-04-26T16:45:46.751956Z INFO permission_broker[1313]: Found claimed interface with
driver: btusb
2024-04-26T16:45:46.791301Z INFO permission_broker[1313]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T16:45:46.791591Z INFO permission_broker[1313]: Verdict for
/dev/bus/usb/002/005: DENY
2024-04-26T16:45:46.791854Z INFO permission_broker[1313]:
ProcessPath(/dev/bus/usb/002/005)
2024-04-26T16:45:47.495170Z INFO vm_cicerone[4486]: System timezone changed, updating
container timezones
2024-04-26T16:45:48.637178Z INFO permission_broker[1313]: AllowUsbDeviceRule: ALLOW
2024-04-26T16:45:48.637409Z INFO permission_broker[1313]: AllowTtyDeviceRule: IGNORE
2024-04-26T16:45:48.647094Z INFO permission_broker[1313]: Found claimed interface with
driver: btusb
2024-04-26T16:45:48.650755Z INFO permission_broker[1313]: Found claimed interface with
driver: btusb
2024-04-26T16:45:48.683495Z INFO permission_broker[1313]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T16:45:48.683711Z INFO permission_broker[1313]: Verdict for
/dev/bus/usb/002/005: DENY
2024-04-26T16:45:48.685584Z INFO permission_broker[1313]:
ProcessPath(/dev/bus/usb/002/005)
2024-04-26T16:45:50.805548Z INFO permission_broker[1313]: AllowUsbDeviceRule: ALLOW
2024-04-26T16:45:50.805770Z INFO permission_broker[1313]: AllowTtyDeviceRule: IGNORE
2024-04-26T16:45:50.825348Z INFO permission_broker[1313]: Found claimed interface with
driver: btusb
2024-04-26T16:45:50.833624Z INFO permission_broker[1313]: Found claimed interface with
driver: btusb
2024-04-26T16:45:50.844272Z INFO permission_broker[1313]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T16:45:50.845204Z INFO permission_broker[1313]: Verdict for
/dev/bus/usb/002/005: DENY
2024-04-26T16:45:50.845797Z INFO permission_broker[1313]:
ProcessPath(/dev/bus/usb/002/006)
2024-04-26T16:45:52.612984Z INFO permission_broker[1313]: AllowUsbDeviceRule: ALLOW
2024-04-26T16:45:52.614352Z INFO permission_broker[1313]: AllowTtyDeviceRule: IGNORE
2024-04-26T16:45:52.651183Z INFO permission_broker[1313]: Found claimed interface with
driver: usbhid
2024-04-26T16:45:52.659277Z INFO permission_broker[1313]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T16:45:52.659563Z INFO permission_broker[1313]: Verdict for
/dev/bus/usb/002/006: DENY
2024-04-26T16:45:52.661741Z INFO permission_broker[1313]:
ProcessPath(/dev/bus/usb/002/006)
2024-04-26T16:45:54.689377Z WARNING debugd[3800]: Failed to open procfs entry of process
7361
2024-04-26T16:45:54.691536Z WARNING debugd[3800]: Failed to open uid map file
/proc/7361/uid_map for process 7361
2024-04-26T16:45:54.694329Z WARNING debugd[3800]: Invalid pid 7361, operation not allowed
2024-04-26T16:45:54.694942Z WARNING debugd[3800]: Failed to open procfs entry of process
7638
2024-04-26T16:45:54.695368Z WARNING debugd[3800]: Failed to open uid map file
/proc/7638/uid_map for process 7638
2024-04-26T16:45:54.695581Z WARNING debugd[3800]: Invalid pid 7638, operation not allowed
2024-04-26T16:45:54.697318Z WARNING debugd[3800]: Failed to open procfs entry of process
10351
```

```
2024-04-26T16:45:54.698160Z WARNING debugd[3800]: Failed to open uid map file
/proc/10351/uid_map for process 10351
2024-04-26T16:45:54.698484Z WARNING debugd[3800]: Invalid pid 10351, operation not
allowed
2024-04-26T16:45:54.699986Z WARNING debugd[3800]: Failed to open procfs entry of process
12142
2024-04-26T16:45:54.705549Z WARNING debugd[3800]: Failed to open uid map file
/proc/12142/uid_map for process 12142
2024-04-26T16:45:54.705882Z WARNING debugd[3800]: Invalid pid 12142, operation not
allowed
2024-04-26T16:45:54.784226Z INFO permission_broker[1313]: AllowUsbDeviceRule: ALLOW
2024-04-26T16:45:54.784312Z INFO permission_broker[1313]: AllowTtyDeviceRule: IGNORE
2024-04-26T16:45:54.789704Z INFO permission_broker[1313]: Found claimed interface with
driver: usbhid
2024-04-26T16:45:54.798980Z INFO permission_broker[1313]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T16:45:54.799120Z INFO permission_broker[1313]: Verdict for
/dev/bus/usb/002/006: DENY
2024-04-26T16:45:54.799463Z INFO permission_broker[1313]:
ProcessPath(/dev/bus/usb/002/006)
2024-04-26T16:45:56.436703Z INFO permission_broker[1313]: AllowUsbDeviceRule: ALLOW
2024-04-26T16:45:56.436810Z INFO permission_broker[1313]: AllowTtyDeviceRule: IGNORE
2024-04-26T16:45:56.464332Z INFO permission_broker[1313]: Found claimed interface with
driver: usbhid
2024-04-26T16:45:56.512610Z INFO permission_broker[1313]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T16:45:56.512691Z INFO permission_broker[1313]: Verdict for
/dev/bus/usb/002/006: DENY
2024-04-26T16:45:58.551509Z INFO kernel: [ 2718.755295] binder: release 4781:5167
transaction 403986 out, still active
2024-04-26T16:45:58.588565Z INFO kernel: [ 2718.788004] binder: release 4781:5494
transaction 403833 in, still active
2024-04-26T16:45:58.588601Z INFO kernel: [ 2718.792748] binder: send failed reply for
transaction 403833 to 21787:21787
2024-04-26T16:45:58.596432Z INFO kernel: [ 2718.796914] binder: release 4781:6185
transaction 403861 in, still active
2024-04-26T16:45:58.596475Z INFO kernel: [ 2718.800701] binder: send failed reply for
transaction 403861 to 20663:20681
2024-04-26T16:45:58.612639Z INFO kernel: [ 2718.808616] binder: release 4781:8031
transaction 403844 in, still active
2024-04-26T16:45:58.612684Z INFO kernel: [ 2718.812085] binder: send failed reply for
transaction 403844 to 12120:12329
2024-04-26T16:45:58.637692Z INFO kernel: [ 2718.838011] binder: release 4781:8409
transaction 404157 in, still active
2024-04-26T16:45:58.637727Z INFO kernel: [ 2718.841513] binder: send failed reply for
transaction 404157 to 26013:26013
2024-04-26T16:45:58.653788Z INFO kernel: [ 2718.854692] binder: release 4781:8674
transaction 403863 in, still active
2024-04-26T16:45:58.653823Z INFO kernel: [ 2718.858318] binder: send failed reply for
transaction 403863 to 5312:5312
2024-04-26T16:45:58.668552Z INFO kernel: [ 2718.868193] binder: release 4781:9718
transaction 403880 in, still active
2024-04-26T16:45:58.684170Z INFO kernel: [ 2718.884762] binder: send failed reply for
transaction 403880 to 12103:12328
2024-04-26T16:45:58.684204Z INFO kernel: [ 2718.888434] binder: release 4781:11409
transaction 403839 in, still active
2024-04-26T16:45:58.693616Z INFO kernel: [ 2718.896329] binder: send failed reply for
transaction 403839 to 5341:5341
2024-04-26T16:45:58.714076Z INFO kernel: [ 2718.906296] binder: undelivered transaction
403879, process died.
2024-04-26T16:45:58.714113Z INFO kernel: [ 2718.917849] binder: undelivered transaction
403884, process died.
2024-04-26T16:45:58.718249Z INFO kernel: [ 2718.922416] binder: undelivered transaction
403990, process died.
2024-04-26T16:45:58.817593Z INFO kernel: [ 2719.018575] binder: undelivered death
notification, 00007b9a83e5ec20
2024-04-26T16:45:58.817642Z INFO kernel: [ 2719.022086] binder: undelivered death
notification, 00007b9a6b8a9f40
2024-04-26T16:45:58.817655Z INFO kernel: [ 2719.025637] binder: undelivered death
```



```
notification, 00007b9a70e0d8c0
2024-04-26T16:45:58.839414Z INFO kernel: [ 2719.039633] binder: undelivered death
notification, 00007b9a6b996a00
2024-04-26T16:45:58.839457Z INFO kernel: [ 2719.043208] binder: undelivered death
notification, 00007b9a70e10700
2024-04-26T16:45:58.839466Z INFO kernel: [ 2719.046543] binder: undelivered death
notification, 00007b9a7531a920
2024-04-26T16:45:58.845884Z INFO kernel: [ 2719.050081] binder: undelivered death
notification, 00007b9a7531aa60
2024-04-26T16:45:58.845923Z INFO kernel: [ 2719.053714] binder: undelivered death
notification, 00007b9a69440d40
2024-04-26T16:45:58.858817Z INFO kernel: [ 2719.057137] binder: undelivered death
notification, 00007b9a6943fd00
2024-04-26T16:45:58.858851Z INFO kernel: [ 2719.066245] binder: undelivered death
notification, 00007b9a71541ea0
2024-04-26T16:45:59.031454Z INFO kernel: [ 2719.230980] binder: 5341:5341 transaction
failed 29189/-22, size 120-8 line 2893
2024-04-26T16:45:59.087108Z INFO kernel: [ 2719.260549] binder: 5312:5312 transaction
failed 29189/-22, size 120-8 line 2893
2024-04-26T16:45:59.360206Z INFO kernel: [ 2719.536240] binder: 26013:26013 transaction
failed 29189/-22, size 3392-8 line 2893
2024-04-26T16:45:59.430842Z INFO kernel: [ 2719.633190] binder: 4775:4997 transaction
failed 29189/-22, size 60-0 line 2893
2024-04-26T16:45:59.653651Z INFO kernel: [ 2719.828687] binder: 20663:20681 transaction
failed 29189/-22, size 3792-8 line 2893
2024-04-26T16:46:01.185368Z INFO kernel: [ 2721.375834] binder: 4775:5493 transaction
failed 29189/-22, size 60-0 line 2893
2024-04-26T16:46:01.243327Z ERR arc-kmsg-logger[3892]: init: failed to set pid 19850
ioprio=1,4: Operation not permitted
2024-04-26T16:46:01.249879Z ERR arc-kmsg-logger[3892]: init: failed to set pid 19852
ioprio=1,4: Operation not permitted
2024-04-26T16:46:01.269220Z ERR arc-kmsg-logger[3892]: init: couldn't write 19851 to
/dev/cpuset/camera-daemon/tasks: No such file or directory
2024-04-26T16:46:01.293291Z ERR arc-kmsg-logger[3892]: init: failed to set pid 19851
ioprio=1,4: Operation not permitted
2024-04-26T16:46:01.296618Z ERR arc-kmsg-logger[3892]: init: failed to set pid 19855
ioprio=1,4: Operation not permitted
2024-04-26T16:46:05.830806Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.camera.provider@2.4::ICameraProvider/external/0
2024-04-26T16:46:07.637626Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.audio@4.0::IDevicesFactory/default
2024-04-26T16:46:07.637663Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.audio@2.0::IDevicesFactory/msd
2024-04-26T16:46:07.843538Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.audio.effect@4.0::IEffectsFactory/default
2024-04-26T16:46:08.373626Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.audio.effect@4.0::IEffectsFactory/default
2024-04-26T16:46:14.787823Z INFO vm_cicerone[4486]: System timezone changed, updating
container timezones
2024-04-26T16:46:16.092078Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.power@1.0::IPower/default
2024-04-26T16:46:16.437725Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.light@2.0::ILight/default
2024-04-26T16:46:35.157217Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.soundtrigger@2.0::ISoundTriggerHw/default
2024-04-26T16:46:35.268632Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.health@2.0::IHealth/default
2024-04-26T16:46:35.289103Z INFO kernel: [ 2755.492330] binder: release 4815:4815
transaction 408939 in, still active
2024-04-26T16:46:35.311103Z INFO kernel: [ 2755.505534] binder: send failed reply for
transaction 408939 to 26148:26246
2024-04-26T16:46:35.324446Z INFO kernel: [ 2755.522840] binder: release 4815:5165
transaction 403986 in, still active
2024-04-26T16:46:35.324483Z INFO kernel: [ 2755.527057] binder: send failed reply for
transaction 403986, target dead
2024-04-26T16:46:35.937918Z INFO iioservice[712]: INFO iioservice: [iio_sensor.cc(56)]
(2) Request(): Received SensorService from Mojo Service Manager
2024-04-26T16:46:35.992883Z INFO iioservice[712]: INFO iioservice:
[sensor_service_impl.cc(417)] (2) OnSensorServiceDisconnect(): SensorDevice disconnected.
```

ReceiverId: 5

```
2024-04-26T16:46:36.551421Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.vibrator@1.0::IVibrator/default
2024-04-26T16:46:36.832813Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.vibrator@1.0::IVibrator/default
2024-04-26T16:46:36.833481Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.vibrator@1.0::IVibrator/default
2024-04-26T16:46:36.923177Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.ir@1.0::IConsumerIr/default
2024-04-26T16:46:37.624606Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.vr@1.0::IVr/default
2024-04-26T16:46:38.692049Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.oemlock@1.0::IOemLock/default
2024-04-26T16:46:43.231420Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.thermal@1.0::IThermal/default
2024-04-26T16:46:43.537266Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.contexthub@1.0::IContexthub/default
2024-04-26T16:46:44.106500Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.weaver@1.0::IWeaver/default
2024-04-26T16:46:44.127313Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.authsecret@1.0::IAuthSecret/default
2024-04-26T16:46:45.351363Z INFO kernel: [ 2765.548675] binder: 26148:26159 transaction
failed 29189/-22, size 280-0 line 2893
2024-04-26T16:46:45.931329Z INFO permission_broker[1313]:
ProcessPath(/dev/bus/usb/002/006)
2024-04-26T16:46:47.003688Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.gnss@1.1::IGnss/default
2024-04-26T16:46:47.012900Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.gnss@1.0::IGnss/default
2024-04-26T16:46:47.092675Z INFO permission_broker[1313]: AllowUsbDeviceRule: ALLOW
2024-04-26T16:46:47.093049Z INFO permission_broker[1313]: AllowTtyDeviceRule: IGNORE
2024-04-26T16:46:47.104469Z INFO permission_broker[1313]: Found claimed interface with
driver: usbhid
2024-04-26T16:46:47.113224Z INFO permission_broker[1313]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T16:46:47.114581Z INFO permission_broker[1313]: Verdict for
/dev/bus/usb/002/006: DENY
2024-04-26T16:46:47.115629Z INFO permission_broker[1313]:
ProcessPath(/dev/bus/usb/002/005)
2024-04-26T16:46:48.316472Z INFO permission_broker[1313]: AllowUsbDeviceRule: ALLOW
2024-04-26T16:46:48.316785Z INFO permission_broker[1313]: AllowTtyDeviceRule: IGNORE
2024-04-26T16:46:48.326793Z INFO permission_broker[1313]: Found claimed interface with
driver: btusb
2024-04-26T16:46:48.329593Z INFO permission_broker[1313]: Found claimed interface with
driver: btusb
2024-04-26T16:46:48.333389Z INFO permission_broker[1313]: DenyClaimedUsbDeviceRule:
DENY
2024-04-26T16:46:48.333708Z INFO permission_broker[1313]: Verdict for
/dev/bus/usb/002/005: DENY
2024-04-26T16:46:55.971999Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface hardware.google.media.c2@1.0::IComponentStore/software
2024-04-26T16:46:57.019895Z INFO kernel: [ 2777.183672] binder_alloc: 26313:
binder_alloc_buf, no vma
2024-04-26T16:46:57.019976Z INFO kernel: [ 2777.223997] binder: 26148:26172 transaction
failed 29189/-3, size 76-0 line 3061
2024-04-26T16:47:03.316247Z INFO session_manager[1034]: INFO session_manager:
[upstart_signal_emitter.cc(50)] Emitting arc-booted Upstart signal
2024-04-26T16:47:03.983192Z INFO minijail0[26564]: libminijail[26564]: applying policy
for default runtime: /etc/security/minijail/v0.bin
2024-04-26T16:47:04.004405Z WARNING minijail0[26564]: libminijail[26564]: failed to
create a ruleset: Function not implemented
2024-04-26T16:47:04.004702Z WARNING minijail0[26564]: libminijail[26564]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:47:04.005289Z WARNING minijail0[26573]: libminijail[1]: failed to create a
ruleset: Function not implemented
2024-04-26T16:47:04.005379Z WARNING minijail0[26573]: libminijail[1]: Landlock is not
supported by the current kernel: Function not implemented
2024-04-26T16:47:04.005663Z INFO minijail0[26573]: libminijail[1]: Landlock support for
LANDLOCK_ACCESS_FS_REFERER: false
```

```
2024-04-26T16:47:20.597447Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.secure_element@1.0::ISecureElement/eSE1
2024-04-26T16:47:20.629817Z ERR arc-kmsg-logger[3892]: init: Could not find service
hosting interface android.hardware.secure_element@1.0::ISecureElement/SIM1
2024-04-26T16:47:25.234379Z WARNING kernel: [ 2805.429486] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:47:25.234482Z WARNING kernel: [ 2805.433632] audit: audit_backlog=65 >
audit_backlog_limit=64
2024-04-26T16:47:25.234495Z WARNING kernel: [ 2805.437265] audit: audit_lost=179
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:47:25.234500Z WARNING kernel: [ 2805.438765] audit: audit_lost=180
audit_rate_limit=0 audit_backlog_limit=64
2024-04-26T16:47:25.255077Z ERR kernel: [ 2805.455983] audit: backlog limit exceeded
2024-04-26T16:47:25.255107Z ERR kernel: [ 2805.457694] audit: backlog limit exceeded
2024-04-26T16:47:47.715995Z INFO kernel: [ 2827.909219] binder_alloc: 27367:
binder_alloc_buf, no vma
2024-04-26T16:47:47.716601Z INFO kernel: [ 2827.921652] binder: 26148:26172 transaction
failed 29189/-3, size 76-0 line 3061
```